

Precision Analytical Laboratory, Inc.

4136 LAKESIDE DRIVE, RICHMOND, CA 94806

PHONE (510) 222-3002

FAX (510) 222-1251

CERTIFICATE OF ANALYSIS

STATE LICENSE NO. 1150

Attn: Willie Eneridge
Willie Eneridge Service
1211 7th Street
Oakland, CA 94607

Date Received: 09/23/93
Date Analyzed: 10/07/93
Date Reported: 10/14/93
Job #: 75074

Project: Willie Eneridge Service
1211 7th Street, Oakland, CA
Matrix: Soil

soil in pit

Total Petroleum Hydrocarbon Analysis EPA Method 5030

mg/kg

| <u>Lab I.D.</u> | <u>Client I.D.</u> | <u>Gasoline Range</u> | <u>MDL</u> |
|-----------------|--------------------|-----------------------|------------|
| 75074-1 | MW-1 | 7.8 | 1.0 |
| 75074-2 | MW-2 | 2,690 | 50 |
| 75074-3 | MW-3 | 4,380 | 50 |
| 75074-4 | MW-4 | 3,290 | 50 |
| 75074-5 | MW-5 | 1,370 | 50 |
| 75074-6 | MW-6 | 1,500 | 50 |

(MW)

QA/QC: Matrix Spike Recovery for Gasoline: 111%
Matrix Spike Duplicate Recovery for Gasoline: 111%

MDL: Method Detection Limit. Compound below this level would not be detected.

Swinder Sidhu (for)

Jaime Chow
Laboratory Director

JC/dwc

Precision Analytical Laboratory, Inc.

4136 LAKESIDE DRIVE, RICHMOND, CA 94806

PHONE (510) 222-3002

FAX (510) 222-1251

CERTIFICATE OF ANALYSIS

STATE LICENSE NO. 1150

Attn: Willie Eneridge
Willie Eneridge Service
1211 7th Street
Oakland, CA 94607

Date Received: 09/23/93
Date Analyzed: 09/24/93
Date Reported: 10/14/93
Job #: 75074

Project: Willie Eneridge Service
1211 7th Street, Oakland, CA
Matrix: Soil

EPA Method 6010
Preparation Method 3050
mg/Kg

| <u>Lab I.D.</u> | <u>Client I.D.</u> | <u>Lead</u> | <u>MDL</u> |
|-----------------|--------------------|-------------|------------|
| 75074-1 | MW-1 | 365 | 0.40 |
| 75074-2 | MW-2 | 74.6 | 0.40 |
| 75074-3 | MW-3 | 12.7 | 0.40 |
| 75074-4 | MW-4 | 120 | 0.40 |
| 75074-5 | MW-5 | 22.4 | 0.40 |
| 75074-6 | MW-6 | 24.0 | 0.40 |

QA/QC: Matrix Spike Recovery for Lead: 77%
Matrix Spike Duplicate Recovery for Lead: 84%

MDL: Method Detection Limit. Compound below this level would not be detected.

Jaime Chow
Jaime Chow
Laboratory Director

JC/dwc

Precision Analytical Laboratory, Inc.

4136 LAKESIDE DRIVE, RICHMOND, CA 94806

PHONE (510) 222-3002

FAX (510) 222-1251

CERTIFICATE OF ANALYSIS

STATE LICENSE NO. 1150

Attn: Willie Eneridge Service
Willie Eneridge Service
1211 7th Street
Oakland, CA 94607

Date Received: 09/23/93
Date Analyzed: 10/07/93
Date Reported: 10/14/93
Job #: 75074

Project: Willie Eneridge Service
1211 7th Street, Oakland, CA
Matrix: Soil

Aromatic Volatile Hydrocarbon Analysis
EPA Method 8020
mg/Kg

| <u>Lab I.D.</u> | <u>Client I.D.</u> | <u>Benzene</u> | <u>MDL</u> | <u>Toluene</u> | <u>MDL</u> |
|-----------------|--------------------|----------------|------------|----------------|------------|
| 75074-1 | MW-1 | ND<0.005 | 0.005 | 0.066 | 0.005 |
| 75074-2 | MW-2 | ND<0.03 | 0.3 | 1.4 | 0.3 |
| 75074-3 | MW-3 | 2.0 | 0.3 | 110 | 0.3 |
| 75074-4 | MW-4 | ND<0.3 | 0.3 | 3.4 | 0.3 |
| 75074-5 | MW-5 | ND<0.3 | 0.3 | 2.8 | 0.3 |
| 75074-6 | MW-6 | ND<0.3 | 0.3 | 2.5 | 0.3 |

| <u>Lab I.D.</u> | <u>Client I.D.</u> | <u>Ethyl- benzene</u> | <u>MDL</u> | <u>Xylenes</u> | <u>MDL</u> |
|-----------------|--------------------|---------------------------|------------|----------------|------------|
| 75074-1 | MW-1 | 0.027 | 0.005 | 0.320 | 0.005 |
| 75074-2 | MW-2 | 0.96 | 0.3 | 70 | 0.3 |
| 75074-3 | MW-3 | 70 | 0.3 | 400 | 0.3 |
| 75074-4 | MW-4 | 3.8 | 0.3 | 110 | 0.3 |
| 75074-5 | MW-5 | 6.8 | 0.3 | 50 | 0.3 |
| 75074-6 | MW-6 | 8.2 | 0.3 | 60 | 0.3 |

QA/QC: Matrix Spike Recovery for Benzene: 93%
Matrix Spike Recovery for Toluene: 102%
Matrix Spike Recovery for o-Xylene: 107%

Matrix Spike Duplicate Recovery for Benzene: 93%
Matrix Spike Duplicate Recovery for Toluene: 103%
Matrix Spike Duplicate Recovery for o-Xylene: 108%

MDL: Method Detection Limit. Compound below this level would not be detected.

Swinder Sidhu (For)
Jaime Chow
Laboratory Director

JC/dwc

Box # None

CHAIN OF CUSTODY

| | | |
|---|--|--|
| PROJECT NO. | SAMPLERS (Signature) <i>Kulwinder Sidhu</i> | ANALYSIS REQUESTED |
| PROJECT NAME AND ADDRESS: <i>Willie Enridge Service</i> <i>452-0266 1211 7th St. OAKLAND CA</i> | | <i>93 OCT 22 PM 3:40</i> <i>94601</i> |

| CROSS REFERENCE NUMBER | DATE | TIME | Soil | Water | STATION LOCATION | ANALYSIS REQUESTED | | | | | | | REMARKS | |
|------------------------|---------|-------|------|-------|------------------|--------------------|---------------|--------------------|--------------|--------------|-----------------|------|---------|--|
| | | | | | | TPH - Gas/Oil | BTEX - (8020) | Halogenated (8010) | Oil & Grease | PCB - (8080) | Metals (CAM-17) | 8240 | | |
| MW-1 | 9/23/93 | 11:30 | Y | | | X | X | | | | X | | | |
| MW-2 | ↓ | 11:45 | Y | | | X | X | | | | X | | | |
| MW-3 | ↓ | 12:15 | Y | | | X | X | | | | X | | | |
| MW-4 | ↓ | 12:30 | Y | | | X | X | | | | X | | | |
| MW-5 | ↓ | 12:45 | Y | | | X | X | | | | X | | | |
| MW-6 | ↓ | 1:00 | Y | | | X | X | | | | X | | | |

| | | | |
|---|------------------------|--|------------------------|
| RELINQUISHED BY: (Signature) <i>Willie Enridge</i> | DATE <i>9/23/93</i> | RECEIVED BY: (Signature) <i>Kulwinder Sidhu</i> | DATE <i>9/23/93</i> |
| RELINQUISHED BY: (Signature) | TIME <i>1:15 PM</i> | RECEIVED BY: (Signature) | TIME <i>1:15 PM</i> |
| RELINQUISHED BY: (Signature) | DATE | RECEIVED BY: (Signature) | DATE |
| RELINQUISHED BY: (Signature) | TIME | RECEIVED BY: (Signature) | TIME |
| RELINQUISHED BY: (Signature) | DATE | RECEIVED BY: (Signature) | DATE |
| RELINQUISHED BY: (Signature) | TIME | RECEIVED BY: (Signature) | TIME |

Turnaround Time: * 24 hrs _____ * 2/3 days _____ * 4/5 _____ Normal X * Surcharge Applies

Special Instructions: _____

Possible Sample Hazards: _____