

BLAINE TECH SERVICES

P. O. BOX 5745 SAN JOSE, CA 95150 (408) 723-3974

September 26, 1986

Jack Quarle c/o Simas Properties P.O. Box 403 Diablo, CA 94528

Re: Field sampling at

40th & Telegraph Oakland, CA on September 25, 1986

SAMPLING REPORT

Sampling was performed in accordance with approved methodology at the locations shown on the accompanying site diagram. The lab numbers assigned to the samples are given on the site diagram. Samples were collected in appropriate containers, which were sealed, chilled and transported to the laboratory for analysis. Analytical services were provided by Soil And Water Laboratory with a separate report referencing their lab numbers.

Tanks

age -- unspecified


type -- three 10,000 gallon gasoline

reason for removal -- discontinuation of on site storage

Reportage

Submission to the Regional Water Quality Control Board and the Fire Department should include copies of both the sampling report and the laboratory report. The property owner should attach a cover letter and submit all documents together in a package.

Rpt 86268F1 9-25-86 Jack Quarle, 40th & Telegraph, Oakland page 1 of 3



40TH STREET

MAP REF: THOMAS BROS.

LEGEND: F = FILL PIPE

- #1 SOIL FROM 10'
 500 PPM-VAPOR
 ANALYSIS FOR GASOLINE AT
 SOIL AND WATER LABORATORY
 S & W LAB NO. 26886-1
- #2 SOIL FROM 9.5"

 ANALYSIS FOR GASOLINE
 S & W LAB NO. 28686.2
- #3 SOIL FROM 10'
 2,000 PPM-VAPOR
 ANALYSIS FOR GASOLINE
 S & W LAB NO. 26886-3
- #4 SOIL FROM 9.5'
 ANALYSIS FOR GASOLINE
 S & W LAB NO. 26886-4
- #5 SOIL FROM 10'
 2,000 PPM-VAPOR
 ANALYSIS FOR GASOLINE
 S & W LAB NO. 26886-5

SAMPLING PERFORMED BY DIAGRAM PERFARED BY

Tammie Stallings

The following addresses have been listed here for your convenience:

Water Quality Control Board
San Francisco Bay Region
1111 Jackson Street
Room 6040
Oakland, CA 94607
ATTN: Dale Bowyer

Alameda County Health
Hazardous Materials Management
Oakland, Ca 94612
Attn: Edgar Howell

City of Oakland Fire Prevention Bureau
One City Hall Plaza
Oakland, CA 94612
ATTN: Robert Dawson

If I can be of any further assistance, please call.

Richard C. Blaine

RCB/tls

BLAINE TECH SERVICES

P.O. BOX 5745 SAN JOSE, CA 95150 (408) 723-3974

Include All, of the fol 862 EVERYTHING written abo	16 1	7.7
Field sampling completed 1:20	of this line is the project designable or 1-25-86 performed by	ali
	ACCEPTED BY	- 0
1.58,0,9 25,00 let	a 6,59 nrs. 9 25.86 71	rel Jone
(2007) 전 경기 (1.2003) - 1 전문 (1.2003) 전 1 전문 (2.2003) (1.2003) (1.2003) (1.2003) (1.2003) (1.2003) (1.2003)		
	:hrs86	
T.D. TYPE · A	NALYSIS LAB PRELINS	-
#1 Soil -	Ggs	1900
#.2		8
H.3		24
H4 V	1	24
-		66
15	16	
		-
	<u> </u>	. —
		-
THEN AROUND 24 hrs.	643-	
REPORT TO: Tech Services	Samo.	
	Atta	
Attn Phone	Verbal/Ref PO From:	
CC BLAINE TECH SERVICES (always)	SPECIAL INSTRUCTIONS	
	() Phone results to BTS () Phone results to client d	irect



Pollution and Residue Control Drinking Water

14072 W. Park Avenue Boulder Creek, CA 95006

(408) 338-3053

Blaine Technical Services P.O. Box 5745 San Jose, California 95150

Jack Quarle 40th and Telegraph Oakland, CA

LABORATORY REPORT

Total Hydrocarbon Analysis : Gasoline

Procedure: EPA Method 5020 for Headspace Analysis


Detection Limit: 1 ppm

Received: September 25, 1986

Analyzed: September 25, 1986

S&W ID	Client ID	Concentration ppm	
268B6 1	86268Fl l soil, gas	99	
268B6-2	86268Fl 2 soil, gas	8	
268B6 3	86268Fl 3 soil, gas	27	
268B6 4	86268Fl 4 soil, gas	74	
268B6 5	86268Fl 5 soil, gas	86	

Analyst



LEGEND MOHITORING WELL 40TH STREET



MONITORIN	G WELL LOC	ations.
	H STREET	

FIGURE

DESIGNED BY : PROJECT NO: 1-3532 DRAWN BY : C. HEINRITZ

SCALE : 1"=30'-0" DATE: 7-19-82