



ENVIRONMENTAL ENGINEERING, INC
2680 Bishop Drive • Suite 203 • San Ramon, CA 94583
TEL (925) 244-6600 • FAX (925) 244-6601

2624

May 27, 2004

Mr. Amir Gholami
Alameda County Environmental Health Services
1131 Harbor Bay Parkway, Ste 250
Alameda, California 94502

Alameda County
JUN 03 2004
Environmental Health

Re: Well Replacement
Tony's Express Auto Service
3609 International Blvd, Oakland, California

Dear Mr. Gholami:

SOMA recently observed a cracked well casing in monitoring well MW-4. It is a 2-inch diameter well, with an approximate depth of 26.0 feet. The enclosed figure shows the location of MW-4.

SOMA recommends this well to be abandoned, and replaced with a new identical groundwater monitoring well. During the replacement SOMA will follow Alameda County well destruction guidelines.

Thank you for taking the time to review this matter. Meanwhile, please do not hesitate to call me at (925) 244-6600, if you have any questions or comments.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Tony Perini', is written above the typed name.

Tony Perini
Project Engineer

Enclosure


cc: Abolghessem Razi

COMMERCIAL AREA

INTERNATIONAL BLVD

Alameda County
JUN 03 2004
Environmental Health
COMMERCIAL AREA

36th AVENUE



- ▲ MONITORING WELL
- ▲ EXTRACTION WELL
- EXTRACTION MANIFOLD PIPING

approximate scale in feet




Figure 2: Site map showing location of groundwater monitoring wells, French drain, SVE system, and GAC system