## ENVIRONMENTAL PROTECTION

97 JAN 22 PH 3:31



January 17, 1997

Ms. Susan Hugo Alameda County Health Care Services Department of Environmental Health 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 Chevron Products Company 6001 Bollinger Canyon Road Building L San Ramon, CA 94583 P.O. Box 6004 San Ramon, CA 94583-0904

Marketing – Sales West Phone 510 842-9500

Re:

Chevron Service Station #9-0329 340 Highland Avenue Piedmont, California

Dear Ms. Hugo:

Enclosed is the report of the results of the Soil and Groundwater Investigation, that was prepared by our consultant Pacific Environmental Group Inc. at the above noted facility. The purpose of this investigation was to determine the vertical and lateral extent of petroleum hydrocarbon constituents in the soil and groundwater crossgradient and downgradient of the site.

This investigation included drilling two soil borings C-5 and C-6, to a depth of approximately 18 feet and then converting them to monitoring wells. Soil samples were collected at the five and ten foot levels and were analyzed for the presence of TPH-g, BTEX and MtBE constituents. The monitoring wells were developed and water samples taken and analyzed for the presence of TPH-g, BTEX and MtBE constituents. The results of the sampling indicated that these constituents were below method detection limits for the four soil samples and the two water samples collected in wells C-5 and C-6.

Based on these results it appears that the vertical and lateral extent of petroleum hydrocarbons crossgradient and downgradient of this site has been delineated to non-detectable soil and groundwater concentrations. These wells will be added to the quarterly monitoring program to ensure plume stability.

If you have any questions or comments call me at (510) 842-9136.

Sincerely,

CHEVRON PRODUCTS COMPANY

Philip R. Briggs

Site Assessment and Remediation Project Manager

Enclosure

January 17, 1997 Ms. Susan Hugo Chevron Service Station # 9-0329 Page 2

## cc. Ms. Bette Owen, Chevron

Mr. Kevin Graves RWQCB-San Francisco Bay Region 2101 Webster Street, Suite 500 Oakland, CA 94612

Mr. Frank Hoffman Hoffman Investment Company 1760 Willow Road Hillsborough, CA 94010

Mir Ghafari Chevron Service Station 340 Highland Avenue Piedmont, CA 94611

CLIENT NAME; REC. BY (PRINT);	PEG			WORKORDER: DATE OF LOG-IN:	96100	-		
CIRCLE THE APPROPRIATE	RESPONSE	LAB SAMPLE	DASH	CLIENT	CONTAINER	SAMPLE	DATE	REMARKS:
1. Cuslody Seal(s) F	resent (Absent)	#	#	IDENTIFICATION	DESCRIPTION	MATRIX	SAMP.	CONDITION(ETC
li de la companya de	nlact / Broken*	0[	A	C-S0 5'	CORF	SUA	7	
2. Custody Scal Nos.: P	Put In Remarks Section	02		1 10'	1	14.	1	
3. Chain-of-Custody				12'	₹1			
Records:	Presenty Absent*		,	181				
4. Traffic Reports or		5	4	C-6 @ 5'			4	
Packing List: P	resent / Absent	of	L L	1 10'		:   .		
5. Airbill: A	irbill Sticker			15'				
C	resenty Absent			18'				
6. Airbill No.:	009818527 843				:		J	
7. Sample Tags:	resent / Absent*		·	·				
Sample Tag Nos.: 🖽	sted / Not Listed						:	
or	n Chain-of-Custody						2 3 to 1	
8. Sample Condition: (In	Lact / Broken* / Leaking*				27.00			: .
9. Does information on cust	lody			,				
reports, traffic reports and	i			1				
sample tags agree? 🛛 🗨	Es No*	·					ž.	
10. Proper preservalives	^				·			
used: (Ye	9\$ / <sub>3</sub> No*							•
11. Dalo Reć. at Lab:	10.21.96						•	
12. Temp. Rec. at Lab:	12.0							
13. Time Rec. at Lab:	11:12							

<sup>\*</sup> If Circled, contact Project manager and attach record of resolution

Lax_cop	y of	Lab	Kej	por	t a	nd (	JUC to	Che	vron	Co	ntac	t: L	I No	,						<u>- yus</u>			
Chevron U.S.A. Inc. P.O. BOX 5004 San Ramon, CA 94583 FAX (415)842-9591  Chevron Facility Number 9-0329 Facility Address 340 H34/and Consultant Project Number 320-160. Consultant Name Pacific Environment Polyment Plant Project Contact (Ndms) Rose Inc. (Phone) 408441700								o. (A o. (A o. ue. o. s in li	tre, Predmont A ventral Group Site 440, S.S. 9510 line					Chevron Contact (Name)									195
Sample Number	Lab Sample Number	Number of Containors	Matthe S = Soll A = Air W = Water C = Charmel	1 8	type c = composite D = Clearate	Time	Sample Preservation	iced (Yes or No)	BIEX + TPH GAS (8020 + 8015)	TPH Diesel (8015)	Oll and Grasse (5520)	Purpedble Holocorbons (8010)	Purpeable Arametics (8020)		Extractable Organica (8270)	Metals Cd,Cr,Pb,Zn,Ni (ICAP or AA)		Ηοτ			DO TB	TE: NOT E LB SA	,
C-5@10' C-5@10' C-5@18' C-6@10' C-6@15 C-6@18	<b>り</b>		S		G			Yes	X									XX			is Co-	Meteo Selec Som l Sentrati	ted whest
Relinquished B	y (Signature	1) 47012		PA Orga	nization CIFIC nization		Date/Time [0/12/96 // Date/Time 10/1 09 Date/Time 29/21 11	7:40 55	Received	13en	noture)	By fisio	nature)	Organiz PACH Organiz	E (C atlon	Dia Co	ate/Time /(8/GL ate/Time T/2/ Cote/Time	17:40 935	ľ	Turn Around	1 Time 24 Hr 48 Hr 5 Doy 10 Do	i.	o•)

,