



July 18, 1996









photo notes:

B & C Gas and Mini Mart  
2008 First Street  
Livermore, CA 94550

September 7, 1995 by Don Atkinson-Adams

Excavation and repair of a single wall fiberglass motorvehicle fuel tank/

1- Sessions Tank Liners truck and dispenser island



photo notes:

B & C Gas and Mini Mart  
2008 First Street  
Livermore, CA 94550

September 7, 1995 by Don Atkinson-Adams

5. View of excavation pit from the office. Ross Sessions is the person on the left.





photo notes:

B & C Gas and Mini Mart  
2008 First Street  
Livermore, CA 94550

September 7, 1995 by Don Atkinson-Adams

4- View of opening cut through the end of the tank. Note the continuation of the steel pipe in the upper left of the photo {see # 3 above}. One worker is in the tank at the time of the photo and one is in the pit.




photo notes:

B & C Gas and Mini Mart  
2008 First Street  
Livermore, CA 94550

September 7, 1995 by Don Atkinson-Adams

3- View of opening cut through the end of the tank. Steel pipe is probably a drain pipe not a product pipe judging by the diameter.





photo notes:

B & C Gas and Mini Mart  
2008 First Street  
Livermore, CA 94550

September 7, 1995 by Don Atkinson-Adams

2- Ventilation for the tank under repair. Note the ground wire going off to the left of the photo.






B&C Gas and Minimart  
2008 First Street  
Livermore  
Photos taken 6/15/95  
by RWeston



B&C Gas and Minimart  
2008 First Street  
Livermore  
Photos taken 6/15/95  
by RWeston



B&C Gas and Minimart  
2008 First Street  
Livermore  
Photos taken 6/15/95  
by RWeston



B&C Gas and Minimart  
2008 First Street  
Livermore  
Photos taken 6/15/95  
by RWeston

*Highlighted  
union leaked for  
4 mo.*