



North State Environmental
Chemical Waste Disposal - Tracking - Consulting

CERTIFICATE OF ANALYSIS

Lab Number: 98-455
Client: Semco HK2
Project: 1001 Marin Ave., Albany, CA

Date Reported: 04/24/98

Carbons by Method 8015 M
Benzene, Toluene, Ethylbenzene and Xylenes by Method 8020

Analyte	Method	Result	Unit	Date Sampled	Date Analyzed
Sample: 98-455-01	Client ID: [REDACTED]			04/23/98	
Benzene	8020	ND			04/23/98
Ethylbenzene	8020	ND			
Toluene	8020	ND			
Xylenes	8020	ND			04/23/98
Diesel	8015M	[REDACTED]	mg/Kg		
Sample: 98-455-02	Client ID: [REDACTED]			04/23/98	SOIL
Benzene	8020	ND			04/23/98
Ethylbenzene	8020	ND			
Toluene	8020	ND			
Xylenes	8020	ND			04/23/98
Diesel	8015M	[REDACTED]	mg/Kg		
Sample: 98-455-03	Client ID: [REDACTED]			04/23/98	SOIL
Benzene	8020	ND			04/23/98
Ethylbenzene	8020	ND			
Toluene	8020	ND			
Xylenes	8020	ND			04/23/98
Diesel	8015M	[REDACTED]	mg/Kg		

Page

P. O. Box 3624 • South San Francisco, California 94081 • 650-598-1838 FAX 650-598-1510



North State Environmental
Chemical Waste Disposal - Trucking - Consulting

CERTIFICATE OF ANALYSIS

Quality Control/Quality Assurance

Lab Number: 98-455
Client: Semco HK2
Project: 1001 Marin Ave., Albany, CA

Date Reported: 04/24/98

Diesel Range Hydrocarbons by Method 8015 M
Benzene, Toluene, Ethylbenzene and Xylenes by Method 8020

Analyte	Method	Reporting Limit	Unit	Blank	MS/MSD Recovery	RPD
Benzene	8020	.005	mg/Kg	ND	111	13
Ethylbenzene	8020	.005	mg/Kg	ND	104	18
Toluene	8020	.005	mg/Kg	ND	107	16
Xylenes	8020	.010	mg/Kg	ND	98	13
Diesel	8015M	1.0	mg/Kg	ND	95	1

ELAP Certificate NO:1753

Reviewed and Approved

John A. Murphy, Laboratory Director

Page 2 of 2

P. O. Box 5624 • South San Francisco, California 94087 • 650-588-1434 FAX 650-588-1050



North State Environmental Analytical Laboratory
Phone: (415) 588-9652 Fax: (415) 588-1950

98-455

Chain of Custody / Request for Analysis
Lab Job No.: _____ Page ____ of ____

Client: HK2, INC.	Report to: HK2, Inc.	Phone: (650) 261-1968	Turnaround Time A.S.A.P.
Mailing Address: 70 Chemical Way Redwood City CA	Billing to: Semco Modesto, CA	Fax: (650) 261-0735	Date: 4-23-98
		PO# / Billing Reference: 97-0365	Sampler: Jim Cox

Project / Site Address: **1001 Marin Avenue Albany, CA**
Analysis Requested

Sample ID	Sample Type	Container No. / Type	Pres.	Sampling Date / Time	Analysis Requested		Comments/Hazards
1 Stackpile	Soil	4 B.T.	1cc	4/23/98 12:30	X	X	4 Point Composite East End 2 B.T. Fill End 2 B.T.
2 Stackpile	Soil	1 D.T.	1cc	4/23/98 12:32	X	X	
Stackpile	Soil	1 B.T.	1cc	4/23/98 12:34	X	X	
							and pool

Relinquished by: <i>[Signature]</i>	Date: 4/23/98 Time: 2:00	Received by: <i>[Signature]</i>	Lab Comments
Relinquished by:	Date: _____ Time: _____	Received by:	
Relinquished by:	Date: _____ Time: _____	Received by:	