### **Atlantic Richfield Company**

**Shannon Couch** 

Operations Project Manager

#### **RECEIVED**

4:32 pm, Nov 01, 2012

Alameda County Environmental Health PO Box 1257 San Ramon, CA 94583 Phone: (925) 275-3804 Fax: (925) 275-3815 E-Mail: shannon.couch@bp.com

October 31, 2012

Re: Work Plan for Monitoring Well Installation and Vapor Intrusion Assessment

Former Richfield Oil Company Station #402 1450 Fruitvale Avenue, Oakland, California ACEH Case #RO0000307

I declare that to the best of my knowledge at the present time, that the information and/or recommendations contained in the attached document are true and correct.

Submitted by,

Shannon Couch Operations Project Manager

Attachment





# WORK PLAN FOR MONITORING WELL INSTALLATION AND VAPOR INTRUSION ASSESSMENT Former Richfield Oil Company Station #402 1450 Fruitvale Avenue Oakland, Alameda County, California ACEH Case #RO0000307

#### **Prepared for:**

Ms. Shannon Couch Atlantic Richfield Company P.O. Box 1257 San Ramon, CA 94583

#### **Prepared by:**

Broadbent & Associates, Inc. 1324 Mangrove Avenue, Suite 212 Chico, California 95926 (530) 566-1400

October 31, 2012

08-88-602



October 31, 2012

Project #08-88-602

Atlantic Richfield Company P.O. Box 1257 San Ramon, CA 94583 Submitted via ENFOS

Attn.: Ms. Shannon Couch

Re: Work Plan for Monitoring Well Installation and Vapor Intrusion Assessment

Former Richfield Oil Company Station #402, 1450 Fruitvale Ave., Oakland, Alameda County

ACEH Case #RO0000307

Dear Ms. Couch:

Broadbent & Associates, Inc. (Broadbent) is pleased to submit this *Work Plan for Monitoring Well Installation and Vapor Intrusion Assessment* (Work Plan) on behalf of Atlantic Richfield Company (a BP affiliated company), for Former Richfield Oil Company Station #402 located at 1450 Fruitvale Avenue, Oakland, Alameda County, California (Site). This Work Plan presents a description of proposed activities to install monitoring wells and perform a vapor intrusion assessment in order to evaluate residual onsite petroleum hydrocarbon contamination. This Work Plan supersedes the previously submitted *Monitoring Well Installation Work Plan* (Broadbent, June 19, 2012).

As this project is just beginning the assessment phase anew, this work plan is not being provided with the Low-Threat UST Case Closure Policy Checklist discussed at the September 11, 2012 meeting with ACEH. Broadbent intends to submit the Low-Threat UST Case Closure Policy Checklist with the report generated subsequent to this investigation.

Should you have any questions or require additional information please do not hesitate to contact us at

(530) 566-1400.

Sincerely,

**BROADBENT & ASSOCIATES, INC.** 

Thomas A. Venus, P.E.

Senior Engineer

cc: Ms. Dilan Roe, P.E., Alameda County Environmental Health (submitted via ACEH ftp site)

Mr. Bill Phua, Fruitvale-Farnum Associates, LLC, 638 Webster St., #300, Oakland, CA 94607

xpires /2-3 /- 20/

Mr. Hugh K. Phares, III, Attorney at Law, 911 Paru St., Alameda, CA 94501-4033

Electronic copy uploaded to GeoTracker

## WORK PLAN FOR MONITORING WELL INSTALLATION AND

#### **VAPOR INTRUSION ASSESSMENT**

Former Richfield Oil Company Station #402 1450 Fruitvale Avenue Oakland, Alameda County, California

#### **TABLE OF CONTENTS**

No.	<u>Sect</u>	<u>ion</u>	Page
1.0	Intro	oduction	1
2.0	Site	Description and Background	1
3.0		onal Geology and Hydrogeology	
4.0	Prop	posed Monitoring Well Installation Activities	3
	4.1	Preliminary Activities, Local Permitting, and Notification	4
	4.2	Soil Borings	4
	4.3	Groundwater Monitoring Well Construction	4
	4.4	Groundwater Monitoring Well Development, Surveying, and Sampling	5
5.0	Prop	posed Vapor Intrusion Assessment Activities	5
	5.1	Preliminary Activities, Local Permitting, and Notification	5
	5.2	Soil Gas Monitoring Implant Borings	5
	5.3	Soil Gas Implant Construction	
	5.4	Soil Gas Implant Sampling	6
	5.5	Laboratory Analysis of Soil Gas Samples	
6.0	Inve	stigation Reporting	
7.0	Prop	oosed Schedule	8
8.0	Limi	tations	8
9.0	Refe	rences	9

#### **DRAWINGS**

Drawing 1: Site Location Map

Drawing 2: Site Map with Historic Boring and Monitoring Well Locations

Drawing 3: Site Map with Proposed Sampling Locations

#### **APPENDICES**

Appendix A: Historic Soil Data

Appendix B: Historic Groundwater Data

Appendix C: Soil Boring/Well Construction Logs and Geologic Cross-Section

## WORK PLAN FOR MONITORING WELL INSTALLATION AND

#### VAPOR INTRUSION ASSESSMENT

Former Richfield Oil Company Station #402 1450 Fruitvale Avenue Oakland, Alameda County, California

#### 1.0 INTRODUCTION

Broadbent & Associates, Inc. (Broadbent) has prepared this *Work Plan for Monitoring Well Installation and Vapor Intrusion Assessment* (Work Plan) on behalf of the Atlantic Richfield Company (ARC) – a BP affiliated company, for Former Richfield Oil Company Station #402 located at 1450 Fruitvale Avenue in Oakland, Alameda County, California (Site). A Site Location Map has been provided as Drawing 1.

In a letter dated October 16, 2008 Alameda County Environmental Health (ACEH) requested the completion of a soil and groundwater investigation. The *Work Plan – Monitoring Well Installation, 1450 Fruitvale Avenue, Oakland, California* (AEI Consultants, Inc., 3/3/2005), originally prepared for Fruitvale-Farnam Associates, LLC, was previously approved by the ACEH in a letter dated June 22, 2006. This work plan had proposed installing four additional groundwater monitoring wells on and off the Site, replacing the three onsite monitoring wells that had been lost or destroyed as a result of property redevelopment activities at the Site. ARC had repeatedly attempted without success to collectively implement the approved scope of work with the other co-Responsible Parties (RPs) listed in the ACEH letters. ARC was finally able to negotiate a property access agreement with Mr. Phua / Fruitvale-Farnam Associates, LLC, on April 11, 2012.

This Work Plan proposes the installation of four new onsite groundwater monitoring wells to provide sampling locations to assist with the evaluation of residual hydrocarbon contamination. In addition, a Vapor Intrusion Assessment is proposed to determine whether there is a vapor intrusion risk associated with the historic release. This Work Plan provides a discussion of the Site Description and Background, Proposed Activities, and Proposed Schedule.

This Work Plan supersedes the *Monitoring Well Installation Work Plan*, submitted by Broadbent on June 19 2012, which proposed installation of groundwater monitoring wells without concurrently performing an active soil gas vapor intrusion assessment.

#### 2.0 SITE DESCRIPTION AND BACKGROUND

The Site is currently occupied by the Fruitvale Commercial Center office building located on the northeast corner of Farnam Street and Fruitvale Avenue in Oakland, Alameda County, California (Drawing 2). A restaurant and large Laundromat occupy the first floor of this three-story building. A health & dental clinic occupy the second floor, while a tax preparation service and real estate mortgage company occupy the third floor of the building. The open space of the Site not occupied by the building footprint is covered by cement concrete with exception of thin landscape planters located along the western and southern property boundaries.

Work Plan for MW Installation and VIA Former Station #402/Oakland October 31, 2012 Page 2

The Site was reportedly developed as a gas station in 1950 by Richfield Oil Company and operated until 1983 (Richfield Oil Company sold the property to Curtis & Joyce Thomas in 1976, however ACEH was not satisfied with the proof Broadbent provided that Mr. Thomas was the last operator of the USTs at the Site). Four underground storage tanks (USTs) were supposedly located along the southern boundary of the Site. The fuel dispenser island was located on the northwestern portion of the former parking lot. AEI Consultants (AEI) conducted research at the City of Oakland Fire and Building Departments for records relating to the location of the USTs and associated piping. Although formal tank removal records were not available, it was determined that the former UST basin was along Farnam Street, as depicted in Drawing 2 (AEI, 10/11/1999).

Following an inconclusive geophysical survey, AEI conducted three excavations in May 1999 in order to confirm the presence or absence of USTs remaining onsite. The approximate locations of these excavations are depicted on Drawing 2. No tanks were found and soils removed from the larger excavation appeared to be consistent with imported fill material commonly used to backfill former tank basins. A total of six soil samples and one groundwater sample (labeled AEI GW 8') were collected from the larger excavation. The analytical results obtained from the collected samples indicated very low to non-detect concentrations of petroleum hydrocarbons. Historic soil and groundwater laboratory analytical results from this investigation are summarized in Appendices A and B, respectively (AEI, 6/11/1999).

According to AEI, a previous subsurface investigation performed by Glenfos had revealed a release. However, AEI concluded that it was apparent that the USTs had been removed and that the release that had occurred did not take place in the former UST basin but rather within the vicinity of the product piping or dispenser island (AEI, 10/9/2002).

Between July 1998 and June 2002, a total of 22 soil borings (GP-1 through GP-8 and AEI-9 through AEI-22) were advanced, and three monitoring wells (MW-1 through MW-3) installed. A Site Map with Historic Boring and Monitoring Well Locations is provided as Drawing 2. Historic soil data are presented in Appendix A, historic groundwater data are provided in Appendix B, and historic soil boring/well construction logs and a geologic cross-section are provided in Appendix C.

On September 26, 2002, AEI advanced an additional three shallow soil borings (AEI-23 through AEI-25) with a hand auger in the vicinities of the former dispenser (AEI-23), product piping (AEI-24), and beneath the proposed building (AEI-25). The purpose of these borings was to confirm the absence of hydrocarbon impacts within the shallow soil and to collect a soil sample for grain size analysis. Reportedly, soil sample analytical data did not reveal significant presence of source material remaining within the vadose zone (AEI, 10/9/2002).

Within the Site Summary and Risk Evaluation Report (AEI, 10/9/2002), AEI included an analysis of groundwater, soil, and vapor exposure pathways present at the Site and the results of a conduit survey. A comparative analysis of Site groundwater and soil analytical data with Regional Water Quality Control Board risk-based screening levels and City of Oakland screening levels was included within the report. Based on the results of this evaluation, AEI recommended formal case closure. The ACEH did not grant closure and requested that additional groundwater investigation activities be conducted following redevelopment of the property.

On March 7, 2005, AEI submitted a *Work Plan – Monitoring Well Installation*, proposing the installation of four additional monitoring wells to further assess the extent of the hydrocarbon contaminant plume. However, the work activities proposed within this Work Plan were not conducted.

A total of eight groundwater monitoring/sampling events were conducted at the Site between October 2000 and September 2002 utilizing the three original onsite wells MW-1, MW-2, and MW-3. These three wells appear to have been paved over with cement concrete or otherwise abandoned, although a record of proper destruction/decommissioning was not on file with the ACPWA.

#### 3.0 REGIONAL GEOLOGY AND HYDROGEOLOGY

According to the East Bay Plain Groundwater Basin Beneficial Use Evaluation Report (California Regional Water Quality Control Board – San Francisco Bay Region/SFRWQCB, June 1999), the Site is located within the Oakland Sub-Area of the East Bay Plain of the San Francisco Basin. The Oakland Sub-Area contains a sequence of alluvial fans. The alluvial fill thickness ranges from 300 to 700 feet deep. There are no well-defined aquitards such as estuarine muds. The largest and deepest wells in this sub-area historically pumped one to two million gallons per day at depths greater than 200 feet. Overall, sustainable yields are low due in part to low recharge potential. The Merrit sand in West Oakland was an important part of the early water supply for the City of Oakland. It is shallow (up to 60 feet), but before the turn of the last century, septic systems contaminated the water supply wells.

Throughout most of the Alameda County portion of the East Bay Plain, from Hayward north to Albany, water level contours show that the general direction of groundwater flow is from east to west or from the Hayward Fault to the San Francisco Bay. Groundwater flow direction generally correlates to topography. Flow direction and velocity are also influenced by buried stream channels that typically are oriented in an east to west direction.

Based on the eight monitoring events, depth-to-water (DTW) measurements have ranged from approximately 8 to 18 feet below ground surface (bgs). The groundwater gradient direction associated with the Site has varied, but the predominant direction was to the southeast. Historic groundwater monitoring data including gradient magnitude and direction is provided in Appendix B.

Based on review of geologic boring logs, soil beneath the Site generally consists of mixed silty, sandy, and gravely clays, which have been encountered up to the maximum boring depth of 35 feet bgs. Soils observed between 10 and 12 feet bgs are predominantly clay while sand and gravel content increase with depth. Lenses of sand have been observed ranging from several inches to several feet thick in several borings in the 10 to 15 feet bgs range.

#### 4.0 PROPOSED MONITORING WELL INSTALLATION ACTIVITIES

As previously mentioned, the historic wells onsite have been abandoned and/or paved over, thus warranting additional monitoring well installation activities onsite in order to properly assess current residual hydrocarbon impacts to soil and groundwater within the vicinity of the Site. Accordingly, Site evaluation activities will be facilitated through installation of four monitoring wells MW-4, MW-5, MW-6, and MW-7 on-Site (Drawing 3). The proposed monitoring well locations are tentative, and are subject to change due to access and utility clearance.

#### 4.1 Preliminary Activities, Local Permitting, and Notification

Prior to initiating field activities, Broadbent will obtain the necessary well permits from ACPWA, prepare a site-specific Health and Safety Plan (HASP) for the proposed work, and clear the proposed boring locations of conflicts with subsurface utilities. The utility clearance will include notifying Underground Service Alert (USA) of the pending work a minimum of 48 hours prior to initiating the field investigation, and procuring the services of a private utility locating company to confirm the absence of underground utilities at each boring location. Boreholes will be physically cleared to 6.5 feet bgs using hand auger or air knife methods consistent with BP's and Broadbent's Defined Practice for Ground Disturbance.

The Site-specific HASP will be prepared for use by field personnel implementing this Work Plan. The HASP will address hazards associated with drilling activities and potential exposure pathways and media which project personnel may encounter during proposed replacement well installation. A copy of the HASP will be available on-site during work. The subcontractor(s) performing field activities will be provided with a copy of the HASP prior to initiating work, and daily safety tailgate meetings will also be conducted to review hazards and drilling safety associated with execution of the work.

#### 4.2 Soil Borings

The borings will be completed under the direct supervision of Broadbent field personnel. A California C-57 licensed drilling company will provide a hollow-stem auger rig for well installation. The borings will be advanced to an approximate total depth of 25 ft bgs. Each boring will be continuously cored to assist with detailed lithologic logging and identification of potential contamination. Select soil samples collected above groundwater will be submitted for laboratory analysis (4 ft bgs, 6 ft bgs, and possibly 8 ft bgs). Soil cuttings will be classified according to the Unified Soil Classification System (USCS), and will be examined using visual and manual methods for parameters including odor, staining, color, grain size, and moisture content. Field screening for hydrocarbons will include visual and olfactory observations and portable photo-ionization detector (PID) measurements.

Collected soil sample cores will be sealed with Teflon sheets, capped and placed in a chilled cooler. Samples will be then be submitted to a state-certified analytical laboratory under standard chain-of-custody protocol. Soil samples will be analyzed for Gasoline-Range Organics (GRO, C6-C12) by EPA Method 8015M and for Benzene, Toluene, Ethylbenzene, Total Xylenes (BTEX) and Methyl Tertiary Butyl Ether (MTBE) by EPA Method 8260B.

Investigation-derived residuals will be temporarily stored on-site in 55-gallon drums, pending characterization for proper disposal. Broadbent will coordinate the transportation and disposal of surplus soils and liquids to the appropriate California-regulated facilities.

#### 4.3 Groundwater Monitoring Well Construction

New onsite monitoring wells MW-4 through MW-7 will be constructed of four-inch diameter, Schedule 40 poly-vinyl chloride (PVC) threaded casing. The screened intervals will consist of 0.010-inch machine-cut slots extending from approximately five feet bgs to approximately 25 feet bgs (total depth drilled). This screen interval should span the water table that has historically fluctuated between 8 to 18 ft bgs. A filter pack consisting of No.2/12 sand will be installed in the annular space from total depth drilled to one foot above the casing screen interval. A one-foot Bentonite clay seal will be placed above the filter

pack with neat cement grout completing the seal. The well will be completed with a traffic-rated locking vault which will be set in cement concrete to protect the well head.

#### 4.4 Groundwater Monitoring Well Development, Surveying, and Sampling

The wells will be developed no sooner than 48 hours after installation. The well development process will consist of surging and bailing each well to remove fine-grained sediments from the well and sand filter pack. A minimum of three and a maximum of ten wetted casing volumes of groundwater will be removed until water quality parameters have stabilized. Periodic measurements of the water quality parameters pH, temperature, and conductivity will be recorded during the development to establish baseline values for groundwater. Purge water generated during development activities will be temporarily stored on-site in 55-gallon drums, pending characterization for proper disposal. Broadbent will coordinate the transportation and disposal of purge water to the appropriate California-regulated facilities.

After installation, the monitoring wells will be surveyed in accordance with State Water Resource Control Board's standards for the GeoTracker database. Consistent with California Department of Water Resources (DWR) and ACPWA requirements, the licensed C-57 well driller will prepare a Well Completion Report (DWR Form 188) for each new monitoring well. The completed well reports shall be submitted to the DWR, ACPWA, and the ACEH (within the resultant investigation report).

The wells will be sampled no sooner than 48 hours after well development. Groundwater samples will be submitted to a state-certified analytical laboratory under standard chain-of-custody protocol. Groundwater samples will be analyzed for GRO (hydrocarbon chain lengths between C6-C12) by EPA Method 8015M and for BTEX and MTBE by EPA Method 8260B.

#### 5.0 PROPOSED VAPOR INTRUSION ASSESSMENT ACTIVITIES

Vapor Intrusion Assessment is proposed to determine whether there is a vapor intrusion risk associated with the historic release.

#### 5.1 Preliminary Activities, Local Permitting, and Notification

Concurrent with the groundwater monitoring well installation preliminary activities, Broadbent will obtain the necessary permits for soil gas monitoring implants from ACPWA, include the proposed work in the site-specific HASP, and clear the proposed installation locations of conflicts with subsurface utilities. The utility clearance will include notifying Underground Service Alert (USA) of the pending work a minimum of 48 hours prior to initiating the field investigation, and procuring the services of a private utility locating company to confirm the absence of underground utilities at each soil gas monitoring implant locations. Soil gas monitoring implant locations will be physically cleared using a hand auger consistent with BP's and Broadbent's Defined Practice for Ground Disturbance.

#### 5.2 Soil Gas Monitoring Implant Borings

The soil gas monitoring implant borings will be installed by a C-57 licensed drilling contractor using hand augers under the direct supervision of Broadbent field personnel. The first soil gas boring location (SG-1) is proposed to be located approximately five feet from the front side of the building, between the

former USTs/pump island and the portion of the building occupied by the coin-operated Laundromat. The second soil gas boring location (SG-2) is proposed to be located approximately five feet from the northwest corner of the building, near the portion of the building used for the stairwell and elevator. The third soil gas boring location (SG-3) is proposed to be located approximately five feet from the eastern property boundary near newly proposed groundwater monitoring well MW-6. This location in the southeastern portion of the property is near the adjacent occupied residence at 3216 Farnam Street. The fourth soil gas boring location (SG-4) is proposed to be located approximately five feet from the eastern property boundary near newly proposed groundwater monitoring well MW-7. This location in the northeastern portion of the property is near an area of the adjacent residential property that is not currently developed but could be at some time in the foreseeable future.

Two soil gas implants will be installed at each location: An "A" soil gas implant will be constructed with the probe installed at 3.5 ft bgs, and a "B" soil gas implant will be constructed with the probe installed at 5.5 ft bgs. However, in lieu of nested multi-level wells, each soil gas boring will be constructed to a specific depth within its own boring, thus minimizing the potential for short-circuiting. Therefore there will be a SG-1A and SG-1B in front of the building, a SG-2A and SG-2B by the northwest stairwell and elevator, a SG-3A and SG-3B in the southeast portion of the property, and a SG-4A and SG-4B in the northeast portion of the property. Each "A" and "B" implant will be horizontally separated by at least three feet. Proposed soil gas implant boring locations are shown in Drawing 3.

#### 5.3 Soil Gas Implant Construction

Soil gas implants will be constructed by attaching a 6-inch long soil gas probe tip to a 0.125-inch diameter nylon tubing (i.e. NylaFlow) extending approximately two feet above the surface. The soil gas probe tips will be constructed of double-woven stainless steel wire screen with a 0.057-inch pore diameter, equipped with stainless-steel end fittings. Each soil gas implant will be embedded within the middle of a one-foot thick sand filter pack of #2/12 sorted sand, topped with one-half foot of dry powdered Bentonite clay below a minimum of one-half foot of hydrated powdered Bentonite clay, and completed with a traffic-rated well vault at the surface set with neat cement concrete surface seal to match the existing grade. Care will be taken to prevent the tubing and Swagelok fittings at their ends from being damaged or kinked when coiled back into the well vaults.

#### 5.4 Soil Gas Implant Sampling

Sampling will occur at least one month after installation of the soil gas monitoring implants to allow them time for the concrete to cure and the disturbed subsurface conditions to equilibrate. In addition, soil gas sampling shall not be performed during or immediately after a rainfall event of 0.5 inches or more. If a rainfall event of this magnitude occurs within 24 hours of the scheduled soil gas sampling activities, the field work shall be rescheduled.

After setting up a secure and barricaded work area, the soil gas sampling train will be assembled. The Swagelok fitting at the end of the implant's tubing will be connected to an inline vacuum gauge with a tee then to a 100-cubic centimeter (cc) calibrated syringe with three-way valve at the tip. Coming off the tee for the sample will be a one-liter Summa canister, supplied by the laboratory under high vacuum (-30 inches Mercury, in.Hg), leak checked and batch-certified to be free of contaminants. With the valve of the soil gas monitoring implant closed and the valve to the Summa canister closed, the sampling train will be checked for leaks during a "shut-in" leak test by applying with the calibrated syringe a vacuum of -15 in.Hg for a period of five minutes (-15 in.Hg is fifty percent above the standard threshold of -10 in.Hg

considered representative of "No Flow" conditions). When the applied vacuum does not drop during the shut-in test, the sampling train assembly will be considered leak-tested tight.

After the shut-in leak test, the closed valve of the soil gas monitoring implant will be opened and the sampling train slowly purged of one calculated interior volume using the calibrated syringe. The calculated interior volume shall include the aboveground tubing and appurtenances and below-ground tubing and probe tip, but not the pore space within the filter pack. The main purpose in waiting to sample for at least one month after installation is to allow the soil gas in the fine sand filter pack to equilibrate to the soil gas in the undisturbed soil surrounding the implant location. In the tight permeability soils anticipated to be encountered at this Site, the first soil gas drawn in from outside the implant tubing will be most representative and likely contain higher concentrations than would be encountered through excessive purging.

Following the completion of purging, a clear-plastic shroud will be setup over the sampling train to contain the chemical tracer/leak-check compound (i.e. Helium gas) that will be released within. The shroud will be placed to completely cover the soil gas sampling implant wellhead, its aboveground tubing, and the tubing, fittings, and sample Summa canister that will make up the sampling train. Once setup, Helium gas will be released via tubing under the shroud. A Radiodetection Model MGD-2002 Helium detector (or equivalent) will be used to monitor the concentration within the shroud by placing its sensor probe within. Prior to and during sampling, a positive-pressure concentration of approximately 20 percent Helium will be maintained within the shroud using the compressed gas cylinder's flow regulator. Helium concentrations within the shroud will be recorded in the field notes at one-minute intervals.

Once a positive-pressure Helium atmosphere is created under the shroud, the valve to the Summa canister will be opened and the sample collected. The sampling rates into the Summa canisters will be fixed by laboratory-supplied critical orifice assemblies (i.e. mini flow regulators) with a 0.0060 inch orifice allowing approximately 200 standard cc per minute (cc/min). Samples will be collected into the Summa canisters until the vacuum has dropped from the initial laboratory-supplied vacuum of -30 in.Hg to -5 in.Hg. Sample start times, end times, starting vacuums, ending vacuums, and Helium concentrations during sampling will be recorded in the field notes.

#### 5.5 Laboratory Analysis of Soil Gas Samples

Collected samples will be submitted to a state-certified analytical laboratory under standard chain-of-custody protocol. At the laboratory, soil gas samples will be analyzed for GRO by EPA Method TO-3 and for BTEX and MTBE by EPA Method TO-15. Soil gas samples will also be analyzed for Oxygen ( $O_2$ ) and Argon, Carbon Dioxide ( $CO_2$ ), Methane ( $CH_4$ ), and Helium (tracer/leak-check compound) by Modified ASTM D-1946. Laboratory analyses for soil gas samples will be performed in accordance with EPA standard holding times for Summa canisters.

#### 6.0 INVESTIGATION REPORTING

Upon completion of field activities described above and compilation of field data, reports will be prepared and submitted to ACEH and the State GeoTracker database (including the required individual GeoTracker upload files). A *Monitoring Well Installation and Quarterly Groundwater Monitoring Event Report* will be prepared summarizing the monitoring well installation and sampling activities.

Separately, a *Vapor Intrusion Assessment Report* will be prepared summarizing installation and sampling of the soil gas monitoring implants. Each report will document fieldwork and analytical data and will include the following information:

- Scope of Work
- Lithologic boring/well construction logs (GEO\_BORE files)
- Site map showing monitoring well and soil gas implant locations (GEO\_MAP file)
- Location survey data for the wells and soil gas implants (GEO XY and GEO Z files)
- Text and tabulated investigation results (GEO\_WELL files)
- Laboratory reports and chain of custody records (EDFs)
- Significance of detected petroleum hydrocarbons
- Recommendations for future activities, if warranted

#### 7.0 PROPOSED SCHEDULE

The proposed schedule for the work described above shall proceed as follows:


- Monitoring Well Installation Monitoring well installation activities will begin immediately
  and are anticipated to be completed within 75 calendar days following approval of this work
  plan.
- Monitoring Well Installation and Initial Quarterly Sampling Event Report A summary report
  of well installation activities combined with the first round of quarterly sampling results is
  proposed to be submitted within 45 calendar days following completion of the well
  installation activities, above (i.e. within 120 calendar days of work plan approval).
- <u>Vapor Intrusion Assessment</u> Soil gas monitoring implant installation and sampling activities will begin immediately and are anticipated to be completed within 75 calendar days following approval of this work plan.
- <u>Vapor Intrusion Assessment Report</u> A summary report of soil gas monitoring implant installation and sampling activities is proposed to be submitted within 45 calendar days following completion of the soil gas implant installation activities, above (i.e., within 120 calendar days of work plan approval).


#### **8.0 LIMITATIONS**


Broadbent will do its best to alert the client of matters which, in the opinion of Broadbent, require immediate attention to protect public health, safety, and the environment. Broadbent will make every effort to advise the client of matters which should be reported to government regulatory agencies. However, the client is solely responsible for reporting such matters, and Broadbent shall not be held liable in the event that the proper agency is not notified. Our services will be performed in accordance with generally accepted practice at the time work commences. Results and recommendations will be based on review of available documentation and written or verbal correspondence with appropriate regulatory agencies, laboratory results, observations of field personnel, and the points investigated. No warranty is expressed or implied.

#### 9.0 REFERENCES

- ACEH, June 22, 2006. Fuel Leak Case No. RO0000307, ARCO #402/Parking Lot, 1450 Fruitvale Avenue, Oakland, CA. Letter from Mr. Steven Plunkett (ACEH) to Mr. Bill Puha (Fruitvale-Farnam Associates, LLC), Mr. Ken Phares (Jay Phares Corporation), and Mr. Paul Supple (BP West Coast Products, LLC).
- ACEH, December 20, 2006. Fuel Leak Case No. RO0000307, ARCO #402/Parking Lot, 1450 Fruitvale Avenue, Oakland, CA Work Plan Approval. Letter from Mr. Steven Plunkett (ACEH) to Mr. Bill Puha (Fruitvale-Farnam Associates, LLC), Mr. Ken Phares (Jay Phares Corporation).
- ACEH, October 16, 2008. Fuel Leak Case No. RO0000307 and Geotracker Global ID T06019734265, ARCO #0402, 1450 Fruitvale Avenue, Oakland, CA 94601. Letter from Mr. Paresh Khatri (ACEH) to Bill Puha (Fruitvale-Farnam Associates, LLC), Curtis & Joyce Thomas, Ken Phares (c/o Jay Phares Corporation), and Paul Supple (Atlantic Richfield Company).
- AEI Consultants, Inc., June 11, 1999. *Subsurface Investigation,* 1450 Fruitvale Avenue, Oakland, California. Prepared for Jay-Phares Corporation.
- AEI Consultants, Inc., October 11, 1999. *Phase II Subsurface Investigation,* 1450 Fruitvale Avenue, Oakland, California. Prepared for Jay-Phares Corporation, and forwarded to ACEH.
- AEI Consultants, Inc., November 22, 2000. *Monitoring Well Installation and Sampling Report,* 1450 Fruitvale Avenue, Oakland, California. Prepared for Jay-Phares Corporation, and forwarded to ACEH.
- AEI Consultants, Inc., April 5, 2002. *Quarterly Groundwater Monitoring Report,* 1450 Fruitvale Avenue, Oakland, California.
- AEI Consultants, Inc., July 5, 2002. *Groundwater Investigation Report,* 1450 Fruitvale Avenue, Oakland, California. Prepared for Fruitvale-Farnam Associates, LLP, and forwarded to ACEH and Mr. Bill Phua care of Jay-Phares Corporation.
- AEI Consultants, Inc., October 9, 2002. *Site Summary and Risk Evaluation Report,* 1450 Fruitvale Avenue, Oakland, California. Prepared for Fruitvale-Farnam Associates, LLP, and forwarded to ACEH.
- AEI Consultants, Inc., March 3, 2005. Work Plan Monitoring Well Installation, 1450 Fruitvale Avenue, Oakland, California. Prepared for Fruitvale-Farnam Associates, LLP, and forwarded to ACEH on March 7, 2005.
- Glenfos, Inc., July 27, 1998. Limited Phase I and Phase II Environmental Site Assessment, 1450 Fruitvale Avenue, Oakland, California. Prepared for Glendale Federal Bank.







#### **APPENDIX A**

Historic Soil Data

Table 1 - Soil Sample Analytical Data 1450 Fruitvale Avenue, Oakland, CA - AEI Project # 10460

Sample ID	Consul- tant	Sample Date	TPH-g mg/kg	MTBE mg/kg	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Xylenes mg/kg	Total Lead mg/kg
GP-1 10'	Glenfos	7/9/1998	10	-	<0.005	0.022	0.015	< 0.01	
GP-2 10'	Glenfos	7/9/1998	1.5	. <del>-</del>	0.017	< 0.005	< 0.005	< 0.01	•
GP-2 15'	Glenfos	7/9/1998	27	-	0.017	0.056	0.052	0.51	-
GP-2 30'	Glenfos	7/9/1998	2.5	-	< 0.005	< 0.005	< 0.005	< 0.01	•
GP-3 10'	Glenfos	7/9/1998	95	-	0.59	0.42	1.1	1.5	7.3
GP-3 15'	Glenfos	7/9/1998	2.5	-	0.055	0.018	0.055	0.26	-
GP-3 20'	Glenfos	7/9/1998	1.6	-	0.02	< 0.005	0.02	0.032	-
GP-3 25'	Glenfos	7/9/1998	<1	_	< 0.005	< 0.005	< 0.005	<0.01	-
GP-4 10'	Glenfos	7/9/1998	2.5	_	0.017	< 0.005	0.003	0.021	4.1
GP-5 10'	Glenfos	7/9/1998	6.5	-	< 0.005	0.022	0.018	0.041	-
GP-5 15'	Glenfos	7/9/1998	19	-	0.077	0.016	0.43	0.49	-
GP-5 20 <sup>t</sup>	Glenfos	7/9/1998	<1	-	< 0.005	< 0.005	< 0.005	< 0.01	-
GP-6 5'	Glenfos	7/9/1998	<1	-	< 0.005	< 0.005	< 0.005	< 0.01	-
GP-6 10'	Glenfos	7/9/1998	7.7	-	0.008	0.015	0.012	0.047	6.2
GP-6 15'	Glenfos	7/9/1998	190	-	0.34	0.53	2.3	4.7	-
GP-6 20'	Glenfos	7/9/1998	28	_	0.083	0.081	0.052	0.19	-
GP-7 10'	Glenfos	7/9/1998	86	· _	< 0.005	0.088	0.09	0.5	-
GP-7 15'	Glenfos	7/9/1998	2.7		0.008	0.012	< 0.005	0.031	-
GP-8 10'	Glenfos	7/9/1998	24	-	0.022	0.061	0.071	0.45	-
GP-8 15'	Glenfos	7/9/1998	5.8	-	0.021	0.014	0.022	0.06	•
GP-8 20'	Glenfos	8/23/1999	<1	-	< 0.005	< 0.005	< 0.005	<0.01	_
AEI-9 10'	AEI	8/23/1999	<1	< 0.05	< 0.005	< 0.005	< 0.005	< 0.005	-
AEI-9 20'	AEI	8/23/1999	<1	< 0.05	< 0.005	< 0.005	< 0.005	< 0.005	-
AEI-10 10'	AEI	8/23/1999	77	< 0.05	< 0.005	< 0.005	0.078	< 0.005	-
AEI-10 15'	AEI	8/23/1999	69	0.071	0.1	0.21	0.23	< 0.005	-
AEI-11 10'	AEI	8/23/1999	<1	< 0.05	< 0.005	< 0.005	< 0.005	< 0.005	
AEI-11 15'	AEI	8/23/1999	210	< 0.40	< 0.020	1.1	1.2	2.4	-
AEI-12 10'	AEI	8/23/1999	24	< 0.05	< 0.005	0.12	< 0.005	< 0.005	-
AEI-12 15'	AEI	8/23/1999	120	< 0.40	< 0.020	< 0.020	1.6	1.6	-
MW-1 6.5'	AEI	9/25-26/00	<1.0	<.05	<.005	<.005	<.005	<.005	-
MW-1 11.5'	AEI	9/25-26/00	15.0	<.05	<.005	0.31	<.005	0.011	-
MW-2 6.5'	AEI	9/25-26/00	<1.0	<.05	<.005	<.005	<.005	<.005	-
MW-2 11'	AEI	9/25-26/00	73.0	<.05	<.005	0.044	0.0080	0.040	-
MW-3 6.5'	AEI	9/25-26/00	<1.0	<.05	<.005	<.005	<.005	<.005	-
MW-3 16'	AEI	9/25-26/00	360.0	<1.0	0.42	2.1	6.5	11.0	-
MDL			1.0	0.05	0.005	0.005	0.005	0.005	

MDL = Method Detection Limit

mg/kg = milligrams per kilogram (ppm)

<sup>-</sup> Sample not analyzed for this chemical

TPH-g = Total petroleum hydrocarbons as gasoline

Table 1 - Soil Sample Analytical Data: Continued 1450 Fruitvale Avenue, Oakland, CA - AEI Project # 10460

Sample ID	Date	TPH-g mg/kg	MTBE mg/kg	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Xylenes mg/kg
AEI-13 10'	610-12/02	<1	<0.05	< 0.005	<0.005	<0.005	<0.005
AEI-14 10'	610-12/02	<1	<0.05	< 0.005	<0.005	<0.005	<0.005
AEI-15 10'	610-12/02	<1	< 0.05	<0.005	<0.005	<0.005	<0.005
AEI-16 10'	610-12/02	< <u>1</u>	< 0.05	<0.005	<0.005	<0.005	<0.005 <0.005
AEI-16 19'	610-12/02	41	<0.2	<0.02	<0.003	0.003	0.079
AEI-17 10'	610-12/02	<1	<0.5	< 0.005	<0.02	< 0.005	< 0.079
AEI-17 20'	610-12/02	290	< 0.05	0.84	1.3	1.8	2.8
AEI-18 4'	610-12/02	<1	< 0.05	< 0.005	<0.005	< 0.005	< 0.005
AEI-18 14'	610-12/02	290	<0.02*	<0.2	0.91	2.3	2.9
AEI-19 15'	610-12/02	<1	< 0.05	< 0.005	< 0.005	< 0.005	< 0.005
AEI-20 10'	610-12/02	<1	< 0.05	< 0.005	< 0.005	<0.005	< 0.005
AEI-20 20'	610-12/02	42	<0.5	<0.05	0.20	0.003	0.003
AEI-21 5'	610-12/02	<1	<0.05	< 0.005	< 0.005	< 0.005	
AEI-21 13'	610-12/02	12	<0.05	<0.005	0.090	0.003	<0.005 <0.005
AEI-22 10'	610-12/02	74	<0.1	0.0086	0.58	0.028	0.003
AEI-22 20'	610-12/02	5	< 0.05	0.30	0.016	0.11	
AEI-23 2.5'	9/27/2002	<1	< 0.05	< 0.005	< 0.005	< 0.005	0.42
AEI-24 2.5'	9/27/2002	<1	< 0.05	<0.005	<0.005		<0.005
AE1-25 2.5'	9/27/2002	<1	< 0.05	<0.005	<0.005	<0.005	<0.005
	2.2772002	~1	CO.02	~0.003	~0.003	<0.005	< 0.005
MDL		1.0	0.05	0.005	0.005	0.005	0.005

MDL = Method Detection Limit

mg/kg = milligrams per kilogram (ppm)

<sup>-</sup> Sample not analyzed for this chemical

TPH-g = Total petroleum hydrocarbons as gasoline

<sup>\*</sup> MTBE by EPA method 8260, all others by 602/8020

Table 5 - Sample Analtyical Data: Exploratory Excavation Project 1450 Fruitvale Avenue, Oakland, CA - AEI Project # 10460

Sample ID	Location	TPH-g mg/kg	TPH-d mg/kg	TOG mg/kg	MTBE mg/kg	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Xylenes mg/kg	Total Lead mg/kg
AEI EBA 6'	Exc. A - Bottom	<1.0	<1.0	<50.0	<0.05	<0.005	<0.005	< 0.005	<0.005	6.9
AEI EBB 6'	Exc. B - Bottom	<1.0	<1.0	<50.0	< 0.05	< 0.005	< 0.005	< 0.005	< 0.005	9.1
AEI EBW 8'	Exc. C - West	<1.0	<1.0	-	< 0.05	< 0.005	< 0.005	< 0.005	< 0.005	9.4
AEI EBE 8'	Exc. C - East	11	<1.0	-	< 0.05	< 0.005	0.059	0.028	0.042	32
AEI EBN 8'	Exc. C - North	<1.0	<1.0	-	< 0.05	< 0.005	< 0.005	< 0.005	< 0.005	8.7
AEI EBS 8'	Exc. C - South	<1.0	<1.0	_	< 0.05	< 0.005	< 0.005	< 0.005	< 0.005	80

#### **APPENDIX B**

Historic Groundwater Data

Table 2 - Groundwater Sample Analytical Data: Temporary Borings 1450 Fruitvale Avenue, Oakland, CA - AEI Project # 10460

Sample ID	Consultant	Date	TPH-g µg/L	MTBE µg/L	Benzene µg/L	Toluene μg/L	Ethyl- Benzene µg/L	Xylenes μg/L
GP 1	Glenfos	7/9/1998	170	_	0.53	<0.5	1.2	2.0
GP 4	Glenfos	7/9/1998	210	-	< 0.5	< 0.5	0.58	<1
GP 5	Glenfos	7/9/1998	17,000	-	42	24	820	110
GP 8	Glenfos	7/9/1998	20,000	<10	1,000	19	420	290
AEI GW 8'	AEI	5/27/1999	<50	<5.0	< 0.5	< 0.5	<0.5	< 0.5
AEI-9W	AEI	8/23/1999	690	3.8	72	0.79	29	24
AEI-13 W	AEI	610-12/02	<50	<5.0	<0.5	< 0.5	<0.5	<0.5
AEI-14 W	AEI	610-12/02	830	<5.0	0.56	2.7	1.2	2.9
AEI-15 W	AEI	610-12/02	<50	14*	<0.5	< 0.5	< 0.5	< 0.5
AEI-16 W	AEI	610-12/02	190	<5.0	0.86	1.0	0.75	1.3
AEI-17 W	AEI	610-12/02	1,700	<0.5*	56	2.5	89	69
AEI-18 W	AEI	610-12/02	780	<5.0	10	1.1	41	20
AEI-19 W	AEI	610-12/02	<50	<5,0	< 0.5	< 0.5	< 0.5	< 0.5
AEI-20 W	AEI	610-12/02	170	<5.0	0.81	0.55	7.7	3.1
AEI-21 W	AEI	610-12/02	2,200	2.8*	36	<5.0	110	58
AEI-22 W	AEI	610-12/02	25000	<12*	3800	290	1100	1900

MDL = Method Detection Limit

ND = Not detected above the Method Detection Limit (unless otherwise noted)

μg/L = micrograms per liter (ppb)

<sup>-</sup> Sample not analyzed for this chemical

TPH-g = Total petroleum hydrocarbons as gasoline

<sup>\*</sup> MTBE by EPA method 8260, all others by 602/8020

Table 3 - Groundwater Elevation Data 1450 Fruitvale Avenue, Oakland, CA - AEI Project # 10460

Well ID (Screen - ft bgs)	Date	Well Elevation (ft msl)	Depth to Water (ft)	Groundwater Elevation (ft msl)
MW-1	10/16/00	42.13	17.72	24.41
	1/19/01	42.13	9.15	32.98
(15-30)	4/26/01	42.13	9.40	32.73
	8/3/01	42.13	12.38	29.75
	11/5/01	42.13 42.13	16.22	25.73
			7.96	34.17
	3/29/02	42.13	7.9 <b>6</b> 12.1 <b>8</b>	29.95
	6/11/02 <b>9/16/02</b>	42.13 42.13	11.35	30.78
MW-2	10/16/00	42.08	14.98	27.10
(15-30)	1/19/01	42.08	9.00	33.08
(/	4/26/01	42.08	8.34	33.74
	8/3/01	42.08	11.70	30.38
	11/5/01	42.08	15.08	27.00
	3/29/02	42.08	8.96	33.12
	6/11/02	42.08	12.49	29.59
	9/16/02	42.08	10.52	31.56
MW-3	10/16/00	42.55	17.98	24.57
(15-30)	1/19/01	42.55	10.90	31.65
• ,	4/26/01	42.55	9.21	33.34
	8/3/01	42.55	12.67	29.88
	11/5/01	42.55	15.90	26.65
	3/29/02	42.55	9.20	33.35
	6/11/02	42.55	11.83	30.72
	9/16/02	42.55	11.42	31.13

Episode #	Date	Average Water Table (ft msl)	Change from Previous Episode	Flow direction (gradient)
1	10/16/00	25.36	<del>-</del> .	E/SE (0.116)
2	1/19/01	32.57	+7.21	E/NE (0.041)
3	4/26/01	33.27	+0.70	SE (0.034)
4	8/3/01	30.00	-3.27	ESE (0.024)
5	11/5/01	26.52	-3.48	SE (0.033)
. 6	3/29/02	33.55	+7.03	NW (0.032)
7	6/11/02	30.09	-3.46	SW (0.040)
8	9/16/02	31.16	+1.07	SE (0.028)

Notes:

All well elevations are measured from the top of the casings

ft msl = feet above mean sea level

Table 4 - Groundwater Monitoring Well Analytical Data 1450 Fruitvale Avenue, Oakland, CA - AEI Project # 10460

Well/Sample	Date	Consultant/	TPHg	MTBE	Benzene	Toluene	Ethylbenzene	Xylenes
	Collected	Lab	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L
ID		000	EPA 8015			PA method 8	. •	
MW-1	10/16/00	AEI/MAI	4.500	-20	560	1.4	53	<i>C</i> 2
IAT AA - I			4,500	<20		14	53	62
	01/19/01	AEI/MAI	13,000	<100	790	46	1,100	210
	04/26/01	AEI/MAI	7,500	<30	470	23	720	120
	08/03/01	AEI/MAI	4,500	<10	440	11	55	6.6
	11/05/01	AEI/MAI	1,700	<10	100	6.0	4.6	2.1
	03/29/02	AEI/MAI	9,500	ND<100	880	32	400	59
	06/11/02	AEI/MAI	3,400	<50	620	9.7	75	11
	09/16/02	AEI/MAI	3,800	<10	190	15.0	14	7.7
MW-2	10/16/00	AEI/MAI	4,600	<300	380	3.8	95	33
	01/19/01	AEI/MAI	4,200	<10	450	4.7	120	50
	04/26/01	AEI/MAI	5,600	<20	810	12	210	65
	08/03/01	AEI/MAI	2,900	<20	360	3	97	46
	11/05/01	AEI/MAI	2,400	<85	280	3.2	. 76	25
	03/29/02	AEI/MAI	7,100	ND<100	930	11	220	39
	06/11/02	AEI/MAI	4,400	<150	680	8.1	160	38
	09/16/02	AEI/MAI	7,400	<250	360	8.4	150	38
MW-3	10/16/00	AEI/MAI	12,000	<10	570	32	680	1,200
	01/19/01	AEI/MAI	27,000	<200	3,400	110	2,200	2,700
	04/26/01	AEI/MAI	33,000	<200	3,300	190	2,800	3,400
	08/03/01	AEI/MAI	23,000	<50	2,300	52	1,800	1,400
	11/05/01	AEI/MAI	30,000	<200	1,900	58	2,000	1,600
	03/29/02	AEI/MAI	29,000	ND<100	2,100	57	2,500	1,700
	06/11/02	AEI/MAI	22,000	<50	2,100	44	2,300	1,600
	09/16/02	AEI/MAI	25,000	<220	2,000	47	2,200	1,100
MRL			50.0	5.0	0.5	0.5	0.5	0.5

Fuel Oxygenates

Well/Sample ID	Date Collected	DIPE μg/L	ETBE µg/L	MTBE μg/L	TAME µg/L	TBA µg/L	EDB µg/L	1,2-DCA μg/L
		•		Et	PA method 82	60		
MW-1	06/11/02		_	2.4	-	-	_	_
	09/16/02	0.56	<0.5	<3.0	<0.5	<0.5	<0.5	<0.5
MW-2	06/11/02	-	_	23	-		-	_
	09/16/02	7.30	<1.2	92	<1.2	<1.2	<1.2	<1.2
MW-3	06/11/02	-	_	<2.5	-		-	•
	09/16/02	<5.0	<5.0	<5.0	<5.0	<50	<5.0	<5.0
MRL		0.5	0.5	0.5	0.5	5.0	0.5	0.5

MRL = Method Reporting Limit, unless otherwise shown

 $\mu$ g/L = micrograms per liter

AEI = AEI Consultants

MAI = McCampbell Analytical, Inc.

TPHg = total petroleum hydrocarbons as gasoline

MTBE = methyl tertiary butyl ether

150 Fruitvale Avenue Ecranento, CA 94601 -94601-061798 LENFOS, Inc.
20 TOPANGA CANYON PLACE SUITE F
PATSVORTH, CA 81311

FAIWAM STREET

FACILITY LAYOUT MAP



FIGURE 2

#### APPENDIX C

Soil Boring/Well Construction Logs and Geologic Cross-Section

					SOIL BO	RING LOG
Onlling Company	Green Dr	niliar	Station Name			
Dnilen:			Address:	1450 Fruitvale		Bonng Namber: GP-1  Oste Ontlied: Zely 9,1998
Rig Type:	Cooprebe	GII-40	City	Oakland		Deput Drilled: 12 feet
Rie Namber			Some Zin:	CA, 94601		Soring Distancer 2 lackes
Sumpling Tech: Logged By:	Bill Miller		Neurest X-St	геек: Еценини		Casing Diameter NA
cogget o7.	gar ivii(g					
DEFTR	SAMPLE	i	ILOW	GRAPING	90tL	KING DESCRIPTION
SURFACE (R.)	INTERVAL	READING (ppon)	COLNTE	LOG	CLASSIFICATION	Color, Totture, Mainten
	i I	1	<del></del>	9 201		I 1⊣nch asphail, no base
			-	13	GC	Fill-Clayey Gravel, some fine to coarse sand, light brown, moist,
<del></del>				70		ng oders
5	x -	0		49	1	
	<u> </u>	1	<u> </u>	7.4		Same, no odor
				7.5		
				67A		
10	"	_	[	7.3		
10	×	0	1	AYA		Same, soil saturated, no Hydrocarbon odor
				<b>7</b>	TO = 12 feet	
		1				
15		<del> </del>	ļ		] .	
<del></del>						
					1	
. 20		1				
<del></del>						
<del></del>					···. ·	·
			ļ. <b>1</b>			
25		<u> </u>	-		}	•
-						
						• .
		[ "	<u>.</u>	ŀ		•
30						
						•
			i		1	}
35		<u> </u>		1	[	İ
<del></del> [						
_					j	
_				İ	1	
40						
		1	1			
<u> </u>			1			···
_			. [			
45						
	1		1	1		
_	1		1	ļ	1	
_ ·	1	ĺ		ļ	İ	
50				Ì	1	
_		1		1	1	
- 1			1			Note: Collegiad groupduster comple CT 4 Constant
				1		Note: Collected groundwater sample GP-1. Groundwater appears clean, and perched in the UST tank pit.
55						
LIENT NAME:		Giendale Fed			GLENFOS, IN	
MAN TOBLOF ROJECT NUM		1450 Fruitval			Global Environm	
COSECT NUM	er: ]	P1/P2-94601	-051/98		9620 Topanga C	
					Chaisworth, CA	¥1317

					SOIL BO	RING LOG
	_					
Drilling Company:	Greek Dull	yell	Station Nam	e:		Sonny Number: GF-I
Dnil <del>as</del> :			Address:	1450 Francis /	A Produce	Date Dritted: July 9,1998
Rig Type:	Geogrape	CHAO	City.	Cabland		Depth Drillet: 34 feet
Lig Number			State Zip:	CA 94601		Boring Diameter I lecker
sampling Tech.:	Hydrantie		Nearest X-St	rem: Paream 54	re <del>ct</del>	Cuing Diameer NA
Logged By:	all Milene	eü				and addition to
מנדודו .	SWITLE	] QVA	NO.	GRAPRIC	\$OiL	
BET'OM	LYTERVAL	READING	COLORES	LOG	CLASSIFICATION	MIL DESCRIPTION
SERFACE IN		1 pperah	1			Coder, Ferture, Maisrape
	i			Irmi	T	1- inch asphait, no base.
	i	l		1 11111	ML	Clayey silt, greyish brown, moist, no Hydrocarbon odor
			1			and a superior of the superior
		1				
5	X	<u> </u>		1 13 1 1 1 1		Same as above, moist, no Hydrocarbon odor
				1 11111111	1	Series as above, moist, no riyorocarour odor
				1 11111		
					1	
10	x	0	1		1	Comp. Autori attache at da da anno a con a
_		······································		f (111111		Same, except streams of dark grey, and a slight odor.
			1			
<del>-</del>				<del>                                    </del>		
- 1				1//	1	
15	x		1	1 1//		
	_^-		·	1//	1 i	
- '				1//		Silty day, dark brown to grey, moist, slight to moderate Hydrocarbon odor
-	1	ļ		1999	1 1	
		Î		1//	]	
	1			1//	<b>!</b> [	
20				1//	}	
- "		1			CL	
		i		355	ŀ	
	- 1	. 1	i			
}	- 1	1	1	1//	1	
25				1//2		•
_ 1						•
	1	1	J		f	
		1	ł		1	
	- 1					
30	x i	0	1		TD = 30 feet	Carrie no Undescribes ander
				V.C.	100000	Same - no Hydrocarbon odor
-	I	I				
	1	ı		[	1	
-	1				1	
35	l	1	j		1	
	<del></del>				1	
-	1	1	1	ļ		
-	1	-	- 1	}		
- 1			i	ł	Į	
40				ı	1	•
⁴∪	<del></del>			j	1	ł
-		1	1	ĺ	1	
-	1				1	l
_	l	1	1	ļ		
_	1	1	i	l		
45				ſ		
. 「				ł		
_ 1	- 1	[	1	1	-	
_		1	. !	Ī	1	İ
- 1	j		1			
50		1	- 1	1	J	
— ·-	<del></del>			}	1	1
-	ł		1	1	ì	
- 1	-	-	1	1		
•	- 1	1	1	.		Notes: Groundwater not encountered.
- 55			1	ļ	_	
ENT NAME:	G	iendale Fedi	eral Bank	1	GLENFOS, IN	C.
JECT NAME		150 Fruitvale	:		Giobal Environme	
JECT NUMB		1/P2-94601-			620 Topanga C	anno Alsos
					Chatsworth CA	

			-		SOIL BOR	RING LOG
Dalling Company	Carre Beil		Station Name			District Co.
Drillers:	Crest Dell		Address:	1450 Prester	ia	Boring Number: GP-3 One Onited: July 9,1994
Rig Type:	Great obt (	3H-40	City:	Oskissa		Deput Deilind: 10 feet
Rig Number			State Zip:	CA 94661		Boring Distretor 1 Inches
Sampling Tech.	Hydrautic		Newsa X-Su	CEE CHART AVE	111	Cusine Diameter NA
Logged By:	Bill Mitche	, W				
DEFTR	SAMPLE	QVA	No-	GRAPHIC	401L	SOIL DESCRIPTION
SELOW	INTERVAL	READUNG	COUNTS	LOG	CLASSIFICATION	Color, Travers, Maistern
SURFACEIRS	<u> </u>	(pq-=1				
						1- inch asphalt no base
<b></b>	l					
<del> </del>						
<u> </u>	х	0	•			Clayey silt, greenish brown, moist, no Hydrocarbon odor
			<u> </u>			
				1111		
<u></u>						
10	x	210				Same, moist no Hydrocarbon odor.
·*	<del>  ^</del>	1 214	<u> </u>		ML	Satire, moist no prycepta act.
			}	1111		
	1					
15	X	2	1			Same, moist, slight to moderate Hydrocarbon odor
	ł					
<del>-</del>			{			
				ШШ		
20	X	39				Same, moderate Hydrocarbon odor
<del> </del>			}			
<del> </del>	1	÷-;+- *				·
_	1	14.9				,
25	X	1				Sandy Gravel, some clay, light brown, moist, no Hydrocarbon odor.
					GP	
<b></b>				3.04	TD = 28 feet	
30					·	·
						· ·
<b></b>						
<del></del>						
35						
<del></del>	1		, ·			
<del></del>						
40						
45					,	
50						
~~~~		·				
						No.
55						Note: Groundwater not encoutered
CLIENT NAME	<u></u> E:	Glendale F	deral Bank		GLENFOS, I	NC.
PROJECT NA		1450 Fruity			Giobal Environ	
PROJECT NU		P1/P2-9460			9620 Topanga	

ı

			SOIL BORING LOG									
Drilling Company:	Gregg Ori	liet	Station Name	t.		Brian Number CB 4 TV						
Drillen:			Address.	1450 Franvale A	YEMRA	Boring Humbur: GP-4 (2) Date Drilles: July 9, 1998						
Rig Type:	Geograbe	G11-44	City.	Oakland		Depth Onlint: 18 feet						
Rig Number				CA. 94601		Soring Ciameter 1 inches						
Sampling Tech.:	Hydrasite		Newen X-St	rect: Farmans		Caring Diameter MA						
Logged By:	Bill Milchi	24			,							
OEFTI	SWITLE	DVA	Now	GRAFING	501L	SOIL DESCRIPTION						
serom	LYTERVAL	READING	COUNTS	Loc	CLASSIFICATION	Color, Testura, Measture						
(よりきりふもに)2		-										
	x	a				Inch asphalt, no base.     Fill- Clayey Gravel, some fine to coarse sand, light brown, most, no Hydrocarbon odor.  Same, moist, no Hydrocarbon odor.						
10	x	468		50	GC	Sandy Siit, some gravet, light brown with streaks,of						
					ML TO = 12 feet	greenish grey, strang Hydrocarbon odor						
20												
25					·							
30			·									
35					·							
40												
45												
50												
55						Note: Groundwater collected at a depth of 10 feet. Obtained sample G2-4 Groundwater had no Hydrocarbon odor and appears to have been perched UST pit.						
LIENT NAME		Glendale Fe			GLENFOS, IN	IC.						
ROJECT NAM		1450 Fruitva			Global Environmental Focus							
ROJECT NUM	BER:	P1/P2-9460	1-061798									
				***************************************	9620 Topanga Canyon Place							

					SOIL BOR	RING LOG
Seilling Company	Creek Du	illag	Station Name:			Bonne Number C7-1
Drillers:			Address:	1450 Praire	aie .	Date District: July 9, 1948
tie Type:	Geogrape	G11-40	Cily:	Onkland		Deput Drilled. 11 feet
lig Number			State, Zip:	CA 94601		Boring Diameter 1 lockes
Sampling Tech.:	liviralie		Newest X-Street	t: Farans		Caping Diameter NA
Logged By:	Siil Milch	eü	,			
DEPTH	SAMPLE	GYA	l atow	GRAPHIC	SOIL	NOIL DESCRIPTION
BELOW	ENTERVAL	READING	COLPITS	LOG	CLASSIFICATION	Color, Tettoris, Mundaro
SURFACE IO.		(Secol	<u> </u>			
	l	i	T	7777		t Hoch asphalt, no base
		1			ì	Clayey silt, greyish brown, moist, no Hydrocarbon odor
				11111		
		ì	1 1	11111		•
, 5	Х	1		111111		
				11111	ML	Same, moist, no Hydrocarbon odor.
			1 1	ППП		
				111111		
	1					
10	x	1	<u>1</u>			
		1				
	1	1		ШШ		Clayey sill, greyish brown to grey, with black streaks, moist
	1	1		977		moderate Hydrocarbon odor.
_	1	1	1	1//	]	·
15	×	1	1	(//)	1	
				777	CL	
	1				1	•
	]	ļ			1	Silty clay, dark brown to grey, moist
	}	1		ITM		moderate Hydrocarbon odor.
20	х	1	1 1		ML	
	1	1			1 1	
<del></del>	1	j		11111	TD = 22 feet	Clayey silt, some fine gravel, greyish brown with black streaks, moist
		1	1 1			slight Hydrocarbon odor.
		1	1		1	
25		1	1 1			•
		í	1		}	
	ł		1			
	[		1 1			
		I	1			
30		1	1 1			
		1	;			
		i	1			
		1				
		1	1 1			
35		I				
		<del> </del>	†			
	1					
			1			
		1				
40		1				
		<del> </del>	<del>                                     </del>			
		1			,	
<del></del>		1			į l	
<del></del> .					}	
45		1				
		<del>}</del>	<del>  </del>		.	
		1	1		]	
			1		]	
<del></del>					1	
50		1	1		1	
	-	<del> </del>	<del>                                     </del>		]	
			1		į l	
					1	
		"			ļ	
55		1				•
CLIENT NAME	<u></u>	Classia 5	adaes) Basi:		GLENFOS, I	NC .
PROJECT NAME			ederal Bank			
		1450 Fruity			Global Environ	
PROJECT NU	MBER:	P1/P2-946	91		9620 Topanga	
					Chatsworth, CA	A 91311

					SOIL BO	RING LOG				
1										
Orithing Company	: Greet Dr	-illag	Station Name	<del></del>		Baring Mumber: CP-4				
Dollers:			Address	1450 Fraity	rie	Date Dailed: July 9,1998				
Rig Type:	Geoprebe	CH-44	City Onbland			Cepus Drillat: 11 feet				
Rie Number			Suie Zia:	CA 94401		Borne Diseases 1 lackes				
Sampling Total:	Hydraello		Neurost X-Su	ren: Farman		Cassing Diameter MA				
Logged By:	8# Mita	æ								
PEFTR	SWOLE	OVA	MOW	GRAFFIC	3OIL					
BELOW	INTERVAL	. AEADING	COUNTY	LOG	CLASSIFICATION	ROIL DESCRIPTION Color, Tottons, Maintene				
SURFACEIAI	<u> </u>	(7640)	ļ <u></u>			Cont. I strong, Manage				
<u></u>		1			1	1-inch aspnait, no base				
	1		1			Clayey silt-greyish brown, moist, no Hydrocarbon odor				
			1	:						
<u> </u>				:	ML	·				
5	×	0	<del> </del>			Same, moist, no Hydrocarbon odor				
<del></del>	1			<del>                                      </del>						
		1	1							
		1								
10	X	15	]		1	Clayey silt, greyish brown with black streaks, moist, moderate Hydrocarbon				
						Service and the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second				
		1		ШШ	L					
<u>_</u>										
15		l				·				
13		14			CL	Silty Clay, dark brown to grey, moist, moderate Hydrocarbon odor				
		1								
	l			24						
. 20	X	1			GP	Clayey silt, some fine gravel, greyish brown with				
					<b>J</b> .	black streaks, moist, slight Hydrocarbon odor				
		1			TO = 22 feet	and an end, many and a character of the				
i			1	1 11	· · · · · · · · · · · · · · · ·	-				
				-						
25				Ì						
			i	ļ						
				Ì						
					İ					
30			1							
			1		- 1					
			-		1					
				1	.					
35				1						
			-	.		•				
				ļ						
· ·	.		1	İ	1					
40		}			1					
	<del></del> i	<del></del>			1					
		1	1	1	ł	ł				
	1	- ]	.			1				
_	ļ	1				İ				
45		[		1						
_	1	1		İ	İ					
!	ļ									
	ļ	1		1						
- 50	- 1			1						
~¦				1	1	No. 20 de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya de la companya				
	İ	i			1	Notes: Groundwater encountered at 20 feet, rose to 9 feet in 10 minuteS.				
<del></del>		1	1	1	1	Collected sample GP-4. Strong Hydrocarbon odor, and a petroleum sheen				
_	- 1	1		1	1	observed.				
55				1	į					
LIENT NAME:		Glendale Fed	leral Bank		GLENFOS, IN	ic.				
ROJECT NAM	E: 7	450 Fruitval			Global Environm					
ROJECT NUM		1/P2-94601			9620 Topanga C					
	-				Chatsworth Ca					

					SOIL BOR	ING LOG					
Oniting Company	Greek Dott	ing	Susion Name:	:		Bonng Nuraber: CP-7					
Onitions:			Address:	1450 Fraites	je	Date Drilled: Joly 9,1998 .					
Rig Type: Groupeabe GH-40		City:	Osklade		Depth Dallock 21 feet						
Rig Number			State Zip:	CX 94401		Soring Diameter 2 Inches					
Sampling Tech.	Rydraulic I		Nearest X-Sur	ect: Farnam		Casing Diameter NA					
Logged By:	Bill Milche	-8									
DEFTI	MALE	OYA	N.OW	GENTHIC	301 <b>L</b>	SOIL DESCRIPTION					
15TO-A	LYTERYAL	READING	COUNTE	roc	CLASSIFICATION	Color, Tottera, Malabara					
TURE SOLUTION	<del> </del>	(Lives)		71111		t-inch asphalt, no base					
				11111	ML	Clayey sitt, greyish brown, moist, no Hydrocarbon odor					
<del></del>				4 1		Oldjej sti, grejizit statiti, tibeti na vijetasisti tati					
<del>-</del>				11111							
5	X	100			,	,					
						Same, moist, strong Hydrocarbon odor					
<del></del>											
: 10	×	323				Sandy silt, some gravel, light brown with streaks of					
	<u> </u>		i		ML	greenish grey, moist, strong Hydrocarbon odor					
			1								
	1										
15	×	25	ļ ·		TD = 15 feet	Silty Clay, dark brown to grey, moist, moderate Hydrocarbon odor					
				dillo	10 = 10 (65)						
			1								
·		1									
. 20		136				Sandy gravel, some day, light brown, moist, moderate Hydrocaroon odor					
	-										
zs											
			<del> </del>								
			Ì								
						· ·					
30		<u> </u>									
					1						
35											
		Ī	1								
<u></u>			1								
<u> </u>		}		1							
	-	<del> </del>	<del> </del>	1		·					
<del></del>											
		İ			ļ l						
	1				<b>j</b>						
45			<u> </u>								
			1								
<u></u>			1	-							
<b>_</b>		1	1		1						
50	1	1			]	·					
<del>                                     </del>		<del> </del>	<del>†</del>	1	1						
<b> </b>	1				{	note; Groundwater not encountered					
		1		ł	1						
		1			1						
55		1	1	<u> </u>	A. 41:454						
CLIENT NAM			ederal Bani	<u> </u>	GLENFOS, I						
PROJECT NA		1450 Fruit			Global Environ 9520 Topanga						
PROJECT N	meen:	P11FZ-946	01-001198								
1					Chatsworth, CA 91311						

Online C-		Gergg Drill		Francis 11			
Daller.	mpany	CAME DAIL	<u> </u>	Station Name:			Boring Number: G7-4
tig Type:		Geoprebe G	H-10	City	1450 Frant Oakland	THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE STATE OF THE S	Our Orilled: July 1,1998
Rig Number	,			State, Zip:	CA 24601		Depth Drilled: 16 feet
Sampling T	۳th.:	Hydraslie ?	116	Newest X-Sur		***************************************	Boring Diameter 11sches Causey Diameter NA
Logged B	у <del>.</del>	Bill Milchel	1				Catal Diagram 194
DEFT	ıí	SAMPLE	OVA	ELOW	GRAPRIC	501L	THE DESCRIPTION
321,01		INTERVAL	READING	COUNTE	Loc	CLASSINCATION	SOIL DESCRIPTION Color, Tentura, Makasara
SUTURACE	(0,)	<u> </u>	(pp.m)				
		i 1		T	11111		0.5 inch concrete, no base
						ML	Clayey silt, grayish brown, moist, no Hydrocarbon odor
					:[]]]	1	,
	,	.	_			1	
	5	X		<u> </u>	ПП		
				]			Same, moist, slight Hydrocarbon odor
						1	
	10		45		<del>//////</del>		
	10	X	85		11111	ML	Sandy sill, some gravel, light brown with streaks of grey,
					41111	}	strong Hydrocaroon odor
					11111	1	•
					++++		
	15	x	36	·		1	
		<del>- '                                   </del>	ادب			1	Same, moist, slight to moderate Hydrocarbon odgr
			i	-		!	
_				ĺ	11111		·
	Í	1			1144	<del></del>	
	20	×				-	
		1				GP	
-	1	Ì	Ì			TO = 22 feet	
			į		- 9:0 0	10 - 22 1661	
_	.		1	l			
-	25	1		J			
	Ī						
_	- 1		1	1			
_	l		1				•
_			1				
_	30						
_	Γ						
		1	1				•
	- 1			-			
			1			ļ.	
	35					-	
	Π						
_	- 1		ł	1			
			1			1	
_			1			- 1	
	40				İ	1	
	- 1	1		-	Į	1	
	-	1			1		
_	}	1			1		
_		1			İ	1	
	45				j	1	
<del></del>	- 1			1		1	
-			}				
-			1	1	1	Į	
	50	1	- 1	l	l		
	~" <del> </del> ⊢	<del></del> -				1	
-	1	1	İ	-		Ì	
		1		-	-		
<b>-</b> .	1	İ		.	1		
-	55				1	ļ	Note: Groundwater not encountered
ENT NA		G	endale Fed	eral Bank		GLENFOS, IN	
DJECT !			50 Fruitvale Avenue			Giobal Environm	ental Focus
UJECT!	NUME	SER: Pt	/P2-94601-	061798		9620 Topança C	ativon Place

Project No: 3397

Project Name: FRUITVALE

Log of Borehole: AEI-9

Client: JAY-PHARES CORP

Location: WESTERN CORNER

				Sampl	e Data			
Depth	Soil Symbol	Subsurface Description	Sample Label	Туре	Blow Counts/	Recovery	Well Data	Remarks
0 t m	2000	Ground Surface				1		<u> </u>
1 -		ASPHALT	-					
2 - 1 3 - 1 4 - 1		CLAY Silty and sandy clay						
5			AEI-9 5'	SS		100		No hydrocarbon odor
6- 2								
7								
10-3		Sandy clay with gravel	AEI-9 10'	ss		100		No hydrocarbon odor
11		up to 2 cm		-				
12_								
13 - 4							▼.	Groundwater after 15 min.
15		Stiff silty clay	AEI-9 15'	SS		45		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
16-1-5								No hydrocarbon odor
17- 18								
19-								
20 - 6	೪೭೦೦		AEI-9 20'	ss		80		Strong hydrocarbon odor
21_	ۯۮؽ							_ ,
22	ర్మంగ్రా							
23 7	,OO;	GRAVEL						
25_	0000	Coarse sandy gravel up to 3 cm, clast supported						
26 _ 8	.00%							
27.	200			!				
28	$_{0}O_{0}$			:				
30-9								No hydrocarbon odor
31		CLAY Silty clay with gravel up to 2.5 cm	AEI-9 30'	SS		90		Groundwater initially observed
32 - 10			:	-			i	Groundwater initially observed
33 - 10		End of Borehole						
35 -								
36-								
			<u> </u>					I

Drill Date 9/28/99

Drill Method: DIRECT PUSH

Total Depth: 32 ft. Depth to Water: 14 ft. Reviewed by: JPD

Logged by: PJM

AEI Consultants 901 Moraga Road, Suite C Lafayette, CA 94549 (800) 801-3224

Sheet: 1 of 1

Sheet: 1 of 1

Project No: 3397

Project Name: FRUITVALE

Log of Borehole: AEI-10

Client: JAY-PHARES CORP

Location: SOUTHERN PORTION, NEAREST EXCAVATION

		A Maria Company	3	ampl	e Data		Well Data	Remarks
Depth	Soil Symbol	Subsurface Description	Sample Label	Туре	Blow Counts/	Recovery		
oft m	)	Ground Surface						7-14
1_		CONCRETE						
3 - 1 4 - 1	·	CLAY Silty clay, moderately plastic						
5			AEI-10 5'	ss		100		Moderate hydrocarbon odor
6 - 2 7 - 2 8 - 2 9 - 3								
10 - 3		Stiff silty clay with fine sand	AEI-10 10'	SS	-	100		Moderate hydrocarbon odor
12-	1							
14- 15-			AEI-10 15'	ss		100		
16- 17-	5		ALFOR			100		Mild hydrocarbon odor
18 19-								
20 - 6		Sandy clay, damp	AEI-10 20'	SS		100	: -	No hydrocarbon odor
22-	7							.*
24 - 25 26 - 8			AEI-10 25'	SS		50		No hydrocarbon odor
26							:	
29-	9 <i>//////</i>					100	-	No booker or deep on a deep
30 31		Stiff silty clay	AEI-10 30'	∵SS ↓——		100		No hydrocarbon odor
32	10	,						No groundwater generation
34		End of Borehole						
35-								
36-		1		<u></u>		1		

Drill Date 9/28/99

Drill Method: DIRECT PUSH

Total Depth: 33 ft.
Depth to Water: NA

Reviewed by: JPD

Logged by: PJM

AEI Consultants 901 Moraga Road, Suite C Lafayette, CA 94549 (800) 801-3224

Project Name: FRUITVALE

Log of Borehole: AEI-11

Client: JAY-PHARES CORP

Location: SOUTH EAST OF FORMER DISPENSERS

			S	ampl	e Data			
Depth	Soil Symbol	Subsurface Description	Sample Label	Туре	Blow Counts/	Recovery	Well Data	Remarks
0 + 0	XXX	Ground Surface ASPHALT						
1	<b>}</b>	CLAY	į					
2 - 1 3 - 1 4 - 1		Silty clay, moderately plastic						
5		Gravel present at 5%	AEI-11 5'	ss		60		No hydrocarbon odor
7 - 2 8 9 -				3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
10 - 3		Stiff silty clay	AEI-11 10'	ss		100		No hydrocarbon odor
12 4 13 4						-		
15   16   5			AEI-11 15'	SS		100		Strong hydrocarbon odor
17 18 19								·
20 – 6 21 –			AEI-11 20'	SS		5		No sample recovery
22 - 23 - 7 24 -		Califf according house because the second						
25- 25- 26- 8		Stiff sandy clay, locally damp					,	
27 - 28 -							!	
29 9			AEI-11 30'	ÇC		20		No hydrocarbon odor
31-			AEI-1130	SS		20		Not sufficient soil collected
32_								No groundwater generation
33 - 10		End of Borehole	-					
34		Fud of Rolevois				!		
35_ 36_	1					1		
30-						<u> </u>		

Drill Date 9/28/99

Drill Method: DIRECT PUSH

Total Depth: 33 ft. Depth to Water: NA Reviewed by: JPD

Logged by: PJM

AEI Consultants 901 Moraga Road, Suite C Lafayette, CA 94549 (800) 801-3224

Project Name: FRUITVALE

Log of Borehole: AEI-12

Client: JAY-PHARES CORP

Location: NORTH OF FORMER DISPENSERS

				Samp	le Data			
Depth	Soil Symbol	Subsurface Description	Sample Label	Туре	Blow Counts/	Recovery	Well Data	Remarks
oft m	XXXX	Ground Surface CONCRETE						
1-		CLAY						
2 - 1 3 - 1 4 - 1		Stiff clay with minor sand						
5			AEI-12 5'	ss		60		No hydrocarbon odor
7 - 2								
9- 10-3 11-		Sandy clay w/ coarse gravel up to 2.5 cm, unconsolidated	AEI-12 10'	SS		90		Mild hydrocarbon odor
12-		up to 2.0 om, unochoolidated						
14 <u> </u> 15 <u> </u> 16 <u> </u>		Stiff silty clay, dry	AEI-12 15'	SS		85		
17 5								Moderate hydrocarbon odor
19_20 - 6			AEI-12 20'	SS		15		No sample recovery
21— 22— 23—7		Silty clay						
24 <u> </u>								
26 — 8 27 — 28 — -			-	'				
29 9								Groundwater sample exposed
31 <u> </u>								between 30 and 34 feet bgs. No groundwater generation
33 10 34								
35_		End of Borehole						
36								

Drill Date 9/28/99

Drill Method: DIRECT PUSH

Total Depth: 34 ft. Depth to Water: NA Reviewed by: JPD

Logged by: PJM

AEI Consultants 901 Moraga Road, Suite C Lafayette, CA 94549 (800) 801-3224

Project Name: Fruitvale

Log of Borehole: SB-13

Client: PHUA

Location: Oakland, CA

	USC	os		Sa	mple	Data			
Depth	Symbol	Label	Subsurface Description	Sample Label	Туре	Blow/ft	Recovery	Well Data	Remarks
0-			Ground Surface						
2- 4-	<i>Conur</i>		Hand Auger Black, earthy soils						Slight HC odor
6-			0/	AEI-13 5'	SS				PID <1 ppm
8-			Clay Sandy, grey color						FID < I ppin
_									
10-			Clay	AEI-13 10'	SS				Slight HC odor
12-			Firm clay, less sand, redish/grey						
'-			mottled appearance						PID <1 ppm
14-			Clay					¥	,
16-			Stiff, tan color, very few sands	AEI-13 15'	SS		***************************************	•	
18			<i>Clay</i> Gravelly, sandy						PID <1 ppm
20-				AEI-13 20'	SS				
22-									
24-			Clay						PID <1 ppm
26-			Stiff, tan color, 10-20 % sands	AEI-25'	SS				
					•				
28-			Sand						Slight HC odor
30-			Silty w/ lots of gravels						
_			End of Borehole	AEI-13 30'	SS		** ********		
32-									
34-									
-									

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 30 Depth to Water: 14.5 Reviewed by:

Logged by: AW

AEI Consultants 3210 Old Tunnel Road, Suite B Lafayette, CA 94549 (925) 283-6000

Sheet: 1 of 1

Project Name: Fruitvale

Log of Borehole: SB-14

Client: PHUA

Location: Oakland, CA

		20		Sai	nple	Data			
Depth	Symbol	Label	Subsurface Description	Sample Label	Туре	Blow/ft	Recovery	Well Data	Remarks
0-			Ground Surface						
2-	-		Hand Auger Black, earthy soils	·					
6- 8-			Clay Sandy, brown color Clay						
10-			Stiff, olive green color, some	AEI-14 10'	SS		-		PID 2 ppm
12- 14-			gravels  Clay  Firm, very sandy, green/brown mottled appearance						Slight HC odor
16-			Clay Stiff, olive green color	AEI-14 15'	SS				PID 1 ppm
18- 20- 22- 24-			<i>Clay</i> Gravelly, 30% gravels, olive color	AEI-14 20'	SS				Slight HC odor PID 4 ppm No HC odor
	-			AEI-14 25'	SS				10 110 000
26-	_		Clay Soft, very wet, tan color				,		
30- 32- 34-			Sand Clayey w/ some gravels, wet and dry layers	AEI-14 30'	SS			<b>Y</b>	

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 35 Depth to Water: 32 Reviewed by:

Logged by: AW

Project Name: Fruitvale

Log of Borehole: SB-15

Client: PHUA

Location: Oakland, CA

	US	cs		Sa	mple	Data			4.5
Depth	Symbol	Label	Subsurface Description	Sample Label	Туре	Blow/ft	Recovery	Well Data	Remarks
0-			Ground Surface						
2- - 4-	,		Sand Clayey, some gravels, black color						No HC odor
- 6-				AEI-15 5'	SS				PID <1ppm
- 8 -			Clay Very sandy, some gravels, tan color						
10-				AEI-15 10'	SS				
12- - 14-			Clay Gravelly, black color						
16-			Sand Black color, gravelly	AEI-15 15'	SS				PID <1 ppm
18-				AEI-15 18'	SS				No HC odor
20- - 22-			Clay Dry, sandy, gravelly, brown color			-			PID <1 ppm
24-				AEI-15 24'	SS			*	No HC odor
26-	00° 00° 00°		Gravel  Mixed with firm brown clays and						
28-	:0S		some sands						
30-			End of Borehole	AEI-15 30'	SS				
32-						Ţ			
34-									
24									

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 30 Depth to Water: 23 Reviewed by:

Logged by: AW

AEI Consultants 3210 Old Tunnel Road, Suite B Lafayette, CA 94549 (925) 283-6000

Project Name: Fruitvale

Log of Borehole: SB-16

Client: PHUA

Location: Oakland, CA

	USC	cs		Sa	mple	Data			
Depth	Symbol	Label	Subsurface Description	Sample	Type	Blow/ft	Recovery	Well Data	Remarks
0-	2200000		Ground Surface						
2-			Clay Stiff, gravelly 10-20%, black						No HC odor
6-				AEI-16 5'	SS				PID <1ppm
8- - 10-			Clay						
12-			Firm, gravel 50%, brown color	AEI-16 10'	SS				
14-									PID <1 ppm
16-			Clay	AEI-16 15'	SS				HC odor
18-			Stiff, tan color  Clay						PID 309 ppm
20-			Stiff, olive green color, minor gravels	AEI-16 19'	SS				т 10 308 ррпі
22 - 24-			Clay Stiff, sandy, brownish/green mottled color						PID 17 ppm
-			Clay	AEI-16 25'	SS				
26-			Gravelly, sandy, wet					,	
28-			Clay  Mottled grey/green/bron appearance, gravelly, wet					*	
30- 32-			End of Borehole						
34-						,			·
_			,						

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 30 Depth to Water: 28 Reviewed by:

Logged by: AW

Project Name: Fruitvale

Log of Borehole: SB-17

Client: PHUA

Location: Oakland, CA

	USC	os.		Sa	mple	Data			
Depth	Symbol	Label	Subsurface Description	Sample Label	Type	Blow/ft	Recovery	Well Data	Remarks
0-	***************************************		Ground Surface						A LI Market Line Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Control of the Cont
2-			Soil Firm, clayey, black color		:				
4- 6- 8-			Clay Firm, green color, some gravels and sands 20-30%						No HC odor
10-				AEI-17 10'	SS				
12-			Sand Brown, gravelly, some clay						No HC odor
14-									
16-				AEI-17 15'	SS				Strong HC odor
18-			Clay Stiff, olive green color, minor						
20-			gravels	AEI-17 20'	SS				Slight HC odor
22								<b>x</b>	
-				AEL 47.05'	00				
26-				AEI-17 25'	SS			1	
28-			Clay Stiff, green color						
30-				151 17 551	-				Strong HC odor
32-			Clay Stiff. green	AEI-17 30'	SS				
34-			Clay Tan, saturated						

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 35 Depth to Water: 23.5 Reviewed by:

Logged by: AW

AEI Consultants 3210 Old Tunnel Road, Suite B Lafayette, CA 94549 (925) 283-6000

Sheet: 1 of 1

Project Name: Fruitvale

Log of Borehole: SB-18

Client: PHUA

Location: Oakland, CA

	US	CS		Sa	mple	Data	***************************************		
Depth.	Symbol	Label	Subsurface Description	Sample	Туре	Blow/ft	Recovery	Well Data	Remarks
0-			Ground Surface						
2-			Soil Firm, black color, 20% gravels						PID 112 ppm
7	W.			AEI-18 4'	SS				CID FIZ ppin
6- 8-			Clay Stiff, brownish, 20% sand						Slight HC odor
10									Strong HC odor
-				AEI-18 10'	SS				
12 -			Clay Stiff, green color						PID 112 ppm
14-				AEI-18 14'	SS				
40			O. C.	,					PID 181 ppm
16- - 18-		٠	Clay Stiff, 40% sand and gravels, olive green/orange mottled appearance						Slight HC odor
20-									PID 46 ppm
22- 24-			<i>Clay</i> Firm, brownish color, slightly wet			-			Strong HC odor
-				AEI-18 25'	SS			T.	
26			Clay						
28			Stiff. green						
30			Isolated lens						PID <1 ppm
30-				AEI-18 30'	SS				LID <1 bbill
32-			<i>Clay</i> Stlff, brown, 40% gravels						
34-			Outi, brown, 40% gravers						

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 35 Depth to Water: 25.3 Reviewed by:

Logged by: AW

Project Name: Fruitvale

Log of Borehole: SB-19

Client: PHUA

Location: Oakland, CA

	USC	os		Sa	mple	Data			
Depth	Symbol	Labe	Subsurface Description	Sample Label	Туре	Blow/ft	Recovery	Well Data	Remarks
0-			Ground Surface						
2- 4-			Soil Firm, black color, 20% gravels						
6- 8- 10- 12- 14-			<i>Clay</i> Stiff, brownish, 20% gravels	AEI-19 10'	SS				No HC odor PID <1 ppm
14- 16- 18- 20-			<i>Clay</i> Stiff, green color, fine grained	AEI-19 15'				_	PID <1 ppm  HC odor  PID 9 ppm
22- 22- - 24-			Clay	AEI-19 20'	SS			<b>y</b> .	PID 3 ppm
-			Firm, brown, 20% gravels	AEI-19 25'	SS				
26- 28- 30- 32- 34-			End of Borehole	AEI-19 25	22			·	

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 25 Depth to Water: 20.5 Reviewed by:

Logged by: AW

Log of Borehole: SB-20

Sheet: 1 of 1

Project Name: Fruitvale

Client: PHUA

Location: Oakland, CA

	USC	os		Sa	mple	Data			
Depth	Symbol	Label	Subsurface Description	Sample Label	Туре	Blow/ft	Recovery	Well Data	Remarks
0-			Ground Surface						
2 4			<i>Soil</i> Firm, black color, sandy						
6-				AEI-20 5'	SS				
-									PID <1 ppm
8- - 10-			<i>Clay</i> Soft, brown, 30% sand	AEI-20 10'	SS				PID 2 ppm
12-									
-									Slight HC odor
14- - 16			Clay Stiff, green color	AEI-20 15'	SS				PID 4 ppm
18-			Clay Firm, brown, 30% sand						HC odor
20-			Clay Stiff, green color, 40% gravels	AEI-20 20'	SS				PID 12 ppm
22-								<b>T</b>	
24									HC odor
26-			Clay	AEI-20 25'	SS				PID 13 ppm
- 28-			Stiff, green/grey color w/ some orange sands						
30									PID 8 ppm
32-	STATE !								Slight HC odor
34			<i>Sand</i> Firm, wet, clayey	AEI-20 33'	SS				

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 35 Depth to Water: 22 Reviewed by:

Logged by: AW

Project Name: Fruitvale

Log of Borehole: SB-21

Client: PHUA

Location: Oakland, CA

Subsurface Description  Ground Surface  Soll Firm, black color, 30% sand  AEI-21 5' SS S Strong HC odor  AEI-21 13' SS STRONG Gravels  Stiff, clive green color, 5% sands  AEI-21 15' SS STRONG HC odor  AEI-21 15' SS STRONG HC odor  AEI-21 15' SS STRONG HC odor  PID 239 ppm  AEI-21 15' SS STRONG HC odor  PID 239 ppm  AEI-21 20' SS STRONG HC odor  PID 38 ppm  PID 38 ppm  PID 124 ppm  PID 124 ppm  PID 124 ppm  End of Borehole		US	cs	AM US	Sa	mple	Data			
Soil Firm, black color, 30% sand  AEI-21 5' SS HC odor  Clay Firm, olive green color, 5% sand  AEI-21 9' SS ST Strong HC odor  Clay Stiff, olive green color, 20% AEI-21 13' SS ST Strong HC odor  14- 16- 18- 20- 21- 22- 24- 24- 25- 26- 28- 28- 28- 28- 28- 28- 28- 28- 29- 29- 29- 20- 20- 20- 20- 20- 20- 20- 20- 20- 20	Depth				Sample Label	Туре	Blow/ft	Recovery	Well Data	Remarks
Soil Firm, black color, 30% sand  AEI-21 5' SS	0-			Ground Surface						
Clay Firm, olive green color, 5% sand  Clay Stiff, olive green color, 20% Gravels  Clay Stiff, olive green color, 20% AEI-21 13' SS  AEI-21 15' SS  Clay Stiff, olive green color, fine grained, 5% sands  Clay Stiff, olive green color, fine grained, 5% sands  AEI-21 20' SS  Gravels  Soluted layer Sand Firm, grey color, clayey AEI-21 24' SS  Clay Very sandy w/ gravels, brown color End of Borehole  Find of Borehole	2-									Slight HC odor
Clay Firm, olive green color, 5% sand  Clay Stiff, clive green color, 20% gravels  AEI-21 13' SS  AEI-21 13' SS  AEI-21 15' SS  PID 239 ppm  AEI-21 15' SS  PID 38 ppm  PID 38 ppm  PID 38 ppm  PID 38 ppm  PID 124 ppm  PID 124 ppm  End of Borehole					AEI-21 5'	SS				HC adar
Firm, olive green color, 5% sand  AEI-21 9' SS  Clay Stiff, clive green color, 20% gravels  AEI-21 13' SS  AEI-21 13' SS  PID 239 ppm  AEI-21 15' SS  Clay Stiff, clive green color, fine grained, 5% sands  AEI-21 20' SS  Gravels Isolated layer Sand Firm, grey color, clayey  AEI-21 24' SS  PID 124 ppm  PID 124 ppm  End of Borehole	-			Clay						THO buoi
Clay Stiff, clive green color, 20% gravels  AEI-21 13' SS  AEI-21 15' SS  Clay Stiff, olive green color, 20% gravels  AEI-21 15' SS  PiD 239 ppm  PiD 239 ppm  AEI-21 20' SS  Gravels Isolated layer Sand Firm, grey color, clayey  AEI-21 24' SS  Clay Very sandy w/ gravels, brown color Color  End of Borehole	8-									
Stiff, clive green color, 20% Gravels  AEI-21 13' SS  AEI-21 15' SS  AEI-21 15' SS  PiD 239 ppm  AEI-21 20' SS  Gravels  Isolated layer  Sand Firm, grey color, clayey  AEI-21 24' SS  PiD 124 ppm  PiD 124 ppm  PiD 124 ppm  PiD 124 ppm	10-				AEI-21 9'	SS		,		
gravels  AEI-21 13' SS  AEI-21 15' SS  PID 239 ppm  PID 239 ppm  PID 38 ppm  AEI-21 20' SS  Gravels  Isolated layer  Sand Firm, grey color, clayey  AEI-21 24' SS  PID 124 ppm  PID 124 ppm  PID 124 ppm  PID 124 ppm  Firm of Borehole  End of Borehole	12-								¥	Strong HC oder
Clay Stiff, olive green color, fine grained, 5% sands  PID 38 ppm  AEI-21 20' SS  Gravels Isolated layer Sand Firm, grey color, clayey  Clay Very sandy w/ gravels, brown color End of Borehole  AEI-21 15' SS  PID 38 ppm  PID 124 ppm  PID 124 ppm	14-			gravels	AEI-21 13'	SS				-
Clay Stiff, olive green color, fine grained, 5% sands  AEI-21 20' SS  Gravels Isolated layer Sand Firm, grey color, clayey  Clay Very sandy w/ gravels, brown color End of Borehole  PID 38 ppm  PID 124 ppm  PID 124 ppm	16-				AEI-21 15'	ss				PID 239 ppm
AEI-21 20' SS    Solated layer   Sand   Firm, grey color, clayey   AEI-21 24' SS    Clay   Very sandy w/ gravels, brown color   End of Borehole   Sand   End of Borehole   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand   Sand				Stiff, olive green color, fine						PID 38 ppm
Solated layer   Sand   Firm, grey color, clayey   AEI-21 24'   SS	20-				AEI-21 20'	SS				
Firm, grey color, clayey  AEI-21 24' SS  Clay Very sandy w/ gravels, brown color  End of Borehole  Firm, grey color, clayey  AEI-21 24' SS  PID 124 ppm	22	976B		\solated layer/						
Clay Very sandy w/ gravels, brown color End of Borehole	24-				AEI-21 24'	SS				PID 124 ppm
End of Borehole  30 32	26			Clay Very sandy w/ gravels, brown						
30-	28-	THINK!								
	30-			Lid of Doferiole						
	32-									
	-									
	34-									

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 28 Depth to Water: 13 Reviewed by:

Logged by: AW

AEI Consultants 3210 Old Tunnel Road, Suite B Lafayette, CA 94549 (925) 283-6000

Project Name: Fruitvale

Log of Borehole: SB-22

Client: PHUA

Location: Oakland, CA

	USC	os		Sa	mple	Data			
Depth	Symbol	Label	Subsurface Description	Sample	Туре	Blow/ft	Recovery	Well Data	Remarks
0-			Ground Surface						
2- 4-			Soil Firm, sands and gravels present						
- 6-				AEI-22 5'	SS				
8- -			Clay Stiff w/ fine sands and silts, dk brown						
10-				AEI-22 10'	SS				
12- 14-			Clay		·				HC odor
16-			Stiff, olive green color, 10%	AEI-22 15'	SS				
-			gravels						
18-								¥	
20-				AEI-22 20'	SS				Slight HC odor
22- - 24-			Clay Stiff, olive green color, gravel locally						
26	<i>9900</i>			AEI-22 25'	SS				
00			End of Borehole						
28-									
30-									
32									
34-									
347									

Drill Date 6/10/02

Drill Method: Direct Push

Total Depth: 25 Depth to Water: 19 Reviewed by:

Logged by: AW

AEI Consultants 3210 Old Tunnel Road, Suite B Lafayette, CA 94549 (925) 283-6000

Sheet: 1 of 1

Project No: 3581

Project Name: Jay Phares Corp.

Log of Borehole: MW-1

Client: Ken Phares

Location: 1450 Fruitvale Avenue

		Subsurface Description		Sample	Data .		
Depth	Soil Symbol		Sample Label	Туре	Blow Counts/	Recovery Well Data	Remarks
0 m 0	77777	Ground Surface					
1 2 3 4 1 1 4 5 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		CLAY			~		
6 - 2		dark silty clay	MW-1	SS			PID= 3 ppm, no odor
8 1 1 3 1 3		,					
11 = 12 = 1		sandy clay w/coarse gravel	MW-1	SS			PID= 193 ppm, grey green staining, strong odor
13 4							<b>.</b>
14 to the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of the total of							
19 6 20 6 21							
22 -	9702	SAND	MW-1	SS			PID= 29 ppm, wet grey
23 = 7	60°	sandy gravel					
25- 268							
27 - 28 -				-			
29 <del>1</del> 9			4			U	
31 = 32	A ALMAN MARKATANA	End of Borehole					

Drill Date 09/25/00

Drill Method: HS

Total Depth: 30' Depth to Water: ~15' Reviewed by: PM


Logged by: NW

Project Name: Jay Phares Corp.

Log of Borehole: MW-2

Client: Ken Phares

Location: 1450 Fruitvale Avenue



Drill Date 09/25/00

Drill Method: HS

Total Depth: 30'
Depth to Water: ~15'

Reviewed by: PM

Logged by: NW

AEI Consultants 3210 Old Tunnel Road, Suite B Lafayette, CA 94549 (925) 283-6000

Project Name: Jay Phares Corp.

Log of Borehole: MW-3

Client: Ken Phares

Location: 1450 Fruitvale Avenue

		Subsurface Description	Sample Data				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Depth	Soil Symbol		Sample Label	Туре	Blow Counts/	Recovery	Well Data	Remarks
0 T 0		Ground Surface		<u> </u>	+=	<del>-</del>	-	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
2		CLAY brown silty clay w/ organic matter to 5'		•				
4 5 6 7 8 9 9		silty clay, stiff	MW-3	SS				PID= 20 ppm, dark green staining, strong odor
10 - 3 11 - 1 12 - 1 13 - 4		silty gravelly clay intermixed w/coarse gravel	MW-3	SS				PID≃ 220 ppm, green staining strong odor
4 1 1 5 6 7 7 8 8 9 9		stiff silty clay	MVV-3	SS				PID= 522 ppm, light grey green staining, strong odor
0 - 6	97.00	gravelly sandy clay / light brown	MW-3	SS				PID= 19 ppm, light odor
27. 31. 41. 51.		gravelly sandy clay / light brown clayey sand	101110					
6 7 8 7 8 8 9 9 9 9 9 9	\$2.00 \$2.00 \$2.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00 \$3.00	gravelly sandy silt, light brown	MVV-3	SS				no odor or staining
30 = 3 31 = 1 32 = 1	A.E.C.	End of Borehole					V	

Drill Date 09/25/00

Drill Method: HS


Total Depth: 30'

Depth to Water: ~15'

Reviewed by: PM


Logged by: NW


AEI Consultants 3210 Old Tunnel Road, Suite B Lafayette, CA 94549 (925) 283-6000




## **KEY**

- Existing 2" Monitoring Wells
- ♦ Temporary Borings: 1998-1999
- → Temporary Borings: June 2002
- ₩ Hand Auger Borings: Sept. 2002







## AEI CONSULTANTS 3210 OLD TUNNEL ROAD, SUITE B, LAFAYETTE, CA

## **BORING AND WELL LOCATIONS**

1450 FRUITVALE AVENUE OAKLAND, CALIFORNIA

FIGURE 4 **AEI PROJECT NO 5624** 

