



Atlantic Richfield Company
(a BP affiliated company)

P.O. Box 1257
San Ramon, California 94583
Phone: (925) 275-3801
Fax: (925) 275-3815

18 April 2007

Re: First Quarter 2007 Status Report
Former BP Service Station #11266
1541 Park Street
Alameda, California
ACEH Case # RO0000318

RECEIVED

1:26 pm, May 01, 2007

Alameda County
Environmental Health



"I declare, that to the best of my knowledge at the present time, that the information and/or recommendations contained in the attached document are true and correct."

Submitted by:

Paul Supple
Environmental Business Manager

Broadbent & Associates, Inc.
1324 Mangrove Ave., Suite 212
Chico, CA 95926
Voice (530) 566-1400
Fax (530) 566-1401



18 April 2007

Project No. 06-08-658

Atlantic Richfield Company
P.O. Box 1257
San Ramon, California 94583
Submitted via ENFOS

Attn.: Mr. Paul Supple

Re: First Quarter 2007 Status Report, Former BP Station #11266, 1541 Park Street, Alameda, Alameda County, California; ACEH Case #RO0000624.

Dear Mr. Supple:

Provided herein is the *First Quarter 2007 Status Report* for Former BP Station #11266 (herein referred to as Station #11266) located at 1541 Park Street, Alameda, California.

Should you have questions regarding this submission, please do not hesitate to contact us at (530) 566-1400.

Sincerely,


BROADBENT & ASSOCIATES, INC.

A handwritten signature in black ink that reads 'Thomas A. Venus'.

Thomas A. Venus, P.E.
Senior Engineer

A handwritten signature in black ink that reads 'Robert H. Miller'.

Robert H. Miller, P.G., C.HG.
Principal Hydrogeologist



Enclosures

cc: Mr. Steven Plunkett, Alameda County Environmental Health (Submitted via ACEH ftp Site)
Mr. Chris Jimmerson, Delta Environmental Consultants (electronic copy uploaded to ENFOS)
Electronic copy uploaded to GeoTracker

STATION #11266 QUARTERLY GROUND-WATER STATUS REPORT

Facility: #11266	Address:	1541 Park Street, Alameda, California
Environmental Business Manager:		Mr. Paul Supple
Consulting Company/Contact Person:		Broadbent & Associates, Inc.(BAI)/Rob Miller & Tom Venus (530)566-1400
Consultant Project No.:		06-08-658
Primary Agency/Regulatory ID No.:		Alameda County Environmental Health (ACEH) ACEH Case #RO0000624

WORK PERFORMED THIS QUARTER (First Quarter 2007):

1. Prepared and submitted the Fourth Quarter 2006 Ground-Water Monitoring Report.
2. No environmental work was conducted at the site during the First Quarter 2007.

WORK PROPOSED FOR NEXT QUARTER (Second Quarter 2007):


1. Prepared and submitted this First Quarter 2007 Status Report (contained herein).
2. No environmental work is scheduled for the Second Quarter 2007.

DISCUSSION:

Case closure was requested on 21 February 2003 from ACEH. BP has been awaiting a response from the ACEH. In a letter dated 7 July 2006, ACEH requested rehabilitation, redevelopment, ground-water monitoring and sampling of the onsite monitoring wells to resume the site closure process. A summary of well rehabilitation/redevelopment, and ground-water monitoring and sampling results were presented in the Third Quarter 2006 Ground-Water Monitoring Report. For reference, a Ground-Water Elevation Contour and Analytical Summary Map from Third Quarter 2006 is provided as Drawing 1.

ATTACHMENTS:

Drawing 1 Ground-Water Elevation Contour and Analytical Summary Map, 24 August 2006,
Former BP Service Station #11266, 1541 Park Street, Alameda, California



LEGEND

- Monitoring Well Location
- GROUND-WATER RECOVERY WELL
- 10.55 Ground-water elevation contour (ft MSL)
- | | |
|---------|---|
| Well | Well designation |
| ELEV | Ground-water elevation (ft MSL) |
| GRO | GRO, Benzene and MTBE concentrations (µg/L) |
| Benzene | |
| MTBE | |
- Ground-water flow direction and gradient (ft/ft)

