



Atlantic Richfield Company  
(a BP affiliated company)

P.O. Box 1257  
San Ramon, California 94583  
Phone: (925) 275-3801  
Fax: (925) 275-3815



**RECEIVED**

2:30 pm, Jan 25, 2008

Alameda County  
Environmental Health

18 January 2008

Re: Fourth Quarter 2007 Status Report  
Former BP Service Station #11266  
1541 Park Street  
Alameda, California  
ACEH Case # RO0000318

"I declare, that to the best of my knowledge at the present time, that the information and/or recommendations contained in the attached document are true and correct."

Submitted by:

Paul Supple  
Environmental Business Manager

Broadbent & Associates, Inc.  
1324 Mangrove Ave., Suite 212  
Chico, CA 95926  
Voice (530) 566-1400  
Fax (530) 566-1401



18 January 2008

Project No. 06-08-658

Atlantic Richfield Company  
P.O. Box 1257  
San Ramon, California 94583  
Submitted via ENFOS

Attn.: Mr. Paul Supple

Re: Fourth Quarter 2007 Status Report, Former BP Station #11266  
1541 Park Street, Alameda, California; ACEH Case #RO0000318

Dear Mr. Supple:

Provided herein is the *Fourth Quarter 2007 Status Report* for Former BP Station #11266 (herein referred to as Station #11266) located at 1541 Park Street, Alameda, California. This report presents a summary of current developments at the Site through Fourth Quarter 2007.


Should you have questions regarding this submission, please do not hesitate to contact us at (530) 566-1400.

Sincerely,

BROADBENT & ASSOCIATES, INC.

Thomas A. Venus, P.E.  
Senior Engineer

Robert H. Miller, P.G., C.HG.  
Principal Hydrogeologist



Enclosures

cc: Mr. Steven Plunkett, Alameda County Environmental Health (Submitted via ACEH ftp Site)  
Mr. Chris Jimmerson, Delta Environmental Consultants (electronic copy uploaded to ENFOS)  
Electronic copy uploaded to GeoTracker

## STATION #11266 QUARTERLY GROUND-WATER STATUS REPORT

Facility: #11266	Address:	1541 Park Street, Alameda, California
Environmental Business Manager:		Mr. Paul Supple
Consulting Company/Contact Person:		Broadbent & Associates, Inc.(BAI)/Rob Miller & Tom Venus (530)566-1400
Consultant Project No.:		06-08-658
Primary Agency/Regulatory ID No.:		Alameda County Environmental Health (ACEH) ACEH Case #RO0000318

### WORK PERFORMED THIS QUARTER (Fourth Quarter 2007):

1. Prepared and submitted the Third Quarter 2007 Status Report.
2. No environmental work was conducted at the site during the Fourth Quarter of 2007.

### WORK PROPOSED FOR NEXT QUARTER (First Quarter 2008):


1. Prepared and submitted this Fourth Quarter 2007 Status Report (contained herein).
2. No environmental work is scheduled for the First Quarter 2008.

### DISCUSSION:

Case closure was requested on 21 February 2003 from ACEH. In a letter dated 7 July 2006, ACEH requested rehabilitation, redevelopment, ground-water monitoring and sampling of the onsite monitoring wells to resume the site closure process. A summary of well rehabilitation/redevelopment, and ground-water monitoring and sampling results were presented in the *Third Quarter 2006 Ground-Water Monitoring Report* (BAI, 25 October 2006). BP is currently awaiting comments from ACEH to this submittal. For reference, a Ground-Water Elevation Contour and Analytical Summary Map from Third Quarter 2006 is provided as Drawing 1.

### ATTACHMENTS:

Drawing 1      Ground-Water Elevation Contour and Analytical Summary Map, 24 August 2006,  
Former BP Service Station #11266, 1541 Park Street, Alameda, California



**LEGEND**

- Monitoring Well Location
- GROUND-WATER RECOVERY WELL
- 10.55 Ground-water elevation contour (ft MSL)

<b>Well</b>	Well designation
<b>ELEV</b>	Ground-water elevation (ft MSL)
GRO	GRO, Benzene and MTBE concentrations (µg/L)
Benzene	
MTBE	

- Ground-water flow direction and gradient (ft/ft)

