



Figure 3 :  
 SHALLOW GROUND-WATER  
 ELEVATION CONTOURS  
 MAY 24, 1993  
 YERBA BUENA PROJECT SITE  
 EMERYVILLE AND OAKLAND, CALIFORNIA  
*Oakland 7/30/93*



1 - 580



- EXPLANATION
- SHALLOW (LESS THAN 25 FEET) MONITORING WELL LOCATION
  - ◐ INTERMEDIATE (35 TO 45 FEET) MONITORING WELL LOCATION
  - ◑ DEEPER (62 FEET) MONITORING WELL LOCATION
  - ABANDONED WELL
  - LOCATION OF FORMER BUSINESSES
  - 11.32 GROUND-WATER ELEVATION (FEET)
  - 15 GROUND-WATER ELEVATION CONTOUR (FEET)
  - NM NOT MEASURED

Figure 3 :  
 SHALLOW GROUND-WATER ELEVATION  
 CONTOUR MAP  
 FEBRUARY 9, 1993  
 YERBA BUENA PROJECT SITE

*Bushland*  
*4/5/93 report*