

3164 Gold Camp Drive Suite 200 Rancho Cordova, California 95670-6021 916/638-2085 <u>FAX</u>: 916/638-8385

# MONITORING WELL INSTALLATION REPORT

at Chevron Service Station #9-4800 1700 Castro Street Oakland, California

GR Report No. 346383.06-1 Delta Project No. DG94-800

## Prepared for:

Mr. Thomas Bauhs Chevron Products Company P.O. Box 6004 San Ramon, California 94583

## Prepared by:

# DELTA ENVIRONMENTAL CONSULTANTS INC.

Network Associate GETTLER - RYAN INC. 3140 Gold Camp Drive, Suite 170 Rancho Cordova, California 95670

Tony P. Mikacich

Project Geologist

Stephen J. Carter Senior Geologist

R.G. 5577

reologist o

No. 5577

May 29, 2001

# TABLE OF CONTENTS

INTRODUC	TION 1
SITE DESC	RIPTION 1
PREVIOUS	ENVIRONMENTAL WORK 1
	IVITIES 2
Well Instal	lation 2
Well Devel	opment, Monitoring and Sampling3
Wellhead S	survey3
RESULTS O	F THE SUBSURFACE INVESTIGATION3
CHEMICAI	ANALYTICAL RESULTS3
Soil Analy	ical Results4
Groundwat	er Analytical Results4
WASTE DIS	POSAL4
CONCLUSI	ONS4
	TABLES
Table 1.	Soil Chemical Analytical Data
Table 2.	Groundwater Chemical Analytical Data
	FIGURES
Figure 1.	Vicinity Map
Figure 2.	Site Plan
	APPENDICES
Appendix A. Appendix B. Appendix C. Appendix D. Appendix E.	Field Methods and Procedures Encroachment and Monitoring Well Permits, Boring Log, and Well Completion Report Well Development and Field Data Sheet Wellhead Survey Report Chemical Analytical Reports and Chain-of-Custody Forms
hhamary Di	the many warm trapers and country a country a country

at
Chevron Service Station #9-4800
1700 Castro Street
Oakland, California

GR Report No. 346383.06-1 Delta Project No. DG94-800

#### INTRODUCTION

At the request of Chevron Products Company (Chevron), Delta Environmental Consultants, Inc. Network Associate Gettler-Ryan Inc. (GR) installed one monitoring well at the follow Chevron Station #9-4800, located at 1700 Castro Street in Oakland, California. The work was performed to evaluate if soil and groundwater downgradient of the subject site have been impacted by petroleum hydrocarbons. The scope of work included: obtaining the required monitoring well and encroachment permits; updating a site safety plan; installing one monitoring well; surveying the newly installed well; developing and sampling the new well; analyzing groundwater and selected soil samples; arranging for disposal of waste material; and preparing a report documenting the work. This work was proposed in GR's, Work Plan for Monitoring Well Installation, dated November 19, 1999 and approved by the Alameda County Health Care Services Agency (ACHCSA) in a letter dated November 30, 1999.

#### SITE DESCRIPTION

The subject site is an active service station located on the southeast corner of Castro Street and 18<sup>th</sup> Street in Oakland, California (Figure 1). The current facilities consist of a kiosk, five dispenser islands and four gasoline UST's that share a common excavation in the northern portion of the site. Locations of pertinent site features are shown on Figure 2.

#### PREVIOUS ENVIRONMENTAL WORK

Five dispenser islands were upgraded in February 1997. On February 18, 1997, one soil sample was collected from beneath each of the five dispenser islands at a depth of 4.0 feet below ground surface (bgs). Total Petroleum Hydrocarbons as gasoline (TPHg) were detected in four samples ranging from 1.9 to 890 parts per million (ppm). Benzene was detected in four samples at concentrations ranging from 0.016 to 15 ppm. Total Petroleum Hydrocarbons as diesel (TPHd) were detected in four samples at concentrations ranging from 1.9 to 220 ppm. The highest concentrations of hydrocarbons at the site were detected in samples collected beneath the central and southern dispenser islands.

On February 21 and 22, 1997 GR hand augered 12 soil borings, to a maximum depth of 10.0 feet, to evaluate the extent of the hydrocarbon impact to the soil beneath the site. Groundwater was not encountered in the soil borings. TPHg were detected in five soil samples and ranged from 1.9 to 890 ppm. TPHd were detected in six soil samples and ranged from 1.0 to 640 ppm. Benzene was detected in 12 soil samples and ranged in concentrations from 0.011 to 3.0 ppm.

On May 29, 1997 GR supervised the installation of three groundwater monitoring wells at the site. TPHg were not detected in soil samples from these well borings. TPHd were detected in the well borings MW-2

Chevron Service Station #9-4800 1700 Castro Street Oakland, California 2 of 4

at 21.0 feet bgs (1.9 ppm) and MW-3 at 16.0 feet bgs (1.1 ppm). Benzene was detected in soil from the well borings MW-1 and MW-3 at concentrations of 0.0069 to 0.12 ppm, respectively. Benzene was not detected in the soil from well boring MW-2. Methyl tertiary-Butyl Ether (MtBE) was detected in soil from well boring MW-2 and MW-3 at concentrations ranging from 0.041 to 0.58 ppm. MtBE was not detected in the soil samples collected from well soil boring MW-1.

On March 23,1999, GR supervised the installation of three groundwater monitoring wells at the site (MW-4, MW-5 and MW-6). Concentrations of TPHg, benzene, toluene, ethylbenzene and xylenes (BTEX) and MtBE were not detected in any of the soil samples collected and analyzed from well borings MW-5 or MW-6. Concentrations of benzene (0.0051 ppm) and MtBE (0.045 ppm) were detected in boring MW-4 at 23.0 feet bgs. MtBE was detected in the soil sample from 6 feet bgs in boring MW-4 at a concentration of 0.22 ppm. No other petroleum hydrocarbons were detected in soil samples from boring MW-4.

The most recent (March 1, 2001) quarterly groundwater monitoring analytical results indicated TPHg concentrations in monitoring wells MW-1 through MW-4 ranged in concentrations from 193 to 2,340 parts per billion (ppb). Benzene concentrations in these wells ranged from 2.31 to 218 ppb. TPHd concentrations were detected in all six wells at concentrations ranging from 77.4 to 1,320 ppb. MtBE by EPA Method 8020 was detected in samples collected from wells MW-1 through MW-6 at concentrations of 7.52 to 1,220 ppb. Groundwater flow direction was westerly at a depth of approximately 25 feet bgs.

#### FIELD ACTIVITIES

Field work was conducted in accordance with GR's Field Methods and Procedures (Appendix A) and the Site Safety Plan dated March 29, 2001. Drilling permit #WO1-107 was obtained from the Alameda Public Works Agency and a Minor Encroachment Permit #X000214 was obtained for the City of Oakland. Underground Service Alert (USA) was notified prior to drilling at the site. Copies of the permits are included in Appendix B.

#### Well Installation

On March 30, 2001 a GR geologist observed Gregg Drilling Inc. (C57-485165) install one monitoring well (MW-7) in the location shown on Figure 2. A hand auger was used for the first five feet of the borehole in order to clear the location of any underground utilities. A truck-mounted rig using 8-inch-diameter hollow stem augers advanced the borehole to 30 feet bgs. A GR geologist prepared a log of the boring (Appendix B).

The well was constructed of 2-inch-diameter polyvinyl chloride (PVC) to a depth of 30 feet bgs. The bottom 20 feet of the well was screened with 0.01-inch machine-slotted casing. Lonestar #3 sand was placed in the annular space from the bottom of the boring to approximately 2 feet above the well screen. The well was then sealed with hydrated bentonite followed by neat cement. A water-resistant box installed in concrete was placed over the well. An expandable waterproof well cap secured with a lock was placed on the top of the well casing. Well construction details are shown on the boring log in Appendix B.

Chevron Service Station #9-4800 1700 Castro Street Oakland, California 3 of 4

Drill cuttings were placed on and covered with plastic sheeting pending disposal. One 4-point disposal characterization sample (SP-1-4) was collected from the stockpile.

#### Well Development, Monitoring, and Sampling

Well MW-7 was developed and sampled on May 4, 2001, during the regularly scheduled monitoring and sampling event. Depth-to-water was measured and the well was checked for the presence of separate phase hydrocarbons (SPH). SPH were not found in the well. The newly installed well de-watered during development, but the well yielded a minimum 10 casing volumes. Following development, groundwater samples were collected from the well. Purge water generated during development and sampling procedures were stored on-site in properly labeled 55-gallon drums pending disposal. Well development procedures are included in Appendix A. A copy of the well development form is included in Appendix C.

#### Wellhead Survey

Following installation of the well, the elevation was surveyed by Virgil Chavez Land Surveying of Vallejo, CA (license #6323). Top of casing and vault box elevation was measured relative to Mean Sea Level (MSL), and the horizontal location of the well was measured. The surveyor's report is included in Appendix D.

#### RESULTS OF THE SUBSURFACE INVESTIGATION

Soil encountered during this investigation consisted of silty sand and sandy silt to approximately 15 feet bgs. Poorly graded sand with abundant iron oxide staining was encountered at approximately 20 feet bgs and appeared to continue to approximately 29 feet bgs. Clay with sand was encountered at 29 feet bgs. Groundwater was first encountered at approximately 28 feet bgs. Based on the groundwater monitoring data collected on May 4, 2001, the water table beneath the site is at approximately 25 feet bgs. Detailed descriptions of the soil encountered during drilling are presented on the boring log in Appendix B.

#### CHEMICAL ANALYTICAL RESULTS

All samples were analyzed by Sequoia Analytical in Walnut Creek, California (ELAP #1271). Soil samples from the well borings were analyzed for TPHg, TPHd, BTEX and MtBE by DHS LUFT. Stockpile samples were analyzed for TPHg, TPHd, BTEX, MtBE, and total lead by EPA Method 6010. Groundwater samples were analyzed for TPHg, TPHd, BTEX and MtBE by DHS LUFT, and Ethanol, Tertiary-Butyl Alcohol (TBA), Di-isopropyl ether (DIPE), Ethyl tertiary-butyl ether (EtBE), and tertiary-Amyl methyl ether (TAME) by EPA Method 8260B. Copies of the laboratory analytical reports and chains-of-custody are included in Appendix E. Analytical reports for the newly installed well and the groundwater sampling event are included in the same report.

Chevron Service Station #9-4800 1700 Castro Street Oakland, California 4 of 4

### Soil Analytical Results

Concentrations of TPHg, BTEX and MtBE were not detected in any of the five soil samples collected from well boring MW-7. TPHd was detected in the sample from 15 feet bgs at a concentration of 1.5 ppm, slightly above the laboratory reporting limit of 1.0 ppm. The disposal characterization samples from the drill cuttings contained lead at a concentration of 2.8 ppm. Concentrations where acceptable to the disposal facility. These data are summarized in Table 1

#### **Groundwater Analytical Results**

TPHg or TPHd were not detected in the groundwater sample collected from MW-7. MtBE was detected at concentrations of 567 ppb by EPA Method 8021B and 470 ppb by EPA Method 8260B. TBA and TAME were detected at concentrations of 57 ppb and 11 ppb, respectively. These data are summarized in Table 2.

#### WASTE DISPOSAL

Drill cuttings were removed from the site on April 9, 2001, by IWM. The drill cuttings were transported to the Republic landfill in Livermore California for disposal. Waste water generated during well development and sampling was transported by IWM to Mckittrick for disposal.

#### CONCLUSIONS

The purpose of this investigation was to evaluate if soil and groundwater downgradient of the subject site have been impacted by petroleum hydrocarbons. Hydrocarbon impact to soil at a depth of 15 feet bgs in the vicinity of MW-7 is negligible. Additional assessment of soil conditions in the vicinity of MW-7 is not warranted.

Dissolved gasoline, diesel, and BTEX hydrocarbons were not detected in samples collected from MW-7. Oxygenating compounds TBA, MtBE, and TAME were detected in samples at concentrations of 57 ppb, 470 ppb (by EPA Method 8260B) and 567 ppb (by EPA Method 8021B), and 11 ppb, respectively.

The dissolved hydrocarbon plume remains undefined downgradient. Based on the analytical results of groundwater samples from MW-7, the concentrations of detected TBA, MtBE and TAME with no detected TPHg, TPHd, or BTEX may indicate the leading edge of the hydrocarbon plume. GR recommends that quarterly monitoring and sampling be implemented for MW-7. Groundwater samples from MW-7 should be analyzed for TPHg, TPHd, BTEX and MtBE.

#### TABLE 1 - SOIL CHEMICAL ANALYTICAL DATA

## Chevron Service Station, #9-4800 1700 Castro Street Oakland, California

Sample ID	Sample Date	Sample Depth (feet bgs)	TPHg (ppm)	TPHd (ppm)	Benzene (ppm)	Toluene (ppm)	Ethyl- benzene (ppm)	Total Xylenes (ppm)	MtBE* (ppm)	Total Pb (ppm)
Boring MW-7 MW-7-6'	03/30/01	6.0	<1.0	<1.0	<0.005	<0.005	<0.005	<0.005	<0.05	
Boring MW-7 MW-7-10'	03/30/01	10.0	<1.0	<1.0	<0.005	<0.005	<0.005	<0.005	<0.05	
Boring MW-7 MW-7-15'	03/30/01	15.0	<1.0	1.5	<0.005	<0.005	<0.005	<0.005	<0.05	
<b>Boring MW-7</b> MW-7-19.5'	03/30/01	19.5	<1.0	<1.0	<0.005	<0.005	<0.005	<0.005	<0.05	
Boring MW-7 MW-7-24.5'	03/30/01	24.5	<1.0	<1.0	<0.005	<0.005	<0.005	<0.005	<0.05	_
Stockpile Samples SP-1-4	03/30/01		<1.0	<2.0	<0.005	<0.005	<0.005	<0.005	<0.05	2.8

#### Explanation:

TPHg = Total Petroleum Hydrocarbons as gasoline

TPHd = Total Petroleum Hydrocarbons as diesel

BTEX = benzene, toluene, ethyl-benzene, total xylenes

MtBE = methyl tertiary-butyl ether

feet bgs = feet below ground surface

(ppm) = parts per million

--- = not applicable

Pb = total lead

### Analytical Laboratory:

Sequoia Analytical (CA ELAP #1271)

## Analytical Methods:

TPHg/TPHd/BTEX/MtBE: DHS LUFT Total Lead by EPA Method 6010A

#### TABLE 2 - GROUNDWATER CHEMICAL ANALYTICAL DATA

## Chevron Service Station #9-4800 1700 Castro Street Oakland, California

Sample ID	Sample Date	Depth to Water (ft.)	TPHg (ppb)	TPHd (ppb)	Benzene (ppb)	Toluene (ppb)	Ethyl- benzene (ppb)		MtBE* (ppb)	TBA (ppb)	DIPE (ppb)	EtBE (ppb)	TAME (ppb)	Ethanol (ppb)
MW-7 MW-7 (Water)	05/04/01	27.87	<50	<50	<0.50	<5.0	<5.0	<5.0	567/470	57	<2.0	<2.0	11.00	<500

#### Explanation:

TPHg = total petroleum hydrocarbons as gasoline (includes MtBE)

TPHd = total petroleum hydrocarbons as diesel

BTEX = benzene, toluene, ethylbenzene, total xylenes

MtBE = methyl tertiary-butyl ether

TBA = tertiary-butyl alcohol

DIPE = di-isopropyl ether

EtBE = ethyl tertiary-butyl ether

TAME = tertiary-amyl methyl ether

(ppb) = parts per billion

ft = feet


#### **Analytical Laboratory**

Sequoia Analytical (ELAP #1271)

#### **Analytical Methods**

TPHg/TPHd/BTEX/MtBE: DHS LUFT Oxygenates: EPA Method 8260B

<sup>\*</sup> Reported as MtBE by DHS LUFT/EPA Method 8260B





# Gettler - Ryan Inc.

(510) 551-7555 6747 Sierra Ct., Suite J Dublin, CA 94568


Chevron Service Station No. 9-4800 1700 Castro Street Oakland, California

DATE

REVISED DATE

REVIEWED BY JOB NUMBER 6383

2/97



· · ..



# Gettler - Ryan Inc.

6747 Sierra Ct., Suite J **Dublin, CA 94568** 

(925) 551-7555

Chevron Service Station No. 9-4800 1700 Castro Street

Oakland, California

REVIEWED BY

DATE 11/99 REVISED DATE

JOB NUMBER 346383.05

#### GETTLER-RYAN INC.

#### FIELD METHODS AND PROCEDURES

### Site Safety Plan

Fieldwork performed by Gettler-Ryan Inc. (G-R) is conducted in accordance with G-R's Health and Safety Plan (revised January 16, 1995) and the Site Safety Plan. G-R personnel and subcontractors who perform work at the site are briefed on the contents of these plans prior to initiating site work. The G-R geologist or engineer at the site when the work is performed acts as the Site Safety Officer. G-R utilizes a photoionization detector (PID) to monitor ambient conditions as part of the Health and Safety Plan.

#### Collection of Soil Samples

Soil borings are drilled by a California-licensed well driller. A G-R geologist is present to observe the drilling, collect soil samples for description, physical testing, and chemical analysis, and prepare a log of the exploratory soil boring. Soil samples are collected from the soil boring with a split-barrel sampling device fitted with 2-inch-diameter, clean brass tube or stainless steel liners. The sampling device is driven approximately 18 inches with a 140-pound hammer falling 30 inches. The number of blows required to advance the sampler each successive 6 inches is recorded on the boring log. The encountered soils are described using the Unified Soil Classification System (ASTM 2488-84) and the Munsell Soil Color Chart.

After removal from the sampling device, soil samples for chemical analysis are covered on both ends with Teflon sheeting or aluminum foil, capped, labeled, and placed in a cooler with blue ice for preservation. A chain-of-custody form is initiated in the field and accompanies the selected soil samples to the analytical laboratory. Samples are selected for chemical analysis based on:

- a. depth relative to underground storage tanks and existing ground surface
- b. depth relative to known or suspected groundwater
- c. presence or absence of contaminant migration pathways
- d. presence or absence of discoloration or staining
- e. presence or absence of obvious gasoline hydrocarbon odors
- f. presence or absence of organic vapors detected by headspace analysis

#### Field Screening of Soil Samples

A PID is used to perform headspace analysis in the field for the presence of organic vapors from the soil sample. A small volume of sample (20-30 cm³) is placed in a Ziplock®-type plastic bag with headspace. After allowing the sample to warm for approximately 10 minutes, the PID sample tube is inserted into the headspace above the sample and a measurement taken. PID screening results are recorded on the boring log as reconnaissance data. G-R does not consider field-screening techniques to be verification of the presence or absence of hydrocarbons.

## **Construction of Monitoring Wells**

Monitoring wells are constructed in the exploratory soil borings with Schedule 40 polyvinyl chloride (PVC) casing. All joints are thread-joined; no glues, cements, or solvents are used in well construction. The screened interval is constructed of machine-slotted PVC well screen that generally extends from the total well depth to a point above the groundwater. Appropriately sized sorted sand is placed in the annular adjacent to the entire screened interval. A bentonite seal is placed in the annular space above the sand, and the remaining annular space is sealed with neat cement or cement grout.

Wellheads are protected with water-resistant traffic-rated vault boxes placed flush with the ground surface. The top of the well casing is sealed with a locking waterproof cap. A lock is placed on the well cap to prevent vandalism and unintentional introduction of materials into the well.

## Measurement of Water Levels

The top of the newly installed well casing is surveyed by a California-licensed Land Surveyor to mean sea level (MSL). Depth-to-groundwater in the well is measured from the top of the well casing with an electronic water-level indicator. Depth-to-groundwater is measured to the nearest 0.01-foot, and referenced to MSL.

## Well Development and Sampling

The purpose of well development is to improve hydraulic communication between the well and the surrounding aquifer. Prior to development, each well is monitored for the presence of floating product and the depth-to-water is recorded. Wells are then developed by alternately surging the well with a vented surge block, then purging the well with a pump or bailer to remove accumulated sediments and draw groundwater into the well. Development continues until the groundwater parameters (temperature, pH, and conductivity) have stabilized. After the wells have been developed, groundwater samples are collected. Well development and sampling is performed by Gettler-Ryan Inc. of Dublin, California.

# Storing and Sampling of Drill Cuttings

Drill cuttings are stockpiled on plastic sheeting and samples are collected and analyzed on the basis of one composite sample per 100 cubic yards of soil. Stockpile samples are composed of four discrete soil samples, each collected from an arbitrary location on the stockpile. The four discrete samples are then composited in the laboratory prior to analysis.

Each discrete stockpile sample is collected by removing the upper 3 to 6 inches of soil, and them driving the stainless steel or brass sample tube into the stockpiled material with a hand, mallet, or drive sampler. The sample tubes are then covered on both ends with Teflon sheeting or aluminum foil, capped, labeled, and placed in a cooler with blue ice for preservation. A chain-of-custody form is initiated in the field and accompanies the selected soil samples to the analytical laboratory. Stockpiled soils are covered with plastic sheeting after completion of sampling.

DDRESS: 6001 Bollinger Canyon Road Bldg,L

P.O.Box 6004

San Ramon, CA 94583-0904 (APN: 003-0059-013-02)

RE: Minor Encroachment Permit for installation of one monitoring well adjacent to 1700 Castro Street.

## CONDITIONS FOR GRANTING A MINOR ENCROACHMENT PERMIT

- 1. That this permit shall be revocable at the pleasure of the Director of Building Services.
- 2. That the permittee, by the acceptance, either expressed or implied, of the minor encroachment permit hereby disclaims any right, title, or interest in or to any portion of the public street area, and agrees that said temporary use of said area does not constitute an abandonment on the part of the City of Oakland of any of its rights for street purposes and otherwise.
- 3. The permittee shall maintain in force and effect at all times that said encroachment occupies said public area, good and sufficient public liability insurance in the amount of \$300,000 for each occurrence, and property damage insurance in the amount of \$50,000 for each occurrence, both including contractual liability, insuring the City of Oakland, its officers and employees against any and all claims arising out of the existence of said encroachment in said sidewalk area, as respects liabilities assumed under this permit, and that a certificate of such insurance and subsequent notices of the renewal thereof, shall be filed with the Director of Building Services of the City of Oakland, and that such certificate shall state that said insurance coverage shall not be canceled or be permitted to lapse without thirty (30) days written notice to said Director of Building Services. The permittee also agrees that the City may review the type and amount of insurance required of the permittee every five (5) years and may require the permittee to increase the amount of and/or change the type of insurance coverage required.
- 4. That the permittee, by the acceptance, either expressed or implied, of this revocable permit shall be solely and fully responsible for the repair or replacement of any portion or all of said improvements in the event that said improvements shall have failed or have been damaged to the extent of creating a menace or of becoming a hazard to the safety of the general public; and that the permittee shall be liable for the expenses connected therewith.
- 5. That the permittee is aware that the proposed work is out of the ordinary and does not comply with City standard installations. Permittee is also aware that the City has to conduct work in the public right-of-way, which may include, but may not be limited to, excavation, trenching, and relocation of its facilities, all of which may damage encroachments. Permittee is further aware that the City takes no responsibility for repair or replacement of encroachments, which are damaged by the City or its contractors. That the permittee, by the acceptance, either expressed or implied, of the encroachment permit hereby agrees that upon receipt of notification from the City, permittee shall immediately repair or replace within 30 days all damages to permittee's encroachments within the public right-of-way which are damaged by the City or its contractors in carrying out the City's work. Permittee agrees to employ interim measures required and approved by the City until repair or replacement work is completed.
- 6. That upon the termination of the permission herein granted, permittee shall immediately remove said encroachment from the street area, and any damage resulting therefrom shall be repaired to the satisfaction of the Director of Building Services.

- That the permittee shall file the City of Oakland for recordation. Minor Encroachment Permit and Agreement, and shall be bound by and comply with all the terms and conditions of said permit.
- That said permittee shall obtain an excavation permit prior to construction and a separate excavation permit prior to the removal of the ground water monitoring well.
  - 9. That said permittee shall provide to the City of Oakland an AS BUILT plan showing the actual location of the monitoring well and the results of all data collected from the monitoring well.
  - 10. That said permittee shall remove the monitoring well and repair any damage to the street area in accordance with City standards two (2) years after construction or as soon as monitoring is complete.
  - 11. That said permittee shall notify the Community & Economic Development Agency, Building Services Division after the monitoring weil is removed and the street area restored to initiate the procedure to rescind the minor encroachment permit.
  - 12. That the monitoring well cover installed within the sidewalk area shall have a skid-proof surface.
  - 13. That the ground water monitoring well casting and cover shall be iron and shall meet H-20 load rating. The cover shall be secured with a minimum of two stainless steel bolts. Bolts and cover shall be mounted flush with the surrounding surface. For sidewalk installations, a pre-cast concrete utility box and non-skid cover may be needed in conjunction with the bolted cast iron cover with City approval.
  - 14. That the permittee acknowledges that the City makes no representations or warranties as to the conditions beneath said encroachment. By accepting this revocable permit, permittee agrees that it will use the encroachment area at its own risk, is responsible for the proper coordination of its activities with all other permittees, underground utilities, contractors, or workmen operating, within the encroachment area and for the safety of itself and any of its personnel in connection with its entry under this revocable permit.
  - 15. The permittee acknowledges that the City is unaware of the existence of any hazardous substances beneath the encroachment area, and permittee hereby waives and fully releases and forever discharges the City and its officers, directors, employees, agents, servants, representatives, assigns and successors from any and all claims, demands, liabilities, damages, actions, causes of action, penalties, fines, liens, judgements, costs, or expenses whatsoever (including, without limitation, attorneys' fees and costs), whether direct or indirect, known or unknown, foreseen or unforeseen, that may arise out of or in any way connected with the physical condition or required remediation of the excavation area of any law or regulation applicable thereto, including without limitation, the Comprehensive Environmental Response, Compensation and Liability Act of 1980, as amended (42 U.S.C. Sections 9601 et seq.), the Resource Conservation and Recovery Act of 1976 (42 U.S.C. Section 466 et seq.), the Safe Drinking Water Act (14 U.S.C. Sections 1401, 1450), the Hazardous Waste Control Law (California Health and Safety Code Sections 25100 et seq.), the Porter-Cologne Water Quality Control Act (California Health and Safety Code Section 13000 et seq.), the Hazardous Substance Account Act (California Health and Safety Code Sections 253000 et seq.), and the Safe Drinking Water and Toxic Enforcement Act (California Health and Safety Code Section 25249.5 et seq.).
  - 16. Permittee further acknowledges that it understands and agrees that it hereby expressly waives all rights and benefits which it now has or in the future may have, under and by virtue of the terms of California Civil Code Section 1542, which reads as follows: "A GENERAL RELEASE DOES NOT EXTEND TO CLAIMS WHICH THE CREDITOR DOES NOT KNOW OR SUSPECT TO EXIST IN HIS FAVOR AT THE TIME OF EXECUTING THE RELEASE, WHICH IF KNOWN BY HIM MUST HAVE MATERIALLY AFFECTED HIS SETTLEMENT WITH THE DEBTOR."

Permittee recognizes that by valving the provisions of this section, positive will not be able to make any claims for damages that may exist, and to which, if known, would masorially affect its decision to agree to these encroachment terms and conditions, regardless of whether permittee's lack of knowledge is the result of ignorance, oversight, error, negligence, or any other cause.

- That the permittee, by the acceptance of this revocable permit, agrees and promises to indemnify, 18. (a) defend, and hold harmless the City of Oakland, its officers, agents, and employees, to the maximum extent permitted by law, from any and all claims, demands, liabilities damages, actions, causes of action, penalties, fines, liens, judgments, costs, or expenses whatsoever (including, without limitation, attorneys' fees and costs; collectively referred to as "claims", whether direct or indirect, known or unknown, foreseen or unforeseen, to the extent that such claims were either (1) caused by the permittee, its agents, employees, contractors or representatives, or, (2) in the case of environmental contamination, the claim is a result of environmental contamination that emanates or emanated from 1700 Castro Street, Oakland, California site, or was otherwise caused by the permittee, its agents, employees, contractors or representatives.
  - That, if any contamination is discovered below or in the immediate vicinity of the encroachment, **(b)** and the contaminants found are of the type used, housed, stored, processed or sold on or from 1700 Castro Street, Oakland, California site, such shall amount to a rebuttable presumption that the contamination below, or in the immediate vicinity of, the encroachment was caused by the permittee, its agents, employees, contractors or representatives.
  - That the permittee shall comply with all applicable federal, state, county and local laws, rules, and (c) regulations governing the installation, maintenance, operation and abatement of the encroachment.
- That the permittee hereby does remise, release, and forever discharge, and agree to defend, indemnify, and 19. save harmless, the City, its officers, agents and employees and each of them, from any and all actions, claims, and demands of whatsoever kind or nature, and any damage, loss or injury which may be sustained directly or by the undersigned and any other person or persons, and arising out of, or by reason of the occupation of said public property, and the future removal of the above-mentioned encroachment.
- That the herein above conditions shall be binding upon the permittee and the successive owners and assigns 20. thereof.
- That said permittee shall provide to the City of Oakland a performance bond for the amount of \$3,000 per 21, each monitoring well encroaching within the public right-of-way prior to the issuance of the encroachment permit. Said performance bond shall be returned to the permittee after the monitoring is complete and the monitoring well is removed and the street area is restored.
- That said Minor Encroachment Permit and Agreement shall take effect when all the conditions hereinabove **22**. set forth shall have been complied with to the satisfaction of the Director of Building Services, and shall become null and void upon the failure of the permittee to comply with all conditions.

Recording Requested by: CITY OF OAKLAND

When Recorded Mail to:
City of Oakland
Community & Economic
Development Agency
Building Services Division,
Engineering Information
250 Frank H. Ogawa Plaza, 2nd Floor
Oakland, CA 94612

TAX ROLL PARCEL NUMBER
(ASSESSOR'S REFERENCE NUMBER)

003		013	02
МАР	BLOCK	PARCEL	SUB

Address: 1700 CASTRO STREET

Space Above for Recorder's Use Only

## MINOR ENCROACHMENT PERMIT AND AGREEMENT

Chevron Products Company (Chevron) is hereby granted a Conditional Revocable Permit to encroach into the public right-of-way of Castro Street to install one monitoring well. The location of said encroachment shall be as delineated in Exhibit 'A' attached hereto and made a part hereof.

The permittee agrees to comply with and be bound by the conditions for granting an Encroachment Permit attached hereto and made a part hereof.

NAME: David Wickland TITLE: Office manager - JAR

-----Below for Official Use Only-----

#### CITY OF OAKLAND

Dated: By:

CALVIN N. WONG

Director of Building Services


For:

WILLIAM E. CLAGGETT

Executive Director,

Community & Economic Development Agency

# CALIFORNIA ALL-PURPOSE ACKNOWLEDGMENT



Chevron Service Station No. 9-4800 1700 Costro Street Oakland. California

EXHIBIT 'A'

PHONE NO. : 916 631 1317

Feb. 08 2001 02:04PM P2

# ALAMEDA COUNTY PUBLIC WORKS AGENCY

FROM : GETTLER-RYAN INC. PUBLIC WORKS

WATER RESOURCES SECTION
199 FLMHURST ST. RAYWARD CA. 14544-1595 THONE (\$19) 679-8654 FAX (\$16)792-1939

DRILLING PERMIT	APPLICATION
for applicant to complete Location of Project <u>CHEVRON</u> # 9 – 4800	FOR OFFICE USE  FERMIT NUMBER WO 1 - 10 7
1700 CASTRO STREET , CAKING	WELL NUMBER
	0,10
CLIENT	PERMIT CONDITIONS Circled Permit Requirements Apply
THENT  Hame CHENRON Products Company  Address RO.Box Good Prone (925/842-898  Tity SAN RAMON Zie 94583	A. GENERAL  1. A person application should be submitted to say to strive at the ACPWA office five days prior to a proposed starting date.
IPPLICANT Gettler-RYM IVC.  Idenes 8140Goll Comport. #170 Phone GS1-1317  Idenes Substance Grown CA Tip 75670	2. Submit to ACPWA within 60 days after completion of parmitted engines Department of Water Resources. Well Completion Report. 2. Formis is void if project not pagen within 90 days of
YPE OF PROJECT Nell Construction Consechnical Investigation	approval date  8. WATER SUPPLY WELLS  1. Minimum surface cas, utilizings; is two inches of comment of comment of comment of comment of the co
Cathodic Protection C General Q Witer Supply D Contamination C Membering MQ Well Contraction 2	Industrial wells or 10 feet for demostric and irrigation wells unlest a lesser depth is specially approved.  C. GROUNDWATER MONITORING WELLS INCLUDING PIEZOMETERS
ROPOSED WATER SUPPLY WELL USE New Demostic G Resiscement Comestic C Minimipal C Impation C Industrial C Cher G	LIGEODING FIEZOMETERS  I. Minimum surface seek thickpass is two inches of terminis.  Entering group blaces by treminis.  Z.Minimum seek pepth for freencaring weeks is the maximum depth processed or 20 feet.
RILLING METHOD:  Mad Relaty C Air Robby C Auger   Cible C Other I	D. GEOTECHNICAL  Backfill bore hole by wome with extreme group or coment groups and mixture. Opper two-three legs replaced in this or with soreposard evaluage.
ULLER'S NAME CASCADE DEILING, INC.	CATHODIC     Fill hole snode same with concrete placed by Methic  F. WELL DESTRUCTION  Set attached requirements for accounted a of shallow
PFF. F31-02	wells.Sord a map of work size. A different parmit application is required for wells depper than 45 feet.  G. SFECIAL CONDITIONS
Drill Hole Districtor  Cating Diameter 2 in. Depth 30 n. Surface Seel Depth 9 n. Owner's We'll Number MW-7	NOTE. One application must be submitted for each well or well deprection. Multiple begings on one application are acceptable for government and came minerion investigations.
OTECHNICAL FROJECTS  Vuriber of Borings  Hole Diameter	· · · · · · · · · · · · · · · · · · ·
IMATED COMPLETION DATE DZ/20/0/ -03/3/01	APPROVED DATE
service to comply with all requirements of this parmit and Adminds County Ord LICANT'S SIGNATURE Tomp. Mulacura L. DATE 02	inanse Ng. 73-68.
AME FRINT NAME TONY F. MIKACICH ROM	4-5-0

	6	ettle	<b>r</b> —	Ry	an, II	nc.	Log of Boring	, MW−7 ——
ROJI	ECT:	Chevron	Sei	rvice	Station	No. 9-4800	LOCATION: 1700 Castro Street, Oa	akland, CA.
				383.			CASING ELEVATION:	
		RTED: 0					WL (ft. bgs): 27.6 DATE: 03/30/01	TIME: 10:30
				30/0			WL (ft. bgs): DATE:	TIME:
		METHOD:				em Auger	TOTAL DEPTH: 30 feet	
		COMPANY			Drilling		GEOLOGIST: Tony Mikacich	
112				,, 0,93				
	×	SAMPLE NUMBER	Ė	SRAPHIC LOG	SS			WELL DIAGRAM
	F	z щ	E J	유	CLASS	GE	EOLOGIC DESCRIPTION	
(feet)	BLOWS/FT.	풀	SAMPLE INT	.≱P	SOIL			
٤	ద	<u></u> ⊗	ŝ	ß	Š	Planting soil (fill).		T T T T T T T T T T T T T T T T T T T
4			-			SILTY SAND/SANDY	Still	-   LY   1/2
								I NC
5-	36	MW-7-6			SM	SILTY SAND (SM) - 60% fine sand, 40% s	olive brown (2.5Y 4/3), moist, dense; silt.	grant schedule 40 PVC
-	<u> </u>				ML	SANDY SILT (ML) - silt, 40% fine sand, t staining.	olive brown (2.5Y 4/4), moist, hard; 60% race of clay, trace of iron oxide	2" 5'3 "5 - 2" 5'3 2" 5'3 2" 5'3
-	47	MW-7-10		{		Stannia.		
10-	1	,,,,		4	]]	· -		
-	-			$\{[]\}$				∅≡₩
- - 15-	777	MW-7-15		- - -	SM	SILTY SAND (SM) – fine sand, 30% silt, a clay.	olive (5Y 4/4), moist, very dense; 70% abundand iron oxide staining, trace of	10 vach)
20-	>50	     MW-7-19.	5 🗾		SP	l moist, verv dense: 10	ND (SP) - light olive brown (2.5Y 5/4), 00% fine to medium sand, abundand iron e of clay, trace of silt.	
25-	>50	MW-7-24	.5					cap
30-	61	MW-7-3	0		CL	CLAY WITH SAND ( hard, medium to hig Bottom of boring at	rown (10YR 4/3), becomes saturated; no (CL) - light olive brown (2.5Y 5/3), moist, th plasticity; 80% clay, 20% fine sand. t 30 feet bgs. equivalent standard penetration	
35		MBER: 3						Page 1 c

# CONFIDENTIAL

STATE OF CALIFORNIA DWR WELL COMPLETION REPORT (WELL LOGS)

# REMOVED

# WELL MONITORING/DEVELOPMENT FIELD DATA SHEET

dress: <u>170</u> y: <u>04</u> 66	LAND	ST	Date:	5-4-01 FB		
Well ID	MW-7-	Well Conditio	n:	OK		
al Diameter	i	Hydrocarbon	ob_	Amount Balle (product/water)	( ) )	oal.i
tel Depth	29.97 1	Volume Factor (VF)	2* = 0.17 6* = 1	3" = 0.38	4" = 0.66 2" = 5.80	
pth to Water	27.87 n	4 2 357			Volume: #7.70	(cet.)
ਪਾge uipment:	Disposable Bailer Bailer Stack Suction		Bi Pi	isposable Balle Blief ressure Bailer	er -	••
	Grundfos Other: Merel Be	liter	_	irab Sample		
tarting Time: ampling Time: urging Flow Ra		SD # 20 Water C	Conditions:	5,21	oder: NO	
urgang mow na Jid well de-wat			Time:		e:	<u>(cat.)</u>
Tirue	Volume pH (gai.)	Conductivity  µmhos/cm	Temperature •C	D.O. (mg/L)		linity pm)
10:11 10:15 10:31	1 6.16 2 6.01 3 594 4 550	956 871 856 849	74.3 71.4 72.6 72.8			
15:34 15:38 15:42	5 6 7					
		i				
		LABORATORY	INFORMATION		AMA: VESE	
SAMPLE ID	(#) - CONTAINER	LABORATORY REFRIG. PRESE	7	BORATURT	Analyses TPH-6/Etelia te	ele.h

## Virgil Chavez Land Surveying

312 Georgia Street, Suite 225 Vallejo, California 94590-5907 (707) 553-2476 • Fax (707) 553-8698

April 17, 2001 Project No. 1104-67B

Tony Mikacich Gettler-Ryan, Inc. 3140 Gold Camp Drive, Suite 170 Rancho Cordova, CA 95670

Subject: Monitoring Well Survey

Chevron SS # 9-4800 1700 Castro Street

Oakland, Ca.

Dear Tony:

This is to confirm that we have proceeded at your request to survey the monitoring wells at the above referenced location. The survey was performed on April 11, 2001. The benchmark for the survey was the top of curb at the south end of the return at the southeast corner of Castro Street and 18th Street. Measurement locations were marked at the approximate north side of top of box and top of casing. The station and offset data are relative to the back of sidewalk on 18th Street.

Benchmark Elevation 29.65 feet, MSL.

	Rim	TOC		
Well No.	Elevation	<u>Elevation</u>	<u>Station</u>	<u>Offset</u>
MW - 7	32.14'	31.90'	0-88.90	152.62(Rt)
BSW Intx.			0+00.00	0.00
BSW-18th S	treet			0.00

Sincerely,

Virgil D. Ch

Chavez, PLS 63

APPENDIX E





12 April, 2001

Tony Mikacich
Gettler Ryan, Inc. - Rancho Cordova
3140 Gold Camp Drive #170
Rancho Cordova, CA 95670


RE: Chevron Sequoia Report: W103680

Enclosed are the results of analyses for samples received by the laboratory on 30-Mar-01 13:00. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Charlie Westwater Project Manager

CA ELAP Certificate #1271



. 404 N. Wiget Lane Walnut Creek, CA 94598 (925) 988-9600 FAX (925) 988-9673 www.sequoialabs.com

Gettler Ryan, Inc. - Rancho Cordova

3140 Gold Camp Drive #170 Rancho Cordova CA, 95670 Project: Chevron

Project Number: Chevron # 9-4800

Project Manager: Tony Mikacich

Reported:

12-Apr-01 07:40

### ANALYTICAL REPORT FOR SAMPLES


Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
MW-7-6'	W103680-01	Soil	30-Mar-01 09:34	30-Mar-01 13:00
MW-7-10'	W103680-02	Soil	30-Mar-01 09:40	30-Mar-01 13:00
MW-7-15'	W103680-03	Soil	30-Mar-01 09:46	30-Mar-01 13:00
MW-7-19.5'	W103680-04	Soil	30-Mar-01 09:55	30-Mar-01 13:00
MW-7-24.5'	W103680-05	Soil	30-Mar-01 10:00	30-Mar-01 13:00
SP-1-4	W103680-06	Soil	30-Mar-01 10:55	30-Mar-01 13:00

Sequoia Analytical - Walnut Creek

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Charlie Westwater, Project Manager





3140 Gold Camp Drive #170 Rancho Cordova CA, 95670 Project: Chevron

Project Number: Chevron # 9-4800

Project Manager: Tony Mikacich


Reported:

12-Apr-01 07:40

# Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT Sequoia Analytical - Walnut Creek

Analyte	Result	eporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
MW-7-6' (W103680-01) Soil	Sampled: 30-Mar-01 09:34	Receive	d: 30-M	ar-01 13:00	)	•			
Purgeable Hydrocarbons	ND	1.0	mg/kg	20	11002003	02-Apr-01	04-Apr-01	EPA 8015/8020	
Benzene	ND	0.0050	"	u	"	"	'n	**	CC-3
Toluene	ND	0.0050	n.	"		**	и	"	
Ethylbenzene	ND	0.0050	11		"	**	н	н	
Xylenes (totai)	ND	0.0050	u	17	11	"	**	"	
Methyl tert-butyl ether	ND	0.050	**	*	**	n	**	n	CC-3
Surrogate: a,a,a-Trifluorotoluen	ie	95.3 %	40-	140	"	"	n	n .	
MW-7-10' (W103680-02) Soil	Sampled: 30-Mar-01 09:40	0 Receiv	/ed: 30-N	1ar-01 13:0	00				
Purgeable Hydrocarbons	ND	1.0	mg/kg	20	1D02003	02-Apr-01	04-Apr-01	EPA 8015/8020	
Benzene	ND	0.0050	17	+	"	"	11	ıı	CC-3
Toluene	ND	0.0050		**	"	11	11	u	
Ethylbenzene	ND	0.0050	"	H	ч	"	n	"	
Xylenes (total)	ND	0.0050	u	н	"	н	u	t <del>t</del>	
Methyl tert-butyl ether	ND	0.050	44	"	II .	II	п	11	CC-3
Surrogate: a,a,a-Trifluorotoluer	ie	99.7%	40-	140	"	"	"	u	
MW-7-15' (W103680-03) Soil	Sampled: 30-Mar-01 09:46	6 Receiv	ved: 30-M	1ar-01 13:0	00				
Purgeable Hydrocarbons	ND	1.0	mg/kg	20	1D02003	02-Apr-01	04-Apr-01	EPA 8015/8020	
Benzene	ND	0.0050	н	II .	11	II .	"	*	CC-3
Toluene	ND	0.0050	H	п	11	u	11	**	
Ethylbenzene	ND	0.0050	"	"	17	II	Ħ	11	
Xylenes (total)	ND	0.0050	"	п	11	u	77	"	
Methyl tert-butyl ether	ND	0.050	u	u	11	ш	**	п	CC-3
Surrogate: a,a,a-Trifluorotoluer	1e	124 %	40-	140	"	"	"	"	





3140 Gold Camp Drive #170 Rancho Cordova CA, 95670 Project: Chevron

Project Number: Chevron # 9-4800


Reported:

Project Manager: Tony Mikacich

12-Apr-01 07:40

# Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT Sequoia Analytical - Walnut Creek

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
MW-7-19.5' (W103680-04) Soil	Sampled: 30-Mar-01 (	19:55 Rece	ived: 30-	Mar-01 13	3:00			· · · - · ·	
Purgeable Hydrocarbons	ND	1.0	mg/kg	20	1D02003	02-Apr-01	04-Apr-01	EPA 8015/8020	
Benzene	ND	0.0050	n	U	п	n	н	н	CC-3
Toluene	ND	0.0050	п	п	"	II.	n	11	
Ethylbenzene	ND	0.0050		n	u	II .	"	#	
Xylenes (total)	ND	0.0050	μ	n .	11	ıı	19	#	
Methyl tert-butyl ether	ND	0.050	ч	"		u	"	**	CC-3
Surrogate: a,a,a-Trifluorotoluene		97.0 %	40-	140	"	11	<i>"</i>	n	
MW-7-24.5' (W103680-05) Soil	Sampled: 30-Mar-01	0:00 Rece	eived: 30-	Mar-01 13	3:00				
Purgeable Hydrocarbons	ND	1.0	mg/kg	20	1D02003	02-Apr-01	04-Apr-01	EPA 8015/8020	
Benzene	ND	0.0050	"	n	"	11	n	14	CC-3
Toluene	ND	0.0050	11	II	и	п	u	**	
Ethylbenzene	ND	0.0050	п	II	u	II	ű	11	
Xylenes (total)	ND	0.0050	**	"		"		n	
Methyl tert-butyl ether	ND	0.050	11	ц	a	п	п	"	CC-3
Surrogate: a,a,a-Trifluorotoluene		116 %	40-	140	"	"	"	"	· · · · · · · · · · · · · · · · · · ·
SP-1-4 (W103680-06) Soil Sam	pled: 30-Mar-01 10:55	Received:	30-Mar-	01 13:00					
Purgeable Hydrocarbons	ND	1.0	mg/kg	20	LD02003	02-Apr-01	02-Apr-01	EPA 8015/8020	
Benzene	ND	0.0050	14	"	19	ц	**	ц	
Toluene	ND	0.0050	**	11	**	п	n	н	
Ethylbenzene	ND	0.0050	"	**	**	a	"	I+	
Xylenes (total)	ND	0.0050		77	n	11	n	H	
Methyl tert-butyl ether	ND	0.050	**	**	"	u	"	"	CC-3
Surrogate: a,a,a-Trifluorotoluene		100 %	40-	140	"	ır	"	"	





3140 Gold Camp Drive #170 Rancho Cordova CA, 95670 Project: Chevron

Project Number: Chevron # 9-4800

Project Manager: Tony Mikacich

Reported:

12-Apr-01 07:40

# Diesel Hydrocarbons (C9-C24) by DHS LUFT Sequoia Analytical - Walnut Creek

Analyte	R Result	eporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
MW-7-6' (W103680-01) Soil	Sampled: 30-Mar-01 09:34	Receive	ed: 30-Mar	-01 13:00	)	<del></del>	_		
Diesel Range Hydrocarbons	ND	1.0	mg/kg	1	1D02017	02-Apr-01	04-Арг-01	DHS LUFT	
Surrogate: n-Pentacosane		85.0 %	50-1.	50	и	"	"		
MW-7-10' (W103680-02) Soil	Sampled: 30-Mar-01 09:4	0 Receiv	ved: 30-Ma	ir-01 13:0	00				
Diesel Range Hydrocarbons	ND	1.0	mg/kg	1	1D02017	02-Apr-01	04-Apr-01	DHS LUFT	
Surrogate: n-Pentacosane		79.1%	50-1.	50	"	"	"	H	
MW-7-15' (W103680-03) Soil	Sampled: 30-Mar-01 09:4	6 Receiv	ved: 30-Ma	ar-01 13:0	00				
Diesel Range Hydrocarbons	1.5	1.0	mg/kg	1	1D02017	02-Apr-01	04-Apr-01	DHS LUFT	12-06
Surrogate: n-Pentacosane		96.4 %	50-1.	50	"	п	"	ď	
MW-7-19.5' (W103680-04) So	il Sampled: 30-Mar-01 09	:55 Rece	eived: 30-N	Mar-01 13	3:00				
Diesel Range Hydrocarbons	ND	1.0	mg/kg	1	1D02017	02-Apr-01	04-Apr-01	DHS LUFT	
Surrogate: n-Pentacosane		79.1 %	50-1.	50	"	rr	n	u	
MW-7-24.5' (W103680-05) So	il Sampled: 30-Mar-01 10	:00 Rec	eived: 30-N	/lar-01 13	3:00				
Diesel Range Hydrocarbons	ND	1.0	mg/kg	1	1D02017	02-Apr-01	04-Apr-01	DHS LUFT	
Surrogate: n-Pentacosane		8.01 %	50-1.	50	"	п	"	(1	S-03
SP-1-4 (W103680-06) Soil Sa	ompled: 30-Mar-01 10:55 ]	Received:	30-Mar-0	1 13:00					
Diesel Range Hydrocarbons	ND	2.0	mg/kg	1	1C28017	30-Mar-01	03-Apr-01	DHS LUFT	
Surrogate: n-Pentacosane		100 %	50-1.	50	"	"	"	"	•





3140 Gold Camp Drive #170 Rancho Cordova CA, 95670 Project: Chevron

Project Number: Chevron # 9-4800

Project Manager: Tony Mikacich


Reported:

12-Apr-01 07:40

# Total Metals by EPA 6000/7000 Series Methods

## Sequoia Analytical - Walnut Creek

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SP-1-4 (W103680-06) Soil	Sampled: 30-Mar-01 10:55	Received:	30-Mar	-01 13:00					
Lead	2.8	1.0	mg/kg	1	1C30019	30-Mar-01	02-Apr-01	EPA 6010A	






3140 Gold Camp Drive #170 Rancho Cordova CA, 95670 Project: Chevron

Project Number: Chevron # 9-4800 Project Manager: Tony Mikacich Reported:

12-Apr-01 07:40

# Total Purgeable Hydrocarbons (C6-C12), BTEX and MTBE by DHS LUFT - Quality Control Sequoia Analytical - Walnut Creek

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes	
Batch 1D02003 - EPA 5030B MeOH											
Blank (1D02003-BLK1)				Prepared	& Analyz	ed: 02-Ap	r-01				
Purgeable Hydrocarbons	ND	1.0	mg/kg		· · · · ·						
Benzene	ND	0.0050	•								
Toluene	ND	0.0050	**								
Ethylbenzene	ND	0.0050									
Xylenes (total)	ND	0.0050	**								
Methyl tert-butyl ether	ND	0.050	μ								
Surrogate: a,a,a-Trifluorotoluene	0.682		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	0.600		114	40-140				
LCS (1D02003-BS1)		**		Prepared: 02-Apr-01 Analyzed: 03-Apr-01							
Benzene	0.528	0.0050	mg/kg	0.800		66.0	50-150				
Toluene	0.720	0.0050	"	0.800		90.0	50-150				
Ethylbenzene	0.756	0.0050	**	0.800		94.5	50-150				
Xylenes (total)	2.34	0.0050	••	2.40		97.5	50-150				
Surrogate: a.a.a-Trifluorotoluene	0.654		<i>n</i>	0.600	<u>-</u> :	109	40-140				
Matrix Spike (1D02003-MS1)	Sc	ource: W1036	80-01	Prepared: 02-Apr-01 Analyzed: 05-Apr-01							
Benzene	0.610	0.0050	mg/kg	0.800	ND	76,3	50-150				
Toluene	0.758	0.0050	н	0.800	ND	94.8	50-150				
Ethylbenzene	0.800	0.0050	n	0.800	ND	100	50-150				
Xylenes (total)	2.47	0.0050	"	2.40	ND	103	50-150				
Surrogate: a.a.a-Trifluorotoluene	0.482		IJ	0.600		80.3	40-140	-			
Matrix Spike Dup (1D02003-MSD1)	trix Spike Dup (1D02003-MSD1) Source: W103680-01			Prepared: 02-Apr-01 Analyzed: 05-Apr-01							
Benzene	0.650	0.0050	mg/kg	0.800	ND	81.2	50-150	6.35	20		
Toluene	0.752	0.0050	U	0.800	ND	94.0	50-150	0.795	20		
Ethylhenzene	0.800	0.0050	11	0.800	ND	100	50-150	0	20		
Xylenes (total)	2.45	0.0050	п	2.40	ND	102	50-150	0.813	20		
Surrogate: a.a.a-Trifluorotoluene	0.472			0.600		78.7	40-140				



Gettler Ryan, Inc. - Rancho Cordova 3140 Gold Camp Drive, #170


3140 Gold Camp Drive #170 Rancho Cordova CA, 95670 Project: Chevron

Project Number: Chevron # 9-4800 Project Manager: Tony Mikacich Reported:

12-Apr-01 07:40

# Diesel Hydrocarbons (C9-C24) by DHS LUFT - Quality Control Sequoia Analytical - Walnut Creek

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes	
Batch 1C28017 - EPA 3550A						-					
Blank (1C28017-BLK1)				Prepared:	28-Mar-0	1 Analyz	ed: 03-Apr	:-01			
Diesel Range Hydrocarbons	ND	1.0	mg/kg								
Surrogate: n-Pentacosane	1.59		· · · · · · · · · · · · · · · · · · ·	1.11	<del></del>	143	50-150		· · · · · · · ·		
Blank (1C28017-BLK2)				Prepared:	30-Mar-0	1 Analyz	ed: 03-Apı	r-01			
Diesel Range Hydrocarbons	ND	1.0	mg/kg								
Surrogate: n-Pentacosane	0.889		n	1.11		80.1	50-150				
LCS (1C28017-BS1)				Prepared:	28-Mar-0	1 Analyz	ed: 03-Api	r-01			
Diesel Range Hydrocarbons	14.0	1.0	mg/kg	15.0		93.3	60-140				
Surrogate: n-Pentacosane	1.70		"	1.11		153	50-150			S-05	
LCS (1C28017-BS2)				Prepared: 30-Mar-01 Analyzed: 03-Apr-01							
Diesel Range Hydrocarbons	8.90	1.0	mg/kg	15.0		59.3	60-140	••		Q-01	
Surrogate: n-Pentacosane	0.944		и	1.11		85.0	50-150		•		
LCS Dup (1C28017-BSD1)				Prepared: 28-Mar-01 Analyzed: 03-Apr-01							
Diesel Range Hydrocarbons	16.7	1.0	mg/kg	15.0		111	60-140	17.6	40		
Surrogate: n-Pentacosane	1.91	,	и	1.11	<del></del>	172	50-150			S-03	
Matrix Spike (1C28017-MS1)	Se	ource: W1036	19-01	Prepared: 28-Mar-01 Analyzed: 03-Apr-01							
Diesel Range Hydrocarbons	60.0	1.0	mg/kg	15.0	43	113	50-150				
Surrogate: n-Pentacosane	2.44		n	1.11		220	50-150			S-0.	
Matrix Spike Dup (1C28017-MSD1)	Source: W103619-01			Prepared: 28-Mar-01 Analyzed: 03-Apr-01							
Diesel Range Hydrocarbons	94.7	1.0	mg/kg	15.0	43	345	50-150	44.9	50	Q-01	
Surrogate: n-Pentacoxane	2.36		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1.11		213	50-150			S-0.	





Gettler Ryan, Inc. - Rancho Cordova 3140 Gold Camp Drive #170

Rancho Cordova CA, 95670


Project: Chevron

Project Number: Chevron # 9-4800 Project Manager: Tony Mikacich Reported:

12-Apr-01 07:40

# Diesel Hydrocarbons (C9-C24) by DHS LUFT - Quality Control Sequoia Analytical - Walnut Creek

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1D02017 - EPA 3510B										
Blank (1D02017-BLK1)				Prepared:	02 <b>-A</b> pr-0	l Analyze	d: 03-Apr	-01		
Diesel Range Hydrocarbons	ND	1.0	mg/kg							
Surrogate: n-Pentacosane	0.722		II.	1.11		65.0	50-150			
LCS (1D02017-BS1)				Prepared: 02-Apr-01 Analyzed: 03-Apr-01						
Diesel Range Hydrocarbons	11.7	1.0	mg/kg	15.0		78.0	60-140			
Surrogate: n-Pentacosane	0.777		"	1.11		70.0	50-150		· · · · · · ·	
LCS Dup (1D02017-BSD1)				Prepared: 02-Apr-01 Analyzed: 03-Apr-01						
Diesel Range Hydrocarbons	10.6	1.0	mg/kg	15.0		70.7	60-140	9.87	40	
Surrogate: n-Pentacosane	0.700		"	1.11		63.1	50-150		•	
Matrix Spike (1D02017-MS1)	So	ource: W1036	95-01	Prepared: 02-Apr-01 Analyzed: 03-Apr-01						Q-0
Diesel Range Hydrocarbons	7.88	2.0	mg/kg	15.0	5.4	16.5	50-150		•	
Surrogate: n-Pentacosane	1.73		"	1.11		156	50-150	<del> </del>		S-0-
Matrix Spike Dup (1D02017-MSD1)	Source: W103695-01			Prepared: 02-Apr-01 Analyzed: 03-Apr-01						Q-01
Diesel Range Hydrocarbons	7.88	2.0	mg/kg	15.0	5.4	16.5	50-150	0	50	
Surrogate: n-Pentacosane	1.41		"	1.11		127	50-150			





3140 Gold Camp Drive #170 Rancho Cordova CA, 95670 Project: Chevron

Project Number: Chevron # 9-4800


Project Manager: Tony Mikacich

Reported:

12-Apr-01 07:40

# Total Metals by EPA 6000/7000 Series Methods - Quality Control Sequoia Analytical - Walnut Creek

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes	
Batch 1C30019 - EPA 3050B											
Blank (1C30019-BLK1)				Prepared:	30-Mar-0	l Analyze	ed: 02-Apr	-01			
Lead	ND	1.0	mg/kg						-		
LCS (1C30019-BS1)				Prepared:	30-Mar-0	1 Analyze	ed: 02- <b>A</b> pr	-01			
Lead	49.5	1.0	mg/kg	50.0		99.0	80-120				
LCS Dup (1C30019-BSD1)					Prepared: 30-Mar-01 Analyzed: 02-Apr-01						
Lead	50.7	1.0	mg/kg	50,0	~	101	80-120	2.40	20		



404 N. Wiget Lane Wainut Creek, CA 94598 (925) 988-9600 FAX (925) 988-9673 www.sequoialabs.com

Gettler Ryan, Inc. - Rancho Cordova 3140 Gold Camp Drive #170

3140 Gold Camp Drive #170 Project Nu Rancho Cordova CA, 95670 Project Mar

Project: Chevron
Project Number: Chevron # 9-4800
Project Manager: Tony Mikacich

**Reported:** 12-Apr-01 07:40

#### **Notes and Definitions**

CC-3	Continuing Calibration indicates that the quantitative result for this analyte includes a greater than 15% degree of uncertainty. The
	value as reported is within method acceptance.

D-06 Discrete peaks.

Q-01 The spike recovery for this QC sample is outside of established control limits. Review of associated batch QC indicates the recovery for this analyte does not represent an out-of-control condition for the batch.

S-03 The surrogate recovery for this sample is outside of established control limits. Review of associated QC indicates the recovery for this surrogate does not represent an out-of-control condition.

S-04 The surrogate recovery for this sample is outside of established control limits due to a sample matrix effect.


DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis

RPD Relative Percent Difference



404 N. Wiger Lane Walnut Creek, CA 94598 (\$25) 988-9600 7AX (925) 988-9673 www.segubiatans.com

Gettier Ryan, Inc. - Dublin 6747 Sierm Court Suite J Dublin CA, 94568

Project: Chevron Project Number: Chevron # 9-4800 Project Manager Deanna L. Harding

Reported: 22-May-01 10:31

# ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory (D	Matrix	Date Sampled	Date Received
TA-LB	W105122-01	Water	04-May-01 00:00	04-May-01 15:25
MW-l	W105122-02	Water	04-May-01 13:40	04-May-01 15:25
MW-2	W105122-03	Water	04-May-01 14:19	04-May-01 15:25
MW-3	W105122-04	Water	94-May-01 12:36	04-May-01 15:25
MW-4	W105122-05	Water	04-May-01 13:03	04-May-01 15:25
MW-6	W105122-06	Water	04-May-01 12:18	04-May-01 15:25
MW-7	W105122-07	Water	04-May-01 15:10	04-May-01 15:25


Sequoia Analytical - Walnut Creek

Charlis Westwater, Project Manager

The results in this report apply to the camples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Page 1 of 11

FROM : GETTLER RYAN INC



404 N. Wiger Land Watner Creek, CA 94598 (925) 988-9600 FAX (925) 988-9673 www.seguoialaus.com


Gettler Ryan, Inc. - Dublin 6747 Sierra Court Scite I Dublin CA, 94568

Project: Chevron

Project Number: Chevron # 9-4800 Project Manager: Deanna L. Harding Reported: 22-May-01 10:31

## Diesel Hydrocarbons (C9-C24) by DHS LUFT Sequoia Analytical - Walnut Creek

Analyte	Re Resuk	porting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
MW-1 (W105122-02) Water	Sampled: 04-May-01 13:40	Receive	d: 04-M:	ay-01 15:2:	5		_		
Diesei Range Hydrocarbons	130	50	ug/l	1	1E17008	17-May-01	17-May-01	EPA 8015M	<b>D-14</b>
Surrogate: n-Pentacosane		77.2 %	50-	150	#	7	"	"	
MW-2 (W105122-03) Water	Sampled: (14-May-61 14:19	Receive	d: 04-M:	ny-01 15:2:	5				
Diesel Range Hydrocarbons	3100	50	ug/l	1	1E17008	17-May-01	17-May-01	EPA 8015M	D-14
Surrogate: n-Pentacoxane		!!!%	50-	150	H	#	"	0	
MW-3 (W105]22-04) Water	Sampled: 04-May-01 12:36	Receive	d: <b>04-M</b> :	py-01 15:25	5				
Diesei Range Hydrocarbons	ND	50	ug/i	1	1E17008	17-May-01	17-May-01	EPA 8015M	
Surrogate: n-Pentacosune		73.1 %	50-	150	"	ų.	"	tr	
MW-4 (W105122-05) Water	Sampled: 04-May-01 13:03	Receive	d: <b>04-M</b> :	ay-01 15:2:	5				
Diesei Range Hydrocarbons	1100	50	112/1	1	1217008	17-May-01	17-May-01	EPA 8015M	D-14
Surrogate: n-Pentacosane		125 %	50-	150	"	#	"	u	
MW-6 (W105)22-06) Water	Sampled: 04-May-01 12:18	Roccive	d: 04-Ms	ay-01 15:2:	S				
Diesel Range Hydrocarbons	ND	50	ug/i	1	1517008	17-May-01	17-May-01	EPA 8015M	
Surrogate: n-Pentacosane		68.2 %	50-	150	"	2	4	И	_
MW-7 (W105122-07) Water	Sampled: 04-May-01 15:10	Receive	d: 04-Ms	ay-01 15:25	5				
Diesel Range Hydrocarbons	ND	50	u <b>g/1</b>	1	1E17008	17-May-01	17-May-0.	EPA 8015M	
Surrogate: n-Pentacasane		87.1 %	50-	150	и	4	ď	7	



404 N. Wiget Land Welcut Croek, CA 94598 (925) 988-9600 FAX (925) 988-9673 www.sequoiatans.com

Gettler Ryan, Inc. - Dublin 6747 Signa Court Suite J

Duhlin CA, 94568

Project: Chevron

Project Number: Chevron # 9-4800


Project Manager: Deanna L. Harding

Reported:

22-May-01 10:31

## Volatile Organic Compounds by EPA Method 8260B Sequoia Analytical - Walnut Creek

Analyte	Resuli	porting Limit	Units	Dilotion	Batch	Prepared	Analyzed	Mathod	Notes
MW-7 (W105122-07) Water	Sampled: 04-May-01 15:10	Receive	zi: 04-M	y-01 15:2	5				
Ethanol	ND	500	الود	1	1E11003	16-May-01	16-May-01	EPA 8260B	
tert-Butyl alcohol	57	20	4	Þ	u	"	Ħ	ij	
Methyl tart-butyl ether	470	10	н	5		н	17-May-01	U	
Di-isopropyl ether	ND	2.G	ıı	1	(I		16-May-01	n	
Ethyl tert-buryl ether	ND	2.0	14	**	н	4			
tert-Amyl methyl ether	11	2.0	14	н	lı	4	**	я	
Surrogate: Dibromofhiorometh	ane	90.0%	50-	30	"	ıt	"	14	
Surrugate: 1,2-Dichloroethane	-d4	90.0 %	50-,	150	"	*	"	u	



404 N. Wiget cane Walnut Creek, CA 94598 (925) 988-9600 IAX (925) 988-9673 www.seguo.alabs.com

Gettler Ryan, inc. - Dublin 6747 Sierra Court Suite J Dublin CA, 94568


Project: Chevron

Project Number: Chevron # 9-4800 Project Manager: Deanna L. Harding Reported: 22-May-01 10:31

Total Petroleum Hydrocarbons as Gasoline by EPA 8015M

#### Great Lakes Analytical

		porting							
Analyte	Result	Limii	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
TB-LB (W105122-01) Water	Sampled: 04-May-01 00:00	Receiv	ed: 04-N	fay-01 15:2	5				
Gasoline	ND	50.0	ug/l	ì	1050388	17-May-01	18-May-01	EPA 8015M-YOA	
MW-1 (W105122-02) Water	Sampled: 04-May-01 13:40	Receive	sd: 04-M	ay-01 15:2	5				
Gasoline	991	50.0	ug/l	1	1050388	17-May-01	18-May-01	EPA 2015M-VOA	T
MW-2 (W105122-03) Water	Sampled: 04-May-01 14:19	Recuire	xi: 04-M	ay-01 15:2:	5				
Gasoline	11900	1250	ugʻl	25	1050388	17-May-C1	18-May-01	EPA 8015M-VOA	G12,T
MW-3 (W105122-04) Water	Sampled: 04-May-01 12:36	Receive	d: 04-M	ay-01 15:2:	5				
Gusoline	1260	50.0	o⊌]i	1	10 <b>5038</b> K	17-May-61	18-May-01	EPA 8015M-VOA	Tì
MW-4 (W105122-05) Weter	Sampled: 04-May-01 13:03	Receive	ed: 04-M	ay-01 15:2:	5				
Gasoline	722	50.0	ugl	1	1050388	17-May-01	18-May-01	EPA 8015M-VOA	11
MW-6 (W105122-06) Water	Sampled: 04-May-01 12:18	Receive	ы: 04- <b>М</b>	ay-01 15:25	5				
Gasoline	ND	50.0	ug/l	1	1050388	17-May-01	18-May-01	EPA 8015M-VOA	
MW-7 (W105122-07) Water	Sumpled: 04-May-01 15:10	Receive	d: 04-M	ay-01 15:25	Ś				
Gasoline	ND	50.0	ugd	1	1050388	17-May-01	18-May-01	EPA 8015M-VOA	· · · · · · · · · · · · · · · · · · ·



404 N. Wiger Lane Walnut Creek, CA 94598 (925) 988-9600 TAX (925) 988-9673 www.sequoialabs.com

Gettler Ryan, Inc. - Dublin 6747 Sierra Court Suite J Dublin CA, 94568

Project: Chevron

Project Number: Chevron # 9-4800

Project Manager: Deanna L. Harding

Reported:


22-May-01 10:31

## BTEX+MTBE by EPA Method 8021B

#### Great Lakes Analytical

Analyte	Result	eporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
<u> </u>						1 teheted	/ Hulyaco	Memor	14/7/25
TB-LB (W105122-01) Water			ed: 04-M	lay-01 15:2	5	· · · · · · · · · · · ·			
Benzene	ND	0.500	սաջ∕1	1	1050388	17-May-01	18-May-01	EPA 8021B	
Toluene	ДN	5.00		4	p	•	1	*	
Ethylbenzene	מא	5.00		ħ	11	"	lı	+	
Total Xylenes	ND	5,00	il		**	•	*	II	
Methyl text-butyl ether	מא	0.500	n	n	-	P		п	
Swrogote: 4-BFB		101%	41.8	-147	**	۲	л	77	·
MW-1 (W105122-02) Water	Sampled: 04-May-01 13:40	Receive	:d: 04-M	ay-01 15:2	3				
Benzene	127	-0.500	ug/i	1	1050388	17-Mey-01	18-May-01	EPA 90218	
Toluene	32.6	5.00	4	ti	u	•	"	и	
Ethylbonzene	73,0	5.00	"	41	и	22	н	at .	
Total Xylenes	137	5.00	•	11	91	. *	И	14	
Methyl tert-butyl ether	95.4	0.500	н	11	н	Ħ	н	<del>-</del>	
Surrogute. 4-BFB	· · · · · · · · · · · · · · · · · · ·	124 %	41.8	-147	н		P	#	<del></del> -
MW-2 (W105122-03) Water	Sampled: 04-May-01 14:19	Receive	d: 04-M	ay-01 15:25	<b>i</b>				
Benzene	199	0.500	ug/1	Ĭ	1050388	17-May-01	18-May-01	EPA 8021B	
Toluene	33.9	5.00	<b>61</b>	Iţ.	<b>)1</b>	r	29	10	
Ethylbenzene	1420	125	н	25	tr	k	18-May-01	Ç1	G12
Total Xylenes	290	5.00	н	1	*	•	18-May-01	9	
Methyl teri-butyl other	3896	12.5	H	25	*		18-May-01	ii.	G12
Storogate: 4-BFB		262 %	41.8	-147	.,	*	18-May-01	"	<i>3</i> 5
MW-3 (W105122-04) Water	Sampled: 04-May-01 12:36	Receive	d: (I4-M	ay-61 15:25	5				
Benzene	146	0.500	บอ/เ	İ	1050388	17-May-01	18-May-01	EPA 8021B	<del></del>
Toluene	79.6	5.00	n	ti	a	Þ	11	·	
E thylbenzene	38.2	5.00	Ħ	h	77	ŧ*	11	•	
Total Xylenes	101	5.00		u	4	Ħ	*1	•	
Methyl tert-butyl ether	1070	5.00	"	10	**	77	JR-May-01	•	312
Surroyau: 4-BFE		95.5 %	41.8	-147	II.	4	18-May-01	e e e e e e e e e e e e e e e e e e e	

FAX NO. : 9255517899



404 N. Wiger Lane Walnut Creek, CA 945/28 (925) 988-9600 FAX (925) 988-9673 www.sequolalabs.com

Gettler Ryan, Inc. - Dublin 6747 Sierra Court Seile J Dublin CA, 94568 Project: Chevron

Project Number: Chevron # 9-4800


Project Manager: Deanna L. Harding

Reported: 22-May-0] 10:31

## BTEX+MTBE by EPA Method 8021B

#### Great Lakes Analytical

	Re	porting							
Analyte	Result	Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
MW-4 (W105122-05) Water	Sampled: 04-May-01 13:03	Receive	d: <b>04-</b> M	ay-01 15:2	5				
Benzene	12.0	0,500	प्रद्य/1	Ţ	1050388	17-May-01	18-May-01	EPA 8021B	
Toluëne	ND	5.00	#1	P	i#	ıí	*	ч	
Ethylbenzene	37.X	5.00	*	11	4	•	4	ŧi	
Total Xylenes	89.4	5.00	74	1	н	4	**	н	
Methyl tert-hutyl ether	2390	25.0		50	**		18-Mav-01	н	G)2
Surrogate: 4-BFB	++-	110 %	41.8	1-147	11	7	18-31ay-01	n	
MW-6 (W105122-06) Water	Sampled: 04-May-01 12:18	Recuive	d: 04-M	ay-01 15:2	5				
Велиспе	ND	0.500	ug l	1	1050388	17-May-01	18-May-01	EPA 8021B	
Toluene	ND	5.00	**	"	**	"	₩	#	
Ethylbonzene	ND	5.00	2.7	ч	H	y	şe.	•	
Totai Xyienes	ND	5.00	1*	н	i†	1	п	->	
Methyl tert-buryl other	2.74	0.500	и	h	•	•1	и	4	
Surrogate: 4-BFB	The same of the sa	86.5 %	41.8	-147	r#	н	"	11	
MW-7 (W105122-07) Water	Sampled: 04-May-01 15:10	Receive	d: 04-M	ay-01 15:2:	5				
Benzene	MD	0.500	ug/l	1	1050388	17-May-01	18-May-01	EPA 8021B	
Toluene	ND	5.00		#	4	lt.	μ	d	
Ethylbenzene	מא	5.00	•	••	*:	н	15	-3	
Yotal Xylanes	ND	5,00	-t	**	•	Þ	14	o	
Methy) tert-butyl ether	567	5.00	A	10	**	11	18-May-01	-	Giž
Surrogate: 4-BFB		108 %	41.8	-147	"	er.	18-May-01		



404 N. Wiget Lane Walnut Creek, CA 94598 (925) 988-9600 1AX (925) 988-9671 AWA sequolalabs.com

Gettler Ryan, inc. Dublin 6747 Sterra Court State J Dublin CA, 94568


Project: Chevron

Project Number: Chevron # 9-4800 Project Manager: Deanna L. Harding Reported:

22-May-01 10:31

## Diesel Hydrocarbons (C9-C24) by DHS LUFT - Quality Control Sequoia Analytical - Walnut Creek

Analyte	<b>Re</b> sult	Reporting Limit	Unus	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1E17008 - EPA 3510B										
Blank (1E17008-BLK1)				Prepared	& Analyz	ed: 17 <b>-Ma</b>	y-01			
Diesel Range Hydrocarbons	מא	50	ուն/լ							
Surregate: n-Pontacoyane	28.0		1	33.3		59.I	59-150			Mary Land (
LCS (1E17008-BS1)				Prepared	& Anaiyz	ed: 17-Ma	y-01			
Diesel Rango Hydrocarbons	401	30	ug/l	500	<del></del>	¥0.1	60-140			
Surrogate: n-Pentacorane	33.7		, u	33.3		71.2	50-150			
LCS Dup (1E17008-BSD1)				Prepared	& Analyza	ed: 17-Ma	y-01			
Diesel Range Hydrocarbous	411	50	ug/	500		82.2	60-140	2 46	5Ç	<del></del>
Surregate: n-Pensacosane	23.3			33.3	······································	70.0	50-150		<del></del>	- <del></del>



464 N. Wiger Line Wainut Creek, CA 94598 (925) 988-9600 FAX (925) 988-9673 www.sequolalabs.com

Gettler Ryan, Inc. - Oublin 6747 Sierra Court Suite J Dublin CA, 94568

Project: Chevron


Project Number: Chevron # 9-4800

Project Manager: Deanna L. Harding

Reported: 22-May-01 10:31

## Volatile Organic Compounds by EPA Method 8260B - Quality Control Sequoia Analytical - Walnut Creek

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1E11003 - EPA 5030B (P/T)									•	
Blank (IE11003-BLK1)				Prepared.	& Analyz	d: 16-Ma	y-01		<i>"</i>	
Ethinol	ND	500	นยู/โ		· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·		·
tert-Butyl Alcohol	ND	20	**							
Methyl tert-butyl other	ND	2.0								
Di-sopropyl ether	NTD	2.3	1							
Ethyl tert-butyi cther	ND	2.0	*							
tert-Amy! methyl ether	ND	2.0	•							
Surrogate: Dibramafinaromathane	47.1		7,25	50.0		94.2	50-1 <b>50</b>		•	
Surroguse: 1,2-Dichloroetham-44	40.6		1	500		81.2	50 <b>-130</b>			
LCS (1E11003-BS1)				Prepared a	& Analyz	:d: 16-Ma	y-01			
Methyl terubutyl ether	49.2	2.0	ug/i	50.0		98.4	70-130		•	
Surrogate: Dibroim/fluoramethane	47.9		lf .	50.0		95.8	50-150			
Surrogale: 1.2-Dichloroethane-d-	37.8		μ	50.0		75.6	50-150			
Matrix Spike (IE11003-MS1)	So	arce: W1050	49-04	Prepared a	& Analyze	:d: 16•Ma	y-01			
Methyl termbutyt ether	44.1	2.0	u <b>y</b> /l	50.0	ND	88.2	60-150		,_	
Surrogate: Dibromoftworometiume	48.O		V	50.6		96.0	\$0-150			
Surroyats: 1,2-Dichiaroctham-44	43.0		•	50.0		56.0	50-150			
Matrix Spike Dup (1E11003-MSD1)	So	urce: W1050	49-04	Prepared a	& Analyza	d: 16-Ma;	y <b>-</b> 01			
Mathyl tert-bulyl other	54.4	2.0	ยช/เ	50.0	ND	109	60-150	20.9	25	,
Surrogate: Dibromoftuoremethene	48.0		r	50.6		96.0	50-150			
Surrogate: 1.2-Dichioroethane-d4	53.0		-	50.0		106	50-150			



404 N. Wiget Land Walnut Creek, CA 94598 (925) 988-9600 FAX (925) 988-9673 Www.seguoialabs.com

Gettler Ryan, Inc. - Dublin

6747 Sierra Court Suite J Dublin CA, 94568 Project. Chevrun


Project Number: Chavron # 9-4800

Project Manager: Deanna L. Harding

Reported: 22-May-01 10:31

# Total Petroleum Hydrocarbons as Gasoline by EPA 8015M - Quality Control Great Lakes Analytical

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limita	RPD	RPD Limit	Notes
Batch 1050388 - EPA 5030B (P/T)							·*		-	
Blank (1050388-BLK1)				Prepared	& Analyzo	cd: 17-Ma	y-01	. ·- tyt		
Gasoline	ND	59.0	កជារ							
LCS (1050388-BS2)				Prepared.	& Analyze	ed: 17-Ma	ıy-(i)			
Gastrine	2220	30.0	194	2000		III	85.1-124	± 4.1 <sub>2</sub>		
Matrix Spike (1050388-MS2)	So	urce: B10516	5-04	Prepared:	17- <b>May-</b> 0	)i Analyz	ed: 19-May	y=01		
G190,iae	1880	50.0	ug/l	2000	ND	54.0	69.6-142			. P
Matrix Spike Dup (1050388-MSD2)	So	urce: B10516	5-04	Prepared:	1 <b>7-Ma</b> y-0	l Analyz	ad: 19-Maj	y-01		
Casoline	1980	50.0	ug/l	2000	ND	99.0	69.6-142	5.18	33.7	



904 N. Wiger Lane Wainut Creek, CA 94598 (925) 988-9600 FAX (925) 988-9673 www.acquotalaus.com

Gettler Ryan, Inc. - Dublin 6747 Sierra Court, Suite J Dublin CA, 94568

Project Chevron


Project Number: Chevron # 9-4800

Project Manager: Deanna L. Harding

Reported: 22-May-01 10:31

## BTEXTMTBE by EPA Method 8021B - Quality Control Great Lakes Analytical

Analyte	Result	Reporting Limit	Units	Spike Lavel	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1050388 - EPA 5030B (P/T)									· <del>·</del>	
Blank (1050288-BLK1)				Prepared	& Analyzo	d: 17-M	av-61		•	
Benzenc	, dr	0.500	ug/l							
Toluene	ND	5,00	11							
Ethylbenzene	ND	5.00	,,							
Total Xylenes	GR	5.00	+							
Methyl tert-butyl ether	ND	9.500	1							
Surrogate: 4-KFB	19.5		10	20.0		97.5	41.8-147			
LCS (10503#8-BS1)				Prepared:	17-May-()	l Analyz	ed: 18-Ma	v-01		
Ecnzone	25.8	0.500	ugi	25.0		103	74.8-116	,		
Toluene	27.3	5.00	4	25.0		109	75.9-116			
Ethylbenzene	26.4	5.00	ii	25.0		166	73.8-117			
Fotal Xylenes	21.9	5.00		75.C		109	72,6-122			
Mothyl tert-hutyl ether	24.3	0.500	*	25 e		97.2	73.2-123			
iurengate: 4-BFB	22.6		,	20.0		116	41.8-147			
Matrix Spike (1050388-MS1)	So	urce: B10516	5-04	Prepared:	17-May-0	l Analyz	ed: 19 <b>-Ma</b> r	v-01		
Benzene	23.2	0.500	ug/i	25.C	ND	92.8	34.2-160			
l'oluena	22.6	5.00	1"	25.0	ND	90.4	30.8-161			
Lihyibenzane	22.9	5.00	1-	25.0	ND	916	34.8-163			
otal Xylenes	64.3	5.00	r	75.0	ND	85.7	32.9-160			
dethyl ten-butyl ether	23.6	C.500	۴	25.0	ND	94.4	10.0-282			
urrogae: 1-BFB	19.4	<del></del>		20.6	v	27.6	41.8-147			
Matrix Spike Dup (1050388-MSD1)	So	urce: B10516:	5-4)4	Prepared:	17-May-0	l Anaiyz	ed: 19-Mar	v-01		
lenzeno	22.8	0.500	ug/l	25.0	ND	91.2	34.2-160	1.74	37.0	
'oluene	22.9	5.00	11	25.0	ND	91.6	30.8-161	1.32	27.3	
thythenzeas	22.7	5.00	н	25.0	ממ	90.8	34.8-163	0.877	28.0	
otal Xylenes	64.9	5.00	n	75,0	ND	86.5	32.9-160	0.929	28.1	
fethyl tert-butyl ether	22.4	0.500	<b>9</b> T	25.0	ND	89.6	10.0-282	5.22	79.4	
wrogais: 4-BFB	12.8		- n	20.0		94.0	11.8-147			



404 N. Wiger Lane Weinut Creek, CA 94598 (925) 988-9600 FAX (925) 988-9673 WWW.sequolalabs.com

Gettler Ryan, Inc. - Dublin 6747 Storra Court Suite J Dublin CA, 94568

Project: Chevron

Project Number: Chevron # 9-4800

Project Manager Deanna L. Harding

Reported:

22-May-01 10:31

#### Notes and Definitions

D-14 Chromatogram Pattern: Unidentified Hydrocarbons C9-C24

G12 The reporting limit of this sample/analyte is elevated due to sample matrix and/or other effects.

O5 The recovery for this analyte is above the laboratory's established acceptance criteria.

TI Gas Pattern

DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis

RPD Relative Percent Difference

LI Yes Fax copy of Lab Report and COC to Chevron Contact: No Chain-of-Custody-Record Chevroe Feelily Humber #9-4800 Chinron Contact (Marrie) MR. TOM BAUHS Faultly Address 1700 CASTRO ST., OAKLAND, CA. (Phone) (925) 842-8898 Chevron Products Co. Consultant Project Humber 386383 Laboratory Home SEQUOIA P.O. BOX 8004 Consulted Name GETTLER-RYAN INC. Leberalary Service Order Son Roman, CA 94583 RYPE IN Address 6747 SIERRA COURT, SUITE J, DUBLIN, CA 94568 FAX (925)842-8370 **Estoratori Service Code** FRANKH Freject Contact (Name) DEANNA L. HARDING (Phone) 925-551-7555 (Fex Number) 925-551-7899 State Method: MZ CA | OR | WA | NW Series | CO | UT IDAKO Remarks (5) (0938) BEX + 1774 GAS (BCZD + BC)(S) Entractable Organi (8270) (0104) (8015) Lab Sample Né. 5-4-01 HCL 73-LB /3:40 Mw-1 02 A-D 9255517899 14:19 mw2 12:36 mw3 13:03 Mw4 12:18 mw 6 07A-F 15:10 mw7 И 28:33AM Rainepiched By (Signature) Organization Date/Ilma Received By (Signature) Organization Date/Time iced Y/N Turn Around Time (Circle Choice) G-R INC. 24 Hrs. Ritaguished By (Signature) Organization Date/Iller Revelyed By (Signature) Orgonization Date/Time ked Y/N 5 Days 10 Days-Relagatolist By (Signature) Organization . Date/Ilms Reclayed For Laboratory By (Signature) Bol4/Ilme