


ACTIVITY RECORD



RO #: 000034-8
DATE: Oct 20, 2009
TIME: _____

- Meeting
- Site Visit/Inspection
- Telephone Conversation
- Document Review
- Peer Review

HAZ MAT SPECIALIST: Paresh Khatri
Work Location: 1131 Harbor Bay Pkwy, Alameda
Conferee('s): Daniel Bergin (GeoHydrologic)
Vicky Hamlin (ALCO Public Works)
Phone # _____

SITE NAME & ADDRESS: THRIFTY OIL #54, 2504 Castro Valley Blvd.
TOPIC: Monitoring Well Destruction for case closure.
SUMMARY: _____

Arrived onsite, met w/ Test Menca (Daniel Bergin) GeoHydrologic.

Well RS-11 (TD = 25 ft) OFF-SITE Well.

Wells are being drilled out and ^{grouted via} extreme-pipe.

Also met w/ Vicky Hamlin w/ ALCO public works.

The off-site monitoring wells are being abandoned first with the onsite wells to be abandoned last.

Left site.