



HARTCROWSER

Earth and Environmental Technologies

Hart Crowser, Inc.
353 Sacramento Street Suite 1140
San Francisco, California 94111
FAX 415.391.2216
415.391.1885

August 1, 1990

Shell Oil Company
511 N. Brookhurst Street
P. O. Box 4848
Anaheim, California 92803

Attn: Mr. Paul Hayes

Re: 90-Day Progress Report
Shell Service Station
4226 First Street
Pleasanton, California Project J-6006

Dear Mr. Hayes:

This letter constitutes a 90-Day Progress Report for May through July 1990 on the site assessment Hart Crowser is conducting at the above-referenced site. On April 23, 1990, we presented you with a supplemental site assessment report for this site. Since that time, we have drilled two additional soil borings onsite.

Borings

On July 17, 1990, two soil borings were drilled to a depth of approximately 50 feet below ground surface (See Figure 1 for locations). The borings were drilled with a truck-mounted drilling rig using eight inch diameter hollow stem augers. Groundwater was not encountered in either of the borings. Soil samples were collected every five feet during drilling. A total of six soil

ENVIRONMENTAL
AUG 06 1990
ENGINEERING



samples were submitted to an analytical laboratory for analysis. Results of this testing will be included in a forthcoming report.

Our planned activities for the future include analysis of chemical data and compilation of a report of findings for this latest phase of investigation.

If there are any questions or comments, please do not hesitate to call.

Sincerely,

HART CROWSER, INC.


A handwritten signature in black ink, appearing to read 'Eric Schniewind', is written over a horizontal line.

Eric Schniewind
Senior Staff Hydrogeologist






ETS/ar

Attachments: Figure 1 - Site Plan

cc: Ms. Diane Lundquist, Shell Oil Company
 Mr. Tom Callaghan, Regional Water Quality Control Board
 Mr. Rick Mueller, Pleasanton Fire Department



Legend

-  Planter Area
-  Subsurface Waste Oil Tank Location
-  Abandoned Monitoring Well
-  Location of Hart Crowser Borings
-  Location of EMCON Borings

SITE PLAN
 4226 First Street
 Pleasanton, California


HARTCROWSER

J-6006 8/90
 Figure 1