


UNDERGROUND STORAGE TANK (UST) SITE - UNAUTHORIZED RELEASE / CONTAMINATION REPORT

EMERGENCY <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.	
REPORT DATE		CASE #		SIGNED _____ DATE _____	
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT Corissa Lutz		PHONE (510) 763-2911		SIGNATURE 
	REPRESENTING <input type="checkbox"/> LOCAL AGENCY <input type="checkbox"/> REGIONAL BOARD <input checked="" type="checkbox"/> OWNER/OPERATOR <input type="checkbox"/> OTHER		COMPANY OR AGENCY NAME Balco Properties LTD, LLC		
RESPONSIBLE PARTY	ADDRESS 1624 Franklin Street, Suite 1115		Oakland		CA 94612
	STREET		CITY		STATE ZIP
SITE LOCATION	NAME Balco Properties LTD, LLC		<input type="checkbox"/> Unknown		CONTACT PERSON Corissa Lutz
	ADDRESS 1624 Franklin Street, Suite 1115		Oakland		CA 94612
IMPLEMENTING AGENCIES	FACILITY NAME (IF APPLICABLE)		OPERATOR Balco Properties LTD, LLC		PHONE (510) 763-2911
	ADDRESS 2855 Mandela Parkway		Oakland		Alameda 94612
	STREET		CITY		COUNTY ZIP
SUBSTANCES INVOLVED	CROSS STREET Willow Street				
	LOCAL AGENCY AGENCY NAME				PHONE
DISCOVERY/ABATEMENT	Alameda County Department of Environmental Health				(510) 567-6700
	REGIONAL BOARD				PHONE
SOURCE/CAUSE	San Francisco Bay Regional Water Quality Control Board				(510) 622-2300
	(1) NAME		QUANTITY LOST (GALLONS)		
CASE TYPE	Gasoline				<input checked="" type="checkbox"/> Unknown
	(2)				<input type="checkbox"/> Unknown
CURRENT STATUS	DATE DISCOVERED June 21, 1991		HOW DISCOVERED		<input type="checkbox"/> Tank Test <input checked="" type="checkbox"/> Tank Removal <input type="checkbox"/> Nuisance Conditions
			<input type="checkbox"/> Inventory Control <input type="checkbox"/> Subsurface Monitoring <input type="checkbox"/> Other		
REMEDIAL ACTION	DATE DISCHARGE BEGAN		METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)		
	<input checked="" type="checkbox"/> Unknown		<input checked="" type="checkbox"/> Remove Contents <input type="checkbox"/> Close Tank <input type="checkbox"/> Repair Tank <input type="checkbox"/> Change Procedure <input type="checkbox"/> Replace Tank <input checked="" type="checkbox"/> Other Tank Removal <input type="checkbox"/> Repair Piping		
COMMENTS	HAS DISCHARGE BEEN STOPPED?				
	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES, DATE June 21, 1991				
REMEDIAL ACTION	SOURCE OF DISCHARGE		CAUSE(S)		
	<input checked="" type="checkbox"/> Tank <input type="checkbox"/> Piping <input type="checkbox"/> Dispenser <input type="checkbox"/> Delivery Problem <input type="checkbox"/> Submersible Turbine Pump (STP) <input type="checkbox"/> Other		<input type="checkbox"/> Spill <input type="checkbox"/> Overfill <input type="checkbox"/> Physical/Mechanical Damage <input checked="" type="checkbox"/> Corrosion <input type="checkbox"/> Installation Problem <input type="checkbox"/> Unknown <input type="checkbox"/> Other		
REMEDIAL ACTION	CHECK ONE ONLY				
	<input type="checkbox"/> Undetermined <input type="checkbox"/> Soil Only <input checked="" type="checkbox"/> Groundwater <input type="checkbox"/> Drinking Water - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)				
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S)				
	Human health exposure control? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown Groundwater migration control? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> No Action Required (NAR) <input type="checkbox"/> Excavate & Treat (ET) <input type="checkbox"/> Treatment at Hookup (TH) <input type="checkbox"/> Other <input type="checkbox"/> Excavate & Dispose (ED) <input type="checkbox"/> Free Product Removal (FPR) <input type="checkbox"/> Replace Supply (RS)				