



IT Corporation

1921 Ringwood Avenue
San Jose, CA 95131-1721
Tel. 408.453.7300
Fax. 408.437.9526

A Member of The IT Group

20391
L of 1109

February 8, 2000
Project 340-414.9C

Ms. Susan Hugo
Alameda County Health Care Services Agency
1131 Harbor Bay Parkway, 2nd Floor
Alameda, California 94502-6577

Re: **Certified List of Record Fee Title Owners for:**
Former Texaco Service Station
500 Grand Avenue at Euclid Avenue
Oakland, California
Incident No. 88870189

Dear Ms. Hugo:

In accordance with section 25297.15(a) of Chapter 6.7 of the Health Safety Code and on behalf of Equiva Services LLC, we certify that the following is a complete list of current record fee title owners and their mailing addresses for the above site.

Mr. Joseph D. Howard, Howard Family Trust, 146 Bell Ave., Piedmont, CA 94611

Sincerely,

IT Corporation

Kristen Flesoras
Project Scientist

cc: Ms. Karen Petryna, P.E., Equiva Services LLC, P.O. Box 7869, Burbank, CA 91501-7869
Mr. Joseph D. Howard, Howard Family Trust, 146 Bell Ave., Piedmont, CA 94611
Mr. Richard Hiatt, California Regional Water Quality Control Board, San Francisco Bay Region,
1515 Clay St., Ste. 1400, Oakland, CA 94612

950 E. Calaveras Blvd. At Highway 680
 Milpitas, California

Date: 5.19.99

Time of arrival on site: 7:15

Sampling Information:

3050515A

Well Number	Time beginning sample taken	Time final sample taken
Mw-1	7:45	12:15

18" FROM (2500 Gal)
 TOP OF TANK.

Depth to Water Measurements:

Well Number	Time	DTW (feet)
Mw1	7:00	10.05
	8:00	22.50
	8:30	21.65
	9:00	20.90

Well Number	Time	DTW (feet)
MW5	7:24	9.70
	8:00	9.82
	8:33	9.95
	9:03	10.00

Comments:	Time	DTW (feet)
	9:30	21.00
	10:00	18.85
	10:30	19.30
	11:00	19.55
	11:30	19.10

Comments:	Time	DTW (feet)
	9:33	10.00
	10:03	10.04
	10:34	10.08
	11:05	10.09
	11:33	10.11

Comments:	Time	DTW (feet)
	12:00	19.35
		10.90

Comments:	Time	DTW (feet)
	12:03	10.10

Comments:	Time	DTW (feet)
MW6	7:22	10.21
	8:01	10.55
	8:32	10.09
	9:02	10.70
	9:30	10.75

Comments:	Time	DTW (feet)

Comments:	Time	DTW (feet)
	10:02	10.79
	10:30	10.81
	11:03	10.83
	11:30	10.85
	12:02	10.80

Comments:	Time	DTW (feet)



SHELL OIL COMPANY 3050515A
 RETAIL ENVIRONMENTAL ENGINEERING - WEST

CHAIN OF CUSTODY RECORD
 Serial No: _____

Date: 5-17-99
 Page 1 of 1

Site Address: 950 E. CALAVERAS BLVD. Milpitas

WIC#: 204 4962 0309

Shell Engineer: _____ Phone No.: _____
 Fax #: _____

Consultant Name & Address:
 PACIFIC ENVIRONMENTAL GROUP, INC.
 2025 GATEWAY PLACE, Ste. 440 SAN JOSE, CALIFORNIA 95110

Consultant Contact: JANET MARTIN Phone No.: 408
 441-7500
 Fax #: 441-9102

Comments: _____

Sampled by: _____

Printed Name: PEDRO E. RUIZ

Analysis Required

TPH (EPA 8015 Mod. Gas)	TPH (EPA 8015 Mod. Diesel)	BTEX (EPA 8020/602)	Volatile Organics (EPA 8240)	Test for Disposal	Combination TPH 8015 & BTEX 8020	Asbestos	Container Size	Preparation Used	Composite Y/N
					<u>MTBE by 80250</u>				

LAB: SEQUOIA

CHECK ONE (1) BOX ONLY	CT/DT	TURN AROUND TIME
G.W. Monitoring <input checked="" type="checkbox"/> 4461		24 hours <input type="checkbox"/>
Site Investigation <input type="checkbox"/> 4441		48 hours <input type="checkbox"/>
Soil Classify/Disposal <input type="checkbox"/> 4442		15 days <input checked="" type="checkbox"/> (Normal)
Water Classify/Disposal <input type="checkbox"/> 4443		Other <input type="checkbox"/>
Soil/Air Rem. or Sys. O & M <input type="checkbox"/> 4452		
Water Rem. or Sys. O & M <input type="checkbox"/> 4453		
Other <input type="checkbox"/>		

NOTE: Notify Lab as soon as possible of 24/48 hrs. TAT.

UST AGENCY: _____

Sample ID	Date	Sludge	Soil	Water	Air	No. of conts.	TPH (EPA 8015 Mod. Gas)	TPH (EPA 8015 Mod. Diesel)	BTEX (EPA 8020/602)	Volatile Organics (EPA 8240)	Test for Disposal	Combination TPH 8015 & BTEX 8020	Asbestos	Container Size	Preparation Used	Composite Y/N	MATERIAL DESCRIPTION	SAMPLE CONDITION/ COMMENTS	
<u>Mw1 @ 7:45</u>	<u>5/19/99</u>			<u>w</u>		<u>3</u>						<u>X</u>	<u>X</u>	<u>2</u>	<u>40 ml</u>	<u>HC</u>	<u>N</u>		
<u>Mw1 @ 12:15</u>	<u>↓</u>			<u>↓</u>		<u>↓</u>						<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>			

Relinquished By (signature): _____	Printed Name: <u>PEDRO E. RUIZ</u>	Date: <u>5-19-99</u>	Received (signature): _____	Printed Name: _____	Date: _____
Relinquished By (signature): _____	Printed Name: _____	Date: _____	Received (signature): _____	Printed Name: _____	Date: _____
Relinquished By (signature): _____	Printed Name: _____	Date: _____	Received (signature): _____	Printed Name: _____	Date: _____

THE LABORATORY MUST PROVIDE A COPY OF THIS CHAIN-OF-CUSTODY WITH INVOICE AND RESULTS

Project # 3050515A

DATE: 5-19-99

Site Add. 950 E CALOUPAS BLVD

NAME: PEDRO E. POIZ

Mojitas

Client Name/Phone#: _____

DRUMS

Label#	Drum#	Contents	Date Generated	-Gallons
	1	Silt Contaminas	4-28-99	1/2 Full
	2	↓	↓	Full
	3	↓	↓	Full
	4	Rinsate	↓	1/4 Full

Is this an operating site? Y / N

Are drums accessible? Y / N

Drums in compound? Y / N Key# _____

Do you need drums left at site? Y / N Need them pumped by _____ How Many to be left?

DRUMS ORDERED _____

Silt Placed on Spoils Y / N

Delivery Date _____

Drums left at site? Y / N

Supplier: _____

If yes, how many & contents _____

SPOILS PILES

Date Generated _____

Approximate Yardage _____

ATTACH MAP AND SHOW LOCATION

Covered w/ visqueen? Y / N

OF SPOILS AND WHAT SOIL IS FROM

Labeled? Y / N Label I.D. _____

PLEASE NOTE BELOW HOW THE SPOILS WERE GENERATED (i.e., drilled wells MW-1, thru MW-5)

Is this an operating station? Y / N

Is the soil/site accessible for hauler? Y / N

Is a key needed to access the site? Y / N Key# _____

Well development req'd? _____

Scheduled Y / N

When? _____

Spoils Generated How?: _____

Comments: _____