Jul 10,91

REPORT OF QUARTERLY ACTIVITIES

FOR

BROADWAY VOLKSWAGEN 2740 BROADWAY OAKLAND, CALIFORNIA

Prepared For:

Alameda County Department of Environmental Health Hazardous Materials Program 80 Swan Way, Room 200 Oakland, California 94621

and

Vorelco, Inc. 888 West Big Beaver Road P.O. Box 7050 Troy, Michigan 48007-7050

Prepared by:

Environmental Science & Engineering, Inc. (ESE)
4090 Nelson Avenue, Suite J
Concord, CA 94520
(415) 685-4053

Project No. 6-91-5165 July 10, 1991 This report has been prepared by Environmental Science & Engineering, Inc. for the exclusive use of Broadway Volkswagen as it pertains to their site located at 2740 Broadway, in Oakland, California. Our professional services have been performed using that degree of care and skill ordinarily exercised under similar circumstances by other geologists and engineers practicing in this field. No other warranty, express or implied, is made as to professional advice in this report.

REPORT PREPARED BY:

Michael Dulli FOR

Sari S. Miller

Senior Associate Geologist

JULY 10, 1991

Date

UNDER THE PRIMARY REVIEW OF:

Susan S. Wickham, R.G.

Staff Hydrogeologist

California Registered Geologist No. 3851

July 10,1991 Date

TABLE OF CONTENTS

		Page
1.0	INTRODUCTION	1
	1.1 Purpose 1.2 Background 1.3 Activities	1 1 2
2.0	METHODS AND PROCEDURES	4
	 2.1 Soil Sampling 2.2 Well Installation 2.3 Water Sampling 2.4 Analytical Methods Used 	4 4 4 5
3.0	FINDINGS	6
	 3.1 Site Conditions 3.2 Ground-Water Flow Direction and Gradient 3.3 Results of Petroleum Hydrocarbons Analyses 3.4 Results of Metals and Halogenated Volatiles Analyses 	6 6 7 7
4.0	CONCLUSIONS	8
5.0	RECOMMENDATIONS	9
60	DEFEDENCES	10

FIGURES (Tab A)

Figure

- 1 Vicinity Map
- 2A Site Plan
- 2B Detail "B"
- 2C Detail "A"
- 3 Ground-Water Elevation Map May, 1991

TABLES (Tab B)

Table

- A Ground-Water Information in Vicinity of Broadway Volkswagen
- 1 Ground-Water and Product Level Measurements
- 2 Analytical Results for Petroleum Hydrocarbons in Soil Samples
- 3 Analytical Results for Halogenated Volatiles in Soil Samples
- 4 Analytical Results for Petroleum Hydrocarbons in Water Samples
- 5 Analytical Results for Halogenated Volatiles in Water Samples
- 6 Analytical Results for Metals in Soil Sample SB-3 10'

APPENDICES (Tab C)

Appendix

- A Boring Log and Well Completion Summaries
- B Well Purging and Sampling Data
- C Analytical Results

1.0 INTRODUCTION

1.1 Purpose

Four underground fuel storage tanks were removed from three areas at the Broadway Volkswagen Facility located at 2740 Broadway, Oakland, Alameda County, California during August of 1988 (Figure 1 - Vicinity Map). Soil and ground-water samples collected at two of the three tank areas were found to contain detectable petroleum hydrocarbons. A recent site investigation, was conducted in combination with quarterly monitoring activities, to determine whether overexcavation was performed at the tank areas, determine the extent of contaminated soil at the tank areas, further identify ground-water contamination in the vicinity of the former tank sites and determine the ground-water flow direction at the site.

This report documents the findings of the abovementioned investigation and monitoring activities, as well as, provide recommendations for future work.

1.2 Background

In August of 1988, four underground fuel storage tanks (herein referred to as Tanks A, B, C and D) were removed from three areas at the Broadway Volkswagen Facility located at 2740 Broadway, Oakland, Alameda County, California (Figure 2A - Site Plan) which is owned by Vorelco, Inc. of Troy, Michigan. Engineering Science (ES) was the environmental consultant and SEMCO of Modesto, California acted as the tank removal contractor.

Environmental Science & Engineering, Inc. (ESE), formerly known as Hunter/Gregg, Inc. was retained by SEMCO in November of 1988 to install three ground-water monitoring wells (MW-1, MW-2 and MW-3) at the site. The purpose of these wells was to provide the Alameda County Department of Environmental Health (ACDEH) with a characterization of ground-water downgradient from the former underground tanks and information as to the local ground-water flow direction.

A tank removal report was issued to Vorelco by ES during January of 1990. Findings from the ES report and a Hunter/Gregg, Inc. (1989) report which documents the ground-water monitoring data collected at the three tank areas, are presented in the ESE workplan for Site Assessment dated March 27, 1991.

In summary:

- Tank A was a 1,000 gallon waste oil tank and samples collected at the tank area during removal were nondetectable for hydrocarbons.
- Tank B was a 550 gallon waste oil tank reported to have holes at the time of removal. Soil samples taken at the tank site contained detectable Total Petroleum Hydrocarbons (TPH) and Oil and Grease (O&G) concentrations.

Soil samples collected during the installation of monitoring well MW-2, located 15 feet southeast of the former tanks, were nondetectable for O&G and ground-water samples were nondetectable for TPH and Benzene, Toluene, Ethylbenzene, and Total Xylenes (BTEX).

- Tanks C and D, located adjacent to each other, were reported to be a 3,000 gallon gasoline tank and a 550 gallon waste oil tank, respectively. Both tanks did have holes when removed and all ground-water samples (plus some soil samples) taken during tank removal contained detectable TPH and BTEX. Ground water collected at monitoring well MW-1, installed 15 feet east of the C/D tank area during 1989, contained detectable BTEX.
- Soil and ground-water samples collected during the installation of monitoring well MW-3, located 45 feet west of the C/D area contained detectable O&G in the soil and detectable TPH as gasoline and BTEX in the ground-water.
- Site ground-water levels may be skewed by perched water zones in clays found in the Bay Mud. January 1989, ground-water level measurements in the three site monitoring wells vary from the assumed regional ground-water gradient by approximately 90 degrees.
- Additional research has shown that several sites surrounding the subject area handle hazardous waste and have documented leaks. No data have been reported indicating a hazardous material release to the subsurface immediately north (up gradient) of the subject site. Ground-water levels at surrounding properties indicate a regional south-southeast ground-water flow direction toward Lake Merritt. Documentation of soil removal from the former tank areas has not been located.

1.3 Activities

All field activities reported were performed in accordance with Alameda County Department of Environmental Management (ACDEM) and Regional Water Quality Control Board guidelines. Field activities included a subsurface investigation, well monitoring, and well surveying.

Upon locating and permitting boring locations, ESE drilled five soil borings (including SB1, SB2A, SB2B, SB3 and SB4) and installed one monitoring well, MW4 (Figure 2A - Site Plan). A total of three soil borings were drilled and sampled at the Tank B area (Figure 2C - Detail "B") in order to determine if overexcavation was performed, whether soil containing hydrocarbons exists beneath the former tank site and the lateral extent of contamination if detected. Two soil borings were drilled and one ground-water monitoring well was installed at the Tank C/D area (Figure 2B - Detail "A") in order to, as for the Tank B area, determine if any overexcavation had been performed at this tank area, whether soil containing hydrocarbons exists beneath the former tanks and whether lateral

movement of contamination, if any, was occurring within the unsaturated soil. A ground-water monitoring well, MW-4, was installed to assist in further defining conditions downgradient.

Ground-water at two existing monitoring wells (MW-1 and MW-3) was measured, purged and sampled. One monitoring well, MW-2, was found to be abandoned, improperly destroyed, and impossible to sample. All recent measurements and sampling activities are considered to be the first quarter of site monitoring.

Monitoring wells MW1, MW3 and MW4 were surveyed to determine relative elevation and location. Measured ground-water levels at the three wells were corrected to the relative elevation and results are tabulated in the body of this report. Due to the effect of local perched ground-water zones and the small amount of data presently available, no ground-water contours have been plotted.

2.0 METHODS AND PROCEDURES

2.1 Soil Sampling

Soil borings were drilled with hollow stem auger drill rigs. A SIMCO 2400 rig, being compact in size and having the capability of drilling with a short mast, was used for installing monitoring well MW-4 located inside the building (Figure 2B - Detail "A") and drilling soil borings SB-2A and SB-2B located on the sidewalk area adjacent to the building on Broadway Avenue (Figure 2C - Detail "B"). The larger mobile B-61 was used for all other soil borings located outside of the building including SB-1, SB-3 and SB-4.

All soil borings were drilled to a depth of 15 feet and samples were collected at 5, 10 and 15-foot depth intervals in three two-inch diameter brass rings loaded within a split-spoon sampler. Upon retrieval each sample was logged in accordance with the Unified Soil Classification System (USCS), and each borehole was backfilled with grout (Appendix A).

2.2 Monitoring Well Installation

One ground-water monitoring well, MW-4, was installed under ACDEM and Regional Water Quality Control Board specifications within the Broadway Volkswagen building. This two-inch diameter well was emplaced to a depth of 25 feet with a 0.02 inch slot-sized screen portion extending from the 5 foot to 25 foot depth (Appendix A). Sand was used as a filter from 4 feet and downwards, and bentonite pellets overlain by grout acted as a seal from the ground surface to the top of the sand filter.

The well was developed by surveying with a surge block and evacuated until dry two times with a bailer. Evacuated water from the second well volume was consistently clear.

2.3 Water Sampling

As for monitoring well MW-4, both of the existing wells (MW-1 and MW-3) were also purged. Ground-water in all wells was allowed to return to a static level over a period of 48 hours before any free floating product and/or ground-water level measurements were taken with an electronic interface probe and sampling with a disposable polyethylene bailer was performed.

Six 40 ml vials and one 1-liter amber bottle of ground water were collected from each well. Each container was labeled and immediately placed in a cooler for cold transport to the laboratory under chain of custody.

2.4 Analytical Methods Used

All samples were submitted and analyzed by Curtis and Tompkins, Ltd. of Berkeley, California (a State certified laboratory). Four soil samples collected at the Tank B area were analyzed for Total Petroleum Hydrocarbons as diesel (TPH-d) using method EPA 3550/8015 modified which focuses on quantifying diesel and high boiling point hydrocarbons such as Kerosene and oil. Selected samples was further analyzed for Volatile Halocarbons using method 5030/8010, which identifies solvent constituents.

Seven soil samples collected at the Tank C/D area were analyzed for TPH-d, Total Volatile Hydrocarbons as gasoline (TVH-g) using method EPA 5030/8015 modified, and Benzene, Toluene, Ethylbenzene, and Total Xylenes (BTEX) using method EPA 5030/8020. One selected sample was then analyzed for pH using method EPA 9045, Volatile Halocarbons, Cadmium (Cd), Chromium (Cr), Nickel (Ni), Zinc (Zn) using method EPA 6010, Total and soluble lead (Pb) using method EPA 7420, Cyanide using method SW-846 Section 7.3.3.2, Sulfide using method SW-846 Section 7.3.4.1, and corrosivity using method EPA 1110. The purpose of these additional analyses was for waste characterization for soil disposal.

Five water samples, including one trip blank and one duplicate, were analyzed for TVH-g and BTEX. All of these samples, excluding the trip blank, were also analyzed for TPH-d and Volatile Halocarbons.

3.0 FINDINGS

3.1 Site Conditions

Based upon the results of drilling activities to date, the local sediments have been identified as unconsolidated, dark, plastic Bay Mud clays with lesser localized interlayers of sand.

Free floating product was found in soil boring SB-4 located at the former C and D tank area (Figure 2B - Detail "A"). Product was observed in the intergranular space of a pea gravel fill from three feet to twelve feet below the surface (Appendix A - Boring Log and Well Completion Summaries).

Three feet of poorly graded, angular gravel was intersected at soil boring SB-2B located to the immediate northeast of the former tank B area (Figure 2C - Detail "B"). This layer is most probably a fill. Well MW 2 was found destroyed with asphalt and no measurements could be collected.

3.2 Ground-Water Flow Direction and Gradient

In general, the ground-water flow direction at the area surrounding the subject facility follows the south to southeast trending topographic slope toward Lake Merritt. Based upon additional research conducted by ESE, eight sites in the vicinity of the subject facility which handle hazardous materials and have documented leaks and had available documentation concerning ground-water flow direction (Table A - Ground-Water Information). All sites, except the most distant, have documented ground-water flow towards the south and southeast (Figure 1 - Vicinity Map) and a reported ground-water depth range of 5 to 15 feet below surface.

Past ground-water level measurements in monitoring wells MW-1, MW-2 and MW-3 at the subject facility indicated an easterly ground-water flow direction and were considered to be skewed by perched water zones in the Bay Mud clays (Hunter/Gregg, 1989). It was reported that, upon well development, MW-1 ground-water levels increased by approximately 9 feet, whereas, other local wells (MW3 and MW4) have ground-water levels which have remained more-or-less static. MW-1 may be in a confined or perched ground-water zone thereby skewing the small amount of data presently available (Table 1 - Ground Water and Product Level Measurements). Ground-water levels in May 1991 were between 10 and 13 feet below surface. Measurements made during 1989 indicate that the ground-water level has decreased approximately 2 feet on average. The ground-water flow direction, based upon data collected at surrounding properties, is towards the southeast (Figure 3 - Ground Water Elevation).

3.3 Results of Petroleum Hydrocarbons Analyses

Two soil borings, SB-2A and SB-2B, were completed in the tank B area during this phase of field work (Figure 2C - Detail "B"). All samples were nondetectable for TPH-d (Table 2 - Analytical Results). An existing ground-water monitoring well, MW-2, in the tank B area was unable to be sampled.

Soil samples collected from the Tanks C/D area in boreholes SB-3, SB-4 and MW-4 contain detectable concentrations of TPH as oil, TVH-g and BTEX (Table 2 - Analytical Results). In general, the highest TVH-g and BTEX concentrations in soil occur between a depth of 10 to 15 feet below surface.

Detectable TVH-g and BTEX were found in ground-water samples collected in May 1991 from MW-1, MW-3 and MW-4 (Table 3 - Analytical Results). TPH as oil was also detected in ground-water in MW-1 and MW-3. Monitoring well MW-3 contained the highest ground-water concentrations of petroleum constituents and is located west of the former tanks C and D area.

3.4 Results of Metals and Volatile Halocarbons Analyses

Soil boring sample SB-3, collected at a depth of 10 feet in the tanks C and D area, was noted to contain the highest in-situ concentrations of TPH as oil, TPH-g and BTEX of all samples submitted for analyses. Follow-up analyses for metals (including Cd, Cr, Pb, Ni and Zn) indicate values (Table 4 - Analytical Methods) less than Soluble Threshold Limit Concentration (STLC) and Total Threshold Limit Concentration (TTLC) as defined by California Code of Regulations (CCR) Title 22.

Soil boring sample SB-2A, collected at a depth of 15 feet in the former Tank B area, was non-detectable for volatile halocarbons (Table 5 - Analytical Results). Sample SB-3 from a 10-foot depth at the Tanks C and D area was also nondetectable for volatile halocarbons.

Ground-water samples collected from monitoring wells MW-1, MW-3 and MW-4 in 1991 contained detectable trichloroethylene (TCE) with the highest concentrations found in MW-4 (Table 6 - Analytical Results). A ground-water sample from MW-3 contained the least TCE, as compared to the other samples, but was the only sample to have detectable 1,2 - dichloroethane (1,2 DCA).

4.0 CONCLUSIONS

The following conclusions are made from the findings of this subsurface investigation, in combination with quarterly monitoring observations:

- Soil and ground-water samples collected from and around the former tanks C and D area, including sample points MW-1, MW-3, MW-4, SB-3 and SB-4, contain detectable petroleum hydrocarbons in the oil and gasoline range.
- Ground-water flow in the surrounding vicinity is towards the southeast. Monitoring well MW-3 is thereby situated upgradient and is noted to contain detectable hydrocarbons. This suggests upgradient migration of petroleum constituents from the former tank area within the capillary zone or manmade conduit or downgradient migration from a source located off of the subject property. A plume of petroleum and organic volatile products may be migrating in a southeasterly direction from the former tanks C and D area and possibly from off-site sources toward monitoring well MW-4.
- Volatile halocarbons are present in ground water at the tanks C and D area as trichloroethylene (TCE). Ground water in MW-4 contains the highest concentration of TCE. Ground water in MW-3 contains both TCE and 1,2 DCA. 1,2 DCA is a known degradation product of TCE.
- The TCE and 1,2 DCA concentrations found in ground water from these wells are above State of California maximum contaminant levels of 5 μ g/L.


5.0 RECOMMENDATIONS


Based upon the conclusions derived from the findings of a recent field investigation and monitoring program at the Broadway Volkswagen Facility, ESE recommends;

- A. Two monitoring wells be installed upgradient from MW-3 and the former tanks C and D area in order to identify petroleum and organic volatile products sourcing beyond the subject facility.
- B. Monitoring well MW-2 be permitted for destruction by Alameda County and the well be destroyed by drilling out.
- C. One monitoring well be installed downgradient from MW-4 in order to determine the extent of product migration. As well, three to four groundwater samples collected with a HYDROPUNCH at locations downgradient may be suitable for maximum coverage.


6.0 REFERENCES

- Hunter/Gregg, Inc., (1989). Letter Report on Findings at Broadway Volkswagen, 2740 Broadway Avenue, Oakland, California
- Engineering Science (ES) Report, (1989). Removal of Underground Storage Tanks at Broadway Volkswagen, Oakland, California.
- Environmental Science & Engineering, Inc., (1991). Workplan for Site Assessment for Broadway Volkswagen, 2740 Broadway Avenue, Oakland, California










LEGEND


- MONITORING WELL
- * SOIL BORING





		DETA	II. A	
DRAWN BY CVS		APPROVED	BY	REVISED
6/91		1A10	PROJ.	NO. 6-91-5165







LEGEND

- **BANDONED MONITORING WELL**
- ♦ SOIL BORING







Ground-Water Information In Vicinity
Of Broadway Volkswagen, 2740 Broadway, Oakland, California

Site	Description Address	Distance to Broadway VW	Reported Contamination and Date	Ground-Water Depth	Ground-Water Flow Direction
A	Vorelco 2740 Broadway	Waste oil, - - 1988, 1989		9-11'	south-southeast
В	Oakland Acura 255 27th	1050' south	Gasoline? ground water	5'	south
С	Shell 2800 Telegraph	- -		10-11.5'	south
D	Broadway Medical 3300 Webster	2110' north	ground water (low conc.) 1990	10-15'	southwest
E	Tracy Buick 2735 Broadway	450' west	waste oil - soil 1989	NA	NA
F	Connel Auto 3093 Broadway	750' north	gasoline, soil 1989	NA	south
G	Oakland Tribune 2302 Valdez	1050' south	gasoline - soil, ground water 1989	14-16'	south
н	European Motors 2915 Broadway	450' north	waste oil, diesel ground water	10-12'	southeast
I	Alameda County Alcopark	4828' south	gasoline ground water	20.5'	east

NA = Information not available

TABLE 1 - GROUND WATER AND PRODUCT LEVEL MEASUREMENTS

VORELCO

2740 BROADWAY, OAKLAND, CALIFORNIA 94612

	DEPTH TO WATER (feet)	WELL	PRODUCT	WELL ELEVATION	WATER ELEVATION (feet ams1)	
WELL #	5/13/91	DEPTH (feet)	THICKNESS (feet)	(feet)	5/13/91	
MW-1	12.60	20	0	29.22	16.62	
MM-3	10.56	20	o	30.00	19.44	
MW-4	11.20	25	0	29.70	18.50	

amsl = above mean sea level

Note: Well #2 is abandoned.

TABLE 2 - ANALYTICAL RESULTS PETROLEUM HYDROCARBONS (METHOD 8015 AND 8020) FOR SOIL SAMPLES

VORELCO

2740 BROADWAY, OAKLAND, CALIFORNIA 94612

SAMPLE ID	KEROSENE (mg/Kg)	DIESEL (mg/Kg)	MOTOR OIL (mg/Kg)	TVH AS GASOLINE (mg/Kg)	BENZENE (ug/Kg)	TOLUENE (ug/Kg)	ETHYL- BENZENE (ug/Kg)	TOTAL XYLENES (ug/Kg)
SB-2A at 10'	ND	ND						
SB-2A at 15'	ND	ND						
SB-2B at 10'	ND	ND						
SB-2B at 15'	ND	ND						
SB-3 at 5'	ND	ND	ND	2.3	5.2	6.0	ND	21
SB-3 at 10'	ND	ND	91	740	1,200	30,000	9,400	42,000
SB-3 at 15'	ND	ND	ND	5.9	810	480	99	380
SB-4 at 5'	ND	ND	ND	ND	ND	ND	ИD	ND
SB-4 at 15'	ND	ND	14	13	610	1,100	170	840
MW-4 at 5'	ND	ND	ND	ND	ND	ND	ND	ND
MW-4 at 10'	ND	ND	ND	21	220	700	260	1,300

ND = Not detectable at analysis detection limit.

All samples were collected by Environmental Science & Engineering, Inc. (ESE) on May 14 and 15, 1991.

mg/Kg = 1 milligram per Kilogram or parts per million (ppm).

ug/Kg = 1 microgram per Kilogram or parts per billion (ppb).

^{-- =} Not analyzed

TABLE 3 - ANALYTICAL RESULTS PETROLEUM HYDROCARBONS (METHOD 8015 AND 8020) FOR WATER SAMPLES

VORELCO

2740 BROADWAY, OAKLAND, CALIFORNIA 94612

SAMPLE ID	KEROSENE (ug/L)	DIESEL (ug/L)	MOTOR OIL (ug/L)	TVH AS GASOLINE (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	ETHYL- BENZENE (ug/L)	TOTAL XYLENES (ug/L)
TRIP				ND	ND	ND	ND	ND
MW-1	ND	ND	ND	130	ND	ND	ND	1.1
MW-3 -∞	ND	ND	155	41,000	7,800	12,000	1,200	4,000
MW-4	ND	ND	ИD	13,000	160	690	250	1,100
MW-4D	ND	ND	610	14,000	170	730	260	1,200

ND = Not detectable at detection limit value shown.
ug/L = 1 microgram per liter or parts per billion (ppb).
-- = Not analyzed

All samples were collected by Environmental Science & Engineering, Inc. (ESE) on May 14 and 15, 1991.

TABLE 4 - ANALYTICAL RESULTS HEAVY METALS (EPA METHODS 6010, 7420, 1110 AND SW-846 SECTIONS 7.3.3.2 AND 7.3.4.1) FOR SOIL SAMPLE SB-3 10'

VORELCO

2740 BROADWAY, OAKLAND, CALIFORNIA 94612

SAMPLE	1	CHROMIUM (mg/Kg)		SOLUBLE LEAD (mg/L)	NICKEL (mg/Kg)	ZINC (mg/Kg)	CYANIDE (mg/Kg)	SULFIDE (mg/Kg)
SB-3 10'	0.27	27.4	5.0	0.24	42.5	42.5	ND	ND

^{*} Corrosivity was analyzed as < 6.35 mm/year.</p>

ND = Not detectable at analysis detection limit.
mg/Kg = 1 milligram per Kilogram or parts per million (ppm).
mg/L = 1 milligram per Liter or parts per billion (ppb).

All samples were collected by Environmental Science & Engineering, Inc. (ESE) on May 14, 1991.

TABLE 5 - ANALYTICAL RESULTS HALOGENATED VOLATILES EPA METHOD 8010 FOR SOIL SAMPLES VORELCO

2740 BROADWAY, OAKLAND, CALIFORNIA. 94612

(All results reported in ug/L)

COMPOUND	SB-2A 15'	SB-3 10'
Chloromethane	ND	ND
Bromomethane	ND	ND
Vinyl chloride	ND	ND
Chloroethane	ND	ND
Methylene chloride	ND	ND
Trichlorofluoromethane	ND	ND
1,1-Dichloroethene	ND	ND
1,1-Dichloroethane	ND	ND
cis-1,2-Dichloroethane	ND	ND
trans-1,2-Dichloroethane	ND	ND
Chloroform	ND	ND
Freon 113	ND	ND
1,2-Dichloroethane	ND	ND
1,1,1-Trichloroethane	ND	ND
Carbon tetrachloride	ND	ND
Bromodichloromethane	ND	ND
1,2-Dichloropropane	ND	ND
cis-1,3-Dichloropropene	ND	ND
Trichloroethylene	ND	ND
1,1,2-Trichloroethane	ND	ND
trans-1,3-Dichloropropene	ND	ND
Dibromochloromethane	ND	ND
2-Chloroethyl vinyl ether	ND	ND
Bromoform	ND	ND
Tetrachloroethene /		
1,1,2,2-Tetrachloroethane	ND	ND
Chlorobenzene	ND	ND
1,3-Dichlorobenzene	ND	ND
1,2-Dichlorobenzene	ND	ND
1,4-Dichlorobenzene	ND	ND

ug/Kg = 1 microgram per Kilogram or parts per billion (ppb). ND = Not detectable at analysis detection limit.

All samples were collected by Environmental Science & Engineering, Inc. (ESE) on May 14 and 15, 1991.

5165-3.gm 6/18/91 obc-d

2740 BROADWAY, OAKLAND, CALIFORNIA.94612

(All results reported in ug/L)

of const

COMPOUND	MW-1	MW-3	MW-4	MW-4D					
Chloromethane	ND	ND	ND	ND					
Bromomethane	ND	ND	ND	ND					
Vinyl chloride	ND	ND	ND	ND					
Chloroethane	ND	ND	ND	ND					
Methylene chloride	ND	ND	ND	ND					
Trichlorofluoromethane	ND	ND	ND	ND					
1,1-Dichloroethene	ND	ND	ND	ИD					
1,1-Dichloroethane	ND	ND	ND	ND					
cis-1,2-Dichloroethane	ND	ND	ND	ND					
trans-1,2-Dichloroethane	ND	ND	ND	ND					
Chloroform	ND	ND	ND	ND					
Freon 113	ND	ND	ND	ND					
1,2-Dichloroethane	ND	380	ND	ND					
1,1,1-Trichloroethane	ND	ND	ND	ND					
Carbon tetrachloride	ND	ND	ND	ND					
Bromodichloromethane	ND	ND	ND	ND					
1,2-Dichloropropane	ND	ND	ND	ND					
cis-1,3-Dichloropropene	ND	ИD	ND	ND					
Trichloroethylene	58	14	490	660					
1,1,2-Trichloroethane	ND	ND	ND	ND					
trans-1,3-Dichloropropene	ИD	ND	ND	ND					
Dibromochloromethane	ND	ИD	ND	ND					
2-Chloroethyl vinyl ether	ND	ND	ИD	ND					
Bromoform	ND	ND	ND	ИD					
Tetrachloroethene /									
1,1,2,2-Tetrachloroethane	ND	ND	ND	ND					
Chlorobenzene	ND	ND	ND	ND					
1,3-Dichlorobenzene	ND	ND	ND	ND					
1,2-Dichlorobenzene	ND	ND	ND	DИ					
1,4-Dichlorobenzene	ND	ND	ND	ND					

ug/L = 1 microgram per liter or parts per billion (ppb).

ND = Not detectable at analysis detection limit.

All samples were collected by Environmental Science & Engineering, Inc. (ESE) on May 14 and 15, 1991. 5165-5.gm 6/26/91 obc-d


	Environmental Science & Engineering, Inc.			WEL			OG AND ON SUMMARY	SB1
Co	LL COMPLETION npletion Depth: N/A Size/Type From	То		Project Name: Voreico Project No: 6-91-5165 Location: Broadway Volkswagen 2740 Broadway Ave. Oakland, CA				Page 1 of 1
Scr Filt Sei	Casing: Screen: Filter: Seal: Well Cap or Box:				gg Drilling and I ollow Stem Auge ster: 8 In. ons: NA Bart Miller	F	Depth: 15 Feet	Dates: Start: 5-13-91 Finish: 5-13-91
Depth (ft)	Lithologic Description	USC	Sample/	Graphic Log	Well Installation	Vapor	Remarks Water, drilling/completion, sumi	nary, sample type
5-		Sn G C C C C C C C C C C C C C C C C C C	10 13 15 20 25	Lithology	Well Installation	1 1	Water, drilling/completion, sum RING @ 5 FEET (*) RING @ 10 FEET (*) RING @ 15 FEET (*) (*) - Sample submitted for a	8:40 8:45
30-		+ + + + + + + + + + + + + + + + + + + +					REVIEWED AND APP Susan with PHONO 9, 4500 DESTRUCTION 6.4	m

	Environmental Science & Engineering, Inc.			WEL	BORING L COMPL		OG AND ON SUMMARY	SB-2A
WE	L COMPLETION pletion Depth: N/A Size/Type From	То		2	ne: Vorelco Iroadway Volksw 740 Broadway A Dakland, CA		Project No: 6-91-5165	Page 1 of 1
Cas Scre Filte Sea Wel	BACKFILLED WITH GROUT			Method: Si Hole Diame Ref. Elevati	eter: 8 In.	Total (Depth: 15 Feet	Dates: Start: 5-15-91 Finish: 5-15-91
Depth (ft)	Lithologic Description	nsc	Sample/	Graphic Log	Well Installation	Vapor	Remarks Water, drilling/completion, sum	mary, sample type
5 - 10	CEMENT - 4 in. GRAVEL FILL - 1 In. EORMATIONAL SEDIMENTS CLAY with trace sllt and gravel, tan brown, slightly grey mottled, dry, no odor, trace root stains. AS ABOVE, but slightly damp.	GP CL	Blows			2	RING @ 5 FEET RING @ 10 FEET	TIME: 13:30
20		++++++++++++++++++++++++++++++++++++++				0	REVIEWED AND A SWAM W SUSAN S. W REGISTERED C GEOLOGIST	White ALIFORNIA

	Environmental Science & Engineering, Inc.			WEL			OG AND ION SUMMARY	SB-2B
	ELL COMPLETION ompletion Depth: N/A Size/Type From	То		2	ne: Voreico Iroadway Volksw 1740 Broadway A Dakland, CA		Project No: 6-91-5165	Page 1 of 1
Si Si	ising: reen: BACKFILLED WITH GROUT ler: BACKFILLED WITH GROUT leil:			Driller: Gre Method: SI Hole Dlame Ref. Elevati	egg Drilling and I MCO Rig ster: 8 In.	Total	Depth: 15 Feet	Dates: Start: 5-15-91 Finish: 5-15-91
Depth (ft)	Lithologic Description	nsc	Sample/ Blows	Graphic Log	Well Installation	Vapor	Remarks Water, drilling/completion, sum	nary, sample type
5=	GRAVEL, approximately 1 inch diameter, poorly graded, trace Clay, brown, moist, no odor. CLAY, tan brown, soft, moist, no odor.		Blows	Lithology	Well Installation	A	RING @ 5 FEET RING @ 10 FEET REVIEWED AND API SUBAN S. VINE RESISTANCE ON GROUPEST	TIME: 14:20 15:00

	Environmental Science & Engineering, Inc.		<u>-</u>		L COMPI		OG AND ION SUMMARY	2003
Co	ILL COMPLETION mpletion Depth: N/A Size/Type From	To		Location: E	ne: Vorelco Broadway Volksw 1740 Broadway A Dakland, CA		Project No: 6-91-5165	Page 1 of 1
Scr Filt Sea				Method: Ho Hole Diame Ref. Elevat		r	Depth: 15 Feet	Dates: Start: 5-13-91 Finlsh: 5-13-91
Depth (ft)	Lithologic Description	nsc	Sample/ Blows	Graphic Log	Well Installation	Vapor	Remarks Water, drilling/completion, sum	mary, sample type
15	CLAY, light brown with grey mottling, low to medium plasticity, moist, etrang fuel eder (i.e. gasoline).			Lithology	Well Installation	1 8	REVIEWED AND AN SUBANIS. WE RECONTERS C.	10:01 10:10 10:16 Analysis CKHASS GLEGGRAA
35-							GEOLO 2157	HONDA LONGORA

	Environmental Science & Engineering, Inc.		<u>.</u>	1	L COMPL		OG AND ON SUMMARY	26 4
Cor	LL COMPLETION npletion Depth: N/A Size/Type From	Ťο		Location: E	ne: Voreico Iroadway Volksw 1740 Broadway A Dakland, CA		Project No: 6-91-5165	Page 1 of 1
Scr Filte Sea				Method: He Hole Diame Ref. Elevat		r	Depth: 15 Feet	Dates: Start: 5-13-91 Finish: 5-13-91
Depth (ft)	Lithologic Description	osn n	Sample/ Blows	Graphic Log Lithology	Well Installation	Vapor	Remarks Water, drilling/completion, sum	nary, sample type
10-15-20-25-30-35-	PEA GRAVEL FILL, abundant gasoline product, impossible to sample	GP	10 8 9 9 440			1	RING @ 5 FEET (*) Lost all sample @ 10 Feet RING @ 15 FEET (*) (*) - Sample submitted for a SUSAN S. WE REGISTERED CA CEDUCSIDE	PROVED BY:



WELL PURGING AND SAMPLING DATA

Date: 5-(3-9) Project Number:	6-91-5165	Project Name:_	VORELCO
Well Number: <u>Mw /</u> Boring Diam	eter: 10 12CM	Casing Diamete	r: 2 124
Column of Fluid in Well	Volume to be	e Removed	
depth to product	column of volume of gal per ft column of volume of total volumber of total vol	water annular space of casing water casing me vol to remove to remove	X
method of measuring fluidE	1 c		
method of purging well			
method of decon Alconox/w	late(
Physical appearance of water (odor)
Initial			
During			
Final	*		
Field Analysis <u>Initial</u>	Duri	ng	<u>Final</u>
conductivity			
рн			
temperature			
method of measurement	:		
Total volume purged 3 gallons	Comments		
Sample Number Mw ! '	Amount of Sam	ole <u>6 x 40 m i vo</u>	Avials and Ix I lite
Signed/Sampler OLIVER CH	IRISTEN	Dat	e <u>5-13-91</u>
Signed/Reviewer		Dat	e

WELL PURGING AND SAMPLING DATA

Date: 5-13-91 Proj Well Number: MW3				
Column of Fluid in	Well	Volume to b	e Removed	
depth to product depth to water total depth of we column of product column of water method of measuring method of purging w	10.56 11	column of volume of gal per f column of volume of total vol number of total vol	annular space t of casing water casing ume vol to remove to remove rate	X
method of decon Physical appearance				
Initial During Final				
Field Analysis	Initial	Dur	ıng	<u>Final</u>
time conductivity pH				
temperature			:	
Total volume purged	1 3 gallons	Comments		
Sample Number _MW	3	Amount of Sam	ple <u>6×40ml V</u> o	Avials and IxI.lil
Signed/Sampler	OLIVER	CHRISTEN	Da	te <u>5-13-41</u>
Signed/Reviewer		<u></u>	Da	te

WELL PURGING AND SAMPLING DATA

Date: 5-13-41 Project Number: 6-91 Well Number: MW 4 Boring Diameter:	
Column of Fluid in Well Volu	me to be Removed
depth to water	olumn of water X
method of measuring fluid <u>Electrical</u> method of purging well <u>Barler</u>	rate
method of decon	
Initial During Final	
Field Analysis Initial	During Final
time	
conductivity	· · · · · · · · · · · · · · · · · · ·
рН	
method of measurement	
Total volume purged 25 gallons C	omments Buled dy twice Slow
cechage.	
Sample Number <u>NW 4</u> Amount	of sample 6x 40mi VoA vials and 1x1
Signed/Sampler OLIVER CHRISTE.	
Signed/Reviewer	Date



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (415) 486-0900

DATE RECEIVED: 05/14/91 DATE REQUESTED: 05/29/91 DATE REPORTED: 06/05/91

LAB NUMBER: 103982

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT 1D: 6-91-5165

LOCATION: VORELCO

RESULTS: SEE ATTACHED

QA/QC Approval

Final Appro



LABORATORY NUMBER: 103982-1

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165 LOCATION: VORELCO SAMPLE ID: SB-2A@15'

DATE RECEIVED: 05/14/91 DATE REQUESTED: 05/30/91 DATE ANALYZED: 06/03/91 DATE REPORTED: 06/05/91

EPA 8010: Volatile Halocarbons in Soil & Wastes Extraction Method: EPA 5030 - Purge & Trap

		REPORTING
Compound	RESULT	LIMIT
•	ug/Kg	ug/Kg
chloromethane	ND	10
bromomethane	ND	10
vinyl chloride	ND	10
chloroethane	ND	10
methylene chloride	ND	5.0
trichlorofluoromethane	ND	5.0
1,1-dichloroethene	ND	5.0
1,1-dichloroethane	ND	5.0
cis-1,2-dichloroethene	ND	5.0
trans-1,2-dichloroethene	ND	5.0
chloroform	ND	5.0
freon 113	ND	5.0
1,2-dichloroethane	ND	5.0
1,1,trichloroethane	ND	5.0
carbon tetrachloride	ND	5.0
bromodichloromethane	ND	5.0
1,2-dichloropropane	ND	5.0
cis-1,3-dichloropropene	ND	5.0
trichloroethylene	ND	5.0
1,1,2-trichloroethane	ND	5.0
trans-1,3-dichloropropene	ND	5.0
dibromochloromethane	ND	5.0
2-chloroethylvinyl ether	ND	10
bromoform	ND	5.0
tetrachloroethylene	ND	5.0
1,1,2,2-tetrachloroethane	ND	5.0
chlorobenzene	, ND	5.0
1,3-dichlorobenzene	ND	5.0
1,2-dichlorobenzene	ND	5.0
1,4-dichlorobenzene	ND	5.0

ND = Not detected at or above reporting limit.

QA/QC SUMMARY

10 Duplicate: Relative % Difference 105 Spike: Average % Recovery

F 5-14-91 PAGE OF	/ · · · c	HAIN OF	CUSTODY REC	ORD	Environmental		
JECT NAME VORELCO	ANALYSES	TO BE	PERFORMED	MATRIX	Science &		
ADDRESS 2740 Brogdway Ogkland, CA DJECT NO. 6-91-5165	120 3 4 5 5			M M TR IN	## Engineering, Inc. ### 4090 Nelson Avenue Sulte		
NAME Ortis & Tompkins MPLE # DATE TIME LOCATION	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	;		X O E F R S			
1W-4 5-15-91 13:30 Oakland 4W-40 5-15-91 13:30 Oakland	XXX			Water 7 Water 7	6 VOAS & 1 Liter 6 VOAS & 1 Liter		
B-2A 5-15-91 1415 Oakland 3-2A 9+5-15-91 14125 Oakland 3-2A 9+5-15-91 14:35 Oakland		782-11	pavesta	501 1 501 1 501 1	HOLD		
28 40 5-1591 15:00 Baklan	I on 9	7	or 8010.	Soil 1 Soil 1	HOCD		
3-28+15 5-15-9 15115 Oaklan	4 -			<u> 50 1 </u>			
\$1.00 \$1.00 \$1.00					TOTAL NUMBER OF CONTAINERS		
ELINQUISHED BY: (signature)	RECEIVED BY	: (signa	aturd) date	RESULT	ORT SPECIAL SHIPMENT REQUIREMENTS		
•	Khaw SAMPLE RECEIPT						
NSTRUCTIONS TO LABORATORY (handling, analyses, storage, etc.): NSTRUCTIONS TO LABORATORY (handling, analyses, storage, etc.): REC'D GOOD CONDTN/COLD CONFORMS TO RECORD							
10 Day IA	for	U/ate	r Jam	(f) 150	COMPOSAD TO ALBORITO		



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 9471O, Phone (415) 486-0900

DATE RECEIVED: 05/14/91 DATE REPORTED: 05/29/91

LAB NUMBER: 103828

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO

RESULTS: SEE ATTACHED

QA/QC Approval

Final Appro

Berkeley

Wilmington

Los Angeles



LABORATORY NUMBER: 103828 DATE RECEIVED: 05/14/91

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING DATE ANALYZED: 05/23/91

PROJECT ID: 6-91-5165 DATE REPORTED: 05/29/91

LOCATION: VORELCO

Total Volatile Hydrocarbons with BTXE in Aqueous Solutions
TVH by California DOHS Method/LUFT Manual October 1989
BTXE by EPA 5030/8020

LAB ID	SAMPLE ID	TVH AS GASOLINE	BENZENE	TOLUENE	ETHYL BENZENE	TOTAL XYLENES	
		(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	
103828-1	MW-4	13,000	160	690	250	1,100	
103828-2	MW- 4D	14,000	170	730	260	1,200	

QA/QC SUMMARY	1	
		<1
RPD, %		100
RECOVERY, %		<u> </u>



LABORATORY NUMBER: 103828

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO

DATE RECEIVED: 05/14/91
DATE EXTRACTED: 05/21/91
DATE ANALYZED: 05/22/91

DATE REPORTED: 05/29/91

Extractable Petroleum Hydrocarbons in Aqueous Solutions California DOHS Method LUFT Manual October 1989

LAB ID	CLIENT ID	KEROSENE RANGE (ug/L)	DIESEL RANGE (ug/L)	MOTOR OIL RANGE (ug/L)	REPORTING LIMIT* (ug/L)	
103828-1	MW - 4	ND	ND	ND	5 0	
103828-2	2.21	ND	ND	610	5 0	

ND = Not detected at or above reporting limit.

*Reporting limit applies to all analytes.

QA/QC SUMMARY

RPD. %
RECOVERY, %
104



DATE RECEIVED: 05/14/91

DATE ANALYZED: 05/24/91

DATE REPORTED: 05/29/91

LABORATORY NUMBER: 103828-1

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO SAMPLE ID: MW-4

EPA 8010 Purgeable Halocarbons in Water

Compound	Result	Reporting
	ug/L	Limit
·		ug/L
chloromethane	ND	20
bromome than e	ND	20
vinyl chloride	ND	20
chloroethane	ND	20
methylene chloride	ND	20
trichlorofluoromethane	ND	10
1,1-dichloroethene	ND	10
l.l-dichloroethane	ND	10
cis-1,2-dichloroethene	ND	10
trans-1,2-dichloroethene	ND	10
chloroform	ND	10
freen 113	ND	10
1,2-dichloroethane	ND	10
1,1,1'-trichloroethane	ND	10
carbon tetrachloride	ND	10
bromodichloromethane	ND	10
1,2-dichloropropane	ND	10
cis-1,3-dichloropropene	ND	10
trichloroethylene	490	10
1,1,2-trichloroethane	ND	10
trans-1,3-dichloropropene	ND	10
dibromochloromethane	ND	10
2-chloroethyl vinyl ether	ND	20
bromoform	ND	10
tetrachloroethene	ND	10
1,1,2,2-tetrachloroethane	ND	10
chlorobenzene	ND	10
	ND	10
1,3-dichlorobenzene	ND	10
1,2-dichlorobenzene	ND	10
1,4-dichlorobenzene	- · -	/

ND = Not detected at or above reporting limit.

OA.	/QC	SUN	ΛMA	RY

RPD, %	3
RECOVERY, %	109



LABORATORY NUMBER: 103828-2

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO SAMPLE ID: MW-4D

DATE RECEIVED: 05/14/91

DATE ANALYZED: 05/24/91

DATE REPORTED: 05/29/91

EPA 8010

Purgeable Halocarbons in Water

Compound	Result	Reporting
Compound	ug/L	Limit
		ug/L
chloromethane	ND	20
hromome than e	ND	20
vinyl chloride	ND	20
chloroethane	ND	2 0
methylene chloride	ND	2 0
trichlorofluoromethane	ND	10
1,1-dichloroethene	ND	10
l, l-dichloroethane	ND	10
cis-1,2-dichloroethene	ND	10
trans-1,2-dichloroethene	ND	10
chloroform	ND	10
freen 113	ND	10
1,2-dichloroethane	ND	10
1,1,1-trichloroethane	ND	10
carbon tetrachloride	ND	10
bromodichloromethane	ND	10
1,2-dichloropropane	ND	10
cis-1,3-dichloropropene	ND	10
trichloroethylene	660	10
1,1,2-trichloroethane	ND	10
trans-i,3-dichloropropene	ND	10
dibromochloromethane	ND	10
2-chloroethyl vinyl ether	ND	20
bromoform	ND	10
tetrachloroethene	ND	10
1,1,2,2-tetrachloroethane	ND	10
chlorobenzene	ND	10
l, 3 - dichlorobenzene	ND	10
1,2-dichlorobenzene	ND	10
1,4-dichlorobenzene	ND	10
1,4-dichioropenzene		

ND = Not detected at or above reporting limit.

QA/QC SUMMARY

ATE 5-15-91 PAGE [_0:	F /		CHA	AIN OF	CUS	TOD	Y REC	CORD	•			and)	Environm	ental
		ANALYS	RS 1	O BE	PERF	ORM	ED	MATE	RIX				Science &	
OPUL D					T			<u> </u>		N C			Engineeri	ng, Inc.
6 1 1 6 1	Nah (2)	(30g)			1 1	- [MA		DOZHAHZHKO	,	A CILCORP Company	(415)	685-4053
<u>Cakiana CA</u>	—\ <i>\</i> %	2 2 c						MATRIX		BT	4090 N Suite J	lelson Avenue rd, CA 94520		
ROJECT NO. 6-91-3-165	\psi	20 25	1		1	1		ij	•	RI	Conco	rd, CA 94520	Fax (415) 685-5023
MPLED BY <u>Oliver Christ</u>	1 2 120	W 27			1 1			^		ပ္က နို		ם ד	MARKS	
AB NAME Curtis & Tompki	NS I	75	3				€ 1			r s	(C	ONTAINÉ	EMARKS R, SIZE,	ETC.)
SAMPLE # DATE TIME LOCAT	ION F	ヒイエ	<u> </u>	' _	\perp			MAT	7	<u> </u>		11646	+ 1	1 1.0-
MW-4 5-15-91 13:30 Oakle	rud X	$\times \times$					_	Wa	<u>ter</u>	17	Q	VOAS	<u> </u>	Liter
MW-47 5-15-91 13:30 Oakk		XX		$ \cdot _{-}$				Wa	rtec	17	6	VOAS	3 # 1	Liter
	and	T .						50		1	7			
	and							50	<u> </u>	1		HOL.	D	
	and				1			50						
10-21 9+3 D-11 15:00 Oak		1-1-	Ì					50	1	1.1		11.		
18 - 28 - 15 - 15 - 10 10 10 10 10 10 10 10 10 10 10 10 10	and a	1	1					30	77)) HOL	<u> </u>	
18-28-40 5-1591 15:10 Oakl	7 [-					50		1		•		
18-28-415 5-159 15115 Ook	1941	 			1					1	/			
		 	+	┼─┼╌		 	_			1				
										 				
表 人的				┼├-		╌┤				-				
(A)	<u>l</u>	<u> </u>	<u></u>	<u> </u>				1	T		TO	TAT. NIIMB	ER OF CON	TAINERS
RELINQUISHED BY: (signature)	RECE	TYED I	3Y :	(sign	ature	74	Q I	trwe	` <u> </u> -					
1. Hur Charten	15	XI F	12			1			RE	repu Tuuz	S TO:	ŘEQUIRE	SHIPMENT MENTS	
2.	+	·		<u> </u>				 	1	50				•
3.			-					-	١,					
4.		···		.,,				 	⊣ ℓ	Nic	Khau	S	AMPLE REC	EIPT
5.										· · · · · ·			F CUSTOD	
VOUNTED TO TABLE TO THE TABLE T	(bandli	ing, a	nalj	ses,	stor	249 P	المحارا	4/2	XIS	•				
INSTRUCTIONS TO LABORATORY	V47 7	501	_	-PO		(ソリ	ピン	$I \cup I$	0	•		ם מיטקק	OOD COND	IN/COLD+



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (415) 486-0900

DATE RECEIVED: 05/14/91 DATE REPORTED: 05/31/91

LAB NUMBER: 103800

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO

RESULTS: SEE ATTACHED

QA/QC Approval

Final Approva

Berkeley

Wilmington

Los Angeles



DATE RECEIVED: 05/14/91

LABORATORY NUMBER: 103800-1

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO SAMPLE ID: MW-1

DATE ANALYZED: 05/24/91 DATE REPORTED: 05/31/91

EPA 8010

Purgeable Halocarbons in Water

Chloromethane ND Limit ug/L ug/L ug/L ug/L ug/L ug/L chloromethane ND 2.0 bromomethane ND 2.0 vinyl chloride ND 2.0 chloroethane ND 2.0 methylene chloride ND 1.0 trichlorofluoromethane ND 1.0 1,1-dichloroethane ND 1.0 1,1-dichloroethane ND 1.0 1,1-dichloroethane ND 1.0 trans-1,2-dichloroethene ND 1.0 trans-1,2-dichloroethane ND 1.0 trong freen ND 1.0 trong freen ND 1.0 trong freen ND 1.0 1,2-dichloroethane ND 1.0 trichloroethane ND 1.0 trichloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 trichloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 tetra	Compound	Result	Reporting
chloromethane ND 2.0 bromomethane ND 2.0 vinyl chloride ND 2.0 chloroethane ND 2.0 methylene chloride ND 1.0 trichlorofluoromethane ND 1.0 1,-dichloroethane ND 1.0 1,-dichloroethane ND 1.0 trans-1,2-dichloroethene ND 1.0 trans-1,2-dichloroethene ND 1.0 chloroform ND 1.0 freen li3 ND 1.0 1,2-dichloroethane ND 1.0 1,1,1-trichloroethane ND 1.0 1,1,1-trichloroethane ND 1.0 torderbylene ND 1.0 1,2-dichloropropane ND 1.0 cis-1,3-dichloropropene ND 1.0 trichloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 trichloroethyl vinyl ether ND 1.0 bromoform	Combogua	ug/L	
ND 2.0			
ND	ah laramathana	ND	
vinyl chloride ND 2.0 chloroethane ND 2.0 methylene chloride ND 2.0 trichlorofluoromethane ND 1.0 l,l-dichloroethene ND 1.0 l,l-dichloroethene ND 1.0 cis-l,2-dichloroethene ND 1.0 cis-l,2-dichloroethene ND 1.0 chloroform ND 1.0 freon 113 ND 1.0 l,2-dichloroethane ND 1.0 l,1,1-trichloroethane ND 1.0 carbon tetrachloride ND 1.0 bromodichloromethane ND 1.0 cis-l,3-dichloropropene ND 1.0 cis-l,3-dichloropropene ND 1.0 trichloroethane ND 1.0 l,2-trichloroethane ND 1.0 chloroethyl vinyl ether ND 1.0 bromoform ND 1.0 tetrachloroethene ND 1.0 l,2-trichlor		ND	
chloroethane ND 2.0 methylene chloride ND 2.0 trichlorofluoromethane ND 1.0 1,1-dichloroethane ND 1.0 1,1-dichloroethane ND 1.0 cis-1,2-dichloroethene ND 1.0 trans-1,2-dichloroethene ND 1.0 chloroform ND 1.0 freon 113 ND 1.0 1,2-dichloroethane ND 1.0 1,1,1-trichloroethane ND 1.0 carbon tetrachloride ND 1.0 bromodichloromethane ND 1.0 trichloropropane ND 1.0 cis-1,3-dichloropropene ND 1.0 trichloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 trinchloroethylene ND 1.0 trinchloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 tetrachloroethene ND 1.0 te		ND	2.0
methylene chloride ND 2.0 trichlorofluoromethane ND 1.0 1,1-dichloroethene ND 1.0 1,1-dichloroethane ND 1.0 cis-1,2-dichloroethene ND 1.0 trans-1,2-dichloroethene ND 1.0 chloroform ND 1.0 freon 113 ND 1.0 1,2-dichloroethane ND 1.0 1,1-trichloroethane ND 1.0 carbon tetrachloride ND 1.0 bromodichloromethane ND 1.0 1,2-dichloropropane ND 1.0 cis-1,3-dichloropropene ND 1.0 trichloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 trans-1,3-dichloropropene ND 1.0 dibromochloromethane ND 1.0 2-chloroethyl vinyl ether ND 1.0 bromoform ND 1.0 tetrachloroethene ND 1.0		ND	2.0
trichlorofluoromethane ND 1.0 1,1-dichloroethene ND 1.0 1,1-dichloroethane ND 1.0 cis-1,2-dichloroethene ND 1.0 trans-1,2-dichloroethene ND 1.0 chloroform ND 1.0 freon 113 ND 1.0 1,2-dichloroethane ND 1.0 1,1,1-trichloroethane ND 1.0 carbon tetrachloride ND 1.0 bromodichloromethane ND 1.0 1,2-dichloropropane ND 1.0 cis-1,3-dichloropropene ND 1.0 trichloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 trans-1,3-dichloropropene ND 1.0 dibromochloromethane ND 1.0 2-chloroethyl vinyl ether ND 1.0 bromoform ND 1.0 tetrachloroethene ND 1.0 1,1,2,2-tetrachloroethane ND 1.0 chlorobenzene ND 1.0 1,3-dichloroben		ND	2.0
1, 1-dichloroethene		ND	1.0
1, 1 - dichloroethane		ND	1.0
cis-1,2-dichloroethene ND 1.0 trans-1,2-dichloroethene ND 1.0 chloroform ND 1.0 freon 113 ND 1.0 1,2-dichloroethane ND 1.0 1,1,1-trichloroethane ND 1.0 carbon tetrachloride ND 1.0 bromodichloromethane ND 1.0 1,2-dichloropropane ND 1.0 cis-1,3-dichloropropene ND 1.0 trichloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 trans-1,3-dichloropropene ND 1.0 dibromochloromethane ND 1.0 2-chloroethyl vinyl ether ND 1.0 bromoform ND 1.0 tetrachloroethene ND 1.0 1,1,2,2-tetrachloroethane ND 1.0 chlorobenzene ND 1.0 1,3-dichlorobenzene ND 1.0 1,4-dichlorobenzene ND 1.0	•	ND	1.0
trans-1, 2-dichloroethene chloroform freon 113 1, 2-dichloroethane 1, 1, 1-trichloroethane carbon tetrachloride bromodichloromethane 1, 2-dichloropropane cis-1, 3-dichloropropene trichloroethylene 1, 1, 2-trichloroethane trans-1, 3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1, 1, 2, 2-tetrachloroethane chlorobenzene 1, 3-dichlorobenzene 1, 3-dichlorobenzene 1, 4-dichlorobenzene		ND	1.0
chloroform ND 1.0 freon 113 ND 1.0 1,2-dichloroethane ND 1.0 1,1,1-trichloroethane ND 1.0 carbon tetrachloride ND 1.0 bromodichloromethane ND 1.0 tromodichloromethane ND 1.0 t,2-dichloropropene ND 1.0 trichloroethylene ND 1.0 1,1,2-trichloroethane ND 1.0 trans-1,3-dichloropropene ND 1.0 dibromochloromethane ND 1.0 chloroethyl vinyl ether ND 1.0 bromoform ND 1.0 tetrachloroethene ND 1.0 1,1,2,2-tetrachloroethane ND 1.0 chlorobenzene ND 1.0 1,3-dichlorobenzene ND 1.0 1,4-dichlorobenzene ND 1.0			1.0
1.0	-	ND	1.0
1, 2 - dichloroethane ND 1.0 1, 1, 1 - trichloroethane ND 1.0 carbon tetrachloride ND 1.0 bromodichloromethane ND 1.0 1, 2 - dichloropropane ND 1.0 cis - l, 3 - dichloropropene ND 1.0 trichloroethylene ND 1.0 l, 1, 2 - trichloropropene ND 1.0 dibromochloromethane ND 1.0 2 - chloroethyl vinyl ether ND 1.0 bromoform ND 1.0 tetrachloroethene ND 1.0 1, 1, 2, 2 - tetrachloroethane ND 1.0 chlorobenzene ND 1.0 1, 3 - dichlorobenzene ND 1.0 1, 2 - dichlorobenzene ND 1.0 1, 4 - dichlorobenzene ND 1.0		ND	1.0
1,1,1-trichloroethane carbon tetrachloride bromodichloromethane 1,2-dichloropropane cis-1,3-dichloropropene trichloroethylene 1,1,2-trichloroethane trans-1,3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,1,2-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,1,2-dichlorobenzene 1,1,2-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,1,2-dichlorobenzene 1,1,2-dichlorobenzene 1,2-dichlorobenzene 1,1,2-dichlorobenzene 1,2-dichlorobenzene 1,1,2-dichlorobenzene 1,1,2-dichlorobenzene		ND	1.0
carbon tetrachloride bromodichloromethane 1,2-dichloropropane cis-1,3-dichloropropene trichloroethylene 1,1,2-trichloroethane trans-1,3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.			1.0
bromodichloromethane 1,2-dichloropropane cis-1,3-dichloropropene trichloroethylene 1,1,2-trichloroethane trans-1,3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene ND 1.0			1.0
l,2-dichloropropane cis-l,3-dichloropropene trichloroethylene l,1,2-trichloroethane trans-l,3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene l,1,2,2-tetrachloroethane chlorobenzene l,3-dichlorobenzene l,4-dichlorobenzene l,1-dichlorobenzene l,1-dichlorobenzene l,2-dichlorobenzene l,4-dichlorobenzene			1.0
1,2-dichloropropene cis-1,3-dichloropropene trichloroethylene 1,1,2-trichloroethane trans-1,3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,1,0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.			1.0
trichloroethylene 1,1,2-trichloroethane trans-1,3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,2-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,1,2,2-dichlorobenzene 1,1,2,2-dichlorobenzene 1,2-dichlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene 1,1,0 1,0			1.0
trichloroethylene 1,1,2-trichloroethane trans-1,3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,1,0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0			1.0
trans-1,3-dichloropropene dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,2-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,1,0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0			
dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,1,0 1,0 1,0			1.0
dibromochloromethane 2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,2-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene			
2-chloroethyl vinyl ether bromoform tetrachloroethene 1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,2-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene			2.0
bromoform ND 1.0 tetrachloroethene ND 1.0 1,1,2,2-tetrachloroethane ND 1.0 chlorobenzene ND 1.0 1,3-dichlorobenzene ND 1.0 1,2-dichlorobenzene ND 1.0 1,4-dichlorobenzene ND 1.0			
tetrachloroethene ND 1.0 1,1,2,2-tetrachloroethane ND 1.0 chlorobenzene ND 1.0 1,3-dichlorobenzene ND 1.0 1,2-dichlorobenzene ND 1.0 1,4-dichlorobenzene ND 1.0			
1,1,2,2-tetrachloroethane chlorobenzene 1,3-dichlorobenzene 1,2-dichlorobenzene 1,4-dichlorobenzene 1,4-dichlorobenzene			
chlorobenzene 1,3-dichlorobenzene 1,2-dichlorobenzene 1,4-dichlorobenzene ND 1.0 ND 1.0 ND 1.0			
1,3-dichlorobenzene 1,2-dichlorobenzene ND 1.0 1,4-dichlorobenzene			
1,2-dichlorobenzene 1,4-dichlorobenzene ND 1.0		="	
t 4.dichloropenzene	· · · · · · · · · · · · · · · · · · ·		
	l,4-dichlorobenzene	1417	

Nb = Nct detected at or above reporting limit.

Λ	/OC	SUMMA	RY
1 1/4	. / 1 71 .	OTATATA	

3 RPD, % 109 RECOVERY, %



LABORATORY NUMBER: 103800-2

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO SAMPLE ID: MW-3

DATE RECEIVED: 05/14/91 DATE ANALYZED: 05/24/91

DATE REPORTED: 05/31/91

EPA 8010

Purgeable Halocarbons in Water

Compound	Result	Reporting
Compound	ug/L	Limit
		ug/L
chloromethane	ND	20
bromome than e	ND	20
vinyl chloride	ND	20
chloroethane	ND	20
methylene chloride	ND	20
trichlorofluoromethane	ND	10
1.1-dichloroethene	ND	10
1,1-dichloroethane	ND	10
cis-1,2-dichloroethene	ND	10
trans-1,2-dichloroethene	ND	10
chloroform	ND	10
freen 113	ND	10
1,2-dichloroethane	380	10
l, l, l-trichloroethane	ND	10
carbon tetrachloride	ND	10
bromodichloromethane	ND	10
1,2-dichloropropane	ND	10
cis-1,3-dichloropropene	ND	10
trichloroethylene	14	10
1,1,2-trichloroethane	ND	10
trans-1,3-dichloropropene	ND	10
dibromochloromethane	ND	10
2-chloroethyl vinyl ether	ND	20
bromoform	ND	10
tetrachloroethene	ND	10
1,1,2,2-tetrachloroethane	ND	10
chlorobenzene	ND	10
1,3-dichlorobenzene	ND	10
I, 2-dichlorobenzene	ND	10
1,4-dichlorobenzene	, ND	10
.,	1	

ND = Not detected at or above reporting limit.

QA/QC SUMMARY

3 RPD, % 109 RECOVERY, %



LABORATORY NUMBER: 103800 DATE RECEIVED: 05/14/91 CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING DATE ANALYZED: 05/22,25/91

PROJECT ID: 6-91-5165 DATE REPORTED: 05/31/91

LOCATION: VORELCO

Total Volatile Hydrocarbons with BTXE in Aqueous Solutions TVH by California DOHS Method/LUFT Manual October 1989 BTXE by EPA 5030/8020

LAB ID	SAMPLE	ID	TVH AS GASOLINE	BENZENE	TOLUENE	ETHYL BENZENE	TOTAL XYLENES
·			(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
103800-1	MW-1		130	ND(0.5)	ND(0.5)	ND(0.5)	1.1
103800-2	MW-3		81,000	7,800	,	1,200	4,000
103800-3	TRIP		ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)

ND = Not detected at or above reporting limit; Reporting limit indicated in parentheses.

QA/QC SUMMARY	
RPD, %	<1
RECOVERY, %	100
•	



LABORATORY NUMBER: 103800

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO

DATE RECEIVED: 05/14/91 DATE EXTRACTED: 05/21/91 DATE ANALYZED: 05/22/91

DATE REPORTED: 05/31/91

Extractable Petroleum Hydrocarbons in Aqueous Solutions California DOHS Method LUFT Manual October 1989

LAB ID	CLIENT ID	KEROSENE RANGE (ug/L)	DIESEL RANGE (ug/L)	MOTOR OIL RANGE (ug/L)	REPORTING LIMIT* (ug/L)	
				N.T.D.	50	
103800-1	MW- 1	ND	ND	ND		
		NITS	ND	155	50	
103800-2	MW - 3	ND	MD	155		

ND = Not detected at or above reporting limit.

*Reporting limit applies to all analytes.

QA/QC SUMMARY		* * ·	
	 =======	=	

RPD, % RECOVERY, % 2 104



LABORATORY NUMBER: 103800

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO

DATE RECEIVED: 05/14/91
DATE EXTRACTED: 05/22/91

DATE ANALYZED: 05/23/91 DATE REPORTED: 05/31/91

Extractable Petroleum Hydrocarbons in Soils & Wastes
California DOHS Method
LUFT Manual October 1989

LAB ID	SAMPLE ID	KEROSENE RANGE (mg/Kg)	DIESEL RANGE (mg/Kg)	MOTOR OIL RANGE (mg/Kg)	REPORTING LIMIT* (mg/Kg)
103800-6	SB - 3@5 ' SB - 3@1 0 ' SB - 3@1 5 '	ND ND ND	ND ND ND	ND 91 ND	1.0 1.0 1.0
103800-8	SB - 4@5 ' SB - 4@1 5 ' MW - 4@5 '	ND ND ND ND	ND ND ND ND	ND 14 ND ND	1.0 1.0 1.0 1.0

ND = Not Detected at or above reporting limit.

*Reporting limit applies to all analytes.

QA/QC SUMMARY

(/ / /



DATE RECEIVED: 05/14/91 LABORATORY NUMBER: 103800

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING DATE ANALYZED: 05/23/91

PROJECT ID: 6-91-5165

DATE REPORTED: 05/31/91

LOCATION: VORELCO

Total Volatile Hydrocarbons with BTXE in Soils & Wastes TVH by California DOHS Method/LUFT Manual October 1989 BTXE by EPA 5030/8020

LAB ID	SAMPLE ID	TVH AS GASOLINE	BENZENE	TOLUENE	ETHYL BENZENE	TOTAL XYLENES
		(mg/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)	(ug/Kg)
103800-5	SB-3@5;	2.3	5.2	6.0	ND(5.0)	21
103800-6	SB - 3@10'	740	1,200	30,000	9,400	42,000
103800-7	SB - 3@15'	5.9	810	480	99	380
103800-8	SB - 4@5 '	ND(1.0)	ND(5.0)	ND(5.0)	ND(5.0)	ND(5.0)
103800-9	SB - 4@15'	13	610	1,100	170	840
103800-10	MW- 4@5 '	ND(1.0)	ND(5.0)	ND(5.0)	ND(5.0)	ND(5.0)
103800-11	MW - 4@10'	21	220	700	260	1,300

ND = Not detected at or above reporting limit; Reporting limit indicated in parentheses.

QA/QC SUMMARY ,		
	=======================================	3
RPD, %	,	94
RECOVERY, %		

DATE 5-14-91 PAGE OF	CHAIN OF CUSTOD	Y RECORD .		Environmental
	ANALYSES TO BE PERFORM	ED MATRI	x	Science &
PROJECT NAME VORELCO ADDRESS 2740 Broadway			N C	Engineering, Inc.
Oakland, CA	(308) (308)	M A	M M	A CILCORP Company (415) 685-4053 Nelson Avenue
PROJECT NO. $(a-91-5/65)$		M A T R I X	N C W O M N H T A090 N Suite Conco	ord, CA 94520 Fax (415) 685-5323
SAMPLED BY Oliver Christer	lega die	±	N	
LAB NAME Curtis & Tompkins	4 . 4 . 4 . 4		F R (C	REMARKS CONTAINER, SIZE, ETC.)
SAMPLE # DATE TIME LOCATION	コピンスタンド マンド・ファイン	MATRI		
MW-1 5/13/91 10:25 Oakland		Wate	7 6	VOAS and 1 Liter
2 MW-3 5/13/41 10:45 Oakland		Wate		VOAS and 1 Liter
JRIP 5/13/91 6:45 Oakland		Wate	T-1 - 1	3 VOAS
15 B-1 5/13/91 8:45 Oakland		<i></i>	$ 3 \rightarrow $	HOLD SAMPLES
5 8-35 5/3/91 10:01 Oaklan		Soi		
58-3 1 5/13/91 10:10 Oaklan		Soil	{- -<i>{</i>- -/-	All in
15B-33t 5/13/91 10:16 Oaklane		Soi	/ 	Brass
8 58-4 9+ 5/13/91 10:49 Oakkn	4×1×1-1-1-1-1	_ Soil		Rings
15B-4 3 5/13/91 11:00 Daklan		<u>Soi</u> 50i		18199
MW-4 35 5/13/91 11:40 Oaklan		5011		
MW-4 6 5/13/11 13:30 Daklan				
9889	RECEIVED BY: (signature)	date time	27 TO	TAL NUMBER OF CONTAINERS
RELINQUISHED BY: (signature)	Watt Killen	date time 5/14/9, 2:35	REPORT	SPECIAL SHIPMENT REQUIREMENTS
2.	7	ř ř	RESULTS TO:	REQUIREMENTS
3.			Sue	
4.			Wickham	SAMPLE RECEIPT
5.		040 11		CHAIN OF CUSTODY SEALS
INSTRUCTIONS TO LABORATORY (ha	ndling, analyses, storage	, ecc.,: /NJSTRU	ICTIONS	REC'D GOOD CONDTN/COLD
	WICHAM!	1100.11		CONFORMS TO RECORD
10 v TA				



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (415) 486-0900

DATE RECEIVED: 05/14/91 DATE REQUESTED: 06/04/91 DATE REPORTED: 06/11/91

LAB NUMBER: 104012

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO

RESULTS: SEE ATTACHED

DA/OC Approval

Final App



Client:

Environmental Science & Engineering Laboratory Login Number: 104012

Project Name:

Vorelco

Report Date:

11 June 91

Project Number: 6-91-5165

ANALYSIS: pH

ab ID	Sample ID	Matrix	Sampled	Received	Analyzed	Result	Ųnits	Method	Analyst	QC Batch
104012-001	se-3a10*	Soil	13-MAY-91	14-MAY-91	06-JUN-91	7.6	su +	EPA 9045	TR	1625
										4
							* Soil	pH measu	ıred as wa	ter
					•					
			•							
	- (,					

QC Batch Report

Environmental Science & Engineering Laboratory Login Number: 104012 Client:

Report Date: Project Name: Vorelco

11 June 91

Project Number: 6-91-5165

ANALYSIS: pH

QC Batch Number:

1625

Calibration Verification Results

Sample	Result	TV	Difference	Limit	Analyzed
ICV	10.00	10.00	.00	< 0.10	06-JUN-91
	10.04	10.00	.04	< 0.10	06-JUN-91

Sample Duplicate Results

Sample	Duplicate	RPD	Analyzed
7.60	7.59	.1%	06-JUN-91



PEPORTING

LABORATORY NUMBER: 104012-1

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165 LOCATION: VORELCO SAMPLE ID: SB-3@10' DATE RECEIVED: 05/14/91
DATE REQUESTED: 06/04/91
DATE ANALYZED: 06/06/91
DATE REPORTED: 06/11/91

EPA 8010: Volatile Halocarbons in Soil & Wastes Extraction Method: EPA 5030 - Purge & Trap

		REPORTING
Compound	RESULT	LIMIT
	ug/Kg	ug/Kg
ch lor ome t ban e	ND	10
bromome than e	ND	10
vinyl chloride	ND	10
chloroethane	ND	10
methylene chloride	ND	5.0
trichlorofluoromethane	ND	5.0
1,1-dichloroethene	ND	5.0
1,1-dichloroethane	ND .	5.0
cis-1,2-dichloroethene	ND	5.0
trans-1,2-dichloroethene	ND	5.0
chloroform	ND	5.0
freon 113	ND	5.0
l,2-dichloroethane	ND	5.0
l,l,l-trichloroethane	ND	5.0
carbon tetrachloride	ND	5.0
bromodichloromethane	ND	5.0
1,2-dichloropropane	ND	5.0
cis-1,3-dichloropropene	ND	5.0
trichloroethylene	ND	5.0
l, l, 2 - trichloroethane	ND	5.0
trans-1,3-dichloropropene	ND	5.0
d i bromo ch l o rome than e	ND	5.0
2-chloroethylvinyl ether	ND	10
bromo form	ND	5.0
tetrachloroethylene	ND	5.0
l,l,2,2-tetrachloroethane	ND	5.0
chlorobenzene	ND	5.0
l,3-dichlorobenzene	ND	5.0
l, 2-dichlorobenzone	ND	5.0
l, 4-dichlorobenzene	ND	5.0

ND = Not detected at or above reporting limit.

QA/QC SUMMARY

Duplicate: Relative % Difference
Spike: Average % Recovery

13



LABORATORY NUMBER: 104012-1

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING DATE REQUESTED: 06/04/91

PROJECT ID: 6-91-5165

LOCATION: VORELCO

SAMPLE ID: SB-3@10'

DATE RECEIVED: 05/14/91

DATE ANALYZED: 06/06/91

DATE REPORTED: 06/11/91

PARAMETER	RESULT	UNITS	REPORTING LIMIT	METHOD
CADMIUM	0.27	mg/Kg	0.25	EPA 6010
CHROMIUM	27.4	mg/Kg	0.5	EPA 6010
LEAD	5.0	mg/Kg	3.0	EPA 7420
NICKEL	42.5	mg/Kg	1.6	EPA 6010
ZINC	45.5	mg/Kg	0.5	EPA 6010

QA/QC SUMMARY

	RPD, %	Recovery, %
CADMIUM	1	92
CHROMI UM	<1	99
LEAD	5	108
NICKEL	<1	100
ZINC	<1	9 2



LABORATORY NUMBER: 104012-1

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO SAMPLE ID: SB-3@10'

DATE RECEIVED: 05/14/91

DATE REQUESTED: 06/05/91 DATE ANALYZED: 06/06,10/91

DATE REPORTED: 06/11/91

PARAMETER	RESULT	UNITS	REPORTING LIMIT	METHOD
CYANIDE	ND	mg/Kg	1.0	SW-846 SECTION 7.3.3.2
SULFIDE	ND	mg/Kg	1.0	SW-846 SECTION 7.3.4.1
CORROSIVITY	<6.35	mm/year		EPA 1110

QA/QC SUMMARY

	RPD, %	RECOVERY, %	
SULFIDE	<1	* =	
CYANIDE	<1	105	((
CORROSIVITY	4	• •	(,



VERBAL ADDITIONS / CANCELLATIONS TO ANALYSIS REQUEST SHEET

CLIENT: E	32			DATE:	5/5/9		
REQUESTED BY	r: Oliver Cl	tain	e	TIME: 09:	36 am/	pm	
RECORDED BY:		·					,
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1	,					
Current Lab ID		Circle	Specify add				
(Previous Lab II	D) Client ID	matrix	or cancel	Anal		Due date	
1 }	SB-3 B10'	soil water other	(AD)	Wet P	b .	juine 10	1,199
(103800 - 00	76)						
-	34, SB-3810'	soil water other	ADD	RCI:	r, Suffe	6/10	/91
-)	soil water other		conoc	int ptin		
-)	soil water other					
)	soil water other					
		soil water other					
(-	;	soil water otner					
-)	soil water other					
Original in job	jacket.		Copies to	analytical de	partments.		



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (415) 486-0900

DATE RECEIVED: 05/15/91 DATE REQUESTED: 05/21/91 DATE REPORTED: 05/28/91

LAB NUMBER: 103871

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO

RESULTS: SEE ATTACHED

QA/QC Approval

Final Apple



LABORATORY NUMBER: 103871

CLIENT: ENVIRONMENTAL SCIENCE & ENGINEERING

PROJECT ID: 6-91-5165

LOCATION: VORELCO

DATE RECEIVED: 05/15/91 DATE REQUESTED: 05/21/91

DATE EXTRACTED: 05/22/91

DATE ANALYZED: 05/23/91 DATE REPORTED: 05/28/91

Extractable Petroleum Hydrocarbons in Soils & Wastes California DOHS Method LUFT Manual October 1989

LAB ID	SAMPLE ID	KEROSENE RANGE (mg/Kg)	DIESEL RANGE (mg/Kg)	REPORTING LIMIT* (mg/Kg)
103871-2 103871-3	SB-2A @ +10' SB-2A @ +15' SB-2B @ +10' SB-2B @ +15'	ND ND ND ND	ND ND ND ND	1.0 1.0 1.0

ND = Not Detected at or above reporting limit.

*Reporting limit applies to all analytes.

QA/QC SUMMARY	· · · · · · · · · · · · · · · · · · ·
RPD, %	16
RECOVERY, %	99
======================================	

Loca 103271



VERBAL ADDITIONS / CANCELLATIONS TO ANALYSIS REQUEST SHEET

CLIENT: 85 REQUESTED BY: RECORDED BY: JOAM Voreles Pro Specify add Circle Current Lab ID Due date Analysis Client ID matrix or cancel (Previous Lab ID) (soil 103828-4 water other soil-water 2A@15 103828-5 ۔ سانوی ZB@10 water other (soil Add 103828-0 2B@15 water other soil run 8010 soil water other soil water other soil water other Original in job jacket. Copies to analytical departments.