

- Nedtocation MBE+ other
oxygenates n 18260 next event
- provide area otte plan so he can
December 7, 1999 plan location a soffsite
pull, if recessary. If The

QUARTERLY GROUNDWATER MONITORING REPORT NOVEMBER 1999 GROUNDWATER SAMPLING ASE JOB NO. 3190

at
Peerless Stages Bus Property
2021 Brush Street
Oakland, California

Prepared by:
AQUA SCIENCE ENGINEERS, INC.
208 W. El Pintado
Danville, CA 94526
(925) 820-9391

1.0 INTRODUCTION

The following is a report detailing the results of the November 1999 quarterly groundwater sampling at the Peerless Stages bus company site located on 2021 Brush Street in Oakland, California (Figures 1 and 2).

2.0 SITE HISTORY

2.1 October 1997 Soil and Groundwater Assessment

For decades, the site has been used as a maintenance yard and fueling site for the Peerless Stages bus company. In October 1997, Cambria Environmental Technology, Inc. of Oakland, California drilled five (5) soil These borings were drilled in the vicinity of the borings at the site. existing 2,000 gallon gasoline underground storage tank (UST), 8,000 gallon diesel-fuel UST and dispensers for the collection of soil and groundwater samples (Figure 2). Elevated concentrations petroleum hydrocarbons as gasoline (TPH-G) and diesel (TPH-D) were detected in the grab groundwater samples collected from two borings. to 120 parts per billion (ppb) TPH-G and 58,000 ppb TPH-D were detected in the groundwater samples. See Cambria's Subsurface Assessment Report dated October 20, 1997 for complete details regarding these activities.

2.2 May 1998 Gasoline UST Removal

In May 1998, ASE removed the 2,000 gallon gasoline UST from the site. Soil samples were collected from the bottom of the excavation and from the stockpiled soil generated during excavation activities. The soil samples were analyzed for TPH-G, TPH-D, benzene, toluene, ethyl benzene, total xylenes (collectively known as BTEX), methyl tertiary butyl ether (MTBE) and total lead. The only constituent identified in soil samples collected from the excavation was MTBE at concentrations up to 4.0 parts per million (ppm). The stockpiled soil contained 1.6 ppm TPH-G, 170 ppm TPH-D, trace concentrations of BTEX and MTBE, and 180 ppm total lead. The excavation was backfilled with import material on May 13, 1998. See ASE's UST Removal Report dated June 8, 1998 for complete details regarding these activities.

2.3 December 1998 Diesel UST Removal

In December 1998, ASE returned to the site to remove the 8,000 gallon diesel-fuel UST and the two dispensers. Soil samples were collected from the bottom of the excavation, from beneath the dispensers, and from the

Peerless Stages Quarterly Report - November 1999 Sampling

stockpiled soil generated during excavation activities. The soil samples were analyzed for TPH-G, TPH-D, BTEX, MTBE and total lead. constituents detected in the soil samples collected from the excavation were 0.064 ppm MTBE and 30 ppm TPH-D in soil samples collected from the eastern end of the excavation, and 5.1 ppm TPH-D in soil samples collected from the western end of the excavation. The soil samples collected beneath the dispensers contained up to 3,800 ppm TPH-D and trace concentrations of BTEX and MTBE. No TPH-G was detected in these Soil samples collected from the stockpiled soil contained 2,900 samples. ppm TPH-D, 510 ppm TPH-G, trace concentrations of BTEX and MTBE, 130 ppm total lead, and 4.9 ppm soluble lead by the waste extraction test The excavation was backfilled with clean import material. ASE's UST Removal Report dated January 8, 1999 for complete details regarding these activities. The stockpiled soil generated during the UST removal activities was transported to the Forward, Inc. Landfill in Manteca, California on May 25, 1999 for disposal. Also on May 25, 1999, the dispenser area was overexcavated to a depth of 11-feet below ground surface (bgs) in an effort to define and remove the vertical depth of TPH-D contamination beneath the dispensers previously identified in December Approximately 10 cubic yards of soil were removed and were 1998. transported along with the original stockpile to the Forward, Inc. landfill in Manteca, California. Two soil samples were collected from the northern and southern end of the excavation after overexcavation activities were completed. Analytical results indicated hydrocarbon concentrations up to 17 ppm TPH-G, 250 ppm TPH-D, and 4.6 ppm total lead.

2.4 Monitoring Well Installation

On August 18, 1999. ASE constructed monitoring wells, MW-1, MW-2, MW-3, and MW-4 at the site.

The soil sample collected from 15.5-feet bgs in boring MW-2 contained 53 ppm TPH-G, 190 ppm TPH-D, and 0.018 ppm flourene. No other compounds were detected in the soil samples collected above the laboratory reporting limits.

The groundwater sample collected from monitoring well MW-1 contained 81 ppb TPH-G, 3.5 ppb benzene, 7.9 ppb toluene, 3.2 ppb ethyl benzene, and 15.0 ppb total xylenes. The groundwater sample collected from monitoring well MW-2 contained 8,600 ppb TPH-G, 1,200 ppb TPH-D, and 14,000 ppb MTBE. The groundwater sample collected from monitoring well MW-3 contained 2.5 ppb benzene, 3.0 ppb toluene, 0.87 ppb ethyl benzene, and 4.0 ppb total xylenes. The groundwater sample collected

Peerless Stages Quarterly Report - November 1999 Sampling

-2-

well MW-3 contained 2.5 ppb benzene, 3.0 ppb toluene, 0.87 ppb ethyl benzene, and 4.0 ppb total xylenes. The groundwater sample collected from monitoring well MW-4 contained 420 ppb TPH-D, 0.88 ethyl benzene, and 3.6 ppb total xylenes.

3.0 GROUNDWATER FLOW DIRECTION AND GRADIENT

On November 11, 1999, ASE associate geologist Ian Reed measured the depth to water in all four site groundwater monitoring wells using an electric water level sounder. The surface of the groundwater was also checked for the presence of free-floating hydrocarbons or sheen. No free-floating hydrocarbons or sheen were observed in any site monitoring well. Groundwater elevation data is presented as Table One.

A groundwater potentiometric surface map is presented as Figure 2. The groundwater flow direction is to the northwest with an approximate gradient ranging between 0.001 ft/ft and 0.004 ft/ft. The water table has risen an average of 0.05-feet since October 1999.

4.0 GROUNDWATER SAMPLE COLLECTION AND ANALYSIS

Prior to sampling, each monitoring well was purged of four well casing volumes of groundwater using dedicated polyethylene bailers. The parameters pH, temperature and conductivity were monitored during the well purging. Samples were not collected until these parameters stabilized. Groundwater samples were collected from each well using dedicated polyethylene bailers.

The samples to be analyzed for volatile compounds were decanted from the bailers into 40-ml volatile organic analysis (VOA) vials, pre-preserved with hydrochloric acid and capped without headspace. The samples to be analyzed for TPH-D were contained in 1-liter amber glass containers. All of the samples were labeled and placed in a cooler with wet ice for transport to Chromalab, Inc. of Pleasanton, California (ELAP #1094) under appropriate chain-of-custody documentation. Well sampling field logs are presented in Appendix A.

The well purge water was placed in 55-gallon steel drums, labeled, and left on-site for temporary storage.

The groundwater samples were analyzed for total petroleum hydrocarbons as gasoline (TPH-G) by EPA Method 5030/8015M, TPH-D by modified EPA Method 3510/8015M, benzene, toluene, ethylbenzene and total xylenes (collectively known as BTEX) by EPA Method 8020 and methyl tertiary-

Peerless Stages Quarterly Report - November 1999 Sampling

butyl ether (MTBE) by EPA Method 8020. The analytical results for this and previous sampling periods are presented in Table Two. The certified analytical report and chain-of-custody documentation are included as Appendix B.

5.0 CONCLUSIONS

The groundwater samples collected from monitoring well MW-1 contained 110 ppb TPH-D. The groundwater samples collected from monitoring well MW-2 contained 710 ppb TPH-G, 2,300 ppb TPH-D, and 6,200 ppb MTBE. The groundwater samples collected from monitoring well MW-4 contained 120 ppb TPH-D. No other compounds were detected above laboratory reporting limits.

In general, the TPH-G, BTEX and MTBE concentrations decreased from last quarter. The TPH-D concentrations in groundwater samples collected from monitoring well MW-1 and MW-2 increased slightly. The MTBE concentration in the groundwater sample collected from monitoring well MW-2 exceeded the DHS MCL for drinking water. There is no DHS MCL established for TPH-G and TPH-D.

6.0 RECOMMENDATIONS

ASE recommends the subject site remain on a quarterly sampling schedule. The next sampling is scheduled for February 2000.

7.0 REPORT LIMITATIONS

The results presented in this report represent the conditions at the time of the groundwater sampling, at the specific locations where the groundwater samples were collected, and for the specific parameters analyzed by the laboratory. It does not fully characterize the site for contamination resulting from sources other than the former underground storage tanks and associated plumbing at the site, or for parameters not analyzed by the laboratory. All of the laboratory work cited in this report was prepared under the direction of independent CAL-EPA certified laboratory. The independent laboratory is solely responsible for the contents and conclusions of the chemical analysis data.

-4-

Aqua Science Engineers appreciates the opportunity to provide environmental consulting services for this site and trust that this report meets your needs. Please feel free to call us at (925) 820-9391 if you have any questions or comments.

No. 6586

Respectfully submitted,

AQUA SCIENCE ENGINEERS, INC.

Ian T. Reed

Associate Geologist

Robert E. Kitay, R.G., R.E.A.

Senior Geologist

Attachments: Figures 1 through 2

Appendices A and B

cc: Mr. Alex Gaeta, Responsible Party

Mr. Gardner Kent, Property Owner

Ms. Eva Chu, ACHSA

Mr. Chuck Headlee, RWQCB, San Francisco Bay Region

- 5 -

TABLES

TABLE ONE
Summary of Groundwater Well Survey Data
Peerless Stages Property, Oakland, California

| Well ID | Date of Measurement | Top of Casing Elevation (relative to project datum) | Depth to Water (feet) | Groundwater Elevation (project datum) |
|------------|---------------------------|---|-----------------------------|---|
| MW-1 | 08/26/99 11/11/99 | 19.66 | 16.44 16.56 | 3.22 3.10 |
| MW-2 | 08/26/99 11/11/99 | 20.00 | 16.88 16.92 | 3.12 3.08 |
| MW-3 | 08/26/99 11/11/99 | 18.91 | 15.94 15.98 | 2.97 2.93 |
| MW-4 | 08/26/99 11/11/99 | 19.43 | 16.48 16.50 | 2.95 2.93 |

2

TABLE TWO
Summary of Chemical Analysis for Groundwater Samples
Peerless Stages Property, Oakland, California

All results are in parts per billion (ppb)

| SAMPLE ID | DA TE SAMP LED | TPH-G | TPH-D | BENZENE | TOLUENE | ETHYL- BENZENE | TOTAL XYLENES | MTBE | PNA's |
|------------|---------------------------------|-------|-------|---------|------------|-------------------|------------------|--------|------------------|
| MW-1 | 9/24/00 | 0.1 | . 50 | 2 " | ~ ^ | 2.2 | 15 | 5.0 | N7.4 |
| IVI VV - I | 8/26/ 99 | 81 | < 50 | 3.5 | 7.9 | 3.2 | 15 | < 5.0 | NA |
| | 11/11 /99 | < 50 | 110 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | < 5.0 | NA |
| MW-2 | 8/26 /99 | 8,600 | 1,200 | < 25 | < 25 | < 25 | < 25 | 14,000 | < 0.057 - < 0.23 |
| | 11/11 /99 | 710 | 2,300 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | 6,200 | NA |
| MW-3 | 8/26/ 99 | < 50 | < 63 | 2.5 | 3 | 0.87 | 4 | < 5.0 | NA |
| | 11/11 /99 | < 50 | < 56 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | < 5.0 | NA |
| MW-4 | 8/26/ 99 | < 50 | 420 | < 0.5 | < 0.5 | 0.88 | 3.6 | < 5.0 | NA |
| | 11/1 1/99 | < 50 | 120 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | < 5.0 | NA |

Notes:

Non-Detectable concentrations are noted by a less than symbol (<) followed by the laboratory reporting limit


NE = DHS MCL not established

PNAs = Polynuclear Aromatic Hydrocarbons

DHS MCLs = Department of Health Services Maximum Contaminant Levels for drinking water

NA = Sample was not analyzed

FIGURES





SITE LOCATION MAP

Former Peerless Stages, Inc Property 2021 Brush Street Oakland, California

Aqua Science Engineers

Figure 1





GROUNDWATER ELEVATION
CONTOUR MAP
11/11/99

Former Peerless Stages, Inc. Property
2021 Brush Street
Oakland, California

AQUA SCIENCE ENGINEERS

Figure 2

APPENDIX A

Well Sampling Field Logs



| Project Name and Address: | reerless |
|-------------------------------|---|
| Job #:3190 | Date of sampling: |
| Well Name: Mw-1 | Sampled by:/TR_ |
| Total depth of well (feet): | Well diameter (inches): 2 1 |
| Depth to water before sample | ing (feet): |
| Thickness of floating product | t if anv: |
| Depth of well casing in water | er (feet): |
| Number of gallons per well | casing volume (gallons): 1.8 |
| Number of well casing volume | nes to be removed: 4 |
| Req'd volume of groundwater | r to be purged before sampling (gallons): 2.1 |
| | e well: deducated barler |
| Time Evacuation Began:1 | Time Evacuation Finished: 1425 |
| Approximate volume of gro | undwater purged: |
| Did the well go dry?: | After how many gallons: |
| Time samples were collected | d:/431 |
| Depth to water at time of s | ampling: IL.56 |
| Percent recovery at time of | sampling: [OV]. |
| Samples collected with: | dedicated batt |
| Sample color: clar quar | Odor: PMC |
| Description of sediment in s | sample: sil any |
| CHEMICAL DATA | · · |
| Volume Purged Temp | pH Conductivity |
| 17.4 | _ 1272 |
| 7 71.4 | |
| 3 72.4 | |
| 4 43.1 | <u> 1326</u> |
| | |
| SAMPLES COLLECTED | |
| <u>MW.1</u> 3 40m | & type container Pres Iced? Analysis V V V V V V V V V V V V V V V V V V V |
| | |



| Project Name and Address: | tecricss |
|--|---|
| | Date of sampling: 11-11.99 |
| Well Name: MV-2 Total depth of well (feet): | Sampled by: |
| Total depth of well (feet): | 30.0' Well diameter (inches): 24 |
| Depth to water before samp | ling (feet): |
| Thickness of floating produc | |
| Depth of well casing in water | |
| | casing volume (gallons): 2 2 |
| | mes to be removed: 4 |
| | r to be purged before sampling (gallons): 8.9 |
| Equipment used to purge th | e well: dedicated scales |
| Time Evacuation Began: 13 | Time Evacuation Finished: 1420 |
| Approximate volume of gro | undwater purged:9 |
| Did the well go dry?: NO | After how many gallons: |
| Time samples were collecte | After how many gallons: |
| Depth to water at time of s | ampling: /6,43 sampling: /00// |
| Percent recovery at time of | sampling: 150 % |
| Samples collected with: | dedicated Sailer |
| Sample color: arem | Odor: slightnen -Hl'sdor |
| Description of sediment in | sample: |
| CHEMICAL DATA | |
| <u>Volume Purged</u> <u>Temp</u> | pH Conductivity |
| 71,4 | 6.14 1092 |
| <u>2</u> | 1110 |
| 3 77,3 | 6.54 1242 |
| 4 77.6 | |
| | |
| SAMPLES COLLECTED | |
| Sample # of containers Volume | & type container Pres Iced? Analysis |
| MV? 3 40 | |
| MW"-) | er Amber |
| | |
| | |
| | |
| | |

| Project Name and Address: | Peerless | | |
|-----------------------------------|---------------------------|----------------------|---|
| Job #:3190 | Date of sampling: | 11 11 99 | |
| Well Name: MW -3 | Sampled by: | | |
| Total depth of well (feet): | 29,40' Well dia | meter (inches): z" | _ |
| Depth to water before sampling | g (feet): <i>/5.98</i> " | | _ |
| Thickness of floating product is | f any: | | _ |
| Depth of well casing in water | (feet):13.62 | | _ |
| Number of gallons per well ca | sing volume (gallons):_ | 23 | _ |
| Number of well casing volume | s to be removed: | | |
| Req'd volume of groundwater t | o be purged before san | npling (gallons): 95 | |
| Equipment used to purge the | well: | | |
| Time Evacuation Began: 445 | Time Evacua | tion Finished: 1505 | - |
| Approximate volume of ground | | | |
| Did the well go dry?: UU | | any gallons: | |
| Time samples were collected:_ | | | |
| Depth to water at time of sam | pling: | | |
| Percent recovery at time of sa | | | |
| Samples collected with: | | 1 bailor | |
| Sample color: char gray | Odor: | none | |
| Description of sediment in san | iple: <u>- Silt</u> | | _ |
| CHEMICAL DATA | | | |
| Volume Purged Temp | <u>pH</u> <u>Conducti</u> | vitv | |
| 1,9 | 5.W 784 | <u> </u> | |
| <u> </u> | 5.01 716 | | |
| <u> </u> | 5,94 741 | | |
| <u> 7. C</u> | 5.13 7-82 | | |
| | | | |
| SAMPLES COLLECTED | | | |
| | | | |
| Sample # of containers Volume & t | ype container Pres Iced? | <u>Analysis</u> | |
| | ops I | | |
| MW-3 3 1-11h1 | Anjo | | |
| | | | |
| | | | |
| | | | |
| | | | |

| Project Name and Address: | Per less |
|---|--|
| Job #: 3 190 Well Name: MW-4 | Date of sampling: 11-11-99 |
| Total depth of well (feet): | Sampled by: The state of the st |
| Depth to water before compline | 29.64' Well diameter (inches): Z' |
| Depth to water before sampling | f onv: |
| Thickness of floating product is Depth of well casing in water | (foot): |
| Number of gallons per wall so | (leet): 13 / 1 |
| Number of well casing volume | sing volume (gallons): $\geq \cdot 2$ |
| Number of well casing volume. | s to be removed: |
| Equipment used to purge the | o be purged before sampling (gallons): 8.8 |
| Time Evacuation Regard 194 | Time Evacuation Finished: 1455 |
| Approximate volume of ground | الله Evacuation Finished: الله الله الله الله الله الله الله الل |
| Did the well go dry?: NO | |
| (T)' | |
| Depth to water at time of sam Percent recovery at time of sa | nling: // CU |
| Percent recovery at time of sa | maling: 9k./ |
| Samples collected with: | detroled will |
| Sample color: | |
| Description of sediment in sam | Odar: <u>none</u> uple: Silt |
| sain sain | bic: |
| CHEMICAL DATA | |
| Volume Purged Temp | pH Conductivity |
| +6.4 | <u>6:71</u> <u>813</u> |
| $\frac{2}{3}$ $\frac{23.5}{231}$ | (e.41) 423 |
| <u>75.1</u> 4 27.6 | 657 4=1 |
| 77.6 | 487 |
| | |
| SAMPLES COLLECTED | |
| | |
| Sample # of containers Volume & to | |
| | $\frac{\partial i^4 s}{\partial x^4}$ |
| MW 9 2 1-1-11/ | Ameris |
| | |
| | |
| | |
| | |

APPENDIX B

Certified Analytical Report and Chain of Custody Documentation Environmental Services (SDB)

Submission #: 1999-11-0229

Date: November 23, 1999

Aqua Science Engineers, Inc. 208 West El Pintado Road Danville, CA 94526

Attn.: Mr. lan T. Reed

Project: 3190

Peerless Stages Bus

Dear Mr. Reed,

Attached is our report for your samples received on Friday November 12, 1999. This report has been reviewed and approved for release. Reproduction of this report is permitted only in its entirety.

Please note that any unused portion of the samples will be discarded after December 12, 1999 unless you have requested otherwise. We appreciate the opportunity to be of service to you. If you have any questions, please call me at (925) 484-1919.

Sincerely,

Vincent Vancil

Environmental Services (SDB)

Diesel

Aqua Science Engineers, Inc.

208 West El Pintado Road

Danville, CA 94526

Attn: Ian T. Reed

Danimo, 01104020

Phone: (925) 820-9391 Fax: (925) 837-4853

Project #: 3190

Project: Peerless Stages Bus

Samples Reported

| Sample ID | Matrix | Date Sampled | Lab# |
|-----------|--------|--------------|------|
| MW-1 | Water | 11/11/1999 | 1 |
| MW-2 | Water | 11/11/1999 | 2 |
| MW-3 | Water | 11/11/1999 | 3 |
| MW-4 | Water | 11/11/1999 | 4 |

Submission #: 1999-11-0229

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method: 8015m

Attn.: Ian T. Reed

Prep Method: 3510/8015M

Diesel

Sample ID: MW-1 Lab Sample ID: 1999-11-0229-001

Project:

3190

Received:

11/12/1999 13:31

Peerless Stages Bus

Extracted:

11/17/1999 09:00

Sampled:

11/11/1999

Matrix:

Water

QC-Batch: 1999/11/17-02.10

| Compound | Result | Rep.Limit | Units | Dilution | Analyzed | Flag |
|--------------|--------|-----------|-------|----------|------------------|------|
| Diesel | 110 | 50 | ug/L | 1.00 | 11/17/1999 17:08 | qbn |
| Surrogate(s) | | | | | | • |
| o-Terpheny! | 88.9 | 60-130 | % | 1.00 | 11/17/1999 17:08 | |

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Attn.: Ian T. Reed

Test Method:

8015m

Submission #: 1999-11-0229

Prep Method:

3510/8015M

Diesel

MW-2 Sample ID:

Lab Sample ID: 1999-11-0229-002

Project:

3190

Peerless Stages Bus

Received:

11/12/1999 13:31

Extracted:

11/17/1999 09:00

Sampled:

11/11/1999

Matrix:

Water

QC-Batch:

1999/11/17-02.10

Sample/Analysis Flag: rl (See Legend & Note section)

| Compound | Result | Rep.Limit | Units | Dilution | Analyzed | Flag |
|-----------------------------|--------|-----------|-------|----------|------------------|------|
| Diesel | 2300 | 57 | ug/L | 1,14 | 11/17/1999 17:52 | ndp |
| Surrogate(s) o-Terphenyl | 85.2 | 60-130 | % | 1.14 | 11/17/1999 17:52 | • |

Environmental Services (SDB)

Aqua Science Engineers, Inc.

To: Attn.: Ian T. Reed Test Method:

8015m

Submission #: 1999-11-0229

Prep Method:

3510/8015M

Diesel

Sample ID:

MW-3

Lab Sample ID: 1999-11-0229-003

Project:

3190

Peerless Stages Bus

Received:

11/12/1999 13:31

Extracted:

11/17/1999 09:00

Sampled:

11/11/1999

Matrix:

Water

QC-Batch:

1999/11/17-02.10

| Compound | Result | Rep.Limit | Units | Dilution | Analyzed | Flag |
|-----------------------------|--------|-----------|-------|----------|------------------|-------|
| Diesel | ND | 56 | ug/L | 1,11 | 11/17/1999 18:36 | ndp · |
| Surrogate(s) o-Terphenyl | 100.4 | 60-130 | % | 1.00 | 11/17/1999 18:36 | |

Submission #: 1999-11-0229

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

8015m

Attn.: Ian T. Reed

Prep Method:

3510/8015M

Diesel

Sample ID:

MW-4

Lab Sample ID: 1999-11-0229-004

Project:

3190

Received:

11/12/1999 13:31

Peerless Stages Bus

Extracted:

11/17/1999 09:00

Sampled:

11/11/1999

Matrix:

Water

QC-Batch:

1999/11/17-02.10

| Result | Rep.Limit | Units | Dilution | Analyzed | Flag |
|--------|-----------|--------|-------------|------------------|-----------------------------------|
| 120 | 55 | ug/L | 1.10 | 11/17/1999 19:20 | ndp |
| 101.2 | 60-130 | % | 1 00 | 11/17/1999 19:20 | |
| | | 120 55 | 120 55 ug/L | 120 55 ug/L 1.10 | 120 55 ug/L 1.10 11/17/1999 19:20 |

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8015m

Attn.: lan T. Reed

Prep Method:

3510/8015M

Batch QC Report

Diesel

Water

Method Blank

QC Batch # 1999/11/17-02.10

Submission #: 1999-11-0229

MB: 1999/11/17-02.10-001

Date Extracted: 11/17/1999 09:00

| Compound | Result | Rep.Limit | Units | Analyzed | Flag |
|--------------|--------|-----------|-------|------------------|------|
| Diesel | ND | 50 | ug/L | 11/17/1999 12:55 | |
| Surrogate(s) | | | | | |
| o-Terphenyl | 104.5 | 60-130 | % | 11/17/1999 12:55 | |

Submission #: 1999-11-0229

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8015m

Attn: lan T. Reed

Prep Method:

3510/8015M

Batch QC Report

Diesel

Laboratory Control Spike (LCS/LCSD)

Water

QC Batch # 1999/11/17-02.10

LCS:

1999/11/17-02.10-002

Extracted: 11/17/1999 09:00

Analyzed: 11/17/1999 13:31

LCSD:

1999/11/17-02.10-003

Extracted: 11/17/1999 09:00

Analyzed: 11/17/1999 14:08

| Compound | Conc. | [ug/L] | J/L] Exp.Conc. [ug/L] Recovery [%] RPD Ctrl. Limits [%] | | Recovery [%] R | | Recovery [%] | | Recovery [%] RPD | | its [%] | Flags | |
|---------------------|-------|----------|---|------|----------------|-------|--------------|----------|------------------|-----|---------|-------|--|
| | LCS | LCSD | LCS | LCSD | LCS | LCSD | [%] | Recovery | RPD | LCS | LCSD | | |
| Diesel Surrogate(s) | 1170 | 1190 | 1250 | 1250 | 93.6 | 95.2 | 1.7 | 60-130 | 25 | | | | |
| o-Terphenyl | 21.3 | 20.7 | 20.0 | 20.0 | 106.5 | 103.5 | | 60-130 | | | | | |

£{

Submission #: 1999-11-0229

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method: 8015m

Attn:lan T. Reed

Prep Method: 3510/8015M

Legend & Notes

Diesel

Analysis Flags

rl

Reporting limits raised due to reduced sample size.

Analyte Flags

ndp

Hydrocarbon reported does not match the pattern of our Diesel standard

Environmental Services (SDB)

Gas/BTEX and MTBE

Aqua Science Engineers, Inc.

Danville, CA 94526

Attn: Ian T. Reed

Phone: (925) 820-9391 Fax: (925) 837-4853

Project #: 3190

Project: Peerless Stages Bus

Samples Reported

| Sample ID | Matrix | Matrix Date Sampled | | | |
|-----------|--------|---------------------|---|--|--|
| MVV-1 | Water | 11/11/1999 | 1 | | |
| MW-2 | Water | 11/11/1999 | 2 | | |
| MW-3 | Water | 11/11/1999 | 3 | | |
| MW-4 | Water | 11/11/1999 | 4 | | |

Environmental Services (SDB)

Aqua Science Engineers, Inc.

Test Method:

8015M

Submission #: 1999-11-0229

8020

Attn.: Ian T. Reed

To:

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID: MW-1

Lab Sample ID: 1999-11-0229-001

Project:

3190

Received:

11/12/1999 13:31

Peerless Stages Bus

Extracted:

11/19/1999 04:31

Sampled:

11/11/1999

QC-Batch:

1999/11/18-01.05

Matrix:

Water

| Compound | Result | Rep.Limit | Units | Dilution | Analyzed | Flag |
|--------------------------|--------|-----------|-------|----------|------------------|------|
| Gasoline | ND | 50 | ug/L | 1.00 | 11/19/1999 04:31 | |
| Benzene | ND | 0.50 | ug/L | 1.00 | 11/19/1999 04:31 | |
| Toluene | ND | 0.50 | ug/L | 1.00 | 11/19/1999 04:31 | |
| Ethyl benzene | ND | 0.50 | ug/L | 1.00 | 11/19/1999 04:31 | |
| Xylene(s) | ИD | 0.50 | ug/L | 1.00 | 11/19/1999 04:31 | |
| MTBE | ND | 5.0 | ug/L | 1.00 | 11/19/1999 04:31 | |
| Surrogate(s) | | | | | | |
| Trifluorotoluene | 75.8 | 58-124 | % | 1.00 | 11/19/1999 04:31 | |
| 4-Bromofluorobenzene-FID | 58.4 | 50-150 | % | 1.00 | 11/19/1999 04:31 | |
| | 1 | [| 1 1 | | 1 | |

Submission #: 1999-11-0229

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method: 8015M

8020

Attn.: Ian T. Reed

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-2

Lab Sample ID: 1999-11-0229-002

Project:

3190

Received:

11/12/1999 13:31

Peerless Stages Bus

Extracted:

Sampled:

11/11/1999

11/19/1999 05:03

Matrix:

Water

QC-Batch:

1999/11/18-01.05

| Compound | |
|----------|--|
| Gasolina | |

| Compound | Resuit | Rep.Limit | Units | Dilution | Analyzed | Flag |
|--------------------------|--------|-----------|-------|----------|------------------|------|
| Gasoline | 710 | 50 | ug/L | 1.00 | 11/19/1999 05:03 | g |
| Benzene | ND | 0.50 | ug/L | 1.00 | 11/19/1999 05:03 | |
| Toluene | ND | 0.50 | ug/L | 1.00 | 11/19/1999 05:03 | |
| Ethyl benzene | ND | 0.50 | ug/L | 1.00 | 11/19/1999 05:03 | |
| Xylene(s) | ND | 0.50 | ug/L | 1.00 | 11/19/1999 05:03 | |
| MTBE | 6200 | 250 | ug/L | 50.00 | 11/22/1999 10:39 | |
| Surrogate(s) | | | | | | |
| Trifluorotoluene | 86.8 | 58-124 | % | 1.00 | 11/19/1999 05:03 | |
| 4-Bromofluorobenzene-FID | 58.7 | 50-150 | % | 1.00 | 11/19/1999 05:03 | |

Environmental Services (SDB)

Aqua Science Engineers, Inc.

Test Method:

8015M

Submission #: 1999-11-0229

8020

Attn.: Ian T. Reed

To:

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-3

Lab Sample ID: 1999-11-0229-003

Project:

3190

Received:

11/12/1999 13:31

Peerless Stages Bus

Extracted:

11/22/1999 10:12

Sampled:

11/11/1999

QC-Batch:

Matrix:

Water

1999/11/22-01.01

| Compound | Result | Rep.Limit | Units | Dilution | Analyzed | Flag |
|----------------------|--------|-----------|-------|----------|------------------|------|
| Gasoline | ND | 50 | ug/L | 1.00 | 11/22/1999 10:12 | |
| Benzene | ND | 0.50 | ug/L | 1.00 | 11/22/1999 10:12 | |
| Toluene | DN | 0.50 | ug/L | 1.00 | 11/22/1999 10:12 | |
| Ethyl benzene | ND | 0.50 | ug/L | 1.00 | 11/22/1999 10:12 | |
| Xylene(s) | ND | 0.50 | ug/L | 1.00 | 11/22/1999 10:12 | |
| MTBE | ND | 5.0 | ug/L | 1.00 | 11/22/1999 10:12 | |
| Surrogate(s) | | | | | | |
| Trifluorotoluene | 69.4 | 58-124 | % | 1.00 | 11/22/1999 10:12 | |
| Trifluorotoluene-FID | 58.5 | 58-124 | % | 1.00 | 11/22/1999 10:12 | |

Environmental Services (SDB)

Aqua Science Engineers, Inc.

Test Method:

8015M

Submission #: 1999-11-0229

8020

Attn.: Ian T. Reed

To:

Prep Method:

5030

Gas/BTEX and MTBE

Sample ID:

MW-4

Lab Sample ID: 1999-11-0229-004

Project:

3190

Received:

11/12/1999 13:31

Peerless Stages Bus

Extracted:

11/22/1999 10:25

Sampled:

11/11/1999

Matrix:

Water

QC-Batch: 1999/11/22-01.05

| Compound | Result | Rep.Limit | Units | Dilution | Analyzed | Flag |
|--------------------------|--------|-----------|-------|----------|------------------|------|
| Gasoline | ND | 50 | ug/L | 1.00 | 11/22/1999 10:25 | · |
| Benzene | ND | 0.50 | ug/L | 1.00 | 11/22/1999 10:25 | |
| Toluene | ND | 0.50 | ug/L | 1.00 | 11/22/1999 10:25 | |
| Ethyl benzene | ND | 0.50 | ug/L | 1.00 | 11/22/1999 10:25 | |
| Xylene(s) | ND | 0.50 | ug/L | 1.00 | 11/22/1999 10:25 | |
| MTBE | ND | 5.0 | ug/L | 1.00 | 11/22/1999 10:25 | |
| Surrogate(s) | | | | | | |
| Trifluorotoluene | 71.9 | 58-124 | % | 1.00 | 11/22/1999 10:25 | |
| 4-Bromofluorobenzene-FID | 60.4 | 50-150 | % | 1.00 | 11/22/1999 10:25 | |

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

8015M

8020

Attn.: Ian T. Reed

Prep Method:

5030

Batch QC Report Gas/BTEX and MTBE

Method Blank

Water

QC Batch # 1999/11/18-01.05

Submission #: 1999-11-0229

MB:

1999/11/18-01.05-001

Date Extracted: 11/18/1999 14:02

| Compound | Result | Rep.Limit | Units | Analyzed | Flag |
|--------------------------|--------|-----------|-------|------------------|----------|
| Gasoline | ND | 50 | ug/L | 11/18/1999 14:02 | <u>_</u> |
| Benzene | ND | 0.5 | ug/L | 11/18/1999 14:02 | |
| Toluene | ND | 0.5 | ug/L | 11/18/1999 14:02 | |
| Ethyl benzene | ND | 0.5 | ug/L | 11/18/1999 14:02 | |
| Xylene(s) | ND | 0.5 | ug/L | 11/18/1999 14:02 | |
| MTBE | ND | 5.0 | ug/L | 11/18/1999 14:02 | |
| Surrogate(s) | | | | | |
| Trifluorotoluene | 68.4 | 58-124 | % | 11/18/1999 14:02 | |
| 4-Bromofluorobenzene-FID | 51.4 | 50-150 | % | 11/18/1999 14:02 | |

Submission #: 1999-11-0229

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method: 8015M

8020

Attn.: Ian T. Reed

Prep Method:

5030

Batch QC Report Gas/BTEX and MTBE

Method Blank

Water

QC Batch # 1999/11/22-01.05

MB:

1999/11/22-01.05-001

Date Extracted: 11/22/1999 05:41

| Compound | Result | Rep.Limit | Units | Analyzed | Flag |
|--------------------------|--------|-----------|-------|------------------|------|
| Gasoline | ND | 50 | ug/L | 11/22/1999 05:41 | |
| Benzene | ND | 0.5 | ug/L | 11/22/1999 05:41 | |
| Toluene | ND | 0.5 | ug/L | 11/22/1999 05:41 | |
| Ethyl benzene | ND | 0.5 | ug/L | 11/22/1999 05:41 | |
| Xylene(s) | ND | 0.5 | ug/L | 11/22/1999 05:41 | |
| MTBE | ND | 5.0 | ug/L | 11/22/1999 05:41 | |
| Surrogate(s) | İ | | | | |
| Trifluorotoluene | 113.6 | 58-124 | % | 11/22/1999 05:41 | |
| 4-Bromofluorobenzene-FID | 54.6 | 50-150 | % | 11/22/1999 05:41 | |

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method:

8015M

8020

Attn.: Ian T. Reed

Prep Method:

5030

Batch QC Report Gas/BTEX and MTBE

Method Blank

Water

QC Batch # 1999/11/22-01.01

Submission #: 1999-11-0229

MB:

1999/11/22-01.01-001

Date Extracted: 11/22/1999 06:33

| Compound | Result | Rep.Limit | Units | Analyzed | Flag |
|--------------------------|--------|-----------|-------|------------------|------|
| Gasoline | ND | 50 | ug/L | 11/22/1999 06:33 | |
| Benzene | ND | 0.5 | ug/L | 11/22/1999 06:33 | |
| Toluene | ND | 0.5 | ug/L | 11/22/1999 06:33 | |
| Ethyl benzene | ND | 0.5 | ug/L | 11/22/1999 06:33 | |
| Xylene(s) | ND | 0.5 | ug/L | 11/22/1999 06:33 | |
| MTBE | ND | 5.0 | ug/L | 11/22/1999 06:33 | |
| Surrogate(s) | | | | | |
| Trifluorotoluene | 104.0 | 58-124 | % | 11/22/1999 06:33 | |
| 4-Bromofluorobenzene-FID | 53.8 | 50-150 | % | 11/22/1999 06:33 | |

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method: 8015M

8020

Submission #: 1999-11-0229

Attn: Ian T. Reed

Prep Method:

5030

Batch QC Report

Gas/BTEX and MTBE

Laboratory Control Spike (LCS/LCSD)

Water

QC Batch # 1999/11/18-01.05

LCS:

1999/11/18-01.05-002

Extracted: 11/18/1999 15:24

Analyzed: 11/18/1999 15:24

LCSD:

1999/11/18-01.05-003

Extracted: 11/18/1999 15:56

Analyzed: 11/18/1999 15:56

| Compound | Conc. | [ug/L] | Exp.Conc. | [ug/L] | Recovery [%] | | RPD | Ctrl. Limits [%] | | Flags | |
|-------------------------|-------|--------|-----------|----------|--------------|-------|-----|------------------|-----|-------|------|
| | LCS | LCSD | LCS | LCSD | LCS | LCSD | [%] | Recovery | RPD | LCS | LCSD |
| Gasoline | 428 | 408 | 500 | 500 | 85.6 | 81.6 | 4.8 | 75-125 | 20 | | |
| Benzene | 90.2 | 97.8 | 100.0 | 100.0 | 90.2 | 97.8 | 8.1 | 77-123 | 20 | | |
| Toluene | 93.6 | 98.5 | 100.0 | 100.0 | 93.6 | 98.5 | 5.1 | 78-122 | 20 | | |
| Ethyl benzene | 93.7 | 97.3 | 100.0 | 100.0 | 93.7 | 97.3 | 3.8 | 70-130 | 20 | | |
| Xylene(s) | 269 | 277 | 300 | 300 | 89.7 | 92.3 | 2.9 | 75-125 | 20 | | |
| Surrogate(s) | | | | | | | | | | | |
| Trifluorotoluene | 551 | 546 | 500 | 500 | 110.2 | 109.2 | | 58-124 | | ! | |
| 4-Bromofluorobenzene-FI | 338 | 324 | 500 | 500 | 67.6 | 64.8 | | 50-150 | | | |

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Laboratory Control Spike (LCS/LCSD)

Test Method:

8015M

Submission #: 1999-11-0229

8020

Attn: Ian T. Reed

Prep Method:

5030

Batch QC Report

Gas/BTEX and MTBE

Water

QC Batch # 1999/11/22-01.05

LCS:

1999/11/22-01.05-002

Extracted: 11/22/1999 06:13

Analyzed: 11/22/1999 06:13

LCSD:

1999/11/22-01.05-003

Extracted: 11/22/1999 06:46

Analyzed: 11/22/1999 06:46

| Compound | Conc. | [ug/L] | Exp.Conc. | [ug/L] | Recovery [%] | | RPD | Ctrl. Limits [%] | | Flags | |
|-------------------------|-------|--------|-----------|--------|--------------|-------|-----|------------------|-----|-------|--------------|
| | LCS | LCSD | LCS | LCSD | LCS | LCSD | [%] | Recovery | RPD | LCS | LCSD |
| Gasoline | 478 | 495 | 500 | 500 | 95.6 | 99.0 | 3.5 | 75-125 | 20 | | |
| Benzene | 113 | 109 | 100.0 | 100.0 | 113.0 | 109.0 | 3.6 | 77-123 | 20 | | |
| Toluene | 119 | 112 | 100.0 | 100.0 | 119.0 | 112.0 | 6.1 | 78-122 | 20 | | |
| Ethyl benzene | 117 | 110 | 100.0 | 100.0 | 117.0 | 110.0 | 6.2 | 70-130 | 20 | | |
| Xylene(s) | 324 | 306 | 300 | 300 | 108.0 | 102.0 | 5.7 | 75-125 | 20 | | |
| Surrogate(s) | } | | | | | | | | | | |
| 4-Bromofluorobenzene | 514 | 519 | 500 | 500 | 102.8 | 103.8 | | 50-150 | | | |
| 4-Bromofluorobenzene-Fi | 316 | 330 | 500 | 500 | 63.2 | 66.0 | | 50-150 | | | |

Submission #: 1999-11-0229

Environmental Services (SDB)

To: Aqua Science Engineers, Inc. Test Method:

8015M

8020

Attn: Ian T. Reed

Prep Method:

5030

Batch QC Report

Gas/BTEX and MTBE

Laboratory Control Spike (LCS/LCSD)

Water

QC Batch # 1999/11/22-01.01

LCS:

1999/11/22-01.01-002

Extracted: 11/22/1999 07:00

Analyzed: 11/22/1999 07:00

LCSD:

1999/11/22-01.01-003

Extracted: 11/22/1999 07:28

Analyzed: 11/22/1999 07:28

| Compound | Conc. | [ug/L] | Exp.Conc. | [ug/L] | Recov | ery [%] | RPD | Ctrl. Lim | its [%] | Flags | | |
|-------------------------|-------|----------|-----------|----------|-------|---------|------|-----------|---------|-------|----------------|--|
| | LCS | LCSD | LCS | LCSD | LCS | LCSD | [%] | Recovery | RPD | LCS | LCSD | |
| Gasoline | 523 | 438 | 500 | 500 | 104.6 | 87.6 | 17.7 | 75-125 | 20 | | - | |
| Benzene | 98.3 | 101 | 100.0 | 100.0 | 98.3 | 101.0 | 2.7 | 77-123 | 20 | | | |
| Toluene | 101 | 103 | 100.0 | 100.0 | 101.0 | 103.0 | 2.0 | 78-122 | 20 | | | |
| Ethyl benzene | 101 | 103 | 100.0 | 100.0 | 101.0 | 103.0 | 2.0 | 70-130 | 20 | | | |
| Xylene(s) | 299 | 307 | 300 | 300 | 99.7 | 102.3 | 2.6 | 75-125 | 20 | | } | |
| Surrogate(s) | ļ | | | | | | | | | | | |
| Trifluorotoluene | 530 | 542 | 500 | 500 | 106.0 | 108.4 | | 58-124 | | | | |
| 4-Bromofluorobenzene-FI | 356 | 276 | 500 | 500 | 71.2 | 55.2 | | 50-150 | | | | |

Environmental Services (SDB)

To: Aqua Science Engineers, Inc.

Test Method: 8015M

8020

Submission #: 1999-11-0229

Attn:lan T. Reed Prep Method: 5030

Legend & Notes

Gas/BTEX and MTBE

Analyte Flags

g

Hydrocarbon reported in the gasoline range does not match our gasoline standard.

Aqua Science Engineers, Inc. 208 W. El Pintado Road Danville, CA 94526 (925) 820-9391 FAX (925) 837-4853

99110229 Chain of Custody

| CAUGITE (CICHERIDA) | | | | | | | | | | | | PAGE | <i>:</i> ' | 1_0 | ۴ | <u> </u> | | | | | | |
|---------------------------------|--------------------|------|----------------------------------|---|---------------------------------|-------------------------------|---|---------------------------------------|---------------------------------------|--|---------------|---|----------------------------------|-------------------------------------|---|---|-------------------------------|--------------------|--|----|-------------|----------|
| SAMPLER (SIGNATURE) (PHONE NO.) | | | | | |) | PROJECT NAME | | | Pecrless Stag | | | | ges Bus | | | | JOB NO. 3190 | | | | |
| 1 les | le 7 Reed 925-820- | | | | 939 | , [| | | 2021 Br | | wh street | | t 00 | Dakland CA | | DATI | | | | | | |
| ANAL | YSIS | 3 RE | QUES | Τ | | T | <u> </u> | l ., | | | | | | | | T | l | · | | | | _ |
| SPECIAL INSTRUCTIONS: | | | | д (2) | TPH-GASOLINE (EPA 5030/8015) | | S S S S | Ŕ | VOLATILE ORGANICS (EPA 624/8240) | SEMI-VOLATILE ORGANICS (EPA 625/8270) | teAse (20) | LUFT METALS (5) (EPA 6010+7000) | CAM 17 METALS (EPA 6010+7000) | PCBs & PESTICIDES (EPA 608/8080) | ORGANOPHOSPHORUS PESTICIDES (EPA 8140) (EPA 608/8080) | ORGANOCHLORINE HERBICIDES (EPA 8150) | FUEL OXYGENATES (EPA 8260) | ı | | • | | |
| 5-day T.AT. | | | | TPH-GAS / MTBE & BTEX (EPA 5030/8015-8020) | | TPH-DIESEL (EPA 3510/8015) | PURGEABLE HALOCARBONS (EPA 601/8010) | PURGEABLE AROMATICS (EPA 602/8020) | | | | | | | | | | | | | COMPOSITE | |
| SAMPLE ID. | DATE | TIME | MATRIX | NO. OF SAMPLES | TPH-G/ (EPA 50 | TPH-G/ (EPA 50 | TPH-DIE (EPA 39 | PURGE/ (EPA 60 | PURGEA (EPA 6C | YOLATIL (EPA 62 | SEMI-VO | OIL & GREASE (EPA 5520) | LUFT ME (EPA 60 | CAM 17 (EPA 6C | PCBs & (EPA 6 | ORGAN PESTIC (EPA 6 | ORGAN | FUEL 0) (EPA 8; | | | i İ | COMP |
| MW-1 | 1] 11 49 | | water | 6 | \times | | × | | | | | | | | | | | | | | | |
| Mw-2 | 11 11 49 | | water | 6 | X | | X | | | - | | | | | | | | <u></u> | | | | |
| MW-3 | 11 11 99 | | water | 6 | X | | × | i | | | | | | | | | | | | | | <u> </u> |
| MW-4 | 11 11 99 | | water | b | X | | × | | | | | | | | | | | | | _, | | |
| | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | - | - | i | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | · | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | |
| | | | (CC (time) 1 (/) (date) | | (printed name) | | | (tlme) | · · · · · · · · · · · · · · · · · · · | | | RATOR ren (time) gto: (date) | Y: gtor | comments: 5. day | | | ¥7. | | | | | |
| ASE (compa | | | Company | 76 | | | Company- | | | | | D. Harrington 5 (printed name) (date) Company- Caramalab 11/12/990 1215 | | | | | | 5.4 | | | | |