

RECEIVED

2:21 pm, Oct 02, 2008

Alameda County
Environmental Health

REVISED REPORT: 12/30/86

LOG NO.: 4325

DATE SAMPLED: 12/22/86


DATE RECEIVED: 12/22/86

CUSTOMER: Atlas Hydraulic Corporation


REQUESTER: Bob Corsun

PROJECT: Mobil, San Leandro

Sample Type	Sample	Volatile Hydrocarbons	Benzene	Toluene	Xylene	Extractable Hydrocarbons
<u>Soil</u>		<u>mg/kg</u>	<u>mg/kg</u>	<u>mg/kg</u>	<u>mg/kg</u>	<u>mg/kg</u>
	#1	120	<0.7	<0.7	11	
	#2	1,700	<0.5	3.1	27	
	#3	3.8	0.058	<0.03	0.45	
	#4	1,600	<6	13	150	
	#5	<1	<0.03	<0.03	<0.03	
	#6	27	<0.06	<0.06	1.8	
	Waste Oil	<1				<0.1


Susan R. Setzer
Assistant Laboratory Director

SRS:les



DATE: 1/06/87

LOG NO.: 4338

DATE SAMPLED: 12/31/86


DATE RECEIVED: 12/31/86

CUSTOMER: Atlas Hydraulic Corporation

REQUESTER: Bob Corsun



PROJECT: Mobil, San Leandro
EAST 14TH & 150TH

<u>Sample Type</u>	<u>Sample</u>	<u>Volatile Hydrocarbons</u>	<u>Benzene</u>	<u>Toluene</u>	<u>Xylene</u>
<u>Soil</u>		<u>mg/kg</u>	<u>mg/kg</u>	<u>mg/kg</u>	<u>mg/kg</u>
	#2, 3 1/2 feet deeper than 12/22/86 excavation	110	< 0.3	< 0.5	< 0.5
	#4, 3 1/2 feet deeper than 12/22/86 excavation	940	< 0.3	< 0.5	< 0.5
	Pile, Sample #1	< 3	< 0.06	< 0.3	< 0.3
	Pile, Sample #2	10	< 0.06	< 0.6	< 0.6



Susan R. Setzer
Assistant Laboratory Director

SITE DIAGRAM, MOBIL , SAN LEANDRO



SITE DIAGRAM, MOBIL , SAN LEANDRO

