

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (#.)	DTW (#.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-8											
09/07/90 ³	123.61	16.07	--	107.54	--	<50	<0.5	<0.5	<0.5	<0.5	<0.05
09/25/90	123.61	16.20		107.41	--	--	--	--	--	--	--
11/29/90	123.61	16.30		107.31	--	<50	<0.5	<0.5	<0.5	<0.5	--
11/29/90 (D)	123.61	--		--	--	<50	<0.5	<0.5	<0.5	<0.5	--
02/20/91	123.61	16.32		107.29	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/19/91	123.61	14.71		108.90	--	--	--	--	--	--	--
05/22/91	123.61	15.42		108.19	--	<50	0.6	<0.5	<0.5	1.0	--
08/22/91	123.61	17.15		106.46	--	<50	<0.5	<0.5	<0.5	<0.5	--
11/14/91	123.61	16.99		106.62	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/30/92	123.61	16.30		107.31	--	<50	1.0	0.7	<0.5	1.1	--
04/23/92	123.61	15.05		108.56	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/27/92	123.61	16.08		107.53	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/26/92	123.61	16.72		106.89	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/29/93	123.61	12.82		110.79	--	1,400	470	470	37	160	--
04/30/93	123.61	13.54		110.07	--	1,600	<13	15	18	29	--
07/14/93	123.61	14.65		108.96	--	<50	<0.5	0.7	<0.5	2.0	--
10/27/93	123.61	15.04		108.57	--	<50	3.0	4.0	2.0	4.0	--
01/13/94	123.61	15.14		108.47	--	<50	<0.5	4.0	<0.5	<0.5	--
04/22/94	123.61	15.01		108.60	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/28/94	123.61	14.70		108.91	--	69	7.3	18	3.3	12	--
10/25/94	123.61	15.20		108.41	--	<50	<0.5	0.8	<0.5	1.6	--
01/19/95	123.61	12.00		111.61	--	<50	<0.5	3.1	<0.5	0.7	--
05/01/95	123.61	11.40		112.21	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/03/97	123.61	11.72		111.89	--	<200	<2.0	<2.0	<2.0	<2.0	610
10/07/97	123.61	13.60		110.01	--	<50	<0.5	<0.5	<0.5	<0.5	500
04/14/98	123.61	8.75		114.86	--	<50	<0.5	<0.5	<0.5	<0.5	120
10/13/98	123.61	12.72		110.89	--	270	<0.5	<0.5	<0.5	<0.5	2,600
04/16/99	123.61	11.55		112.06	--	480	<2.0	<2.0	<2.0	<2.0	5,000
07/29/99 ⁶	123.61	12.35		111.26	--	--	--	--	--	--	--
10/26/99	123.61	12.68		110.93	--	1,890	<5.0	12.1	<5.0	<5.0	39,000
04/07/00 ⁹	123.61	11.24		112.37	0.00	<500	<5.0	<5.0	<5.0	<5.0	2,500
10/10/00 ⁹	123.61	12.76		110.85	0.00	295 ¹¹	<0.500	<0.500	<0.500	<0.500	19,500
04/03/01 ⁹	123.61	12.09		111.52	0.00	3,340	2.84	3.05	<0.500	2.58	21,500
08/14/01 ¹³	123.61	13.06		110.55	0.00	2,800 ¹⁴	<20	<20	<20	<20	25,000
11/16/01	123.61	13.07		110.54	0.00	3,000	<1.0	1.1	<1.0	<3.0	16,000/19,000 ¹⁵
02/15/02	123.61	12.71		110.90	0.00	2,000	<0.50	<0.50	<0.50	<1.5	15,000/19,000 ¹⁵

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (<i>ft.</i>)	DTW (<i>ft.</i>)	S.L. (<i>ft.bgs</i>)	GWE. (<i>msl</i>)	SPHT (<i>ft.</i>)	TPH-G. (<i>ppb</i>)	B. (<i>ppb</i>)	T (<i>ppb</i>)	E (<i>ppb</i>)	X (<i>ppb</i>)	MTBE (<i>ppb</i>)
MW-8 (cont)											
05/09/02	123.61	12.95	--	110.66	0.00	3,900	<1.0	<1.0	<1.0	<3.0	16,000/15,000 ¹⁵
08/05/02	123.61	13.51		110.10	0.00	4,000	<1.0	<1.0	<1.0	<3.0	16,000/15,000 ¹⁵
11/04/02	123.61	13.85		109.76	0.00	2,800	<0.50	0.77	<0.50	<1.5	15,000/17,000 ¹⁵
02/05/03	123.61	12.60		111.01	0.00	3,600	<20	<2.5	<2.5	<7.5	16,000/18,000 ¹⁵
05/07/03	123.61	12.00		111.61	0.00	2,800	<2.5	<2.5	<2.5	<7.5	14,000/13,000 ¹⁵
08/11/03 ¹⁶	123.61	13.12		110.49	0.00	2,400	<10	<10	<10	<10	13,000
11/10/03 ¹⁶	123.61	15.16		108.45	0.00	2,600	<10	<10	<10	<10	13,000
02/09/04 ^{16,17}	123.61	13.16		110.45	0.00	<50	<0.5	<0.5	<0.5	<0.5	140
05/10/04 ¹⁶	123.61	12.75		110.86	0.00	1,900	<5	<5	<5	<5	12,000
08/09/04 ¹⁶	123.61	13.32		110.29	0.00	1,200	<10	<10	<10	<10	7,200
11/08/04 ¹⁶	123.61	13.50		110.11	0.00	710	<1	<1	<1	<1	3,900
02/07/05 ^{16,17}	123.61	12.13		111.48	0.00	<50	<0.5	<0.5	<0.5	<0.5	12
05/06/05 ¹⁶	123.61	12.15		111.46	0.00	770	<5	<5	<5	<5	5,100
08/05/05 ¹⁶	123.61	13.49		110.12	0.00	660	<3	<3	<3	<3	3,600
11/04/05 ¹⁶	123.61	13.03		110.58	0.00	210	<0.5	<0.5	<0.5	<0.5	1,600
02/01/06 ¹⁶	123.61	11.22		112.39	0.00	170	<0.5	<0.5	<0.5	<0.5	1,800
05/03/06 ¹⁶	123.61	10.15		113.46	0.00	210	<1	<1	<1	<1	3,500
08/02/06 ¹⁶	123.61	11.81		111.80	0.00	480	<1	<1	<1	<1	3,800
10/31/06¹⁶	123.61	12.75		110.86	0.00	540	<0.5	<0.5	<0.5	<0.5	3,200
MW-9											
08/22/91 ³	124.20	17.60	--	106.60	--	9,600	46	170	98	1,200	<0.05
11/14/91 ³	124.20	17.48		106.72	--	11,000	130	58	86	1,500	<0.05
01/30/92	124.20	16.71		107.49	--	11,000	210	29	110	1,900	--
04/23/92	124.20	15.23		108.97	--	17,000	180	25	100	1,900	--
07/27/92	124.20	16.72		107.48	--	2,800	59	1.6	18	280	--
10/26/92	124.20	17.22		106.98	--	3,200	38	<0.5	19	200	--
01/29/93	124.20	13.39		110.81	--	1,300	23	6.0	8.0	100	--
04/30/93	124.20	14.00		110.20	--	<1,300	<13	<13	<13	58	--
07/14/93	124.20	15.08		109.12	--	1,300	25	4.0	15	120	--
10/27/93	124.20	15.62		108.58	--	1,100	21	10	19	73	--
01/13/94	124.20	15.59		108.61	--	80	0.7	3.0	0.6	3.0	--
04/22/94	124.20	15.43		108.77	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/29/94	124.20	15.20		109.00	--	1,400	19	11	11	69	--
10/25/94	124.20	15.70		108.50	--	1,200	11	2.0	7.6	28	--

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (<i>ft.</i>)	DTW (<i>ft.</i>)	S.L. (<i>ft.bgs</i>)	GWE (<i>msl</i>)	SPHT (<i>ft.</i>)	TPH-G (<i>ppb</i>)	B (<i>ppb</i>)	T (<i>ppb</i>)	E (<i>ppb</i>)	X (<i>ppb</i>)	MTBE (<i>ppb</i>)
MW-9 (cont)											
01/19/95	124.20	12.58	--	111.62	--	380	1.6	4.3	1.5	11	--
05/01/95	124.20	11.96		112.24	--	350	1.1	<0.5	1.8	2.3	--
10/12/95	124.20	13.85		110.35	--	1,700	3.8	<2.5	5.3	7.8	18
04/11/96	124.20	11.87		112.33	--	140	<0.5	<0.5	<0.5	<0.5	2.8
10/03/96	124.20	14.07		110.13	--	53	<0.5	<0.5	<0.5	<0.5	<2.5
04/03/97	124.20	12.38		111.82	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/07/97	124.20	14.14		110.06	--	66	1.3	<0.5	<0.5	<0.5	<2.5
04/14/98	124.20	9.55		114.65	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/13/98	124.20	12.61		111.59	--	190	<0.5	<0.5	<0.5	<0.5	1,900
04/16/99	124.20	11.01		113.19	--	3,800	<12	<12	<12	<12	4,400
07/29/99 ⁶	124.20	12.85		111.35	--	--	--	--	--	--	--
10/26/99	124.20	13.24		110.96	--	88.6	<0.5	<0.5	<0.5	<0.5	530
04/07/00 ⁹	124.20	11.68		112.52	0.00	<5,000	<50	<50	<50	<50	27,000
10/10/00 ⁹	124.20	13.30		110.90	0.00	<50.0	<0.500	<0.500	<0.500	<0.500	322
04/03/01 ⁹	124.20	12.69		111.51	0.00	258	<0.500	<0.500	<0.500	0.743	1,300
08/14/01 ¹³	124.20	13.60		110.60	0.00	170 ¹⁴	<0.50	<0.50	<0.50	<0.50	1,300
11/16/01	124.20	13.81		110.39	0.00	100	<0.50	0.99	<0.50	<1.5	330/330 ¹⁵
02/15/02	124.20	13.32		110.88	0.00	<50	<0.50	<0.50	<0.50	<1.5	220/240 ¹⁵
05/09/02	124.20	13.50		110.70	0.00	300	<0.50	<0.50	<0.50	<1.5	970/940 ¹⁵
08/05/02	124.20	14.10		110.10	0.00	110	<0.50	<0.50	<0.50	<1.5	470/420 ¹⁵
11/04/02	124.20	14.41		109.79	0.00	110	<0.50	0.67	<0.50	<1.5	530/520 ¹⁵
02/05/03	124.20	13.17		111.03	0.00	70	<0.50	<0.50	<0.50	<1.5	320/340 ¹⁵
05/07/03	124.20	12.65		111.55	0.00	87	<0.5	0.7	<0.5	<1.5	440/390 ¹⁵
08/11/03 ¹⁶	124.20	13.71		110.49	0.00	74	<0.5	<0.5	<0.5	<0.5	370
11/10/03 ¹⁶	124.20	14.27		109.93	0.00	53	<0.5	<0.5	<0.5	<0.5	190
02/09/04 ^{16,17}	124.20	12.72		111.48	0.00	1,600	<5	<5	<5	<5	8,100
05/10/04 ¹⁶	124.20	13.35		110.85	0.00	<50	<0.5	<0.5	<0.5	<0.5	120
08/09/04 ¹⁶	124.20	13.95		110.25	0.00	<50	<0.5	<0.5	<0.5	<0.5	61
11/08/04 ¹⁶	124.20	14.11		110.09	0.00	<50	<0.5	<0.5	<0.5	<0.5	74
02/07/05 ^{16,17}	124.20	11.69		112.51	0.00	600	<3	<3	<3	<3	3,200
05/06/05 ¹⁶	124.20	11.73		112.47	0.00	<50	<0.5	<0.5	<0.5	<0.5	45
08/05/05 ¹⁶	124.20	14.15		110.05	0.00	<50	<0.5	<0.5	<0.5	<0.5	1
11/04/05 ¹⁶	124.20	13.60		110.60	0.00	<50	<0.5	<0.5	<0.5	<0.5	130
02/01/06 ¹⁶	124.20	11.90		112.30	0.00	<50	<0.5	<0.5	<0.5	<0.5	27
05/03/06 ¹⁶	124.20	10.89		113.31	0.00	<50	<0.5	<0.5	<0.5	<0.5	82
08/02/06 ¹⁶	124.20	11.45		112.75	0.00	<50	<0.5	<0.5	<0.5	<0.5	85

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-9 (cont)											
10/31/06 ¹⁶	124.20	13.41	--	110.79	0.00	60	<0.5	<0.5	<0.5	<0.5	280
MW-10											
07/27/92	125.03	17.52	--	107.51	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/27/92	125.03	18.06	--	106.97	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/29/93	125.03	14.15	--	110.88	--	<50	<0.5	<0.5	<0.5	0.7	--
04/30/93	125.03	14.68	--	110.35	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/14/93	125.03	15.80	--	109.23	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/27/93	125.03	16.33	--	108.70	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/13/94	125.03	16.29	--	108.74	--	<50	<0.5	0.5	<0.5	<0.5	--
04/22/94	125.03	16.15	--	108.88	--	<50	<0.5	<0.5	<0.5	1.1	--
07/29/94	125.03	15.85	--	109.18	--	<50	0.8	2.1	0.5	1.3	--
10/25/94	125.03	16.41	--	108.62	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/19/95	125.03	13.29	--	111.74	--	<50	<0.5	<0.5	<0.5	<0.5	--
05/01/95	125.03	12.60	--	112.43	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/11/95	125.03	14.54	--	110.49	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/11/96	125.03	12.47	--	112.56	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/03/96	125.03	14.74	--	110.29	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/03/97	125.03	12.99	--	112.04	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/07/97	125.03	14.86	--	110.17	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/14/98	125.03	10.24	--	114.79	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/13/98 ⁷	124.69	13.06	--	111.63	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/16/99	124.69	11.80	--	112.89	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/26/99	124.69	13.43	--	111.26	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/07/00	124.69	12.00	--	112.69	0.00	--	--	--	--	--	--
10/10/00	124.69	13.59	--	111.10	0.00	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50
04/03/01	124.69	13.00	--	111.69	0.00	<50.0	<0.500	<0.500	<0.500	0.580	<0.500
08/14/01	124.69	13.91	--	110.78	0.00	<50	<0.50	<0.50	<0.50	<0.50	<2.5
11/16/01	124.69	13.94	--	110.75	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5/<2 ¹⁵
02/15/02	124.69	13.65	--	111.04	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/09/02	124.69	13.87	--	110.82	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
08/05/02	124.69	14.45	--	110.24	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
11/04/02	124.69	14.77	--	109.92	0.00	<50	<0.50	1.2	<0.50	<1.5	<2.5/<2 ¹⁵
02/05/03	124.69	13.49	--	111.20	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/07/03	124.69	12.99	--	111.70	0.00	<50	<0.5	<0.5	<0.5	<1.5	<2.5

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (<i>ft.</i>)	DTW (<i>ft.</i>)	S.L. (<i>ft.bgs</i>)	GWE (<i>msl</i>)	SPHT (<i>ft.</i>)	TPH-G (<i>ppb</i>)	B (<i>ppb</i>)	T (<i>ppb</i>)	E (<i>ppb</i>)	X (<i>ppb</i>)	MTBE (<i>ppb</i>)
MW-10 (cont)											
08/11/03 ¹⁶	124.69	14.04	--	110.65	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/10/03 ¹⁶	124.69	15.54		109.15	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/09/04 ¹⁶	124.69	13.46		111.23	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/10/04 ¹⁶	124.69	13.69		111.00	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/09/04 ¹⁶	124.69	14.30		110.39	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/08/04 ¹⁶	124.69	14.45		110.24	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/07/05 ¹⁶	124.69	12.41		112.28	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/06/05 ¹⁶	124.69	12.35		112.34	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/05/05 ¹⁶	124.69	14.44		110.25	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/04/05	124.69	13.96		110.73	0.00	--	--	--	--	--	--
02/01/06	124.69	12.19		112.50	0.00	--	--	--	--	--	--
05/03/06	124.69	11.25		113.44	0.00	--	--	--	--	--	--
08/02/06	124.69	12.42		112.27	0.00	--	--	--	--	--	--
10/31/06	124.69	13.72		110.97	0.00	--	--	--	--	--	--
MW-11											
07/27/92	122.92	15.38	--	107.54	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/26/92	122.92	15.97		106.95	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/29/93	122.92	12.24		110.68	--	<50	8.0	16	2.0	10	--
04/30/93	122.92	12.77		110.15	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/14/93	122.92	13.84		109.08	--	<50	<0.5	0.7	<0.5	1.0	--
10/27/93	122.92	14.23		108.69	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/13/94	122.92	14.24		108.68	--	<50	<0.5	1.0	<0.5	<0.5	--
04/22/94	122.92	14.08		108.84	--	<50	<0.5	0.5	<0.5	1.4	--
07/29/94	122.92	13.90		109.02	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/25/94	122.92	14.38		108.54	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/19/95	122.92	11.45		111.47	--	<50	<0.5	1.8	<0.5	<0.5	--
05/01/95	122.92	11.10		111.82	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/11/95	122.92	12.57		110.35	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/11/96	122.92	11.05		111.87	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/03/96	122.92	12.92		110.00	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/03/97	122.92	11.22		111.70	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/07/97	122.92	13.05		109.87	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/14/98	122.92	9.05		113.87	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/13/98	122.92	12.34		110.58	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-11 (cont)											
04/16/99	122.92	10.73	--	112.19	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/26/99	122.92	11.97		110.95	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/07/00	122.92	10.90		112.02	0.00	<50	<0.50	<0.50	<0.50	<0.50	<2.5
10/10/00	122.92	12.09		110.83	0.00	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50
04/03/01	122.92	11.59		111.33	0.00	<50.0	<0.500	<0.500	<0.500	<0.500	<0.500
08/14/01	122.92	12.40		110.52	0.00	<50	<0.50	<0.50	<0.50	<0.50	<2.5
11/16/01	122.92	13.45		109.47	0.00	<50	<0.50	0.73	<0.50	<1.5	<2.5/<2 ¹⁵
02/15/02	122.92	12.24		110.68	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/09/02	122.92	12.44		110.48	0.00	<50	<0.50	1.0	<0.50	<1.5	<2.5
08/05/02	122.92	12.97		109.95	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
11/04/02	122.92	13.28		109.64	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5/<2 ¹⁵
02/05/03	122.92	12.07		110.85	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/07/03	122.92	11.58		111.34	0.00	<50	<0.5	<0.5	<0.5	<1.5	<2.5
08/11/03 ¹⁶	122.92	12.61		110.31	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/10/03 ¹⁶	122.92	13.06		109.86	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/09/04 ¹⁶	122.92	12.04		110.88	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/10/04 ¹⁶	122.92	12.24		110.68	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/09/04 ¹⁶	122.92	12.85		110.07	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/08/04 ¹⁶	122.92	12.99		109.93	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/07/05 ¹⁶	122.92	11.87		111.05	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/06/05 ¹⁶	122.92	11.82		111.10	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/05/05 ¹⁶	122.92	12.98		109.94	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/04/05	122.92	12.50		110.42	0.00	--	--	--	--	--	--
02/01/06	122.92	10.75		112.17	0.00	--	--	--	--	--	--
05/03/06	122.92	10.22		112.70	0.00	--	--	--	--	--	--
08/02/06	122.92	11.91		111.01	0.00	--	--	--	--	--	--
10/31/06	122.92	12.28		110.64	0.00	--	--	--	--	--	--
MW-12											
09/01/00 ¹⁰	--	11.69	10-28.5	--	--	--	--	--	--	--	--
10/10/00	--	12.13		--	0.00	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50
04/03/01	--	11.35		--	0.00	<50.0	<0.500	<0.500	<0.500	<0.500	<0.500
08/14/01	122.36	12.21		110.15	0.00	<50	<0.50	<0.50	<0.50	<0.50	<2.5
11/16/01	122.36	12.72		109.64	0.00	<50	<0.50	0.59	<0.50	<1.5	<2.5/<2 ¹⁵
02/15/02	122.36	11.98		110.38	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-12 (cont)											
05/09/02	122.36	12.17	10-28.5	110.19	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
08/05/02	122.36	12.69		109.67	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
11/04/02	122.36	12.98		109.38	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5/<2 ¹⁵
02/05/03	122.36	11.81		110.55	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/07/03	122.36	11.28		111.08	0.00	<50	<0.5	<0.5	<0.5	<1.5	<2.5
08/11/03 ¹⁶	122.36	12.33		110.03	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/10/03 ¹⁶	122.36	12.77		109.59	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/09/04 ¹⁶	122.36	11.66		110.70	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/10/04 ¹⁶	122.36	11.90		110.46	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/09/04 ¹⁶	122.36	12.56		109.80	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/08/04 ¹⁶	122.36	12.70		109.66	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/07/05 ¹⁶	122.36	11.48		110.88	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/06/05 ¹⁶	122.36	11.41		110.95	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/05/05 ¹⁶	122.36	12.70		109.66	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/04/05	122.36	12.40		109.96	0.00	--	--	--	--	--	--
02/01/06 ¹⁸	122.36	10.69		111.67	0.00	--	--	--	--	--	--
05/03/06 ¹⁶	122.36	9.60		112.76	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/02/06	122.36	11.50		110.86	0.00	--	--	--	--	--	--
10/31/06	122.36	12.18		110.18	0.00	--	--	--	--	--	--
MW-13											
09/01/00 ¹⁰	--	11.57	19-34	--	--	--	--	--	--	--	--
10/10/00	--	11.83		--	0.00	<50.0	<0.500	<0.500	<0.500	<0.500	28.0
04/03/01	--	11.46		--	0.00	<50.0	<0.500	<0.500	<0.500	<0.500	<0.500
08/14/01	121.49	12.36		109.13	0.00	<50	<0.50	<0.50	<0.50	<0.50	<2.5
11/16/01	121.49	12.08		109.41	0.00	<50	<0.50	0.64	<0.50	<1.5	<2.5/<2 ¹⁵
02/15/02	121.49	11.81		109.68	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/09/02	121.49	12.00		109.49	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
08/05/02	121.49	12.48		109.01	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5/<2 ¹⁵
11/04/02	121.49	12.71		108.78	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5/<2 ¹⁵
02/05/03	121.49	11.51		109.98	0.00	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/07/03	121.49	10.81		110.68	0.00	<50	<0.5	0.6	<0.5	<1.5	<2.5
08/11/03 ¹⁶	121.49	12.15		109.34	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/10/03 ¹⁶	121.49	12.51		108.98	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/09/04 ¹⁶	121.49	11.56		109.93	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.I. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-13 (cont)											
05/10/04 ¹⁶	121.49	11.87	19-34	109.62	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/09/04 ¹⁶	121.49	12.37		109.12	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/08/04 ^{16,17}	121.49	13.00		108.49	0.00	75	<0.5	<0.5	<0.5	<0.5	400
02/07/05 ¹⁶	121.49	10.49		111.00	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/06/05 ¹⁶	121.49	10.45		111.04	0.00	60	<1	<1	<1	<1	570
08/05/05 ¹⁶	121.49	12.50		108.99	0.00	<50	<0.5	<0.5	<0.5	<0.5	470
11/04/05	121.49	12.18		109.31	0.00	--	--	--	--	--	--
02/01/06	121.49	10.43		111.06	0.00	--	--	--	--	--	--
05/03/06	121.49	8.87		112.62	0.00	--	--	--	--	--	--
08/02/06	121.49	10.55		110.94	0.00	--	--	--	--	--	--
10/31/06	121.49	11.95		109.54	0.00	--	--	--	--	--	--
MW-14											
09/01/00 ¹⁰	--	11.96	15-30	--	--	--	--	--	--	--	--
10/10/00	--	12.33		--	0.00	79.9 ¹¹	<0.500	<0.500	<0.500	<0.500	854
04/03/01	--	11.62		--	0.00	494	<0.500	<0.500	<0.500	<0.500	3,150
08/14/01	122.04	12.55		109.49	0.00	<1,000	<10	<10	<10	<10	2,600
11/16/01	122.04	12.55		109.49	0.00	1,500	<0.50	0.84	<0.50	<1.5	7,800/8,200 ¹⁵
02/15/02	122.04	12.31		109.73	0.00	1,100	<0.50	<0.50	<0.50	<1.5	6,300/6,000 ¹⁵
05/09/02	122.04	12.52		109.52	0.00	1,500	<0.50	<0.50	<0.50	<1.5	6,900/6,300 ¹⁵
08/05/02	122.04	12.94		109.10	0.00	870	<0.50	<0.50	<0.50	<1.5	3,700/3,600 ¹⁵
11/04/02	122.04	13.17		108.87	0.00	890	<0.50	<0.50	<0.50	<1.5	4,400/4,700 ¹⁵
02/05/03	122.04	12.41		109.63	0.00	880	<0.50	<0.50	<0.50	<1.5	4,500/4,500 ¹⁵
05/07/03	122.04	11.50		110.54	0.00	530	<0.5	0.6	<0.5	<1.5	2,400/1,800 ¹⁵
08/11/03 ¹⁶	122.04	12.63		109.41	0.00	290	<1	<1	<1	<1	1,500
11/10/03 ¹⁶	122.04	13.06		108.98	0.00	360	<1	<1	<1	<1	1,700
02/09/04 ¹⁶	122.04	12.11		109.93	0.00	300	<1	<1	<1	<1	1,700
05/10/04 ¹⁶	122.04	12.38		109.66	0.00	130	<0.5	<0.5	<0.5	<0.5	630
08/09/04 ¹⁶	122.04	12.88		109.16	0.00	94	<1	<1	<1	<1	570
11/08/04 ^{16,17}	122.04	12.49		109.55	0.00	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/07/05 ¹⁶	122.04	11.46		110.58	0.00	51	<0.5	<0.5	<0.5	<0.5	280
05/06/05 ¹⁶	122.04	11.39		110.65	0.00	<50	<0.5	<0.5	<0.5	<0.5	55
08/05/05 ¹⁶	122.04	12.97		109.07	0.00	<50	<0.5	<0.5	<0.5	<0.5	69
11/04/05 ¹⁶	122.04	12.67		109.37	0.00	<50	<0.5	<0.5	<0.5	<0.5	32
02/01/06 ¹⁶	122.04	10.75		111.29	0.00	<50	<0.5	<0.5	<0.5	<0.5	34

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-14 (cont)											
05/03/06 ¹⁶	122.04	9.80	15-30	112.24	0.00	<50	<0.5	<0.5	<0.5	<0.5	260
08/02/06 ¹⁶	122.04	11.48		110.56	0.00	<50	<0.5	<0.5	<0.5	<0.5	74
10/31/06¹⁶	122.04	12.50		109.54	0.00	<50	<0.5	<0.5	<0.5	<0.5	6
EW-2											
08/01/91	125.79	18.07	--	107.72	--	--	--	--	--	--	--
04/22/94	125.79	--		--	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/25/94	125.79	16.69		109.10	--	--	--	--	--	--	--
01/19/95	125.79	12.20		113.59	--	1,700	540	69	56	400	--
05/01/95	125.79	12.16		113.63	--	<50	13	<0.5	<0.5	2.1	--
04/16/99	125.79	10.04		115.75	--	3,500	350	160	130	550	3,800
07/29/99	125.79	INACCESSIBLE		--	--	--	--	--	--	--	--
10/26/99	125.79	13.82		111.97	--	2,760	20.6	17.8	40.2	196	13,300
04/07/00	125.79	10.94		114.85	0.00	4,100 ⁸	480	21	310	560	6,800
10/10/00	125.79	13.32		112.47	0.00	3,010 ¹²	14.4	<5.00	61.0	28.2	15,700
04/03/01	125.79	12.57		113.22	0.00	2,870	11.2	5.63	50.2	35.3	5,140
08/14/01	125.52	14.31		111.21	0.00	<5,000	<50	<50	<50	<50	16,000
11/16/01	125.52	14.21		111.31	0.00	2,300	3.2	0.58	13	6.3	4,100/5,300 ¹⁵
02/15/02	125.52	13.74		111.78	0.00	3,500	26	<0.50	74	33	6,900/8,200 ¹⁵
05/09/02	125.52	13.98		111.54	0.00	3,900	11	<0.50	14	2.5	24,000/22,000 ¹⁵
08/05/02	125.52	14.11		111.41	0.00	3,600	<20	<1.0	20	6.5	15,000/14,000 ¹⁵
11/04/02	125.52	14.97		110.55	0.00	3,100	7.1	<1.0	1.4	2.1	5,400/5,600 ¹⁵
02/05/03	125.52	13.41		112.11	0.00	1,300	4.7	<2.0	0.65	<1.5	1,600/1,700 ¹⁵
05/07/03	125.52	12.61		112.91	0.00	1,200	3.6	<2.0	6.5	2.5	1,900/2,400 ¹⁵
08/11/03 ¹⁶	125.52	13.95		111.57	0.00	980	<0.5	<0.5	0.5	<0.5	350
11/10/03 ¹⁶	125.52	13.93		111.59	0.00	1,700	<0.5	<0.5	3	<0.5	1,500
02/09/04 ¹⁶	125.52	13.59		111.93	0.00	1,100	<0.5	<0.5	<0.5	<0.5	840
05/10/04 ¹⁶	125.52	13.32		112.20	0.00	1,100	<2	<2	<2	<2	3,800
08/09/04 ¹⁶	125.52	14.05		111.47	0.00	930	<5	<5	<5	<5	3,000
11/08/04 ¹⁶	125.52	14.31		111.21	0.00	1,200	<0.5	<0.5	0.5	<0.5	240
02/07/05 ¹⁶	125.52	12.72		112.80	0.00	510	<0.5	<0.5	<0.5	<0.5	390
05/06/05 ¹⁶	125.52	13.02		112.50	0.00	890	<1	<1	<1	<1	430
08/05/05 ¹⁶	125.52	14.23		111.29	0.00	1,300	1	<0.5	2	<0.5	1,300
11/04/05 ¹⁶	125.52	13.86		111.66	0.00	1,000	<0.5	<0.5	<0.5	<0.5	1,200
02/01/06 ¹⁶	125.52	11.75		113.77	0.00	700	<0.5	<0.5	<0.5	<0.5	1,400

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
EW-2 (cont)											
05/03/06 ¹⁶	125.52	8.00	--	117.52	0.00	1,200	2	<0.5	<0.5	<0.5	440
08/02/06 ¹⁶	125.52	11.45		114.07	0.00	1,000	<0.5	<0.5	<0.5	<0.5	350
10/31/06¹⁶	125.52	13.70		111.82	0.00	1,200	<0.5	<0.5	3	3	910
EW-3											
08/01/91	125.22	17.49	--	107.73	--	--	--	--	--	--	--
10/27/93	125.22	--		--	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/13/94	125.22	--		--	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/22/94	125.22	--		--	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/29/94	125.22	--		--	--	<50	1.3	1.3	0.6	5.3	--
10/25/94	125.22	16.20		109.02	--	--	--	--	--	--	--
01/19/95	125.22	12.71		112.51	--	240	45	0.8	22	48	--
04/03/97	125.22	12.33		112.89	--	450	140	<1.2	4.3	3.9	17
10/07/97	125.22	14.58		110.64	--	1,900	510	<5.0	26	8.7	12
04/14/98	125.22	INACCESSIBLE		--	--	--	--	--	--	--	--
10/13/98	125.22	12.48		112.74	--	1,500	130	<2.5	9.0	4.7	3,600
04/16/99	125.22	11.55		113.67	--	3,800	280	37	270	300	2,800
07/29/99	125.22	INACCESSIBLE		--	--	--	--	--	--	--	--
10/26/99	125.22	13.49		111.73	--	710	204	2.87	7.31	11.8	3,760
04/07/00	125.22	11.41		113.81	0.00	1,100 ⁸	30	<5.0	20	48	2,800
10/10/00	125.22	13.55		111.67	0.00	119 ¹²	2.77	<0.500	4.65	2.77	172
04/03/01	125.22	12.73		112.49	0.00	1,910	22.3	7.23	136	116	16.1
08/14/01	125.21	13.98		111.23	0.00	1,900 ⁸	130	<5.0	39	84	710
11/16/01	125.21	14.03		111.18	0.00	8,800	110	20	530	840	99/99 ¹⁵
02/15/02	125.21	13.51		111.70	0.00	1,300	18	1.1	33	27	600/600 ¹⁵
05/09/02	125.21	13.75		111.46	0.00	740	22	<0.50	15	10	390/360 ¹⁵
08/05/02	125.21	14.28		110.93	0.00	8,200	77	21	480	710	<20
11/04/02	125.21	14.92		110.29	0.00	4,300	45	2.9	110	83	<2.5/<2 ¹⁵
02/05/03	125.21	13.34		111.87	0.00	1,800	45	1.7	32	16	<20
05/07/03	125.21	12.87		112.34	0.00	860	14	<2.0	5.3	1.6	180/170 ¹⁵
08/11/03 ¹⁶	125.21	13.86		111.35	0.00	2,500	7	5	190	130	0.7
11/10/03 ¹⁶	125.21	14.53		110.68	0.00	1,600	14	1	43	10	0.8
02/09/04 ¹⁶	125.21	13.44		111.77	0.00	550	1	<0.5	0.6	<0.5	<0.5
05/10/04 ¹⁶	125.21	13.49		111.72	0.00	170	<0.5	<0.5	<0.5	<0.5	2
08/09/04 ¹⁶	125.21	14.08		111.13	0.00	710	14	<0.5	8	6	190

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (#.)	DTW (#.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
EW-3 (cont)											
11/08/04 ¹⁶	125.21	14.37	--	110.84	0.00	3,300	10	2	280	19	<0.5
02/07/05 ¹⁶	125.21	12.47		112.74	0.00	400	<0.5	<0.5	<0.5	<0.5	<0.5
05/06/05 ¹⁶	125.21	12.87		112.34	0.00	590	0.6	0.5	9	21	<0.5
08/05/05 ¹⁶	125.21	14.27		110.94	0.00	1,700	2	2	97	34	5
11/04/05 ¹⁶	125.21	13.79		111.42	0.00	1,700	4	2	150	170	0.8
02/01/06 ¹⁶	125.21	11.68		113.53	0.00	85	<0.5	<0.5	<0.5	<0.5	5
05/03/06 ¹⁶	125.21	10.34		114.87	0.00	560	4	<0.5	7	4	43
08/02/06 ¹⁶	125.21	12.27		112.94	0.00	1,000	2	<0.5	10	11	10
10/31/06¹⁶	125.21	13.57		111.64	0.00	9,000	15	6	540	460	12
MW-1											
12/05/89 ^{1,3}	127.09	--	--	--	--	<500	<0.5	<0.5	<0.5	<0.5	<0.5
03/23/90	127.09	12.92		114.17	--	--	--	--	--	--	--
05/24/90	127.09	--		--	--	<50	<0.5	<0.5	<0.5	<0.5	--
09/06/90 ³	127.09	14.68		112.41	--	<50	<0.5	0.8	<0.5	<0.5	<0.5
09/25/90	127.09	15.01		112.08	--	--	--	--	--	--	--
11/29/90	127.09	14.82		112.27	--	<50	0.7	0.9	<0.5	1.0	--
02/20/91	127.09	14.29		112.80	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/19/91	127.09	12.16		114.93	--	--	--	--	--	--	--
05/22/91	127.09	13.69		113.40	--	<50	<0.5	<0.5	<0.5	<0.5	--
08/22/91	127.09	15.38		111.71	--	<50	<0.5	<0.5	<0.5	<0.5	--
11/13/91	127.09	15.80		111.29	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/30/92	127.09	14.71		112.38	--	<50	0.5	<0.5	<0.5	0.5	--
04/23/92	127.09	12.22		114.87	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/27/92	127.09	14.30		112.79	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/26/92	127.09	15.90		111.19	--	<50	0.6	<0.5	<0.5	<0.5	--
01/29/93	127.09	10.51		116.58	--	<50	3.0	3.0	0.7	3.0	--
04/30/93	127.09	9.90		117.19	--	<50	<0.5	0.7	<0.5	1.0	--
07/14/93	127.09	12.28		114.81	--	<50	0.7	1.0	<0.5	3.0	--
10/27/93	127.09	15.53		111.56	--	<50	0.9	2.0	<0.5	2.0	--
01/13/94	127.09	12.24		114.85	--	<50	<0.5	0.9	<0.5	<0.5	--
04/22/94	127.09	12.91		114.18	--	<50	1.1	2.6	1.0	5.5	--
07/29/94	127.09	12.75		114.34	--	<50	<0.5	0.9	<0.5	<0.5	--
10/25/94	127.09	13.63		113.46	--	100	0.6	1.6	<0.5	4.1	--

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (<i>ft.</i>)	DTW (<i>ft.</i>)	S.L. (<i>ft.bgs</i>)	GWE (<i>msl</i>)	SPHT (<i>ft.</i>)	TPH-G (<i>ppb</i>)	B (<i>ppb</i>)	T (<i>ppb</i>)	E (<i>ppb</i>)	X (<i>ppb</i>)	MTBE (<i>ppb</i>)
MW-1 (cont)											
01/19/95	127.09	9.93	--	117.16	--	<50	<0.5	<0.5	<0.5	<0.5	--
ABANDONED											
MW-2											
12/05/89 ^{1,3}	--	--	--	--	--	<500	<0.5	<0.5	<0.5	0.9	<0.5
03/23/90	125.98	12.40		113.58	--	--	--	--	--	--	--
05/24/90	125.98	--		--	--	<50	<0.5	<0.5	<0.5	<0.5	--
09/06/90 ³	125.98	14.85		111.13	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
09/25/90	125.98	14.80		111.18	--	--	--	--	--	--	--
11/29/90	125.98	14.40		111.58	--	<50	<0.5	<0.5	<0.5	<0.5	--
02/20/91	125.98	14.09		111.89	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/19/91	125.98	12.62		113.36	--	--	--	--	--	--	--
05/22/91	125.98	12.98		113.00	--	<50	<0.5	<0.5	<0.5	<0.5	--
08/22/91	125.98	14.93		111.05	--	<50	<0.5	<0.5	<0.5	<0.5	--
11/13/91	125.98	15.42		110.56	--	58	<0.5	0.5	0.7	2.3	--
01/30/92	125.98	14.70		111.28	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/23/92	125.98	13.83		112.15	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/27/92	125.98	15.30		110.68	--	<50	<0.5	<0.5	<0.5	1.1	--
10/26/92	125.98	15.62		110.36	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/29/93	125.98	9.26		116.72	--	<50	3.0	8.0	1.0	5.0	--
04/30/93	125.98	9.66		116.32	--	<1,300	<13	<13	<13	<13	--
07/14/93	125.98	11.90		114.08	--	<50	0.8	2.0	0.8	4.0	--
10/27/93	125.98	13.49		112.49	--	<50	1.0	2.0	1.0	2.0	--
01/13/94	125.98	11.99		113.99	--	<50	<0.5	0.6	<0.5	<0.5	--
04/22/94	125.98	12.73		113.25	--	<50	0.6	<0.5	<0.5	1.7	--
07/29/94	125.98	12.30		113.68	--	<50	<0.5	0.9	<0.5	<0.5	--
10/25/94	125.98	13.39		112.59	--	<50	<0.5	0.8	<0.5	2.1	--
01/19/95	125.98	8.71		117.27	--	<50	<0.5	2.3	<0.5	<0.5	--
ABANDONED											
MW-3											
12/05/89 ^{2,3}	--	--	--	--	--	24,000	2,400	1,800	360	2,600	<0.5
12/05/89 ³ (D)		--		--	--	24,000	2,500	1,900	390	2,600	<0.5
03/23/90	127.84	17.50		110.34	--	--	--	--	--	--	--
05/24/90	127.84	--		--	--	9,000	2,600	1,700	250	1,500	--
05/24/90 (D)	127.84	--		--	--	10,000	2,600	1,800	260	1,600	--
09/06/90 ³	126.77	18.72		108.05	--	3,500	900	550	110	460	<0.5

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-3 (cont)											
09/25/90	126.77	18.40	--	108.37	--	--	--	--	--	--	--
11/29/90	126.77	18.97		107.80	--	9,200	1,100	1,100	210	1,100	--
02/20/91	126.77	19.20		107.57	--	8,800	960	780	200	920	--
04/19/91	126.77	17.81		108.96	--	--	--	--	--	--	--
05/22/91	126.77	17.88		108.89	--	28,000	5,800	1,200	460	2,300	--
08/01/91	126.77	19.23		107.54	--	--	--	--	--	--	--
08/22/91	126.77	20.17		106.60	--	21,000	3,100	2,000	480	2,000	--
08/22/91 (D)	126.77	--		--	--	19,000	2,700	1,800	420	1,700	--
11/13/91	126.77	19.95		106.82	--	18,000	2,400	1,200	450	2,200	--
01/30/92	126.77	19.14		107.63	--	18,000	3,800	920	700	2,600	--
04/23/92	126.77	17.75		109.02	--	46,000	5,000	1,900	1,000	3,500	--
07/27/92	126.77	19.00		107.77	--	26,000	4,900	1,100	1,200	3,600	--
10/26/92	126.77	19.62		107.15	--	6,600	1,100	41	220	570	--
01/29/93	126.77	15.95		110.82	--	32,000	5,900	2,900	1,300	5,000	--
04/30/93	126.77	15.67		111.10	--	14,000	6,100	98	870	2,400	--
07/14/93	126.77	16.83		109.94	--	12,000	3,100	1,100	720	2,900	--
10/27/93	126.77	17.70		109.07	--	19,000	7,800	400	1,500	3,400	--
01/13/94	126.77	16.54		110.23	--	51,000	3,700	140	720	1,800	--
04/22/94	126.77	17.02		109.75	--	22,000	9,300	89	1,200	2,400	--
07/29/94	126.77	16.95		109.82	--	13,000	4,700	44	580	420	--
10/25/94	126.77	17.66		109.11	--	24,000	8,700	52	1,500	1,400	--
01/19/95	126.77	13.87		112.90	--	17,000	9,300	36	1,600	740	--
10/12/95	126.77	14.23		112.54	--	37,000	12,000	180	1,800	1,500	13,000
04/11/96	126.77	11.04		115.73	--	19,000	2,400	81	1,400	1,500	6,800
10/03/96	126.77	14.62		112.15	--	--	--	--	--	--	--
ABANDONED											
MW-4											
12/05/89 ³	--	--	--	--	--	19,000	390	1,300	460	1,800	<0.5
03/23/90	125.22	16.02		109.20	--	--	--	--	--	--	--
05/24/90	125.22	--		--	--	4,500	210	440	140	480	--
09/06/90 ³	125.22	17.35		107.87	--	6,000	680	520	170	580	<0.5
09/25/90	125.22	17.48		107.74	--	--	--	--	--	--	--
11/29/90	125.22	17.61		107.61	--	15,000	800	1,000	430	1,700	--
02/20/91	125.22	17.81		107.41	--	15,000	640	390	420	1,600	--
02/20/91 (D)	125.22	--		--	--	15,000	680	410	430	1,600	--
04/19/91	125.22	15.80		109.42	--	--	--	--	--	--	--

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-4 (cont)											
05/22/91	125.22	16.68	--	108.54	--	9,800	580	140	310	740	--
05/22/91 (D)	125.22	--	--	--	--	7,200	520	130	270	670	--
REDESIGNATED EW-3											
MW-5											
03/23/90	125.85	16.89	--	108.96	--	--	--	--	--	--	--
05/25/90 ⁴	125.85	--	--	--	--	28,000	920	1,100	460	1,300	2.4
09/07/90	125.85	18.46	--	107.42**	0.04	--	--	--	--	--	--
09/25/90	125.85	18.87	--	108.02**	1.30	--	--	--	--	--	--
11/29/90	125.85	18.91	--	107.51**	0.71	--	--	--	--	--	--
02/20/91	125.85	16.99	--	109.24**	0.47	--	--	--	--	--	--
04/19/91	125.85	19.30	--	106.93**	0.48	--	--	--	--	--	--
05/22/91	125.85	17.69	--	108.42**	0.33	--	--	--	--	--	--
REDESIGNATED EW-2											
MW-6											
03/23/90	124.18	18.51	--	105.67	--	--	--	--	--	--	--
05/25/90 ⁵	124.18	--	--	--	--	<50	<2.0	<3.0	<3.0	<3.0	<0.02
09/07/90 ³	124.18	16.18	--	108.00	--	<50	<2.0	<3.0	<3.0	<3.0	<0.05
09/25/90	124.18	16.42	--	107.76	--	--	--	--	--	--	--
11/29/90 ³	124.18	16.11	--	108.07	--	<50	<0.5	<0.5	<0.5	<0.5	<0.05
02/20/91	124.18	16.09	--	108.09	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/19/91	124.18	15.15	--	109.03	--	--	--	--	--	--	--
05/22/91	124.18	15.41	--	108.77	--	<50	0.5	0.7	<0.5	1.1	--
08/23/91	124.18	17.80	--	106.38	--	<50	<0.5	<0.5	<0.5	<0.5	--
11/14/91 ⁵	124.18	16.52	--	107.66	--	<50	<0.5	<0.5	<0.5	<0.5	<0.02
11/14/91 ³ (D)	124.18	--	--	--	--	<50	<0.5	0.6	<0.5	1.1	<0.05
01/31/92	124.18	16.48	--	107.70	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/31/92 (D)	124.18	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/23/92	124.18	16.20	--	107.98	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/23/92 (D)	124.18	--	--	--	--	--	--	--	--	--	--
07/27/92	124.18	16.52	--	107.66	--	<50	1.2	0.6	<0.5	1.9	--
10/26/92	124.18	17.12	--	107.06	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/29/93	124.18	13.13	--	111.05	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/30/93	124.18	14.86	--	109.32	--	<50	<0.5	<0.5	<0.5	0.6	--
07/14/93	124.18	14.61	--	109.57	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/27/93	124.18	15.38	--	108.80	--	<50	0.9	1.0	0.6	1.0	--

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (<i>ft.</i>)	DTW (<i>ft.</i>)	S.L. (<i>ft.bgs</i>)	GWE (<i>msl</i>)	SPHT (<i>ft.</i>)	TPH-G (<i>ppb</i>)	B (<i>ppb</i>)	T (<i>ppb</i>)	E (<i>ppb</i>)	X (<i>ppb</i>)	MTBE (<i>ppb</i>)
MW-6 (cont)											
01/13/94	124.18	15.34	--	108.84	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/22/94	124.18	15.07		109.11	--	<50	<0.5	<0.5	<0.5	2.5	--
07/29/94	124.18	15.30		108.88	--	<50	7.5	1.2	1.0	1.1	--
10/25/94	124.18	15.69		108.49	--	<50	<0.5	<0.5	<0.5	1.2	--
01/19/95	124.18	11.49		112.69	--	<50	<0.5	3.1	<0.5	0.6	--
10/11/95	124.18	14.16		110.02	--	--	--	--	--	--	--
11/07/95	124.18	14.30		109.88	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/11/96	124.18	10.63		113.55	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/03/96	124.18	13.34		110.84	--	--	--	--	--	--	--
ABANDONED											
MW-7											
03/23/90	126.86	21.40	--	105.46	--	--	--	--	--	--	--
05/25/90 ⁵	126.86	--		--	--	<50	<2.0	<3.0	<3.0	<3.0	<0.02
09/07/90	126.86	18.38		108.48	--	--	--	--	--	--	--
09/25/90	126.86	19.25		107.61	--	--	--	--	--	--	--
09/27/90 ³	126.86	--		--	--	<50	<2.0	<3.0	<3.0	<3.0	<0.05
09/27/90 ³ (D)	126.86	--		--	--	<50	<2.0	<3.0	<3.0	<3.0	<0.05
11/29/90	126.86	18.55		108.31	--	<50	<0.5	<0.5	<0.5	<0.5	--
02/20/91	126.86	18.55		108.31	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/19/91	126.86	17.33		109.53	--	--	--	--	--	--	--
05/22/91	126.86	17.42		109.44	--	<50	<0.5	<0.5	<0.5	<0.5	--
08/22/91	126.86	19.05		107.81	--	<50	<0.5	<0.5	<0.5	<0.5	--
11/13/91	126.86	21.84		105.02	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/30/92	126.86	22.42		104.44	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/23/92	126.86	22.04		104.82	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/27/92	126.86	22.24		104.62	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/26/92	126.86	22.11		104.75	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/29/93	126.86	17.07		109.79	--	<50	4.0	13	2.0	8.0	--
04/30/93	126.86	14.86		112.00	--	<50	<0.5	<0.5	<0.5	0.6	--
07/14/93	126.86	16.10		110.76	--	<50	<0.5	1.0	<0.5	2.0	--
10/27/93	126.86	18.71		108.15	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/13/94	126.86	17.89		108.97	--	<50	<0.5	0.9	<0.5	1.0	--
04/22/94	126.86	16.94		109.92	--	<50	<0.5	<0.5	<0.5	1.3	--
07/29/94	126.86	16.70		110.16	--	74	19	8.2	7.8	11	--
10/25/94	126.86	17.42		109.44	--	<50	<0.5	0.6	<0.5	1.6	--

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-7 (cont)											
01/19/95	126.86	13.66	--	113.20	--	<50	<0.5	1.4	<0.5	<0.5	--
ABANDONED											
EW-1											
05/25/90	--	--	--	--	--	3,900	260	430	64	340	0.03
08/01/91	124.95	17.54	--	107.41	--	--	--	--	--	--	--
10/27/93	124.95	--	--	--	--	350	<0.5	<0.5	<0.5	<0.5	--
01/13/94	124.95	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/22/94	124.95	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/29/94	124.95	--	--	--	--	97	0.6	0.5	0.6	5.1	--
01/19/95	124.95	12.63	--	112.32	--	3,000	1,600	100	350	760	--
ABANDONED											
TRIP BLANK											
TB-LB											
02/20/91	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
05/22/91	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
05/22/91	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
11/13/91	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/30/92	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/23/92	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/27/92	--	--	--	--	--	<0.5	<0.5	<0.5	<0.5	<0.5	--
10/26/92	--	--	--	--	--	<0.5	<0.5	<0.5	<0.5	<0.5	--
01/29/93	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/30/93	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/14/93	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/27/93	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/13/94	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/22/94	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
07/29/94	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/25/94	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
01/19/95	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
05/01/95	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
10/12/95	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/11/96	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/03/96	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	--
04/03/97	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	S.L. (ft.bgs)	GWE (msl)	SPHT (ft.)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
TB-LB (cont)											
10/07/97	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/14/98	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
10/13/98	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/16/99	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<2.5
04/07/00	--	--	--	--	--	<50	<0.50	<0.50	<0.50	<0.50	<2.5
10/10/00	--	--	--	--	--	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50
04/03/01	--	--	--	--	--	<50.0	<0.500	<0.500	<0.500	<0.500	<0.500
08/14/01	--	--	--	--	--	<50	<0.50	<0.50	<0.50	<0.50	<2.5
QA											
11/16/01	--	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
02/15/02	--	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/09/02	--	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
08/05/02	--	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
11/04/02	--	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
02/05/03	--	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
05/07/03	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<1.5	<2.5
08/11/03 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/10/03 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/09/04 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/10/04 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/09/04 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/08/04 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/07/05 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/06/05 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/05/05 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
11/04/05 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
02/01/06 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
05/03/06 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
08/02/06 ¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
10/31/06¹⁶	--	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1
Groundwater Monitoring and Analytical Results
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

EXPLANATIONS:

Groundwater monitoring data and laboratory analytical results prior to April 7, 2000, were compiled from reports prepared by Blaine Tech Services, Inc.

TOC = Top of Casing (ft.) = Feet	SPHT = Separate Phase Hydrocarbon Thickness	(ppb) = Parts per billion
DTW = Depth to Water	TPH-G = Total Petroleum Hydrocarbons as Gasoline	-- = Not Measured/Not Analyzed
S.I. = Screen Interval (ft.bgs) = Feet Below Ground Surface	B = Benzene	(D) = Duplicate
GWE = Groundwater Elevation (msl) = Mean sea level	T = Toluene	ND = Not Detected
	E = Ethylbenzene	QA = Quality Assurance/Trip Blank
	X = Xylenes	
	MTBE = Methyl tertiary butyl ether	

- * TOC elevations were surveyed on September 16, 2000, by Virgil Chavez Land Surveying. The benchmark used for the survey was a copper disc set in the top of headwall on the east side of Foothill, approximately 158 feet south of Miramar Avenue, stamped EBMUD 17B, (Benchmark Elev. = 127.162 feet, NAVD 29).
- ¹ Total Petroleum Hydrocarbons as Diesel (TPH-D) was ND with a detection limit of 1,000 ppb and Total Oil and Grease (TOG) was ND with a detection limit of 5,000 ppb.
- ² TOG was ND with a detection limit of 5,000 ppb.
- ³ Ethylene dibromide (EDB) was <0.05 ppb.
- ⁴ EDB was detected at 2.4 ppb.
- ⁵ EDB was <0.02 ppb.
- ⁶ ORC installed.
- ⁷ TOC altered due to wellhead maintenance.
- ⁸ Laboratory report indicates gasoline C6-C12.
- ⁹ ORC in well.
- ¹⁰ Well development performed.
- ¹¹ Laboratory report indicates unidentified hydrocarbons C6-C8.
- ¹² Laboratory report indicates weathered gasoline C6-C12.
- ¹³ ORC removed from well.
- ¹⁴ Laboratory report indicates unidentified hydrocarbons C6-C12.
- ¹⁵ MTBE by EPA Method 8260.
- ¹⁶ BTEX and MTBE by EPA Method 8260.
- ¹⁷ Current laboratory analytical results do not coincide with historical data, and although the laboratory results were confirmed; it appears that the samples were switched.
- ¹⁸ Due to an oversight; this well was not sampled.

Table 2
Groundwater Analytical Results - Oxygenate Compounds
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID	DATE	ETHANOL (ppb)	TBA (ppb)	MTBE (ppb)	DIPE (ppb)	ETBE (ppb)	TAME (ppb)	1,2-DCA (ppb)	EDB (ppb)
MW-8	11/04/02	--	250	17,000	<3.0	<3.0	2,600	<3.0	<3.0
	02/05/03	--	--	18,000	--	--	--	--	--
	05/07/03	--	--	13,000	--	--	--	--	--
	08/11/03	<1,000	<100	13,000	<10	<10	2,200	<10	<10
	11/10/03 ¹	--	--	13,000	--	--	--	--	--
	02/09/04 ²	<50	<5	140	<0.5	<0.5	22	<0.5	<0.5
	05/10/04	<500	<50	12,000	<5	<5	1,900	<5	<5
	08/09/04	<1,000	<100	7,200	<10	<10	1,100	<10	<10
	11/08/04	<130	<13	3,900	<1	<1	540	<1	<1
	02/07/05 ²	<50	<5	12	<0.5	<0.5	2	<0.5	<0.5
	05/06/05	<500	<50	5,100	<5	<5	740	<5	<5
	08/05/05	<250	<25	3,600	<3	<3	510	<3	<3
	11/04/05	--	<5	1,600	--	--	210	--	--
	02/01/06	--	86	1,800	--	--	260	--	--
	05/03/06	--	40	3,500	--	--	500	--	--
	08/02/06	--	<10	3,800	--	--	460	--	--
	10/31/06	--	<5	3,200	--	--	440	--	--
MW-9	11/04/02	--	<100	520	<2	<2	88	<2	<2
	02/05/03	--	--	340	--	--	--	--	--
	05/07/03	--	--	390	--	--	--	--	--
	08/11/03	<50	<5	370	<0.5	<0.5	69	<0.5	<0.5
	11/10/03 ¹	--	--	190	--	--	--	--	--
	02/09/04 ²	<500	<50	8,100	<5	<5	1,400	<5	<5
	05/10/04	<50	<5	120	<0.5	<0.5	14	<0.5	<0.5
	08/09/04	<50	<5	61	<0.5	<0.5	7	<0.5	<0.5
	11/08/04	<50	<5	74	<0.5	<0.5	9	<0.5	<0.5
	02/07/05 ²	<250	<25	3,200	<3	<3	520	<3	<3
	05/06/05	<50	<5	45	<0.5	<0.5	6	<0.5	<0.5
	08/05/05	<50	<5	1	<0.5	<0.5	<0.5	<0.5	<0.5
	11/04/05	--	<5	130	--	--	15	--	--
	02/01/06	--	<5	27	--	--	0.9	--	--
	05/03/06	--	<5	82	--	--	12	--	--
	08/02/06	--	<5	85	--	--	12	--	--
	10/31/06	--	<5	280	--	--	54	--	--

Table 2
Groundwater Analytical Results - Oxygenate Compounds
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID	DATE	ETHANOL (ppb)	TBA (ppb)	MTBE (ppb)	DIPE (ppb)	ETBE (ppb)	TAME (ppb)	1,2-DCA (ppb)	EDB (ppb)
MW-10	11/04/02	--	<100	<2	<2	<2	<2	<2	<2
	08/11/03	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	11/10/03 ¹	--	--	<0.5	--	--	--	--	--
	02/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/10/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	08/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	11/08/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	02/07/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/06/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	08/05/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
MW-11	11/04/02	--	<100	<2	<2	<2	<2	<2	<2
	08/11/03	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	11/10/03 ¹	--	--	<0.5	--	--	--	--	--
	02/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/10/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	08/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	11/08/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	02/07/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/06/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	08/05/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
MW-12	11/04/02	--	<100	<2	<2	<2	<2	<2	<2
	08/11/03	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	11/10/03 ¹	--	--	<0.5	--	--	--	--	--
	02/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/10/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	08/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	11/08/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	02/07/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/06/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	08/05/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	02/01/06 ³	--	--	--	--	--	--	--	--
05/03/06	--	<5	<0.5	--	--	<0.5	--	--	

Table 2
Groundwater Analytical Results - Oxygenate Compounds
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID	DATE	ETHANOL (ppb)	TBA (ppb)	MTBE (ppb)	DIPE (ppb)	ETBE (ppb)	TAME (ppb)	1,2-DCA (ppb)	EDB (ppb)
MW-13	11/04/02	--	<100	<2	<2	<2	<2	<2	<2
	08/11/03	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	11/10/03 ¹	--	--	<0.5	--	--	--	--	--
	02/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/10/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	08/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	11/08/04	<50	<5	400	<0.5	<0.5	59	<0.5	<0.5
	02/07/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/06/05	<100	<10	570	<1	<1	48	<1	<1
	08/05/05	<50	<5	470	<0.5	<0.5	52	<0.5	<0.5
MW-14	11/04/02	--	<100	4,700	<2	<2	680	<2	<2
	02/05/03	--	--	4,500	--	--	--	--	--
	05/07/03	--	--	1,800	--	--	--	--	--
	08/11/03	<100	<10	1,500	<1	<1	270	<1	<1
	11/10/03 ¹	--	--	1,700	--	--	--	--	--
	02/09/04	<100	<10	1,700	<1	<1	230	<1	<1
	05/10/04	<50	<5	630	<0.5	<0.5	96	<0.5	<0.5
	08/09/04	<100	<10	570	<1	<1	76	<1	<1
	11/08/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	02/07/05	<50	<5	280	<0.5	<0.5	41	<0.5	<0.5
	05/06/05	<50	<5	55	<0.5	<0.5	6	<0.5	<0.5
	08/05/05	<50	<5	69	<0.5	<0.5	8	<0.5	<0.5
	11/04/05	--	<5	32	--	--	4	--	--
	02/01/06	--	<5	34	--	--	3	--	--
	05/03/06	--	<5	260	--	--	34	--	--
	08/02/06	--	<5	74	--	--	8	--	--
10/31/06	--	<5	6	--	--	<0.5	--	--	
EW-2	11/04/02	--	550	5,600	<2.0	<2.0	850	<2.0	<2.0
	02/05/03	--	--	1,700	--	--	--	--	--
	05/07/03	--	--	2,400	--	--	--	--	--
	08/11/03	<50	47	350	<0.5	<0.5	120	<0.5	<0.5
	11/10/03 ¹	--	--	1,500	--	--	--	--	--
	02/09/04	<50	110	840	<0.5	<0.5	250	<0.5	<0.5
	05/10/04	<200	300	3,800	<2	<2	640	<2	<2

Table 2
Groundwater Analytical Results - Oxygenate Compounds
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

WELL ID	DATE	ETHANOL (ppb)	TBA (ppb)	MTBE (ppb)	DIPE (ppb)	ETBE (ppb)	TAME (ppb)	1,2-DCA (ppb)	EDB (ppb)
EW-2	08/09/04	<500	<50	3,000	<5	<5	480	<5	<5
(cont)	11/08/04	<50	33	240	<0.5	<0.5	110	<0.5	<0.5
	02/07/05	<50	42	390	<0.5	<0.5	140	<0.5	<0.5
	05/06/05	<100	120	430	<1	<1	160	<1	<1
	08/05/05	<50	360	1,300	<0.5	<0.5	390	<0.5	<0.5
	11/04/05	--	210	1,200	--	--	340	--	--
	02/01/06	--	130	1,400	--	--	290	--	--
	05/03/06	--	260	440	--	--	120	--	--
	08/02/06	--	120	350	--	--	76	--	--
	10/31/06	--	130	910	--	--	210	--	--
EW-3	11/04/02	--	<100	<2	<2	<2	<2	<2	<2
	05/07/03	--	--	170	--	--	--	--	--
	08/11/03	<50	<5	0.7	<0.5	<0.5	<0.5	<0.5	<0.5
	11/10/03 ¹	--	--	0.8	--	--	--	--	--
	02/09/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/10/04	<50	<5	2	<0.5	<0.5	0.6	<0.5	<0.5
	08/09/04	<50	<5	190	<0.5	<0.5	51	<0.5	<0.5
	11/08/04	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	02/07/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	05/06/05	<50	<5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	08/05/05	<50	<5	5	<0.5	<0.5	0.7	<0.5	<0.5
	11/04/05	--	<5	0.8	--	--	<0.5	--	--
	02/01/06	--	<5	5	--	--	0.6	--	--
	05/03/06	--	<5	43	--	--	10	--	--
	08/02/06	--	<5	10	--	--	1	--	--
	10/31/06	--	<5	12	--	--	2	--	--

Table 2
Groundwater Analytical Results - Oxygenate Compounds
Chevron Service Station #9-8139
16304 Foothill Boulevard
San Leandro, California

EXPLANATIONS:

TBA = Tertiary butyl alcohol
MTBE = Methyl tertiary butyl ether
DIPE = Di-isopropyl ether
ETBE = Ethyl tertiary butyl ether
TAME = Tertiary amyl methyl ether
1,2-DCA = 1,2-Dichloroethane
EDB = 1,2-Dibromoethane
(ppb) = Parts per billion
-- = Not Analyzed

ANALYTICAL METHOD:

EPA Method 8260 for Oxygenate Compounds

¹ Analysis inadvertently omitted.

² Current laboratory analytical results do not coincide with historical data, and although the laboratory results were confirmed; it appears that the samples were switched.

³ Due to an oversight; this well was not sampled.