



11/10/92

BERLON #604
1619 1ST ST.
Livermore

opposing northern-most 8K gallon UST



11/10/92

BEACON #604
1619 1st St.
Livermore

pitting on side of one UST



11/10/92

BEACON #604
1619 1ST Street
Livermore



11/10/92

BEACON #604
1619 1st St
Livermore

UST cavity where middle (of 3) UST was
just removed. Note apparent native gravels
at right-middle of photo. View towards SE.



11/10/92

BEACON #604
1619 1st St
Livermore

center 8K gallon UST



11/10/92

BEACON #604
1619 1ST ST.
Livermore

drop tube from overflow bucket with holes (near foot)



11/10/92

BEACON #604
1619 1st St.
Livermore

close up of sandy gravels in UST pit



11/10/92

BEXCON #604
1619 1st St.
Livermore

sandy gravel native soil in UST pit
(orientation of photo unknown)



11/10/92

BEACON #604
1619 1st St.
Livermore





Overflow protection
Basin # 604
1619 - 1st St. Livermore
03216211255-8 11/10/92



Basin # 604
1619 - 1st St. Livermore
10K-unleaded tank
across 1st St.
03216211255-8 11/10/92