

Ultramar

Ultramar, Inc.
P.O. Box 466
525 W. Third Street
Hanford, CA 93232-0466
(209) 582-0241

(559) 583-3345

ENVIRONMENTAL
PROTECTION

99 NOV 18 PM 3:59
Telecopy: 209-585-5685 Credit
209-583-3330 Administrative
209-583-3302 Information Services
209-583-3358 Accounting

November 15, 1999

Ms. Eva Chu
Department of Environmental Health
Alameda County Health Care Services
1131 Harbor Bay Parkway, Room 250
Alameda, CA 94502-6577

SUBJECT: BEACON STATION NO. 604, 1619 FIRST STREET, LIVERMORE, CALIFORNIA

Dear Ms. Chu:

Enclosed is a copy of the *Third Quarter 1999 Ground Water Monitoring Report* for the above-referenced Ultramar facility. Also included is a copy of the Quarterly Status Report

Please call if you have any questions regarding this site.

Sincerely,

ULTRAMAR INC.

Terrence A. Fox
Terrence A. Fox
Senior Project Manager
Marketing Environmental Department

Enclosures

cc w/encl: Mr. Cecil Fox, San Francisco Bay Region, RWQCB
Walter and Dorothy Anderson, 1091 Buckingham Drive, Los Altos,
CA 94024



A Member of the Ultramar Group of Companies

BEACON
#1 Quality and Service

Ultramar

Ultramar, Inc.
P.O. Box 466
525 W. Third Street
Hanford, CA 93232-0466
(209) 582-0241

Telecopy: 209-585-5685 Credit
209-583-3330 Administrative
209-583-3302 Information Services
209-583-3358 Accounting

ENVIRONMENTAL PROJECT QUARTERLY STATUS REPORT

DATE REPORT SUBMITTED: November 15, 1999
QUARTER ENDING: September 30, 1999

SERVICE STATION NO.: 604
ADDRESS: 1619 First Street, Livermore, CA
COUNTY: Alameda
ULTRAMAR CONTACT: Terrence A. Fox

TEL. NO: 559-583-3345

BACKGROUND:

In November 1992, three underground storage tanks were removed. Hydrocarbons were detected and the excavation was extended to a depth of 27 feet in the southwest corner. Hydrocarbons were detected in the sample collected from the base of the overexcavation.

In May and June 1993, three monitoring wells (MW-1 through MW-3), three vapor wells (VW-1 through VW-3), and one boring were drilled. The soil plume has been defined.

The site has been placed on a quarterly monitoring program.

In March 29 and 30, 1994, four additional offsite wells (MW-4 through MW-7) were installed. The ground-water plume is not defined downgradient.

In June 1994, performed assessment on the Livermore Arcade Shopping Center Property by drilling borings and collecting ground-water samples using a Hydropunch tool.

In June 1994, performed vapor extraction and ground-water extraction tests.

In September and October 1995, installed of vapor extraction and air sparging wells.

In January, 1997, discontinued operation of the remediation system.

In August 1997, submitted RBCA.



A Member of the Ultramar Group of Companies

BEACON
#1 Quality and Service

SUMMARY OF THIS QUARTER'S ACTIVITIES:

Performed quarterly monitoring on September 7, 1999.

RESULT OF QUARTERLY MONITORING:

Monitoring data indicates that the benzene concentrations were not detected in MW-1. The benzene concentrations were detected MW-2, MW-5, MW-6, and MW-7. MW-3 and MW-4 were not sampled this quarter.

PROPOSED ACTIVITY OR WORK FOR NEXT QUARTER:

<u>ACTIVITY</u>	<u>ESTIMATED COMPLETION DATE</u>
Continue quarterly monitoring program.	
Sample for bio-parameters.	