


EXPLANATION

- ◆ Groundwater monitoring well
- ⊕ UST Pit backfill well

RECEIVED

2:28 pm, Oct 17, 2008

Alameda County
Environmental Health



Source: Figure modified from drawing provided by MPDS Services Inc.



GETTLER - RYAN INC.
6747 Sierra Ct., Suite J
Dublin, CA 94568 (925) 551-7555

SITE PLAN
Tosco (76) Service Station No. 6419
6401 Dublin Boulevard
Dublin, California

FIGURE
2

PROJECT NUMBER
140101

REVIEWED BY

DATE
10/01

REVISED DATE