

Site Visit; November 14, 2012  
11 – 11:30 AM  
RO 464; Chevron #9-1851  
451 Hegenberger Rd, Oakland

Onsite to observe waste oil remedial excavation. Sign in at H&S station. Work started last week, conducting excavation work using a slide-rail box shoring system; planned to use six box units, but have evolved to use of three larger boxes. Observe center box undergoing excavation. TD @ 9 ft; greenish soil to approx 8.5 ft; thereafter black bay mud. Currently collecting four corner soil samples at base of excavation. Request soil samples to be positively biased toward contaminated soil and that locations be moved from corners as corner to corner samples will characterize essentially same soil. Backfill with ¾-inch crushed drain rock to 2 ft bgs, then AB rock; no paving planned as building to be relocated to on top of excavation. Anticipate backfilling center section this afternoon; starting third section tomorrow, finishing dependent on rain called for later this week. Four photos taken and attached.







