5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 Phone: 510-450-6000

9 12 12 1100

July 1, 1994

Scott Seery
Alameda County Department of
Environmental Health
80 Swan Way, Room 200
Oakland, CA 94621

Re: Shell Service Station WIC #204-5508-3301 6039 College Avenue Oakland, California WA Job #81-618-104

Dear Mr. Seery:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1). This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the second quarter 1994 and proposed work for the third quarter 1994.

Second Quarter 1994 Activities:

- Blaine Tech Services, Inc. (BTS) of San Jose, California measured depths to ground water and collected ground water samples from the site wells. Well MW-4 contained floating hydrocarbons and was not sampled. BTS' report describing these activities and analytic results for ground water is included as Attachment A.
- Weiss Associates (WA) compiled the ground water elevation and analytic data (Tables 1 and 2) and prepared a ground water elevation contour map (Figure 2). WA also tabulated separate-phase hydrocarbon (SPH) removal data (Table 3). To date, about 10.12 pounds of SPHs have been removed from the subsurface.

Scott Seery July 1, 1994



Anticipated Third Quarter 1994 Activities:

• WA will submit a report presenting the results of third quarter 1994 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results and a ground water elevation contour map.

Conclusions and Recommendations:

WA recommends continued monitoring of dissolved hydrocarbon concentrations in ground water. Despite the fact that hydrocarbons were detected in soil borings between wells MW-4 and MW-5, no total petroleum hydrocarbons as gasoline (TPH-G) or benzene, ethylbenzene, toluene and xylenes (BETX) have ever been detected in ground water samples from well MW-5 since it was installed in 1991. Although 98 ppb TPH-G were detected in the ground water sample collected from MW-6 during the first quarter of 1994, no TPH-G, BETX, petroleum oil and grease or semi-volatile organic compounds were detected during the second quarter sampling. Therefore, the extent of hydrocarbons in ground water have been fully assessed downgradient of the site.

Scott Seery July 1, 1994



Please call if you have any questions.

No. EG 1578
CERTIFIED
ENGINEERING
GEOLOGIST

Sincerely, Weiss Associates

J. Michael Asport Technical Assistant

James W. Carmody, C.E.G. Senior Project Hydrogeologist

JMA/JWC:mb

J:\SHELL\600\QMRPTS\618QMJU4.WP

Attachments: A - Blaine Tech Services' Ground Water Monitoring Report

cc: Dan Kirk, Shell Oil Company, P.O. Box 5278, Concord, CA 94520 Tom Callaghan, San Francisco Bay Regional Water Quality Control Board, 2101 Webster Street, Oakland, CA 94612



Figure 1. Site Location Map - Shell Service Station WIC #204-5508-3301, 6039 College Avenue, Oakland, California




Figure 2. Monitoring Well and Ground Water Elevation Contours - May 4, 1994 - Shell Service Station WIC #204-5510-0303, 6039 College Avenue, Oakland, California

Table 1. Ground Water Elevations - Shell Service Station WIC #204-5508-3301, 6039 College Avenue, Oakland, California

Well ID	Date	Top-of-Casing Elevation (ft above msl)	Depth to Water (ft)	Separate-Phase Hydrocarbon Thickness (ft)	Ground Water Elevation (ft above msl) ^a
MW-1	06/03/91	195.89	17.82		178.07
	08/30/91		19.87		176.02
	11/22/91		20.58		175.31
	03/18/92		13.55		182.34
	05/28/92		17.08		178.81
	08/19/92		19.07		176.82
	11/17/92		20.11		175.78
4	02/12/93		12.10		183.79
	06/10/93		14.87		181.02
	08/18/93		16.90		178. 99
	11/19/93		19.72		176.17
	02/28/94		15.08		180.81
	05/04/94		17.20		178.69
MW-2	06/03/91	194.27	17.00		177.27
IVI VV -Z	08/30/91	154.27	18.95		175.32
	11/22/91		19.55		173.32
	03/18/92		12.91		181.36
	05/28/92		16.25		178.02
	08/19/92		18.21		176.06
	11/17/92		19.15		175.12
	02/12/93		11.60		182.67
	06/10/93		14.14		180.13
	08/18/93		16.10		178.17
	11/19/93		18.77		175.50
	02/28/94		14.35		179.92
	05/04/94		16,34		177.93
MW-3	06/03/91	192.52	15.84		176.68
141 44 -7	08/30/91	172.52	17.79		174.73
	11/22/91		18.40		174.12
	03/18/92		12.03		180.49
	05/28/92		15.16		177.36
	08/19/92		17.03		175.49
	11/17/92		17.94		174.58
	02/12/93		9.16		183.36
	06/10/93		13.20		179.32
	08/18/93		14.93		177.59
	11/19/93		17.58		174.94

⁻⁻ Table 1 continues on next page --

Table 1. Ground Water Elevations - Shell Service Station WIC #204-5508-3301, 6039 College Avenue, Oakland, California (continued)

Well ID	Date	Top-of-Casing Elevation (ft above msl)	Depth to Water (ft)	Separate-Phase Hydrocarbon Thickness (ft)	Ground Water Elevation (ft above msl) ^a
	02/28/94		13.30		179.22
	05/04/94		15.25		177.27
MW-4	06/03/91	193.37	16.77		176.60
	08/30/91		18.71		174.66
	11/22/91				
	03/18/92 ^a		13.15	0.24	180.41
	05/28/92 ^a		16.22	0.12	177.25
	08/19/92a		18.05	0.09	175.39
	11/17/92		18.89		174.48
	02/12/93		11.78	< 0.01	181.59
	06/10/93		14.20		179.17
	08/18/93		15.95	0.01	177.43
	11/1 9/93		18.48	0.01	174.90
	02/28/94		14.60	< 0.01	178.77
	05/04/94		16.15	< 0.01	177.22
MW-5	08/30/91	190.35	16.74		173.61
	11/22/91		17.27		173.08
	03/18/92		11.28		179.07
	05/28/92 ^b				
	08/19/92		15.99		174.36
	11/17/92		16.84		173.51
	02/12/93		10.30		180.05
	06/10/93		12.36		1 77.99
	08/18/93		14.02		176.33
	11/19/93		16.50		173.85
	02/28/94		12.55		177.80
	05/04/94		14,27		176,08
MW-6	09/21/93	189.05	14.64		174.41
	11/19/93				
	02/28/94		12.18		176.87
	05/04/94		13.62		175.43

⁻⁻ Table 1 continues on next page --



Table 1. Ground Water Elevations - Shell Service Station WIC #204-5508-3301, 6039 College Avenue, Oakland, California (continued)

Notes:

a = When separate-phase hydrocarbons are present, ground water elevation is corrected by the relation: Corrected ground water elevation = (Top-of-Casing Elevation) - (depth to water) + (0.8 x separate-phase hydrocarbon thickness)

b = Well inaccessible --- = Data not available

		Depth to	TPH-G	TPH-D	TPH-MO	POG	В	E	T	Х	SVOC
/ell/Boring	Date	Water	<			-parts per	billion (ug,	/L)			>
D	Sampled	(ft)			•						
IW-1	06/03/91	17.82	ND	ND	ND		ND	ND	ND	ND	
	08/30/91	19.87	ND	520	ND		ND	ND	ND	ND	
	11/22/91	20.58	<50	<50	<500		<0.5	<0.5	<0.5	<0.5	
	03/18/92	13.55	<30	<50			<0.3	<0.3	<0.3	<0.3	
	05/28/92	17.08	<50	<50			<0.5	<0.5	<0.5	<0.5	
	08/19/92	19.07	<50	<50			<0.5	<0.5	<0.5	<0.5	
	11/17/92	20.11	<50	<50			<0.5	<0.5	<0.5	<0.5	
	02/12/93	12.10	<50	< 5 0			<0.5	<0.5	<0.5	<0.5	
	06/10/93	14.87	< 5 0				<0.5	<0.5	<0.5	<0.5	
	06/10/93 ^{dup}	14.87	<50	•••			<0.5	<0.5	<0.5	<0.5	
			<50				<0.5				
	08/18/93	16.90 19.72	<50				<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
	11/19/93										
	02/18/94	15.08	<50		 Leon bábarca A Alg ica lefted		<0.5	<0.5	<0.5	1.7	
	05/04/94	17.20	<50				<0.5	<0.5	<0.5	<0.5	
W-2	06/03/91	17.00	ND	ND	ND		ND	ND	ND	ND	
_	08/30/91	18.95	ND	ND	ND		ND	ND	ND	ND	
	11/22/91	19.55	<50	<50	<500		<0.5	<0.5	<0.5	<0.5	
	03/18/92	12.91	<30	•••		•••	<0.3	<0.3	<0.3	<0.3	
	05/28/92	16.25	<50				<0.5	<0.5	<0.5	<0.5	
	08/19/92	18.21	< 50				<0.5	1.2	2	1.9	
	11/17/92	19.15	<50				<0.5	1.2	2	1.9	
	02/12/93 ^{dup}	11.60	<50				<0.5	<0.5	<0.5	<0.5	
	02/12/93		<50 <50		•••	•••	<0.5	<0.5	<0.5	<0.5	
	02/12/93	11.60									
	06/10/93	14.14	<50				<0.5	<0.5	<0.5	<0.5	
	08/18/93	16.10	<50				<0.5	<0.5	<0.5	<0.5	
	08/18/93 ^{dup}	16.10	<50				<0.5	<0.5	<0.5	<0.5	
	11/19/93	18.77	<50				<0.5	<0.5	<0.5	<0.5	
	02/18/94	14.55	<50				<0.5	<0.5	<0.5	1.6	 -
	05/04/94 *	16.34	<50			4.5	<0.5	<0.5	<0.5	<0.5	02.020.000.000
w-3	06/03/91	15.84	1,700	690°	ND		260	98	13	24	
	08/30/91	17.79	870	370 ^b	500		44	10	6.1	2.9	
	11/22/91	18.40	310	140	500		18	3.3	1.2	2.9	
	03/18/92	12.03	67,100	1,900	20,000		620	220	28	38	
	05/28/92	15.16	2,300	1,100°	4,600		200	71	9	17	
		17.03	5,700	1,000°	1,800		71	52	77	130	
	08/19/92			1,000 160 ^c	1,200		16	24	8.6	50	
	11/17/92	17.94	3,600 / 700							70 77	
	02/12/93	9.16	4,700	560°	<50		820	130	58	77 27	
	06/10/93	13.20	2,200	•••	940 ^d		310	89	23	23	
	08/18/93	14.93	260		460 ^d		27	_ 7. 0	_2.0	2.2	
	11/19/93	17.58	1,500 ^e		960d	<5,000	24	37	54	17	
	02/18/94	13.30	2,700		1,600	<5,000	65	16	5.2	6.3	
	02/18/94 ^{dup}		3,100		2,200	<5,000	82	19	6.7	7.9	

⁻⁻ Table 2 continues on next page --



		Water (ft)	<	•••••	TPH-MO	parts per	billion (ug	/L)			SVOCs >
	05/04/94 ^{dap}	15.25	920	***	1,600	<5,000	120	22	7.7	7.1	g
4W-4	06/03/91	16.77	670 ^h	1,100	ND		240	1.6	2.3	2.3	
	08/30/91	18.71	570	280	2,000		64	0.9	1.8	0.9	
	11/22/91 ^{SPH}				•••						
	03/18/92 ^{SPH}	13.15									
	05/28/92 ^{SPH}	16.22									
	08/19/92 ^{SPH}	18.05									
	11/17/92 ^{SPH}	18.89									
	02/12/93 ^{SPH}	11.78 14.20									
	06/10/93 08/18/93 ^{SPH}	14.20 15.95									
	11/19/93 ^{SPH}	18.48									
	02/28/94 SPH	14.60									
	05/04/94 ^{SPH}	16.15			444	444			***		
MW-5	08/30/91	16.74	ND	80	ND		ND	ND	ND	ND	
	11/22/91	17.27	<50	<50	<500		<0.5	<0.5	<0.5	<0.5	
	03/18/92	11.28	<30	<50			<0.3	<0.3	<0.3	<0.3	
	05/28/92 ³										
	08/19/92	15.99	<50	<50			<0.5	<0.5	<0.5	<0.5	
	11/17/92	16.84	<50	<50			<0.5	<0.5	<0.5	<0.5	
	02/12/93	10.30	<50	<50			<0.5	<0.5	<0.5	<0.5	
	06/10/93	12.36	<50				<0.5	<0.5	<0.5	<0.5	
	08/18/93	14.02	<50				<0.5	<0.5	<0.5	<0.5	
	11/19/93	16.50	<50				<0.5	<0.5	<0.5	<0.5	
	11/19/93 ^{dup}	16.50	< 50				<0.5	<0.5	<0.5	<0.5	
	02/18/94	12.55	<50		 		<0.5	<0.5	<0.5	<0.5	
	05/04/94	14.27	<50	· · · · · · · · · · · · · · · · · · ·		200	<0.5	<0.5	<0.5	<0.5	
MM-6	09/21/93	14.64	<50	<50		<5,000	<0.5	<0.5	<0.5	<0.5	<10-50
	11/19/93 ^k	42.40	98¹								
	02/28/94 05/04/94	12.18 13.62	98 ≤50	an an area and a second and a second		<5,000 <5,000	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	
	U3/U4/94	13.02	~30	**************************************		~ 3,000	~U. O	50.3	~v.o	SU.5	<2-10
BH-A	09/09/93	16.50	4,900	2.900 ^c		<5,000	. 18	54	<5	11	m
BH-B	09/09/93	15.85	<50	150		<5,000	<0.5	<0.5	<0.5	<0.5	ND
BH-C ⁿ	09/10/93	15.80	640°	100		<5,000	3.5	0.6	<0.5	<0.5	ND
BH-D ⁿ	09/10/93	14.2	24.000°	25,000°		20,000	720	44	86	11	₽
Bailer	08/19/92 11/17/92		<50 <50				<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5	

⁻⁻ Table 2 continues on next page --



Well/Boring	Date	Depth to Water	TPH-G	TPH-D	TPH-MO	POG	В	Ε	T	Х	SVOCs	
ID	Sampled	(ft)	<pre><> </pre>									
Trip	06/03/91		ND				ND	ND	ND	ND		
Blank	08/30/91		ND				ND	ND	ND	ND		
	03/18/92		<30	<50			<0.3	<0.3	<0.3	<0.3		
	05/28/92		<50				<0.5	<0.5	<0.5	<0.5		
	08/19/92		<50				<0.5	<0.5	<0.5	<0.5		
	11/17/92		<50				<0.5	<0.5	<0.5	<0.5		
	02/12/93		<50				<0.5	<0.5	<0.5	<0.5		
	06/10/93		<50		** +- **		<0.5	<0.5	<0.5	<0.5		
	11/19/93		<50				<0.5	<0.5	<0.5	<0.5		
	02/28/94		<50				<0.5	<0.5	<0.5	<0.5		
	05/04/94		<50	55.5			<0.5	<0.5	<0.5	<0.5		
DTSC MCLs			NE	NE	NE.		1	680	100 ^q	1,750		

Abbreviations:

TPH-G = Total petroleum hydrocarbons as gasoline by Modified EPA Method 8015

TPH-D = Total petroleum hydrocarbons as diesel by Modified EPA Method 8015

TPH-MO = Total petroleum hydrocarbons as motor oil by EPA Method 8015

B = Benzene by EPA Method 8020 E = Ethylbenzene by EPA Method 8020

T = Toluene by EPA Method 8020

X = Xvlenes by EPA Method 8020

POG = Petroleum Oil & Grease by EPA Method 5520B/F

SVOCs = Semivolatile organic compounds by EPA Method 8270

NE = Not established

DTSC MCLs = California Department of Toxic Substances Control maximum contaminant levels for drinking water

--- = Not analyzed or measured

<n = Not detected at detection limits of n ppb
ND = Not detected, detection limit not known</pre>

SPH - Separate-phase hydrocarbons in well, not sampled

dup = Duplicate sample

<u>Notes</u>:

Chail Compine Chabins LIC #20/ FEOG 7704 (070 Callege Avenue Callege Bull and Callege Chail

- a = Positive results for diesel appear to be less volatile constituents of gasoline
- b = Positive results for diesel has a typical diesel pattern
- c = Concentration reported as diesel is primarily due to the presence of a lighter petroleum product, possibly gasoline or kerosene
- d = Concentration reported as motor oil is due to the presence of a combination of motor oil and a lighter petroleum product of hydrocarbon range C6-C12, possibly gasoline
- e = Concentration reported as gasoline is due to the presence of gasoline and a descrete peak not indicative of gasoline
- f = Compounds are within chromatographic range of gasoline but are not characteristic of the standard gasoline pattern
- g = Results include compounds apparently due to gasoline as well as those due to diesel
- h = 6.5 ppb Napthalene detected
- i = 11.0 ppb Napthalene detected
- j = Well inaccessible and not sampled
- k = Well inadvertantly not sampled
- 1 = The concentration reported as gasoline is primarily due to the presence of a discrete peak not indicative of gasoline
- m = 13 ppb-methylnaphthalene and 23 ppb naphthalene detected
- n = Due to chain of custody mis-communication analyses run after holding time expiration
- o = The positive result has an atypical pattern for gasoline analysis
- p = 75 ppb 2-methylnapthalene and 18 ppb napthalene detected
- q = DTSC recommended action level: MCL not established


Separate-Phase Hydrocarbon Removal - Shell Service Station WIC #204-5508-3301, 6039 College Avenue, Oakland, California Table 3.

Well ID	Date	Separate-Phase Hydrocarbon Thickness (ft)	Separate-Phase Hydrocarbons Removed (lbs)	Cumulative Hydrocarbons Removed (lbs)
MW-4ª	01/15/92	,	3.12	3.12
	02/15/92		3.12	6.24
	03/18/92	0.24		6.24
	04/29/92		1.50	7.74
	05/28/92	0.12	0.18	7.92
	08/19/92	0.09	0.96	8.86
	11/17/92		0.96	9.82
	02/12/93	< 0.01	·	9.82
	06/10/93	0.02	0.06	9.88
	08/18/93	0.01	0.06	9.94
	11/19/93	0.01	0.06	10.00
	02/28/94	0.01	0.06	10.06
	05/04/94	0.00	0.06	10.12

Petrotrap separate-phase hydrocarbon skimmer installed in well
 Not measured or no hydrocarbons bailed



ATTACHMENT A GROUND WATER MONITORING REPORT AND ANALYTIC REPORT



BLAINE TECH SERVICES INC.

985 TIMOTHY DRIVE SAN JOSE, CA 95133 (408) 995-5535 FAX (408) 293-8773

May 23, 1994

Shell Oil Company P.O. Box 5278 Concord, CA 94520-9998

Attn: Daniel T. Kirk

SITE: Shell WIC #204-5508-3301 6039 College Avenue Oakland, California

QUARTER: 2nd quarter of 1994

QUARTERLY GROUNDWATER SAMPLING REPORT 940504-K-2

This report contains data collected during routine inspection, gauging and sampling of groundwater monitoring wells performed by Blaine Tech Services, Inc. in response to the request of the consultant who is overseeing work at this site on behalf of our mutual client, Shell Oil Company. Data collected in the course of our field work is presented in a TABLE OF WELL GAUGING DATA. The field information was collected during our preliminary gauging and inspection of the wells, the subsequent evacuation of each well prior to sampling, and at the time of sampling.

Measurements taken include the total depth of the well and the depth to water. The surface of water was further inspected for the presence of immiscibles which may be present as a thin film (a sheen on the surface of the water) or as a measurable free product zone (FPZ). At intervals during the evacuation phase, the purge water was monitored with instruments that measure electrical conductivity (EC), potential hydrogen (pH), temperature (degrees Fahrenheit), and turbidity (NTU). In the interest of simplicity, fundamental information is tabulated here, while the bulk of the information is turned over directly to the consultant who is making professional interpretations and evaluations of the conditions at the site.

STANDARD PROCEDURES

Evacuation

Groundwater wells are thoroughly purged before sampling to insure that the sample is collected from water that has been newly drawn into the well from the surrounding geologic formation. The selection of equipment to evacuate each well is based on the physical characteristics of the well and what is known about the performance of the formation in which the well has been installed. There are several suitable devices which can be used for evacuation. The most commonly employed devices are air or gas actuated pumps, electric submersible pumps, and hand or mechanically actuated bailers. Our personnel frequently employ USGS/Middleburg positive displacement pumps or similar air actuated pumps which do not agitate the water standing in the well.

Normal evacuation removes three case volumes of water from the well. More than three case volumes of water are removed in cases where more evacuation is needed to achieve stabilization of water parameters and when requested by the local implementing agency. Less water may be removed in cases where the well dewaters and does not recharge to 80% of its original volume within two hours and any additional time our personnel have reason to remain at the site. In such cases, our personnel return to the site within twenty four hours and collect sample material from the water which has recharged into the well case.

Decontamination

All apparatus is brought to the site in clean and serviceable condition. The equipment is decontaminated after each use and before leaving the site. Effluent water from purging and on-site equipment cleaning is collected and transported to Shell's Martinez Manufacturing Complex in Martinez, California.

Free Product Skimmer

The column headed, VOLUME OF IMMISCIBLES REMOVED (ml) is included in the TABLE OF WELL GAUGING DATA to cover situations where a free product skimming device must be removed from the well prior to gauging. Skimmers are installed in wells with a free product zone on the surface of the water. The skimmer is a free product recovery device which often prevents normal well gauging and free product zone measurements. The 2.0" and 3.0" PetroTraps fall into the category of devices that obstruct normal gauging. In cases where the consultant elects to have our personnel pull the skimmers out of the well and gauge the well, our personnel perform the additional task of draining the accumulated free product out of the PetroTrap before putting it back in the well. This

recovered free product is measured and logged in the VOLUME OF IMMISCIBLES REMOVED column. Gauging at such sites is performed in accordance with specific directions from the professional consulting firm overseeing work at the site on Shell's behalf.

Sample Containers

Sample material is collected in specially prepared containers which are provided by the laboratory that performs the analyses.

Sampling

Sample material is collected in stainless steel bailer type devices normally fitted with both a top and a bottom check valve. Water is promptly decanted into new sample containers in a manner which reduces the loss of volatile constituents and follows the applicable EPA standard for handling volatile organic and semi-volatile compounds.

Following collection, samples are promptly placed in an ice chest containing prefrozen blocks of an inert ice substitute such as Blue Ice or Super Ice. The samples are maintained in either an ice chest or a refrigerator until delivered into the custody of the laboratory.

Sample Designations

All sample containers are identified with a site designation and a discrete sample identification number specific to that particular groundwater well. Additional standard notations (e.g. time, date, sampler) are also made on the label.

Chain of Custody

Samples are continuously maintained in an appropriate cooled container while in our custody and until delivered to the laboratory under a standard Shell Oil Company chain of custody. If the samples are taken charge of by a different party (such as another person from our office, a courier, etc.) prior to being delivered to the laboratory, appropriate release and acceptance records are made on the chain of custody (time, date, and signature of the person releasing the samples followed by the time, date and signature of the person accepting custody of the samples).

Hazardous Materials Testing Laboratory

The samples obtained at this site were delivered to Sequoia Analytical Laboratory in Redwood City, California. Sequoia Analytical Laboratory is a California Department of Health Services certified Hazardous Materials Testing Laboratory and is listed as DOHS HMTL #1210.

Objective Information Collection

Blaine Tech Services, Inc. performs specialized environmental sampling and documentation as an independent third party. In order to avoid compromising the objectivity necessary for the proper and disinterested performance of this work, Blaine Tech Services, Inc. performs no consulting and does not become involved in the marketing or installation of remedial systems of any kind. Blaine Tech Services, Inc. is concerned only with the generation of objective information, not with the use of that information to support evaluations and recommendations concerning the environmental condition of the site. Even the straightforward interpretation of objective analytical data is better performed by interested regulatory agencies, and those engineers and geologists who are engaged in the work of providing professional opinions about the site and proposals to perform additional investigation or design remedial systems.

Reportage

Submission of this report and the attached laboratory report to interested regulatory agencies is handled by the consultant in charge of the project. Any professional evaluations or recommendations will be made by the consultant under separate cover.

Please call if we can be of any further assistance.

Richard C. Blaine

RCB/lp

attachments: table of well gauging data

chain of custody

certified analytical report

cc: Weiss Associates

5500 Shellmound Street Emeryville, CA 94608-2411

ATTN: Michael Asport

TABLE OF WELL GAUGING DATA

WELL I.D.	DATA COLLECTION DATE	MEASUREMENT REFERENCED TO	QUALITATIVE OBSERVATIONS	DEPTH TO FIRST IMMISCIBLES LIQUID (FPZ)	THICKNESS OF IMMISCIBLES LIQUID ZONE	VOLUME OF IMMISCIBLES REMOVED	DEPTH TO WATER	DEPTH TO WELL BOTTOM
			(sheen)	(feet)	(feet)	(mi)	(feet)	(feet)
		-				•		
MW-1	5/4/94	TOC	• •	NONE	-	-	17.20	24.58
MW-2	5/4/94	TOC	-	NONE			16.34	24.37
MW-3 *	5/4/94	TOC	ODOR	NONE	•	-	15.25	24.78
MW-4	5/4/94	TOC	FREE PRODUCT	_	_	50	16.15	
MW-5	5/4/94	TOC	-	NONE	-	-	14.27	28.60
MW-6	5/4/94	TOC	_	NONE	· <u></u> ·	**	13.62	24.32
T-1	5/4/94	TOC	DRY	NONE			-	4.16
T-2	5/4/94	TOC	DRY	NONE	-	- .	-	8.22

^{*} Sample DUP was a duplicate sample taken from well MW-3.

additions of the

	- व्यक्तिकार्यः	ť i																				
ژ≽.	SHELL RETAIL E	NVIR	ONMEN	ITAL E	NGIN		NG -	WES	CHAIN OF CUSTODY RECORD Sodd No: 940504-162						ORD	Dale: - Page	5/4/94 1_01					
]"' 	Sile Address; \$ 6039	Colle	ge Ave.	, Oak	land	•	·	Analysis Required						LAB: Squis								
	WIC#: 204-5	.¦i	1301												$\overline{}$					CHECK ONE EI) TOX OHER	CI/OI , I	URH AROUND THAT
	Sholl Engineer:	:			Phone 75–61 ax #:	No.; 68 675-1	(510) 6160						_			୍ଦିର				· _		hour [
	Consultant Name & A Blaine Tech Serv 985 Timothy Drive Consultant Contact:	ddres ices, e S	is: Inc. an Jose	<u>. CΛ</u>	9513 Phono	3 No.	((00)		·		6)		& BTEX 8020			827				-	un	doys X (Houmob)
	Jim Keller			Ş	95-55 ax #:	35 293-4	8773	(503)	Diesel)	'	4 8240)		5 & B	.	70	V					110	OTG Helly Le:
	Commonis:	,			•			Mod.	Mod.	(209/0	Ics (EPA	ซ	PH 801.	10.	00	2		P	z	Other .		on as Possible of 1/45 hm. 1A1.
	Sampled by: / K		C. 13	יניים	<u> </u>	, 		(EPA 8015	(EPA 8015	(EPA 8020/602)	Volatile Organics	Test for Disposal	Combination TPH 8015	V-Hd	0	8	olner Size	Preparation Used	Composite Y/N	MATERIAL DESCRIPTION		SAMPLE :
	Sample ID 🖟	Dale	Sludge	Soll	Wolse	114	No, of contr,	TPH () на	BTEX	Vola	Test (Com	11	9		Container	Prep	S	DESCRIPTION	C	OMMENTS *
/	TB	3/4			ω		2				.		X						<u>. </u>	9405292.	08	A/B
را0	XW.				W		3					·	X								01	A-C
1	MW2	1		<u>'</u>	W		3						X]					02	A-C
8	MW3				ω		7						X	X	\times	X				RLA	03/	4-G 0
i	MW5		·		W		3				· '		\times								04	A-C
Ø	NW6				W		7			_			X		X	X					05	A-G_
8	DUP				W		7		_			_	X	X	\sum	X	2	lec 2	E	Frank regul	<u>ا</u> ا	A-G
. /	EB	Y			W	<u> </u>	3	<u> </u>	L,	ردار	10-		X		أسا		<u>_</u>	Ľ,	Dal-1	d Norman	07	A-C Dale: 5-5-99
	Religgifing by (significa): Religgifing by (significa): Philod Home: Religgifing by (significa): Philod Home: Philod Home: Philod Home: Philod Home: Philod Home:						0: \$/ 10: 9 0: 5	5/15 3-9	Ker FRee	NY O	1 (1)0	nalus nalus	M				Pilot	od Name: CS FUHChe		lime: 9://3		
ļ	Relinguished by (signature): Printed Name: Relinguished by (signature): Printed Name;					Dal	10: /C	Ž 14 9	٤١	elve) (NO	úajnie				_	Pilni	ed Hame:		DalesoSoS34		
	THE LABORATORY MUST PROV					ROYIDE	IIm A CC		F 11115	CIIA			1007	WITH	INYC	DICE.	MQ	TYN	ith E. Gress		Time: 1045	

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, ČA 95133 Attention: Jim Keller

Project: 940504-K2, Shell, 6039 College Ave.

Enclosed are the results from 8 water samples received at Sequoia Analytical on May 5,1994. The requested analyses are listed below:


SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
4E29201	Water, MW-1	5/4/94	EPA 5030/8015 Mod./8020
4E29202	Water, MW-2	5/4/94	EPA 5030/8015 Mod./8020
4E29203	Water, MW-3	5/4/94	EPA 3510/3520/8015 Mod. EPA 5030/8015 Mod./8020 EPA 8270 SM 5520 B&F (Gravimetric)
4E29204	Water, MW-5	5/4/94	EPA 5030/8015 Mod./8020
4E29205	Water, MW-6	5/4/94	EPA 5030/8015 Mod./8020 EPA 8270 SM 5520 B&F (Gravimetric)
4E29206	Water, DUP	5/4/94	EPA 3510/3520/8015 Mod. EPA 5030/8015 Mod./8020 EPA 8270 SM 5520 B&F (Gravimetric)
4E29207	Water, EB	5/4/94	EPA 5030/8015 Mod./8020
4E29208	Water, TB	5/4/94	EPA 5030/8015 Mod./8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager



680 Chesapeake Drive 1900 Bates Avenue, Suite L Concord, CA 94520 819 Striker Avenue, Suite 8 Sacramento, CA 95834

Redwood City, CA 94063

(415) 364-9600 (510) 686-9600 (916) 921-9600

FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive

Client Project ID:

940504-K2, Shell, 6039 College Ave.

Sampled:

May 4, 1994 May 5, 1994

San Jose, CA 95133 Attention: Jim Keller

Sample Matrix: Analysis Method:

Water EPA 5030/8015 Mod./8020 Received: Reported:

May 16, 1994

First Sample #:

4E29201

TOTAL PURGEABLE PETROLEUM HYDROCARBONS with BTEX DISTINCTION

Analyte	Reporting Limit μg/L	Sample I.D. 4E29201 MW-1	Sample I.D. 4E29202 MW-2	Sample I.D. 4E29203 MW-3	Sample I.D. 4E29204 MW-5	Sample 1.D. 4E29205 MW-6	Sample I.D. 4E29206 DUP
Purgeable Hydrocarbons	50	N.D.	N.D.	780	N.D.	N.D.	920
Benzene	0.50	N.D.	N.D.	120	N.D.	N.D.	120
Toluene	0.50	N.D.	N.D.	7.5	N.D.	N.D.	7.7
Ethyl Benzene	0.50	N.D.	N.D.	21	N.D.	N.D.	22
Total Xylenes	0.50	N.D.	N.D.	6.9	N.D.	N.D.	7.1
Chromatogram Pat	tern:		••	C6 - C12		••	C6 - C12

Quality Control Data


Report Limit Multiplication Factor:	1.0	1.0	5.0	1.0	1.0	5.0
Date Analyzed:	5/9/94	5/9/94	5/9/94	5/8/94	5/9/94	5/9/94
Instrument Identification:	GCHP-3	GCHP-3	GCHP-3	GCHP-3	GCHP-3	GCHP-3
Surrogate Recovery, %: (QC Limits = 70-130%)	93	76	91	83	80	90

Purgeable Hydrocarbons are quantitated against a fresh gasoline standard. Analytes reported as N.D. were not detected above the stated reporting limit.

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager

4E29201.BLA <1>



680 Chesapeake Drive 1900 Bates Avenue, Suite L. Concord, CA 94520 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600

FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive

Client Project ID:

940504-K2, Shell, 6039 College Ave.

Sampled:

May 4, 1994 May 5, 1994

San Jose, CA 95133

Sample Matrix: Analysis Method: Water

Received:

Attention: Jim Keller

First Sample #:

EPA 5030/8015 Mod./8020

4E29207

Reported: May 16, 1994

TOTAL PURGEABLE PETROLEUM HYDROCARBONS with BTEX DISTINCTION

Analyte	Reporting Limit μg/L	Sample I.D. 4E29207 EB	Sample I.D. 4E29208 TB	
Purgeable Hydrocarbons	50	N.D.	N.D.	
Benzene	0.50	N.D.	N.D.	
Toluene	0.50	N.D.	N.D.	
Ethyl Benzene	0.50	N.D.	N.D.	
Total Xylenes	0.50	N.D.	N.D.	
Chromatogram Par	itern:		••	

Quality Control Data


Report Limit Multiplication Factor:	1.0	1.0	
Date Analyzed:	5/10/94	5/10/94	
Instrument Identification:	GCHP-17	GCHP-17	`
Surrogate Recovery, %: (QC Limits = 70-130%)	96	97	

Purgeable Hydrocarbons are quantitated against a fresh gasoline standard. Analytes reported as N.D. were not detected above the stated reporting limit.

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager

4E29201.BLA <2>



680 Chesapeake Drive 1900 Bates Avenue, Suite L. Concord, CA 94520 819 Striker Avenue, Suite 8 Sacramento, CA 95834

Redwood City, CA 94063

(415) 364-9600 (510) 686-9600 (916) 921-9600

FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133 Attention: Jim Keller

Client Project ID: Sample Descript: Analysis Method:

Lab Number:

940504-K2, Shell, 6039 College Ave. Water, MW-3 **EPA 8270** 4E29203

Sampled: Received: Extracted:

May 4, 1994 May 5, 1994 May 9, 1994

Analyzed: May 12, 1994 Reported: May 16, 1994

SEMI-VOLATILE ORGANICS by GC/MS (EPA 8270)

Analyte	Detection Limit		Sample Results
	μg/L		μg/L
Acenaphthene	2.0	***************************************	N.D.
Acenaphthylene	2.0	***************************************	N.D.
Anthracene	2.0	***************************************	N.D.
Benzoic Acid	10		N.D.
Benzo(a)anthracene	2.0		N.D.
Benzo(b)fluoranthene	2.0	***************************************	N.D.
Benzo(k)fluoranthene	2.0	***************************************	N.D.
Benzo(g,h,i)perylene	2.0	***************************************	N.D.
Benzo(a)pyrene	2.0		N.D.
Benzyl alcohol	2.0		N.D.
Bis(2-chloroethoxy)methane	2.0	***************************************	N.D.
Bis(2-chloroethyl)ether	2.0	,	N.D.
Bis(2-chloroisopropyl)ether	2.0	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N.D.
Bis(2-ethylhexyl)phthalate	10		N.D.
4-Bromophenyl phenyl ether	2.0		N.D.
Butyl benzyl phthalate	2.0		N.D.
4-Chloroaniline	2.0		N.D.
2-Chloronaphthalene	2.0		N.D.
4-Chloro-3-methylphenol	2.0		N.D.
2-Chiorophenol	2.0		N.D.
4-Chlorophenyl phenyl ether	2.0	************	N.D.
Chrysene	2.0	***************************************	N.D.
Dibenz(a,h)anthracene	2.0		N.D.
Dibenzofuran	2.0	***************************************	N.D.
Di-N-butyl phthalate	10	***************************************	N.D.
1,3-Dichlorobenzene	2.0		N.D.
1,4-Dichlorobenzene	2.0		N.D.
1,2-Dichlorobenzene	2.0	***************************************	N.D.
3,3-Dichlorobenzidine	10	*******************************	N.D.
2,4-Dichlorophenol	2.0	***************************************	N.D.
Diethyl phthalate	2.0		N.D.
2,4-Dimethylphenol	2.0	***************************************	N.D.
Dimethyl phthalate	2.0	***************************************	N.D.
4,6-Dinitro-2-methylphenol	10		N.D.
2,4-Dinitrophenol	10		N.D.
2,4-Dinitrotoluene	2.0	***************************************	N.D.
2,6-Dinitrotoluene	2.0	***************************************	N.D.



680 Chesapeake Drive 1900 Bates Avenue, Suite L. Concord, CA 94520 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133

Attention: Jim Keller

Client Project ID: Sample Descript: 940504-K2, Shell, 6039 College Ave. Water, MW-3

Sampled: Received: May 4, 1994 May 5, 1994

Analysis Method: Lab Number:

EPA 8270 4E29203

Extracted: Analyzed:

May 9, 1994 May 12, 1994

Reported: May 16, 1994

SEMI-VOLATILE ORGANICS by GC/MS (EPA 8270)

Analyte	Detection Limit µg/L		Sample Results µg/L
Di-N-octyl phthalate	2.0		N.D.
Fluoranthene	2.0		N.D.
Fluorene	2.0		N.D.
Hexachlorobenzene	2.0		N.D.
Hexachlorobutadiene	2.0		N.D.
Hexachlorocyclopentadiene	2.0	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N.D.
Hexachloroethane	2.0		N.D.
Indeno(1,2,3-cd)pyrene	2.0		N.D.
Isophorone	2.0	***************************************	N.D.
2-Methylnaphthalene	2.0		N.D.
2-Methylphenol	2.0		N.D.
4-Methylphenol	2.0		N.D.
Naphthalene	2.0	***************************************	
2-Nitroaniline	10	***************************************	N.D.
3-Nitroaniline	10	***************************************	N.D.
4-Nitroaniline	10	***************************************	N.D.
Nitrobenzene	2.0		N.D.
2-Nitrophenol	2.0	***************************************	N.D.
4-Nitrophenoi	10		N.D.
N-Nitrosodiphenylamine	2.0	441441411111111111111111111111111111111	N.D.
N-Nitroso-di-N-propylamine	2.0	***************************************	N.D.
Pentachlorophenol	10		N.D.
Phenanthrene	2.0		N.D.
Phenol	2.0		N.D.
Pyrene	2.0	,	N.D.
1,2,4-Trichlorobenzene	2.0		N.D.
2,4,5-Trichlorophenol	10	***************************************	N.D.
2,4,6-Trichlorophenol	2.0	***************************************	N.D.


Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager

Page 2 of 2

4E29201.BLA <4>



680 Chesapeake Drive 1900 Bates Avenue, Suite L. Concord, CA 94520 819 Striker Avenue, Suite 8 Sacramento, CA 95834

Redwood City, CA 94063

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133 Attention: Jim Keller

Client Project ID: Sample Descript: Analysis Method:

Lab Number:

940504-K2, Shell, 6039 College Ave. Water, MW-6

EPA 8270 4E29205


Sampled: May 4, 1994 Received: May 5, 1994 Extracted: May 9, 1994 Analyzed:

May 12, 1994 Reported: May 16, 1994

SEMI-VOLATILE ORGANICS by GC/MS (EPA 8270)

Acenaphthene 2.0 N.D. Acenaphthylene 2.0 N.D. Anthracene 2.0 N.D. Benzoic Acid 10 N.D. Benzo(a)anthracene 2.0 N.D. Benzo(b)fluoranthene 2.0 N.D. Benzo(k)fluoranthene 2.0 N.D. Benzo(g,h,i)perylene 2.0 N.D. Benzo(a)pyrene 2.0 N.D. Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Acenaphthylene 2.0 N.D. Anthracene 2.0 N.D. Benzoic Acid 10 N.D. Benzo(a)anthracene 2.0 N.D. Benzo(b)fluoranthene 2.0 N.D. Benzo(k)fluoranthene 2.0 N.D. Benzo(g,h,i)perylene 2.0 N.D. Benzo(a)pyrene 2.0 N.D. Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Anthracene 2.0 N.D. Benzoic Acid 10 N.D. Benzo(a)anthracene 2.0 N.D. Benzo(b)fluoranthene 2.0 N.D. Benzo(k)fluoranthene 2.0 N.D. Benzo(g,h,i)perylene 2.0 N.D. Benzo(a)pyrene 2.0 N.D. Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Benzo(a)anthracene 2.0 N.D. Benzo(b)fluoranthene 2.0 N.D. Benzo(k)fluoranthene 2.0 N.D. Benzo(g,h,i)perylene 2.0 N.D. Benzo(a)pyrene 2.0 N.D. Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Benzo(b)fluoranthene 2.0 N.D. Benzo(k)fluoranthene 2.0 N.D. Benzo(g,h,i)perylene 2.0 N.D. Benzo(a)pyrene 2.0 N.D. Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Benzo(k)fluoranthene 2.0 N.D. Benzo(g,h,i)perylene 2.0 N.D. Benzo(a)pyrene 2.0 N.D. Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Benzo(k)fluoranthene 2.0 N.D. Benzo(g,h,i)perylene 2.0 N.D. Benzo(a)pyrene 2.0 N.D. Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Benzo(g,h,i)perylene
Benzo(a)pyrene 2.0 N.D. Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Benzyl alcohol 2.0 N.D. Bis(2-chloroethoxy)methane 2.0 N.D. Bis(2-chloroethyl)ether 2.0 N.D. Bis(2-chloroisopropyl)ether 2.0 N.D.
Bis(2-chloroethoxy)methane
Bis(2-chloroethyl)ether
Bis(2-chloroisopropyl)ether
Bis(2-ethylhexyl)phthalate
4-Bromophenyl phenyl ether
Butyl benzyl phthalate
4-Chloroaniline
2-Chloronaphthalene
4-Chloro-3-methylphenol
2-Chlorophenol
4-Chlorophenyl phenyl ether
Chrysene
Dibenz(a,h)anthracene
Dibenzofuran
Di-N-butyl phthalate
1,3-Dichlorobenzene
1,4-Dichlorobenzene
1,2-Dichlorobenzene
3,3-Dichlorobenzidine
2,4-Dichlorophenol
Diethyl phthalate
2,4-Dimethylphenol
Dimethyl phthalate
A O Distance O secretar destruction of
0.4 Blatton band
2,4-Dinitrophenol
2,4-Dinitrotoluene





680 Chesapeake Drive 1900 Bates Avenue, Suite L Concord, CA 94520 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133 Attention: Jim Keller

Client Project ID: Sample Descript: Analysis Method:

Lab Number:

940504-K2, Shell, 6039 College Ave. Water, MW-6

EPA 8270 4E29205

Sampled: Received: Extracted:

May 4, 1994 May 5, 1994 May 9, 1994

Analyzed: May 12, 1994

Reported: May 16, 1994

SEMI-VOLATILE ORGANICS by GC/MS (EPA 8270)

Analyte	Detection Limit µg/L		Sample Results µg/L
Di-N-octyl phthalate	2.0	***************************************	N.D.
Fluoranthene	2.0	***************************************	N.D.
Fluorene	2.0		N.D.
Hexachlorobenzene	2.0	***************************************	N.D.
Hexachlorobutadiene	2.0		N.D.
Hexachlorocyclopentadiene	2.0	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N.D.
Hexachloroethane	2.0	***************************************	N.D.
Indeno(1,2,3-cd)pyrene	2.0		N.D.
Isophorone	2.0	***************************************	N.D.
2-Methylnaphthalene	2.0		N.D.
2-Methylphenol	2.0		N.D.
4-Methylphenol	2.0		N.D.
Naphthalene	2.0	***************************************	N.D.
2-Nitroaniline	10	***************************************	N.D.
3-Nitroaniline	10	***************************************	N.D.
4-Nitroaniline	10	***************************************	N.D.
Nitrobenzene	2.0	***************************************	N.D.
2-Nitrophenol	2.0		N.D.
4-Nitrophenol	10		N.D.
N-Nitrosodiphenylamine	2.0		N.D.
N-Nitroso-di-N-propylamine	2.0		N.D.
Pentachlorophenol	10		N.D.
Phenanthrene	2.0		N.D.
Phenol	2.0		N.D.
Pyrene	2.0		N.D.
1,2,4-Trichlorobenzene	2.0	,	N.D.
2,4,5-Trichlorophenol	10		N.D.
2,4,6-Trichlorophenol	2.0	******************************	N.D.

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Suzanne Chin **Project Manager**

Page 2 of 2

4E29201.BLA <6>



680 Chesapeake Drive 1900 Bates Avenue, Suite L. Concord, CA 94520 819 Striker Avenue, Suite 8 Sacramento, CA 95834

Redwood City, CA 94063

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive

San Jose, CA 95133 Attention: Jim Keller

Client Project ID: 940504-K2, Shell, 6039 College Ave.

Sample Descript: Water, Dup

Analysis Method: EPA 8270 Lab Number: 4E29206

Sampled: Received:

May 4, 1994 May 5, 1994

Analyzed:


May 27, 1994

Jun 1, 1994 Reported:

SEMI-VOLATILE ORGANICS by GC/MS (EPA 8270)

Analyte	Detection Limit μg/L	·	Sample Results µg/L
Acenaphthene	2.0	***************************************	N.D.
Acenaphthylene	2.0	***************************************	N.D.
Anthracene	2.0	,	N.D.
Benzoic Acid	10	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N.D.
Benzo(a)anthracene	2.0	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N.D.
Benzo(b)fluoranthene	2.0	***************************************	N.D.
Benzo(k)fluoranthene	2.0	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N.D.
Benzo(g,h,i)perylene	2.0		N.D.
Benzo(a)pyrene	2.0	***************************************	N.D.
Benzyl alcohol	2.0	***************************************	N.D.
Bis(2-chloroethoxy)methane	2.0	•••••	N.D.
Bis(2-chloroethyl)ether	2.0	***************************************	N.D.
Bis(2-chloroisopropyl)ether	2.0		N.D.
Bis(2-ethylhexyl)phthalate	10	***************************************	N.D.
4-Bromophenyl phenyl ether	2.0	***************************************	N.D.
Butyl benzyl phthalate	2.0	***************************************	N.D.
4-Chloroaniline	2.0		N.D.
2-Chloronaphthalene	. 2.0	***************************************	N.D.
4-Chloro-3-methylphenol	2.0		N.D.
2-Chlorophenol	2.0	***************************************	N.D.
4-Chlorophenyl phenyl ether	2.0		N.D.
Chrysene	2.0		N.D.
Dibenz(a,h)anthracene	2.0		N.D.
Dibenzofuran	2.0	***********	N.D.
Di-N-butyl phthalate	10		N.D.
1,3-Dichlorobenzene	2.0		N.D.
1,4-Dichlorobenzene	2.0		N.D.
1,2-Dichlorobenzene	2.0		N.D.
3,3-Dichlorobenzidine	10	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N.D.
2,4-Dichlorophenol	2.0	,	N.D.
Diethyl phthalate	2.0	******	N.D.
2,4-Dimethylphenol	2.0		N.D.
Dimethyl phthalate	2.0	***************************************	N.D.
4,6-Dinitro-2-methylphenol	10	*******************************	N.D.
2,4-Dinitrophenol	10	***************************************	N.D.
2,4-Dinitrotoluene	2.0	***************************************	N.D.
2,6-Dinitrotoluene	2.0	***************************************	N.D.





Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133

Client Project ID: Sample Descript:

940504-K2, Shell, 6039 College Ave. Water, Dup

Sampled: Received: May 4, 1994 May 5, 1994

Attention: Jim Keller

Analysis Method: Lab Number:

EPA 8270 4E29206

Analyzed: Reported:

May 27, 1994 Jun 1, 1994

SEMI-VOLATILE ORGANICS by GC/MS (EPA 8270)

Analyte	Detection Limit µg/L	. *	Sample Results µg/L
Di-N-octyl phthalate	2.0		N.D.
Fluoranthene	2.0	***************************************	N.D.
Fluorene	2.0		N.D.
Hexachlorobenzene	2.0	***************************************	N.D.
Hexachlorobutadiene	2.0	***************************************	N.D.
Hexachlorocyclopentadiene	2.0		N.D.
Hexachloroethane	2.0		N.D.
Indeno(1,2,3-cd)pyrene	2.0		N.D.
Isophorone	2.0		N.D.
2-Methylnaphthalene	2.0	***************************************	N.D.
2-Metnylpnenol	2.0	***************************************	N.D.
4-Methylphenol	2.0		N.D
Naphthalene	2.0	**********	
2-Nitroaniline	10	***************************************	N.D.
3-Nitroaniline	10	***************************************	N.D.
4-Nitroaniline	10		N.D.
Nitrobenzene	2.0		N.D.
2-Nitrophenol	2.0		N.D.
4-Nitrophenol	10	***************************************	N.D.
N-Nitrosodiphenylamine	2.0	***************************************	N.D.
N-Nitroso-di-N-propylamine	2.0		N.D.
Pentachlorophenol	10	•••••	N.D.
Phenanthrene	2.0	***************************************	N.D.
Phenol	2.0		N.D.
Pyrene	2.0	***************************************	N.D.
1,2,4-Trichlorobenzene	2.0		N.D.
2,4,5-Trichlorophenol	10		N.D.
2,4,6-Trichlorophenol	2.0		N.D.


Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Project Manager

Page 2 of 2

4E29201.BLA <8>



Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600

FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133 Attention: Jim Keller

Client Project ID:

940504-K2, Shell, 6039 College Ave.

Sampled: Received: May 4, 1994

Sample Matrix: Analysis Method: First Sample #:

Water EPA 3510/3520/8015 Mod.

Reported:

May 5, 1994 May 16, 1994

4E29203

Amended:

Jun 1, 1994

FUEL FINGERPRINT: Motor Oil

Analyte	Reporting Limit μg/L	Sample I.D. 4E29203 MW-3	Sample I.D. 4E29206 Dup	
Extractable Hydrocarbons	50	710	1,600	
Chromatogram Pa	ittem:	Motor Oil	Motor Oil	

Quality Control Data


1.0	1.0		
5/9/94	5/25/94		
5/11/94	5/26/94		
GCHP-4	GCHP-4		
	5/9/94 5/11/94	5/9/94 5/25/94 5/11/94 5/26/94	5/9/94 5/25/94 5/11/94 5/26/94

Extractable Hydrocarbons are quantitated against a fresh motor oil standard. Analytes reported as N.D. were not detected above the stated reporting limit.

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager

4E29201.BLA <9>



680 Chesapeake Drive 1900 Bates Avenue, Suite L Concord, CA 94520 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133

Attention: Jim Keller

Client Project ID: Matrix Descript:

940504-K2, Shell, 6039 College Ave.

Water

Analysis Method: First Sample #:

SM 5520 B&F (Gravimetric)

4E29203

Sampled: May 4, 1994 Received: May 5, 1994

May 6, 1994 Extracted: Analyzed: May 6, 31, 1994 Reported: May 16, 1994

Amended: Jun 1, 1994

TOTAL RECOVERABLE PETROLEUM OIL

Sample Number	Sample Description	Oil & Grease mg/L
4E29203	MW-3	N.D.
4E29205	MW-6	N.D.
4E29206	Dup	N.D.

Detection Limits:

5.0

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager

4E29201.BLA < 10>



680 Chesapeake Drive 1900 Bates Avenue, Suite L Concord, CA 94520 819 Striker Avenue, Suite 8 Sacramento, CA 95834

Redwood City, CA 94063

(415) 364-9600 (510) 686-9600 (916) 921-9600

FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc.

985 Timothy Drive

Client Project ID:

940504-K2, Shell, 6039 College Ave.

Matrix:

Liquid

San Jose, CA 95133 Attention: Jim Keller

QC Sample Group: 4E29201-06

Reported:

May 16, 1994


QUALITY CONTROL DATA REPORT

ANALYTE	Benzene	Toluene	Ethyl Benzene	Xylenes		<u></u>	
Method: Analyst:	EPA 8020 A. Miraftab	EPA 8020 A. Miraftab	EPA 8020 A. Miraftab	EPA 8020 A. Miraftab			
MS/MSD Batch#:	4E22801	4E22801	4E22801	4E22801			
Date Prepared: Date Analyzed:	- 5/8/94	- 5/8/94	- 5/8/94	- 5/8/ 94			·
Instrument I.D.#: Conc. Spiked:	GCHP-3 10 μg/L	GCHP-3 10 μg/L	GCHP-3 10 μg/L	GCHP-3 30 µg/L			
Matrix Spike % Recovery:	100	100	100	100			
Matrix Spike Duplicate % Recovery:	94	93	92	90			
Relative % Difference:	6.2	7.3	8.3	11			
LCS Batch#:	-	-	•	•			
Date Prepared: Date Analyzed: Instrument I.D.#:	- - -	- - -	• •	- - -			
LCS % Recovery:			-	-			
% Recovery Control Limits:	71-133	72-128	72-130	71-120	 		

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834 (415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc.

985 Timothy Drive San Jose, CA 95133 Client Project ID:

940504-K2, Shell, 6039 College Ave.

Matrix:

Liquid

Attention: Jim Keller QC Sample Group: 4E29207-08

Reported:

May 16, 1994


QUALITY CONTROL DATA REPORT

ANALYTE	Benzene	Toluene	Ethyl	Xylenes				
ANALTIE	Delizene	loidelle	Benzene	Aylettes				
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020				i
Analyst:	J. Minkel	J. Minkel	J. Minkel	J. Minkel				
MS/MSD								
Batch#:	4DH7901	4DH7901	4DH7901	4DH7901				
2010117	.5							
Date Prepared:	•	-	-	•				
Date Analyzed:	5/9/94	5/9/94	5/9/94	5/9/94				
Instrument I.D.#:	GCHP-17	GCHP-17	GCHP-17	GCHP-17				
Conc. Spiked:	10 μg/L	10 μg/L	10 μg/L	30 μg/L				
Matrix Spike								•
% Recovery:	99	100	98	100				
•								
Matrix Spike								
Duplicate %								
Recovery:	94	94	91	93				
Relative %								
Difference:	5.2	6.2	7.4	7.3		÷		
***************************************		000000000000000000000000000000000000000		**********************				60400000000000
LCS Batch#:	-	-	-	-				
Data Branaradi					•			
Date Prepared: Date Analyzed:	-	-	•	_	·			
Instrument I.D.#:	-	- -	•	-	•			
ing a grant to the transfer				·				
LCS %								
Recovery:		-	•	-				
% Recovery			<u></u>		··-		<u> </u>	
Control Limits:	71-133	72-128	72-130	71-120			•	
Control Limits.	7 1-100	/ E-120	72-100	77 120				

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



680 Chesapeake Drive 1900 Bates Avenue, Suite L Concord, CA 94520 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc.

985 Timothy Drive San Jose, CA 95133 Client Project ID:

940504-K2, Shell, 6039 College Ave.

Matrix:

Attention: Jim Keller

QC Sample Group: 4E29203, 05

Reported: May 16, 1994

QUALITY CONTROL DATA REPORT

ANALYTE	Phenol	2-Chlorophenol	1,4-Dichloro- benzene	N-Nitroso-Di- N-propylamine	1,2,4-Trichloro- benzene	4-Chloro-3- Methylphenol	
Method:	EPA 8270	EPA 8270	EPA 8270	EPA 8270	EPA 8270	EPA 8270	•
Analyst:	L. Duong	L. Duong	L. Duong	L. Duong	L. Duong	L. Duong	
			•		-		
MS/MSD							
Batch#:	4E24904	4E24904	4E24904	4E24904	4E24904	4E24904	
Date Prepared:	5/9/94	5/9/94	5/9/94	5/9/94	5/9/94	5/9/94	
Date Analyzed:	5/12/94	5/12/94	5/12/94	5/12/94	5/12/94	5/12/94	
Instrument I.D.#:	F4	F4	F4	F4	F4	F4	
Conc. Spiked:	1 00 N G	100 NG	50 NG	50 NG	50 NG	100 NG	
Matrix Spike % Recovery:	73	73	68	92	74	76	
Matrix Spike Duplicate % Recovery:	71	72	68	92	76	78	
Relative % Difference:	2.8	1.4	0.0	0.0	2.7	2.6	
LCS Batch#:	•	•	-	-	-	· -	
Date Prepared:	-	-	-	•	•	, -	
Date Analyzed:	-	•	-	-	÷.	-	
Instrument I.D.#:	-	-	•	-	-	-	
LCS %						•	
Recovery:	•	•	-	-	-		
% Recovery							
Control Limits:	5-112	23-134	20-124	DL-230	44-142	22-147	

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834 (415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc.

985 Timothy Drive San Jose, CA 95133 Client Project ID:

940504-K2, Shell, 6039 College Ave.

Matrix:

Liquid

San Jose, CA 95133 Attention: Jim Keller

QC Sample Group: 4E29203, 05

Reported: May 16, 1994


QUALITY CONTROL DATA REPORT

ANALYTE	Assashibasa	4 Miterathanal	O 4 Diniara	Pentachloro-	Durana	
ANALTIC	Acenaphthene	4-Nitrophenol	2,4-Dinitro- toluene	phenol	Pyrene	
			loidollo	phonor		
Method:	EPA 8270	EPA 8270	EPA 8270	EPA 8270	EPA 8270	
Analyst:	L. Duong	L. Duong	L. Duong	L. Duong	L. Duong	
MC (MCD						
MS/MSD Batch#:	4E24904	4E24904	4E24904	4E24904	4E24904	,
Datcii#.	4024904	4E249U4	4524904	4624904	4624904	
Date Prepared:	5/9/94	5/9/94	5/9/94	5/9/94	5/9/94	
Date Analyzed:	5/12/94	5/12/94	5/12/94	5/12/94	5/12/94	
nstrument l.D.#:	F4	F4	F4	F4	F4	
Conc. Spiked:	50 NG	100 NG	50 NG	100 NG	50 NG	
Matrix Spike						
% Recovery:	78	77	68	95	90	
% necovery.	70	**	66	93	90	
Matrix Spike			-			
Duplicate %			•			
Recovery:	78	103	74	104	100	
Relative %						
Difference:	0.0	29	8.5	9.0	11	
			***************************************	***************************************	***************************************	~~~
LCS Batch#:	-	_		_	-	
Date Prepared:	-	•	•	-	•	
Date Analyzed:	-	•	-	•	••	
nstrument I.D.#:	-	-	٠.	-	-	
LCS %						
Recovery:			_	_	_	
Hebbyely.	-	•	•	-	-	
% Recovery						
Control Limits:	47-145	DL-132	39-139	14-176	52-115	

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



680 Chesapeake Drive 1900 Bates Avenue, Suite L. Concord, CA 94520 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc.

985 Timothy Drive San Jose, CA 95133 Client Project ID:

940504-K2, Shell, 6039 College Ave.

Matrix:

Attention: Jim Keller

QC Sample Group: 4E29203

Reported:

May 16, 1994

QUALITY CONTROL DATA REPORT

ANALYTE	Diesel					
		•				
Method:	EPA 8015					
Analyst:	A. Nagra		<u> </u>		 	
MS/MSD						
Batch#:	4E07002					
Date Prepared:	5/9/94					
Date Analyzed:	5/10/94					
Instrument I.D.#:	GCHP-5					
Conc. Spiked:	600 μg/L	-		•		
Matrix Spike				-		
% Recovery:	87					
Matrix Spike						
Duplicate %						
Recovery:	95					
Relative %						
Difference:	9.0					

LCS Batch#:

Date Prepared: Date Analyzed:

Instrument I.D.#:

LCS % Recovery:

% Recovery

Control Limits:

28-122

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc.

985 Timothy Drive San Jose, CA 95133 Attention: Jim Keller Client Project ID:

Matrix:

940504-K2, Shell, 6039 College Ave.

Liquid

QC Sample Group: 4E29203, 05

Reported:

May 16, 1994

QUALITY CONTROL DATA REPORT

ANALYTE

Total Oil &

Grease

Method:

EPA 5520BF

Analyst:

J. Ball

MS/MSD

Batch#:

BLK050294

Date Prepared: Date Analyzed:

5/2/94

5/4/94

Instrument I.D.#: Conc. Spiked:

N/A 30 mg/L

Matrix Spike

% Recovery:

93

100

Matrix Spike Duplicate %

Recovery:

Relative %

Difference:

7.3

LCS Batch#:

BLK050294

Date Prepared:

5/2/94

Date Analyzed:

5/4/94

Instrument I.D.#:

N/A

LCS %

Recovery:

93

% Recovery

Control Limits:

70-110

SEQUOIA ANALYTICAL

Suzanne Chin **Project Manager** Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive

Client Project ID:

940504-K2, Shell, 6039 College Ave.

Matrix:

Water

San Jose, CA 95133 Attention: Jim Keller

QC Sample Group: 4E29206

Reported:

QUALITY CONTROL DATA REPORT

ANALYTE	Total Oil & Grease	Diesel		·
Method:	EPA 5520 BF	EPA 8015		
Analyst:	J. Ball	A. Nagra	 	
MS/MSD			•	
Batch#:	BLK052794	4EC7701	•	
Date Prepared:	5/27/94	5/25/94		
Date Analyzed:	5/27/94	5/25/94		
Instrument I.D.#:	N/A	GCHP-5		
Conc. Spiked:	30 mg/L	600 μg/L		
Matrix Spike				
% Recovery:	87	75	:	
Matrix Spike		•		
Duplicate %				
Recovery:	90	80		
Relative %				
Difference:	3.4	6.5		

LCS Batch#:

BLK052794

Date Prepared: Date Analyzed: 5/27/94 5/27/94

Instrument I.D.#:

N/A

LCS %

Recovery:

87

% Recovery **Control Limits:**

70-110

28-122

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.

4E29201.BLA < 17>



Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834 (415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive Client Project ID:

940504-K2, Shell, 6039 College Ave.

Matrix:

Liquid

San Jose, CA 95133 Attention: Jim Keller

QC Sample Group: 4E29206

Reported: Jun 1, 1994

QUALITY CONTROL DATA REPORT

ANALYS			=			4.00-1	·
ANALYTE	Phenol	2-Chlorophenol	1,4-Dichloro-		1,2,4-Trichloro-		
			benzene	N-propylamine	benzene	Methylphenol	
Method:	EPA 8270	EPA 8270	EPA 8270	EPA 8270	EPA 8270	EPA 8270	
Analyst:	E. Manuel	E. Manuel	E. Manuel	E. Manuel	E. Manuel	E. Manuel	
MS/MSD							•
Batch#:	BLK052494	BLK052494	BLK052494	BLK052494	BLK052494	BLK052494	
Date Prepared:	5/24/94	5/24/94	5/24/94	5/24/94	5/24/94	5/24/94	
Date Analyzed:	5/28/94	5/28/94	5/28/94	5/28/94	5/28/94	5/28/94	
Instrument I.D.#:	H5	H5	H5	H5	H5	H5	
Conc. Spiked:	100 μg/L	100 μg/L	50 μg/L	50 μg/L	50 μg/L	100 μg/L	
			,,-	, 0,		, 0.	
Matrix Spike					•		
% Recovery:	79	78	84	104	86	84	
Matrix Spike							
Duplicate %							
Recovery:	79	78	84	94	86	83	
,.			-				
Relative %							
Difference:	0.0	0.0	0.0	10	0.0	1.2	
LCS Batch#:				_	_	_	•
LOS Dalcim.	-	•	-	-	_	_	
Date Prepared:	-	•	-	-		-	
Date Analyzed:	-		-	• •	-,	-	
Instrument i.D.#:	-	-	•	-	•	-	
LCS %					•		
Recovery:	_	_		•	-	_	
neovery.	-	-	-				
% Recovery		·				,	
Control Limits:	5-112	23-134	20-124	DL-230	44-142	22-147	

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834 (415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc.

985 Timothy Drive

Client Project ID:

940504-K2, Shell, 6039 College Ave.

Matrix:

Liquid

San Jose, CA 95133 Attention: Jim Keller

QC Sample Group: 4E29206

Reported: Jun 1, 1994

QUALITY CONTROL DATA REPORT

ANALYTE	Acenaphthene	4-Nitrophenol	2,4-Dinitro- toluene	Pentachioro- phenol	Pyrene	
Method:	EPA 8270	EPA 8270	EPA 8270	EPA 8270	EPA 8270	•
Analyst:	E. Manuel	E. Manuel	E. Manuel	E. Manuel	E. Manuel	
MS/MSD						
Batch#:	BLK052494	BLK052494	BLK052494	BLK052494	BLK052494	
Date Prepared:	5/24/94	5/24/94	5/24/94	5/24/94	5/24/94	
Date Analyzed:	5/28/94	5/28/94	5/28/94	5/28/94	5/28/94	
Instrument I.D.#:	H5	H5	H5	H5	H5	
Conc. Spiked:	50 μg/L	100 μg/L	50 μg/L	100 µg/L	50 μg/L	
Matrix Spike % Recovery:	88	87	82	79	72	
Matrix Spike Duplicate % Recovery:	90	86	86	80	80	
Relative % Difference:	2.2	1.2	4.8	1.3	11	
LCS Batch#:	•	-	•	•	-	
Date Prepared:	-	-	-	-	•	
Date Analyzed:	-		-	-	-	
Instrument I.D.#:	-	•	-	-	-	
LCS % Recovery:		-	-	•	-	
% Recovery Control Limits:	47-145	DL-132	39-139	14-176	52-115	

SEQUOIA ANALYTICAL

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.

Page 2 of 2

4E29201.BLA < 19>