



floating product  
in UST pit

01017130013-0

Chevron

2920 C.V. Blvd

9-11-90



south piping  
trench; view  
to the west

01017130013-0

Chevron

2920 C.V. Blvd.

9-11-90



fuel tank  
removal

01017130013-0  
Chapman  
2920 C.V. Blvd

9-11-90



checking  
LEL

01017130013-0  
Chapman  
2920 C.V. Blvd.

9-11-90



ash in  
o. tank

01017130013-0

9-11-80

Chevron  
2920 C.V. Blod.



being  
L of  
o. tank

01017130013-0

9-11-80

Chevron  
2920 C.V. Blod



o. tank pit.  
de staining  
pou gravel

01017130013-0

Chevron  
2920 C.U. Blvd

8-11-90



above formation

on w.o. tank 01017130013-0

t. Note secondary Chevron  
rosity 2920 C.U. Blvd.

9-11-90



sample from  
o. tank pit.  
leaving 1120m  
rotlet holes

01017130013-0

Chevron  
2920 C.U. Blvd

9-11-90