

May 5, 2003

Scott Seery
Alameda County Health Care Services Agency
1131 Harbor Bay Parkway, Suite 250
Alameda, California 94502-6577

Subject: Shell-branded Service Station
29 Wildwood Avenue
Piedmont, California

Dear Mr. Seery:

Attached for your review and comment is a copy of the *First Quarter 2003 Monitoring Report* for the above referenced site. Upon information and belief, I declare, under penalty of perjury, that the information contained in the attached document is true and correct.

As always, please feel free to contact me directly at (559) 645-9306 with any questions or concerns.

Sincerely,

Shell Oil Products US



Karen Petryna
Sr. Environmental Engineer

May 5, 2003

Scott Seery
Alameda County Health Care Services Agency
1131 Harbor Bay Parkway, Suite 250
Alameda, California 94502-6577

Re: First Quarter 2003 Monitoring Report
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, California
Incident #98995822
Cambria Project# 245-0687-002



Dear Mr. Seery:

On behalf of Equilon Enterprises LLC dba Shell Oil Products US, Cambria Environmental Technology, Inc. (Cambria) is submitting this groundwater monitoring report in accordance with the reporting requirements of 23 CCR 2652d.

FIRST QUARTER 2003 ACTIVITIES

Groundwater Monitoring: Blaine Tech Services, Inc. (Blaine) of San Jose, California measured dissolved oxygen (DO) concentrations, gauged and sampled all site wells, calculated groundwater elevations, and compiled the analytical data. Cambria prepared a vicinity map (Figure 1) and a groundwater elevation contour map (Figure 2). Blaine's report, presenting the laboratory report and supporting field documents, is included as Attachment A.

ANTICIPATED SECOND QUARTER 2003 ACTIVITIES

Groundwater Monitoring: Blaine will measure DO, gauge and sample all site wells, and tabulate the data. Cambria will prepare a monitoring report.

**Cambria
Environmental
Technology, Inc.**

5900 Hollis Street
Suite A
Emeryville, CA 94608
Tel (510) 420-0700
Fax (510) 420-9170

Sample Frequency Reduction Request: In the *Fourth Quarter 2002 Monitoring Report*, Cambria proposed to reduce the sampling frequency of certain wells based on historical results that show non-detectable or very low chemical concentrations, beginning in the second quarter of 2003. Cambria proposed to sample well MW-1 annually in the first quarter, wells MW-4 and MW-5 semi-annually in the first and third quarters, and wells MW-2 and MW-3 quarterly. All samples will be analyzed for TPHg, BTEX and MTBE. Per a March 27, 2003 telephone call with Alameda County Health Care Services Agency (ACHCSA), case worker, Scott Seery, prior to the second quarter of 2003 sampling event, the ACHCSA informed Cambria that it had not yet reviewed the *Fourth Quarter Monitoring Report* and was unable to address Cambria's request, and that monitoring should continue on the same schedule until further notice.



At Shell's request, and since MW-1 has shown 12 quarters of non-detect results for TPHg and BTEX as well as four quarter of non-detect results for MTBE by 8260, Cambria will implement annual, first quarter sampling of MW-1. Since MW-4 has shown 14 quarters of non-detect results for TPHg and BTEX as well as five quarters of non-detect results for MTBE by 8260, Cambria will implement semi-annual, first and third quarter sampling of MW-4. And since MW-5 has shown 10 consecutive quarters of non-detect results for BTEX, with the exception of one detection of benzene of 0.71 ug/L in May 2002 as well as five quarters of non-detect results for MTBE by 8260 and a range of <30 to only 410 ug/L for TPHg since January 1990, Cambria will implement semi-annual, first and third quarter sampling of MW-5.

Since the above schedule changes result in the elimination of sampling for only one well, MW-1, which has been non-detect since October 1997, for the third quarter 2003 event, we trust that ACHCSA will be able to review the sample frequency reduction request presented in the *Fourth Quarter 2002 Monitoring Report* prior to the fourth quarter 2003 sampling event and inform us if they deem it necessary to sample MW-1, MW-3, and MW-5 at that time. However, we will contact the ACHCSA again, prior to that event, to ensure ACHCSA is in agreement with our proposed monitoring and sampling schedule.


CLOSING

We appreciate the opportunity to work with you on this project. Please call Matt Derby at (510) 420-3332 if you have any questions or comments.

Sincerely,
Cambria Environmental Technology, Inc



Anni Kreml
Senior Staff Scientist



Matthew W. Derby, P.E.
Senior Project Manager




Figures: 1 - Vicinity Map
2 - Groundwater Elevation Contour Map

Attachment: A - Blaine Groundwater Monitoring Report and Field Notes

cc: Karen Petryna, Shell Oil Products US, P.O. Box 7869, Burbank, CA 91510-7869


G:\Piedmont 29 Wildwood\QM\1q03\1q03qm.doc



G:\PIEDMONT29WILDWOODVICINITY.A1

SOURCE: TOPOI MAPS

FIGURE
1




Shell-branded Service Station
 29 Wildwood Avenue
 Piedmont, California
 Incident #98995822



C A M B R I A

Vicinity Map



Groundwater Elevation Contour Map

January 22, 2003



C A M B R I A


FIGURE 2

Shell-branded Service Station
29 Wildwood Avenue
Piedmont, California
Incident #98995822

G:\PIEDMONT29WILDWOOD\FIGURE2\10M03-MP.A1

ATTACHMENT A
Blaine Groundwater Monitoring Report
and Field Notes

BLAINE
TECH SERVICES, INC.



1680 ROGERS AVENUE
SAN JOSE, CA 95112-1105
(408) 573-7771 FAX
(408) 573-0555 PHONE
CONTRACTOR'S LICENSE #746684
www.blainetech.com

February 26, 2003

Karen Petryna
Shell Oil Products US
P.O. Box 7869
Burbank, CA 91510-7869

First Quarter 2003 Groundwater Monitoring at
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Monitoring performed on January 22 and 29, 2003

Groundwater Monitoring Report **030122-DW-2**

This report covers the routine monitoring of groundwater wells at this Shell-branded facility. In accordance with standard procedures that conform to Regional Water Quality Control Board requirements, routine field data collection includes depth to water, total well depth, thickness of any separate immiscible layer, water column volume, calculated purge volume (if applicable), elapsed evacuation time (if applicable), total volume of water removed (if applicable), and standard water parameter instrument readings. Sample material is collected, contained, stored, and transported to the laboratory in conformance with EPA standards. Purgewater (if applicable) is, likewise, collected and transported to the Martinez Refining Company.

Basic field information is presented alongside analytical values excerpted from the laboratory report in the cumulative table of **WELL CONCENTRATIONS**. The full analytical report for the most recent samples and the field data sheets are attached to this report.

At a minimum, Blaine Tech Services, Inc. field personnel are certified on completion of a forty-hour Hazardous Materials and Emergency Response training course per 29 CFR 1910.120. Field personnel are also enrolled in annual eight-hour refresher courses.

Blaine Tech Services, Inc. conducts sampling and documentation assignments of this type as an independent third party. Our activities at this site consisted of objective data and sample collection only. No interpretation of analytical results, defining of hydrological conditions or formulation of recommendations was performed.

Please call if you have any questions.

Yours truly,

Leon Gearhart
Project Coordinator

LG/jt

attachments: Cumulative Table of WELL CONCENTRATIONS
Certified Analytical Report
Field Data Sheets

cc: Anni Kreml
Cambria Environmental Technology, Inc.
5900 Hollis Street, Suite A
Oakland, CA 94608

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
MW-1	07/12/1989	<50	<0.5	<1	<1	<3	NA	NA	37.96	2.76	35.20	NA
MW-1	01/30/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.10	34.86	NA
MW-1	04/27/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.24	34.72	NA
MW-1	07/31/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	4.26	33.70	NA
MW-1	10/30/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	4.25	33.71	NA
MW-1	01/31/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.66	34.30	NA
MW-1	04/30/1991	<50	0.8	<0.5	0.6	1.2	NA	NA	37.96	3.46	34.50	NA
MW-1	07/30/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	4.14	33.82	NA
MW-1	10/29/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.96	34.00	NA
MW-1	01/20/1992	<30	<0.3	<0.3	<0.3	<0.3	NA	NA	37.96	3.59	34.37	NA
MW-1	04/14/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.18	31.71	NA
MW-1	07/21/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	4.17	33.79	NA
MW-1	10/02/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	4.29	33.67	NA
MW-1	01/20/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	2.32	35.64	NA
MW-1	05/03/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.50	34.46	1.9
MW-1	06/28/1993	NA	NA	NA	NA	NA	NA	NA	37.96	3.76	34.20	NA
MW-1	07/21/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	4.09	33.87	4.6
MW-1	10/19/1993	50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.58	34.38	4.3
MW-1	01/20/1994	Well inaccessible		NA	NA	NA	NA	NA	37.96	NA	NA	NA
MW-1	04/12/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.60	34.36	7.5
MW-1	07/20/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	4.10	33.86	3.2
MW-1	10/06/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	4.30	33.66	3.2
MW-1	01/20/1995	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	2.94	35.02	10.6
MW-1	07/06/1995	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	3.68	34.28	NA
MW-1	01/24/1996	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	37.96	2.12	35.84	NA
MW-1	07/12/1996	<50	<0.5	<0.5	<0.5	<0.5	<2.5	NA	37.96	3.58	34.38	2.7

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
MW-1	01/16/1997	120	14	10	3.6	14	<2.5	NA	37.96	2.30	35.66	3
MW-1	10/24/1997	<50	<0.50	<0.50	<0.50	<0.50	8.6	NA	37.96	3.66	34.30	4.5
MW-1	05/13/1998	<50	<0.50	<0.50	<0.50	<0.50	<2.5	NA	37.96	2.81	35.15	5.1
MW-1	10/01/1998	<50	<0.50c	<0.50c	<0.50c	<0.50c	<2.5c	NA	37.96	3.75	34.21	5.0
MW-1	04/29/1999	<50	<0.50	<0.50	<0.50	<0.50	<2.5	NA	37.96	3.52	34.44	4.1
MW-1	11/01/1999	<50.0	<0.500	<0.500	<0.500	<0.500	5.03	NA	37.96	4.05	33.91	3.6
MW-1	04/05/2000	<50.0	<0.500	<0.500	<0.500	<0.500	3.22	NA	37.96	3.74	34.22	4.2
MW-1	10/30/2000	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50	NA	37.96	2.19	35.77	4.1
MW-1	04/27/2001	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50	NA	37.96	4.43	33.53	1.9
MW-1	10/31/2001	<50	<0.50	<0.50	<0.50	<0.50	NA	<5.0	37.96	4.34	33.62	2.4
MW-1	05/09/2002	Well inaccessible		NA	NA	NA	NA	NA	37.96	NA	NA	NA
MW-1	07/25/2002	<50	<0.50	<0.50	<0.50	<0.50	NA	<5.0	37.96	3.53	34.43	1.2
MW-1	10/23/2002	<50	<0.50	<0.50	<0.50	<0.50	NA	<0.50	40.94	3.68	37.26	3.5
MW-1	01/22/2003	Well inaccessible		NA	NA	NA	NA	NA	40.94	NA	NA	NA
MW-1	01/29/2003	<50	<0.50	<0.50	<0.50	<0.50	NA	<5.0	40.94	3.25	37.69	3.7
MW-2	07/12/1989	60	2.7	<1	<1	<3	NA	NA	34.89	3.66	31.23	NA
MW-2	01/30/1990	<50	6.6	<0.5	0.54	0.93	NA	NA	34.89	3.49	31.40	NA
MW-2	04/27/1990	60	2.1	<0.5	<0.5	<0.5	NA	NA	34.89	3.79	31.10	NA
MW-2	07/31/1990	70	1.5	<0.5	<0.5	<0.5	NA	NA	34.89	4.03	30.86	NA
MW-2	10/30/1990	70	<0.5	0.7	<0.5	1.6	NA	NA	34.89	4.21	30.68	NA
MW-2	01/31/1991	80	<0.5	<0.5	0.9	1.9	NA	NA	34.89	4.09	30.80	NA
MW-2	04/30/1991	100	5.9	0.6	0.7	2	NA	NA	34.89	3.95	30.94	NA
MW-2	07/30/1991	<50	<0.5	<0.7	<0.5	<0.5	NA	NA	34.89	4.07	30.82	NA
MW-2	10/29/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.89	4.11	30.78	NA
MW-2	01/20/1992	<30	0.84	<0.3	<0.41	<0.48	NA	NA	34.89	3.86	31.03	NA
MW-2	04/14/1992	70	16	<0.5	3.1	2.1	NA	NA	34.89	3.66	34.30	NA

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
MW-2	07/21/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.89	3.92	30.97	NA
MW-2	10/02/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.89	4.45	30.44	NA
MW-2	01/20/1993	<50	3.8	<0.5	0.52	<0.5	NA	NA	34.89	3.74	31.15	NA
MW-2	05/03/1993	680a	2.8	<0.5	<0.5	<0.5	NA	NA	34.89	3.77	31.12	0.9
MW-2	06/28/1993	NA	NA	NA	NA	NA	NA	NA	34.89	3.96	30.93	NA
MW-2	07/21/1993	<50	8	1.2	1.8	7.9	NA	NA	34.89	4.39	30.50	5.9
MW-2	10/19/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.89	3.92	30.97	5.7
MW-2	01/20/1994	<50	1.5	<0.5	<0.5	<0.5	NA	NA	34.89	4.45	30.44	3.2
MW-2	04/12/1994	<50	2.9	<0.5	<0.5	<0.5	NA	NA	34.89	4.72	30.17	11.4
MW-2	07/20/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.89	5.32	29.57	2.4
MW-2	10/06/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.89	4.03	30.86	2.9
MW-2	01/20/1995	290	28	<0.5	<0.5	<0.5	NA	NA	34.89	3.89	31.00	4.6
MW-2	07/06/1995	120	3	<0.5	<0.5	<0.5	NA	NA	34.89	8.84	26.05	NA
MW-2	01/24/1996	70	3.1	<0.5	0.8	1.5	NA	NA	34.89	3.80	31.09	NA
MW-2 (D)	01/24/1996	70	3.2	0.5	0.7	1.5	NA	NA	34.89	NA	NA	NA
MW-2	07/12/1996	<50	0.68	<0.5	<0.5	<0.5	270	NA	34.89	3.85	31.04	3.8
MW-2	01/16/1997	230	34	1.6	1.6	4.2	460	NA	34.89	3.84	31.05	NA
MW-2	10/24/1997	<50	<0.50	<0.50	<0.50	<0.50	54	NA	34.89	3.75	31.14	2.9
MW-2	05/13/1998	NA	NA	NA	NA	NA	NA	NA	34.89	3.78	31.11	NA
MW-2	10/01/1998	<50	<0.50c	<0.50c	<0.50c	<0.50c	100	NA	34.89	4.90	29.99	3.0
MW-2	04/29/1999	NA	NA	NA	NA	NA	NA	NA	34.89	4.69	30.20	NA
MW-2	11/01/1999	<50.0	<0.500	1.29	0.669	4.52	7.21	NA	34.89	5.24	29.65	2.9
MW-2	04/05/2000	376d	68.1d	3.10d	2.88d	5.35d	729d	NA	34.89	3.43	31.46	3.6
MW-2	10/30/2000	5,790	59.2	315	162	1320	346	NA	34.89	2.35	32.54	2.8
MW-2	04/27/2001	2,720	90.8	22.8	18.1	165	512	578	34.89	4.67	30.22	0.9
MW-2	10/31/2001	<10,000	<100	<100	<100	<100	NA	<100	34.89	3.68	31.21	1.3
MW-2	05/09/2002	490	1.5	7.8	2.1	14	NA	200	34.89	3.18	31.71	1.1

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
MW-2	07/25/2002	1,200	1.0	3.3	1.3	8.3	NA	45	34.89	3.30	31.59	0.4
MW-2	10/23/2002	1,100	0.85	3.8	1.3	7.9	NA	140	37.87	3.87	34.00	0.8
MW-2	01/22/2003	730	<0.50	100	0.96	5.4	NA	230	37.87	2.68	35.19	1.5
MW-3	07/12/1989	3,900	380	41	99	30	NA	NA	35.00	3.83	31.17	NA
MW-3	01/30/1990	5,500	440	35	79	130	NA	NA	35.00	3.24	31.76	NA
MW-3	04/27/1990	4,500	310	26	37	110	NA	NA	35.00	4.02	30.98	NA
MW-3	07/31/1990	3,500	210	17	8.4	62	NA	NA	35.00	4.31	30.69	NA
MW-3	10/30/1990	2,300	610	<0.5	<0.5	28	NA	NA	35.00	4.52	30.48	NA
MW-3	01/31/1991	4,100	300	20	19	81	NA	NA	35.00	4.33	30.67	NA
MW-3	04/30/1991	3,800	370	19	8.6	60	NA	NA	35.00	3.79	31.21	NA
MW-3	07/30/1991	3,300	160	13	15	87	NA	NA	35.00	4.37	30.63	NA
MW-3	10/29/1991	1,000	35	2.8	2.9	8.1	NA	NA	35.00	4.00	31.00	NA
MW-3	01/20/1992	6,900	380	18	47	48	NA	NA	35.00	3.87	31.13	NA
MW-3	04/14/1992	6,000	480	38	41	55	NA	NA	35.00	3.15	31.85	NA
MW-3	07/21/1992	3,700	330	13	30	23	NA	NA	35.00	4.17	30.83	NA
MW-3	10/02/1992	4,200	260	10	13	12	NA	NA	35.00	4.43	30.57	NA
MW-3	01/20/1993	4,200	360	15	32	26	NA	NA	35.00	2.20	32.80	NA
MW-3 (D)	01/20/1993	3,900	370	15	32	26	NA	NA	35.00	NA	NA	NA
MW-3	05/03/1993	12,000	290	520	120	620	NA	NA	35.00	3.50	31.50	0.6
MW-3	06/28/1993	NA	NA	NA	NA	NA	NA	NA	35.00	4.08	30.92	NA
MW-3	07/21/1993	2,000	170	12	<10	11	NA	NA	35.00	4.12	30.88	4.3
MW-3 (D)	07/21/1993	2,000	170	10	<10	14	NA	NA	35.00	NA	NA	NA
MW-3	10/19/1993	2,000	240	<0.5	<0.5	<0.5	NA	NA	35.00	4.20	30.80	5.7
MW-3	01/20/1994	4,200	280	<10	<10	<10	NA	NA	35.00	4.08	30.92	4.1
MW-3 (D)	01/20/1994	3,800	250	<10	<10	<10	NA	NA	35.00	NA	NA	4.1
MW-3	04/12/1994	4,700	380	<10	<10	<10	NA	NA	35.00	3.70	31.30	10.6

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
MW-3 (D)	04/12/1994	3,400	370	<25	<25	<25	NA	NA	35.00	NA	NA	NA
MW-3	07/20/1994	5,100	320	77	15	34	NA	NA	35.00	4.26	30.74	2.3
MW-3 (D)	07/20/1994	4,400	250	14	13	32	NA	NA	35.00	NA	NA	NA
MW-3	10/06/1994	4,300	280	9.7	4	15	NA	NA	35.00	4.31	30.69	2.3
MW-3	01/20/1995	4,600	180	18	16	10	NA	NA	35.00	3.00	32.00	11.1
MW-3 (D)	01/20/1995	4,300	170	12	15	7.2	NA	NA	35.00	NA	NA	NA
MW-3	07/06/1995	3,900	310	<0.5	7.6	13	NA	NA	35.00	3.75	31.25	NA
MW-3 (D)	07/06/1995	4,100	330	<0.5	7.9	2.4	NA	NA	35.00	NA	NA	NA
MW-3	01/24/1996	5,000	210	14	14	12	NA	NA	35.00	3.26	31.74	NA
MW-3	07/12/1996	2,700	210	<0.5	<0.5	<0.5	3,600	NA	35.00	3.77	31.23	2.4
MW-3 (D)	07/12/1996	2,800	210	<0.5	<0.5	<0.5	3,400	NA	35.00	NA	NA	2.4
MW-3	01/16/1997	4,200	130	19	10	34	4,400	4,600	35.00	2.38	32.62	2.3
MW-3	10/24/1997	4,100	270	9	5.1	8.8	2,000	NA	35.00	4.12	30.88	1.9
MW-3 (D)	10/24/1997	1,700	220	<5.0	<5.0	<5.0	1,500	NA	35.00	NA	NA	1.9
MW-3	05/13/1998	NA	NA	NA	NA	NA	NA	NA	35.00	3.22	31.78	NA
MW-3	10/01/1998	1,400	84c	<5.0c	<5.0c	<5.0c	2,300	NA	35.00	4.15	30.85	2.0
MW-3 (D)	10/01/1998	2,100	100c	<10c	<10c	<10c	2,600	NA	35.00	NA	NA	2.0
MW-3	04/29/1999	NA	NA	NA	NA	NA	NA	NA	35.00	4.27	30.73	NA
MW-3	11/01/1999	1,850	94.3	6.09	<5.00	6.67	4,140	NA	35.00	4.65	30.35	2.2
MW-3	04/05/2000	3,070	96.9	12.1	<10.0	<10.0	1,050	NA	35.00	3.50	31.50	2.7
MW-3	10/30/2000	1,570	56.8	1.91	1.39	3.06	572	524	35.00	3.40	31.60	3.1
MW-3	04/27/2001	2,420	103	12.6	<5.00	15.6	314	NA	35.00	3.67	31.33	0.9
MW-3	10/31/2001	<50	0.71	<0.50	<0.50	<0.50	NA	31	35.00	3.79	31.21	1.6
MW-3	05/09/2002	2,000	52	<10	<10	<10	NA	4,100	35.00	3.76	31.24	0.9
MW-3	07/25/2002	1,800	50	<5.0	<5.0	<5.0	NA	1,900	35.00	4.17	30.83	3.7
MW-3	10/23/2002	1,700	27	<5.0	<5.0	<5.0	NA	1,400	37.97	4.36	33.61	1.6
MW-3	01/22/2003	1,800	38	2.4	1.5	2.4	NA	390	37.97	3.09	34.88	1.3

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
MW-4	01/30/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.50	29.23	NA
MW-4	04/27/1990	130a	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.62	30.11	NA
MW-4	07/31/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.19	29.54	NA
MW-4	10/30/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.19	29.54	NA
MW-4	01/31/1991	50a	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.49	29.24	NA
MW-4	04/30/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.02	29.71	NA
MW-4	07/30/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.39	29.34	NA
MW-4	10/29/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.75	29.98	NA
MW-4	01/20/1992	<30	<0.3	<0.3	<0.3	<0.3	NA	NA	33.73	3.94	29.79	NA
MW-4	04/14/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.71	30.02	NA
MW-4	07/21/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.02	29.71	NA
MW-4	10/02/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.13	29.60	NA
MW-4	01/20/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.10	30.63	NA
MW-4	05/03/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.70	30.03	1.7
MW-4	06/28/1993	NA	NA	NA	NA	NA	NA	NA	33.73	3.81	29.92	NA
MW-4	07/21/1993	<50	0.56	<0.5	<0.5	<0.5	NA	NA	33.73	3.81	29.92	4.5
MW-4	10/19/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.94	29.79	5.8
MW-4	01/20/1994	<50	0.71	<0.5	<0.5	<0.5	NA	NA	33.73	4.00	29.73	4.4
MW-4	04/12/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	4.01	29.72	7.3
MW-4	07/20/1994	160	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.91	29.82	6.4
MW-4	10/06/1994	410	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.99	29.74	5.0
MW-4	01/20/1995	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.56	30.17	4.9
MW-4	07/06/1995	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	33.73	3.85	29.88	NA
MW-4	01/24/1996	<50	<0.5	<0.5	0.6	1.8	NA	NA	33.73	2.56	31.17	NA
MW-4	07/12/1996	<50	<0.5	<0.5	<0.5	<0.5	b	NA	33.73	3.36	30.37	2.7
MW-4	01/16/1997	Well inaccessible		NA	NA	NA	NA	NA	33.73	NA	NA	NA

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
MW-4	10/24/1997	Well inaccessible		NA	NA	NA	NA	NA	33.73	NA	NA	NA
MW-4	05/13/1998	Well inaccessible		NA	NA	NA	NA	NA	33.73	NA	NA	NA
MW-4	10/01/1998	<50	<0.50c	<0.50c	<0.50c	0.74c	8.1	NA	33.73	3.90	29.83	2.5
MW-4	04/29/1999	<50	<0.50	<0.50	<0.50	<0.50	5.7	NA	33.73	3.97	29.76	2.1
MW-4	11/01/1999	Well inaccessible		NA	NA	NA	NA	NA	33.73	NA	NA	NA
MW-4	04/05/2000	<50.0	<0.500	<0.500	<0.500	<0.500	3.64	NA	33.73	3.63	30.10	2.1
MW-4	10/30/2000	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50	NA	33.73	3.33	30.40	3.0
MW-4	04/27/2001	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50	NA	33.73	3.48	30.25	2.2
MW-4	10/31/2001	<50	<0.50	<0.50	<0.50	<0.50	NA	<5.0	33.73	3.58	30.15	2.8
MW-4	05/09/2002	<50	<0.50	<0.50	<0.50	<0.50	NA	<5.0	33.73	3.74	29.99	2.0
MW-4	07/25/2002	<50	<0.50	<0.50	<0.50	<0.50	NA	<5.0	33.73	3.71	30.02	1.3
MW-4	10/23/2002	<50	<0.50	<0.50	<0.50	<0.50	NA	<0.50	36.72	3.93	32.79	2.6
MW-4	01/22/2003	<50	<0.50	<0.50	<0.50	<0.50	NA	<5.0	36.72	3.67	33.05	3.1
MW-5	01/30/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	7.12	24.26	NA
MW-5	04/27/1990	210a	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.19	27.19	NA
MW-5	07/31/1990	90	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.09	27.29	NA
MW-5	10/30/1990	100	0.8	0.7	0.6	1.4	NA	NA	31.38	4.39	26.99	NA
MW-5	01/31/1991	80a	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.49	26.89	NA
MW-5	04/30/1991	90	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.27	27.11	NA
MW-5	07/30/1991	90	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.32	27.06	NA
MW-5	10/29/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	3.79	27.59	NA
MW-5	01/20/1992	<30	<0.3	<0.3	<0.3	<0.3	NA	NA	31.38	4.09	27.29	NA
MW-5	04/14/1992	<50a	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.12	27.26	NA
MW-5	07/21/1992	74a	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.13	27.25	NA
MW-5	10/02/1992	76a	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.30	27.08	NA
MW-5	01/20/1993	72a	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	3.12	28.26	NA

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
MW-5	05/03/1993	70a	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.07	27.31	1.6
MW-5 (D)	05/04/1993	80a	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	NA	NA	NA
MW-5	06/28/1993	NA	NA	NA	NA	NA	NA	NA	31.38	4.08	27.30	NA
MW-5	07/21/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.05	27.33	3.5
MW-5	10/19/1993	51	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.20	27.18	3.8
MW-5	01/20/1994	90	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.40	26.98	4.2
MW-5	04/12/1994	67	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.18	27.20	NA
MW-5	07/20/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.06	27.32	3.2
MW-5	10/06/1994	80	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.01	27.37	2.1
MW-5 (D)	10/06/1994	60	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	NA	NA	NA
MW-5	01/20/1995	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	3.49	27.89	3.2
MW-5	07/06/1995	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	31.38	4.06	27.32	NA
MW-5	01/24/1996	70	<0.5	<0.5	0.8	2.9	NA	NA	31.38	2.90	28.48	NA
MW-5	07/12/1996	62	<0.5	<0.5	<0.5	<0.5	b	NA	31.38	4.02	27.36	1.9
MW-5	01/16/1997	66	0.91	0.89	<0.50	1.7	<2.5	NA	31.38	2.59	28.79	2.2
MW-5 (D)	01/16/1997	<50	0.7	0.78	<0.50	1.3	<2.5	NA	31.38	NA	NA	2.2
MW-5	10/24/1997	59	<0.50	<0.50	<0.50	<0.50	17	NA	31.38	4.15	27.23	4.6
MW-5	05/13/1998	72	<0.50	<0.50	<0.50	<0.50	<2.5	NA	31.38	3.64	27.74	2.1
MW-5 (D)	05/13/1998	70	<0.50	<0.50	<0.50	<0.50	<2.5	NA	31.38	NA	NA	2.1
MW-5	10/01/1998	57	<0.50c	<0.50c	<0.50c	0.62c	20	NA	31.38	4.25	27.13	2.2
MW-5	04/29/1999	<50	<0.50	<0.50	<0.50	<0.50	16	NA	31.38	4.56	26.82	2.0
MW-5	11/01/1999	<50.0	<0.500	<0.500	<0.500	<0.500	3.06	NA	31.38	4.19	27.19	2.2
MW-5	04/05/2000	<50.0	<0.500	<0.500	<0.500	<0.500	22.5	NA	31.38	4.34	27.04	2.2
MW-5	10/30/2000	<50.0	<0.500	<0.500	<0.500	<0.500	19.3	NA	31.38	3.25	28.13	4.0
MW-5	04/27/2001	51.5	<0.500	<0.500	<0.500	<0.500	4.29	NA	31.38	4.07	27.31	1.0
MW-5	10/31/2001	210	<0.50	<0.50	<0.50	<0.50	NA	<5.0	31.38	4.02	27.36	1.5
MW-5	05/09/2002	280	0.71	<0.50	<0.50	<0.50	NA	<5.0	31.38	4.31	27.07	1.7

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
---------	------	----------------	-------------	-------------	-------------	-------------	------------------------	------------------------	--------------	----------------------------	--------------------------	------------------------

MW-5	07/25/2002	410	<0.50	<0.50	<0.50	<0.50	NA	<5.0	31.38	4.32	27.06	0.7
MW-5	10/23/2002	290	<0.50	<0.50	<0.50	<0.50	NA	<0.50	34.36	4.37	29.99	2.3
MW-5	01/22/2003	260	<0.50	<0.50	<0.50	<0.50	NA	<5.0	34.36	4.12	30.24	2.4

E-4	07/12/1989	<50	<0.5	<1	<1	<3	NA	NA	34.63	NA	>39.13	NA
E-4	01/30/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	04/27/1990	120a	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	07/31/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	10/30/1990	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	01/31/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	04/30/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	07/30/1991	<50	<0.5	0.6	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	10/29/1991	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	01/20/1992	<30	<0.3	<0.3	<0.3	<0.3	NA	NA	34.63	NA	>34.63	NA
E-4	04/14/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	07/21/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	10/02/1992	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	01/20/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	05/03/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	0.6
E-4	06/28/1993	NA	NA	NA	NA	NA	NA	NA	34.63	NA	>34.63	NA
E-4	07/21/1993	<50	5.4	0.72	1	4.4	NA	NA	34.63	NA	>34.63	5.4
E-4	10/19/1993	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	5.6
E-4	01/20/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	NA
E-4	04/12/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	9.4
E-4	07/20/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	2.0
E-4	10/06/1994	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	1.3
E-4	01/20/1995	<50	<0.5	<0.5	<0.5	<0.5	NA	NA	34.63	NA	>34.63	3.7

WELL CONCENTRATIONS
Shell-branded Service Station
29 Wildwood Avenue
Piedmont, CA

Well ID	Date	TPPH (ug/L)	B (ug/L)	T (ug/L)	E (ug/L)	X (ug/L)	MTBE 8020 (ug/L)	MTBE 8260 (ug/L)	TOC (MSL)	Depth to Water (ft.)	GW Elevation (MSL)	DO Reading (ppm)
E-4	05/16/1995	Well abandoned		NA	NA	NA	NA	NA	NA	NA	NA	NA

Abbreviations:

TPPH = Total petroleum hydrocarbons as gasoline by EPA Method 8260B; prior to October 31, 2001, analyzed by EPA Method 8015.

BTEX = Benzene, toluene, ethylbenzene, xylenes by EPA Method 8260B; prior to October 31, 2001, analyzed by EPA Method 8020.

MTBE = Methyl-tertiary-butyl ether

TOC = Top of Casing Elevation

SPH = Separate-Phase Hydrocarbons

GW = Groundwater

DO = Dissolved Oxygen

ug/L = Parts per billion

ppm = Parts per million

MSL = Mean sea level

ft = Feet

<n = Below detection limit

D = Duplicate sample

NA = Not applicable

Notes:

a = Chromatogram pattern indicated an unidentified hydrocarbon.

b = Due to coelution with early eluters, no result could be determined for MTBE

c = Laboratory reported 1.3 ug/L benzene, 11 ug/L toluene, 0.98 ug/L ethyl benzene, and 6.5 ug/L total xylenes in the equipment blank.

d = Result reported was generated out of hold time.

Well E-4 is a flowing artesian well; potentiometric surface above top-of-casing elevation.

Site surveyed March 5, 2002, by Virgil Chavez Land Surveying of Vallejo, California.



Report Number : 31191

Date : 2/5/03

Leon Gearhart
Blaine Tech Services
1680 Rogers Avenue
San Jose, CA 95112-1105

Subject : 1 Water Sample
Project Name : 29 Wildwood Avenue, Piedmont
Project Number : 030129-BA3
P.O. Number : 98995822

Dear Mr. Gearhart,

Chemical analysis of the samples referenced above has been completed. Summaries of the data are contained on the following pages. Sample(s) were received under documented chain-of-custody. US EPA protocols for sample storage and preservation were followed.

Kiff Analytical is certified by the State of California (# 2236). If you have any questions regarding procedures or results, please call me at 530-297-4800.

Sincerely,

A handwritten signature in black ink that reads "Joel Kiff". The signature is written in a cursive style with a large initial "J".

Joel Kiff



Report Number : 31191

Date : 2/5/03

Project Name : 29 Wildwood Avenue, Piedmont

Project Number : 030129-BA3


Sample : MW-1

Matrix : Water

Lab Number : 31191-01

Sample Date :1/29/03

Parameter	Measured Value	Method Reporting Limit	Units	Analysis Method	Date Analyzed
Benzene	< 0.50	0.50	ug/L	EPA 8260B	1/31/03
Toluene	< 0.50	0.50	ug/L	EPA 8260B	1/31/03
Ethylbenzene	< 0.50	0.50	ug/L	EPA 8260B	1/31/03
Total Xylenes	< 0.50	0.50	ug/L	EPA 8260B	1/31/03
Methyl-t-butyl ether (MTBE)	< 5.0	5.0	ug/L	EPA 8260B	1/31/03
TPH as Gasoline	< 50	50	ug/L	EPA 8260B	1/31/03
Toluene - d8 (Surr)	102		% Recovery	EPA 8260B	1/31/03
4-Bromofluorobenzene (Surr)	91.7		% Recovery	EPA 8260B	1/31/03

Approved By:  Joel Kiff

Report Number : 31191

Date : 2/5/03

QC Report : Method Blank Data

Project Name : **29 Wildwood Avenue, Piedmont**

Project Number : **030129-BA3**

<u>Parameter</u>	<u>Measured Value</u>	<u>Method Reporting Limit</u>	<u>Units</u>	<u>Analysis Method</u>	<u>Date Analyzed</u>
Benzene	< 0.50	0.50	ug/L	EPA 8260B	1/30/03
Toluene	< 0.50	0.50	ug/L	EPA 8260B	1/30/03
Ethylbenzene	< 0.50	0.50	ug/L	EPA 8260B	1/30/03
Total Xylenes	< 0.50	0.50	ug/L	EPA 8260B	1/30/03
Methyl-t-butyl ether (MTBE)	< 5.0	5.0	ug/L	EPA 8260B	1/30/03
TPH as Gasoline	< 50	50	ug/L	EPA 8260B	1/30/03
Toluene - dB (Surr)	102		%	EPA 8260B	1/30/03
4-Bromofluorobenzene (Surr)	90.9		%	EPA 8260B	1/30/03

<u>Parameter</u>	<u>Measured Value</u>	<u>Method Reporting Limit</u>	<u>Units</u>	<u>Analysis Method</u>	<u>Date Analyzed</u>
------------------	-----------------------	-------------------------------	--------------	------------------------	----------------------

KIFF ANALYTICAL, LLC

2795 2nd St. Suite 300 Davis. CA 95616 530-297-4800

Approved By: Joel Kiff



QC Report : Matrix Spike/ Matrix Spike Duplicate

Project Name : **29 Wildwood Avenue,**Project Number : **030129-BA3**

Parameter	Spiked Sample	Sample Value	Spike Level	Spike Dup. Level	Spiked Sample Value	Duplicate Spiked Sample Value	Units	Analysis Method	Date Analyzed	Spiked Sample Percent Recov.	Duplicate Spiked Sample Percent Recov.	Relative Percent Diff.	Spiked Sample Percent Recov. Limit	Relative Percent Diff. Limit
Benzene	31175-19	<0.50	40.0	40.0	39.3	36.9	ug/L	EPA 8260B	1/30/03	98.3	92.3	6.32	70-130	25
Toluene	31175-19	<0.50	40.0	40.0	37.8	40.4	ug/L	EPA 8260B	1/30/03	94.4	101	6.76	70-130	25
Tert-Butanol	31175-19	<5.0	200	200	183	196	ug/L	EPA 8260B	1/30/03	91.7	98.2	6.84	70-130	25
Methyl-t-Butyl Ether	31175-19	<0.50	40.0	40.0	37.7	37.1	ug/L	EPA 8260B	1/30/03	94.2	92.8	1.58	70-130	25

KIFF ANALYTICAL, LLC

2795 2nd St, Suite 300 Davis, CA 95616 530-297-4800

Approved By:  Joel Kiff

QC Report : Laboratory Control Sample (LCS)

Project Name : 29 Wildwood Avenue,

Project Number : 030129-BA3

Parameter	Spike Level	Units	Analysis Method	Date Analyzed	LCS Percent Recov.	LCS Percent Recov. Limit
Benzene	40.0	ug/L	EPA 8260B	1/30/03	93.6	70-130
Toluene	40.0	ug/L	EPA 8260B	1/30/03	107	70-130
Tert-Butanol	200	ug/L	EPA 8260B	1/30/03	95.8	70-130
Methyl-t-Butyl Ether	40.0	ug/L	EPA 8260B	1/30/03	90.9	70-130

KIFF ANALYTICAL, LLC

Approved By: 
Joel Kiff

SHELL Chain Of Custody Record

Lab Identification (if necessary):

Address:

City, State, Zip:

Shell Project Manager to be Invoiced:

Karen Petryna

SCIENCE & ENGINEERING

TECHNICAL SERVICES

CRMT HOUSTON

INCIDENT NUMBER (SEE ONLY)

9 8 9 9 5 8 2 2

SAP or CRMT NUMBER (TS/CRMT)




31191

DATE: 1/29/03

PAGE: 1 of 1

SAMPLING COMPANY Blaine Tech Services		LOG CODE: BTSS	SITE ADDRESS (Street and City): 29 Wildwood Avenue, Piedmont		GLOBAL ID NO.: T0600101246
ADDRESS: 1680 Rogers Avenue, San Jose, CA 95112		EDF DELIVERABLE TO (Responsible Party or Designee): Anni Kremi	PHONE NO.: 510-420-3335	E-MAIL: ShellOaklandEDF@cambria-env.com	CONSULTANT PROJECT NO.: 030129-BA3
PROJECT CONTACT (Hardcopy or PDF Report to): Leon Gearhart		SAMPLER NAME(S) (Print): Brian Alcorn		LAB USE ONLY	
TELEPHONE: 408-573-0555	FAX: 408-573-7771	E-MAIL: lgearhart@blainetech.com			
TURNAROUND TIME (BUSINESS DAYS): <input checked="" type="checkbox"/> 10 DAYS <input type="checkbox"/> 5 DAYS <input type="checkbox"/> 72 HOURS <input type="checkbox"/> 48 HOURS <input type="checkbox"/> 24 HOURS <input type="checkbox"/> LESS THAN 24 HOURS		REQUESTED ANALYSIS			
<input type="checkbox"/> LA - RWQCB REPORT FORMAT <input type="checkbox"/> UST AGENCY:					
GC/MS MTBE CONFIRMATION: HIGHEST _____ HIGHEST per BORING _____ ALL _____		FIELD NOTES: Container/Preservative or PID Readings or Laboratory Notes			
SPECIAL INSTRUCTIONS OR NOTES: CHECK BOX IF EDD IS NOT NEEDED <input type="checkbox"/>					

LAB USE ONLY	Field Sample Identification	SAMPLING		MATRIX	NO. OF CONT.	TPH - Gas, Purgeable	BTEX	MTBE (8021B - 5ppb RL)	MTBE (8260B - 0.5ppb RL)	Oxygenates (5) by (8260B)	Ethanol (8260B)	Methanol	1,2-DCA (8260B)	EDB (8260B)	TPH - Diesel, Extractable (8015m)	TEMPERATURE ON RECEIPT °C
		DATE	TIME													
	MW-1	1/29	1520	W	3	X	X	X								-01

Relinquished by: (Signature) 	Received by: (Signature) 	Date:	Time:
Relinquished by: (Signature)	Received by: (Signature)	Date:	Time:
Relinquished by: (Signature)	Received by: (Signature) 	Date: 013003	Time: 1118



Report Number : 31073

Date : 1/28/2003

Leon Gearhart
Blaine Tech Services
1680 Rogers Avenue
San Jose, CA 95112-1105

Subject : 4 Water Samples
Project Name : 29 Wildwood Avenue, Piedmont
Project Number : 030122-DW-2
P.O. Number : 98995822

Dear Mr. Gearhart,

Chemical analysis of the samples referenced above has been completed. Summaries of the data are contained on the following pages. Sample(s) were received under documented chain-of-custody. US EPA protocols for sample storage and preservation were followed.

Kiff Analytical is certified by the State of California (# 2236). If you have any questions regarding procedures or results, please call me at 530-297-4800.

Sincerely,

A handwritten signature in black ink that reads "Joel Kiff". The signature is stylized with a large, looped initial "J".

Joel Kiff



Report Number : 31073

Date : 1/28/2003

Subject : 4 Water Samples
Project Name : 29 Wildwood Avenue, Piedmont
Project Number : 030122-DW-2
P.O. Number : 98995822

Case Narrative

Hydrocarbons reported as TPH as Gasoline do not exhibit a typical Gasoline chromatographic pattern for sample MW-5.

Approved By:  _____
Joel Kiff

2795 2nd St, Suite 300 Davis, CA 95616 530-297-4800



Report Number : 31073

Date : 1/28/2003

Project Name : 29 Wildwood Avenue, Piedmont

Project Number : 030122-DW-2

Sample : MW-2

Matrix : Water

Lab Number : 31073-01

Sample Date :1/22/2003

Parameter	Measured Value	Method Reporting Limit	Units	Analysis Method	Date Analyzed
Benzene	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Toluene	100	0.50	ug/L	EPA 8260B	1/24/2003
Ethylbenzene	0.96	0.50	ug/L	EPA 8260B	1/24/2003
Total Xylenes	5.4	0.50	ug/L	EPA 8260B	1/24/2003
Methyl-t-butyl ether (MTBE)	230	5.0	ug/L	EPA 8260B	1/24/2003
TPH as Gasoline	730	50	ug/L	EPA 8260B	1/24/2003
Toluene - d8 (Surr)	107		% Recovery	EPA 8260B	1/24/2003
4-Bromofluorobenzene (Surr)	98.9		% Recovery	EPA 8260B	1/24/2003

Sample : MW-3

Matrix : Water

Lab Number : 31073-02

Sample Date :1/22/2003

Parameter	Measured Value	Method Reporting Limit	Units	Analysis Method	Date Analyzed
Benzene	38	1.0	ug/L	EPA 8260B	1/25/2003
Toluene	2.4	1.0	ug/L	EPA 8260B	1/25/2003
Ethylbenzene	1.5	1.0	ug/L	EPA 8260B	1/25/2003
Total Xylenes	2.4	1.0	ug/L	EPA 8260B	1/25/2003
Methyl-t-butyl ether (MTBE)	390	10	ug/L	EPA 8260B	1/25/2003
TPH as Gasoline	1800	100	ug/L	EPA 8260B	1/25/2003
Toluene - d8 (Surr)	96.3		% Recovery	EPA 8260B	1/25/2003
4-Bromofluorobenzene (Surr)	98.3		% Recovery	EPA 8260B	1/25/2003

Approved By:  Joel Kiff



Report Number : 31073

Date : 1/28/2003

Project Name : 29 Wildwood Avenue, Piedmont

Project Number : 030122-DW-2

Sample : MW-4

Matrix : Water

Lab Number : 31073-03

Sample Date :1/22/2003

Parameter	Measured Value	Method Reporting Limit	Units	Analysis Method	Date Analyzed
Benzene	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Toluene	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Ethylbenzene	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Total Xylenes	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Methyl-t-butyl ether (MTBE)	< 5.0	5.0	ug/L	EPA 8260B	1/24/2003
TPH as Gasoline	< 50	50	ug/L	EPA 8260B	1/24/2003
Toluene - d8 (Surr)	97.5		% Recovery	EPA 8260B	1/24/2003
4-Bromofluorobenzene (Surr)	95.1		% Recovery	EPA 8260B	1/24/2003

Sample : MW-5

Matrix : Water

Lab Number : 31073-04

Sample Date :1/22/2003

Parameter	Measured Value	Method Reporting Limit	Units	Analysis Method	Date Analyzed
Benzene	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Toluene	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Ethylbenzene	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Total Xylenes	< 0.50	0.50	ug/L	EPA 8260B	1/24/2003
Methyl-t-butyl ether (MTBE)	< 5.0	5.0	ug/L	EPA 8260B	1/24/2003
TPH as Gasoline	260	50	ug/L	EPA 8260B	1/24/2003
Toluene - d8 (Surr)	97.9		% Recovery	EPA 8260B	1/24/2003
4-Bromofluorobenzene (Surr)	91.8		% Recovery	EPA 8260B	1/24/2003

Approved By:  Joel Kiff

Report Number : 31073

Date : 1/28/2003

QC Report : Method Blank Data

Project Name : 29 Wildwood Avenue, Piedmont

Project Number : 030122-DW-2

Parameter	Measured Value	Method Reporting Limit	Units	Analysis Method	Date Analyzed
Benzene	< 0.50	0.50	ug/L	EPA 8260B	1/25/2003
Toluene	< 0.50	0.50	ug/L	EPA 8260B	1/25/2003
Ethylbenzene	< 0.50	0.50	ug/L	EPA 8260B	1/25/2003
Total Xylenes	< 0.50	0.50	ug/L	EPA 8260B	1/25/2003
Methyl-t-butyl ether (MTBE)	< 5.0	5.0	ug/L	EPA 8260B	1/25/2003
TPH as Gasoline	< 50	50	ug/L	EPA 8260B	1/25/2003
Toluene - d8 (Surr)	107		%	EPA 8260B	1/25/2003
4-Bromofluorobenzene (Surr)	86.8		%	EPA 8260B	1/25/2003

Benzene	< 0.50	0.50	ug/L	EPA 8260B	1/23/2003
Toluene	< 0.50	0.50	ug/L	EPA 8260B	1/23/2003
Ethylbenzene	< 0.50	0.50	ug/L	EPA 8260B	1/23/2003
Total Xylenes	< 0.50	0.50	ug/L	EPA 8260B	1/23/2003
Methyl-t-butyl ether (MTBE)	< 5.0	5.0	ug/L	EPA 8260B	1/23/2003
TPH as Gasoline	< 50	50	ug/L	EPA 8260B	1/23/2003
Toluene - d8 (Surr)	96.8		%	EPA 8260B	1/23/2003
4-Bromofluorobenzene (Surr)	94.5		%	EPA 8260B	1/23/2003

Parameter	Measured Value	Method Reporting Limit	Units	Analysis Method	Date Analyzed
-----------	----------------	------------------------	-------	-----------------	---------------

Approved By:  Joel Kiff

QC Report: Matrix Spike/ Matrix Spike Duplicate

Project Name: 29 Wildwood Avenue,

Project Number: 030122-DW-2

Parameter	Spiked Sample	Sample Value	Spike Level	Spike Dup. Level	Spiked Sample Value	Duplicate Spiked Sample Value	Units	Analysis Method	Date Analyzed	Spiked Sample Percent Recov.	Duplicate Spiked Sample Percent Recov.	Relative Percent Diff.	Spiked Sample Recov. Limit	Relative Percent Diff. Limit
Benzene	31069-01	<0.50	39.9	40.0	35.5	35.1	ug/L	EPA 8260B	1/25/03	89.0	87.7	1.50	70-130	25
Toluene	31069-01	<0.50	39.9	40.0	37.1	36.2	ug/L	EPA 8260B	1/25/03	92.9	90.6	2.51	70-130	25
Tert-Butanol	31069-01	<5.0	200	200	182	179	ug/L	EPA 8260B	1/25/03	91.1	89.5	1.82	70-130	25
Methyl-t-Butyl Ether	31069-01	<0.50	39.9	40.0	39.1	38.8	ug/L	EPA 8260B	1/25/03	97.8	97.0	0.924	70-130	25
Benzene	31039-03	<0.50	40.0	40.0	40.6	40.4	ug/L	EPA 8260B	1/23/03	101	101	0.593	70-130	25
Toluene	31039-03	<0.50	40.0	40.0	40.2	39.7	ug/L	EPA 8260B	1/23/03	100	99.2	1.23	70-130	25
Tert-Butanol	31039-03	<5.0	200	200	211	205	ug/L	EPA 8260B	1/23/03	105	102	2.79	70-130	25
Methyl-t-Butyl Ether	31039-03	<0.50	40.0	40.0	36.9	37.6	ug/L	EPA 8260B	1/23/03	92.2	94.0	1.90	70-130	25

Approved By:  Joel Kiff

KIFF ANALYTICAL, LLC

2795 2nd St, Suite 300 Davis, CA 95616 530-297-4800

QC Report : Laboratory Control Sample (LCS)

Project Name : 29 Wildwood Avenue,

Project Number : 030122-DW-2

Parameter	Spike Level	Units	Analysis Method	Date Analyzed	LCS Percent Recov.	LCS Percent Recov. Limit
Benzene	20.0	ug/L	EPA 8260B	1/25/03	108	70-130
Toluene	20.0	ug/L	EPA 8260B	1/25/03	98.6	70-130
Tert-Butanol	100	ug/L	EPA 8260B	1/25/03	98.3	70-130
Methyl-t-Butyl Ether	20.0	ug/L	EPA 8260B	1/25/03	90.8	70-130
Benzene	40.0	ug/L	EPA 8260B	1/23/03	101	70-130
Toluene	40.0	ug/L	EPA 8260B	1/23/03	100	70-130
Tert-Butanol	200	ug/L	EPA 8260B	1/23/03	102	70-130
Methyl-t-Butyl Ether	40.0	ug/L	EPA 8260B	1/23/03	92.6	70-130

KIFF ANALYTICAL, LLC

Approved By: 
Joel Kiff

SHELL CHAIN OF CUSTODY RECORD

Lab Identification (if necessary):

Address:

City, State, Zip:

Shell Project Manager to be Invoiced:

- SCIENCE & ENGINEERING
- TECHNICAL SERVICES
- CRMT HOUSTON

Karen Petryna

31073

INCIDENT NUMBER (S&E ONLY)

9 8 9 9 5 8 2 2

SAP or CRMT NUMBER (TS/CRMT)

DATE: 1-22-03

PAGE: 1 of 1

SAMPLING COMPANY Blaine Tech Services		LOG CODE: BTSS	SITE ADDRESS (Street and City): 29 Wildwood Avenue, Piedmont		GLOBAL ID NO.: T0600101246
ADDRESS: 1680 Rogers Avenue, San Jose, CA 95112		EDF DELIVERABLE TO (Responsible Party or Designee): Anni Kreaml		PHONE NO.: 510-420-3335	E-MAIL: ShellOaklandEDF@cambria-env.com
PROJECT CONTACT (Hardcopy or PDF Report to): Leon Gearhart		SAMPLER NAME(S) (Print): Dave Walter		CONSULTANT PROJECT NO.: 030122-042	
TELEPHONE: 408-573-0555	FAX: 408-573-7771	E-MAIL: lgearhart@blainetech.com		LAB USE ONLY	

TURNAROUND TIME (BUSINESS DAYS):
 10 DAYS
 5 DAYS
 72 HOURS
 48 HOURS
 24 HOURS
 LESS THAN 24 HOURS

LA - RWQCB REPORT FORMAT
 UST AGENCY: _____

GC/MS MTBE CONFIRMATION: HIGHEST _____ HIGHEST per BORING _____ ALL _____

SPECIAL INSTRUCTIONS OR NOTES: _____ CHECK BOX IF EDD IS NOT NEEDED

REQUESTED ANALYSIS

LAB USE ONLY	Field Sample Identification	SAMPLING DATE	SAMPLING TIME	MATRIX	NO. OF CONT.	TPH - Gas, Purgeable	BTEX	MTBE (#021B - 5ppb RL)	MTBE (#260B - 0.5ppb RL)	Oxygenates (#) by (#260B)	Ethanol (#260B)	Methanol	1,2-DCA (#260B)	EDB (#260B)	TPH - Diesel, Extractable (#015m)	FIELD NOTES: Container/Preservative or PID Readings or Laboratory Notes
	MW-2	1-22	15:03	W	3	X	X	X								-01
	MW-3		15:14			X	X	X								-02
	MW-4		14:30			X	X	X								-03
	MW-5		14:50			X	X	X								-04

LAB USE ONLY	Field Sample Identification	SAMPLING DATE	SAMPLING TIME	MATRIX	NO. OF CONT.	TPH - Gas, Purgeable	BTEX	MTBE (#021B - 5ppb RL)	MTBE (#260B - 0.5ppb RL)	Oxygenates (#) by (#260B)	Ethanol (#260B)	Methanol	1,2-DCA (#260B)	EDB (#260B)	TPH - Diesel, Extractable (#015m)	TEMPERATURE ON RECEIPT C°
	MW-2	1-22	15:03	W	3	X	X	X								-01
	MW-3		15:14			X	X	X								-02
	MW-4		14:30			X	X	X								-03
	MW-5		14:50			X	X	X								-04

Retinquished by: (Signature) <i>David C. Hall</i>	Received by: (Signature) _____	Date: _____	Time: _____
Retinquished by: (Signature) _____	Received by: (Signature) _____	Date: _____	Time: _____
Retinquished by: (Signature) _____	Received by: (Signature) <i>YB: A. Brown</i>	Date: 012303	Time: 1215

WELL GAUGING DATA

Project # 030129-BA3 Date 1/29/03 Client SH&U

Site 29 WILDWOOD AVE, PIEDMONT

Well ID	Well Size (in.)	Sheen / Odor	Depth to Immiscible Liquid (ft.)	Thickness of Immiscible Liquid (ft.)	Volume of Immiscibles Removed (ml)	Depth to water (ft.)	Depth to well bottom (ft.)	Survey Point: TOB or TOC
MW-1	4	pressure - allowed		5 min	to stabilize	3.25	13.13	TOC

SHELL WELL MONITORING DATA SHEET

BTS #: 030129-BAB	Site: 29 WILLOWOOD AVE, PIEDMONT
Sampler: BRIAN ALVARO	Date: 1/29/03
Well I.D.: MW-1	Well Diameter: 2 3 <u>4</u> 6 8
Total Well Depth (TD): 13.73	Depth to Water (DTW): 3.25
Depth to Free Product:	Thickness of Free Product (feet): 5
Referenced to: <u>PVC</u> Grade	D.O. Meter (if req'd): <u>YSI</u> HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 5.23	

Purge Method: Bailer Wtterra Sampling Method: Bailer
 Disposable Bailer Peristaltic Disposable Bailer
 Middleburg Extraction Pump Extraction Port
Electric Submersible Other _____ Dedicated Tubing

Other: _____

$6.4 \text{ (Gals.)} \times 3 = 19.2 \text{ Gals.}$ <p style="font-size: small; margin: 0;"> Case Volume Specified Volumes Calculated Volume</p>	<table border="1" style="width: 100%; border-collapse: collapse; font-size: x-small;"> <thead> <tr> <th>Well Diameter</th> <th>Multiplier</th> <th>Well Diameter</th> <th>Multiplier</th> </tr> </thead> <tbody> <tr> <td>1"</td> <td>0.04</td> <td>4"</td> <td>0.65</td> </tr> <tr> <td>2"</td> <td>0.16</td> <td>6"</td> <td>1.47</td> </tr> <tr> <td>3"</td> <td>0.37</td> <td>Other</td> <td>radius² * 0.163</td> </tr> </tbody> </table>	Well Diameter	Multiplier	Well Diameter	Multiplier	1"	0.04	4"	0.65	2"	0.16	6"	1.47	3"	0.37	Other	radius ² * 0.163
Well Diameter	Multiplier	Well Diameter	Multiplier														
1"	0.04	4"	0.65														
2"	0.16	6"	1.47														
3"	0.37	Other	radius ² * 0.163														

Time	Temp (°F)	pH	Cond. (mS or <u>µS</u>)	Turbidity (NTUs)	Gals. Removed	Observations
1505	63.6	7.6	758	40	6.5	clear gray w/ black particles
1506	63.1	7.1	779	95	13.0	"
1507	Dewatered				@ 14.0	DTW 8.80
1510 1520	65.4	7.0	735	72	—	clear gray w/ black debris particles

Did well dewater? Yes No Gallons actually evacuated: 14

Sampling Date: 1/29/03 Sampling Time: 1520 Depth to Water: 5.20

Sample I.D.: MW-1 Laboratory: Kiff SPL Other _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

EB I.D. (if applicable): @ _____ Duplicate I.D. (if applicable):

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge: <u>3.7</u>	mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

WELL GAUGING DATA

Project # 030122-DW-2 Date 1-22-03 Client Shell

Site 29 Willwood Ave Piedmont

Well ID	Well Size (in.)	Sheen / Odor	Depth to Immiscible Liquid (ft.)	Thickness of Immiscible Liquid (ft.)	Volume of Immiscibles Removed (ml)	Depth to water (ft.)	Depth to well bottom (ft.)	Survey Point: TOB or TOB
mw-1	4	unable to gauge - gas over well					13.13	J
mw-2	4				*2.68		11.99	
mw-3	4				*3.09		9.01	
mw-4	4					3.67	12.80	
mw-5	4					4.12	16.01	
			*gaged w/ ORC's in well					

SHELL WELL MONITORING DATA SHEET

BTS #: 030122-DW-2	Site: 29 Wildwood Ave Piedmont
Sampler: Dave Walther	Date: 1-22-03
Well I.D.: MW-1	Well Diameter: 2 3 <u>4</u> 6 8
Total Well Depth (TD): 13.13	Depth to Water (DTW):
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: <u>PVC</u> Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]:	

Purge Method: Bailor
 Disposable Bailor
 Middleburg
 Electric Submersible
 Other _____

Water Extraction Pump
 Other _____

Sampling Method: Bailor
 Disposable Bailor
 Extraction Port
 Dedicated Tubing
 Other: _____

Case Volume	(Gals.) X <u>3</u>	=	Specified Volumes	=	Calculated Volume	Gals.																
<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <tr> <th>Well Diameter</th> <th>Multiplier</th> <th>Well Diameter</th> <th>Multiplier</th> </tr> <tr> <td>1"</td> <td>0.04</td> <td>4"</td> <td>0.65</td> </tr> <tr> <td>2"</td> <td>0.16</td> <td>6"</td> <td>1.47</td> </tr> <tr> <td>3"</td> <td>0.37</td> <td>Other</td> <td>radius² * 0.163</td> </tr> </table>							Well Diameter	Multiplier	Well Diameter	Multiplier	1"	0.04	4"	0.65	2"	0.16	6"	1.47	3"	0.37	Other	radius ² * 0.163
Well Diameter	Multiplier	Well Diameter	Multiplier																			
1"	0.04	4"	0.65																			
2"	0.16	6"	1.47																			
3"	0.37	Other	radius ² * 0.163																			

Time	Temp (°F)	pH	Cond. (mS or µS)	Turbidity (NTUs)	Gals. Removed	Observations
Unable to sample. Car parked over well. Asked station to move it, which they did. But then they immediately moved another car over the well and began working on it. Asked them when they would move that car twice (once after all other wells were finished and once when I was ready to work on that well) and they replied they were still working on it and didn't move it.						

Did well dewater? Yes No Gallons actually evacuated: _____

Sampling Date: 1-22-03 Sampling Time: _____ Depth to Water: _____

Sample I.D.: _____ Laboratory: Kiff SPL Other _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

SB I.D. (if applicable): _____ Duplicate I.D. (if applicable): _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	mg/L
D.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: <u>030/22-0W-2</u>	Site: <u>29 Wildwood Ave Piedmont</u>
Sampler: <u>Dave Walter</u>	Date: <u>1-22-03</u>
Well I.D.: <u>MW-2</u>	Well Diameter: 2 3 <u>(4)</u> 6 8
Total Well Depth (TD): <u>11.99</u>	Depth to Water (DTW): <u>2.68</u>
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: <u>(PVC)</u> Grade	D.O. Meter (if req'd): <u>(YSI)</u> HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: <u>4.54</u>	

Purge Method: <input type="checkbox"/> Bailer <input type="checkbox"/> Disposable Bailer <input type="checkbox"/> Middleburg <input checked="" type="checkbox"/> Electric Submersible	Waterra <input type="checkbox"/> Peristaltic <input type="checkbox"/> Extraction Pump Other: _____	Sampling Method: <input checked="" type="checkbox"/> Bailer <input type="checkbox"/> Disposable Bailer <input type="checkbox"/> Extraction Port <input type="checkbox"/> Dedicated Tubing Other: _____
--	---	--

6.1 (Gals.) X 3 = 18.3 Gals.
 Case Volume Specified Volumes Calculated Volume

Well Diameter	Multiplier	Well Diameter	Multiplier
1"	0.04	4"	0.65
2"	0.16	6"	1.47
3"	0.37	Other	radius ² * 0.163

Time	Temp (°F)	pH	Cond. (mS or <u>(S)</u>)	Turbidity (NTUs)	Gals. Removed	Observations
13:48	61.7	5.8	761	7200	7	Black/odor
well dewatered			761 @ 7 gal. DTW = 9.42			
15:03	67.4	6.7	713	7200	—	still black/odor

Did well dewater? Yes No Gallons actually evacuated: 7

Sampling Date: 1-22-03 Sampling Time: 15:03 Depth to Water: 4.54

Sample I.D.: MW-2 Laboratory: (Kiff) SPL Other: _____

Analyzed for: (TPH-G BTEX MTBE) TPH-D Other: _____

EB I.D. (if applicable): _____ @ _____ Time Duplicate I.D. (if applicable): _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	<u>1.5</u> mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: 030/22-0W-2	Site: 29 Wildwood Ave Piedmont
Sampler: Dave Walker	Date: 1-22-03
Well I.D.: MW-3	Well Diameter: 2 3 (4) 6 8
Total Well Depth (TD): 9.01	Depth to Water (DTW): 3.07
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Gmde	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 4.27	

Purge Method: Bailer Disposable Bailer Middleburg <input checked="" type="checkbox"/> Electric Submersible	Water: Peristaltic Extraction Pump Other:	Sampling Method: <input checked="" type="checkbox"/> Bailer Disposable Bailer Extraction Port Dedicated Tubing Other:
---	---	---

3.9 (Gals.) X 3 = 11.4 Gals.
 Case Volume Specified Volumes Calculated Volume

Well Diameter	Multiplier	Well Diameter	Multiplier
1"	0.04	4"	0.65
2"	0.16	6"	1.47
3"	0.37	Other	radius ² * 0.163

Time	Temp (°F)	pH	Cond. (mS or μS)	Turbidity (NTUs)	Gals. Removed	Observations
14:00	61.7	6.8	914	7200	4	Brown
well dewatered @ 5 gal. DTW = 6.59						
15:14	61.4	6.9	897	56	—	

Did well dewater? Yes No Gallons actually evacuated: 5

Sampling Date: 1-22-03 Sampling Time: 15:14 Depth to Water: 3.07

Sample I.D.: MW-3 Laboratory: Kirt SPL Other:

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

3B I.D. (if applicable): @ Time Duplicate I.D. (if applicable):

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

D.O. (if req'd): Pre-purge: mg/L Post-purge: 1.3 mg/L

D.R.P. (if req'd): Pre-purge: mV Post-purge: mV

SHELL WELL MONITORING DATA SHEET

BTS #: 030122-0W-2	Site: 29 Wildwood Ave Piedmont
Sampler: Dave Walter	Date: 1-22-03
Well I.D.: mw-4	Well Diameter: 2 3 (4) 6 8
Total Well Depth (TD): 12.80	Depth to Water (DTW): 3.67
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: (PVC) Grade	D.O. Meter (if req'd): (YSI) HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 5.49	

Purge Method: <input type="checkbox"/> Bailor <input type="checkbox"/> Disposable Bailor <input type="checkbox"/> Middleburg <input checked="" type="checkbox"/> Electric Submersible	Watera <input type="checkbox"/> Peristaltic <input type="checkbox"/> Extraction Pump Other: _____	Sampling Method: <input checked="" type="checkbox"/> Bailor <input type="checkbox"/> Disposable Bailor <input type="checkbox"/> Extraction Port <input type="checkbox"/> Dedicated Tubing Other: _____
--	--	--

5.9 (Gals.) X 3 = 17.7 Gals. Case Volume Specified Volumes Calculated Volume	<table border="1" style="width: 100%; border-collapse: collapse; text-align: center;"> <thead> <tr> <th>Well Diameter</th> <th>Multiplier</th> <th>Well Diameter</th> <th>Multiplier</th> </tr> </thead> <tbody> <tr> <td>1"</td> <td>0.04</td> <td>4"</td> <td>0.65</td> </tr> <tr> <td>2"</td> <td>0.16</td> <td>6"</td> <td>1.17</td> </tr> <tr> <td>3"</td> <td>0.37</td> <td>Other</td> <td>radius² * 0.163</td> </tr> </tbody> </table>	Well Diameter	Multiplier	Well Diameter	Multiplier	1"	0.04	4"	0.65	2"	0.16	6"	1.17	3"	0.37	Other	radius ² * 0.163
Well Diameter	Multiplier	Well Diameter	Multiplier														
1"	0.04	4"	0.65														
2"	0.16	6"	1.17														
3"	0.37	Other	radius ² * 0.163														

Time	Temp (°F)	pH	Cond. (mS or μ S)	Turbidity (NTUs)	Gals. Removed	Observations
14:17	63.6	7.7	421	18	6	
			well dewatered @ 9 gal.	DTW =	9.89	

Did well dewater? Yes No Gallons actually evacuated: 9

Sampling Date: 1-22-03 Sampling Time: 14:30 Depth to Water: 7.65 (street water)

Sample I.D.: mw-4 Laboratory: KITE SPL Other: _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

EB I.D. (if applicable): @ Duplicate I.D. (if applicable): _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other: _____

D.O. (if req'd):	Pre-purge:	mg/L	Post-purge:	3.1 mg/L
O.R.P. (if req'd):	Pre-purge:	mV	Post-purge:	mV

SHELL WELL MONITORING DATA SHEET

BTS #: 030122-0W-2	Site: 29 Wildwood Ave Piedmont
Sampler: Dave Walker	Date: 1-22-03
Well I.D.: MW-5	Well Diameter: 2 3 (4) 6 8
Total Well Depth (TD): 16.01	Depth to Water (DTW): 4.12
Depth to Free Product:	Thickness of Free Product (feet):
Referenced to: PVC Grade	D.O. Meter (if req'd): YSI HACH
DTW with 80% Recharge [(Height of Water Column x 0.20) + DTW]: 6.49	

Purge Method: Bailor Water Sampling Method: Bailor
 Disposable Bailor Peristaltic Disposable Bailor
 Middleburg Extraction Pump Extraction Port
 Electric Submersible Other _____ Dedicated Tubing
 Other: _____

7.7 (Gals.) X	3	=	23.1	Gals.	
Case Volume	Specified Volume		Calculated Volume		

Well Diameter	Multplier	Well Diameter	Multplier
1"	0.04	4"	0.65
2"	0.16	6"	1.47
3"	0.37	Other	radius ² * 0.163

Time	Temp (°F)	pH	Cond. (mS or μS)	Turbidity (NTUs)	Gals. Removed	Observations
14:41	64.3	7.0	704	28	8	
14:43	64.3	7.0	707	25	16	
14:45	64.4	7.0	699	18	24	

Did well dewater? Yes No Gallons actually evacuated: 24
 Sampling Date: 1-22-03 Sampling Time: 14:50 Depth to Water: 7.10 (street level)

Sample I.D.: MW-5 Laboratory: KIR SPL Other _____

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

EB I.D. (if applicable): @ _____ Duplicate I.D. (if applicable):

Analyzed for: TPH-G BTEX MTBE TPH-D Other:

D.O. (if req'd):	Pre-purge:		mg/l	Post-purge:	2.4 mg/l
D.R.P. (if req'd):	Pre-purge:		mV	Post-purge:	mV