

**QUARTERLY SUMMARY REPORT**  
2ND QTR - 1992  
(April - June)

**RESNA**

**RECEIVED**

2:02 pm, Jun 17, 2009

Alameda County  
Environmental Health

**UNOCAL SERVICE STATION #5367**  
500 Bancroft Avenue  
San Leandro, California

City/County ID# San Leandro Fire Department

County: Alameda County

**BACKGROUND**

Eight groundwater monitoring wells present. Groundwater has fluctuated between 33 and 38 feet below the ground surface.

**RECENT QUARTER ACTIVITIES**

Second quarter 1992 monitoring performed in June 1992.

**NEXT QUARTER ACTIVITIES**

Perform third quarter 1992 groundwater monitoring.

**CHARACTERIZATION/REMEDIAL STATUS**

Soil contamination delineated?	<u>Yes</u>
Dissolved groundwater delineated?	<u>No</u>
Free Product delineated?	<u>NA</u>
Amount of gw contaminant recovered this quarter?	<u>0 gallons</u>
Soil remediation in progress?	<u>No</u>

**CONSULTANT:**

RESNA Industries