



July 27, 2001

Project 029.15

Mr. Barney Chan Alameda County Health Care Services Agency Environmental Protection 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Site Review for Closure Pacific Supply Company 1735 24th Street Oakland, California

Dear Mr. Chan:

As per our recent telephone conversation, it is our understanding that you are reviewing information regarding soil and groundwater investigation and remediation work at the Pacific Supply Company site, with the intent to evaluate the site for closure. You requested information regarding a summary of work completed at the site that would assist you in evaluating the site closure request. I have briefly reviewed our files and was not able to find a comprehensive summary document of all the work completed at the site to date. In lieu of such a document I have prepared a list of documents which should be in your files that provide information on soil and groundwater quality and remediation activities.

Report of Findings, Soil and Groundwater Investigation - November 30, 1990 Boring logs, soil analytical data and initial groundwater data for monitoring wells MW-1 through MW-7

Report of Findings Vapor Extraction Pilot Study - November 18, 1992 Boring log and soil analytical data for vapor extraction well VEW-1

Soil Investigation Report - May 24, 1993
Boring logs and soil analytical results for soil borings B-1 through B-10

<u>Wapor Recovery Well Installation Report</u> - February 7, 1994

Boring logs, and soil and groundwater analytical results for vapor recovery wells

VRW-1 through VRW-9

P.O. Box 588, Windsor, CA 95492 Phone: (707) 838-3027 Fax: (707) 838-4420

Mr. Barney Chan July 27, 2001 Page 2

Semi-annual Monitoring Report and Final Treatment System Operation Report: July 1996 - August 28, 1996

Summary of Vapor Extraction System Operation

Groundwater Investigation and Monitoring Report - December 14, 2000 Summary of monitoring well analytical results to date and soil and groundwater analytical results for off-site borings B-10, B-11 and B-12

Should you require any additional information regarding the history of investigation and remediation at the site please do not hesitate to contact me at (707) (7-) 838-3027.

Sincerely, Cul Schwal-(707) 884-3370 Gwalala

Carl Schwab, R.G. Senior Geologist

cc: Ms. Normita Callison

