

PHONE LOG

11/22/94

Bob Womack (510)357-1063

Mr. Womack stated that the soil excavated from the pit during the tank removal was backfilled into the pit. I requested the sampling results for the stockpiled soil & Mr. Womack stated that he would try to find that info.

PHONE LOG (22008 Overland)

8/11/94

Bob Womack called & stated that they never received the April '94 letter from County. He stated that he would retain consultants to implement another round of groundwater sampling.

IMPORTANT MESSAGE

FOR JULIET
DATE 6/24/92 TIME 10:30 A.M. P.M.
M. Eddy So
OF REGIONAL WATER
PHONE 964-4366
AREA CODE NUMBER EXTENSION

TELEPHONED	<input checked="" type="checkbox"/>	PLEASE CALL	<input checked="" type="checkbox"/>
CAME TO SEE YOU	<input type="checkbox"/>	WILL CALL AGAIN	<input type="checkbox"/>
WANTS TO SEE YOU	<input type="checkbox"/>	RUSH	<input type="checkbox"/>
RETURNED YOUR CALL	<input type="checkbox"/>	SPECIAL ATTENTION	<input type="checkbox"/>

MESSAGE two alternatives

- ① Carry on monitoring for all 3 wells - no limit ^{values can establish}
- ② a) Fluctuating grad. consistent gradient
_{No wells in true direction - cross gradient}
- b) Clay layers - but looking at

SIGNED potential re surface - aquifer may not be confined laterally
LITHO IN U.S.A.

9/30/91

Dave Lewley - Emcon
Ramon Khue - Blymeyer called

KD Cedar - my letter to him - contaminated soil - needs more time - is applying for funding plans to do soil inv. from

uncover - over exc. - confirmat org samples - no impact on wells -

if funding thru state program - end of Nov -

if not ?? - I told Ramon to cover both contingencies in a work plan written

NOTES

DATE 6/12/92

CONTACT LOG

FROM: Juliet Shin AFFILIATION: Alameda County
TITLE: _____ PHONE: (510) 271-4320
TO: Ramon Khur AFFILIATION: Hyman Engineer
TITLE: _____ PHONE: (510) 521-3773
RE: STID 3606 - KD Cedar Supply, 22008 Merkleland,
Hayward

Ms. Shin asked Ramon Khur whether or not the soil at the bottom of the tank was over excavated since 1,300 ppm TPHg was identified there. Mr. Khur stated that they did not over-excavated after that sample was collected. Mr. Khur stated that the former tank pit area is now paved over w/ concrete, so that there is little chance of the remaining contamination to leach out down to groundwater. Groundwater is located at a depth of ~32 feet and the soil contamination is was identified at about 13 feet below ground surface. Mr. Khur wanted to know whether the site would be ready for closure if the soil problem was addressed through further excavation. Ms. Shin stated that there would be a good chance of that happening. Mr. Khur stated that

The property owner is currently ~~but~~ almost bankrupt and has no money to address the soil problem at this time. Ms. Shin ~~stated that~~ Mr. Kim requested that the requirement for further soil investigations be delayed until the property owner could pay for the investigation. Ms. Shin stated that since concrete pavement is currently over the former tank pit area and since the soils beneath the site consist primarily of clay and g.w. is approximately 20 feet below the bottom of the tank pit, that possibly the property owner could request formally through a letter, that this work be delayed for another year. This officer may approve it.

Ms. Shin stated that she would send Mr. Kim a copy of the closure report requirements for closure certification.

Ms. Shin stated that she would hold off on requesting any further investigations until she receives the next quarterly report.

DATE 5/12/92

CONTACT LOG

FROM: Juliet Shin AFFILIATION: Alameda County
TITLE: _____ PHONE: _____
TO: Mr. Andy Macko AFFILIATION: K.D. Cedar Supply
TITLE: _____ PHONE: _____

RE: STID 3606 - KD Cedar Supply, 22008 Woodland,
Hayward

Mr. Macko stated that he applied for the Petroleum Leaking UST fund and did not receive any money. He is planning to continue quarterly monitoring and will conduct monthly water sampling if ~~it~~ the cost of this work is reasonable.

5/12/92 Ramon Khu, Blymer Engineer & Juliet Shin

Mr. Khu stated that he would speak to Mr. Macko about the monthly monitoring of water levels and get back to Ms. Shin.

IMPORTANT MESSAGE

FOR Scott
 DATE 3-3-92 TIME 10:30 ^{A.M.} _{P.M.}
 M. Eddy So
 OF RWQCB
 PHONE _____
AREA CODE NUMBER EXTENSION

TELEPHONED	<input type="checkbox"/>	PLEASE CALL	<input type="checkbox"/>
CAME TO SEE YOU	<input type="checkbox"/>	WILL CALL AGAIN	<input type="checkbox"/>
WANTS TO SEE YOU	<input type="checkbox"/>	RUSH	<input type="checkbox"/>
RETURNED YOUR CALL	<input type="checkbox"/>	SPECIAL ATTENTION	<input type="checkbox"/>

MESSAGE Re: K.D. Cedar on
meekland av in Hayward.
He has reviewed the case file
+ believes their well placements
are not down gradient of the
contamination.

SIGNED PE
 LITHO IN U.S.A.

TOPS  FORM 3002S

IMPORTANT MESSAGE

FOR DAM
 DATE 2/26/ TIME 3:35 ^{A.M.} _{P.M.}
 M. ROMON KHU
 OF BLYMER
 PHONE _____
AREA CODE NUMBER EXTENSION

TELEPHONED	<input checked="" type="checkbox"/>	PLEASE CALL	<input checked="" type="checkbox"/>
CAME TO SEE YOU	<input type="checkbox"/>	WILL CALL AGAIN	<input type="checkbox"/>
WANTS TO SEE YOU	<input type="checkbox"/>	RUSH	<input type="checkbox"/>
RETURNED YOUR CALL	<input type="checkbox"/>	SPECIAL ATTENTION	<input type="checkbox"/>

MESSAGE KD CEDAR SITE -
Needs my input before he can com-
plete his proposal. as I cant look
at his info earlier than next
week, I will allow an extension
which we will discuss early next
week. by March 8, 1991

SIGNED _____
 LITHO IN U.S.A.

TOPS  FORM 3002S

IMPORTANT MESSAGE

FOR R.E.
DATE 8/5/91 TIME 3:08 AM
M. Ramon Khu
OF Blymyer Engineers
PHONE 521-3723
AREA CODE NUMBER EXTENSION

TELEPHONED		PLEASE CALL	<input checked="" type="checkbox"/>
CAME TO SEE YOU		WILL CALL AGAIN	
WANTS TO SEE YOU		RUSH	
RETURNED YOUR CALL		SPECIAL ATTENTION	

MESSAGE K.O. Cedar - completed
workplan - N.D. in soil
+ g. water for borings + first
round of samples from
wells

Next round = Oct, Jan, Apr, Jul

SIGNED msg to Ramon Khu 8/29
LITHO IN U.S.A.

*what about soil? 1000 ppm
etc.??*

Sample 1 130 ppm

8.5'

Sample 2 13000 ppm

12'

as stated in letter of ^{Aug 21} May Jan 21
must inv. ext. of soil + ground
water - future source of gw
cont.

NOTES

IMPORTANT MESSAGE

FOR fam
DATE 2-19-91 TIME 2:30 P.M.
M. Ramon Khu
OF Blymyer
PHONE 521-3773
AREA CODE NUMBER EXTENSION

TELEPHONED		PLEASE CALL	X
CAME TO SEE YOU		WILL CALL AGAIN	
WANTS TO SEE YOU		RUSH	
RETURNED YOUR CALL		SPECIAL ATTENTION	

MESSAGE KD Cedars Supply
Co. (workplans)

?? about well locations and
need to submit samples for lab
analysis on all wells.

SIGNED _____
LITHO IN U.S.A.

IMPORTANT MESSAGE

FOR TP
DATE 11/16 TIME 8:45 A.M.
M. P
OF R L Stevens
PHONE 889-0908
AREA CODE NUMBER EXTENSION

TELEPHONED		PLEASE CALL	
CAME TO SEE YOU		WILL CALL AGAIN	
WANTS TO SEE YOU		RUSH	
RETURNED YOUR CALL		SPECIAL ATTENTION	*

MESSAGE KD CEPER
-D 22008 Meekland Ave.
Hayward

Tank removal

SIGNED _____
LITHO IN U.S.A.

11/20/89

10:00 am

IMPORTANT MESSAGE

FOR PAM
DATE 2/1/91 TIME 10:18 A.M.
M. RAMONE KHU
OF * BLYMER ENGINEERS -
PHONE 521-3793
AREA CODE NUMBER EXTENSION

TELEPHONED	<input checked="" type="checkbox"/>	PLEASE CALL	<input checked="" type="checkbox"/>
CAME TO SEE YOU	<input type="checkbox"/>	WILL CALL AGAIN	<input type="checkbox"/>
WANTS TO SEE YOU	<input type="checkbox"/>	RUSH	<input type="checkbox"/>
RETURNED YOUR CALL	<input type="checkbox"/>	SPECIAL ATTENTION	<input type="checkbox"/>

MESSAGE RE: WORK PLAN
FOR KD CEDAR SUPPLY

* WILL HANDLE LETTER
FOR KD CEDAR SUPPLY
BY DEADLINE

SIGNED _____
LITHO IN U.S.A.