ALAMEDA COUNTY

HEALTH CARE SERVICES

AGENCY



DAVID J. KEARS, Agency Director

STID # 3994

June 3, 1996

Alameda County CC4580 Environmental Health Services 1131 Harbor Bay Pkwy., #250 Alameda CA 94502-6577 (510)567-6700 FAX(510)337-9335

REMEDIAL ACTION COMPLETION CERTIFICATION

Mr. Alan Zatopa 2900 Ralston Avenue Hillsborough, CA 94010

RE: Commercial Property, 1000 West Grand Avenue, Oakland 94607

Dear Mr. Zatopa:

This letter confirms the completion of site investigation and remedial action for the three (3) 2000-gallon gasoline underground storage tanks at the above described location. Enclosed is the Case Closure Summary for the referenced site for your records.

Based upon the available information and with provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground tank release is required.

This notice is issued pursuant to the regulation contained in Title 23, Division 3, Chapter 16, Section 2721 (e) of the California Code of Regulations.

Please contact Dale Klettke at (510) 567-6880 if you have any questions regarding this matter.

Sincerely,

Mee Ling Tund

Director, Department of Environmental Health

c: Gordon Coleman, Acting Chief, Department of Environmental
Protection--files

Kevin Graves, RWQCB Lori Casias, SWRCB

Mike Harper, SWRCB w/enclosure

3994racc.dkt

AGENCY INFORMATION

AGENCY INFORMATION

Date: April 18, 1996

Agency name: Alameda County-HazMat Address: 1131 Harbor Bay Pkwy City/State/Zip: Alameda, CA 94502 Phone: (510) 567-6700 Responsible staff person: D. Klettke Title: Hazardous Material

II. CASE INFORMATION

Site facility name: Common Site facility name: Co Responsible staff person: D. Klettke Title: Hazardous Materials Spec

Local Case No./LOP Case No.: 3994 RB LUSTIS Case No: N/A

SWEEPS No: N/A URF filing date: 9/27/94

Responsible Parties:

Addresses:

Phone Numbers:

Mr. Alan Zatopa, 2900 Ralston Avenue, Hillborough, CA 94010

(510)574-7771

Tank No:	<u>Size in</u> _gal.:	<u>Contents:</u>	<pre>Closed in-place or removed?:</pre>	<u>Date:</u>
1	2000	Gasoline	removed	9/27/94
2	2000	Gasoline	removed	9/27/94
3	2000	Gasoline	removed	9/27/94

RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and type of release: UST failure, two holes noted in north UST, one hole in middle UST.

Site characterization complete? YES

Date approved by oversight agency: 2/7/96

Monitoring Wells installed? NO Number: N/A

Proper screened interval? N/A

Highest GW depth below ground surface: N/A Lowest depth: N/A

Flow direction: predominantly west-northwesterly at former Chevron Service

Station Site located at 850 West Grand STID # 289. Most sensitive current use: Commercial/industrial

Are drinking water wells affected? NO Aquifer name: N/A

Is surface water affected? NO Nearest affected SW name: N/A

Off-site beneficial use impacts (addresses/locations): N/A

Report(s) on file? YES Where is report(s) filed? Alameda County

1131 Harbor Bay Pkwy Alameda, CA 94502

Treatment and Disposal of Affected Material:

<u>Material</u>	Amount (include units)	Action (Treatment Date or Disposal w/destination)
Tank	3 x 2000-gallon	disposal/Erickson 9/27/94 255 Parr Blvd, Richmond, CA
Piping Free Product Soil	252 cubic yards	disposal/REMCO 10/7/94 2717 Goodrick Avenue, Richmond, CA
Groundwater Barrels Rinsate	250 gallons	disposal/Enviropur West 10/11/94 13331 N Hwy 33, Patterson, CA

Maximum Documented Contaminant Concentrations - - Before and After Cleanup **Soil (ppm)** Before¹ After² Water (ppb)
Before³ Contaminant After4 TPH (Gas) 661 220 12667 100 TPH (Diesel) ___ _ _ _ 1.94 53.4 2.1 Benzene 0.69 2.07 46.9 0.6 Toluene 0.63 10.42 Ethyl benzene 0.82 40.7 < 0.5 13.01 96.1 Xylenes 1.7 <2 Oil & Grease Heavy metals

Comments (Depth of Remediation, etc.):

Other-MTBE

On September 27, 1994, SEMCO removed the three (3) 2000-gallon gasoline underground storage tanks. Upon removal, the conditions of the tanks were observed, with the middle and north USTs were reported as having holes in

< 50

¹Before TPHg, benzene and toluene concentrations were detected in soil sample #2-South Sidewall at a depth of 11' bgs. Before ethyl benzene and total xylene concentrations were detected in soil sample #1-North Sidewall at a depth of 11.5' bgs.

²After soil sample results were detected in soil sample #5-South Sidewall at a depth of 12' bgs, following over excavation of the gasoline UST pit.

³Before water sample results were detected in the grab groundwater sample collected from groundwater which had entered the excavation pit during initial UST removals.

⁴After results were obtained from the grab groundwater sample collected from boring B-1 on 2/13/96.

the bottom of each of these two tanks. Groundwater reported began to enter the UST excavation at a depth of 12 feet below ground surface (bgs).

A total of four (4) sidewall samples, six (6) bottom samples and one grab groundwater sample were collected and analyzed for total petroleum hydrocarbons as gasoline (TPHg), benzene, toluene, ethyl benzene and total xylenes (BTEX). Laboratory analytical results for these soil and groundwater samples are summarized in Table 1.

On September 28, 1994, soil samples were collected at the North Sidewall and South Sidewall at depths of 11' and 11.5' bgs, respectively. These samples were collected from areas in which contamination was noted during September 27, 1994 soil samplings. Laboratory analytical results of these two soil samples are summarized in Table 2.

Due to the high concentrations of petroleum hydrocarbons detected, the excavation was extended approximately three (3) feet at each end. Soil samples were collected at approximate depths of 12' bgs from both the north and south ends. Further excavation of the South end was not possible due to a reportedly extensive amount of utilities and the possible compromise to the integrity of the adjacent building. Laboratory analytical results of these two soil samples are summarized in Table 3.

In order to determine whether the contamination left in place (documented by soil sample #5 which was collected at the south end of the over-excavated pit) would have any impact on groundwater, a preliminary site assessment (PSA) was performed by Geomatrix.

On February 13, 1996, Geomatrix conducted the PSA by advancing three borings and installing temporary wells in order to collect grab groundwater samples from each boring. Borings B-1, B-2 and B-3 were advanced to depths of approximately 16 to 25 feet bgs, using direct-push technology. Soil samples were collected at approximately five (5) foot intervals. One (1) groundwater sample was collected from each temporary wellpoint. Laboratory analytical results of documented soil and groundwater samples are summarized in Tables 4 and 5.

See Section VII, Additional Comments, etc...

IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? YES

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? YES

Does corrective action protect public health for current land use? YES Site management requirements: None

Should corrective action be reviewed if land use changes? YES

Monitoring wells Decommissioned: None

Number Decommissioned: N/A Number Retained: N/A

List enforcement actions taken: None List enforcement actions rescinded: N/A

/. LOCAL AGENCY REPRESENTATIVE DATA

Tall to

Name: Dale Klettke

Title: Hazardous Materials Specialist

Signature:

Date: 5/14/90

Reviewed by

Name: Jennifer Eberle

Title: Hazardous Materials Specialist

Signature: Mele

Date: 5-14-98

Name: Thomas Peacock

Title: Supervising HazMat Specialist

Signature: Dans Dans Da

Date: 5-/4-96

VI. RWQCB NOTIFICATION

Date Submitted to RB:

RB Response: Allowed

Title: AWRCE

Signature:


RWQCB Staff Name | Revin Graves

Date: 5/29/9/

VII. ADDITIONAL COMMENTS, DATA, ETC.

This site qualifies for case closure as a "Low Risk Soils Case" for the following reasons:

- a) The source has been sufficiently removed or has been remediated. Soil contamination remaining in place is documented by soil sample #5 (See Table 3).
- b) The site has been adequately characterized. Laboratory analysis of soil and groundwater samples collected during the PSA documents that that the previous release is very small in extent and is limited to soils in the southern end of the former UST pit.
- c) Little or no groundwater impact currently exists and no contaminants are found at levels above established MCLs or other applicable water quality objectives. Only benzene was detected at a concentration exceeding the MCL of 1 ppb (2.1 ppb in the groundwater sample collected from boring B-1), this is in the "inferred" up gradient direction from the former UST excavation. The temporary wells which were in the "inferred" down gradient location from the former UST pit were found to contain non-detectable concentrations of TPHg, BTEX and MTBE.
- d) No water walls, deeper drinking water wells, surface water or other sensitive receptors are likely to be impacted. The contamination appears to be localized on site, specifically on the southern end of the former UST excavation.
- e) The site presents no significant risk to human health or the environment. Except for benzene which was detected at a concentration of 2.1 ppb, no concentrations of groundwater contaminants exceed Primary Drinking Water MCLs. The contamination appears to be localized and is not migrating off-site at concentrations which would pose a risk to human health or the environment.



Geochem ENVIRONMENTAL LABORATORIES

Mobile & In-House Laboratories Certified by State of California

Phone: (408) 955-9988 / FAX: (408) 955-9538

ANALYTICAL REPORT

OCT 15 1994 Page: 1 of Client: SEMCO Date Sampled: 09/27/94~ 1741 Leslie Dr. Date Received: 09/27/94 San Mateo, CA 94402 Date Analyzed: 09/27/94 Attn: Chuck Kiper Batch: SA-440 Matrix: Soil Conc. Unit mg/kg (ppm) Project: 94-3878 Alan Zatopa ********************** "ND" means "not detected" at indicated detection limit. B:benzene, T:toluene, E:ethylbenzene & X:total xylenes. Samples received at job-site with a chain of custody record. Total 8015M/TPH 8020 SAMPLE I.D. Lead Gasoline SAMPLE DETECTION # LIMIT 1 ppm 1 ppm 0.005 ppm -----2NG-B-13' ND ND ND / 2NG-S-12' 30 0.333 / 0.429 / 0.260 / 0.280 2MG-B-13' ND ND / NDND ND 2SB-S-13' ND 0.318 / ND ND ND 2SG-B-13' ND 0.192 / ND 7 ND ND 4MG-S-13' 2 ND ND ND ND ND Sidewall B-5' ND 0.034 / ND ND ND Sidewall B-12'6" ND 0.040 / ND ND ND Sidewall S-5' ND ND / 0.115 / 0.087 / ND Sidewall S-13' ND 1 ND ND ND ND 7 Comp Spoils 9 222 ND / 3.252 / 7.914 ND 8015M/TPH 602 SAMPLE I.D. Gasoline /. . E DETECTION 0.5 ppb Pit H₂O 12667 53.4 / 46.9 / 40.7 / 96.1

TANK REMOVAL ANALYTICAL

1000 WEST GRAND AVENUE OAKLAND, CALIFORNIA

SEPTEMBER 28, 1994

SAMPLE ID	DEPTH	TPH (G)	BENZENE	TOLUENE	ETHYL BENZENE	XYLENES
#1-NORTH	11'	446	1.425	1.902	10.42	13.01
SIDEWALL		PPM	PPM	PPM	PPM	PPM
#2-SOUTH	11'6"	661	1.942	2.070	5.171	9.653
SIDEWALL		PPM	PPM	PPM	PPM	PPM
#3-PUMP ISLAND	-	ND	ND	ND	ND	ND

SEPTEMBER 28, 1994

SAMPLE ID	DEPTH	TPH (G)	BENZENE	TOLUENE	ETHYL BENZENE	XYLENES
#4- NORTH SIDEWALL EX	12'	ND	ND	ND	ND	ND
#5-SOUTH SIDEWALL EX	12'	220 PPM	0.69 PPM	0.63 PPM	0.82 PPM	1.7 PPM

TABLES 2 3







FIGURE 2

NOT TO SCALE

SEMCO

1000 GRAND AVENUE **OAKLAND**






FIGURE 4



TABLE 4 SOIL SAMPLE ANALYTICAL RESULTS¹

1000 West Grand Avenue Oakland, California

Concentrations are in milligrams per kilogram (mg/kg)

Boring ID ²	Sample Depth (ft bgs ³)	TPHg⁴	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE ⁵
B-1	5.5	0.2	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05
	11.0	0.6	< 0.005	< 0.005	< 0.005	0.0065	< 0.05
	20.5	< 0.2	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05
B-2	5.5	<0.2	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05
	11.0	<0.2	< 0.005	< 0.005	< 0.005	< 0.005	< 0.01
	15.5	< 0.2	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05
B-3	11.0	<0.2	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05
'	14.0	< 0.2	< 0.005	< 0.005	< 0.005	< 0.005	< 0.05

Notes

Samples were collected by Geomatrix Consultants, Inc. and analyzed by American Environmental Network of Pleasant Hill, California, by EPA Method 8020.

² Sample locations are shown on Figure 2

³ bgs = Below ground surface

⁴ TPHg = Total Petroleum Hydrocarbons as gasoline

MTBE = Methyl-t-butyl ether



TABLE 5 GRAB GROUNDWATER ANALYTICAL RESULTS¹

1000 West Grand Avenue Oakland, California

Concentrations are in micrograms per liter (µg/l)

Boring/Sample ID ²	TPHg ³	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE ⁴
B-1/GGW-1	100	2.1	0.6	<0.5	<2	< 50
B-2/GGW-2	< 50	< 0.5	< 0.5	<0.5	<2	< 50
B-3/GGW-3	< 50	<0.5	<0.5	< 0.5	<2	< 50

Notes

Samples were collected by Geomatrix Consultants, Inc. and analyzed by American Environmental Network of Pleasant Hill, California, by EPA Method 8020.

² Sample locations are shown on Figure 2.

³ TPHg = Total Petroleum Hydrocarbons as gasoline

⁴ MTBE = Methyl-t-butyl ether