

ALAMEDA COUNTY  
HEALTH CARE SERVICES  
AGENCY

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, Director

DEPARTMENT OF ENVIRONMENTAL HEALTH  
Environmental Protection Division  
1131 Harbor Bay Parkway, #250  
Alameda, CA 94502-6577  
(510) 567-6700

StID 2127

August 14, 1995

Ms. Barbara Sieminski  
GeoStrategies Inc  
6747 Sierra Court  
Dublin, CA 94568

RE: Well Decommission at Shamrock Ford, 7499 Dublin Blvd,  
Dublin

Dear Ms. Sieminski:

This office and the S.F. RWQCB have reviewed the case closure summary for the above referenced site and concur that no further action related to the underground tank release is required at this time. Before a remedial action completion letter is sent, the onsite monitoring wells should be decommissioned, if they will no longer be monitored. Please notify this office upon completion of well destruction so a closure letter can be issued.

If you have any questions, I can be reached at (510) 567-6762.

Sincerely,

eva chu  
Hazardous Materials Specialist

cc: Jim Woulfe, Shamrock Ford, 7499 Dublin Blvd, Dublin 94568  
files

# UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT

EMERGENCY <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I HAVE DISTRIBUTED THIS INFORMATION ACCORDING TO THE DISTRIBUTION SHOWN ON THE INSTRUCTION SHEET ON THE BACK PAGE OF THIS FORM.	
REPORT DATE 12/29/94		CASE #		SIGNED <i>[Signature]</i> 12/29/94 DATE	
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT Barbara Sieminski		PHONE (510) 551-8777		SIGNATURE <i>[Signature]</i>
	REPRESENTING <input type="checkbox"/> LOCAL AGENCY <input checked="" type="checkbox"/> OWNER/OPERATOR <input type="checkbox"/> REGIONAL BOARD <input type="checkbox"/> OTHER		COMPANY OR AGENCY NAME GeoStrategies Inc		
	ADDRESS 6747 Sierra Court, Suite G Dublin CA 94568				
RESPONSIBLE PARTY	NAME Shamrock Ford <input type="checkbox"/> UNKNOWN		CONTACT PERSON Craig Caldwell		PHONE (510) 829-5211
	ADDRESS 7499 Dublin Blvd Dublin CA 94568				
SITE LOCATION	FACILITY NAME (IF APPLICABLE) Shamrock Ford		OPERATOR Shamrock Ford		PHONE (510) 829-5211
	ADDRESS 7499 Dublin Blvd Dublin CA 94568				
	CROSS STREET Amador Plaza Road				
IMPLEMENTING AGENCIES	LOCAL AGENCY Alameda County Health Agency		CONTACT PERSON Eva Chu		PHONE (510) 567-6762
	REGIONAL BOARD Regional Water Quality Control Board - San Francisco Bay Region		PHONE (510) 286-1255		
SUBSTANCES INVOLVED	(1) Gasoline QUANTITY LOST (GALLONS) <input checked="" type="checkbox"/> UNKNOWN				
	(2) Waste Oil QUANTITY LOST (GALLONS) <input checked="" type="checkbox"/> UNKNOWN				
DISCOVERY/ABATEMENT	DATE DISCOVERED 06/23/93		HOW DISCOVERED <input type="checkbox"/> INVENTORY CONTROL <input type="checkbox"/> SUBSURFACE MONITORING <input type="checkbox"/> NUISANCE CONDITIONS <input type="checkbox"/> TANK TEST <input checked="" type="checkbox"/> TANK REMOVAL <input type="checkbox"/> OTHER		
	DATE DISCHARGE BEGAN <input checked="" type="checkbox"/> UNKNOWN		METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) <input type="checkbox"/> REMOVE CONTENTS <input checked="" type="checkbox"/> CLOSE TANK & REMOVE <input type="checkbox"/> REPAIR PIPING <input type="checkbox"/> REPAIR TANK <input type="checkbox"/> CLOSE TANK & FILL IN PLACE <input type="checkbox"/> CHANGE PROCEDURE <input type="checkbox"/> REPLACE TANK <input type="checkbox"/> OTHER		
	HAS DISCHARGE BEEN STOPPED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF YES, DATE 06/23/93				
SOURCE/CAUSE	SOURCE OF DISCHARGE <input checked="" type="checkbox"/> TANK LEAK <input type="checkbox"/> UNKNOWN <input type="checkbox"/> PIPING LEAK <input type="checkbox"/> OTHER		CAUSE(S) <input type="checkbox"/> OVERFILL <input type="checkbox"/> RUPTURE/FAILURE <input type="checkbox"/> SPILL <input type="checkbox"/> CORROSION <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> OTHER		
	CASE TYPE <input type="checkbox"/> UNDETERMINED <input type="checkbox"/> SOIL ONLY <input checked="" type="checkbox"/> GROUNDWATER <input type="checkbox"/> DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)				
CURRENT STATUS	CHECK ONE ONLY <input type="checkbox"/> NO ACTION TAKEN <input type="checkbox"/> PRELIMINARY SITE ASSESSMENT WORKPLAN SUBMITTED <input type="checkbox"/> POLLUTION CHARACTERIZATION <input type="checkbox"/> LEAK BEING CONFIRMED <input type="checkbox"/> PRELIMINARY SITE ASSESSMENT UNDERWAY <input type="checkbox"/> POST CLEANUP MONITORING IN PROGRESS <input type="checkbox"/> REMEDIATION PLAN <input checked="" type="checkbox"/> CASE CLOSED (CLEANUP COMPLETED OR UNNECESSARY) <input type="checkbox"/> CLEANUP UNDERWAY				
	CHECK APPROPRIATE ACTION(S) <input type="checkbox"/> CAP SITE (CD) <input type="checkbox"/> EXCAVATE & DISPOSE (ED) <input type="checkbox"/> REMOVE FREE PRODUCT (FP) <input type="checkbox"/> ENHANCED BIO DEGRADATION (IT) <input type="checkbox"/> CONTAINMENT BARRIER (CB) <input type="checkbox"/> EXCAVATE & TREAT (ET) <input type="checkbox"/> PUMP & TREAT GROUNDWATER (GT) <input type="checkbox"/> REPLACE SUPPLY (RS) <input type="checkbox"/> VACUUM EXTRACT (VE) <input checked="" type="checkbox"/> NO ACTION REQUIRED (NA) <input type="checkbox"/> TREATMENT AT HOOKUP (HU) <input type="checkbox"/> VENT SOIL (VS) <input type="checkbox"/> OTHER (OT)				

Soils have not been impacted by waste-oil related hydrocarbons or metals and only slightly impacted by gasoline-related hydrocarbons (2.4 ppm TPH-Gas). Groundwater has contained nondetectable levels of hydrocarbons since December 1993.



ALDO  
HAZMAT  
SA AUG -5 2:11:51

August 4, 1994

Ms. Eva Chu  
Alameda County Health Care Services Agency  
1131 Harbor Bay Parkway, 2nd Floor  
Alameda, CA 94502

Subject: Quarterly Groundwater Sampling at Shamrock Ford Site, 7499  
Dublin Boulevard, Dublin, California.

Ms. Chu:

This letter is written to document our telephone conversation on Monday, August 1, 1994, regarding quarterly groundwater sampling at the Shamrock Ford site, 7499 Dublin Boulevard, Dublin, California. In our conversation you have granted a verbal permission to discontinue sampling groundwater monitoring wells A-1 through A-3 for metals: cadmium, chromium, lead, nickel and zinc. During the third quarter 1994, groundwater samples collected from these wells will be analyzed for total petroleum hydrocarbons as gasoline (TPH-G); gasoline constituents benzene, toluene, ethylbenzene and total xylenes (BTEX); total petroleum hydrocarbons as diesel (TPH-D), total petroleum hydrocarbons as motor oil (TPH-MO), and oil and grease (O&G).

If you have any questions or comments, please call us at (510) 551-8777.

Sincerely,  
GeoStrategies Inc.

A handwritten signature in cursive script that reads "Barbara Sieminski".

Barbara Sieminski  
Project Geologist

cc: Mr. Craig Caldwell, Shamrock Ford

ALAMEDA COUNTY  
HEALTH CARE SERVICES  
AGENCY

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH  
State Water Resources Control Board  
Division of Clean Water Programs  
UST Local Oversight Program  
80 Swan Way, Rm 200  
Oakland, CA 94621  
(510) 271-4530

StID 2127

April 18, 1994

Ms. Barbara Sieminski  
GeoStrategies  
6747 Sierra Ct., Suite G  
Dublin, CA 94568

**Subject: QMR for Shamrock Ford, 7499 Dublin Blvd, Dublin 94568**

Dear Ms. Sieminski:

I have completed review of GeoStrategies' April 1994 Quarterly Groundwater Monitoring report for the above referenced site. At this time, please continue with monthly measurement of ground water elevation and quarterly sampling of the wells. It is also acceptable to discontinue sampling groundwater for VOC's.

Should groundwater continue to flow toward the northeast, it may be necessary to install another well in the downgradient direction from the former underground storage tanks. And we will continue to watch the slightly elevated levels of chromium and nickel in groundwater. The next sampling episode should be in June 1994.

If you have any questions, I can be reached at (510) 271-4530.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Eva Chu', written in dark ink.

eva chu  
Hazardous Materials Specialist

cc: Jim Woulfe, Shamrock Ford, 7499 Dublin Blvd, CA 94568  
files

ALAMEDA COUNTY  
HEALTH CARE SERVICES  
AGENCY

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH  
State Water Resources Control Board  
Division of Clean Water Programs  
UST Local Oversight Program  
80 Swan Way, Rm 200  
Oakland, CA 94621  
(510) 271-4530

StID 2127

February 2, 1994

Ms. Barbara Sieminski  
GeoStrategies  
6747 Sierra Ct., Suite G  
Dublin, CA 94568

**Subject: QMR for Shamrock Ford, 7499 Dublin Blvd., Dublin 94568**

Dear Ms. Sieminski:

I have completed review of GeoStrategies' January 1994 Initial Subsurface Investigation report for the above referenced site. Water level data seem to show flow direction toward the northeast. The regional flow direction has been toward the southeast to southwest. A schedule to measure groundwater elevation on a monthly basis should be established to verify gradient and flow direction. Also, a quarterly sampling schedule should be implemented for the site. Technical summary reports documenting each well sampling and monitoring episode are also due quarterly. This schedule shall continue until further notice.

If you have any questions, I can be reached at (510) 271-4530.

Sincerely,

A handwritten signature in black ink, appearing to read "Eva Chu".

eva chu  
Hazardous Materials Specialist

cc: Jim Woulfe, Shamrock Ford, 7499 Dublin Blvd, CA 94568  
files

shamrock.3

ALAMEDA COUNTY  
HEALTH CARE SERVICES  
AGENCY

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH

State Water Resources Control Board

Division of Clean Water Programs

UST Local Oversight Program

80 Swan Way, Rm 200

Oakland, CA 94621

(510) 271-4530

StID 2127

September 17, 1993

Mr. Jim Woulfe  
Shamrock Ford  
7499 Dublin Blvd.  
Dublin, CA 94568

*Craig Caldwell 829-5211*

**Subject: SWI for Shamrock Ford, 7499 Dublin Blvd., Dublin 94568**

Dear Mr. Woulfe:

This office has completed review of GeoStrategies' Underground Tank Removal Report, dated August 16, 1993, for the above referenced site. When two underground storage tanks (USTs) were removed, soil samples collected from the sidewalls of the UST pit indicated that soil has not been severely impacted by fuel products. However, groundwater samples collected, after water was purged from the pit, exhibited up to 8,600 parts per billion (ppb) Motor Oil, 3,600 ppb total petroleum hydrocarbons as gasoline and 67 ppb benzene. It appears groundwater may be impacted by fuel release from the former USTs.

At this time, further investigation is required to determine the extent of ground water contamination at the site. Such an investigation shall be in the form of a Soil/Water Investigation, or SWI. The information gathered by the SWI will be used to determine an appropriate course of action to remediate the site, if deemed necessary. The SWI must be conducted in accordance with the RWQCB Staff Recommendations for the Initial Evaluation and Investigation of Underground Tanks, and Article 11 of Title 23, California Code of Regulations. The major elements of such an investigation are summarized in the attached Appendix A.

The SWI proposal is due **within 45 days** of the date of this letter. Once the proposal is approved, field work should commence within 60 days. A report must be submitted within 45 days after the completion of this phase of work at the site. Subsequent reports are to be submitted quarterly until this site qualifies for RWQCB "sign off." All reports and proposals must be submitted under seal of a California Registered Geologist, Certified Engineering Geologist, or Registered Civil Engineer.

Please be advised that this is a formal request for technical reports pursuant to Title 23, CCR, Section 2722(c). Any extensions of the stated deadlines, or modifications of the required tasks, must be confirmed in writing by either this agency.

Mr. Jim Woulfe  
Shamrock Ford  
re: SWI for 7499 Dublin Blvd.  
September 17, 1993

Page 2

Should you have any questions about the content of this letter,  
please contact me at (510) 271-4530.

Sincerely,



Eva Chu  
Hazardous Materials Specialist

enclosure

cc: files

shamrock.1

ALAMEDA COUNTY  
HEALTH CARE SERVICES  
AGENCY

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH  
State Water Resources Control Board  
Division of Clean Water Programs  
UST Local Oversight Program  
80 Swan Way, Rm 200  
Oakland, CA 94621  
(510) 271-4530

StID 2127

November 15, 1993

Mr. Jim Woulfe:  
Shamrock Ford  
7499 Dublin Blvd  
Dublin, CA 94568

**Subject: Workplan Approval for 7499 Dublin Blvd, Dublin**

Dear Mr. Woulfe:

I have completed review of GeoStrategies' October 1993 Workplan for Initial Subsurface Investigation. The proposal to advance three soil borings and convert them into monitoring wells in order to evaluate the presence and extent of petroleum hydrocarbons in soil and groundwater is acceptable. Field work should commence within 45 days of the date of this letter. Any extensions of the stated deadlines, or modifications of the required tasks, must be confirmed in writing by either this agency or the RWQCB. Please notify this office at least 48 hours prior to the start of field activities.

If you have any questions, I can be reached at (510) 271-4530.

Sincerely,

eva chu  
Hazardous Materials Specialist

cc: Barbara Sieminski, GeoStrategies, 2140 W. Winton Ave., Hayward,  
CA 94545  
files

shamrock.2





GeoStrategies Inc.

LETTER OF TRANSMITTAL

Environmental Consulting  
Engineering and Geologic Services

DATE 8/20/93

TO: Ms. Eva Chew  
Alameda County Health Care Serv. Agency  
Hazardous Materials Division  
80 Swan Way Room 200  
Oakland

PROJECT NO. 610001  
SUBJECT: Underground Tank Removal Report  
for Shamrock Ford, 7499 Dublin Blvd  
Dublin, CA

THE FOLLOWING ITEMS ARE:

- ATTACHED
- FORWARDED SEPARATELY VIA \_\_\_\_\_

QUANTITY	PROJECT NO.	DATE	DESCRIPTION
1	610001-01	8/16/93	Underground Tank Removal Report for Shamrock Ford, 7499 Dublin Blvd., Dublin

93 AUG 24 PM 2:39

THESE ARE TRANSMITTED as checked below:

- For approval
- For your use
- As requested
- For review and
- Approved
- Approved as noted
- Returned for
- Other \_\_\_\_\_

COMMENTS:

[Empty box for comments]

Signed: Barbara Sieminski

- 2140 W. Winton Avenue, Hayward, CA 94545  
(510) 352-4800 - FAX (510) 783-1089
- 601 University Avenue, Suite 150, Sacramento, CA 95825  
(916) 568-7500 - FAX (916) 568-7504

Copies To:

<u>Mr. Craig Caldwell - Shamrock Ford</u>

white -env.health  
 yellow -facility  
 pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200  
 Oakland, CA 94621  
 (415) 271-4320

Hazardous Materials Inspection Form

II, III

Site ID # 117 Site Name Shamrock Foods Today's Date 6/29/93

Site Address 7499 Dublin Blvd.  
 City Dublin Zip 94568 Phone \_\_\_\_\_

MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Business Plans, Acute Hazardous Materials
- III. Underground Tanks

\* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

Comments:

Includes Tank Time 11:00 - 12:49

Water sample from waste oil pit. This is the initial water sample taken from this pit. After purging this pit, the exchanged water wasn't enough to cover the bottom of the pit.

Sample # W-7-T1

II.A BUSINESS PLANS (Title 19)

- 1. Immediate Reporting 2703
- 2. Bus. Plan Stds. 25503(b)
- 3. RR Cars > 30 days 25503.7
- 4. Inventory Information 25504(a)
- 5. Inventory Complete 2730
- 6. Emergency Response 25504(b)
- 7. Training 25504(c)
- 8. Deficiency 25505(a)
- 9. Modification 25505(b)

II.B ACUTELY HAZ. MATLS

- 10. Registration Form Filed 25533(a)
- 11. Form Complete 25533(b)
- 12. RMPP Contents 25534(c)
- 13. Implement Sch. Req'd? (Y/N)
- 14. OffSite Conseq. Assess. 25524(c)
- 15. Probable Risk Assessment 25534(d)
- 16. Persons Responsible 25534(g)
- 17. Certification 25534(i)
- 18. Exemption Request? (Y/N) 25536(b)
- 19. Trade Secret Requested? 25538

III. UNDERGROUND TANKS (Title 23)

- General
- 1. Permit Application 25284 (H&S)
  - 2. Pipeline Leak Detection 25292 (H&S)
  - 3. Records Maintenance 2712
  - 4. Release Report 2651
  - 5. Closure Plans 2670

- Monitoring for Existing Tanks
- 6. Method
    - 1) Monthly Test
    - 2) Daily Vadose Semi-annual groundwater One time soils
    - 3) Daily Vadose One time soils Annual tank test
    - 4) Monthly Gndwater One time soils
    - 5) Daily Inventory Annual tank testing Cont pipe leak def Vadose/gndwater mon.
    - 6) Daily Inventory Annual tank testing Cont pipe leak def
    - 7) Weekly Tank Gauge Annual tank testing
    - 8) Annual Tank Testing Daily Inventory
    - 9) Other \_\_\_\_\_

- 7. Precis Tank Test Date: \_\_\_\_\_ 2643
- 8. Inventory Rec. 2644
- 9. Soil Testing . 2646
- 10. Ground Water. 2647

- New Tanks
- 11. Monitor Plan 2632
  - 12. Access. Secure 2634
  - 13. Plans Submit Date: \_\_\_\_\_ 2711
  - 14. As Built Date: \_\_\_\_\_ 2635

Rev 6/88

Contact: (510) 352-4800  
 Title: Project Geologist  
 Signature: B. Niemiushin

Inspector: Jeff Shepard  
 Signature: Jeff Shepard

II, III

white -env.health  
 yellow -facility  
 pink -files

# ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200  
 Oakland, CA 94621  
 (415) 271-4320

## Hazardous Materials Inspection Form

II, III

Site ID # \_\_\_\_\_ Site Name SHAMRAK FLOW Today's Date 6/24/93

Site Address 7499 Dublin Blvd.

City Dublin Zip 94568 Phone \_\_\_\_\_

MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

4:30-5:30

**Inspection Categories:**

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Business Plans, Acute Hazardous Materials
- III. Underground Tanks

\* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

**Comments:**

WATER Sampling - Post Tank Removal

**II.A BUSINESS PLANS (Title 19)**

- 1. Immediate Reporting 2703
- 2. Bus. Plan Stats. 25503(b)
- 3. RR Cars > 30 days 25503.7
- 4. Inventory Information 25504(a)
- 5. Inventory Complete 2730
- 6. Emergency Response 25504(b)
- 7. Training 25504(c)
- 8. Deficiency 25505(a)
- 9. Modification 25505(b)

**II.B ACUTELY HAZ. MATLS**

- 10. Registration Form Filed 25533(a)
- 11. Form Complete 25533(b)
- 12. RMPP Contents 25534(c)
- 13. Implement Sch. Req'd? (Y/N) 25524(c)
- 14. OffSite Conseq. Assess. 25534(d)
- 15. Probable Risk Assessment 25534(d)
- 16. Persons Responsible 25534(g)
- 17. Certification 25534(f)
- 18. Exemption Request? (Y/N) 25536(b)
- 19. Trade Secret Requested? 25538

**III. UNDERGROUND TANKS (Title 23)**


- General**
- 1. Permit Application 25284 (H&S)
  - 2. Pipeline Leak Detection 25292 (H&S)
  - 3. Records Maintenance 2712
  - 4. Release Report 2651
  - 5. Closure Plans 2670

- Monitoring for Existing Tanks**
- 6. Method
    - 1) Monthly Test
    - 2) Daily Vadose
      - Semi-annual groundwater
      - One time soils
    - 3) Daily Vadose
      - One time soils
      - Annual tank test
    - 4) Monthly Groundwater
      - One time soils
    - 5) Daily Inventory
      - Annual tank testing
      - Cont pipe leak det
      - Vadose/groundwater mon.
    - 6) Daily Inventory
      - Annual tank testing
      - Cont pipe leak det
    - 7) Weekly Tank Gauge
      - Annual tank testing
    - 8) Annual Tank Testing
      - Daily inventory
    - 9) Other \_\_\_\_\_

- 7. Precis Tank Test 2643
  - Date: \_\_\_\_\_
- 8. Inventory Rec. 2644
- 9. Soil Testing . 2646
- 10. Ground Water. 2647

- New Tanks**
- 11. Monitor Plan 2632
  - 12. Access. Secure 2634
  - 13. Plans Submit 2711
    - Date: \_\_\_\_\_
  - 14. As Built 2635
    - Date: \_\_\_\_\_

Rev 6/88



THE WASTE OIL pit was purged once and AS OF 4:30 p.m. has not recharged. The Gasoline pit was purged twice and recharged. Its estimated that about 3000 Gallons of H2O was purged from both pits.

I WAS ON-SITE FOR THE GASOLINE Tank Pit H2O Sample, but not on-site for the WASTE OIL Tank Pit.

II, III

Contact: \_\_\_\_\_

Title: Foreman

Signature: James P. ...

Inspector: JEFF SHAW

Signature: Jeff Shaw

LOP - RECORD CHANGE REQUEST FORM

printed:  
09/13/95

Mark Out What Needs Changing and Hand to LOP Data Entry  
(Name/Address changes go to Annual Programs Data Entry)

Insp: EC

AGENCY # : 10000      SOURCE OF FUNDS: F      SUBSTANCE: 8006619  
 StID : 2127      LOC: -0-  
 SITE NAME: Shamrock Ford      DATE REPORTED : 06/23/93  
 ADDRESS : 7499 -0 Dublin Blvd      DATE CONFIRMED: 06/25/93  
 CITY/ZIP : Dublin      94568      MULTIPLE RPs : N

SITE STATUS

CASE TYPE: G      CONTRACT STATUS: 4      PRIOR CODE:3A1      EMERGENCY RESP: -0-  
 RP SEARCH: S      DATE COMPLETED: 07/09/93  
 PRELIMINARY ASMNT: C      DATE UNDERWAY: -0-      DATE COMPLETED: 11/17/94  
 REM INVESTIGATION: -      DATE UNDERWAY: -0-      DATE COMPLETED: -0-  
 REMEDIAL ACTION: -      DATE UNDERWAY: -0-      DATE COMPLETED: -0-  
 POST REMED ACT MON:-      DATE UNDERWAY: -0-      DATE COMPLETED: -0-

ENFORCEMENT ACTION TYPE: 1      DATE ENFORCEMENT ACTION TAKEN: 07/09/93  
 LUFT FIELD MANUAL CONSID: -0-  
 CASE CLOSED: Y      DATE CASE CLOSED: 09/15/95  
 DATE EXCAVATION STARTED : -0-      REMEDIAL ACTIONS TAKEN: -0-

RESPONSIBLE PARTY INFORMATION

RP#1-CONTACT NAME: Attn. Jim Woulfe  
 COMPANY NAME: Shamrock Ford  
 ADDRESS: 7499 Dublin Blvd  
 CITY/STATE: Dublin, C A 94568

INSPECTOR VERIFICATION:

NAME \_\_\_\_\_ SIGNATURE \_\_\_\_\_ DATE \_\_\_\_\_

DATA ENTRY INPUT:

Name/Address Changes Only			Case Progress Changes	
ANNPGMS _____	LOP _____	DATE _____	LOP _____	DATE _____

white -env.health  
 yellow -facility  
 pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200  
 Oakland, CA 94621  
 (415) 271-4320

Hazardous Materials Inspection Form

P.1

II, III

Site ID # \_\_\_\_\_ Site Name SHAMROCK FINES Today's Date 8/23/93

Site Address 7499 Dublin Blvd.

City Dublin Zip 94568 Phone \_\_\_\_\_

MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Business Plans, Acute Hazardous Materials
- III. Underground Tanks

\* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

Comments:

Tank Removal

1-2000 GAL. GASOLINE + 1-1000 GAL WASTE OIL  
 Time 10:30 A.M. - Delay of 45 mins. - H+H NOT ON-SITE.

This Tank Failed an integrity (550 Gallon waste oil) The sluff being removed from the tank has the odor of waste oil - At least 10 Holes in Tank. ONE Hole is about 1.5" x 1.5". In this inspector's opinion, the odor is similar to that of a chlorinated solvent.

BOTH Tank PITS Show Visual Signs of Ground Water Contamination. Therefore, I will allow each Tank PIT to be purged at least once before taking a water sample.

THE GASOLINE TANK HAS NO APPARENT HOLES. HOWEVER, there are signs of overspill/overflow. Apparently, the gasoline dissolved part of the tank wrap around the tank. Presently, there is tank oil floating on top of the H<sub>2</sub>O.

II.A BUSINESS PLANS (Title 19)

- 1. Immediate Reporting 2703
- 2. Bus. Plan Stats. 25503(b)
- 3. RR Cars > 30 days 25503.7
- 4. Inventory Information 25504(a)
- 5. Inventory Complete 2730
- 6. Emergency Response 25504(b)
- 7. Training 25504(c)
- 8. Deficiency 25505(a)
- 9. Modification 25505(b)

II.B ACUTELY HAZ. MATLS

- 10. Registration Form Filed 25533(a)
- 11. Form Complete 25533(b)
- 12. RMPP Contents 25534(c)
- 13. Implement Sch. Req'd? (Y/N)
- 14. OffSite Conseq. Assess. 25524(c)
- 15. Probable Risk Assessment 25534(d)
- 16. Persons Responsible 25534(g)
- 17. Certification 25534(i)
- 18. Exemption Request? (Y/N) 25536(b)
- 19. Trade Secret Requested? 25538

III. UNDERGROUND TANKS (Title 23)

- General
- 1. Permit Application 25284 (H&S)
  - 2. Pipeline Leak Detection 25292 (H&S)
  - 3. Records Maintenance 2712
  - 4. Release Report 2651
  - 5. Closure Plans 2670

Monitoring for Existing Tanks

- 6. Method
  - 1) Monthly Test
  - 2) Daily Vadose Semi-annual groundwater One time soils
  - 3) Daily Vadose One time soils Annual tank test
  - 4) Monthly Gndwater One time soils
  - 5) Daily Inventory Annual tank testing Cont pipe leak det Vadose/gndwater mon.
  - 6) Daily Inventory Annual tank testing Cont pipe leak det
  - 7) Weekly Tank Gauge Annual tank testing
  - 8) Annual Tank Testing Daily Inventory
  - 9) Other \_\_\_\_\_

- 7. Precis Tank Test 2643  
Date: \_\_\_\_\_
- 8. Inventory Rec. 2644
- 9. Soil Testing . 2646
- 10. Ground Water. 2647

- New Tanks
- 11. Monitor Plan 2632
  - 12. Access. Secure 2634
  - 13. Plans Submit 2711  
Date: \_\_\_\_\_
  - 14. As Built 2635  
Date: \_\_\_\_\_

Rev 6/88

Contact: James P. Allen

Title: Farmer

Signature: \_\_\_\_\_

Inspector: Jeff Shapiro

Signature: \_\_\_\_\_

II, III

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

80 Swan Way, #200  
Oakland, CA 94621  
(415) 271-4320

Hazardous Materials Inspection Form

P.2

II, III

white - env. health  
yellow - facility  
pink - files

Site ID # \_\_\_\_\_ Site Name SAAMROCK FORD Today's Date 6/23/93

Site Address 7499 Dublin Blvd.

City Dublin Zip 94568 Phone \_\_\_\_\_


MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Business Plans, Acute Hazardous Materials
- III. Underground Tanks

\* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

Comments:



Sample 1 - ~~5-7-T1-1~~ 5-7-T1-1  
 " 2 - ~~5-7-T1-2~~ 5-7-T1-2  
 " 3 - 5-7-T2-1  
 " 4 5-7-T2-2

~~Water sampling will be performed on 6/24/93, after the pits are purged and allowed to recharge.~~  
 Water sampling will be performed on 6/24/93, after the pits are purged and allowed to recharge.

II.A BUSINESS PLANS (Title 19)

- 1. Immediate Reporting 2703
- 2. Bus. Plan Stds. 25503(b)
- 3. RR Cars > 30 days 25503.7
- 4. Inventory Information 25504(a)
- 5. Inventory Complete 2730
- 6. Emergency Response 25504(b)
- 7. Training 25504(c)
- 8. Deficiency 25505(a)
- 9. Modification 25505(b)

II.B ACUTELY HAZ. MATLS

- 10. Registration Form Filed 25533(a)
- 11. Form Complete 25533(b)
- 12. RMPP Contents 25534(c)
- 13. Implement Sch. Req'd? (Y/N)
- 14. OffSite Conseq. Assess. 25524(c)
- 15. Probable Risk Assessment 25534(d)
- 16. Persons Responsible 25534(g)
- 17. Certification 25534(i)
- 18. Exemption Request? (Y/N) 25536(b)
- 19. Trade Secret Requested? 25538

III. UNDERGROUND TANKS (Title 23)

- General
- 1. Permit Application 25284 (H&S)
  - 2. Pipeline Leak Detection 25292 (H&S)
  - 3. Records Maintenance 2712
  - 4. Release Report 2651
  - 5. Closure Plans 2670

- Monitoring for Existing Tanks
- 6. Method
    - 1) Monthly Test
    - 2) Daily Vadose
    - Semi-annual groundwater
    - One time soils
    - 3) Daily Vadose
    - One time soils
    - Annual tank test
    - 4) Monthly Gndwater
    - One time soils
    - 5) Daily Inventory
    - Annual tank testing
    - Cont pipe leak det
    - Vadose/gndwater mon.
    - 6) Daily Inventory
    - Annual tank testing
    - Cont pipe leak det
    - 7) Weekly Tank Gauge
    - Annual tank tising
    - 8) Annual Tank Testing
    - Daily inventory
    - 9) Other \_\_\_\_\_

- 7. Precs Tank Test 2643  
Date: \_\_\_\_\_
- 8. Inventory Rec. 2644
- 9. Soil Testing . 2646
- 10. Ground Water. 2647

- New Tanks
- 11. Monitor Plan 2632
  - 12. Access. Secure 2634
  - 13. Plans Submit 2711  
Date: \_\_\_\_\_
  - 14. As Built 2635  
Date: \_\_\_\_\_

Contact: \_\_\_\_\_

Title: \_\_\_\_\_

Signature: James T. [unclear]

Inspector: Jeff [unclear]

Signature: Jeff [unclear]

II, III



6. Contractor GETTLER - RYAN INC.  
Address 2150 W. WINTON AVE  
City HAYWARD Phone (510) 783-7500  
License Type\* A, B C61/D40 HAZA ID# 220793

\*Effective January 1, 1992, Business and Professional Code Section 7058.7 requires prime contractors to also hold Hazardous Waste Certification issued by the State Contractors License Board. Indicate that the certificate has been received, in addition, to holding the appropriate contractors license type.

7. Consultant GEO STRATEGIES INC  
Address 2140 W. WINTON AVE  
City HAYWARD Phone (510) 352-4800

8. Contact Person for Investigation  
Name CRAIG CALDWELL Title VICE - PRESIDENT  
Phone (510) 829-5211

9. Number of tanks being closed under this plan 2  
Length of piping being removed under this plan 20' APPROX  
Total number of tanks at facility 3

10. State Registered Hazardous Waste Transporters/Facilities (see instructions).

\*\* Underground tanks are hazardous waste and must be handled \*\*  
as hazardous waste

a) Product/Residual Sludge/Rinsate Transporter

Name H+H SHIP SERVICE EPA I.D. No. CA0004771168  
Hauler License No. 0334 License Exp. Date 1/31/94  
Address 220 CHINA BASIN  
City SAN FRANCISCO State CA Zip 94107

b) Product/Residual Sludge/Rinsate Disposal Site

Name H & H SHIP SERVICE EPA I.D. No. \_\_\_\_\_  
Address SAME  
City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_



c) Tank and Piping Transporter

Name H & H SHIP SERVICE EPA I.D. No. \_\_\_\_\_  
Hauler License No. \_\_\_\_\_ License Exp. Date \_\_\_\_\_  
Address SAME  
City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_

d) Tank and Piping Disposal Site

Name H & H SHIP SERVICE EPA I.D. No. \_\_\_\_\_  
Address SAME  
City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_

11. Experienced Sample Collector

Name CLYDE GALANTINE OR ROBERT MALLORY  
Company GEO STRATEGIES  
Address 2140 W. WINTON AVE  
City HAYWARD State CA Zip 94545 Phone (510)352-4800

12. Laboratory

Name WESTERN ENVIRONMENTAL SCIENCE & TECHNOLOGY  
Address 45133 COUNTY RD 32 B  
City DAVIS State CA Zip 95616  
State Certification No. 1346

13. Have tanks or pipes leaked in the past? Yes  No

If yes, describe. WASTE OIL TANKS FAILED A TANK TEST  
IN 1987.

14. Describe methods to be used for rendering tank inert

DRY ICE - 30 LBS PER 1000 GALLON  
VENTILATION. OR ENOUGH TO INERT EACH TANK

Before tanks are pumped out and inerted, all associated piping must be flushed out into the tanks. All accessible associated piping must then be removed. Inaccessible piping must be plugged.

The Bay Area Air Quality Management District (771-6000), along with local Fire and Building Departments, must also be contacted for tank removal permits. Fire departments typically require the use of explosion proof combustible gas meters to verify tank inertness. It is the contractor's responsibility to bring a working combustible gas meter on site to verify tank inertness.

15. Tank History and Sampling Information

Tank		Material to be sampled (tank contents, soil, ground-water, etc.)	Location and Depth of Samples
Capacity	Use History (see instructions)		
2000 GALLONS	GASOLINE INSTALLED 1977	SOIL	2 SAMPLES @ NATIVE SOIL/ BACKFILL INTERFACE
<del>1000</del> 500 GALLON	WASTE OIL INSTALLED 1974	SOIL	1 SAMPLE @ NATIVE SOIL/ BACKFILL INTERFACE

One soil sample must be collected for every 20 feet of piping that is removed. A ground water sample must be collected should any ground water be present in the excavation.

Must be placed on

Excavated/Stockpiled Soil	
U. GUANO & COVERED Stockpiled Soil Volume (Estimated) DISCREET - 1 sample/20 yds <sup>3</sup> (BACK IN HOLE)	Sampling Plan Soil samples will be placed in brass tubes, sealed w/ Teflon tape and plastic caps.
Composite 1 sample/50 yds <sup>3</sup> - off site	Samples must be placed on ice and transported to a state certified lab w/ chain of custody.

Stockpiled soil must be placed on bermed plastic and must be completely covered by plastic sheeting.

16. Chemical methods and associated detection limits to be used for analyzing samples

The Tri-Regional Board recommended minimum verification analyses and practical quantitation reporting limits should be followed. See attached Table 2.

Contaminant Sought	EPA, DHS, or Other Sample Preparation Method Number	EPA, DHS, or Other Analysis Method Number	Method Detection Limit
GAS TPH - GAS BTX + E		8015/8020	
WASTE oil TPH - DIESEL BTX + E CHLORINATED HYDROCARBONS TOTAL LEAD METALS / ICAF Oil & Grease	Cd, Cr, Pb, Zn, Ni,	8015 MODIFIED 8020 8240 7420 5520 418	

17. Submit Site Health and Safety Plan (See Instructions)

18. Submit Worker's Compensation Certificate copy

Name of Insurer REPUBLIC INDEMNITY

19. Submit Plot Plan (See Instructions)

20. Enclose Deposit (See Instructions)

21. Report any leaks or contamination to this office within 5 days of discovery. The report shall be made on an Underground Storage Tank Unauthorized Leak/Contamination Site Report form. (see Instructions)

22. Submit a closure report to this office within 60 days of the tank removal. This report must contain all the information listed in item 22 of the instructions.

I declare that to the best of my knowledge and belief the statements and information provided above are correct and true.

I understand that information in addition to that provided above may be needed in order to obtain an approval from the Department of Environmental Health and that no work is to begin on this project until this plan is approved.

I understand that any changes in design, materials or equipment will void this plan if prior approval is not obtained.

I understand that all work performed during this project will be done in compliance with all applicable OSHA (Occupational Safety and Health Administration) requirements concerning personnel health and safety. I understand that site and worker safety are solely the responsibility of the property owner or his agent and that this responsibility is not shared nor assumed by the County of Alameda.

Once I have received my stamped, accepted closure plan, I will contact the project Hazardous Materials Specialist at least three working days in advance of site work to schedule the required inspections.

Signature of Contractor

Name (please type) DAVID A. BYRON - GETTLER-RYAN INC

Signature David A. Byron

Date 2/12/93

Signature of Site Owner or Operator

Name (please type) CRAIG CALDWELL - SHAMROCK FORD

Signature Craig Caldwell

Date 2/12/93



SITE SAFETY PLAN, JOB #1105.01

GENERAL INFORMATION

SITE:                      Company:              Shamrock Ford  
                                 Location:              7499 Dublin Boulevard  
                                 City:                    Dublin, California

PLAN PREPARED BY:    Gettler-Ryan Inc.                      DATE: 01/16/93

OBJECTIVES:            To provide a safety plan for the safe completion of the site work.

PROPOSED DATE OF SITE WORK: 2/22/93

DOCUMENTATION/  
SUMMARY:

Hazardous material may be present, caution is advised. Site work includes removing 2 underground storage tanks and install new above ground tank.

SITE/WASTE CHARACTERISTICS

WASTE TYPE(S):        Liquid                  Solid                  Gas

CHARACTERISTIC(S):    Volatile              Flammable            Toxic

FACILITY DESCRIPTION: New car dealership with underground utilities.

STATUS:

HAZARD EVALUATION

PARAMETER: TLV 300 ppm THC  
HEALTH: ingestion, inhalation, absorption  
LEL 10% Gastehtor max.

**SPECIAL PRECAUTIONS  
AND COMMENTS:**

Correct safety procedures must be followed, per Gettler-Ryan Inc. Health and Safety Plan. UGST to be inerted per BAAQMD guidelines (Reg. 8, Section 40) 300 lbs. of dry ice/1,000-gallon capacity to be placed in each tank prior to removal.

**SITE SAFETY WORKPLAN:**

**PERIMETER ESTABLISHMENT:**

Use barricades and flagging to restrict access to tank removal area.  
Tank excavation to be fenced while hole is open.

**PERSONAL PROTECTION:**

Level of Protection EPA Level D  
Modifications: Rubber gloves and hard hats  
Surveillance Equipment and Material: Gastech

**SITE ENTRY PROCEDURES:** None

**DECONTAMINATION  
PROCEDURES:**

Personnel: Wash thoroughly with detergent solution and water

Equipment: Steam clean as necessary

**FIRST AID:** As applicable

**WORK LIMITATIONS (time of day, weather, heat/cold stress):** none

**INVESTIGATION-DERIVED  
MATERIAL DISPOSAL:**

Tanks and lines to be manifested and hauled by Erickson. All materials removed from tank hole to be sampled, placed on visqueen on site and covered until classified for proper disposal.

**TEAM COMPOSITION:**

Jim Reed - Job Foreman and site safety officer  
2 Laborers  
1 Operator  
1 Field Technician from GeoStrategies Inc.

**EMERGENCY INFORMATION**

**LOCAL RESOURCES:** Ambulance/Hospital Dial 911  
Police/Sheriff/Hwy Patrol Dial 911  
Fire Department Dial 911

**SITE RESOURCES:** Water Supply  
Telephone  
Visqueen  
Fire Extinguisher  
First Aid Kit  
Sorbant Pads

**EMERGENCY CONTACT:** Gettler-Ryan Inc. 1-510-783-7500


**EMERGENCY ROUTES:** Nearest emergency hospital is:  
  
San Ramon Regional Medical Center  
6001 Norris Canyon Road  
San Ramon, California 94583  
1-510-275-9200

Map Attached

**A Full Service 125-Bed Acute Care Hospital**

- Medical, Surgical & Pediatric Care
- 24 Hour Emergency Service
- Obstetrics
- Intensive and Coronary Care
- Physician Referral Service
- Outpatient Surgery and Diagnostic Center
- Center for Reproductive Medicine
- Occupational Medicine
- New Beginnings
- Chemical Dependency Unit

**275-9200**



**SAN RAMON REGIONAL MEDICAL CENTER**

6001 Norris Canyon Road, San Ramon, California 94583

A National Medical Enterprises Health Care Facility

(d)  
 667 3215  
 667 3216  
 667 3217  
 667 3218  
 667 3219  
 667 3220  
 667 3221  
 667 3222  
 667 3223  
 667 3224  
 667 3225  
 667 3226  
 667 3227  
 667 3228  
 667 3229  
 667 3230  
 667 3231  
 667 3232  
 667 3233  
 667 3234  
 667 3235  
 667 3236  
 667 3237  
 667 3238  
 667 3239  
 667 3240  
 667 3241  
 667 3242  
 667 3243  
 667 3244  
 667 3245  
 667 3246  
 667 3247  
 667 3248  
 667 3249  
 667 3250  
 667 3251  
 667 3252  
 667 3253  
 667 3254  
 667 3255  
 667 3256  
 667 3257  
 667 3258  
 667 3259  
 667 3260  
 667 3261  
 667 3262  
 667 3263  
 667 3264  
 667 3265  
 667 3266  
 667 3267  
 667 3268  
 667 3269  
 667 3270  
 667 3271  
 667 3272  
 667 3273  
 667 3274  
 667 3275  
 667 3276  
 667 3277  
 667 3278  
 667 3279  
 667 3280  
 667 3281  
 667 3282  
 667 3283  
 667 3284  
 667 3285  
 667 3286  
 667 3287  
 667 3288  
 667 3289  
 667 3290  
 667 3291  
 667 3292  
 667 3293  
 667 3294  
 667 3295  
 667 3296  
 667 3297  
 667 3298  
 667 3299  
 667 3300  
 667 3301  
 667 3302  
 667 3303  
 667 3304  
 667 3305  
 667 3306  
 667 3307  
 667 3308  
 667 3309  
 667 3310  
 667 3311  
 667 3312  
 667 3313  
 667 3314  
 667 3315  
 667 3316  
 667 3317  
 667 3318  
 667 3319  
 667 3320  
 667 3321  
 667 3322  
 667 3323  
 667 3324  
 667 3325  
 667 3326  
 667 3327  
 667 3328  
 667 3329  
 667 3330  
 667 3331  
 667 3332  
 667 3333  
 667 3334  
 667 3335  
 667 3336  
 667 3337  
 667 3338  
 667 3339  
 667 3340  
 667 3341  
 667 3342  
 667 3343  
 667 3344  
 667 3345  
 667 3346  
 667 3347  
 667 3348  
 667 3349  
 667 3350  
 667 3351  
 667 3352  
 667 3353  
 667 3354  
 667 3355  
 667 3356  
 667 3357  
 667 3358  
 667 3359  
 667 3360  
 667 3361  
 667 3362  
 667 3363  
 667 3364  
 667 3365  
 667 3366  
 667 3367  
 667 3368  
 667 3369  
 667 3370  
 667 3371  
 667 3372  
 667 3373  
 667 3374  
 667 3375  
 667 3376  
 667 3377  
 667 3378  
 667 3379  
 667 3380  
 667 3381  
 667 3382  
 667 3383  
 667 3384  
 667 3385  
 667 3386  
 667 3387  
 667 3388  
 667 3389  
 667 3390  
 667 3391  
 667 3392  
 667 3393  
 667 3394  
 667 3395  
 667 3396  
 667 3397  
 667 3398  
 667 3399  
 667 3400  
 667 3401  
 667 3402  
 667 3403  
 667 3404  
 667 3405  
 667 3406  
 667 3407  
 667 3408  
 667 3409  
 667 3410  
 667 3411  
 667 3412  
 667 3413  
 667 3414  
 667 3415  
 667 3416  
 667 3417  
 667 3418  
 667 3419  
 667 3420  
 667 3421  
 667 3422  
 667 3423  
 667 3424  
 667 3425  
 667 3426  
 667 3427  
 667 3428  
 667 3429  
 667 3430  
 667 3431  
 667 3432  
 667 3433  
 667 3434  
 667 3435  
 667 3436  
 667 3437  
 667 3438  
 667 3439  
 667 3440  
 667 3441  
 667 3442  
 667 3443  
 667 3444  
 667 3445  
 667 3446  
 667 3447  
 667 3448  
 667 3449  
 667 3450  
 667 3451  
 667 3452  
 667 3453  
 667 3454  
 667 3455  
 667 3456  
 667 3457  
 667 3458  
 667 3459  
 667 3460  
 667 3461  
 667 3462  
 667 3463  
 667 3464  
 667 3465  
 667 3466  
 667 3467  
 667 3468  
 667 3469  
 667 3470  
 667 3471  
 667 3472  
 667 3473  
 667 3474  
 667 3475  
 667 3476  
 667 3477  
 667 3478  
 667 3479  
 667 3480  
 667 3481  
 667 3482  
 667 3483  
 667 3484  
 667 3485  
 667 3486  
 667 3487  
 667 3488  
 667 3489  
 667 3490  
 667 3491  
 667 3492  
 667 3493  
 667 3494  
 667 3495  
 667 3496  
 667 3497  
 667 3498  
 667 3499  
 667 3500  
 667 3501  
 667 3502  
 667 3503  
 667 3504  
 667 3505  
 667 3506  
 667 3507  
 667 3508  
 667 3509  
 667 3510  
 667 3511  
 667 3512  
 667 3513  
 667 3514  
 667 3515  
 667 3516  
 667 3517  
 667 3518  
 667 3519  
 667 3520  
 667 3521  
 667 3522  
 667 3523  
 667 3524  
 667 3525  
 667 3526  
 667 3527  
 667 3528  
 667 3529  
 667 3530  
 667 3531  
 667 3532  
 667 3533  
 667 3534  
 667 3535  
 667 3536  
 667 3537  
 667 3538  
 667 3539  
 667 3540  
 667 3541  
 667 3542  
 667 3543  
 667 3544  
 667 3545  
 667 3546  
 667 3547  
 667 3548  
 667 3549  
 667 3550  
 667 3551  
 667 3552  
 667 3553  
 667 3554  
 667 3555  
 667 3556  
 667 3557  
 667 3558  
 667 3559  
 667 3560  
 667 3561  
 667 3562  
 667 3563  
 667 3564  
 667 3565  
 667 3566  
 667 3567  
 667 3568  
 667 3569  
 667 3570  
 667 3571  
 667 3572  
 667 3573  
 667 3574  
 667 3575  
 667 3576  
 667 3577  
 667 3578  
 667 3579  
 667 3580  
 667 3581  
 667 3582  
 667 3583  
 667 3584  
 667 3585  
 667 3586  
 667 3587  
 667 3588  
 667 3589  
 667 3590  
 667 3591  
 667 3592  
 667 3593  
 667 3594  
 667 3595  
 667 3596  
 667 3597  
 667 3598  
 667 3599  
 667 3600  
 667 3601  
 667 3602  
 667 3603  
 667 3604  
 667 3605  
 667 3606  
 667 3607  
 667 3608  
 667 3609  
 667 3610  
 667 3611  
 667 3612  
 667 3613  
 667 3614  
 667 3615  
 667 3616  
 667 3617  
 667 3618  
 667 3619  
 667 3620  
 667 3621  
 667 3622  
 667 3623  
 667 3624  
 667 3625  
 667 3626  
 667 3627  
 667 3628  
 667 3629  
 667 3630  
 667 3631  
 667 3632  
 667 3633  
 667 3634  
 667 3635  
 667 3636  
 667 3637  
 667 3638  
 667 3639  
 667 3640  
 667 3641  
 667 3642  
 667 3643  
 667 3644  
 667 3645  
 667 3646  
 667 3647  
 667 3648  
 667 3649  
 667 3650  
 667 3651  
 667 3652  
 667 3653  
 667 3654  
 667 3655  
 667 3656  
 667 3657  
 667 3658  
 667 3659  
 667 3660  
 667 3661  
 667 3662  
 667 3663  
 667 3664  
 667 3665  
 667 3666  
 667 3667  
 667 3668  
 667 3669  
 667 3670  
 667 3671  
 667 3672  
 667 3673  
 667 3674  
 667 3675  
 667 3676  
 667 3677  
 667 3678  
 667 3679  
 667 3680  
 667 3681  
 667 3682  
 667 3683  
 667 3684  
 667 3685  
 667 3686  
 667 3687  
 667 3688  
 667 3689  
 667 3690  
 667 3691  
 667 3692  
 667 3693  
 667 3694  
 667 3695  
 667 3696  
 667 3697  
 667 3698  
 667 3699  
 667 3700  
 667 3701  
 667 3702  
 667 3703  
 667 3704  
 667 3705  
 667 3706  
 667 3707  
 667 3708  
 667 3709  
 667 3710  
 667 3711  
 667 3712  
 667 3713  
 667 3714  
 667 3715  
 667 3716  
 667 3717  
 667 3718  
 667 3719  
 667 3720  
 667 3721  
 667 3722  
 667 3723  
 667 3724  
 667 3725  
 667 3726  
 667 3727  
 667 3728  
 667 3729  
 667 3730  
 667 3731  
 667 3732  
 667 3733  
 667 3734  
 667 3735  
 667 3736  
 667 3737  
 667 3738  
 667 3739  
 667 3740  
 667 3741  
 667 3742  
 667 3743  
 667 3744  
 667 3745  
 667 3746  
 667 3747  
 667 3748  
 667 3749  
 667 3750  
 667 3751  
 667 3752  
 667 3753  
 667 3754  
 667 3755  
 667 3756  
 667 3757  
 667 3758  
 667 3759  
 667 3760  
 667 3761  
 667 3762  
 667 3763  
 667 3764  
 667 3765  
 667 3766  
 667 3767  
 667 3768  
 667 3769  
 667 3770  
 667 3771  
 667 3772  
 667 3773  
 667 3774  
 667 3775  
 667 3776  
 667 3777  
 667 3778  
 667 3779  
 667 3780  
 667 3781  
 667 3782  
 667 3783  
 667 3784  
 667 3785  
 667 3786  
 667 3787  
 667 3788  
 667 3789  
 667 3790  
 667 3791  
 667 3792  
 667 3793  
 667 3794  
 667 3795  
 667 3796  
 667 3797  
 667 3798  
 667 3799  
 667 3800  
 667 3801  
 667 3802  
 667 3803  
 667 3804  
 667 3805  
 667 3806  
 667 3807  
 667 3808  
 667 3809  
 667 3810  
 667 3811  
 667 3812  
 667 3813  
 667 3814  
 667 3815  
 667 3816  
 667 3817  
 667 3818  
 667 3819  
 667 3820  
 667 3821  
 667 3822  
 667 3823  
 667 3824  
 667 3825  
 667 3826  
 667 3827  
 667 3828  
 667 3829  
 667 3830  
 667 3831  
 667 3832  
 667 3833  
 667 3834  
 667 3835  
 667 3836  
 667 3837  
 667 3838  
 667 3839  
 667 3840  
 667 3841  
 667 3842  
 667 3843  
 667 3844  
 667 3845  
 667 3846  
 667 3847  
 667 3848  
 667 3849  
 667 3850  
 667 3851  
 667 3852  
 667 3853  
 667 3854  
 667 3855  
 667 3856  
 667 3857  
 667 3858  
 667 3859  
 667 3860  
 667 3861  
 667 3862  
 667 3863  
 667 3864  
 667 3865  
 667 3866  
 667 3867  
 667 3868  
 667 3869  
 667 3870  
 667 3871  
 667 3872  
 667 3873  
 667 3874  
 667 3875  
 667 3876  
 667 3877  
 667 3878  
 667 3879  
 667 3880  
 667 3881  
 667 3882  
 667 3883  
 667 3884  
 667 3885  
 667 3886  
 667 3887  
 667 3888  
 667 3889  
 667 3890  
 667 3891  
 667 3892  
 667 3893  
 667 3894  
 667 3895  
 667 3896  
 667 3897  
 667 3898  
 667 3899  
 667 3900  
 667 3901  
 667 3902  
 667 3903  
 667 3904  
 667 3905  
 667 3906  
 667 3907  
 667 3908  
 667 3909  
 667 3910  
 667 3911  
 667 3912  
 667 3913  
 667 3914  
 667 3915  
 667 3916  
 667 3917  
 667 3918  
 667 3919  
 667 3920  
 667 3921  
 667 3922  
 667 3923  
 667 3924  
 667 3925  
 667 3926  
 667 3927  
 667 3928  
 667 3929  
 667 3930  
 667 3931  
 667 3932  
 667 3933  
 667 3934  
 667 3935  
 667 3936  
 667 3937  
 667 3938  
 667 3939  
 667 3940  
 667 3941  
 667 3942  
 667 3943  
 667 3944  
 667 3945  
 667 3946  
 667 3947  
 667 3948  
 667 3949  
 667 3950  
 667 3951  
 667 3952  
 667 3953  
 667 3954  
 667 3955  
 667 3956  
 667 3957  
 667 3958  
 667 3959  
 667 3960  
 667 3961  
 667 3962  
 667 3963  
 667 3964  
 667 3965  
 667 3966  
 667 3967  
 667 3968  
 667 3969  
 667 3970  
 667 3971  
 667 3972  
 667 3973  
 667 3974  
 667 3975  
 667 3976  
 667 3977  
 667 3978  
 667 3979  
 667 3980  
 667 3981  
 667 3982  
 667 3983  
 667 3984  
 667 3985  
 667 3986  
 667 3987  
 667 3988  
 667 3989  
 667 3990  
 667 3991  
 667 3992  
 667 3993  
 667 3994  
 667 3995  
 667 3996  
 667 3997  
 667 3998  
 667 3999  
 667 4000  
 667 4001  
 667 4002  
 667 4003  
 667 4004  
 667 4005  
 667 4006  
 667 4007  
 667 4008  
 667 4009  
 667 4010  
 667 4011  
 667 4012  
 667 4013  
 667 4014  
 667 4015  
 667 4016  
 667 4017  
 667 4018  
 667 4019  
 667 4020  
 667 4021  
 667 4022  
 667 4023  
 667 4024  
 667 4025  
 667 4026  
 667 4027  
 667 4028  
 667 4029  
 667 4030  
 667 4031  
 667 4032  
 667 4033  
 667 4034  
 667 4035  
 667 4036  
 667 4037  
 667 4038  
 667 4039  
 667 4040  
 667 4041  
 667 4042  
 667 4043  
 667 4044  
 667 4045  
 667 4046  
 667 4047  
 667 4048  
 667 4049  
 667 4050  
 667 4051  
 667 4052  
 667 4053  
 667 4054  
 667 4055  
 667 4056  
 667 4057  
 667 4058  
 667 4059  
 667 4060  
 667 4061  
 667 4062  
 667 4063  
 667 4064  
 667 4065  
 667 4066  
 667 4067  
 667 4068  
 667 4069  
 667 4070  
 667 4071  
 667 4072  
 667 4073  
 667 4074  
 667 4075  
 667 4076  
 667 4077  
 667 4078  
 667 4079  
 667 4080  
 667 4081  
 667 4082  
 667 4083  
 667 4084  
 667 4085  
 667 4086  
 667 4087  
 667 4088  
 667 4089  
 667 4090  
 667 4091  
 667 4092  
 667 4093  
 667 4094  
 667 4095  
 667 4096  
 667 4097  
 667 4098  
 667 4099  
 667 4100  
 667 4101  
 667 4102  
 667 4103  
 667 4104  
 667 4105  
 667 4106  
 667 4107  
 667 4108  
 667 4109  
 667 4110  
 667 4111  
 667 4112  
 667 4113  
 667 4114  
 667 4115  
 667 4116  
 667 4117  
 667 4118  
 667