

HKz, Inc. / SEMCO 1751 Leslie Street, San Mateo, CA 94402

FAX

Date: 6-5 97
 Number of pages including cover sheet: 4

To: JULIET

 Phone: _____
 Fax phone: 510.337.9335
 CC: _____

From: DENN

 Phone: 415-572-8033
 Fax phone: 415-572-9734

REMARKS: Urgent For your review Reply ASAP Please comment

LAB DATA SHOWING RESULTS ON SOIL CUTTINGS
 AT 510 LINCOLN AVENUE, ALAMEDA.

Reviewed and Approved



North State Environmental
 Chemical Waste Disposal Trucking - Consulting

CERTIFICATE OF ANALYSIS

Lab Number: 97-417
 Client: Semco HK2
 Project: 510 Lincoln Ave., Alameda, CA #97-0153

Date Reported: 06/02/97

Diesel Range Hydrocarbons by Method 8015 M
 Benzene, Toluene, Ethylbenzene and Xylenes by Method 8020
 Total Cadmium, Chromium, Nickel, Lead and Zinc by AA Spectro

Analyte	Method	Result	Unit	Date Sampled	Date Analyzed
Sample: 97-417-01		Client ID: SP-1,2,3			SOIL COMP.
Benzene	8020	ND		05/16/97	05/23/97
Ethylbenzene	8020	ND			
Toluene	8020	ND			
Xylenes	8020	ND			
Cadmium	7130	ND			05/21/97
Chromium	7190	32	mg/Kg		
Lead	7420	12	mg/Kg		
Nickel	7520	26	mg/Kg		
Zinc	7950	25	mg/Kg		
Diesel	8015M	ND			05/29/97

Page

P O Box 5624 • South San Francisco, California 94087 • 415-588-2838 FAX 415-588-2838



North State Environmental
Chemical Waste Disposal • Tracking • Consulting

CERTIFICATE OF ANALYSIS

Quality Control/Quality Assurance

Lab Number: 97-417
Client: Semco HK2
Project: 510 Lincoln Ave., Alameda, CA #97-0153

Date Reported: 06/02/97

Diesel Range Hydrocarbons by Method 8015 M
Benzene, Toluene, Ethylbenzene and Xylenes by Method 8020
Total Cadmium, Chromium, Nickel, Lead and Zinc by AA Spectro

Analyte	Method	Reporting Limit	Unit	Blank	MS/MSD Recovery	RPD
Cadmium	7130	2.0	mg/Kg	ND	102	1
Chromium	7190	5.0	mg/Kg	ND	102	10
Lead	7420	2.0	mg/Kg	ND	104	5
Nickel	7520	5.0	mg/Kg	ND	117	6
Zinc	7950	1.0	mg/Kg	ND	109	6
Benzene	8020	.005	mg/Kg	ND	84	9
Ethylbenzene	8020	.005	mg/Kg	ND	89	9
Toluene	8020	.005	mg/Kg	ND	89	8
Xylenes	8020	.010	mg/Kg	ND	85	9
Diesel	8015M	1.0	mg/Kg	ND	79	1

SLAP Certificate NO: L753

Reviewed and Approved

John A. Murphy, Laboratory Director

Page 2 of 2

P. O. Box 5624 • South San Francisco, California 94088 • 415-588-2838 FAX (415) 588-1450



North State Environmental Analytical Laboratory

Chain of Custody/Request for Analysis

97-417 (415) 588-9652

Client: SEMCO		Phone: (415) 572-6633		Report to: Dene Milano			Turnaround Time: <i>Normal</i>		
Mailing Address: 1751 Leslie St San Mateo, CA 94402				Billing to: Same			<input type="checkbox"/> 8 Hr <input type="checkbox"/> 24 Hr <input type="checkbox"/> 40 Hr <input type="checkbox"/> 5 Days <input type="checkbox"/> Other		
Site Address: 510 Lincoln Ave Alameda				PO# / Billing Reference: 97-0153 BILL TO SAN MATEO					
Sampler: Keith Craig		Date: 5-15-97		ANALYSIS REQUESTED					
Sample ID	Sample Description	Container # / type	Sampling Time/Date	TPH-D	TPH-G	BTEX	O+G	Luft Samples	Remarks
SP-1	Soil stockpile	Pressliner	5-16-97 1530	X	X	X	X	X	Composite
SP-2	↓		↓	X	X	X	X		
SP-3	↓		↓	X	X	X	X		
* COMPOSITE THE THREE SAMPLES INTO ONE SAMPLE ANALYZE THE COMPOSITE 3 BT. COMP. (SEE)									
Relinquished by: <i>[Signature]</i>		Date: 5/19/97 Time: 12:30P		Received by: <i>[Signature]</i>			Yes No		
Relinquished by:		Date: Time:		Received by:			Were samples Preserved ?		
Relinquished by:		Date: Time:		Received in lab by: <i>[Signature]</i>			In good condition ?		