

FILE OR ENVELOPE
 PER NO. No. of
 OWNER USA Wind Power
 Address 17350 Patterson Pass Rd. ext. 22
Livermore, CA. Phone 455-6012
 Contractor AAA Tank Removal & Demolition
 Address 4900 No. Hi 99 #206
Stockton, CA. Phone 95212 (209) 931-6810
 OTHER (Specify) owner mailing address
 Address 6952 Preston Ave,
Livermore, CA. Phone Al Williamson (209) 931-6810

PLAN REVIEW
 \$ 333 Rec'd. mej. 11/1/90
 No. Plans Rec'd.
 Plans Approved
 Layout Made
 Rejected
 Applicant Notified
 Plans Returned
 Permit Issued
 CONSTRUCTION PROGRESS ACCEPTANCE
 Pre-Plaster/drywall
 Pre-Final
 Final

POOL
 Pre-Concrete/Gunite
 Pre-Plaster
 Final
 EXCAVATION
 Septic Tank
 Absorption Field
 Absorption Bed
 House Sewer
 FINAL
 Septic Tank
 Absorption Field
 Absorption Bed
 U.G. TANKS
 Pre-Covering
 Final

LOP

XR
 REMARKS
 Date By
 2/26/90 GW Review + approve cleanup plan
 3/26 GW Tank removal
 5/3 GW Review results, prepare letter requiring prelim. assess.
 8/13 Overexcavation has taken place, with sampling indicating that all contaminated soil has been removed. Bioremediation proposed for stockpiled soil
 5/21/91 Call from Uihak, Inc.; diesel in stockpiled soil has been reduced to < 10 ppm. However, O & G levels

REMARKS
 seem to be staying in the 200-300 ppm range; Uihak claims that this is from "organic" material in the soil, rather than HCs. I indicate that soil must be tested again for O & G, but divided into polar and nonpolar (HC) fractions. If nonpolar O & G is < 50 ppm, (ND) OK to use soil on-site.
 6/17/92 EL Left
 12/23 EL John Rapp says he will re-sample stockpile

LOCATION
 5603
 Vicinity Map
 John Rapp (209) 551-3591
 Project # 565623
 Fee Paid 333
 Date 2/26/90
 R01051
 17350 Patterson Pass Rd.
 Livermore, CA 94550
 U.S.A. WINDPOWER
 13603

5095