

August 19 1994
SCI 554.006

RECEIVED
AUG 23 1994

Mr. Stan Kintz
Mariner Development Company
2236 Mariner Square Drive
Alameda, California 94501

**Quarterly Groundwater Monitoring Report
July Sampling Event
Mariner Warehouse
Alameda, California**

Dear Mr. Kintz:

This letter presents quarterly groundwater monitoring results for the referenced site. Groundwater monitoring was performed as required by the Alameda County Health Care Services Agency (ACHCSA) in their letter dated July 13, 1994.

On July 25, 1994, five wells were purged and sampled. The groundwater monitoring event consisted of (1) measuring groundwater levels, (2) checking for free-product (3) purging at least 3 well volumes of water from each of the wells, and (4) sampling each well with a new disposable bailer. The samples were retained in glass containers and preserved with hydrochloric acid. The containers were placed in ice filled coolers and remained refrigerated until delivery to the analytical laboratory. Chain-of-Custody records accompanied the samples to the laboratory.

Analytical testing was performed by Curtis and Tompkins, Ltd., a laboratory certified by the State of California Department of Health Services (DHS) for hazardous waste and water testing. The analytical tests included:

1. Total volatile hydrocarbons (TVH), EPA method 8015 mod/5030,
2. Benzene, toluene, xylene and ethylbenzene (BTXE), EPA method 8020/5030, and
3. Total extractable hydrocarbons (TEH), EPA method 8015 mod/3550.

Subsurface Consultants, Inc.

Mr. Stan Kintz
Mariner Development Company
August 19, 1994
SCI 554.006
Page 2

A summary of the current and previous analytical test results and groundwater elevation data are presented in Tables 1 and 2, respectively. Analytical test reports and Chain-of-Custody documents are attached.

Conclusions


The groundwater level data indicate that the groundwater flow direction is toward the north at a gradient of approximately 1 percent.

The analytical test results indicate that extractable hydrocarbons are present in groundwater beneath the site. TEH as diesel was detected in four out of five wells. Volatile hydrocarbons and BTXE have never been encountered in any of the wells.

If you have any questions, please call.

Yours very truly,

Subsurface Consultants, Inc.



R. William Rudolph
Geotechnical Engineer 741 (expires 12/31/96)

MFW:RWR:sld

6 copies submitted

Attachments: Table 1 - Contaminant Concentrations in Groundwater
 Table 2 - Groundwater Elevations
 Plate 1 - Site Plan
 Analytical Test Reports
 Chain-of-Custody Documents

Table 1.
Contaminant Concentrations in Groundwater


<u>Well</u>	<u>Date</u>	<u>TEH</u> <u>ug/l</u>	<u>TOG</u> <u>mg/l</u>	<u>TVH</u> <u>ug/l</u>	<u>Benzene</u> <u>ug/l</u>	<u>Toluene</u> <u>ug/l</u>	<u>Ethyl-</u> <u>Benzene</u> <u>ug/l</u>	<u>Total</u> <u>Xylenes</u> <u>ug/l</u>	<u>Polynuclear</u> <u>Aromatics</u> <u>ug/l</u>
MW-1	09/02/92	260	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	ND(5)
	11/20/92	270	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	03/03/93	ND(50)	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	07/25/94	440	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
MW-2	09/02/92	ND(50)	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	ND(5)
	11/20/92	370	ND(7)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	03/03/93	ND(50)	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	07/25/94	1000	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
MW-3	09/02/92	300	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	ND(5)
	11/20/92	190	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	03/03/93	ND(50)	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	07/25/94	820	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
MW-4	09/02/92	ND(50)	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	ND(5)
	11/20/92	80	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	03/03/93	ND(50)	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	07/25/94	ND(50)	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
MW-5	09/02/92	200	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	ND(5)
	11/20/92	80	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	03/03/93	ND(50)	ND(5)	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--
	07/25/94	250	--	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)	--

TEH = Total extractable hydrocarbons, EPA 8015 mod./3550
 TOG = Total oil and grease, SMWW 17:5520B&F
 TVH = Total volatile hydrocarbons, EPA 8015 mod./5030
 mg/l = milligrams per liter or parts per million (ppm)
 ug/l = micrograms per liter or parts per billion (ppb)
 ND = None detected above reporting limits indicated in parentheses





Table 2.
Groundwater Elevation Data

<u>Well</u>	<u>TOC Elev (ft)</u>	<u>Date</u>	<u>Groundwater Depth (ft)</u>	<u>Groundwater Elev (ft)</u>
MW-1	6.76	09/04/92	8.06	-1.30
		09/08/92	8.02	-1.26
		09/11/92	8.11	-1.35
		11/20/92	7.52	-0.76
		03/03/93	6.50	0.26
		07/25/94	7.39	-0.63
MW-2	6.32	09/04/92	8.72	-2.40
		09/08/92	6.33	-0.01
		09/11/92	8.65	-2.33
		11/20/92	6.37	-0.05
		03/03/93	5.12	1.20
		07/25/94	7.22	-0.90
MW-3	7.19	09/04/92	5.60	1.59
		09/08/92	5.45	1.74
		09/11/92	5.50	1.69
		11/20/92	5.40	1.79
		03/03/93	4.91	2.28
		07/25/94	5.08	2.11
MW-4	7.27	09/04/92	7.86	-0.59
		09/08/92	7.84	-0.57
		09/11/92	7.91	-0.64
		11/20/92	7.56	-0.29
		03/03/93	7.21	0.06
		07/25/94	7.52	-0.25
MW-5	7.22	09/04/92	3.26	3.96
		09/08/92	5.10	2.12
		09/11/92	5.12	2.10
		11/20/92	5.13	2.09
		03/03/93	4.62	2.60
		07/25/94	4.35	2.87

TOC = Top of Casing
Elevation with respect to Mean Sea Level



VICINITY MAP



GROUNDWATER CONTOURS
7/25/94

Subsurface Consultants	MARINER WAREHOUSE - ALAMEDA, CA		PLATE 1
	JOB NUMBER 55-1-006	DATE 8/15/94	



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (510) 486-0900

A N A L Y T I C A L R E P O R T

Prepared for:

Subsurface Consultants

171 12th Street

Suite 201

Oakland, CA 94608

Date: 10-AUG-94

Lab Job Number: 116533

Project ID: 554.006

Location: Mariner Warehouse

Reviewed by:

Teresa K Morrison

Reviewed by:

Mary Plessam

This package may be reproduced only in its entirety.

LABORATORY NUMBER: 116533
 CLIENT: SUBSURFACE CONSULTANTS
 PROJECT ID: 554.006
 LOCATION: MARINER WAREHOUSE

DATE SAMPLED: 07/25,26/94
 DATE RECEIVED: 07/26/94
 DATE ANALYZED: 07/28-29/94
 DATE REPORTED: 08/10/94

Total Volatile Hydrocarbons with BTXE in Aqueous Solutions
 TVH by California DOHS Method/LUFT Manual October 1989
 BTXE by EPA 5030/8020

LAB ID	SAMPLE ID	TVH AS GASOLINE (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	ETHYL BENZENE (ug/L)	TOTAL XYLENES (ug/L)
116533-001	MW-1	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)
116533-002	MW-2	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)
116533-003	MW-3	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)
116533-004	MW-4	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)
116533-005	MW-5	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)
METHOD BLANK		ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)

ND = Not detected at or above reporting limit; Reporting limit indicated in parentheses.

QA/QC SUMMARY

RPD, %	1
RECOVERY, %	103



LABORATORY NUMBER: 116533
CLIENT: SUBSURFACE CONSULTANTS
PROJECT ID: 554.006
LOCATION: MARINER WAREHOUSE

DATE SAMPLED: 07/25,26/94
DATE RECEIVED: 07/26/94
DATE EXTRACTED: 08/06/94
DATE ANALYZED: 08/09/94
DATE REPORTED: 08/10/94

Extractable Petroleum Hydrocarbons in Aqueous Solutions
California DOHS Method
LUFT Manual October 1989

LAB ID	CLIENT ID	KEROSENE RANGE (ug/L)	DIESEL RANGE (ug/L)	REPORTING LIMIT (ug/L)
116533-001	MW-1	**	440	50
116533-002	MW-2	**	1,000	50
116533-003	MW-3	**	820	50
116533-004	MW-4	ND	ND	50
116533-005	MW-5	ND	250	50
METHOD BLANK		ND	ND	50

** Kerosene range not reported due to overlap of hydrocarbon ranges.

ND = Not detected at or above reporting limit. Reporting limit applies to all analytes.

QA/QC SUMMARY:

RPD, %	10
RECOVERY, %	88

