



2000 Crow Canyon Place  
Suite 400  
San Ramon, CA 94583  
925.277.2305  
fax: 925.277.2361

**Environmental  
Compliance  
Department**

June 22, 1999

Ms. Eva Chu  
Alameda County Health Care Services – EHS  
1131 Harbor Bay Parkway, Suite 250  
Alameda, CA 94502-6577

Re: Review of GeoProbe® Data  
Tosco/76 Products Service Station # 11120  
6400 Dublin Blvd.  
Dublin, CA

Dear Ms. Chu:


Recently, you should have received a report from Gettler-Ryan, Inc. containing GeoProbe® collected from this site on May 14, 1999 at your request. The purpose was to verify the presence of MtBE found in MW-7 (adjacent to the tank pit) during the last monitoring and sampling event. It is my understanding that all the monitoring wells were destroyed prior to your receipt of the final sampling data. Based upon new information from the last sampling event and the results of the GeoProbe® investigation, I understand that you will be re-opening the case and require delineation of the MtBE. From our telephone conversation, I am under the impression that Tosco will be named as the Primary Responsible Party.

I reviewed historical monitoring and sampling data and find there have been high levels of dissolved hydrocarbons and MtBE (up to 10,000 ppb) in at least one well, also adjacent to the tank pit, prior to the change of ownership in 1994. Please refer to the figure below. Levels of dissolved petroleum hydrocarbons and in particular, the ratios between dissolved constituents, have remained at similar levels since that time. You will also note that the screened interval for well MW-4 (and other wells for that matter) has been submerged since the initial sampling in 1992. I am under the impression that no active remediation has ever occurred at this site. For that reason, I do not believe that Tosco should be the primary responsible party for the additional MtBE investigation.

99 JUN 25 PM 3:38  
ENVIRONMENTAL  
PROTECTION



SS#11120 - Dublin  
 MW-4



Please feel free to call me (925-277-2384) so that we may discuss this situation.

Sincerely,

David B. De Witt  
 Environmental Project Manager

Cc: Scott Hooton, BP Oil  
 File 11120 : 3