Alameda County

July 19, 2004

Mr. Don Hwang

Alameda County Health Care Services Agency
1131 Harbor Bay Parkway, Suite 250

Alameda, California 94502-6577

Re: Site Investigation Report and Well Installation Work Plan

Shell-branded Service Station 9750 Golf Links Road Oakland, California SAP Code 135683 Incident #98995744

Fuel Leak Case # RO0002441

Dear Mr. Hwang:

Cambria Environmental Technology, Inc. (Cambria) prepared this report on behalf of Equilon Enterprises LLC dba Shell Oil Products US (Shell) to document recent site investigation activities at the above-referenced site. The purpose of this initial phase of the investigation was to further assess the depth to groundwater in sediments beneath the site to determine appropriate screened intervals for monitoring wells proposed in Cambria's Well Installation Work Plan dated May 17, 2002. Alameda County Health Care Services Agency (ACHCSA) responded to the work plan submittal in a correspondence dated May 17, 2002 requesting additional information and a work plan addendum. On December 4, 2002 Cambria submitted Agency Response and Well Installation Work Plan Addendum as requested. Since no response was received, Cambria notified the ACHCSA, in correspondence dated March 17, 2004, of our intent to install a pilot borehole prior to implementing the work plan. The ACHCSA approved the pilot boring activities in a letter dated April 5, 2004, and requested that a site investigation report be issued by June 15, 2004. Due to facility upgrades at this site, the drilling work was postponed. In an email correspondence dated June 7, 2004 Cambria requested the report submittal date be extended to July 20, 2004. The ACHCSA responded on June 8, 2004 via email, approving the extension. The work was performed in accordance with Regional Water Quality Control Board (RWQCB) and Alameda County Public Works Agency (ACPWA) guidelines.

SITE BACKGROUND

Site Description: The site is an active Shell-branded Service Station, located at the intersection of Golf Links Road and Mountain Boulevard in Oakland, California (Figure 1). Residential and commercial properties surround the site. Highway 580 runs near the northern boundary of the site.

Cambria Environmental Technology, Inc.

270 Perkins Street P.O. Box 259 Sonoma, CA 95476 Tel (707) 935-4850 Fax (707) 935-6649

PREVIOUS WORK

1995 Waste Oil Underground Storage Tank (UST) Removal: On March 7, 1995, Weiss Associates of Emeryville, California (WA) observed the removal of a 550-gallon, single-walled, steel waste-oil UST and collected soil samples from the tank excavation floor and sidewalls. The highest hydrocarbon concentrations were 12,000 parts per million (ppm) total oil and grease (TOG), 190 ppm total petroleum hydrocarbons as gasoline (TPHg) and 3,900 ppm total petroleum hydrocarbons as diesel (TPHd), detected at 7 feet below grade (fbg). After over excavation, confirmation soil samples from a depth of 11 fbg at the site contained 62 ppm TOG, and no TPHg or TPHd. No benzene was detected in any of the excavation samples. Sidewall confirmation samples from approximately 7 – 8 fbg reported no TPHd, no TPHg, and no benzene constituents.



1995 Subsurface Investigation: On December 15, 1995, WA advanced one soil boring (B-1 on Figure 2) to 48 fbg in the vicinity of the former waste oil UST. Hydrocarbons detected were 2.8 ppm TPHd at 30.5 fbg and 56 ppm TOG at 40.5 fbg. No groundwater was encountered.

1998 Dispenser Upgrade: On February 4, 1998, Cambria observed station upgrade activities and collected soil samples from beneath one dispenser (D-4). The highest hydrocarbon concentrations were 7,800 ppm TPHg and 37 ppm benzene beneath dispenser D-4 at 4.0 fbg (Figure 2). No field indications of hydrocarbons were observed beneath the other dispensers, and sample collection was not required.

1998 Subsurface Investigation: On July 6 and 31, 1998, Cambria installed one soil boring (SB-1) to a depth of 30 fbg in the vicinity of dispenser sample D-4. Hydrocarbons were detected at a maximum concentration of 14,000 ppm TPHg and 100 ppm benzene at 13 fbg. A maximum concentration of 91 ppm of methyl tertiary butyl ether (MTBE) was reported at 9 fbg by EPA Method 8020. This detection was confirmed by EPA Method 8260 at a concentration of 23 ppm. Low concentrations of TPHg (5.6 ppm), benzene (0.035 ppm), and MTBE (0.16 ppm) by EPA Method 8020 were reported in the deepest sample collected at approximately 26 fbg. Cambria was unable to collect a groundwater sample, as the only water encountered was an apparent thin perched zone at approximately 12 fbg.

1999 Subsurface Investigation: On August 25, 1999, Cambria installed five soil borings (SB-1b and SB-2 though SB-5) to depths ranging from 16 to 30 fbg. The maximum TPHg concentration detected in soil was 243 ppm at approximately 10 fbg in boring SB-2. The maximum MTBE concentration detected in soil was 2.23 ppm (by EPA Method 8260) at approximately 10 fbg in boring SB-4. No benzene was reported in any of the analyzed soil samples collected. A perched

water zone was encountered at approximately 12 fbg in boring SB-2 and approximately 20 fbg in boring SB-3. Groundwater was not encountered in the remaining soil borings. Grab water samples collected from the perched water encountered in borings SB-2 and SB-3 contained were both impacted with a maximum of 256 parts per billion (ppb) TPHg, 2.42 ppb benzene and 11,800 ppb MTBE (by EPA Method 8020) in SB-2.

2000 Sensitive Receptor Survey: In 2000, Cambria conducted a sensitive receptor survey for a ¼-mile radius of the site. Results of the survey are shown on Figure 1. The only well identified within the ¼-mile survey radius was a cathodic protection well located approximately 1,150 feet north-northwest of the site. Arroyo Viejo Creek was the only identified surface water body within the survey radius. Arroyo Viejo Creek is located aboveground southeast of the site and is diverted into an underground storm drain culvert which runs beneath the west portion of the site. The culvert outlet to Arroyo Viejo Creek is located approximately 575 feet northwest of the site.

2000 Conduit Study: In 2000, Cambria reviewed storm drain and sanitary sewer maps from the City of Oakland Public Works Department and the California Department of Transportation. Locations, depths and pipe diameters for the sanitary sewer and storm drain lines in the site vicinity are shown on Figure 2.

2004 Dispenser Upgrades: During upgrades of the dispensers and piping at this site in April 2004, eight soil samples were collected from depths between 4.5 – 5 fbg. The highest TPHg concentration was reported in soil from beneath dispenser piping at 5 fbg in P-1. This sample location was in very close proximity to the 1998 dispenser sample D-4. These activities and results were recently submitted in the July 16, 2004 Product Dispenser and Piping Replacement Report.

In an effort to better understand the lithology and assess the depth to a water-bearing unit, one pilot boring was installed using mud rotary drilling. The results of the pilot boring activities are presented below.

INVESTIGATION RESULTS

Personnel Present: Cambria geologist Anne Wettstone directed the field activities,

working under the supervision of California Registered

Geologist Ana Friel.

Permits: Boring permit No. W04-0325 was obtained from ACPWA

(Appendix A).







Drilling Company:

Gregg Drilling and Testing, Inc. of Martinez, California (C57

License No. 485165).

Drilling Date:

June 14, 2004.

Drilling Method:

Mud-Rotary.

Soil Sampling Methods:

Soil types were logged using the Unified Soil Classification System and Munsell Soil Color Charts. Encountered soil is described on the exploratory boring log presented in Appendix B. Soil samples were collected continuously for lithologic description. Soil samples were screened in the field for the presence of organic vapors using a photo-ionization detector (PID). PID readings are recorded on the boring logs.

Number of Borings:

One pilot-hole soil boring (PH-1) was drilled. Boring specifications are described in Table 1 and the location is shown

on Figure 2.

Boring Depth:

Boring PH-1 was advanced to 62.5 fbg, at which point drilling

was halted due to insufficient sample recovery for the varied

sediments encountered.

Groundwater Depth:

Other than a thin lens of saturated sediment at 7.5 fbg,

groundwater was not encountered during drilling activities.

Sediment Types:

Sediment types encountered while drilling the boring generally

consisted of sandy silt, and sandy clayey silt (ML), sandy gravel (GM), and clayey silty sand (SM) to an approximate depth of 23 fbg. Weathered bedrock was encountered from 23 to 45 fbg, underlain by cobbles of granite, siltstone, and sandstone to the

total explored depth of 62.5 fbg (Appendix B).

Chemical Analyses:

Soil samples were analyzed for TPHg, BTEX, and MTBE by

EPA Method 8260B. The Certified analytical report is provided

in Appendix C.

Soil Disposal:

Soil cuttings from boring PH-1 were stored in a covered 20-cubic yard soil bin. Approximately 2-3 cubic yards of soil was generated during drilling activities. The soil was characterized using analytical data previously collected at the site. Philip Services Inc. of Benicia, California will removed the soil bin from in July 2004 and transported it to Allied Waste's Forward Landfill in Manteca for disposal.

HYDROCARBON DISTRIBUTION IN SOIL



No TPHg, BTEX, or MTBE (by EPA Method 8260B) were detected in any of the nine soil samples collected from boring PH-1.

The soil chemical analytical data is summarized on Table 2, the TPHg, benzene, and MTBE concentrations are presented on Figure 2, and the laboratory analytical report is included in Appendix C.

DISCUSSION

The purpose of this initial phase of the investigation was to further assess the depth to groundwater in sediments beneath the site to determine appropriate screened intervals for proposed monitoring wells and to assess the presence and vertical extent of soil impact at this location. The pilot hole was intended to be extended to 100 fbg, or to groundwater, whichever was shallower. As was encountered during previous site activities, a thin water-bearing perched zone was observed at approximately 7.5 fbg at PH-1. Drilling activities were halted at approximately 62.5 fbg because of poor recovery. Cambria was unable to discern what type of material was being drilled through, and therefore, decided to cease drilling. Other than at 7.5 fbg, no other water-bearing sediments were observed.

WORK PLAN FOR WELL INSTALLATION

Technical Rationale for Proposed Scope of Work

- Impacted soil has been found at this site near the dispenser islands;
- Two grab water samples from a "perched" water zone indicated impact;
- Vertical assessment activities have not produced a more prolific water-bearing unit (to 62.5 fbg);
- Shallow perched water is present at several locations onsite; therefore, groundwater
 monitoring wells will be installed to monitor any water present within the first 20 feet
 below grade (fbg).



Work Tasks

Permits: Cambria will obtain appropriate permits for drilling from Alameda County Public Works Agency, Water Resources Section.

Site Safety Plan: Cambria will prepare a Site Safety Plan and Traffic Control Plan for field work.

Utility Clearance: Cambria will request copies of the service station as-built drawings and communicate with the station operator prior to confirming the locations of the proposed monitoring wells. Cambria will mark proposed drilling locations and the locations will be cleared through Underground Service Alert (USA) prior to drilling. Additionally, since the site is an active service station, a private utility line locating service will be retained to clear the proposed drilling locations of utilities or lines that are not identified by USA. To further protect the workers and subsurface equipment, an air-knife will be used to clear the top 5 to 10 feet at each location to a diameter of three inches larger than the lead auger.

Site Investigation: Five exploratory soil borings (S-1 through S-5) are proposed at the locations shown on Figure 2. The exploratory borings will be drilled using hollow-stem auger equipment and will be converted to groundwater monitoring wells. Well S-1 is positioned approximately 10 feet from the current UST complex, in the assumed downgradient direction. The other wells are positioned to assess the extent of impact at the property boundaries.

A Cambria geologist will supervise the drilling and describe encountered soils using the Unified Soil Classification System and Munsell Soil Color Charts. With the exception of the portion

extended by the air-knife, soil samples from the borings will be collected continuously for soil description and retained at 5-foot intervals for chemical analyses and organic vapor screening with a photo-ionization detector (PID). Cambria will prepare an exploratory boring log for each well, and PID measurements will be recorded on the boring logs.

Soil samples designated for chemical analyses will be retained in stainless steel or brass sample tubes. The tubes will be covered on both ends with Teflon sheets and plastic end caps. Soil samples will be labeled, entered onto a chain-of-custody record, and placed into a cooler with ice for transport to a State of California certified laboratory for analyses. A standard two-week turn-around time will be requested for laboratory results.

3

Monitoring Well Installation: Each boring will be drilled to approximately 20 fbg or to auger refusal, whichever is shallower. Based on information from the activities to date, a perched water zone may be present between approximately 11 and 18 fbg. Wells will be constructed using 4-inch diameter Schedule 40 PVC casing. Each well screen interval will be placed from approximately 7 fbg to 20 fbg. The sandpack in each well will be placed from the bottom of the well screen up to 2 feet above the top of the well screen followed by a 2-foot thick bentonite seal and cement grout to grade. Actual well construction details will be based on field conditions during drilling. Each well will be secured with a locking cap under a traffic-rated well box.

Well Development and Sampling: Blaine Tech Services, Inc. (Blaine) of San Jose, California will develop the new groundwater monitoring wells prior to sampling. If the wells de-water during development, Blaine will add potable water to complete the development and will remove at least as much volume as they placed in the well. No sooner than 48-hours after well development, Blaine will sample the site groundwater monitoring wells and submit the samples to a State of California certified laboratory for chemical analyses.

Chemical Analyses: Groundwater samples and selected soil samples will be analyzed for TPHg, BTEX, and fuel oxygenates (MTBE, tertiary amyl methyl ether, ethyl tertiary butyl ether, tertiary butyl alcohol, and di-isopropyl ether) by EPA Method 8260. Samples will be analyzed on a standard two-week turnaround.

Wellhead Survey Activities: Following monitoring well installation, a licensed surveyor will survey wellhead elevations relative to mean sea level and the latitude and longitude of each well location.

Report Preparation: Following the receipt of analytical results from the laboratory, Cambria will prepare a written report which will include field procedures, laboratory results, boring logs, and conclusions.

Certification: The scope of work described in this work plan will be performed under the supervision of a registered geologist.

SCHEDULE



Upon receipt of approval from the ACHCSA, Cambria will initiate permitting and scheduling activities. If a response is not received within approximately 60 days, we will assume agency concurrence and notify the ACHCSA of our intent to proceed.

CLOSING

If you have any questions regarding the contents of this document, please call Ana Friel at (707) 442-2700.

Sincerely,

Cambria Environmental Technology, Inc.

3

Anne Wettstone Staff Geologist

Ana Friel, ÆG

Senior Project Geologist

RG 6452

RED GEO FRIEL GS FRIEL GS * EXP 9/05 * Lic. *6452 *

Attachments:

Table 1. Boring Data

Table 2. Soil Analytic Data

Figure 1. Site Vicinity Map with Area Well Survey

Figure 2. Site Plan/Soil Chemical Concentration Map

Figure 3. Proposed Monitoring Well Location Map

Appendix A. Permit

Appendix B. Boring Log

Appendix C. Certified Analytical Report

cc: Karen Petryna, Shell

Table 1. Boring Data, Shell-branded Service Station, 9750 Golf Links Rd. Oakland, California

| | | Date | Surface | Total | Soil S | ample | First GW | TOC | Screen | Screen | Depth (fbg) | |
|-------|-------------------|-----------|---------------|-------------|---------------|-------------|-------------|-----------|------------|--------|-------------|--------------|
| Name | Туре | Installed | Elev (ft msl) | Depth (fbg) | Interval (ft) | Depth (fbg) | Depth (fbg) | Elev (ft) | Diam. (in) | Тор | Bottom | Comments |
| | | | | | | | | | | | | |
| B-1 | HSA Boring | 15-Dec-95 | - | 47 | 5 | • | - | - | - | - | - | not surveyed |
| SB-1 | HSA Boring | 31-Jul-98 | - | 30 | 5 | - | - | - | - | - | - | not surveyed |
| SB-1b | HSA Boring | 25-Aug-99 | - | 26.5 | 5 | - | - | - | - | - | - | not surveyed |
| SB-2 | HSA Boring | 25-Aug-99 | - | 16 | 5 | - | - | - | - | - | - | not surveyed |
| SB-3 | HSA Boring | 25-Aug-99 | - | 25 | 5 | - | - | - | - | - | - | not surveyed |
| SB-4 | HSA Boring | 25-Aug-99 | - | 26.5 | 5 | - | - | - | - | - | - | not surveyed |
| SB-5 | HSA Boring | 25-Aug-99 | - | 30 | 5 | - | - | - | • | - | • | not surveyed |
| PH-1 | MR Boring | 04-Jun-04 | - | 62.5 | c | - | - | - | - | - | - | not surveyed |

Abbreviations and Notes:

ft msl - Feet referenced to mean sea level

fbg = Feet below grade

ft = Feet

in = Inches

GW = Groundwater

TOC = Top of well casing

Diam = Diameter

C = Continuous

MR = Mud Rotary

Table 2. Soil Analytic Data, Shell-branded Service Station, 9750 Golf Links Road, Oakland, California

| Sample ID | Depth (feet) | Date | TPHd (mg/kg) | TPHg (mg/kg) | POG (mg/kg) | Benzene (mg/kg) | Toluene (mg/kg) | Ethylbenzene (mg/kg) | Xylenes (mg/kg) | MTBE (mg/kg) |
|--------------------------------|-----------------|------------------------|-----------------|-----------------|----------------|--------------------|--------------------|-------------------------|--------------------|-----------------|
| | (1001) | | | | , | · · | | | <0.0050 | <0.0050 |
| PH-1-5.5' | 5.5 | 07-Jun-04 | NA | <1.0 | NA | <0.0050 | <0.0050 | <0.0050 <0.0050 | <0.0050 <0.0050 | <0.0050 |
| PH-1-10.5' | 10.5 | 07-Jun-04 | NA | <1.0 | NA. | <0.0050 <0.0050 | <0.0050 <0.0050 | <0.0050 <0.0050 | <0.0050 | <0.0050 |
| PH-1-15,5' | 15.5 | 97-Jun-04 | NA. | <1.0 <1.0 | NA NA | <0.0050 <0.0050 | <0.0050 | <0.0050 | <0.0050 | <0.0050 |
| PH-1-19.5' PH-1-24.5' | 19.5 24.5 | 67-Jun-64 07-Jun-64 | NA NA | <1.0 <1.0 | NA. | <0.0050 | <0.0050 | <0.0050 | <0.0050 | <0.0050 |
| PH-1-29.5' | 29.5 | 07-Jun-04 | NA | <1.0 | NA | <0.0050 | <0.0050 | <0.0050 | <0.0050 | < 0.0050 |
| PH-1-34.5' | 34.5 | 07-Jun-04 | NA | <1.0 | NA | <0.0050 | <0.0050 | <0.0050 | <0.0050 | <0.0050 |
| PH-1-40.51 | 40.5 | 07-Jun-04 | NA. | <1.0 | NA | <0.0050 | < 0.0050 | <0.0050 | <0.0050 | <0.0050 |
| PH-1-45.5' | 45.5 | 07-Jun-04 | ŇA | <1.0 | NA | <0.0050 | <0.0050 | <0.0050 | <0.0050 | <0,0050 |
| SB-1b-6.0-6.5 | 6.0 | 25-Aug-99 | NA | <1.0 | NA | <0.005 | < 0.005 | <0.005 | <0.005 | <0.05 |
| SB-1b-11.0-11.5 | 11.0 | 25-Aug-99 | NA. | <1.0 | NA | < 0.005 | < 0.005 | < 0.005 | <0.005 | <0.05 |
| SB-1b-16.0-16.5 | 16.0 | 25-Aug-99 | NA | <1.0 | NA | <0.005 | <0.005 | < 0.005 | < 0.005 | < 0.05 |
| SB-1b-20.0-21.0 | 20.0 | 25-Aug-99 | NA | <1.0 | NA | <0.005 | < 0.005 | < 0.005 | <0.005 | <0.05 |
| SB-1b-25.5-26.0 | 25.5 | 25-Aug-99 | NA | <1.0 | NA | <0.005 | <0.005 | < 0.005 | < 0.005 | <0.05 |
| SB-2-5.5-6.0 | 5.5 | 25-Aug-99 | NA | <1.0 | ΝA | <0.005 | <0.005 | <0.005 | <0.005 | <0.05 |
| SB-2-10.5-11.0 | 10.5 | 25-Aug-99 | NA | 243 | NA | < 0.100 | 0.248 | 0.664 | 1.08 | <1.00 |
| SB-3-6.0-6.5 | 6.0 | 25-Aug-99 | NA | <1.0 | NA | < 0.005 | <0.005 | <0.005 | <0.005 | <0.05 |
| | 11.0 | 25-Aug-99 | NA. | <1.0 | NA | < 0.005 | < 0.005 | < 0.005 | < 0.005 | < 0.05 |
| SB-3-11.0-11.5 | | - | NA NA | <1.0 | NA | <0.005 | < 0.005 | < 0.005 | < 0.005 | 0.449 |
| SB-3-16.0-16.5 | 16.0 | 25-Aug-99 | NA. | <1.0 | NA. | < 0.005 | <0.005 | < 0.005 | <0.005 | 0.380 |
| SB-3-20-21.5 | 20.0 | 25-Aug-99 | | <1.0 | NA NA | < 0.005 | < 0.005 | < 0.005 | <0.005 | 0.418 |
| SB-3-21.0-21.5 | 21.0 | 25-Aug-99 | NA NA | | NA NA | <0.005 | <0.005 | < 0.005 | <0.005 | 0.257 |
| SB-3-24-24.5 SB-3-24.5-25.5 | 24.0 24.5 | 25-Aug-99 25-Aug-99 | NA NA | <1.0 <1.0 | NA NA | <0.005 | 0.00520 | <0.005 | 0.00830 | 0,161 |
| | | 25 4 00 | N/A | <1.0 | NA | <0.005 | <0.005 | <0.005 | <0.005 | <0.05 |
| SB-4-5.5-6.0 | 5.5 | 25-Aug-99 | NA | 74.0 | NA | < 0.0250 | 0.0565 | 0.159 | 0.0915 | 2.60 (2.23 |
| SB-4-10.5-11.0 | 10.5 | 25-Aug-99 | NA | | NA NA | < 0.005 | < 0.005 | <0.005 | < 0.005 | < 0.05 |
| SB-4-15.5-16.0 | 15.5 | 25-Aug-99 | NA | <1.0 | | <0.005 | < 0.005 | <0.005 | 0.00550 | < 0.05 |
| SB-4-20.5-21.0 | 20.5 | 25-Aug-99 | NA | <1.0 | NA NA | <0.005 | < 0.005 | <0.005 | <0.005 | <0.05 |
| SB-4-25.5-26.0 | 25.5 | 25-Aug-99 | NA | <1.0 | NA | ~0.00 3 | 10.003 | 0.505 | | |
| SB-5-5.5-6.0 | 5.5 | 25-Aug-99 | NA | <1.0 | NA | <0.005 | <0.005 | <0.005 | <0.005 | <0.05 |
| SB-5-10.5-11.0 | 10.5 | 25-Aug-99 | NA | <1.0 | NA | < 0.005 | < 0.005 | < 0.005 | <0.005 | <0.05 |
| SB-5-16.0-16.5 | 16.0 | 25-Aug-99 | NA | <1.0 | NA | <0.005 | < 0.005 | < 0.005 | 0.0107 | 0.0726 |
| SB-5-20.5-21.0 | 20.5 | 25-Aug-99 | NA | <1.0 | NA | < 0.005 | 0.00930 | < 0.005 | 0.0193 | < 0.05 |
| SB-5-24.0-24.5 | 24.0 | 25-Aug-99 | NA | <1.0 | NA | < 0.005 | 0.0241 | 0.00890 | 0.0473 | <0.05 |
| SB-5-29.0-29.5 | 29.0 | 25-Aug-99 | NA | <1.0 | NA | < 0.005 | 0.0144 | 0.00596 | 0.0323 | <0.05 |

Table 2. Soil Analytic Data, Shell-branded Service Station, 9750 Golf Links Road, Oakland, California

| Sample ID | Depth (feet) | Date | TPHd (mg/kg) | TPHg (mg/kg) | POG (mg/kg) | Benzene (mg/kg) | Toluene (mg/kg) | Ethylbenzene (mg/kg) | Xylenes (mg/kg) | MTBE (mg/kg) |
|------------|-----------------|-----------|-----------------|-----------------|----------------|--------------------|--------------------|----------------------|--------------------|-----------------|
| | | 06-Jul-98 | NA | 1,100 | NA | 6.1 | 40 | 143 | 98 | 91 (23) |
| SB-1-9.0' | 9.0 | | NA NA | 3,5 | NA | 0.019 | 0.34 | 0.076 | 0.55 | 0.79 |
| SB-1-11.5' | 11.5 | 06-Jul-98 | NA NA | 14,000 | NA. | 100 | 530 | 190 | 1,200 | 66 |
| SB-1-13.0' | 13.0 | 06-Jul-98 | | 1.1 | NA NA | <0.0050 | 0.029 | 0.013 | 0.091 | 1.4 |
| SB-1-16.0' | 16.0 | 31-Jul-98 | NA | | | <0.0050 | < 0.0050 | <0.0050 | < 0.0050 | 0.03 |
| SB-1-21.0' | 21.0 | 31-Jul-98 | NA | <1.0 | NA | | 0.05 | 0.062 | 0.28 | 0.16 |
| SB-1-26.0' | 26.0 | 31-Jul-98 | NA | 5.6 | NA | 0,035 | 0.25 | 0.002 | 0,20 | |
| D1 5 5 | 5.5 | 15-Dec-95 | <1.0 | <1.0 | <50 | <0.005 | <0.005 | <0.005 | <0.005 | NA |
| B1-5.5 | 15.5 | 15-Dec-95 | <1.0 | <1.0 | <50 | < 0.005 | <0.005 | < 0.005 | < 0.005 | NA |
| B1-15.5 | 20.5 | 15-Dec-95 | <1.0 | <1.0 | <50 | < 0.005 | < 0.005 | < 0.005 | <0.005 | NA |
| B1-20.5 | | 15-Dec-95 | 2.8 | <1.0 | <50 | <0.005 | < 0.005 | < 0.005 | < 0.005 | NA |
| B1-30.5 | 30.5 | | <1.0 | <1.0 | <50 | <0.005 | <0.005 | < 0.005 | < 0.005 | NA |
| B1-35.5 | 35.5 | 15-Dec-95 | | <1.0 <1.0 | 56 | <0.005 | <0.005 | <0.005 | < 0.005 | NA |
| B1-40.5 | 40.5 | 15-Dec-95 | <1.0 | | <50 | < 0.005 | <0.005 | < 0.005 | < 0.005 | NA |
| B1-45.5 | 45.5 | 15-Dec-95 | <1.0 | <1.0 | <50 | C00,02 | 40,003 | 21002 | | |
| | 7.0 | 08-Mar-95 | 3,900 | 190 | 12,000 | <0.25 | 0.43 | 1.0 | 2.2 | NA |
| WO1 | | | <1.0 | <1.0 | 62 | <0.005 | 0.072 | < 0.005 | < 0.005 | NA |
| WO2 | 11.0 | 08-Mar-95 | | | <50 | < 0.005 | 0.10 | < 0.005 | < 0.005 | NA |
| NSW | 7.5 | 08-Mar-95 | <1.0 | <1.0 | | <0.005 | 0.19 | < 0.005 | < 0.005 | NA |
| SSW | 7.0 | 08-Mar-95 | <1.0 | <1.0 | <50 | | 0.18 | <0.005 | <0.005 | NA |
| ESW | 7.0 | 08-Mar-95 | <1.0 | <1.0 | <50 | <0.005 | | | < 0.005 | NA |
| wsw | 7.8 | 08-Mar-95 | <1.0 | <1.0 | <50 | < 0.005 | 0.083 | <0.005 | <0.003 | 1121 |

Abbreviations and Notes:

mg/kg = Milligrams per kilogram

 $TPH-G = Total\ petroleum\ hydrocarbons\ as\ gasoline\ (Pre-2004:\ by\ EPA\ Method\ 8015,\ 2004 = EPA\ Method\ 8260B)$

 $B=Benzene\ (Pre\text{-}2004:\ By\ EPA\ Method\ 8020,\ 2004:\ by\ EPA\ Method\ 8260B)$

T = Toluene (Pre-2004: By EPA Method 8020, 2004: by EPA Method 8260B)

E = Ethylbenzene (Pre-2004: By EPA Method 8020, 2004: by EPA Method 8260B)

X = Xylenes (Pre-2004: By EPA Method 8020 2004: by EPA Method 8260B)


MTBE = Methyl tertiary butyl ether (Pre-2004: by EPA Method 8020, results in parenthesis by method 8260, 2004: by EPA Method 8260B)

 $TPH-D = Total \ petroleum \ hydrocarbons \ as \ diesel \ by \ modified \ EPA \ Method \ 8015$

TOG = Total oil and grease by APHA Standard Method 5520E&F

Samples collected on 03/08/95 by Weiss Associates and analyzed by Sequoia Analytical, Redwood City, California; all other by Cambria.

 $<_X =$ Below detection limit of x mg/kg



Shell-branded Service Station


9750 Golf Links Road Oakland, California Incident #98995744



CAMBRIA

Site Vicinity Map with Area Well Survey

(1/4-Mile Radius)



Shell-branded Service Station

9750 Golf Links Road Oakland, California



Site Plan/Soll Chemical Concentration Map

CAMBRIA

Shell-branded Service Station

Approximate Scale (ft)

9750 Golf Links Road Oakland, California



Proposed Monitoring Well Location Map

FIGURE

CAMBRIA

1707 935 6649 P.02/03



LEASE PRINT NAME ATME Wettstone

ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION 399 ELMRURST ST. HAYWARD CA. 94544-1395 PHONE (510) 670-4633 James You FAX (510) 782-1939

APPLICANTS: PLEASE ATTACH A SITE MAP FOR ALL DRILLING PERMIT APPLICATIONS DESTRUCTION OF WELLS OVER 45 FRET REQUIRES A SEPARATE PERMIT APPLICATION

| DRILLING PERM | IIT APPLICATION |
|--|--|
| FOR APPLICANT TO COMPLETE LOCATION OF PROJECT 9750 Golf Links Rd., | FOR OFFICE USE PERMIT NUMBER WELL NUMBER APN |
| School Oil Portures US address JOHN S. Wilmington Phone \$559 05-9301 Sity Carson Dispersion Phone \$559 05-9301 APPLICANT Name August Interstone / Cambria Environmental Feel. Address 270 Perkins Phone 207 933-2369 | PERMIT CONDITIONS Circled Permit Requirements Apply A. GENERAL 1. A permit application should be submitted to as to arrive at the ACPWA office five days prior to proposted starting date. 2. Submit to ACPWA within 60 days after completion of permitted original Department of Water Resources Well Completion Report. 2. Permit in void if services. |
| TYPE OF PROJECT Well Construction Cathodic Protection Weter Supply Monitoring PROPOSED WATER SUPPLY WELL USE New Domestic Municipal Industrial Defer Def | 3. Permit is void if project not begun within 90 days of approval date B. WATER SUPPLY WELLS 1. Minimum surface seal thickness is two inches of exement grout placed by tremit. 2. Minimum seal depth is 50 four for municipal and ladustrial wells or 20 feet for domestic and imigation wells unless a lesser depth is specially approved. C. GROUNDWATER MONITORING WELLS INCLUDING PIEZOMETERS 1. Minimum surface seal thickness is two inches of cement grout placed by tremic. 2. Minimum seal depth for monitoring wells is the maximum depth practicable or 20 feet. D. GEOTECHNICAL CONTAINATE Backful bore boke by tremie with cement grout or cemere grout/sand mixture. Upper two-three fost replaced is kind or with compacted cuttings. |
| PRILLER'S LICENSE NO. (S7-485165 | F. WELL DESTRUCTION Send a map of work site. A separate permit is required for wells deeper than 45 feet. G. SNEGBEL-CONDITIONS RALL |
| Number of Borings Hole Diameter 6 Depth 100 n. | NOTE: One application must be submitted for each well or well destruction. Multiple borings on one application are acceptable for geotechnical and contamination investigations. |
| TARTING DATE 4 2 04 OMPLETION DATE 4 13 0 4 hereby agree to comply with all resolutions and all resolutions are sent and all resolutions. | APPROVED 3-26-0 |

Rcv.9-18-02

Appendix B
Boring Log



Cambria Environmental Technology, Inc. 270 Perkins Street Sonoma, California 95476 Telephone: (707) 935-4850

Fax: (707) 935-6649

BORING/WELL LOG

PH-1 Shell Oil Products US BORING/WELL NAME **CLIENT NAME JOB/SITE NAME** Shell-branded Service Station **DRILLING STARTED** 04-Jun-04 DRILLING COMPLETED 07-Jun-04 9750 Golf Links Road, Oakland LOCATION WELL DEVELOPMENT DATE (YIELD) NA **PROJECT NUMBER** 0735 Not Surveyed DRILLER Gregg Drilling **GROUND SURFACE ELEVATION** TOP OF CASING ELEVATION Not Surveyed DRILLING METHOD Mud-rotary BORING DIAMETER 6" SCREENED INTERVAL: A. Wettstone DEPTH TO WATER (First Encountered)_ NA LOGGED BY **DEPTH TO WATER (Static)** NA **REVIEWED BY** A. Friel, RG 6452 REMARKS

CONTACT DEPTH (fbg) GRAPHIC BLOW (mdd) S.C.S. EXTENT SAMPLE (fpg) LITHOLOGIC DESCRIPTION WELL DIAGRAM ᇛ ASPHALT Sandy SILT (ML); brown (7.5YR 4/2); moist; 5% clay, 60% silt, 35% fine to medium sand; no plasticity. ML 0.0 PH-1-5.5 7.5 Sandy GRAVEL (GM); brown (7.5YR 4/2); wet; 5% clay, 10% silt, 30% fine to coarse sand, 55% fine to coarse gravel. PH-1-0.0 GM 10.5 @12'- light olive brown (2.5Y 5/3); moist; fine gravel. 14.0 Sandy SILT (ML); brown (7.5YR 4/3); moist; 10% clay, 60% silt, 30% fine to medium sand; no plasticity. @15'- Sandy Clayey SILT (ML); dark yellowish brown (10YR 3/6); moist; 25% clay, 55% silt, 20% fine sand; no 0.0 PH-1-15.5 ML plasticity. 18.0 Clayey Silty SAND (SM); dark greenish gray (10Y 3/1); moist; 15% clay, 30% silt, 55% fine to medium sand. 0.0 PH-1-LOG (PID) HOADE75-YGINT240IOAK9750 GPJ DEFAULT GDT 7/8/04 @20'- very dark grayish brown (2.5Y 5/3); moist; 15% 19.5 SM clay, 30% silt, 55% fine to medium sand. 23.0 Weathered BEDROCK; Siltstone with altered granite; dark greenish gray (10Y 3/1); moist. PH-1-0.0 @25'- Weathered SILTSTONE dark greenish gray 24.5 (10Y 4/1). @29'- greenish gray (5GY 5/1). 0.0 PH-1-29.5 Portland Type @34'- greenish black (5GY 2.5/1). PAGE 1 OF Continued Next Page



Telephone: (707) 935-4850 Fax: (707) 935-6649

CLIENT NAME JOB/SITE NAME

LOCATION

Shell Oil Products US Shell-branded Service Station BORING/WELL NAME

PH-1

DRILLING STARTED

04-Jun-04

BORING/WELL LOG

9750 Golf Links Road, Oakland

DRILLING COMPLETED 07-Jun-04

| 0.0 PH-1- 40.5' PH-1- 40.5' PH-1- 40.5' PH-1- 45.5' PH | BLOW | SAMPLEID | EXTENT | DEPTH (fbg) | U.S.C.S. | GRAPHIC | LITHOLOGIC DESCRIPTION | CONTACT DEPTH (fbg) | WEL | L DIAGRAM |
|--|------|----------|----------------------------------|------------------|----------------|---|--|--|--|--|
| @41- greenish black (351 2.3/1). @45- Weathered GRANITE; with recrystalized granite clasts; dark greenish gray (5GY 4/1); moist. @47- unweathered granite clasts. @55- SILTSTONE and SANDSTONE Cobbles Bottom of Boring @ 62.5 | | PH-1- | 0 | | | | @35'- Weathered GRANITE; dark greenish gray (10GY 4/1); moist. @40'- Weathered GRANITE and SILTSTONE moist. | | | |
| @47'- unweathered granite clasts. @65'- SILTSTONE and SANDSTONE Cobbles 62.5 Bottom of Boring @ 62.5 | | | 0 | | | | | | | |
| 62.5 Bottom of Boring @ 62. | | 10.0 | 0 | 50 | | | | | | |
| 62.5 Bottom of Boring @ 62. | | | 0 | -55- | | | @55'- <u>SILTSTONE and SANDSTONE Cobble</u> s | | | |
| | | | 0 | 60- | | | | 62.5 | | Bottom of Boring @ 62 |
| | | | | | | | | | | |
| | | BLOW | PH-1- 34.5' PH-1- 40.5' | PH-1- 34.5' | PH-1- 34.5' | PH-1- 34.5' PH-1- 40- 40- 45- 45- 45- -50- O | PH-1- 34.5' PH-1- 40.5' PH-1- 45.5' PH-1- 45- 45- 45- 45- 45- 45- 45- 45- 45- 45 | PH-1- 34.5' Q40'- Weathered GRANITE; dark greenish gray (10GY 4/1); moist. Q40'- Weathered GRANITE and SILTSTONE moist. Q41'- greenish black (5GY 2.5/1). Q45'- Weathered GRANITE; with recrystalized granite clasts; dark greenish gray (5GY 4/1); moist. Q47'- unweathered granite clasts. Q55'- SILTSTONE and SANDSTONE Cobbles | PH-1- 34.5' PH-1- 40.5' PH-1- 45.5' @40'- Weathered GRANITE and SILTSTONE moist. @41'- greenish black (5GY 2.5/1). @45'- Weathered GRANITE; with recrystalized granite clasts, dark greenish gray (5GY 4/1); moist. @47'- unweathered granite clasts. @47'- unweathered granite clasts. | PH-1- 34.5' PH-1- 40- 40- @40'- Weathered GRANITE and SILTSTONE moist. @41'- greenish black (5GY 2.5/1). PH-1- 45.5' @45'- Weathered GRANITE; with recrystalized granite clasts; dark greenish gray (5GY 4/1); moist. @47'- unweathered granite clasts. @55'- SILTSTONE and SANDSTONE Cobbles |

Appendix C Certified Analytical Report





Cambria Environmental Sonoma

June 22, 2004

270 Perkins Street Sonoma, CA 95476

Attn.:

Ana Friel

Project#: 246-0735-006

Project:

98995744

Site:

9750 Golf Links Road East, Oakland

Attached is our report for your samples received on 06/08/2004 14:15 This report has been reviewed and approved for release. Reproduction of this report is permitted only in its entirety.


Please note that any unused portion of the samples will be discarded after 07/23/2004 unless you have requested otherwise.

We appreciate the opportunity to be of service to you. If you have any questions, please call me at (925) 484-1919.

You can also contact me via email. My email address is: vvancil@stl-inc.com

Sincerely,

Vincent Vancil Project Manager





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

Site: 9750 Golf Links Road East, Oakland

Samples Reported

| Sample Name | Date Sampled | Matrix | Lab# |
|-------------|------------------|--------|------|
| PH-1-5.5` | 06/07/2004 11:35 | Soil | 1 |
| PH-1-10.5` | 06/07/2004 11:41 | Soil | 2 |
| PH-1-15.5` | 06/07/2004 11:52 | Soil | 3 |
| PH-1-19.5` | 06/07/2004 11:55 | Soil | 4 |
| PH-1-24.5` | 06/07/2004 13:05 | Soil | 5 |
| PH-1-29.5° | 06/07/2004 13:35 | Soil | 6 |
| PH-1-34.5` | 06/07/2004 13:50 | Soil | 7 |
| PH-1-40.5` | 06/07/2004 14:15 | Soil | 8 |
| PH-1-45.5` | 06/07/2004 14:35 | Soil | 9 |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700


Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| Prep(s): | 5030B | Tesl(s) | 8260B |
|-----------|------------------|------------|------------------|
| Sample ID | PH-1-5.5 | Lab ID | 2004-05-0275 - 1 |
| Sampled | 06/07/2004 11:35 | Extracted: | 6/10/2004/21:50 |
| Mairix | Sall | QC Batch#. | 2004/06/10-2A 65 |

| Compound | Conc. | RL | Unit | Dilution | Analyzed | Flag |
|--------------------------------|-------|--------|-------|----------|------------------|------|
| Gasoline | ND | 1.0 | mg/Kg | 1.00 | 06/10/2004 21:50 | |
| Benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 21:50 | |
| Toluene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 21:50 | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 21:50 | |
| Total xylenes | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 21:50 | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 21:50 | |
| Surrogate(s) | | 1 | | | | |
| 1,2-Dichloroethane-d4 | 95.9 | 76-124 | % | 1.00 | 06/10/2004 21:50 | |
| Toluene-d8 | 96.3 | 75-116 | % | 1.00 | 06/10/2004 21:50 | |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| Prep(s) | 5030B | Test(s): | 82608 |
|-----------|------------------|-----------|------------------|
| Sample ID | PH-1-10.5 | Lat ID | 2004-06-0275 2 |
| Sampled: | 06/07/2004 11/41 | Extracted | 6/10/2004 23:01 |
| Matrix | Soil | QC Bafch# | 2004/06/10-2A.65 |

| Compound | Conc. | RL | Unit | Dilution | Analyzed | Flag |
|--------------------------------|-------|--------|-------|----------|------------------|------|
| Gasoline | ND | 1.0 | mg/Kg | 1.00 | 06/10/2004 23:01 | |
| Benzene | ND | 0.0050 | mg/Kg | | 06/10/2004 23:01 | |
| Toluene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:01 | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:01 | |
| Total xylenes | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:01 | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:01 | |
| Surrogate(s) | | | " " | | | |
| 1,2-Dichloroethane-d4 | 93.3 | 76-124 | % | 1.00 | 06/10/2004 23:01 | |
| Toluene-d8 | 97.4 | 75-116 | % | | 06/10/2004 23:01 | |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| Prep(s): | 5030B | Test(s): | 8260B | W. |
|-----------|------------------|------------|------------------|----|
| Sample ID | PH-1-15.57 | Lab ID | 2004-06-0276 - 3 | |
| Sampled: | 06/07/2004 11:52 | Extracted. | 6/10/2004 23:26 | |
| Matrix: | Soll | QC Batch#. | 2004/06/40-2A.65 | |

| Compound | Conc. | RL | Unit | Dilution | Analyzed | Flag |
|--------------------------------|-------|--------|-------|----------|------------------|------|
| Gasoline | ND | 1.0 | mg/Kg | 1.00 | 06/10/2004 23:26 | |
| Benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:26 | |
| Toluene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:26 | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:26 | |
| Total xylenes | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:26 | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:26 | |
| Surrogate(s) | | 1 | | | | |
| 1,2-Dichloroethane-d4 | 99.1 | 76-124 | % | 1.00 | 06/10/2004 23:26 | |
| Toluene-d8 | 102.8 | 75-116 | % | 1.00 | 06/10/2004 23:26 | |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| Prep(s): | 50308 | Test(s) | 8260B |
|-----------|------------------|------------|------------------|
| Sample ID | PH-1-19.5 | Lab ID | 2004-06-0275-4 |
| Sampled | 06/07/2004 11/55 | Extracted | 6/10/2004 23:50 |
| Matrix: | Soil | QC Batch#: | 2004/08/10-2A.65 |

| Compound | Conc. | RL | Unit | Dilution | Analyzed | Flag |
|--------------------------------|-------|--------|-------|----------|------------------|------|
| Gasoline | ND | 1.0 | mg/Kg | 1.00 | 06/10/2004 23:50 | |
| Benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:50 | |
| Toluene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:50 | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:50 | |
| Total xylenes | ND | 0.0050 | mg/Kg | | 06/10/2004 23:50 | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | 1.00 | 06/10/2004 23:50 | |
| Surrogate(s) | | | 1 ' ' | | | |
| 1,2-Dichloroethane-d4 | 93.6 | 76-124 | % | 1.00 | 06/10/2004 23:50 | |
| Toluene-d8 | 100.2 | 75-116 | % | | 06/10/2004 23:50 | |



Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

Site: 9750 Golf Links Road East, Oakland

| Prep(s): .5030B | Test(s) | 8260H |
|---------------------------|-----------|-------------------|
| Sample ID: PH-1-24.5 | Lab ID | 2004-06-0275 - 5 |
| Sampled: 06/07/2004 13:05 | Extracted | 6/41/2004 00:15 |
| Matrix Soil | QC Batch# | 2004/06/10 -2A,65 |

| Compound | Conc. | RL | Unit | Dilution | Analyzed | Flag |
|--------------------------------|-------|--------|-------|----------|------------------|------|
| Gasoline | ND | 1.0 | mg/Kg | 1.00 | 06/11/2004 00:15 | |
| Benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 00:15 | |
| Toluene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 00:15 | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 00:15 | |
| Total xylenes | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 00:15 | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 00:15 | |
| Surrogate(s) | | | | | | |
| 1,2-Dichloroethane-d4 | 95.0 | 76-124 | % | 1.00 | 06/11/2004 00:15 | |
| Toluene-d8 | 101.2 | 75-116 | % | 1.00 | 06/11/2004 00:15 | |

Severn Trent Laboratories, Inc.





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| Prep(s): 5030B | Test(s) 8260B |
|---------------------------|-----------------------------|
| Sample ID. PH-1-29.5 | Lab ID 2004-06-0275 - 6 |
| Sampled: 06/07/2004 13:35 | Extracted : 6/11/2084-08:39 |
| Matrix: Soil. | QC Batch#= 2004/06/10-2A:65 |

| Compound | Conc. | RL | Unit | Dilution | Analyzed | Flag |
|--------------------------------|-------|--------|-------|----------|------------------|------|
| Gasoline | ND | 1.0 | mg/Kg | 1.00 | 06/11/2004 00:39 | g |
| Benzene | ND | 0.0050 | mg/Kg | | 06/11/2004 00:39 | |
| Toluene | ND | 0.0050 | mg/Kg | | 06/11/2004 00:39 | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | | 06/11/2004 00:39 | |
| Total xylenes | ND | 0.0050 | mg/Kg | | 06/11/2004 00:39 | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | | 06/11/2004 00:39 | |
| Surrogate(s) | | | 3.3 | | | |
| 1,2-Dichloroethane-d4 | 104.7 | 76-124 | % | 1.00 | 06/11/2004 00:39 | |
| Toluene-d8 | 102.3 | 75-116 | % | | 06/11/2004 00:39 | |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| Prep(s): | 5030B\ | Test(s): | 82608 |
|-----------|---|------------|------------------|
| Sample ID | PH-1-34.5 | Lab ID | 2004-06-0275 - 7 |
| Sampled: | 08/07/2004 13:50 | Extracted: | 6/11/2004 01:03 |
| Matrix: | ISM TO THE REPORT OF THE PARTY | QC Baich# | 2004/06/10-2A.65 |

| Compound | Conc. | RL | Unit | Dilution | Analyzed | Flag |
|--------------------------------|-------|--------|-------|----------|------------------|------|
| Gasoline | ND | 1.0 | mg/Kg | 1.00 | 06/11/2004 01:03 | |
| Benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:03 | |
| Toluene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:03 | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:03 | |
| Total xylenes | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:03 | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:03 | |
| Surrogate(s) | | 1 | | | | |
| 1,2-Dichloroethane-d4 | 99.3 | 76-124 | % | 1.00 | 06/11/2004 01:03 | |
| Toluene-d8 | 98.7 | 75-116 | % | 1.00 | 06/11/2004 01:03 | |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| Prep(s); 5030B | Test(s): 8260B |
|-------------------------------|-----------------------------|
| Sample ID: PH-1-40.5 | Lab ID: 2004-06-0275_8 |
| - Sampled: - 06/07/2004 14/15 | Extracted: 6/11/2004 01:27 |
| Matrix: Soil | QC Batch#: 2004/06/10-2A.65 |

| Conc. | RL | Unit | Dilution | Analyzed | |
|-------|----------------------------|--|---|---|---|
| | | - | Dilation | Arialyzeo | Flag |
| ND | 1.0 | mg/Kg | 1.00 | 06/11/2004 01:27 | |
| ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:27 | |
| ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:27 | |
| ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:27 | |
| ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:27 | |
| ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 01:27 | |
| | |] ' ' | | | |
| 91.4 | 76-124 | _% | 1.00 | 06/11/2004 01:27 | |
| 101.3 | 75-116 | % | | | |
| | ND ND ND ND ND | ND 0.0050 ND 0.0050 ND 0.0050 ND 0.0050 ND 0.0050 ND 76-124 | ND 0.0050 mg/Kg | ND 0.0050 mg/Kg 1.00 91.4 76-124 % 1.00 | ND 0.0050 mg/Kg 1.00 06/11/2004 01:27 91.4 76-124 % 1.00 06/11/2004 01:27 |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700


Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| Prep(s): | 5030B | Test(s): | 8250B |
|------------|------------------|------------|------------------|
| Sample ID: | PH-1-45.5 | Lab ID: | 2004-06-0275 - 9 |
| Sampled | 06/07/2004 14:35 | Extracted | 6/11/2004 20:22 |
| Malrix | Soil | QC Batch#: | 2004/06/11-2A 65 |

| Compound | Conc. | RL | Unit | Dilution | Analyzed | Flag |
|--------------------------------|-------|--------|-------|----------|------------------|------|
| Gasoline | ND | 1.0 | mg/Kg | 1.00 | 06/11/2004 20:22 | |
| Benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 20:22 | |
| Toluene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 20:22 | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 20:22 | |
| Total xylenes | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 20:22 | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | 1.00 | 06/11/2004 20:22 | |
| Surrogate(s) | | | | | | |
| 1,2-Dichloroethane-d4 | 95.1 | 76-124 | % | 1.00 | 06/11/2004 20:22 | |
| Toluene-d8 | 102.7 | 75-116 | % | 1.00 | 06/11/2004 20:22 | |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| 些 不是好你。但对 | Bate | h QG Report | | 生產有關於 | | | | | | | |
|--|-------|-------------|---|------------------|------|--|--|--|--|--|--|
| Prep(s): 5030B Method Blank MB: 2004/06/10-2A:65-035 | | Soll | Test(s): 8260B QC Batch # 2004/06/10-2A 65 Date Extracted: 06/10/2004 18:35 | | | | | | | | |
| Compound | Conc. | RL | Unit | Analyzed | Flag | | | | | | |
| Gasoline | ND | 1.000 | mg/Kg | 06/10/2004 18:35 | | | | | | | |
| Benzene | ND | 0.0050 | mg/Kg | 06/10/2004 18:35 | | | | | | | |
| Toluene | ND | 0.0050 | mg/Kg | 06/10/2004 18:35 | | | | | | | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | 06/10/2004 18:35 | | | | | | | |
| Total xylenes | ND | 0.0050 | mg/Kg | 06/10/2004 18:35 | 1 1 | | | | | | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | 06/10/2004 18:35 | 1 1 | | | | | | |
| Surrogates(s) | | | | | l d | | | | | | |
| 1,2-Dichloroethane-d4 | 94.3 | 76-124 | % | 06/10/2004 18:35 | | | | | | | |
| Toluene-d8 | 101.4 | 75-116 | % | 06/10/2004 18:35 | | | | | | | |



Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476


Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| | Bate | ch QC Report | | 但是以此是 | 100 AND | | | | | | |
|--|-------|--------------|--|------------------------|---------|--|--|--|--|--|--|
| Prep(s): 5030B Method Blank MB: 2004/06/11-2A 65-007 | | Soll | QC Batch # 2004/06/11-2A_6 Date Extracted 06/11/2004 19:0 | | | | | | | | |
| Compound | Conc. | RL | Unit | Analyzed | Flag | | | | | | |
| Gasoline | ND | 1.000 | mg/Kg | 06/11/2004 19:07 | | | | | | | |
| Methyl tert-butyl ether (MTBE) | ND | 0.0050 | mg/Kg | Kg 06/11/2004 19:07 | | | | | | | |
| Benzene | ND | 0.0050 | mg/Kg | 06/11/2004 19:07 | | | | | | | |
| Toluene | ND | 0.0050 | mg/Kg | 06/11/2004 19:07 | | | | | | | |
| Ethyl benzene | ND | 0.0050 | mg/Kg | mg/Kg 06/11/2004 19:07 | | | | | | | |
| Total xylenes | ND | 0.0050 | mg/Kg | 06/11/2004 19:07 | | | | | | | |
| Surrogates(s) | | | | | | | | | | | |
| 1,2-Dichloroethane-d4 | 99.6 | 76-124 | % | 06/11/2004 19:07 | | | | | | | |
| Toluene-d8 | 100.2 | 75-116 | % | 06/11/2004 19:07 | | | | | | | |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| | 為主義官能達得特別的 | Batch QC Report | |
|-------------|--|--|--|
| Prep(s) | 5030B | | Test((s)), 8260B |
| Labora | tory Control Spike | Soll | QC Batch # 2004/06/10-2A.65 |
| LCS LCSD | 2004/06/10-2A 65-046 2004/06/10-2A 65-011 | Extracted: 06/10/2004 Extracted: 06/10/2004 | Analyzed: 06/10/2004 17:46 Analyzed: 06/10/2004 18:11 |

| Compound | Conc. | mg/Kg | Exp.Conc. | Reco | very % | RPD | Ctrl.Lin | nits % | % Flags | | | |
|--|----------------------|----------------------|----------------------|-------------------------|-------------------------|---------------------|----------------------------|----------------|---------|------|--|--|
| | LCS | LCSD | | LCS | LCSD | % | Rec. | RPD | LCS | LCSD | | |
| Benzene Toluene Methyl tert-butyl ether (MTBE) | 54.4 51.2 52.3 | 60.3 57.8 56.1 | 50.0 50.0 50.0 | 108.8 102.4 104.6 | 120.6 115.6 112.2 | 10.3 12.1 7.0 | 69-129 70-130 65-165 | 20 20 20 | | | | |
| Surrogates(s) 1,2-Dichloroethane-d4 Toluene-d8 | 447 500 | 432 489 | 500 500 | 89.4 100.0 | 86.4 97.8 | | 76-124 75-116 | | | | | |



Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700


Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| 是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个 | Batch QC Report | |
|---|--|--|
| Prep(s): 5030B | | Test(s): 8260B |
| Laboratory Control Spike | Soil | QC Batch # 2004/06/11-2A 65 |
| LCS 2004/06/11-2A:65-019 LCSD 2004/06/11-2A:65-043 | Extracted: 06/11/2004 Extracted: 06/11/2004 | Analyzed: 08/11/2004 18:19 Analyzed: 08/11/2004 18:43 |

| Compound | Conc. | mg/Kg | Exp.Conc. | Recov | ery % | RPD | Ctrl.Lin | nits % | Flags | | | |
|--------------------------------|--------|--------|-----------|-------|-------|------|----------|--------|-------|------|--|--|
| | LCS | LCSD | | LCS | LCSD | % | Rec. | RPD | LCS | LCSD | | |
| Methyl tert-butyl ether (MTBE) | 0.0520 | 0.0459 | 0.05 | 104.0 | 91.8 | 12.5 | 65-165 | 20 | | | | |
| Benzene | 0.0536 | 0.0472 | 0.05 | 107.2 | 94.4 | 12.7 | 69-129 | 20 | | | | |
| Toluene | 0.0515 | 0.0447 | 0.05 | 103.0 | 89.4 | 14.1 | 70-130 | 20 | | | | |
| Surrogates(s) | | | | | | | | | | | | |
| 1,2-Dichloroethane-d4 | 442 | 461 | 500 | 88.4 | 92.2 | | 76-124 | | | | | |
| Toluene-d8 | 506 | 502 | 500 | 101.2 | 100.4 | | 75-116 | | | | | |





Cambria Environmental Sonoma

Attn.: Ana Friel

270 Perkins Street Sonoma, CA 95476

Phone: (707) 442-2700 Fax: (707) 442-2700

Project: 246-0735-006

98995744

Received: 06/08/2004 14:15

| | Batch QC Report | | |
|---------------------------|-----------------------|------------------------|-----------------------------------|
| Prep(s): 5030B | | | Teli(s), 8260B |
| Matrix Spike (MS / MSD) | Soil | QC Bate | th # 2004/06/10-2A-65 |
| PH-1-5.5" >> MS | | Lab ID: | 2004-06-0275 - 001 |
| MS 2004/06/10-2A-65-013 | Extracted, 06/10/2004 | Analyzed: Dilution: | 68/10/ <u>2</u> 004-22-13 1.00 |
| MSD: 2004/06/10-24:65-038 | Extracted: 06/10/2004 | Analyzed: Dilution. | 06/40/2034 <u>22</u> :38 1.60 |

| Compound | Conc. | Conc. mg/Kg | | Spk.Level | R | ecovery | % | Limit | s % | Flags | | |
|-------------------------|-------|-------------|--------|-----------|-------|---------|-----|--------|-----|-------|-----|--|
| | MS | MSD | Sample | mg/Kg | MS | MSD | RPD | Rec. | RPD | MS | MSD | |
| Benzene | 47.3 | 48.9 | ND | 46.1 | 102.6 | 106.1 | 3.4 | 69-129 | 20 | | | |
| Toluene | 42.0 | 44.9 | 0.199 | 46.1 | 90.7 | 97.0 | 6.7 | 70-130 | 20 | | | |
| Methyl tert-butyl ether | 45.9 | 47.8 | ND | 46.1 | 99.6 | 103.7 | 4.0 | 65-165 | 20 | | | |
| Surrogate(s) | | 1 | 1 | 1 | | | | | 1 1 | | | |
| 1,2-Dichloroethane-d4 | 441 | 472 | 1 | 500 | 88.2 | 94.4 | | 76-124 | 1 1 | | | |
| Toluene-d8 | 496 | 494 | | 500 | 99.2 | 98.8 | | 75-116 | | | | |

| 1220 Quarry Lane Pieceanton; CA 94568 925) 484-1919 (925) 484-1096 fax | | - TO (1) | ACCRECATE AND ADDRESS OF | | 14 | 11 ADO | | Street, | | | - Main | La compa | | | | 8 | | | a a | 100 | | q | You. | | MGE H _ H |
|--|----------------------------|-------------------|--------------------------|--------|-----------------|-----------------|---|----------|-----------|-----------|---------|----------|-------|----------|-------------------|-------------------------|-----------------------|--|----------|--------------|-----|--------------|--------|------------|---|
| Oria Environmental Technology, Inc. Sec. Perdus Street, Sorioma, CA 95478 EDT CONTACT Persons a PCF Reported Firel FIRE | GETS EARLY office Go | sertificati | 0.200m2 | | | o Frie | I . | to greec | | Roi)(| | | 1 | (707 |) 442 | ×2700 | | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | | | - 4 | 931 mbris | env.co | | 246-0735-006) |
| IO DAYS 🔲 5 DAYS 🔲 772 HOURS 🔲 46 HOURS | Озж | XVRS 🔾 ILI | SS TIWH 2 | HOURS | | | | | n | | | | E T | | R | EQU | EST | ED A | NAI | YSI | 9 | | | | U. a. Transaction |
| The second secon | CK BOX IF | The second second | OFFICE AND ADDRESS. | (a) | 200 | STREETS SECTION | Salar I | | | - Inco | end EDS | 1 | 10 | y exists | clathies by 8270C | o feel to stud or read- | a This g stud g total | a been site or fore | Chaptest | тасыер внеет | | 100 | | | FIELD NOTES: Container/Preservative or PID Readings or Laboratory Notes |
| Field Sample Identification | DATE | TIME | MATRIX | HO, OF | , KA | 17. | ig i | HE | 10 | g/xx0 S | 90 | ethano | 1 | NOCE P | Semi-V | | SE I | CAMPITY. | Tare for | ERAI | - | | | | TEMPERATURE ON RECEIPT OF |
| PH-1-5.5 | 6/7 | 11:35 | 50 | 1 | X | 9 | X | X | find - | | | | 100 A | 115 | | 1 | | | | - 1 | | | 15 | | |
| PH-1-10.51 | 11 | 11:41 | | 1 | X | 1 | X | X | | | 722 | | | 0/17 | ĵ, | | | î | | | | | | | |
| PH-1-155 | 11 | 11:52 | 100 | + 301 | X | | X | X | | | | | | Б | 7 | 19 | 1-1 | | 1 | | | | | | |
| PH- I- M.S | 1 | 11:55 | 3 | 1 | X | | X | X | | 100 | | | | - 8 | | 1 | 1 | | | | 0 | | | | |
| PH-1-24.5 | + | 13:05 | | 1 | X | | X | X | | - | 49 | | | - | | | - | _ | | e to | - 4 | إملا | - | bia | |
| 1211 1 201 61 | + | (3:35 3:50 | | W | Ø | - | X | X | H | - | | | = | - | - Y | | - | | - 5 | | | Н | | V - | |
| PH-1-29.51 | design - | 14:15 | | - 1 | × | | V | V | | | 000 | | + | for i | 7 | - 2 | + | - | - | | | | | 3 | |
| PH-+34.51 | | | | 7 | × | 1 | × | × | | | | | | | 2 | | - | + | | | | 17 | - | | |
| PH-1-40.51 | V | 1 | 1 | 100 | ALC: UNKNOWN OF | 4 | 100 | 1 | | - | | | | | | | 1 | 1 | | | | | | T | *************************************** |
| PH-+34.51 | V | 14-35 | | | | - | *** | | 1 | 1: 1 | | | | | The same | 100 | the second | | | | | | 8 | described. | |
| PH-1-40.51 | V | 1 | | Qu. | | | 111111111111111111111111111111111111111 | | | | _ | | | -1 | | | 1 | ************************************** | | F | 64 | _ | | Time | 45 |