



GETTLER-RYAN INC.

RO CO-065

DEC 17 2001

TRANSMITTAL

November 26, 2001

G-R #386498

TPHD exceeds SEP2 Screening levels

TO: Mr. James Brownell
Delta Environmental Consultants, Inc.
3164 Gold Camp Drive, Suite 200
Rancho Cordova, California 95670

CC: Mr. Thomas Bauhs
Chevron Products Company
P.O. Box 6004
San Ramon, California 94583

FROM: Deanna L. Harding
Project Coordinator
Gettler-Ryan Inc.
6747 Sierra Court, Suite J
Dublin, California 94568

RE: Chevron #206127
(Former Signal Oil Marine Terminal)
2301-2337 Blanding Avenue
Alameda, California

WE HAVE ENCLOSED THE FOLLOWING:

COPIES	DATED	DESCRIPTION
1	November 16, 2001	Groundwater Monitoring and Sampling Report Fourth Quarter - Event of October 8, 2001

COMMENTS:

This report is being sent for your review. Please provide any comments/changes and propose any groundwater monitoring modifications for the next event prior to **December 10, 2001**, at which time the final report will be distributed to the following:

cc: Ms. Eva Chu, Alameda County Health Care Services, Dept. of Environmental Health, 1131 Harbor Bay Parkway, Suite 250, Alameda, CA 94502-6577
Mr. Greg Guss, Gettler-Ryan Inc., 3164 Gold Camp Drive, Suite 240, Rancho Cordova, CA 95670

Enclosures

trans/206127-tb



GETTLER-RYAN INC.

November 16, 2001
G-R Job #386498

Mr. Thomas Bauhs
Chevron Products Company
P.O. Box 6004
San Ramon, CA 94583

RE: Fourth Quarter Event of October 8, 2001
Groundwater Monitoring & Sampling Report
Chevron #206127 (Former Signal Oil Marine Terminal)
2301-2337 Blanding Avenue
Alameda, California

Dear Mr. Bauhs:

This report documents the most recent groundwater monitoring and sampling event performed by Gettler-Ryan Inc. (G-R) at the referenced site. All field work was conducted in accordance with G-R Standard Operating Procedure - Groundwater Sampling (attached).

Static groundwater level was measured and the well was checked for the presence of separate-phase hydrocarbons. Static water level data, groundwater elevation, and separate-phase hydrocarbon thickness (if any) are presented in the attached Table 1. A Groundwater Elevation Map is included as Figure 1.

Groundwater samples were collected from the monitoring well and submitted to a state certified laboratory for analyses. The field data sheet for this event is attached. Analytical results are presented in the table(s) listed below. The chain of custody document and laboratory analytical report are also attached.

Please call if you have any questions or comments regarding this report. Thank you.

Sincerely,

- For -
Deanna L. Harding
Project Coordinator

Douglas J. Lee
Senior Geologist, R.G. No. 6882





Figure 1: Groundwater Elevation Map
Table 1: Groundwater Monitoring Data and Analytical Results
Attachments: Standard Operating Procedure - Groundwater Sampling
Field Data Sheets
Chain of Custody Document and Laboratory Analytical Reports

EXPLANATION

- ◆ Groundwater monitoring well
 - ◆ Canal water level gauging station from Park Street Bridge (RRM, October 1998)
 - ◇ Canal grab surface water sample
 - Shallow groundwater survey point (Geomatrix, April 1995)
 - ⋮ Site features noted on Sanborn Fire Insurance map, dated 1932
- | | |
|-------|--|
| 99.99 | Groundwater elevation in feet referenced to Mean Sea Level (MSL) |
| NA | Not Available |



Source: Figure modified from drawing provided by RRM engineering contracting firm.

FIGURE 1

GROUNDWATER ELEVATION MAP
 Chevron #206127 (Former Signal Oil Marine Terminal)
 2301-2337 Blanding Avenue
 Alameda, California

GETTLER - RYAN INC.
 6747 Sierra Ct., Suite J
 Dublin, CA 94568
 (925) 551-7555

PROJECT NUMBER: 386498
 REVIEWED BY: [Signature]
 DATE: October 8, 2001
 REVISION DATE: [Blank]

FILE NAME: P:\ENVIRO\CHEVRON\206127\001-30-6127.DWG | Layout Tab: Pot4

Table 1
Groundwater Monitoring Data and Analytical Results
 Chevron #206127 (Former Signal Oil Marine Terminal)
 2301-2337 Blanding Avenue
 Alameda, California

WELL ID/ TOC*	DATE	DTW (ft.)	GWE (msl)	TPH-D (ppb)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-1	01/23/01 ¹	7.16	--	1,100 ^{2,3}	5,210 ⁴	868	<50.0	<50.0	<50.0	<250
10.62	04/09/01	8.12	2.50	1,200 ⁶	3,000 ⁵	920	<20	<20	<20	<100
	07/30/01	9.15	1.47	550 ^{4,8}	2,000 ⁷	730	13	<5.0	<5.0	<25
	10/08/01	7.86	2.76	2,200 ⁹	1,200	120	2.4	5.9	6.4	<2.5
CS-2	07/30/01	--	--	140 ^{4,5}	<50	<0.50	<0.50	<0.50	<0.50	<2.5
	10/08/01	--	--	53 ⁹	<50	<0.50	<0.50	<0.50	<1.5	<2.5
Trip Blank										
TB-LB	01/23/01	--	--	--	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50
	04/09/01	--	--	--	<50	<0.50	<0.50	<0.50	<0.50	<2.5
	07/30/01	--	--	--	<50	<0.50	<0.50	<0.50	<0.50	<2.5
QA	10/08/01	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron #206127 (Former Signal Oil Marine Terminal)
2301-2337 Blanding Avenue
Alameda, California

EXPLANATIONS:

TOC = Top of Casing
DTW = Depth to Water
(ft.) = Feet

GWE = Groundwater Elevation
(msl) = Mean sea level

TPH-D = Total Petroleum Hydrocarbons as Diesel

TPH-G = Total Petroleum Hydrocarbons as Gasoline

B = Benzene

T = Toluene

E = Ethylbenzene

X = Xylenes

MTBE = Methyl tertiary butyl ether

(ppb) = Parts per billion

QA = Quality Assurance

-- = Not Measured/Not Analyzed

CS-2 = Creek Sample

* TOC elevations were surveyed on January 25, 2001, by Virgil Chavez Land Surveying. The benchmark used for the survey was a City of Alameda benchmark being a cut square at the centerline return, south corner of Oak and Blanding, (Benchmark Elevation = 8.236 feet, NGVD 29).

¹ Well development performed.

² Laboratory report indicates unidentified hydrocarbons <C16.

³ Laboratory report indicates weathered gasoline C6-C12.

⁴ TPH-D with silica gel cleanup.

⁵ Laboratory report indicates discrete peaks.

⁶ Laboratory report indicates diesel C9-C24 + unidentified hydrocarbons <C16.

⁷ Laboratory report indicates gasoline C6-C12.

⁸ Laboratory report indicates unidentified hydrocarbons C9-C24.

⁹ Analysis performed without silica gel cleanup as requested on the Chain of Custody. *(but not done by lab)*

STANDARD OPERATING PROCEDURE - GROUNDWATER SAMPLING

Gettler-Ryan Inc. field personnel adhere to the following procedures for the collection and handling of groundwater samples prior to analysis by the analytical laboratory. Prior to sample collection, the type of analysis to be performed is determined. Loss prevention of volatile compounds is controlled and sample preservation for subsequent analysis is maintained.

Prior to sampling, the presence or absence of free-phase hydrocarbons is determined using an interface probe. Product thickness, if present, is measured to the nearest 0.01 foot and is noted in the field notes. In addition, static water level measurements are collected with the interface probe and are also recorded in the field notes.

After water levels are collected and prior to sampling, each well is purged a minimum of three well casing volumes of water using pre-cleaned pumps (stack, suction, Grundfos), or polyvinyl chloride bailers. Temperature, pH and electrical conductivity are measured a minimum of three times during the purging. Purging continues until these parameters stabilize.

Groundwater samples are collected using Chevron-designated disposable bailers. The water samples are transferred from the bailer into appropriate containers. Pre-preserved containers, supplied by analytical laboratories, are used when possible. When pre-preserved containers are not available, the laboratory is instructed to preserve the sample as appropriate. Duplicate samples are collected for the laboratory to use in maintaining quality assurance/quality control standards. The samples are labeled to include the job number, sample identification, collection date and time, analysis, preservation (if any), and the sample collector's initials. The water samples are placed in a cooler, maintained at 4°C for transport to the laboratory. Once collected in the field, all samples are maintained under chain of custody until delivered to the laboratory.

The chain of custody document includes the job number, type of preservation, if any, analysis requested, sample identification, date and time collected, and the sample collector's name. The chain of custody is signed and dated (including time of transfer) by each person who receives or surrenders the samples, beginning with the field personnel and ending with the laboratory personnel.

A laboratory supplied trip blank accompanies each sampling set. For sampling sets greater than 20 samples, 5% trip blanks are included. The trip blank is analyzed for some or all of the same compounds as the groundwater samples.

As requested by Chevron Products Company, the purge water and decontamination water generated during sampling activities is transported by IWM to McKittrick Waste Management located in McKittrick, California.

WELL MONITORING/SAMPLING FIELD DATA SHEET

CHEVRON
ent/
cility #

206127

Job#: 386498

Address: 2301-2337 Blanding Ave.

Date: 10-8-01

City: Alameda, CA

Sampler: FRANK T.

Well ID: MW-1

Well Condition: OK

Well Diameter: 2" in.

Hydrocarbon Thickness: 0 in. Amount Bailed (product/water): 0 (gal.)

Total Depth: 17.55 ft.

Volume Factor (VF)	2" = 0.17	3" = 0.38	4" = 0.66
	6" = 1.50	12" = 5.80	

Depth to Water: 7.86 ft.

9.69 x VF 0.17 = 1.64 x 3 (case volume) = Estimated Purge Volume: 4.94 (gal.)

Purge Equipment: (Disposable Bailer)
Bailer
Stack
Suction
Grundfos
Other: _____

Sampling Equipment: (Disposable Bailer)
Bailer
Pressure Bailer
Grab Sample
Other: _____

Starting Time: 3:47

Weather Conditions: SUNNY

Sampling Time: 4:06

Water Color: CLOUDY / GREY Odor: YES

Purging Flow Rate: N/A gpm.

Sediment Description: SILTY

Did well de-water? NO

If yes; Time: _____ Volume: _____ (gal.)

Time	Volume (gal.)	pH	Conductivity (µmhos/cm) x	Temperature (°F)	D.O. (mg/L)	ORP (mV)	Alkalinity (ppm)
<u>3:50</u>	<u>1.5</u>	<u>6.98</u>	<u>907</u>	<u>65.1</u>	_____	_____	_____
<u>3:53</u>	<u>3.0</u>	<u>6.96</u>	<u>730</u>	<u>64.6</u>	_____	_____	_____
<u>3:57</u>	<u>5.0</u>	<u>6.93</u>	<u>662</u>	<u>64.2</u>	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____	_____

LABORATORY INFORMATION

SAMPLE ID	(#) - CONTAINER	REFRIG.	PRESERV. TYPE	LABORATORY	ANALYSES
				LAN.	TPH/G/BTEX/MTOE / TPH-D
<u>MW-1</u>	<u>3 x VOA VIAL</u>	<u>Y</u>	<u>HCL</u>	<u>LAN.</u>	<u>TPH-G/BTEX/MTOE / TPH-D</u>
	<u>2 x 1 LT. AMBER</u>	<u>"</u>	<u>"</u>	<u>"</u>	

COMMENTS: _____

WELL MONITORING/SAMPLING FIELD DATA SHEET

CHEVRON
 Client/ Facility # 206127
 Address: 2301-2337 Blanding Ave.
 City: Alameda, CA

Job#: 386498
 Date: 10.8.01
 Sampler: FRANK T.

Well ID: CS-2
 Well Diameter: N/A in.
 Total Depth: _____ ft.
 Depth to Water: _____ ft.

Well Condition: CREEK SAMPLE
 Hydrocarbon Thickness: 0 in. Amount Bailed (product/water): 0 (gal.)
 Volume Factor (VF) 2" = 0.17 3" = 0.38 4" = 0.66
 6" = 1.50 12" = 5.80

Purge Equipment: N/A
 Disposable Bailer
 Bailer
 Stack
 Suction
 Grundfos
 Other: _____

Sampling Equipment: (Disposable Bailer)
 Bailer
 Pressure Bailer
 Grab Sample
 Other: _____

Starting Time: _____
 Sampling Time: 3:30
 Purging Flow Rate: _____ gpm.
 Did well de-water? _____

Weather Conditions: SUNNY
 Water Color: CLEAR Odor: YES
 Sediment Description: _____
 If yes; Time: _____ Volume: _____ (gal.)

Time	Volume (gal.)	pH	Conductivity $\mu\text{mhos/cm} \times 1000$	Temperature $^{\circ}\text{F}$	D.O. (mg/L)	ORP (mV)	Alkalinity (ppm)
		<u>6.97</u>	<u>220</u>	<u>67.9</u>			

LABORATORY INFORMATION

SAMPLE ID	(#) - CONTAINER	REFRIG.	PRESERV. TYPE	LABORATORY	ANALYSES
<u>CS-2</u>	<u>3 x VOA VIAL</u>	<u>Y</u>	<u>HCL</u>	<u>LAD.</u>	<u>TPH/G/BTEX/MTOE/</u>
	<u>2 x LT. AMBER</u>	<u>"</u>	<u>"</u>	<u>"</u>	<u>TPH-D</u>

COMMENTS: TOOK CREEK SAMPLE FROM LOCATION SHOWN ON THE MAP.

Chevron California Region Analysis Request/Chain of Custody



091001-001

Acct. #: 10905 Sample #: 3703285-87

SCR#: _____

Facility #: 206127 JOB #386498 Site Address: 2301-2337 Dlanding Ave., Alameda, CA Chevron PM: Thomas Bauhs Lead Consultant: Delta/G-R Consultant/Office: G-R Inc. 6747 Sierra Ct, Dublin, CA 94568 Consultant Prj. Mgr.: Deanna L. Harding Deanna@grinc.com Consultant Phone #: 925-551-7555 Fax #: 925-551-7899 Sampler: Frank Terrinoni Service Order #: _____ <input type="checkbox"/> Non SAR: _____			Matrix Potable <input type="checkbox"/> NPDES <input type="checkbox"/> Water <input type="checkbox"/> Oil <input type="checkbox"/> Air <input type="checkbox"/>		Analyses Requested Preservation Codes H H H BTEX + MTBE 8260 <input type="checkbox"/> 8021 <input checked="" type="checkbox"/> TPH 8015 MOD GRO TPH 8015 MOD DRO <input checked="" type="checkbox"/> Silica Gel Cleanup 8260 full scan Oxygenates _____ Lead 7420 <input type="checkbox"/> 7421 <input type="checkbox"/>										Preservative Codes H = HCl T = Thiosulfate N = HNO ₃ B = NaOH S = H ₂ SO ₄ O = Other <input type="checkbox"/> J value reporting needed <input type="checkbox"/> Must meet lowest detection limits possible for 8260 compounds 8021 MTBE Confirmation <input type="checkbox"/> Confirm highest hit by 8260 <input type="checkbox"/> Confirm all hits by 8260 <input type="checkbox"/> Run ___ oxy s on highest hit <input type="checkbox"/> Run ___ oxy s on all hits									
Sample Identification	Date Collected	Time Collected	Grab	Composite	Soil	Water	Oil	Air	Total Number of Containers	BTEX + MTBE 8260	TPH 8015 MOD GRO	TPH 8015 MOD DRO	8260 full scan	Oxygenates	Lead 7420	Lead 7421	Comments / Remarks							
QA	10.8.01					W			2	X	X													
CS-2	█	1530	X			↓			5	X	X	X												
MW-1	↓	1606	X			↓			5	X	X	X												
Turnaround Time Requested (TAT) (please circle) STD. TAT 72 hour 48 hour 24 hour 4 day 5 day			Relinquished by: Frank Terrinoni Date: 10-9-01 Time: _____		Received by: Andrew Amaze Date: 10-9-01 Time: 0820		Relinquished by: Andrew Amaze Date: 10-9-01 Time: 15:10			Received by: Fed Ex Date: _____ Time: _____		Relinquished by: _____ Date: _____ Time: _____			Received by: _____ Date: _____ Time: _____		Relinquished by Commercial Carrier: UPS <input checked="" type="checkbox"/> FedEx Other _____		Received by: _____ Date: 12/1/01 Time: 3:20		Temperature Upon Receipt: 2.5 3.20°C		Custody Seals Intact? <input checked="" type="checkbox"/> Yes No	



RECEIVED

ANALYTICAL RESULTS

Prepared for:

Chevron Products Company
6001 Bollinger Canyon Road
Building L PO Box 6004
San Ramon CA 94583-0904
925-842-8582

Prepared by:

Lancaster Laboratories
2425 New Holland Pike
Lancaster, PA 17605-2425

SAMPLE GROUP

The sample group for this submittal is 781519. Samples arrived at the laboratory on Wednesday, October 10, 2001. The PO# for this group is 99011184 and the release number is BAUHS.

<u>Client Description</u>			<u>Lancaster Labs Number</u>
QA	NA	Water	3703285
CS-2	Grab	Water	3703286
MW-1	Grab	Water	3703287

METHODOLOGY

The specific methodologies used in obtaining the enclosed analytical results are indicated on the laboratory chronicles.


1 COPY TO

Delta C/O Gettler-Ryan

Attn: Deanna L. Harding

Questions? Contact your Client Services Representative
Teresa M. Lis at (717) 656-2300.

Respectfully Submitted,


Christine M. Dufanev
Sr. Chemist





Lancaster Laboratories Sample No. **WW 3703285**

Collected: 10/08/2001 00:00

Account Number: 10905

Submitted: 10/10/2001 09:30
 Reported: 10/18/2001 at 07:46
 Discard: 11/18/2001

Chevron Products Company
 6001 Bollinger Canyon Road
 Building L PO Box 6004
 San Ramon CA 94583-0904

QA NA Water

Facility# 206127 Job# 386498 GRD
 2301-2337 Blanding Alamed NA QA

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor
01729	TPH-GRO N. California (waters)					
01730	TPH-GRO N. California (waters)	n.a.	N.D.	50.	ug/l	1
	The reported concentration of TPH-GRO does not include MTBE or other gasoline constituents eluting prior to the C6 (n-hexane) TPH-GRO range start time.					
	A site-specific MSD sample was not submitted for the project. A LCS/LCSD was performed to demonstrate precision and accuracy at a batch level.					
08214	BTEX, MTBE (8021)					
00776	Benzene	71-43-2	N.D.	0.50	ug/l	1
00777	Toluene	108-88-3	N.D.	0.50	ug/l	1
00778	Ethylbenzene	100-41-4	N.D.	0.50	ug/l	1
00779	Total Xylenes	1330-20-7	N.D.	1.5	ug/l	1
00780	Methyl tert-Butyl Ether	1634-04-4	N.D.	2.5	ug/l	1
	A site-specific MSD sample was not submitted for the project. A LCS/LCSD was performed to demonstrate precision and accuracy at a batch level.					

State of California Lab Certification No. 2116

Laboratory Chronicle

CAT No.	Analysis Name	Method	Analysis		Analyst	Dilution Factor
			Trial#	Date and Time		
01729	TPH-GRO N. California (waters)	N. CALIF. LUFT Gasoline Method	1	10/11/2001 23:54	Melissa Mann	1
08214	BTEX, MTBE (8021)	SW-846 8021B	1	10/11/2001 23:54	Melissa Mann	1
01146	GC VOA Water Prep	SW-846 5030B	1	10/11/2001 23:54	Melissa Mann	n.a.



Lancaster Laboratories, Inc.
 2425 New Holland Pike
 PO Box 12425
 Lancaster, PA 17605-2425
 717-656-2300 Fax: 717-656-2681



Lancaster Laboratories Sample No. **WW 3703286**

Collected: 10/08/2001 15:30 by FT Account Number: 10905

Submitted: 10/10/2001 09:30
 Reported: 10/18/2001 at 07:46
 Discard: 11/18/2001
 CS-2 Grab Water

Chevron Products Company
 6001 Bollinger Canyon Road
 Building L PO Box 6004
 San Ramon CA 94583-0904

Facility# 206127 Job# 386498 GRD
 2301-2337 Blanding Alamed NA NA

BACS2

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor
05553	TPH - DRO CA LUFT (Waters)	n.a.	53. J	50.	ug/l	1
According to the California LUFT Protocol, the quantitation for Diesel Range Organics was performed by peak area comparison of the sample pattern to that of our #2 fuel oil reference standard (between C10 and C28 normal hydrocarbons). Sufficient sample volume was not available to perform a MS/MSD for this analysis. Therefore, a LCS/LCSD was performed to demonstrate precision and accuracy at a batch level.						
01729	TPH-GRO N. California (waters)					
01730	TPH-GRO N. California (waters)	n.a.	N.D.	50.	ug/l	1
The reported concentration of TPH-GRO does not include MTBE or other gasoline constituents eluting prior to the C6 (n-hexane) TPH-GRO range start time. A site-specific MSD sample was not submitted for the project. A LCS/LCSD was performed to demonstrate precision and accuracy at a batch level.						
08214	BTEX, MTBE (8021)					
00776	Benzene	71-43-2	N.D.	0.50	ug/l	1
00777	Toluene	108-88-3	N.D.	0.50	ug/l	1
00778	Ethylbenzene	100-41-4	N.D.	0.50	ug/l	1
00779	Total Xylenes	1330-20-7	N.D.	1.5	ug/l	1
00780	Methyl tert-Butyl Ether	1634-04-4	N.D.	2.5	ug/l	1
A site-specific MSD sample was not submitted for the project. A LCS/LCSD was performed to demonstrate precision and accuracy at a batch level.						

State of California Lab Certification No. 2116

Laboratory Chronicle



Lancaster Laboratories Sample No. **WW 3703286**

Collected: 10/08/2001 15:30 by FT

Account Number: 10905

Submitted: 10/10/2001 09:30

Reported: 10/18/2001 at 07:46

Discard: 11/18/2001

CS-2 Grab Water

Chevron Products Company
6001 Bollinger Canyon Road
Building L PO Box 6004
San Ramon CA 94583-0904

Facility# 206127 Job# 386498 GRD
2301-2337 Blanding Alamed NA NA

BACS2
CAT

No.	Analysis Name	Method	Trial#	Analysis Date and Time	Analyst	Dilution Factor
05553	TPH - DRO CA LUFT (Waters)	CA LUFT Diesel Range Organics	1	10/12/2001 19:42	Devin M. Lahr	1
01729	TPH-GRO N. California (waters)	N. CALIF. LUFT Gasoline Method	1	10/11/2001 18:01	Melissa Mann	1
08214	BTEX, MTBE (8021)	SW-846 8021B	1	10/11/2001 18:01	Melissa Mann	1
01146	GC VOA Water Prep	SW-846 5030B	1	10/11/2001 18:01	Melissa Mann	n.a.
02176	Silica Quick Gel Cleanup	FL-PRO, 11/95	1	10/11/2001 17:00	Elia R. Botrous	1



Lancaster Laboratories Sample No. **WW 3703287**

Collected: 10/08/2001 16:06 by FT

Account Number: 10905

Submitted: 10/10/2001 09:30

Chevron Products Company

Reported: 10/18/2001 at 07:46

6001 Bollinger Canyon Road

Discard: 11/18/2001

Building L PO Box 6004

MW-1 Grab Water

San Ramon CA 94583-0904

Facility# 206127 Job# 386498 GRD
2301-2337 Blanding Alamed NA NA

BAMW1

CAT No.	Analysis Name	CAS Number	As Received Result	As Received		Units	Dilution Factor
				Method	Detection Limit		
05553	TPH - DRO CA LUFT (Waters)	n.a.	2,200.		50.	ug/l	1
<p>According to the California LUFT Protocol, the quantitation for Diesel Range Organics was performed by peak area comparison of the sample pattern to that of our #2 fuel oil reference standard (between C10 and C28 normal hydrocarbons). Sufficient sample volume was not available to perform a MS/MSD for this analysis. Therefore, a LCS/LCSD was performed to demonstrate precision and accuracy at a batch level.</p>							
01729	TPH-GRO N. California (waters)						
01730	TPH-GRO N. California (waters)	n.a.	1,200.		50.	ug/l	1
<p>The reported concentration of TPH-GRO does not include MTBE or other gasoline constituents eluting prior to the C6 (n-hexane) TPH-GRO range start time. A site-specific MSD sample was not submitted for the project. A LCS/LCSD was performed to demonstrate precision and accuracy at a batch level.</p>							
08214	BTEX, MTBE (8021)						
00776	Benzene	71-43-2	120.		0.50	ug/l	1
00777	Toluene	108-88-3	2.4		0.50	ug/l	1
00778	Ethylbenzene	100-41-4	5.9		0.50	ug/l	1
00779	Total Xylenes	1330-20-7	6.4		1.5	ug/l	1
00780	Methyl tert-Butyl Ether	1634-04-4	N.D.		2.5	ug/l	1
<p>A site-specific MSD sample was not submitted for the project. A LCS/LCSD was performed to demonstrate precision and accuracy at a batch level.</p>							

State of California Lab Certification No. 2116

Laboratory Chronicle



Lancaster Laboratories, Inc.
2425 New Holland Pike
PO Box 12425
Lancaster, PA 17605-2425
717-656-2300 Fax: 717-656-2681



Lancaster Laboratories Sample No. WW 3703287

Collected: 10/08/2001 16:06 by FT

Account Number: 10905

Submitted: 10/10/2001 09:30
 Reported: 10/18/2001 at 07:46
 Discard: 11/18/2001

Chevron Products Company
 6001 Bollinger Canyon Road
 Building L PO Box 6004
 San Ramon CA 94583-0904

MW-1 Grab Water

Facility# 206127 Job# 386498 GRD
 2301-2337 Blanding Alamed NA NA

BAMW1 CAT No.	Analysis Name	Method	Trial#	Analysis Date and Time	Analyst	Dilution Factor
05553	TPH - DRO CA LUFT (Waters)	CA LUFT Diesel Range Organics	1	10/12/2001 20:10	Devin M. Lahr	1
01729	TPH-GRO N. California (waters)	N. CALIF. LUFT Gasoline Method	1	10/11/2001 18:36	Melissa Mann	1
08214	BTEX, MTBE (8021)	SW-846 8021B	1	10/11/2001 18:36	Melissa Mann	1
01146	GC VOA Water Prep	SW-846 5030B	1	10/11/2001 18:36	Melissa Mann	n.a.
02176	Silica Quick Gel Cleanup	FL-PRO, 11/95	1	10/11/2001 17:00	Elia R. Botrous	1



Lancaster Laboratories, Inc.
 2425 New Holland Pike
 PO Box 12425
 Lancaster, PA 17605-2425
 717-656-2300 Fax: 717-656-2681



Client Name: Chevron Products Company
 Reported: 10/18/01 at 07:46 AM

Group Number: 781519

Laboratory Compliance Quality Control

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCSD %REC</u>	<u>LCS/LCSD Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Batch number: 012840002A TPH - DRO CA LUFT (Waters)	N.D.	50.	ug/l	99	79	54-120	23*	20
Batch number: 01284A56	Sample number(s): 3703285-3703287							
Benzene	N.D.	0.5	ug/l	106	108	80-118	2	30
Toluene	N.D.	0.5	ug/l	106	108	82-119	1	30
Ethylbenzene	N.D.	0.5	ug/l	108	110	81-119	2	30
Total Xylenes	N.D.	1.5	ug/l	108	110	82-120	2	30
Methyl tert-Butyl Ether	N.D.	2.5	ug/l	103	108	79-127	4	30
TPH-GRO N. California (waters)	N.D.	50.	ug/l	106	109	76-119	3	20

Sample Matrix Quality Control

<u>Analysis Name</u>	<u>MS %REC</u>	<u>MSD %REC</u>	<u>MS/MSD Limits</u>	<u>RPD</u>	<u>MAX</u>	<u>BKG Conc</u>	<u>DUP Conc</u>	<u>DUP RPD</u>	<u>Dup RPD Max</u>
Batch number: 01284A56	Sample number(s): 3703285-3703287								
Benzene	116		66-140						
Toluene	117		72-138						
Ethylbenzene	119		71-138						
Total Xylenes	118		69-140						
Methyl tert-Butyl Ether	140		60-145						
TPH-GRO N. California (waters)	112		74-132						

Surrogate Quality Control

Analysis Name: TPH - DRO CA LUFT (Waters)
 Batch number: 012840002A
 Orthoterphenyl

3703286	86
3703287	87
Blank	85
LCS	125
LCSD	102

Limits: 59-157

Analysis Name: TPH-GRO N. California (waters)
 Batch number: 01284A56
 Trifluorotoluene-F Trifluorotoluene-P

3703285	102	97
3703286	100	99
3703287	128	115

*- Outside of specification

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.



Lancaster Laboratories, Inc.
 2425 New Holland Pike
 PO Box 12425
 Lancaster, PA 17605-2425
 717-656-2300 Fax: 717-656-2681



Lancaster Laboratories

Where quality is a science.

Quality Control Summary

Page 2 of 2

Client Name: Chevron Products Company
Reported: 10/18/01 at 07:46 AM

Group Number: 781519

Surrogate Quality Control

Blank	102	96
LCS	113	97
LCSD	114	97
MS	120	98
<hr/>		
Limits:	65-137	72-134

*- Outside of specification

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.



Lancaster Laboratories, Inc.
2425 New Holland Pike
PO Box 12425
Lancaster, PA 17605-2425
717-656-2300 Fax: 717-656-2681