

Environmental Management
Company
6001 Bollinger Canyon Rd, L4050
P.O. Box 6012
San Ramon, CA 94583-2324
Tel 925-842-1589
Fax 925-842-8370

Karen Streich
Project Manager

Ro 2466

Sept. 15, 2004

ChevronTexaco

Alameda County Health Care Services
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577

Alameda County
SEP 17 2004
Environmental Health

Re: Chevron Service Station # 206127

Address: 2301-2337 Blanding Ave., Alameda, CA

I have reviewed the attached routine groundwater monitoring report dated August 17, 2004.

I agree with the conclusions and recommendations presented in the referenced report. The information in this report is accurate to the best of my knowledge and all local Agency/Regional Board guidelines have been followed. This report was prepared by Gettler-Ryan, Inc., upon whose assistance and advice I have relied.

This letter is submitted pursuant to the requirements of California Water Code Section 13267(b)(1) and the regulating implementation entitled Appendix A pertaining thereto.

I declare under penalty of perjury that the foregoing is true and correct.

Sincerely,



Karen Streich
Project Manager

Enclosure: Report



GETTLER-RYAN INC.

TRANSMITTAL

August 17, 2004
G-R #386498

TO: Mr. Robert Foss
Cambria Environmental Technology, Inc.
5900 Hollis Street, Suite A
Emeryville, California 94608

CC: Ms. Karen Streich
ChevronTexaco Company
P.O. Box 6012, Room K2256
San Ramon, California 94583

FROM: Deanna L. Harding
Project Coordinator
Gettler-Ryan Inc.
6747 Sierra Court, Suite J
Dublin, California 94568

RE: **Chevron #206127**
(Former Signal Oil Marine Terminal)
2301-2337 Blanding Avenue
Alameda, California

WE HAVE ENCLOSED THE FOLLOWING:

COPIES	DATED	DESCRIPTION
1	August 13, 2004	Groundwater Monitoring and Sampling Report Third Quarter - Event of July 23, 2004

COMMENTS:

This report is being sent for your review. Please provide any comments/changes and propose any groundwater monitoring modifications for the next event prior to **September 14, 2004**, at which time the final report will be distributed to the following:

cc: Mr. Barney Chan, Alameda County Health Care Services, Dept. of Environmental Health, 1131 Harbor Bay Parkway, Suite 250, Alameda, CA 94502-6577

Enclosures

trans/206127-ks

6747 Sierra Court, Suite J • Dublin, CA 94568 • (925) 551-7555 • Fax (925) 551-7888
3140 Gold Camp Drive, Suite 170 • Rancho Cordova, CA 95670 • (916) 631-1300 • Fax (916) 631-1317
1364 N. McDowell Blvd., Suite B2 • Petaluma, CA 94954 • (707) 789-3255 • Fax (707) 789-3218



GETTLER-RYAN INC.

August 13, 2004
G-R Job #386498

Ms. Karen Streich
ChevronTexaco Company
P.O. Box 6012, Room K2256
San Ramon, CA 94583

RE: Third Quarter Event of July 23, 2004
Groundwater Monitoring & Sampling Report
Chevron #206127 (Former Signal Oil Marine Terminal)
2301-2337 Blanding Avenue
Alameda, California

Dear Ms. Streich:

This report documents the most recent groundwater monitoring and sampling event performed by Gettler-Ryan Inc. (G-R) at the referenced site. All field work was conducted in accordance with G-R Standard Operating Procedure - Groundwater Sampling (attached).

Static groundwater level was measured and the well was checked for the presence of separate-phase hydrocarbons. Static water level data, groundwater elevation, and separate-phase hydrocarbon thickness (if any) are presented in the attached Table 1. A Groundwater Elevation Map is included as Figure 1.

Groundwater samples were collected from the monitoring well and submitted to a state certified laboratory for analyses. The field data sheet for this event is attached. Analytical results are presented in the table(s) listed below. The chain of custody document and laboratory analytical report are also attached.

Please call if you have any questions or comments regarding this report. Thank you.

Sincerely,

Deanna L. Harding
Project Coordinator


Hagop Kevork
P.E. No. C55734



Figure 1: Groundwater Elevation Map
Table 1: Groundwater Monitoring Data and Analytical Results
Attachments: Standard Operating Procedure - Groundwater Sampling
Field Data Sheets
Chain of Custody Document and Laboratory Analytical Reports

EXPLANATION

- ◆ Groundwater monitoring well 99.99 Groundwater elevation in feet referenced to Mean Sea Level
- ◆ Canal water level gauging station from Park Street Bridge (RRM, October 1998) NM Not Monitored
- ◇ Canal grab surface water sample
- Shallow groundwater survey point (Geomatrix, April 1995)
- ⋯ Site features noted on Sanborn Fire Insurance map, dated 1932



GROUNDWATER ELEVATION MAP
 Chevron #206127 (Former Signal Oil Marine Terminal)
 2301 - 2337 Blanding Avenue
 Alameda, California

GETTLER - RYAN INC.
 6747 Sierrita Ct., Suite J
 Dublin, CA 94568 (925) 551-7555

PROJECT NUMBER 386498
 REVIEWED BY
 DATE July 23, 2004
 REVISED DATE

Source: Figure modified from drawing provided by RRM engineering contracting firm.

Table 1
Groundwater Monitoring Data and Analytical Results
 Chevron #206127 (Former Signal Oil Marine Terminal)
 2301-2337 Blanding Avenue
 Alameda, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	GWE (msl)	TPH-D (ppb)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-1										
01/23/01 ¹	--	7.16	--	1,100 ^{2,3}	5,210 ⁴	868	<50.0	<50.0	<50.0	<250
04/09/01	10.62	8.12	2.50	1,200 ⁶	3,000 ⁵	920	<20	<20	<20	<100
07/30/01	10.62	9.15	1.47	550 ^{3,8}	2,000 ⁷	730	13	<5.0	<5.0	<25
10/08/01	10.62	7.86	2.76	2,200 ⁹	1,200	120	2.4	5.9	6.4	<2.5
01/13/02	10.62	7.02	3.60	3,300 ³	930	320	0.78	0.87	3.8	<2.5
04/08/02	10.62	9.60	1.02	1,200 ³	960	50	1.4	2.6	9.0	<2.5
07/31/02	10.62	9.27	1.35	2,800 ³	930	64	1.4	1.9	11	<5.0
10/15/02	10.62	8.00	2.62	1,000 ³	620	25	0.78	1.4	4.3	<2.5
01/14/03	10.62	7.05	3.57	960 ³	1,600	20	1.3	1.3	<1.5	<2.5
04/15/03	10.62	8.02	2.60	920 ³	870	56	1	1.4	3.1	<2.5
07/16/03 ¹⁰	10.62	10.08	0.54	1,400 ³	780	85	1	0.8	0.7	<0.5
10/18/03 ¹⁰	10.62	8.51	2.11	1,200 ³	640	42	0.8	<0.5	0.5	<0.5
01/22/04 ¹⁰	10.62	8.95	1.67	1,500 ³	440	18	<0.5	<0.5	<0.5	<0.5
04/23/04 ¹⁰	10.62	8.95	1.67	2,200 ³	410	10	<0.5	<0.5	<0.5	<0.5
07/23/04 ¹⁰	10.62	9.21	1.41	1,800 ³	400	6	<0.5	<0.5	<0.5	<0.5
CS-2										
07/30/01	--	--	--	140 ^{3,5}	<50	<0.50	<0.50	<0.50	<0.50	<2.5
10/08/01	--	--	--	53 ⁹	<50	<0.50	<0.50	<0.50	<1.5	<2.5
01/13/02	--	--	--	<50 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
04/08/02	--	--	--	77 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
07/31/02	--	--	--	<50 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
10/15/02	--	--	--	<50 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
01/14/03	--	--	--	<50 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
04/15/03	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<1.5	<2.5
07/16/03 ¹⁰	--	--	--	<50 ³	<50	<0.5	0.7	<0.5	0.6	<0.5
10/18/03 ¹⁰	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
01/22/04 ¹⁰	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
04/23/04 ¹⁰	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
07/23/04 ¹⁰	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1
Groundwater Monitoring Data and Analytical Results
 Chevron #206127 (Former Signal Oil Marine Terminal)
 2301-2337 Blanding Avenue
 Alameda, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	GWE (msl)	TPH-D (ppb)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
Trip Blank										
TB-LB										
01/23/01	--	--	--	--	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50
04/09/01	--	--	--	--	<50	<0.50	<0.50	<0.50	<0.50	<2.5
07/30/01	--	--	--	--	<50	<0.50	<0.50	<0.50	<0.50	<2.5
QA										
10/08/01	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
01/13/02	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
04/08/02	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
07/31/02	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
10/15/02	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
01/14/03	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
04/15/03	--	--	--	--	<50	<0.5	<0.5	<0.5	<1.5	<2.5
07/16/03 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
10/18/03 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
01/22/04 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
04/23/04 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
07/23/04 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1
Groundwater Monitoring Data and Analytical Results
 Chevron #206127 (Former Signal Oil Marine Terminal)
 2301-2337 Blanding Avenue
 Alameda, California

EXPLANATIONS:

TOC = Top of Casing	TPH-G = Total Petroleum Hydrocarbons as Gasoline	(ppb) = Parts per billion
(ft.) = Feet	B = Benzene	-- = Not Measured/Not Analyzed
DTW = Depth to Water	T = Toluene	CS-2 = Creek Sample
GWE = Groundwater Elevation	E = Ethylbenzene	QA = Quality Assurance/Trip Blank
(msl) = Mean sea level	X = Xylenes	
TPH-D = Total Petroleum Hydrocarbons as Diesel	MTBE = Methyl tertiary butyl ether	

* TOC elevations were surveyed on January 25, 2001, by Virgil Chavez Land Surveying. The benchmark used for the survey was a City of Alameda benchmark being a cut square at the centerline return, south corner of Oak and Blanding, (Benchmark Elevation = 8.236 feet, NGVD 29).

¹ Well development performed.

² Laboratory report indicates unidentified hydrocarbons <C16.

³ TPH-D with silica gel cleanup.

⁴ Laboratory report indicates weathered gasoline C6-C12.

⁵ Laboratory report indicates discrete peaks.

⁶ Laboratory report indicates diesel C9-C24 + unidentified hydrocarbons <C16.

⁷ Laboratory report indicates gasoline C6-C12.

⁸ Laboratory report indicates unidentified hydrocarbons C9-C24.

⁹ Analysis performed without silica gel cleanup although was requested on the Chain of Custody.

¹⁰ BTEX and MTBE by EPA Method 8260.

STANDARD OPERATING PROCEDURE - GROUNDWATER SAMPLING

Gettler-Ryan Inc. field personnel adhere to the following procedures for the collection and handling of groundwater samples prior to analysis by the analytical laboratory. Prior to sample collection, the type of analysis to be performed is determined. Loss prevention of volatile compounds is controlled and sample preservation for subsequent analysis is maintained.

Prior to sampling, the presence or absence of free-phase hydrocarbons is determined using an interface probe. Product thickness, if present, is measured to the nearest 0.01 foot and is noted in the field notes. In addition, all depth to water level measurements are collected with a static water level indicator and are also recorded in the field notes, prior to purging and sampling any wells.

After water levels are collected and prior to sampling, if purging is to occur, each well is purged a minimum of three well casing volumes of water using pre-cleaned pumps (stack, suction, Grundfos), or disposable bailers. Temperature, pH and electrical conductivity are measured a minimum of three times during the purging. Purging continues until these parameters stabilize.

Groundwater samples are collected using disposable bailers. The water samples are transferred from the bailer into appropriate containers. Pre-preserved containers, supplied by analytical laboratories, are used when possible. When pre-preserved containers are not available, the laboratory is instructed to preserve the sample as appropriate. Duplicate samples are collected for the laboratory to use in maintaining quality assurance/quality control standards. The samples are labeled to include the job number, sample identification, collection date and time, analysis, preservation (if any), and the sample collector's initials. The water samples are placed in a cooler, maintained at 4°C for transport to the laboratory. Once collected in the field, all samples are maintained under chain of custody until delivered to the laboratory.

The chain of custody document includes the job number, type of preservation, if any, analysis requested, sample identification, date and time collected, and the sample collector's name. The chain of custody is signed and dated (including time of transfer) by each person who receives or surrenders the samples, beginning with the field personnel and ending with the laboratory personnel.

A laboratory supplied trip blank accompanies each sampling set. For sampling sets greater than 20 samples, 5% trip blanks are included. The trip blank is analyzed for some or all of the same compounds as the groundwater samples.

As requested by ChevronTexaco Company, the purge water and decontamination water generated during sampling activities is transported by IWM to McKittrick Waste Management located in McKittrick, California.

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron #206127 (Former Signal Oil Marine Terminal)
2301-2337 Blanding Avenue
Alameda, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	GWE (msl)	TPH-D (ppb)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
MW-1										
01/23/01 ¹	--	7.16	--	1,100 ^{2,3}	5,210 ⁴	868	<50.0	<50.0	<50.0	<250
04/09/01	10.62	8.12	2.50	1,200 ⁶	3,000 ⁵	920	<20	<20	<20	<100
07/30/01	10.62	9.15	1.47	550 ^{3,8}	2,000 ⁷	730	13	<5.0	<5.0	<25
10/08/01	10.62	7.86	2.76	2,200 ⁹	1,200	120	2.4	5.9	6.4	<2.5
01/13/02	10.62	7.02	3.60	3,300 ³	930	320	0.78	0.87	3.8	<2.5
04/08/02	10.62	9.60	1.02	1,200 ³	960	50	1.4	2.6	9.0	<2.5
07/31/02	10.62	9.27	1.35	2,800 ³	930	64	1.4	1.9	11	<5.0
10/15/02	10.62	8.00	2.62	1,000 ³	620	25	0.78	1.4	4.3	<2.5
01/14/03	10.62	7.05	3.57	960 ³	1,600	20	1.3	1.3	<1.5	<2.5
04/15/03	10.62	8.02	2.60	920 ³	870	56	1	1.4	3.1	<2.5
07/16/03 ¹⁰	10.62	10.08	0.54	1,400 ³	780	85	1	0.8	0.7	<0.5
10/18/03 ¹⁰	10.62	8.51	2.11	1,200 ³	640	42	0.8	<0.5	0.5	<0.5
01/22/04 ¹⁰	10.62	8.95	1.67	1,500 ³	440	18	<0.5	<0.5	<0.5	<0.5
04/23/04 ¹⁰	10.62	8.95	1.67	2,200 ³	410	10	<0.5	<0.5	<0.5	<0.5
07/23/04¹⁰	10.62	9.21	1.41	1,800³	400	6	<0.5	<0.5	<0.5	<0.5
CS-2										
07/30/01	--	--	--	140 ^{3,5}	<50	<0.50	<0.50	<0.50	<0.50	<2.5
10/08/01	--	--	--	53 ⁹	<50	<0.50	<0.50	<0.50	<1.5	<2.5
01/13/02	--	--	--	<50 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
04/08/02	--	--	--	77 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
07/31/02	--	--	--	<50 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
10/15/02	--	--	--	<50 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
01/14/03	--	--	--	<50 ³	<50	<0.50	<0.50	<0.50	<1.5	<2.5
04/15/03	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<1.5	<2.5
07/16/03 ¹⁰	--	--	--	<50 ³	<50	<0.5	0.7	<0.5	0.6	<0.5
10/18/03 ¹⁰	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
01/22/04 ¹⁰	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
04/23/04 ¹⁰	--	--	--	<50 ³	<50	<0.5	<0.5	<0.5	<0.5	<0.5
07/23/04¹⁰	--	--	--	<50³	<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1
Groundwater Monitoring Data and Analytical Results
 Chevron #206127 (Former Signal Oil Marine Terminal)
 2301-2337 Blanding Avenue
 Alameda, California

WELL ID/ DATE	TOC* (ft.)	DTW (ft.)	GWE (msl)	TPH-D (ppb)	TPH-G (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MTBE (ppb)
Trip Blank										
TB-LB										
01/23/01	--	--	--	--	<50.0	<0.500	<0.500	<0.500	<0.500	<2.50
04/09/01	--	--	--	--	<50	<0.50	<0.50	<0.50	<0.50	<2.5
07/30/01	--	--	--	--	<50	<0.50	<0.50	<0.50	<0.50	<2.5
QA										
10/08/01	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
01/13/02	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
04/08/02	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
07/31/02	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
10/15/02	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
01/14/03	--	--	--	--	<50	<0.50	<0.50	<0.50	<1.5	<2.5
04/15/03	--	--	--	--	<50	<0.5	<0.5	<0.5	<1.5	<2.5
07/16/03 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
10/18/03 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
01/22/04 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
04/23/04 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5
07/23/04 ¹⁰	--	--	--	--	<50	<0.5	<0.5	<0.5	<0.5	<0.5

Table 1
Groundwater Monitoring Data and Analytical Results
 Chevron #206127 (Former Signal Oil Marine Terminal)
 2301-2337 Blanding Avenue
 Alameda, California

EXPLANATIONS:

TOC = Top of Casing	TPH-G = Total Petroleum Hydrocarbons as Gasoline	(ppb) = Parts per billion
(ft.) = Feet	B = Benzene	-- = Not Measured/Not Analyzed
DTW = Depth to Water	T = Toluene	CS-2 = Creek Sample
GWE = Groundwater Elevation	E = Ethylbenzene	QA = Quality Assurance/Trip Blank
(msl) = Mean sea level	X = Xylenes	
TPH-D = Total Petroleum Hydrocarbons as Diesel	MTBE = Methyl tertiary butyl ether	

* TOC elevations were surveyed on January 25, 2001, by Virgil Chavez Land Surveying. The benchmark used for the survey was a City of Alameda benchmark being a cut square at the centerline return, south corner of Oak and Blanding, (Benchmark Elevation = 8.236 feet, NGVD 29).

- ¹ Well development performed.
- ² Laboratory report indicates unidentified hydrocarbons <C16.
- ³ TPH-D with silica gel cleanup.
- ⁴ Laboratory report indicates weathered gasoline C6-C12.
- ⁵ Laboratory report indicates discrete peaks.
- ⁶ Laboratory report indicates diesel C9-C24 + unidentified hydrocarbons <C16.
- ⁷ Laboratory report indicates gasoline C6-C12.
- ⁸ Laboratory report indicates unidentified hydrocarbons C9-C24.
- ⁹ Analysis performed without silica gel cleanup although was requested on the Chain of Custody.
- ¹⁰ BTEX and MTBE by EPA Method 8260.

STANDARD OPERATING PROCEDURE - GROUNDWATER SAMPLING

Gettler-Ryan Inc. field personnel adhere to the following procedures for the collection and handling of groundwater samples prior to analysis by the analytical laboratory. Prior to sample collection, the type of analysis to be performed is determined. Loss prevention of volatile compounds is controlled and sample preservation for subsequent analysis is maintained.

Prior to sampling, the presence or absence of free-phase hydrocarbons is determined using an interface probe. Product thickness, if present, is measured to the nearest 0.01 foot and is noted in the field notes. In addition, all depth to water level measurements are collected with a static water level indicator and are also recorded in the field notes, prior to purging and sampling any wells.

After water levels are collected and prior to sampling, if purging is to occur, each well is purged a minimum of three well casing volumes of water using pre-cleaned pumps (stack, suction, Grundfos), or disposable bailers. Temperature, pH and electrical conductivity are measured a minimum of three times during the purging. Purging continues until these parameters stabilize.

Groundwater samples are collected using disposable bailers. The water samples are transferred from the bailer into appropriate containers. Pre-preserved containers, supplied by analytical laboratories, are used when possible. When pre-preserved containers are not available, the laboratory is instructed to preserve the sample as appropriate. Duplicate samples are collected for the laboratory to use in maintaining quality assurance/quality control standards. The samples are labeled to include the job number, sample identification, collection date and time, analysis, preservation (if any), and the sample collector's initials. The water samples are placed in a cooler, maintained at 4°C for transport to the laboratory. Once collected in the field, all samples are maintained under chain of custody until delivered to the laboratory.

The chain of custody document includes the job number, type of preservation, if any, analysis requested, sample identification, date and time collected, and the sample collector's name. The chain of custody is signed and dated (including time of transfer) by each person who receives or surrenders the samples, beginning with the field personnel and ending with the laboratory personnel.

A laboratory supplied trip blank accompanies each sampling set. For sampling sets greater than 20 samples, 5% trip blanks are included. The trip blank is analyzed for some or all of the same compounds as the groundwater samples.

As requested by ChevronTexaco Company, the purge water and decontamination water generated during sampling activities is transported by IWM to McKittrick Waste Management located in McKittrick, California.



GETTLER - RYAN INC.

WELL MONITORING/SAMPLING FIELD DATA SHEET

Client/Facility #: ChevronTexaco #206127 Job Number: 386498
 Site Address: 2301-2337 Blanding Avenue Event Date: 7-23-04 (inclusive)
 City: Alameda, CA Sampler: Sec

Well ID: MW-1 Date Monitored: 7-23-04 Well Condition: OK
 Well Diameter: 2 in.
 Total Depth: 17.15 ft.
 Depth to Water: 9.21 ft.
7.94 xVF 0.17 = 1.35 x3 case volume = Estimated Purge Volume: 4 gal.

Volume	3/4"= 0.02	1"= 0.04	2"= 0.17	3"= 0.38
Factor (VF)	4"= 0.66	5"= 1.02	6"= 1.50	12"= 5.80

Purge Equipment:
 Disposable Bailer
 Stainless Steel Bailer _____
 Stack Pump _____
 Suction Pump _____
 Grundfos _____
 Other: _____

Sampling Equipment:
 Disposable Bailer
 Pressure Bailer _____
 Discrete Bailer _____
 Other: _____

Time Started: _____ (2400 hrs)
 Time Bailed: _____ (2400 hrs)
 Depth to Product: _____ ft
 Depth to Water: _____ ft
 Hydrocarbon Thickness: 0 ft
 Visual Confirmation/Description: _____
 Skimmer / Absorbant Sock (circle one)
 Amt Removed from Skimmer: _____ gal
 Amt Removed from Well: _____ gal
 Water Removed: _____
 Product Transferred to: _____

Start Time (purge): 0605 Weather Conditions: clear
 Sample Time/Date: 0630 17-23-04 Water Color: clear Odor: yes
 Purging Flow Rate: 0.5 gpm. Sediment Description: _____
 Did well de-water? _____ If yes, Time: _____ Volume: _____ gal.

Time (2400 hr.)	Volume (gal.)	pH	Conductivity (u mhos/cm) ^{x1000}	Temperature (C/F)	D.O. (mg/L)	ORP (mV)
<u>0613</u>	<u>1</u>	<u>6.47</u>	<u>0.49</u>	<u>64.8</u>	_____	_____
<u>0617</u>	<u>2.5</u>	<u>6.58</u>	<u>0.54</u>	<u>64.1</u>	_____	_____
<u>0621</u>	<u>4</u>	<u>6.56</u>	<u>0.57</u>	<u>64.4</u>	_____	_____
_____	_____	_____	_____	_____	_____	_____

LABORATORY INFORMATION

SAMPLE ID	(#) CONTAINER	REFRIG.	PRESERV. TYPE	LABORATORY	ANALYSES
MW-1	<u>6</u> x vov vial	YES	HCL	LANCASTER	TPH-G(8015)/BTEX+MTBE(8260)
	<u>2</u> x Amber	YES	NP	LANCASTER	TPH-Dw/sq

COMMENTS: _____

Add/Replaced Lock: _____

Add/Replaced Plug: _____ Size: _____



GETTLER - RYAN INC.

WELL MONITORING/SAMPLING FIELD DATA SHEET

Client/Facility #: ChevronTexaco #206127
 Site Address: 2301-2337 Blanding Avenue
 City: Alameda, CA

Job Number: 386498
 Event Date: 7-23-04 (inclusive)
 Sampler: SOC

Well ID: CS-2 Date Monitored: Well Condition: Creek Sample
 Well Diameter: in.
 Total Depth: ft.
 Depth to Water: ft.
 xVF = x3 case volume = Estimated Purge Volume: gal.

Volume	3/4" = 0.02	1" = 0.04	2" = 0.17	3" = 0.38
Factor (VF)	4" = 0.66	5" = 1.02	6" = 1.50	12" = 5.80

Purge Equipment:
 Disposable Bailer _____
 Stainless Steel Bailer _____
 Stack Pump _____
 Suction Pump _____
 Grundfos _____
 Other: _____

Sampling Equipment:
 Disposable Bailer
 Pressure Bailer _____
 Discrete Bailer _____
 Other: _____

Time Started: _____ (2400 hrs)
 Time Bailed: _____ (2400 hrs)
 Depth to Product: _____ ft
 Depth to Water: _____ ft
 Hydrocarbon Thickness: 0 ft
 Visual Confirmation/Description: _____
 Skimmer / Absorbant Sock (circle one)
 Amt Removed from Skimmer: _____ gal
 Amt Removed from Well: _____ gal
 Water Removed: _____
 Product Transferred to: _____

Start Time (purge): _____ Weather Conditions: Clear
 Sample Time/Date: 064217-23-04 Water Color: clear Odor: none
 Purging Flow Rate: _____ gpm. Sediment Description: _____
 Did well de-water? _____ If yes, Time: _____ Volume: _____ gal.

Time (2400 hr.)	Volume (gal.)	pH	Conductivity (u mhos/cm)	Temperature (C/F)	D.O. (mg/L)	ORP (mV)

LABORATORY INFORMATION

SAMPLE ID	(#) CONTAINER	REFRIG.	PRESERV. TYPE	LABORATORY	ANALYSES
CS-2	6 x voa vial	YES	HCL	LANCASTER	TPH-G(8015)/BTEX+MTBE(8260)
	2 x Amber	YES	NP	LANCASTER	TPH-Dw/sg

COMMENTS: _____

Add/Replaced Lock: _____ Add/Replaced Plug: _____ Size: _____

Chevron California Region Analysis Request/Chain of Custody



For Lancaster Laboratories use only
 Acct. #: 10904 Sample #: 4317408-10 SCR#: 905149

072604-09

Facility #: SS#206127 G-R#386498 Global ID#
 Site Address: 2301-2337 BLANDING AVENUE, ALAMEDA, CA
 Chevron P#: KS Lead Consultant: GAMBRIAKW
 Consultant/Office: G-R, Inc., 6747 Sierra Court, Suite J, Dublin, Ca. 94568
 Consultant Prj. Mgr.: Deanna L. Harding (deanna@grinc.com)
 Consultant Phone: 925-551-7555 Fax: #25-551-7899
 Sampler: JOE AJEMIAN
 Service Order #: _____ Non SAR:

Sample Identification	Date Collected	Time Collected	Grab	Composite	Matrix			Total Number of Containers	Analyses Requested							Comments / Remarks			
					Soil	Water	Air		H	H									
QA	-	-	✓		✓			2	<input checked="" type="checkbox"/> BTEX + MTBE 8260	<input checked="" type="checkbox"/> 8021									
MW-1	7-23-04	0630	✓		✓			8	<input checked="" type="checkbox"/> TPH 8015 MOD GRO	<input checked="" type="checkbox"/> TPH 8015 MOD DRO	<input checked="" type="checkbox"/> Silica Gel Cleanup								
CS-2	"	0642	✓		✓			8	<input checked="" type="checkbox"/> 8260 full scan										

Preservative Codes
 H = HCl T = Thiosulfate
 N = HNO₃ B = NaOH
 S = H₂SO₄ O = Other

J value reporting needed
 Must meet lowest detection limits possible for 8260 compounds

8021 MTBE Confirmation
 Confirm highest hit by 8260
 Confirm all hits by 8260
 Run ___ oxy s on highest hit
 Run ___ oxy s on all hits

Turnaround Time Requested (TAT) (please circle)
 STD. TAT 72 hour 48 hour
 24 hour 4 day 5 day

Data Package Options (please circle if required)
 QC Summary Type I — Full
 Type VI (Raw Data) Coelt Deliverable not needed
 WIP (RWQCB)
 Disk

Relinquished by: <u>[Signature]</u>	Date: <u>7-23-04</u>	Time: <u>1100</u>	Received by: _____	Date: _____	Time: _____
Relinquished by: <u>Diano</u>	Date: <u>7/26/04</u>	Time: <u>1340</u>	Received by: <u>Andres Amaya</u>	Date: <u>7/26/04</u>	Time: <u>1340</u>
Relinquished by: <u>Andres Amaya</u>	Date: <u>7/26/04</u>	Time: <u>1500</u>	Received by: <u>DHL</u>	Date: <u>7/26/04</u>	Time: _____
Relinquished by Commercial Carrier: UPS FedEx <u>Other</u>	Temperature Upon Receipt: <u>15.4°C</u>		Received by: <u>[Signature]</u>	Date: <u>7/26/04</u>	Time: <u>1035</u>
Custody Seals Intact?			<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	

ANALYTICAL RESULTS

Prepared for:

ChevronTexaco
6001 Bollinger Canyon Rd L4310
San Ramon CA 94583

925-842-8582

Prepared by:

Lancaster Laboratories
2425 New Holland Pike
Lancaster, PA 17605-2425**SAMPLE GROUP**

The sample group for this submittal is 905149. Samples arrived at the laboratory on Tuesday, July 27, 2004. The PO# for this group is 99011184 and the release number is STREICH.

<u>Client Description</u>		<u>Lancaster Labs Number</u>
QA-T-040723	NA Water	4317408
MW-1-W-040723	Grab Water	4317409
CS-2-W-040723	Grab Water	4317410

1 COPY TO Cambria C/O Gettler- Ryan
ELECTRONIC Gettler-Ryan
COPY TO

Attn: Deanna L. Harding
Attn: Cheryl Hansen



Analysis Report

2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Questions? Contact your Client Services Representative
Megan A Moeller at (717) 656-2300.

Respectfully Submitted,

A handwritten signature in cursive script that reads "Dana M. Kauffman".

Dana M. Kauffman
Group Leader



Analysis Report

2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

Lancaster Laboratories Sample No. WW 4317408

QA-T-040723 NA Water
 Facility# 206127 Job# 386498 GRD
 2301-2337 Blanding Alamed NA QA
 Collected: 07/23/2004

Account Number: 10904

Submitted: 07/27/2004 08:35
 Reported: 08/03/2004 at 14:17
 Discard: 09/03/2004

ChevronTexaco
 6001 Bollinger Canyon Rd L4310
 San Ramon CA 94583

ALMTB

CAT No.	Analysis Name	CAS Number	As Received Result	As Received		Units	Dilution Factor
				Method	Detection Limit		
01728	TPH-GRO - Waters	n.a.	N.D.		50.	ug/l	1
	The reported concentration of TPH-GRO does not include MTBE or other gasoline constituents eluting prior to the C6 (n-hexane) TPH-GRO range start time.						
06054	BTEX+MTBE by 8260B						
02010	Methyl Tertiary Butyl Ether	1634-04-4	N.D.		0.5	ug/l	1
05401	Benzene	71-43-2	N.D.		0.5	ug/l	1
05407	Toluene	108-88-3	N.D.		0.5	ug/l	1
05415	Ethylbenzene	100-41-4	N.D.		0.5	ug/l	1
06310	Xylene (Total)	1330-20-7	N.D.		0.5	ug/l	1

State of California Lab Certification No. 2116

Laboratory Chronicle

CAT No.	Analysis Name	Method	Trial#	Analysis		Analyst	Dilution Factor
				Date and Time			
01728	TPH-GRO - Waters	N. CA LUFT Gasoline Method	1	07/27/2004 15:35		K. Robert Caulfeild-James	1
06054	BTEX+MTBE by 8260B	SW-846 8260B	1	07/29/2004 21:34		Joshua P Schaeffer	1
01146	GC VOA Water Prep	SW-846 5030B	1	07/27/2004 15:35		K. Robert Caulfeild-James	n.a.
01163	GC/MS VOA Water Prep	SW-846 5030B	1	07/29/2004 21:34		Joshua P Schaeffer	n.a.

Lancaster Laboratories Sample No. WW 4317409

 MW-1-W-040723 Grab Water
 Facility# 206127 Job# 386498 GRD
 2301-2337 Blanding Alamed NA MW-1
 Collected: 07/23/2004 06:30 by JA

Account Number: 10904

 Submitted: 07/27/2004 08:35
 Reported: 08/03/2004 at 14:17
 Discard: 09/03/2004

 ChevronTexaco
 6001 Bollinger Canyon Rd L4310
 San Ramon CA 94583

ALMD1

CAT No.	Analysis Name	CAS Number	As Received Result	As Received		Units	Dilution Factor
				Method	Detection Limit		
01728	TPH-GRO - Waters	n.a.	400.		50.	ug/l	1
	The reported concentration of TPH-GRO does not include MTBE or other gasoline constituents eluting prior to the C6 (n-hexane) TPH-GRO range start time.						
02202	TPH-DRO CALUFT(Water) w/Si Gel	n.a.	1,800.		50.	ug/l	2
06054	BTEX+MTBE by 8260B						
02010	Methyl Tertiary Butyl Ether	1634-04-4	N.D.		0.5	ug/l	1
05401	Benzene	71-43-2	6.		0.5	ug/l	1
05407	Toluene	108-88-3	N.D.		0.5	ug/l	1
05415	Ethylbenzene	100-41-4	N.D.		0.5	ug/l	1
06310	Xylene (Total)	1330-20-7	N.D.		0.5	ug/l	1

State of California Lab Certification No. 2116

Laboratory Chronicle

CAT No.	Analysis Name	Method	Trial#	Analysis		Analyst	Dilution Factor
				Date	Time		
01728	TPH-GRO - Waters	N. CA LUFT Gasoline	1	07/29/2004	13:19	Linda C Pape	1
02202	TPH-DRO CALUFT(Water) w/Si Gel	CALUFT-DRO/8015B, Modified	1	07/30/2004	19:39	Tracy A Cole	2
06054	BTEX+MTBE by 8260B	SW-846 8260B	1	07/29/2004	20:13	Joshua P Schaeffer	1
01146	GC VOA Water Prep	SW-846 5030B	1	07/29/2004	13:19	Linda C Pape	n.a.
01163	GC/MS VOA Water Prep	SW-846 5030B	1	07/29/2004	20:13	Joshua P Schaeffer	n.a.
02135	Extraction - DRO Water Special	TPH by CA LUFT	1	07/28/2004	03:20	Deborah A Stasiak-Birkenbine	1

Lancaster Laboratories Sample No. **WW 4317410**
CS-2-W-040723 **Grab** **Water**
Facility# 206127 **Job# 386498** **GRD**
2301-2337 Blanding Alamed NA **CS-2**
 Collected: 07/23/2004 06:42 by JA

Account Number: 10904

 Submitted: 07/27/2004 08:35
 Reported: 08/03/2004 at 14:17
 Discard: 09/03/2004

 ChevronTexaco
 6001 Bollinger Canyon Rd L4310
 San Ramon CA 94583

ALMC2

CAT No.	Analysis Name	CAS Number	As Received Result	As Received		Units	Dilution Factor
				Method	Detection Limit		
01728	TPH-GRO - Waters	n.a.	N.D.		50.	ug/l	1
	The reported concentration of TPH-GRO does not include MTBE or other gasoline constituents eluting prior to the C6 (n-hexane) TPH-GRO range start time.						
02202	TPH-DRO CALUFT(Water) w/Si Gel	n.a.	N.D.		50.	ug/l	1
06054	BTEX+MTBE by 8260B						
02010	Methyl Tertiary Butyl Ether	1634-04-4	N.D.		0.5	ug/l	1
05401	Benzene	71-43-2	N.D.		0.5	ug/l	1
05407	Toluene	108-88-3	N.D.		0.5	ug/l	1
05415	Ethylbenzene	100-41-4	N.D.		0.5	ug/l	1
06310	Xylene (Total)	1330-20-7	N.D.		0.5	ug/l	1

State of California Lab Certification No. 2116

Laboratory Chronicle

CAT No.	Analysis Name	Method	Analysis		Analyst	Dilution Factor
			Trial#	Date and Time		
01728	TPH-GRO - Waters	N. CA LUFT Gasoline	1	07/29/2004 13:52	Linda C Pape	1
02202	TPH-DRO CALUFT(Water) w/Si Gel	CALUFT-DRO/8015B, Modified	1	07/29/2004 16:32	Tracy A Cole	1
06054	BTEX+MTBE by 8260B	SW-846 8260B	1	07/29/2004 20:40	Joshua P Schaeffer	1
01146	GC VOA Water Prep	SW-846 5030B	1	07/29/2004 13:52	Linda C Pape	n.a.
01163	GC/MS VOA Water Prep	SW-846 5030B	1	07/29/2004 20:40	Joshua P Schaeffer	n.a.
02135	Extraction - DRO Water Special	TPH by CA LUFT	1	07/29/2004 03:20	Deborah A Stasiak-Birkenbine	1

Quality Control Summary

Client Name: ChevronTexaco
Reported: 08/03/04 at 02:17 PM

Group Number: 905149

Matrix QC may not be reported if site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

Laboratory Compliance Quality Control

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCSD %REC</u>	<u>LCS/LCSD Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Batch number: 042090004A TPH-DRO CALUFT(Water) w/Si Gel	65.	50.	Sample number(s): 4317409-4317410 ug/l	83	91	61-126	10	20
Batch number: 04209A16A TPH-GRO - Waters	N.D.	50.	Sample number(s): 4317408 ug/l	97	96	70-130	1	30
Batch number: 04211B51A TPH-GRO - Waters	N.D.	50.	Sample number(s): 4317409-4317410 ug/l	101	104	70-130	2	30
Batch number: N042111BB Methyl Tertiary Butyl Ether	N.D.	0.5	Sample number(s): 4317408-4317410 ug/l	112	114	77-127	2	30
Benzene	N.D.	0.5	ug/l	107	109	85-117	2	30
Toluene	N.D.	0.5	ug/l	103	107	85-115	4	30
Ethylbenzene	N.D.	0.5	ug/l	99	103	82-119	4	30
Xylene (Total)	N.D.	0.5	ug/l	101	104	84-120	3	30

Sample Matrix Quality Control

<u>Analysis Name</u>	<u>MS %REC</u>	<u>MSD %REC</u>	<u>MS/MSD Limits</u>	<u>RPD</u>	<u>RPD MAX</u>	<u>BKG Conc</u>	<u>DUP Conc</u>	<u>DUP RPD</u>	<u>Dup RPD Max</u>
Batch number: 04209A16A TPH-GRO - Waters	109		Sample number(s): 4317408 63-154						
Batch number: 04211B51A TPH-GRO - Waters	109	115	Sample number(s): 4317409-4317410 63-154	5	30				
Batch number: N042111BB Methyl Tertiary Butyl Ether	113		Sample number(s): 4317408-4317410 69-134						
Benzene	116		83-128						
Toluene	113		83-127						
Ethylbenzene	109		82-129						
Xylene (Total)	110		82-130						

Surrogate Quality Control

Analysis Name: TPH-DRO CALUFT(Water) w/Si Gel
Batch number: 042090004A
Orthoterphenyl

*- Outside of specification

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.

Quality Control Summary

Client Name: ChevronTexaco
Reported: 08/03/04 at 02:17 PM

Group Number: 905149

Surrogate Quality Control

4317409	94
4317410	90
Blank	74
LCS	114
LCSD	125

Limits: 57-128

Analysis Name: TPH-GRO - Waters
Batch number: 04209A16A
Trifluorotoluene-F

4317408	108
Blank	106
LCS	112
LCSD	111
MS	111

Limits: 57-146

Analysis Name: TPH-GRO - Waters
Batch number: 04211B51A
Trifluorotoluene-F

4317409	122
4317410	104
Blank	104
LCS	115
LCSD	111
MS	108
MSD	112

Limits: 57-146

Analysis Name: BTEX+MTBE by 8260B
Batch number: N042111BB

	Dibromofluoromethane	1,2-Dichloroethane-d4	Toluene-d8	4-Bromofluorobenzene
4317408	114	105	109	96
4317409	110	103	108	106
4317410	112	108	108	98
Blank	110	107	109	98
LCS	109	105	109	109
LCSD	107	108	109	107
MS	107	105	110	108

Limits: 81-120 82-112 85-112 83-113

*- Outside of specification

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.

Explanation of Symbols and Abbreviations

The following defines common symbols and abbreviations used in reporting technical data:

N.D.	none detected	BMQL	Below Minimum Quantitation Level
TNTC	Too Numerous To Count	MPN	Most Probable Number
IU	International Units	CP Units	cobalt-chloroplatinate units
umhos/cm	micromhos/cm	NTU	nephelometric turbidity units
C	degrees Celsius	F	degrees Fahrenheit
meq	milliequivalents	lb.	pound(s)
g	gram(s)	kg	kilogram(s)
ug	microgram(s)	mg	milligram(s)
ml	milliliter(s)	l	liter(s)
m3	cubic meter(s)	ul	microliter(s)
<	less than - The number following the sign is the <u>limit of quantitation</u> , the smallest amount of analyte which can be reliably determined using this specific test.		
>	greater than		
J	estimated value – The result is \geq the Method Detection Limit (MDL) and $<$ the Limit of Quantitation (LOQ).		
ppm	parts per million - One ppm is equivalent to one milligram per kilogram (mg/kg), or one gram per million grams. For aqueous liquids, ppm is usually taken to be equivalent to milligrams per liter (mg/l), because one liter of water has a weight very close to a kilogram. For gases or vapors, one ppm is equivalent to one microliter of gas per liter of gas.		
ppb	parts per billion		
Dry weight basis	Results printed under this heading have been adjusted for moisture content. This increases the analyte weight concentration to approximate the value present in a similar sample without moisture. All other results are reported on an as-received basis.		

U.S. EPA CLP Data Qualifiers:

Organic Qualifiers

A	TIC is a possible aldol-condensation product
B	Analyte was also detected in the blank
C	Pesticide result confirmed by GC/MS
D	Compound quantitated on a diluted sample
E	Concentration exceeds the calibration range of the instrument
N	Presumptive evidence of a compound (TICs only)
P	Concentration difference between primary and confirmation columns $>25\%$
U	Compound was not detected
X,Y,Z	Defined in case narrative

Inorganic Qualifiers

B	Value is $<$ CRDL, but \geq IDL
E	Estimated due to interference
M	Duplicate injection precision not met
N	Spike sample not within control limits
S	Method of standard additions (MSA) used for calculation
U	Compound was not detected
W	Post digestion spike out of control limits
*	Duplicate analysis not within control limits
+	Correlation coefficient for MSA <0.995

Analytical test results for methods listed on the laboratories' accreditation scope meet all requirements of NELAC unless otherwise noted under the individual analysis.

Measurement uncertainty values, as applicable, are available upon request.

Tests results relate only to the sample tested. Clients should be aware that a critical step in a chemical or microbiological analysis is the collection of the sample. Unless the sample analyzed is truly representative of the bulk of material involved, the test results will be meaningless. If you have questions regarding the proper techniques of collecting samples, please contact us. We cannot be held responsible for sample integrity, however, unless sampling has been performed by a member of our staff. This report shall not be reproduced except in full, without the written approval of the laboratory.

WARRANTY AND LIMITS OF LIABILITY - In accepting analytical work, we warrant the accuracy of test results for the sample as submitted. THE FOREGOING EXPRESS WARRANTY IS EXCLUSIVE AND IS GIVEN IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED. WE DISCLAIM ANY OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING A WARRANTY OF FITNESS FOR PARTICULAR PURPOSE AND WARRANTY OF MERCHANTABILITY. IN NO EVENT SHALL LANCASTER LABORATORIES BE LIABLE FOR INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES INCLUDING, BUT NOT LIMITED TO, DAMAGES FOR LOSS OF PROFIT OR GOODWILL REGARDLESS OF (A) THE NEGLIGENCE (EITHER SOLE OR CONCURRENT) OF LANCASTER LABORATORIES AND (B) WHETHER LANCASTER LABORATORIES HAS BEEN INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. We accept no legal responsibility for the purposes for which the client uses the test results. No purchase order or other order for work shall be accepted by Lancaster Laboratories which includes any conditions that vary from the Standard Terms and Conditions of Lancaster Laboratories and we hereby object to any conflicting terms contained in any acceptance or order submitted by client.