

Broadbent & Associates, Inc.
1324 Mangrove Ave., Suite 212
Chico, CA 95926
Voice (530) 566-1400
Fax (530) 566-1401

RECEIVED

By dehloptoxic at 9:09 am, Nov 01, 2006



18 October 2006

Project No. 06-08-614

Atlantic Richfield Company
P.O. Box 1257
San Ramon, California 94583
Submitted via ENFOS

Attn.: Mr. Paul Supple

Re: Third Quarter 2006 Status Report, Atlantic Richfield Company (a BP affiliated company)
Station #2107, 3310 Park Boulevard, Oakland, Alameda County, California
ACEH Case #RO0002526.

Dear Mr. Supple:

Provided herein is the *Third Quarter 2006 Status Report* for Atlantic Richfield Company Station #2107 located at 3310 Park Boulevard, Oakland, Alameda County, California. This report presents a summary of recent developments at the site up to Third Quarter 2006.


Should you have questions regarding this submission, please do not hesitate to contact us at (530) 566-1400.

Sincerely,

BROADBENT & ASSOCIATES, INC.

Thomas A. Venus, P.E.
Senior Engineer

Robert H. Miller, P.G., C.HG.
Principal Hydrogeologist



Enclosure

cc: Mr. Stephen Plunkett, Alameda County Environmental Health (Submitted via ACEH ftp site)
Electronic copy uploaded to GeoTracker

STATION #2107 QUARTERLY GROUND-WATER STATUS REPORT

Facility: #2107	Address:	3310 Park Boulevard, Oakland, California
Environmental Business Manager:		Mr. Paul Supple
Consulting Company/Contact Person:		Broadbent & Associates, Inc.(BAI)/Rob Miller & Tom Venus (530) 566-1400
Consultant Project No.:		06-08-614
Primary Agency/Regulatory ID No.:		Alameda County Environmental Health (ACEH) ACEH Case # RO0002526

WORK PERFORMED THIS QUARTER (Third Quarter 2006):

1. No environmental work was conducted at the site during the Second Quarter 2006.
2. Prepared and submitted this Third Quarter 2006 Status Report.

WORK PROPOSED FOR NEXT QUARTER (Fourth Quarter 2006):

1. No environmental work is authorized to be conducted at the site during the Fourth Quarter 2006 yet.
2. Prepare and submit the Fourth Quarter 2006 Status Report.

DISCUSSION:

No environmental work has been performed for this site since early 2005. BP is still awaiting comments or approval to the Work Plan Addendum for Offsite Investigation, submitted by URS on 5 April 2005. A Site Map is provided as Drawing 1.

ATTACHMENTS:

Drawing 1. Site Map, Station #2107, 3310 Park Boulevard, Oakland, California

OAKLAND HIGH SCHOOL

CONC. SIDEWALK

SB-12/HP-9
SB-13/HP-10
SB-14/HP-11
SB-15/HP-12

PARK BLVD.

E. 34th ST.

MW-7

SB-4

CONC. SIDEWALK

SB-5

SB-6

SB-11 RW-1

PARKING STALLS

MW-3

HP-5

SB-8

SB-7

HP-4

SB-10/HP-7

SB-9

HP-6

MW-5

SB-3

HP-3

MW-6

LEGEND:

- DESTROYED MONITORING WELL
- ⊙ HYDRO PUNCH LOCATION
- ⊕ PROPOSED HYDRO PUNCH LOCATION AND SOIL BORING LOCATION
- SOIL BORING LOCATION

STATION BUILDING

UST3
UST2
UST1
EXISTING FUEL TANK COMPLEX

CANOPY COLUMN


CANOPY

SB-1

MW-4

B-10

RUSH DISC



BROADBENT & ASSOCIATES, INC.
 ENGINEERING, WATER RESOURCES & ENVIRONMENTAL
 1324 Mangrove Ave. Suite 212, Chico, California
 Project No.: 06-08-614 Date: 10/03/06

Station #2107
 3310 Park Boulevard
 Oakland, California

Site Map

Drawing

1