

#6093 May 20, 1997

On site to witness confirmation sampling after OE of area behind car wash/car maintenance which had up contamination. Depth of excavation extended to 3'2"



- #1 @ 3'2" Bottom IB
 - #2 @ 2'8" Side IS
 - #3 @ 2'8" Side IW
 - #4 @ 2'8" Side IN
 - #5 @ 2'8" Side IE
- Z
(project)

Carport



Contaminated soil
behind carport/car wash
area. 5/20/97



5/20/97
Contaminated soil (OE)
excavated from pile.

#6093 06/02/97

On site to witness second round of sampling. Bottom & north sidewall samples came out "hot" w/ TOC (1,800 ppm + 1,500 ppm, resp.) from samples collected on 5/20/97. Pit was OE down to 5' + today a 5' bottom sample + 4.5' north side wall sample was collected.



Bottom sample
Collected @ ~5' bgs after
add'l OE.

6/2/97



North Sidewall sample 6/2/97
Collected @ ~4.5' bgs after OE.