

September ²²/~~17~~, 1992

**MEETING AGENDA
DEL MONTE PLANT 35
EMERYVILLE, CALIFORNIA**

1. Plant 35 Overview
2. West Parcel
 - a. Former fuel oil tank area (chlorinated hydrocarbon source)
 - Hollis Street investigation results (July 1992)
 - Soil excavation
 - Groundwater extraction/treatment from excavation
 - Onsite reinfiltration or sanitary sewer
 - Excavation backfill
 - Groundwater monitoring
 - b. West Parcel monitoring wells
3. East Parcel
 - a. Haven Street soil excavation
 - b. Closed-in-place tank
 - Soil investigation results (July 1992)
 - Excavation of tank and surrounding soil
 - Groundwater monitoring
 - c. East Parcel monitoring wells
4. Criteria for leaving soil onsite
 - a. soil with petroleum hydrocarbons (ie. BTEX, TPH-gas, TPH-diesel, TPH-fuel oil)
 - b. soil with chlorinated hydrocarbons




FIGURE 1
 DEL MONTE PLANT 35
 EMERYVILLE, CALIFORNIA

meeting at RWQCB, Oakland on Del Monte, Emeryville.

Name	Organization	phone number
Sum Arigala	RWQCB #2	510 286 0434
Brian P. O'Quinn	ALCO HAZ MAT	510 567-6737
Thomas Bender	BENDER PARTNERSHIP	415 401-4358
Madeline Wall	CH2M HILL	(510) 251-2888 x2
Mark Zemelman	KAUER	(510) 271-6803
David Hamish	ENVIRON	(510) 655-7400
Ravi Arulamantham	RWQCB-II	286-1331
Susan L. Hugo	ACDEH	(510) 567-6780
Steven Ronzone	Del Monte	(415) 247 247-3526