



LRA ENVIRONMENTAL

3235 SUNRISE BOULEVARD, SUITE E
RANCHO CORDOVA, CA 95742
PHONE 916/631-4455

FAX 916/631-4466

ATTN: JULIET SKIN

DATE: 4-7-92

TO: ALAMOGUE COUNTY HEALTH DEPT

RE: CHLORINE VAPOR DIAGNOSIS

OUR JOB NAME: Tree Hill - Arroyo

OUR JOB NO: 6-9170

NO OF PAGES (INCLUDING THIS PAGE): 3

*These diagrams show, basically, how we construct
our monitor wells. There can change due to
government recommendation or specification. If there
is anything that isn't explained or brings a
question to mind, give me a call.*


Mike

If you did not receive all transmittal pages, please contact:

Mike Melas

Circle
11/16/91 11:11


Circle
11/16/91 11:11



Single-Cased Monitoring Well - Non-Traffic Area

NAME	
CITY, STATE	
SINGLE-CASED MONITORING WELL	
LRA ENVIRONMENTAL	
<small>1000 TUCKER ROAD, SUITE 2 - CHICAGO, IL 60618</small>	

DATE 9-JULY-00
 DRW. NO. E-0002-1



Single-Cased Monitoring Well - Paved Area

NAME	
CITY, STATE	
SINGLE-CASED MONITORING WELL	
LRA ENVIRONMENTAL	
<small>1000 VENTURA ROAD, SUITE 200 - SAN ANTONIO, TX 78216</small>	
DATE	5-JULY-99
DRWG. NO.	E-0992-1

DATE 4/7/92

CONTACT LOG

FROM: Juliet Shin AFFILIATION: _____
TITLE: _____ PHONE: _____
TO: Mike Mitas AFFILIATION: LRA Engineering
TITLE: Staff Geologist PHONE: (916) 926-9267
RE: STID 3695-

Reviewed proposed monitoring well locations and
Ms. Shin feels that a monitoring well should be
installed west of the "suspected area of
contamination." Mr. Mitas stated that it may
be difficult to install a well there since
it is the property of Caltrans (the street) or
the City or County (the sidewalk). Ms. Shin said
she would get back to Mr. Mitas on the processes
to install a well on Caltrans property.

Additionally, Ms. Shin requested a copy of
well profiles for proposed wells.

4/7/92

Called Mr. Mitas back & gave info as to how
to install well on Caltrans property.

