

PERMIT WATER vironmental onsultants Course Course

1285 Edmundson Ave Morgan Hill, Ca 95037

01-1307

(408) 241-1828

1-26-87 JF32-B:SWFrey.RWJ

R.W. Johnston and Sons 801 53rd Avenue OAKLAND, CA 94601

ATTENTION: Dick Burg

SUBJECT: Field sampling and analysis at Schwabacher/Frey, 5733 Paladeau Street, Emeryville, California

1 Alameda

Dear Dick Burg:

Enclosed are the results for the analysis of soil samples taken from excavation holes at the subject facility. This site presented one 2000 gallon diesel tank 6.5' in diameter which rested 8.5' below grade. George Warren of the city of Emeryville was present to observe and direct the sampling. The attached plot plan shows the approximate location of the tank in respect to the facility.

The tank appeared to have two corrosion holes on its side 2 and 8" long at half height. The soil under the tank appeared to be contaminated with product. Samples were taken at 11 feet depth.

Sampling was performed in accordance with approved methodology. The samples were obtained in zero headspace brass tubes which were sealed, logged, chilled and transported to the laboratory for same day analysis.

The samples were analysed in accordance with approved methodology. The results are presented on page three of this report.

Reportage

Submission to the Regional Water Quality Control Board and the City of Emeryville should include copies of this report. The property owner should attach a cover letter and submit all documents together in a package.

listed for your addresses have been following The convenience:

Water Quality Control Board San Francisco Bay Region 1111 Jackson Street Room 6040 Oakland, CA 94507 Attention: Tom Calahan

City of Emeryville 6303 Hollis Street Emeryville, CA 94608 Attention: George Warren

If you have any questions or if we can be of further assistance, please feel free to contact us at your convenience.

Sincerely,

Mark Chips (For N. Kumagai)



SAMPLE HANDLING/LOG-IN

Date .	1/26/87			Test Location Schwabacher Frey 5733 Pciadeau,		
	Sample Type		Volume	Comments		
1	000764	<u> </u>			Nend	11 depth
2	000736	6C_	2		N and S end	11' depth
4. <u>'</u>			···			
5		<u> </u>				-
6						
7.			***********			
9						
10		-	·	 -		
11. <u> </u>				-		
12.				<u> </u>		
		CI	HAIN OF	CUSTODY		
hanny	y Kun	yz.	70.	45 fr	16 /20	187
ning	J. Kun	uza.		_he	(4 // 2 · · · / 2 · · · / 2 · · · · · · ·	187
· /	V				-	/

