## Plunkett, Steven, Env. Health


From:	Sami Malaeb [SMalaeb@jonasinc.com]
Sent:	Thursday, June 26, 2008 1:51 PM
To:	Plunkett, Steven, Env. Health
Cc:	Danielle.Bogni@gsa.gov
Subject:	Alameda Federal Center- 620 Central Avenue, Alameda, California SLIC Case Number 2903
Attachments:	PHASE_I_ALAMEDA.pdf; PHASE_I_PLATES_ALAMEDA.pdf

Hi Steven:

Thanks for your speedy review of the subject SLIC case number 2903 at the Alameda Federal Center, Alameda, California. As you requested, attached please find the electronic copy of the Phase I Environmental Assessment for the site. Please note due to the large size of the report, I will attach the body of the report to this email and the attachments in separate emails.


Your efforts are appreciated!


Sami Malaeb, PE, REA Program Manager Jonas and Associates Inc. 1350 Arnold Drive, Suite 202 Martinez, CA 94553 Tel (Office): (925) 374-0020 Tel (Cellular): (925) 858-9608 Fax: (925) 374-0021 smalaeb@jonasinc.com





caD FILE: Ple-L:\2002\02PROJ\22805\Graphics\001\AERIAL.dwg


©2002, by Kleinfelder, Inc.



















PROJECT NO. 22805/001


DATE: November 8, 2002

BUILDINGS 8, 9, AND 10

8










Photo 5: A typical laboratory spill prevention kit at the USDA laboratory.




Photo 6: View of "flammable" materials storage cabinet at the subject property shop.



SITE PHOTOGRAPHS Alameda Service Center 620 Central Avenue Alameda, CA

PROJECT NO. 22805-001

DATE: November 8, 2002

12

PLATE





Photo 7: View of the former location of Tanks 3 and 4 prior to their removal from the site. The LUST case received closure this year.



## KLEINFELDER

PROJECT NO. 22805-001

DATE: November 8, 2002

SITE PHOTOGRAPHS Alameda Service Center 620 Central Avenue Alameda, CA

13

