



**CONESTOGA-ROVERS  
& ASSOCIATES**

**RECEIVED**

1:34 pm, Jul 11, 2007

Alameda County  
Environmental Health

5900 Hollis Street, Suite A, Emeryville, California 94608  
Telephone: 510-420-0700 Facsimile: 510-420-9170  
www.CRAworld.com

July 6, 2007

Mr. John Rigter  
Livermore-Pleasanton Fire Department  
3560 Nevada St.  
Pleasanton, California 94566

Re: **UST Unauthorized Release Report**  
Former Standard Oil Service Station #30-7233  
2259 First St.  
Livermore, California

Dear Mr. Rigter,

On behalf of Chevron Environmental Management Company (Chevron), Conestoga-Rovers & Associates (CRA) is submitting this underground storage tank (UST) unauthorized release (leak)/contamination site report resulting from the removal of two orphan USTs located beneath Mills Square Park in Livermore, California.

An additional UST unauthorized release (leak)/contamination site report was submitted by the City of Livermore on September 21, 2005. The city located and removed an orphan UST from beneath the sidewalk adjacent to Mills Square Park and we believe that the two cases are connected to the former Standard Oil station located at 2259 First Street, Livermore, CA, now Mills Square Park.

Thank you for your assistance with this project. Please call Charlotte Evans at (510) 420-3351 if you have any questions or comments.

Sincerely,  
**Conestoga-Rovers & Associates**

Charlotte Evans

Attachments: A – Underground Storage Tank Unauthorized Release (Leak)/Contamination Site Report

cc: Mr. Satya Sinha, Chevron EMC, P.O. Box 6012, San Ramon, CA 94583  
Mr. Jerry Wickham, ACEHS, 1131 Harbor Bay Parkway, Suite 250, Alameda,  
CA 94502

I:\Chevron\307233 Livermore\2007 Tank Pull\30-7233 URF Letter.doc

Equal  
Employment  
Opportunity Employer



**CONESTOGA-ROVERS  
& ASSOCIATES**

[www.CRAworld.com](http://www.CRAworld.com)

## **ATTACHMENT A**

### **Underground Storage Tank Unauthorized Release (Leak)/Contamination Site Report**

REGISTERED COMPANY  
**ISO 9001**  
ENGINEERING DESIGN

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT			
EMERGENCY <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
REPORT DATE 6/27/2007		CASE #	
FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.			
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT IAN HULL		PHONE 510-420-3344
	SIGNATURE <i>Ian Hull</i>		
	REPRESENTING <input type="checkbox"/> LOCAL AGENCY <input type="checkbox"/> REGIONAL BOARD <input checked="" type="checkbox"/> OWNER/OPERATOR <input type="checkbox"/> OTHER...		COMPANY OR AGENCY NAME CONESTOGA-ROVERS & ASSOCIATES
RESPONSIBLE PARTY	ADDRESS 5900 HOLLIS STREET, SUITE A. EMERYVILLE CA 94608		
	NAME CHEVRON ENVIRONMENTAL MANAGEMENT COMPANY <input type="checkbox"/> Unknown		PHONE SATYA SINHA 925-842-9876
	ADDRESS 6001 BOLINGER CANYON ROAD SAN RAMON CA 94583		
SITE LOCATION	FACILITY NAME (IF APPLICABLE) FORMER STANDARD OIL #30-7233		OPERATOR
	ADDRESS 2259 FIRST STREET LIVERMORE ALAMEDA 94550		PHONE
	CROSS STREET LIVERMORE AVENUE		
IMPLEMENTING AGENCIES	LOCAL AGENCY AGENCY NAME Livermore-Pleasanton Fire Department - John Rigter		PHONE 925-454-2357
	REGIONAL BOARD SF-RWQCB		PHONE 510-622-2300
SUBSTANCES INVOLVED	(1) NAME UNKNOWN		QUANTITY LOST (GALLONS) <input checked="" type="checkbox"/> Unknown
	(2)		<input type="checkbox"/> Unknown
DISCOVERY/ABATEMENT	DATE DISCOVERED 6/20/2007	HOW DISCOVERED <input type="checkbox"/> Tank Test <input checked="" type="checkbox"/> Tank Removal <input type="checkbox"/> Nuisance Conditions <input type="checkbox"/> Inventory Control <input type="checkbox"/> Subsurface Monitoring <input type="checkbox"/> Other...	
	DATE DISCHARGE BEGAN	METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) <input checked="" type="checkbox"/> Unknown <input checked="" type="checkbox"/> Remove Contents <input checked="" type="checkbox"/> Close Tank <input type="checkbox"/> Repair Tank <input type="checkbox"/> Change Procedure <input type="checkbox"/> Replace Tank <input checked="" type="checkbox"/> Other... <input type="checkbox"/> Repair Piping	
	HAS DISCHARGE BEEN STOPPED? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	IF YES, DATE 06/20/2007 Remove Tank	
SOURCE/CAUSE	SOURCE OF DISCHARGE <input checked="" type="checkbox"/> Tank Leak <input type="checkbox"/> Piping Leak <input type="checkbox"/> Unknown <input type="checkbox"/> Other...	CAUSE(S) <input type="checkbox"/> Overfill <input type="checkbox"/> Corrosion <input type="checkbox"/> Rupture/Failure <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> Spill <input type="checkbox"/> Other...	
CASE TYPE	CHECK ONE ONLY <input checked="" type="checkbox"/> Undetermined <input type="checkbox"/> Soil Only <input type="checkbox"/> Groundwater <input type="checkbox"/> Drinking Water - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)		
CURRENT STATUS	CHECK ONE ONLY <input type="checkbox"/> No Action Taken <input type="checkbox"/> Case Closed (Cleanup Completed or Unnecessary) <input checked="" type="checkbox"/> Leak Being Confirmed <input type="checkbox"/> Pollution Characterization <input type="checkbox"/> Remediation Plan <input type="checkbox"/> Post Cleanup Monitoring in Progress <input type="checkbox"/> Preliminary Site Assessment Workplan Submitted <input type="checkbox"/> Cleanup Underway <input type="checkbox"/> Preliminary Site Assessment Underway		
REMEDIAL ACTION	CHECK APPROPRIATE ACTION(S) <input type="checkbox"/> Cap Site (CD) <input type="checkbox"/> Excavate & Treat (ET) <input type="checkbox"/> Treatment at Hookup (HU) <input checked="" type="checkbox"/> Other... Site Assessment <input type="checkbox"/> Contamination Barrier (CB) <input type="checkbox"/> No Action Required (NA) <input type="checkbox"/> Enhanced Bio Degradation (IT) <input type="checkbox"/> Vacuum Extract (VE) <input type="checkbox"/> Remove Free Product (FP) <input type="checkbox"/> Replace Supply (RS) <input checked="" type="checkbox"/> Excavate & Dispose (ED) <input type="checkbox"/> Pump & Treat Groundwater (GT) <input type="checkbox"/> Vent Soil (VS)		
COMMENTS	A previous URF was submitted by the City of Livermore on 09/21/05 for an orphan tank found in the vicinity. We believe the tanks are connected and want to clarify the owner of the previous excavated orphan tank.		