## **RECEIVED**

8:04 am, May 25, 2007

Alameda County Environmental Health

# PHASE II SUBSURFACE SOIL AND GROUNDWATER SAMPLING SITE ASSESSMENT

Livermore Airport Jet Fuel Line Replacement Livermore Airport Livermore, California

## Requested by:

Mr. Harjit Sidhu
City of Livermore, Engineering Division
1052 South Livermore Avenue
Livermore, California 94550

## Prepared by:

Consolidated Engineering Laboratories 2001 Crow Canyon Road, Suite 100 San Ramon, California 94583 CEL Project No. 81-01824-A May 11, 2007

City of Livermore, Engineering Division 1052 S. Livermore Avenue Livermore, California 94550

Attention:

Mr. Harjit Sidhu

Subject:

Phase II Subsurface Soil and Groundwater Sampling Site Assessment

Livermore Airport Jet Fuel Line Replacement

Livermore Airport Livermore, California

CEL Project No. 81-01824-A

Dear Mr. Sidhu:

Consolidated Engineering Laboratories (CEL) has prepared this Phase II Soil and Groundwater Sampling and Site Assessment Report for an initial subsurface soil and groundwater study for the above referenced project site. The Alameda County Health Care Services Agency (ACHCSA) has requested a subsurface soil and groundwater site assessment of the subject pipeline leak area in their letter dated September 22, 2006. Please note that the ACHCSA desires electronic submittal of this material. If you have any questions regarding this report, please contact the undersigned at (925) 314-7100. We appreciate the opportunity of providing professional services to the City of Livermore.

Sincerely,

CONSOLIDATED ENGINEERING LABORATORIES

Christopher M. Palmer, CEG 1262

Christophy M. Palus

Senior Geologist

Eric J. Swenson, GE 2474, CEG 1855

Senior Geotechnical Engineer

Distribution: 2 plus PDF to Addressee (925/960-4531, Fax 925/960-4504) hsidhu@ci.livermore.ca.us

PALMER ENGINEERING

CMP/ES/pmf

R:\RCL-Livermore\81-01824-PW-Liver Airport\A-Phase II\81-01824-A Report.DOC



# **TABLE OF CONTENTS**

1.0	Background-Excavation and Sampling Activity During Pipeline Replacement	. 1
1.1	November 10, 2005 Soil Excavation and Sampling Summary	. 1
1.2	November 21, 2005 Additional Soil Excavation and Sampling Summary	. 1
1.3	Summary of Stockpile Data and Soil Disposal	. 2
1.4	June 2006 Soil Stockpile Sampling Summary	. 2
2.0	Technical Approach	. 4
3.0	Field Methods - Exploratory Borings	. 5
4.0	Field Methods - Groundwater Sampling	. 6
5.0	Subsurface Conditions	
6.0	Chemical Analysis and Results	. 8
7.0	Discussion	. 9
8.0	2000-foot Radius Well Search	10
9.0	Initial Site Conceptual Model	11
10.0	Conclusions and Recommendations	12
11.0	Limitations	13
Refere	ences	14

#### **FIGURES**

Figure 1 – Location Map

Figure 2 – Boring Location Map

Figure 3A and 3B – Geologic Cross Sections

Figure 4 – Dissolved Contaminants Map

Figure 5 – Well Search Map

#### APPENDIX A

November 2005 and June 2006 Letters and Soil Disposal Information

## APPENDIX B

Drilling Permit and Exploratory Boring Logs

## APPENDIX C

Chemical Analytical Data and Chain-of-Custody

#### APPENDIX D

2000-foot Radius Well Search Information



## 1.0 Background-Excavation and Sampling Activity During Pipeline Replacement

The project site is located in the City of Livermore (City) Municipal Airport, off Airway Boulevard, just inside the airport boundary near the airport entrance, just east of Terminal Circle (see Figures 1 and 2). An underground jet fuel pipeline with remote fill located near three underground storage tanks is used to ship petroleum fuel onto the airport grounds apparently leaked at this location. The City and their pipeline repair contractor (Gettler Ryan, Inc.) were making repairs and upgrades to this pipeline and remote fuel access station just beyond the fence at the cul-de-sac off Terminal Circle (see Figures 2 and 3). The remote fuel access station is used by delivery trucks to fill the three underground fuel storage tanks (one 15,000-gallon Jet A fuel, one 15,000-gallon Aviation gasoline 2, and one 15,000-gallon Aviation gasoline 1). Signs of leakage occurred at the remote fill station adjacent to the cul-de-sac off Terminal Circle (see Figures 1 and 2 and Appendix A).

## 1.1 November 10, 2005 Soil Excavation and Sampling Summary

At the City's request, CEL personnel visited the site on November 10, 2005 (sampling and soil analysis activities reported in our letter dated November 18, 2005) and collected 15 individual soil samples at various locations within and near the jet fuel line trench, remote fill excavation and soil stockpiles located at the Livermore Airport. A Livermore Fire Department representative selected soil sample locations, depths and the chemical analyses and observed the sampling.

Soil samples were collected by a CEL technician using laboratory supplied glass bottles, at locations under the remote fill station, pipeline trench excavation bottoms and nearby stockpiles. The bottles were filled with soil, sealed, labeled, logged onto chain-of-custody forms, and packed in chilled ice chests for shipping to the laboratory. Site native soils appeared to be clayey gravel and sandy clay; trench backfill was predominantly pea gravel; some samples may have contained both native soil and pea gravel.

The soil samples analyzed from the trench base were collected at about 2.0 to 3.5 feet deep, and from the soil stockpiles. Soil sample 1-1 at the remote fill station detected 8,000 micrograms per kilogram (ug/kg) of Total Petroleum Hydrocarbons as Gasoline (TPHG), 200 milligrams per kilogram (mg/kg) Total Petroleum Hydrocarbons as Diesel (TPHD), 59 ug/kg Toluene, 17 ug/kg Ethylbenzene and 210 ug/kg Xylenes. Benzene and Methyl-tert-Butyl-Ether (MTBE) were not detected in the sample. Soil samples 1-2 through 1-7 did not detect TPHG, TPHD, BTEX or MTBE.

### 1.2 November 21, 2005 Additional Soil Excavation and Sampling Summary

An additional excavation was deepened by Gettler-Ryan, Inc. during the pipeline work at the City's request to about 15 feet on November 21, 2006 (letter revision dated December 14, 2005) at sample location 1-1 to estimate depth of possible leakage on the basis of odor and staining at the "remote" filling line adjacent to the cul-de-sac road (off Terminal Circle).

The City asked CEL to provide suggestions for limited reconnaissance soil sampling while the deeper excavation was open to ascertain the presence of fuel contaminants. Petroleum odor emanated from the excavation near the remote fill portion of the pipeline trench. The excavation could not proceed deeper since the equipment could not excavate more than 15 feet and the pipeline and remote fill station had to be rebuilt quickly to support airport operations. Consequently the contaminated soil removed from this excavation was stockpiled and sampled prior to off-site disposal.



On the basis of limited field observations, there appeared to be some historic leakage in this area from the remote fill station. Groundwater was not encountered in the 15-foot deep excavation. CEL collected and tested soil from the excavation and the results are provided below:

- Soil samples collected at 9.5 feet deep detected 970,000 micrograms per kilograms (ug/kg) TPHG; 2,900 ug/kg Xylenes (X) detected and Benzene Ethylbenzene and Toluene (BTE) were not detected; TPHD 2,900 mg/kg detected; and Motor Oil was not detected.
- Soil samples at 13.0 feet deep showed BTEX and MTBE were not detected; 450,000 ug/kg TPHG detected; 1,100 mg/kg TPHD detected; and Motor Oil was not detected.
- Soil samples from 15.0 feet deep showed TPHD and Motor Oil were not detected.

CEL informed the City representatives that on the basis of the field conditions that they should file the appropriate paperwork for a spill to report to the agencies and prepare a work plan for further assessment.

### 1.3 Summary of Stockpile Data and Soil Disposal

The excavated soil and trench backfill were stockpiled near the excavations as shown on Figure 3. The soil stockpile samples (1-8 through 1-15) showed the highest concentrations ranging from 6,000 to 360,000 parts ug/kg of TPHG and 710 to 1,100 mg/kg TPHD. Benzene and Methyl-tert-Butyl-Ether (MTBE) were not detected in the samples. The samples from the underground tank area did not reveal detections; these tanks are equipped with leak detection systems and these systems did not detect any tank leakage according to the airport representative.

Soil samples analyzed for CAM 17 metals showed some Chromium and Cobalt detections above the draft Regional Water Quality Control Board Environmental Screening Levels (February 2005 Interim draft RWQCB ESLs). However, it is our opinion that these and the other metals are interpreted at levels in soils and alluvium or fill that may be attributed to the surrounding regional geologic source rocks.

The excavations were backfilled with a pea gravel fill. Since a relatively large and deep excavation had been excavated at the remote fill station, the contractor used concrete slurry to help the sidewalls stand vertically (to hold back the pea gravel backfill) as the backfill proceeded. The thin slurry "wall" can be removed in the future if needed. The City had the pipeline contractor segregate the contaminated soil (about 18 tons) and shipped to the Altamont landfill in January 2006 (see attached soil disposal documents provided by the City).

## 1.4 June 2006 Soil Stockpile Sampling Summary

CEL was requested to return to the site to sample a small surface stockpile of pea gravel (as reported in our letter dated June 14, 2006). Four soil samples of the stockpiled soil were collected for chemical analysis. The analytical results showed low concentrations of TPHG, Toluene, TPHD and Motor Oil Range Organics. Benzene and MTBE were not detected. CAM 17 metals showed Arsenic and Cobalt just over ESLs and Chromium at a level just over ten times the Soluble Threshold Limit Concentration (STLC). These metals are currently interpreted as being at levels in soil and/or alluvium that may be attributed to the surrounding regional geologic source rocks or fill source rock.



Airport personnel informed CEL that this soil stockpile (estimated at several yards of pea gravel) was moved to another location on the south side of the airport upon receipt of the sample analysis results. It is CEL's understanding that most of this pea gravel has been on the airport property stockpiled in an area south of the airport runways.



#### 2.0 Technical Approach

A Phase II Soil and Groundwater Sampling Site Assessment was performed with an "expedited approach" to initially ascertain the subsurface vertical and lateral extent of soil and groundwater contamination in the vicinity of the pipeline, remote fill area and underground tank locations. This information will be used to assess the general subsurface conditions, the uppermost groundwater aquifer occurrence, to initially locate vadose zone and dissolved groundwater contaminants. The ACHCSA representative reviewed proposed initial assessment boring work plan and added two additional borings, repositioned some borings and added a 2000-foot radius well search to the project to approve the work plan in their letter dated December 27, 2006.

Ten exploratory GeoProbe boring locations were selected for this assessment. The borings are positioned near the previous deep excavation area near the "remote" fill line, pipelines, former soil stockpile area, and underground tanks. Two borings were positioned in the surmised downgradient direction. Groundwater was estimated to be unconfined and to occur at depths of about 20-25 feet below surface grade and with a southwesterly flow direction according to the Zone 7 Water Agency regional groundwater elevation program data (April 2005). The site subsurface soil/alluvial sediments are anticipated to be clayey gravel and sandy to gravelly clay. The soil/sediments will be sampled to provide a profile of potential contaminants near the pipeline and remote fill, and the capillary fringe and/or upper aquifer contact. Groundwater was sampled from each boring. Borings were advanced up to about 32 to 36 feet to attempt to ascertain the presence of the upper contact of an underlying aquitard. Given the proximity to a highly used pipeline and fuel storage facility, the borings were advanced to gather information but at the minimum penetration depth. The GeoProbe exploratory boring locations are shown on Figures 1 and 2.



## 3.0 Field Methods - Exploratory Borings

Ten exploratory borings were drilled at the locations shown on Figure 3. The drilling permit was secured from the Zone 7 Water Agency, and an underground utility clearance was performed prior to doing the fieldwork. The work was coordinated with the airport operations. The boreholes were drilled with a GeoProbe truck mounted with drilling equipment that typically allows for relatively rapid assessment and subsurface sampling. All drilling equipment and sampling tools were clean prior to arriving to the site, between each sample and borehole and decontaminated before leaving the site.

The probe sample barrel was advanced collecting continuous cores of soil in each borehole. The sampler was then retrieved and dissembled, and the portion of the soil filled acetate liner retained for analysis was sealed with Teflon paper or foil and plastic end caps. Soil sample intervals retained for chemical analysis were cut from the liners at depths of suspected contaminant presence and various strata. All soil samples were labeled with the borehole number, date and project number, logged onto a chain-of-custody form, placed into a chilled ice chest on crushed ice and shipped to the laboratory.

The exploratory boreholes were lithologically logged using the Unified Soil Classification System under the supervision of a professional geologist. Additional lithologic information was collected to describe the subsurface stratigraphy. The borings were continuously sampled and soil cores retained in the acetate liners, at intervals of obvious contamination if present and at stratigraphic features of interest. Soil samples at roughly every four feet were field screened both visually and with a portable Thermo Environmental 580B photoionization detector (PID) for possible fuel hydrocarbon vapor. Environmental Instruments of Concord, California calibrated the PID unit prior to field use. Each soil sample was visually checked for evidence of staining, and groundwater samples were checked for presence of sheen.

The drill cuttings, sampler expendables (tips and acetate liners, etc.), grout and cleanup/ decontamination and cement grout water were placed into labeled closed top drums and placed at the Client specified on-site location.

Upon completion of the borehole drilling and collection of soil and groundwater samples, the boreholes were backfilled with cement grout, placed from the bottom to top of the borehole with a tremie pipe as required by the permitting agency. A surface patch was placed as directed by the airport representative to match the pavement.



## 4.0 Field Methods - Groundwater Sampling

Each exploratory boring was advanced to groundwater and sampled; groundwater samples were collected from within the uppermost aquifer strata observed in the borings. The groundwater samples collected from the boreholes were used for an initial reconnaissance of the site for dissolved groundwater contamination. Groundwater tended to enter all boreholes very slowly and some borehole collapse was experienced in some boreholes.

A brief summary of these field borehole groundwater sampling procedures follows: Each borehole was advanced into the uppermost aquifer and either temporarily cased and sampled with a disposable bailer, or used a Hydropunch discrete groundwater sampler tool advanced for sampling. Depth to groundwater measurements of the first encountered groundwater were made to the nearest one-one hundredth of one foot to surface grade, and also checked for the presence of separate phase product. The water entering the borehole was sampled using a clean disposable PVC bailer (or Hydropunch sampler after pushing the sampler to the aquifer and retracting the sampler barrel up to four feet to expose the sampling screen), and carefully poured into the appropriate laboratory prepared container with minimum cavitation and immediately sealed. Each water sample was labeled with the borehole number, date and project number, logged onto a chain-of-custody form, and placed in a chilled ice chest on crushed ice for transport to the laboratory.

Excess sample water and expendable items (such as disposable bailers, etc.) were placed in drums and left at the Client specified location.



#### 5.0 Subsurface Conditions

Ten borings were drilled and sampled April 2-4, 2007 at the locations shown on Figure 2. The deepest boring was advanced to a depth of 36 feet. Borings 1, 2 and 3 were advanced around the remote fuel fill loading area; B-4 was drilled at the former soil stockpile location; B-5 and B-6 drilled along the pipeline and near the sump; B-6 and B-7 near the underground fuel pipeline and storage tanks; and Borings B-8, 9 and 10 in the apparent downgradient flow direction from the fill, pipeline and underground tanks.

Clay and sandy clay strata underlie the pavements to depths of about six to 10 feet. A sand and clayey sand stratum underlies the clay to depths of about 12 to 15 feet. These strata may grade into each other and contain variable amounts of dispersed clay. Another clay stratum underlies the sand and may contain variable amounts of dispersed sand and thin sand beds. A clayey sand stratum occurs near the vicinity of B-1 and B-2 (see Geologic Cross Sections A-A' and B-B', Figures 3A and 3B).

These strata are underlain at depths of about 24 to 27 feet to about 30 feet by sandy clay that contain sandy beds. This interval forms the uppermost aquifer strata. Groundwater occurs at depths of about 24 to 26 feet and appeared to be unconfined. The aquifer strata appear to contain thin sandy beds with dispersed clay, and sandy clay beds that appear somewhat discontinuous and may laterally grade into each other at depths between about 24 to 28 feet. Groundwater entry into most boreholes was slow. Water levels did not appear to rise in the open boreholes and the water yield was low. Some apparent collapse of strata and/or swelling of clay strata precluded obtaining "static" water levels in most boreholes; therefore a rough plot of groundwater flow was not attempted from this boring data. Zone 7 groundwater plot data indicates a general southwestern flow direction.

Clay strata appear to underlie the uppermost water bearing strata at depths of 28 to 30 feet. These underlying clay strata did not yield water and the borings and Hydropunch samplers were terminated into this stratum. Field evidence of vadose soil, aquifer soil or dissolved contaminants were not observed in any borehole on the basis of PID readings, and field observations for stains, odor or sheen on water.



## 6.0 Chemical Analysis and Results

Soil samples (selected in boreholes as indicated from field observations) and groundwater samples were analyzed at McCampbell Analytical, Inc., a certified analytical laboratory. Samples were tested for the following; Total Petroleum Hydrocarbons as Gasoline (TPHG) and Diesel (TPHD) and Jet Fuel (TPHJF), Benzene (B), Toluene (T), Ethylbenzene (E), Xylene (X), and Volatile Organic Compounds (VOCs) including Methyl-tert-Butyl-Ether (MTBE), and fuel oxygenates tert-Amyl-Methyl-Ether, Ethyltert-Butyl-Ether, Di-Isopropyl Ether and tert-Butyl Alcohol, 1,2-Dichloroethane (1,2-DCA), Methanol and Ethanol using EPA Methods 3510/8015, 5030, 8020 and 8260B. The data results are tabulated at the end of this report and the laboratory analytical reports are attached in Appendix C (see Tables 1 and 2).



#### 7.0 Discussion

The soil chemical data shows the contaminants TPHG, TPHJF, BTEX, fuel oxygenates, 1,2-DCA, Ethanol and Methanol were not detected in any soil sample. Soil sample B-1-1@2-2.5 feet showed 1.0 milligram per kilogram (mg/kg) TPHD detected. All other soil samples showed that TPHD was not detected.

Groundwater data showed the water samples from Borings 1 through 10 revealed that TPHG, TPHJF, BTEX, fuel oxygenates, 1,2-DCA, Ethanol and Methanol were not detected in any groundwater sample. Dissolved TPHD was detected in Borings B-1, 2, 4, 7 and 8 at concentrations between 55 and 110 micrograms per liter (ug/l). TPHJF was detected in Borings B-1, 2, 4 and 8 at concentrations between 53 and 86 ug/l. The laboratory notes that Diesel range compounds were significant but not a recognizable pattern for water samples from B-1, 2 and 4 (see Figure 4).

The previous pipeline repair/upgrade reported contaminants appear limited to area observed during excavation in November 2005. The excavated soil that was removed contained fuel contaminants and was disposed as discussed above.

Dissolved contaminants are limited to TPHD and TPHJF in Borings 1, 2, 4, 7 and 8. The detections were near or slightly above the detection limit and no other fuel or volatile compound contaminants were present. The presence of TPHD and TPHJF suggests a very minor amount of dissolved TPHD and TPHJF reached the groundwater and may have moved about 80 feet west of the remote fuel facility. The laboratory reports that some of these do not match a TPHD pattern and are interpreted as degraded.



#### 8.0 2000-foot Radius Well Search

CEL performed a 2000-foot well search for wells within that radius of the project site. The State Department of Water Resources (DWR), City of Livermore and Alameda Zone 7 Water Agency were contacted regarding available well location and information. The available data have been summarized on the attached table (see Table 3) and the well locations plotted on Figure 5. Some of the well location information is incomplete so CEL plotted locations as close as the map or location information allows; wells were plotted in the center of the tract if the logs were not specific to location. Also the well data could contain duplicate logs, poor reproductions, and some logs and well construction details, yield, depth, and other information is incomplete. Some logs were apparently compiled from well owner interviews and then transferred onto well information forms up to several years after the well was constructed.

The information from Zone 7 is presented as sent to CEL that shows; the radius aerial map and well locations and their table of summarized well information (see Table and Appendix D). The Zone 7 well location map uses an aerial photograph and was crosschecked to the DWR information for duplicate well locations.

The well data show that 15 wells are within the 2000-foot radius; some additional wells near to the radius boundary are also included. Approximately six wells have been destroyed and eight are assumed active as irrigation or monitoring wells. The status of 13 wells is currently unknown.

There is one City of Livermore municipal water supply well (currently reported as inactive) just upgradient (northeast) of the site (T3S R1E 1P3 DWR #259569). The available well seal information for this municipal well shows a 110-foot cemented conductor casing and pumps groundwater from strata below that depth. This seal exists through the depth interval of the uppermost water bearing strata at about the 25 to 30 foot depth. A second City well at T3S R1E 1N1 (DWR #701237) is 1,000 feet west-northwest downgradient of the site and the seal from this well is reported from 0 to 220 feet. The status of this well is assumed active but that status was not verified. Telephone inquiries to the City of Livermore did not reveal any other information regarding these wells.



## 9.0 Initial Site Conceptual Model

The site is underlain by alluvium composed of interbedded sandy and clayey strata to a depth drilled of about 36 feet. Large alluvial aquifers underlie the area at depths of about 50 to 70 feet that produce large quantities of water used for drinking, agricultural and industrial uses. A brief review of the 2005 Zone 7 Groundwater Management Plan indicates that regional groundwater flow is westerly to southwesterly in the area of the airport. Subsurface information collected in this study shows that a thin unconfined shallow aquifer occurs at a depth of about 25 to 30 feet at the remote fuel fill and underground tank complex. This aquifer may contain interbeds of clayey strata and display lateral and vertical variation. A groundwater flow plot was not prepared due to slow groundwater entry and borehole collapse in some holes so "static" water level measurements were not collected in the study for an estimated groundwater flow plot, however flow in the shallow aquifer is assumed westerly. Ground monitoring well logs about 2200 feet southwest of the pipeline and underground tank location show somewhat similar hydrogeology and slightly deeper shallow groundwater occurrence for the shallow aquifer.

The project is located in the northeastern corner of the Livermore Airport at the aircraft fueling fill and underground tank complex. The potential receptors that are near to this fuel complex site include; groundwater wells, onsite airport personnel, Arroyo Las Positas Creek flows about 500 feet north of the site. The area is used for access to fuel tanks and fuel reception and storage and light aircraft parking. The City municipal well is reported in inactive or standby status and is not pumping water at this time. Aircraft operations and facilities include the control tower about two hundred yards from the fuel facility and office and reception complex about three hundred yards from the facility.

The 2000-foot radius well search indicates that several wells have been abandoned in the airport well search area and several monitoring wells are present to the north and west of the site. One City of Livermore municipal supply well is reported present within several hundred feet northeast of the aircraft fuel facility. This City of Livermore well has a conductor and seal that extend over 100 feet; this corresponds to sealing through the uppermost aquifer and the well screened interval draws water from depths of several hundred feet. Another City well occurs about 1,000 feet west northwest and also has a long well seal. No pumping wells exist on-site according to discussions with Airport personnel. A review of the well logs shows that water wells producing water for potable and irrigation use is drawn from depths below 50 feet or deeper and more typically large wells draw water from below 150 to 200 feet and deeper.

The site investigation data reported herein shows that petroleum contaminants were not present in the subsurface soil except at B-1 in shallow soil. The remaining soil samples in sandy and clayey texture soil/sediment showed that contaminants were not detected. Groundwater samples showed very low detections of TPHD and TPHJF that did not contain volatile fuel compounds. Airport personnel check fuel pipeline and underground tank systems daily and monthly and per regulations and monitoring requirements for their fueling facilities. Previous excavation in the pipeline and remote fill area did remove petroleum-contaminated soil that was disposed off-site, removing a known source of subsurface contaminants.



#### 10.0 Conclusions and Recommendations

CEL has completed a Phase II Soil and Groundwater Investigation in the area of the Livermore Airport Jet Fuel Line Replacement. At the time of the pipeline work, some petroleum-contaminated soil was observed and removed from the area. On the basis of that work, the ACHCSA requested additional subsurface soil and groundwater assessment study as well as a 2000-foot radius well search.

Ten exploratory borings were drilled and sampled in the pipeline and underground tank complex area. The borings were advanced and soil sampled in the vadose zone and to the uppermost aquifer and just into the underlying aquitard. Groundwater occurs at depths of about 24 to 27 feet and appeared to be unconfined. The aquifer strata appear to contain thin sandy beds with dispersed clay, and sandy clay beds that laterally grade into each other at depths between about 24 to 28 feet. An aquitard stratum appears to occur throughout the area below a depth of about 30 feet. No field evidence of subsurface contamination as odor, stain or vapor was observed in the field.

The soil chemical data show that contaminants TPHG, TPHJF, BTEX, fuel oxygenates, 1,2-DCA, Ethanol and Methanol were not detected in any soil sample. One soil sample at B-1@2.0-2.5 feet showed 1.0 mg/kg TPHD detected. All other soil samples showed that TPHD was not detected.

Groundwater data showed the water samples from Borings 1 through 10 revealed that TPHG, TPHJF, BTEX, fuel oxygenates, 1,2-DCA, Ethanol and Methanol were not detected in any groundwater sample. Dissolved TPHD was detected in Borings B-1, 2, 4, 7 and 8 at concentrations between 55 and 110 micrograms per liter (ug/l). TPHJF was detected in Borings B-1, 2, 4 and 8 at concentrations between 53 and 86 ug/l. The laboratory notes that Diesel range compounds were significant but not in a recognizable pattern for water samples from B-1, 2 and 4.

The site region is underlain by large alluvial aquifers that produce large quantities of water for drinking, agricultural and industrial use. The chemical analysis of the soil samples shows that contaminants were not present. Very low levels of dissolved TPHD and TPHJF occur just downgradient of the pipeline and underground tanks, however some of the detections do not match laboratory patterns. It is our opinion that these detections represent very minor amounts of fuel that may be from the area of the excavated soil at the remote fill. Evidence of widespread volatile contaminants was not observed in the soil and groundwater subsurface data. Previous excavation in the pipeline and remote fill area did remove petroleum-contaminated soil that was disposed off-site in 2006, removing a known source of subsurface contaminants.

On the basis of the investigation data, there is no widespread leakage of petroleum aircraft fuel from the remote fill, pipeline or existing underground tanks. In our opinion, further work is not warranted at this time.



#### 11.0 Limitations

This report has been prepared specifically for the Site at the City of Livermore Airport Underground Fuel Pipeline and Tank location at the Livermore Airport in Livermore, California and was done according to the current State and local agency suggested guidance documents for these investigations. The interpretations, conclusions and recommendations made herein are based on the data and analysis for the soil and water samples collected from the on-site exploratory boring locations. Conditions of the property can change over time and the use of this report by third parties is entirely at their own risk. Please note that reports of contamination must be submitted to the agencies in a timely manner. This report has been prepared for use solely of our Client. Reports of on-site contaminants must be reported to the oversight agencies in a timely manner. This report shall not be relied upon by or transferred to any other party, or used for any other purpose, without the express written authorization of our Client, and Consolidated Engineering Laboratories, Inc. is not responsible for errors in laboratory analysis and reporting, nor for information not available, nor unreported or unknown sources of site contamination during the course of the study, and no warranty or guarantee is expressed or implied therein.



#### References

Alameda County Health Care Services Agency letter dated September 22, 2006 to Mr. Harjit Sidhu, City of Livermore, Engineering Department, 1052 S. Livermore Avenue, Livermore, CA 94550, Subject: Fuel Case No. RO0002090, City of Livermore Airport, 636 Terminal Drive, Livermore, CA 94550-Request of Workplan," with attachments.

Alameda County Health Care Services Agency letter dated December 27, 2006 to Mr. Mike Irby, City of Livermore, Engineering Department, 1052 S. Livermore Avenue, Livermore, CA 94550, Subject: Fuel Case No. RO0002090, City of Livermore Airport, 636 Terminal Drive, Livermore, CA 94550-Work Plan Comments with attachments.

City of Livermore Soil Disposal Documentation.

Consolidated Engineering Laboratories, Inc., letter report dated November 18, 2005, Revised December 14, 2005, City of Livermore City Hall, Engineering Division 1052 South Livermore Avenue Livermore, California 94550-4899 Attention: Robert Tingley Associate Engineering Technician, Subject: Environmental Sampling, Testing and Evaluation of Soil Livermore Airport Jet Fuel Line Replacement, Livermore, California, CEL Proposal No. 81-01824-PW (10-00431-PW-CS).

Consolidated Engineering Laboratories, Inc., letter report dated June 14, 2006 City of Livermore City Hall, Engineering Division 1052 South Livermore Avenue Livermore, California 94550-4899 Attention: Robert Tingley - Associate Engineering Technician, Subject: Environmental Sampling, Testing and Evaluation of Soil Livermore Airport Jet Fuel Line Replacement, Livermore, California, CEL Proposal No. 81-01824-PW (10-00431-PW-CS.

Dibblee, T. W., 2006, Geologic Map of the Livermore Quadrangle Contra Costa and Alameda Counties, California: Dibblee Geology Center Map #DF-196, Santa Barbara Museum of Natural History.

Department of Water Resources, June 1974: Bulletin 118-2, Evaluation of the Ground Water Resources: Livermore and Sunol Valleys.

Department of Water Resources, Request for Well Information, 2000-foot Radius Well Search, 636 Terminal Circle, Airport Underground Tank and Pipeline Site.

Zone 7 Water Agency, 100 North Canyons Parkway, Livermore, CA, Request for Well Information, 2000-foot Radius Well Search, 636 Terminal Circle, Airport Underground Tank and Pipeline Site.

Zone 7 Water Agency, 100 North Canyons Parkway, Livermore, CA, 2005, Annual Report of the Groundwater Management Plan, text, appendices and figures.



Table 1. Soil Chemical Data Boring B-1

	B-1 @2-2.5'	B-1-3 @11.5-12'	B-1-5 @19.5-20'	B-1-7 @27.5-28'	B-1-8 @31.5-32'
TPHG (mg/kg)	<u>≤</u> 1.0	≤1.0	≤1.0	≤1.0	≤1.0
TPHD (mg/kg	1.0	<u>≤</u> 1.0	<u>≤</u> 1.0	≤1.0	≤1.0
TPHJF (mg/kg)	<u>≤</u> 1.0	≤1.0	≤1.0	≤1.0	≤1.0
Benzene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Toluene (mg/kg)	<u>&lt;</u> 0.005	<u>&lt;</u> 0.005	≤0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Xylenes (mg/kg)	<u>&lt;</u> 0.005	≤0.005	≤0.005	≤0.005	≤0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
ETBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	<0.005
DIPE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	<0.005
TAME (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
TBA (mg/kg)	≤0.05	≤0.05	≤0.05	≤0.05	<0.05
1,2-Dichloroethane (mg/kg)	≤0.005	≤0.005	≤0.005	<u>&lt;</u> 0.005	≤0.005
Ethanol (mg/kg)	≤0.25	≤0.25	≤0.25	≤0.25	<0.25
Methanol (mg/kg)	<u>≤</u> 2.5	<u>&lt;</u> 2.5	<u>&lt;</u> 2.5	<u>&lt;</u> 2.5	<u>&lt;</u> 2.5

None Detected at detection limit shown, see laboratory reports. Mg/kg - Milligrams per kilogram.

Table 1 con't. Soil Chemical Data Boring B-2

	B-2-1 @3.5-4.0'	B-2-2 @7.5-8.0'	B-2-4 @15.5-16.0'	B-2-7 @27.5-28'
TPHG (mg/kg)	<u>≤</u> 1.0	≤1.0	≤1.0	≤1.0
TPHD (mg/kg	≤1.0	≤1.0	≤1.0	≤1.0
TPHJF (mg/kg)	≤1.0	≤1.0	≤1.0	≤1.0
Benzene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
Toluene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	<u>&lt;</u> 0.005	<u>&lt;</u> 0.005	≤0.005	≤0.005
Xylenes (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
ETBE (mg/kg)	≤0.005	<u>≤</u> 0.005	≤0.005	≤0.005
DIPE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
TAME (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
TBA (mg/kg)	<u>&lt;</u> 0.05	<u>&lt;</u> 0.05	≤0.05	<u>&lt;</u> 0.05
1,2-Dichloroethane (mg/kg)	≤0.05	≤0.05	≤0.05	≤0.05
Ethanol (mg/kg)	<0.005	<0.005	<0.005	<0.005
Methanol (mg/kg)	≤0.25	≤0.25	<u>≤</u> 0.25	≤0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg - Milligrams per kilogram.



Table 1, con't. Soil Chemical Data Boring B-3

	B-3-1 @2.5-3.0'	B-3-2 @7.5-8.0'	B-3-3 @11.5-12.0'	B-3-4 @15.5-16.0'	B-3-5 @19.5-20.0'	B-3-6 @23.5-24.0'
			1			
TPHG (mg/kg)	≤1.0	≤1.0	≤1.0	≤1.0	≤1.0	≤1.0
TPHD (mg/kg	<u>≤</u> 1.0	<u>&lt;</u> 1.0	<u>≤</u> 1.0	<u>&lt;</u> 1.0	<u>≤</u> 1.0	<u>&lt;</u> 1.0
TPHJF (mg/kg)	<u>&lt;</u> 1.0	<u>&lt;</u> 1.0	≤1.0	<u>&lt;</u> 1.0	<u>≤</u> 1.0	≤1.0
Benzene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Toluene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Xylenes (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
ETBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
DIPE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
TAME (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
TBA (mg/kg)	≤0.05	≤0.05	≤0.05	≤0.05	≤0.05	≤0.05
1,2-Dichloroethane (mg/kg)	≤0.05	≤0.05	≤0.05	≤0.05	≤0.05	≤0.05
Ethanol (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Methanol (mg/kg)	≤0.25	≤0.25	<u>≤</u> 0.25	≤0.25	≤0.25	≤0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg - Milligrams per kilogram.

Table 1, con't. Soil Chemical Data Boring B-4

	B-4-1 @2.0-2.5'	B-4-2 @7.5-8.0'	B-4-4 @15.5-16.0'	B-4-5 @19.5-20.0'	B-4-6 @23.5-24.0'
TPHG (mg/kg)	<u>&lt;</u> 1.0	<u>≤</u> 1.0	<u>≤</u> 1.0	≤1.0	<u>&lt;</u> 1.0
TPHD (mg/kg	≤1.0	≤1.0	<u>≤</u> 1.0	<u>≤</u> 1.0	<u>&lt;</u> 1.0
TPHJF (mg/kg)	≤1.0	≤1.0	≤1.0	<u>&lt;</u> 1.0	<u>≤</u> 1.0
Benzene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Toluene (mg/kg)	≤0.005	≤0.005	≤0.005	<u>&lt;</u> 0.005	≤0.005
Ethylbenzene (mg/kg)	<u>&lt;</u> 0.005	<u>&lt;</u> 0.005	≤0.005	≤0.005	≤0.005
Xylenes (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	<u>&lt;</u> 0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005	<0.005	≤0.005
ETBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
DIPE (mg/kg)	≤0.005	≤0.005	≤0.005	<u>&lt;</u> 0.005	≤0.005
TAME (mg/kg)	≤0.005	≤0.005	≤0.005	<u>&lt;</u> 0.005	≤0.005
TBA (mg/kg)	≤0.05	≤0.05	≤0.05	≤0.05	≤0.05
1,2-Dichloroethane (mg/kg)	≤0.05	≤0.05	≤0.05	≤0.05	≤0.05
Ethanol (mg/kg)	<0.005	<0.005	<0.005	<0.005	≤0.005
Methanol (mg/kg)	≤0.25	≤0.25	<u>&lt;</u> 0.25	≤0.25	≤0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg - Milligrams per kilogram.



Table 1, con't. Soil Chemical Data Boring B-5

	B-5-1 @3.5-4.0'	B-5-2 @7.5-8.0'	B-5-3 @11.5-12.0'	B-5-4 @15.5-16.0'	B-5-6 @23.5-24.0'
TPHG (mg/kg)	≤1.0	<u>≤</u> 1.0	<u>≤</u> 1.0	<u>&lt;</u> 1.0	≤1.0
TPHD (mg/kg	≤1.0	<u>≤</u> 1.0	<u>≤</u> 1.0	≤1.0	≤1.0
TPHJF (mg/kg)	<u>≤</u> 1.0	<u>≤</u> 1.0	≤1.0	<u>&lt;</u> 1.0	≤1.0
Benzene (mg/kg)	<u>&lt;</u> 0.005	<u>&lt;</u> 0.005	<u>&lt;</u> 0.005	≤0.005	≤0.005
Toluene (mg/kg)	≤0.005	≤0.005	<u>&lt;</u> 0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	≤0.005	≤0.005	≤0.005	<u>&lt;</u> 0.005	≤0.005
Xylenes (mg/kg)	≤0.005	<u>&lt;</u> 0.005	≤0.005	≤0.005	≤0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
ETBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
DIPE (mg/kg)	<u>&lt;</u> 0.005	≤0.005	≤0.005	≤0.005	≤0.005
TAME (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
TBA (mg/kg)	<u>&lt;</u> 0.05	<u>&lt;</u> 0.05	<u>&lt;</u> 0.05	≤0.05	≤0.05
1,2-Dichloroethane (mg/kg)	≤0.05	≤0.05	≤0.05	<u>&lt;</u> 0.05	≤0.05
Ethanol (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Methanol (mg/kg)	<u>&lt;</u> 0.25	≤0.25	≤0.25	<u>&lt;</u> 0.25	≤0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg - Milligrams per kilogram.

Table 1, con't. Soil Chemical Data Boring B-6

	B-6-1 @3.5-4.0'	B-6-2 @7.5-8.0'	B-6-4 @15.5-16.0'	B-6-6 @23.5-24.0'	B-6-8 @31.5-32'
TPHG (mg/kg)	<u>≤</u> 1.0	≤1.0	<u>&lt;</u> 1.0	<u>≤</u> 1.0	<u>≤</u> 1.0
TPHD (mg/kg	<u>&lt;</u> 1.0	<u>≤</u> 1.0	≤1.0	<u>≤</u> 1.0	≤1.0
TPHJF (mg/kg)	≤1.0	<u>&lt;</u> 1.0	<u>≤</u> 1.0	≤1.0	≤1.0
Benzene (mg/kg)	<u>&lt;</u> 0.005	≤0.005	≤0.005	≤0.005	≤0.005
Toluene (mg/kg)	<u>&lt;</u> 0.005	<u>&lt;</u> 0.005	≤0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	≤0.005	<u>&lt;</u> 0.005	≤0.005	≤0.005	≤0.005
Xylenes (mg/kg)	≤0.005	≤0.005	≤0.005	<u>&lt;</u> 0.005	≤0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
ETBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
DIPE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
TAME (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
TBA (mg/kg)	<u>&lt;</u> 0.05	≤0.05	≤0.05	≤0.05	≤0.05
1,2-Dichloroethane (mg/kg)	≤0.05	≤0.05	<u>&lt;</u> 0.05	≤0.05	≤0.05
Ethanol (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005	≤0.005
Methanol (mg/kg)	≤0.25	≤0.25	≤0.25	≤0.25	≤0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg – Milligrams per kilogram.



## <sup>a</sup> Table 1, con't. Soil Chemical Data Boring B-7

	B-7-3 @11.5-12.0'	B-7-4 @15.5-16.0'	B-7-5 @19.5-20.0'	B-7-6 @23.5-24.0'
	@11.5-12.0	10013.3-10.0	<u>@19.5-20.0</u>	@23.3-24.0
TPHG (mg/kg)	≤1.0	≤1.0	<1.0	<1.0
TPHD (mg/kg	≤1.0	≤1.0	≤1.0	<u>&lt;</u> 1.0
TPHJF (mg/kg)	<u>≤</u> 1.0	≤1.0	<u>≤</u> 1.0	<u>≤</u> 1.0
Benzene (mg/kg)	<u>&lt;</u> 0.005	<u>≤</u> 0.005	<u>&lt;</u> 0.005	≤0.005
Toluene (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	≤0.005	≤0.005	≤0.005	<u>&lt;</u> 0.005
Xylenes (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
ETBE (mg/kg)	<u>&lt;</u> 0.005	≤0.005	<u>&lt;</u> 0.005	≤0.005
DIPE (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
TAME (mg/kg)	≤0.005	≤0.005	≤0.005	≤0.005
TBA (mg/kg)	≤0.05	≤0.05	≤0.05	≤0.05
1,2-Dichloroethane	≤0.05	≤0.05	≤0.05	≤0.05
(mg/kg)				
Ethanol (mg/kg)	≤0.005	≤0.005	<u>&lt;</u> 0.005	<u>&lt;</u> 0.005
Methanol (mg/kg)	<u>&lt;</u> 0.25	<u>≤</u> 0.25	<u>≤</u> 0.25	<u>&lt;</u> 0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg - Milligrams per kilogram.

Table 1, con't. Soil Chemical Data Boring B-8

	B-8-1 @3.5-4.0	B-8-4 @15.5-16.0'	B-8-6 @23.5-24.0'
TPHG (mg/kg)	<u>≤</u> 1.0	<u>≤</u> 1.0	≤1.0
TPHD (mg/kg	<u>≤</u> 1.0	<u>≤</u> 1.0	<u>≤</u> 1.0
TPHJF (mg/kg)	<u>≤</u> 1.0	≤1.0	≤1.0
Benzene (mg/kg)	≤0.005	≤0.005	≤0.005
Toluene (mg/kg)	≤0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	≤0.005	≤0.005	≤0.005
Xylenes (mg/kg)	≤0.005	≤0.005	≤0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005
ETBE (mg/kg)	≤0.005	≤0.005	≤0.005
DIPE (mg/kg)	≤0.005	≤0.005	≤0.005
TAME (mg/kg)	≤0.005	≤0.005	<0.005
TBA (mg/kg)	≤0.05	<0.05	<u>&lt;</u> 0.05
1,2-Dichloroethane	<0.05	<0.05	≤0.05
(mg/kg)		_	
Ethanol (mg/kg)	<u>&lt;</u> 0.005	≤0.005	≤0.005
Methanol (mg/kg)	≤0.25	<u>&lt;</u> 0.25	<u>&lt;</u> 0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg - Milligrams per kilogram.



Table 1, con't. Soil Chemical Data Boring B-9

	B-9-1 @3.5-4.0'	B-9-4 @15.5-16.0'	B-3-6 @23.5-24.0'
TPHG (mg/kg)	<u>≤</u> 1.0	<u>≤</u> 1.0	<u>&lt;</u> 1.0
TPHD (mg/kg	<u>≤</u> 1.0	<u>≤</u> 1.0	≤1.0
TPHJF (mg/kg)	<u>&lt;</u> 1.0	<u>&lt;</u> 1.0	<u>&lt;</u> 1.0
Benzene (mg/kg)	≤0.005	≤0.005	<u>&lt;</u> 0.005
Toluene (mg/kg)	≤0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	≤0.005	≤0.005	≤0.005
Xylenes (mg/kg)	≤0.005	≤0.005	≤0.005
MTBE (mg/kg)	<u>&lt;</u> 0.005	≤0.005	≤0.005
ETBE (mg/kg)	≤0.005	≤0.005	≤0.005
DIPE (mg/kg)	≤0.005	≤0.005	≤0.005
TAME (mg/kg)	<u>&lt;</u> 0.005	≤0.005	≤0.005
TBA (mg/kg)	≤0.05	≤0.05	≤0.05
1,2-Dichloroethane	≤0.05	≤0.05	≤0.05
(mg/kg)			
Ethanol (mg/kg)	≤0.005	<u>&lt;</u> 0.005	<u>≤</u> 0.005
Methanol (mg/kg)	≤0.25	≤0.25	≤0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg – Milligrams per kilogram.

Table 1, con't. Soil Chemical Data Boring B-10

	B-10-1 @2.5-3.0'	B-10-4 @15.5-16.0'	B-10-6 @23.5-24.0'
TPHG (mg/kg)	<u>≤</u> 1.0	<u>≤</u> 1.0	<u>≤</u> 1.0
TPHD (mg/kg	<u>≤</u> 1.0	<u>≤</u> 1.0	<u>≤</u> 1.0
TPHJF (mg/kg)	≤1.0	≤1.0	<u>≤</u> 1.0
Benzene (mg/kg)	≤0.005	≤0.005	≤0.005
Toluene (mg/kg)	≤0.005	≤0.005	≤0.005
Ethylbenzene (mg/kg)	≤0.005	≤0.005	≤0.005
Xylenes (mg/kg)	<u>&lt;</u> 0.005	≤0.005	≤0.005
MTBE (mg/kg)	≤0.005	≤0.005	≤0.005
ETBE (mg/kg)	≤0.005	≤0.005	≤0.005
DIPE (mg/kg)	≤0.005	<u>&lt;</u> 0.005	<u>&lt;</u> 0.005
TAME (mg/kg)	≤0.005	≤0.005	≤0.005
TBA (mg/kg)	≤0.05	≤0.05	≤0.05
1,2-Dichloroethane	≤0.05	≤0.05	≤0.05
(mg/kg)			
Ethanol (mg/kg)	≤0.005	≤0.005	≤0.005
Methanol (mg/kg)	≤0.25	≤0.25	<u>&lt;</u> 0.25

None Detected at detection limit shown, see laboratory reports. Mg/kg - Milligrams per kilogram.



Table 2. Groundwater Chemical Data Borings B-1 through B-10

	B-1*	B-2	B-3	B-4*	B-5	B-6	B-7	B-8#	B-9	B-10
TPHG (ug/l)	≤50	≤50	≤50	<u>&lt;</u> 50	≤50	≤50	≤50	≤50	≤50	<u>&lt;</u> 50
TPHD (ug/l)	84	100	≤50	110	≤50	≤50	55	110	≤50	<u>&lt;</u> 50
TPHJF (ug/l)	53	81	≤50	86	<u>≤</u> 50	<u>&lt;</u> 50	≤50	94	<u>&lt;</u> 50	≤50
Benzene (ug/l)	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	<u>&lt;</u> 0.5	_<0.5	≤0.5	≤0.5
Toluene (ug/l)	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	_<0.5
Ethylbenzene	≤0.5	≤0.5	≤0.5	≤0.5	<u>&lt;</u> 0.5	<u>&lt;</u> 0.5	≤0.5	≤0.5	≤0.5	≤0.5
(ug/l)										
Xylenes (ug/l)	<u>≤</u> 0.5	≤0.5	_<0.5	≤0.5	<u>&lt;</u> 0.5	<u>≤</u> 0.5	≤0.5	≤0.5	≤0.5	≤0.5
MTBE (ug/l)	≤0.5	≤0.5	≤0.5	≤0.5	<u>&lt;</u> 0.5	≤0.5	≤0.5	≤0.5	≤0.5	<u>&lt;</u> 0.5
ETBE (ug/l)	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	<u>&lt;</u> 0.5	≤0.5	<u>&lt;</u> 0.5
DIPE (ug/l)	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	<u>&lt;</u> 0.5	≤0.5
TAME (ug/l)	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5
TBA (ug/l)	≤5.0	≤5.0	≤5.0	≤5.0	≤5.0	≤5.0	≤5.0	<u>&lt;</u> 5.0	<u>&lt;</u> 5.0	≤5.0
1,2-	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5	≤0.5
Dichloroethane	-	-								1.
(ug/l)	_1									
Ethanol (ug/l)	≤50	<u>≤</u> 50	≤50	<u>&lt;</u> 50	≤50	≤50	≤50	≤50	<u>&lt;</u> 50	≤50
Methanol (ug/l)	≤500	≤500	≤500	≤500	≤500	<u>≤</u> 500	≤500	<u>&lt;</u> 500	≤500	<u>≤</u> 500


None Detected at detection limit shown, see laboratory reports. Ug/l – Micrograms per liter.


\* - Laboratory reports that diesel range compounds are significant but no recognizable pattern and oil range compounds are significant.

<sup># -</sup> A Laboratory report that diesel range compounds are significant and about one percent of the sample was

## **FIGURES**

Figure 1 – Location Map
Figure 2 – Boring Location Map
Figure 3A & 3B – Geologic Cross Sections
Figure 4 – Dissolved Contaminants Map
Figure 5 – Well Search Map







Consolidated Engineering Laboratories, Inc. San Ramon, CA

**Location Map** Aircraft Fuel Fill and USTs **Livermore Airport** Livermore, CA

Proj. No. 81-01824-A May 2007

FIGURE 1





Generalized strata relationships and contacts interpreted locations are portrayed on the cross section, additional vertical and horizontal variations may occur.

Geologic Cross Sections
Pipeline and Underground Fuel Tanks
Livermore Airport, Livermore, CA


May, 2007


CONSOLIDATED ENGINEERING LABORATORIES, INC.


FIGURE 3A


Proj. No. 81-01824-A

Scales: as shown.









Reported Well Location, see well search table and report text.

Consolidated Engineering Laboratories, Inc. San Ramon, CA

2000-Foot Well Search Livermore Airport Livermore, CA Proj. No. 81-01824-A May 2007

FIGURE 5

# **APPENDIX A**

November 2005 & June 2006 Letters & Soil Disposal Information



November 18, 2005 Revised December 14, 2005

City of Livermore City Hall, Engineering Division 1052 South Livermore Avenue Livermore, California 94550-4899

Attention:

Robert Tingley - Associate Engineering Technician

Subject:

**Environmental Sampling, Testing and Evaluation of Soil** 

Livermore Airport Jet Fuel Line Replacement

Livermore, California

CEL Proposal No. 81-01824-PW (10-00431-PW-CS)

Dear Mr. Tingley:

Pursuant to your request, Consolidated Engineering Laboratories (CEL) has provided environmental testing services for onsite soil at the subject site. The project site is located in Livermore Municipal Airport, off of Airway Boulevard, just inside the airport boundary near the airport entrance, just east of Terminal Circle. Our representative visited the site on November 10, 2005, and collected 15 individual soil samples at various locations within and near a jet fuel line excavation located at the Livermore Airport, Livermore, California. Soil samples were collected by hand in the trench excavation bottoms and nearby stockpiles.

The sample locations are shown on the attached Figure 1. Sample 1-1 was obtained in the trench excavation at a depth of two-feet. Samples 1-2 through 1-5 were collected at the trench bottom at a depth of about 3.5-feet and 1-6 and 1-7 was obtained at a depth of three-feet. The remaining samples, 1-8 through 1-15, were obtained about one-foot into the two soil stockpiles shown on Figure 1. The small stockpile is a mixture of soil and pea gravel and the large stockpile is dirty pea gravel.

The soil samples were transported to a California state-certified laboratory for testing. Proper chain-of-custody procedures were followed. The soil samples were analyzed for the presence of Volatile Organic Compounds by GC/MS (EPA 8260B), Nonhalogenated Organics using GC/FID – Modified (Diesel Range Organics) (EPA8015B), Inductively Coupled Plasma – Atomic Emission Spectrometry (EPA 6010B/7471A), Inductivity Coupled Plasma – Atomic Emission Spectrometry – STLC Citrate (EPA 6010B), and Mercury in Solid or Semisolid Waster (Manual Cold Vapor Technique). Copies of the laboratory reports are attached.



Analytical results were compared to pertinent Soluble Threshold Limit Concentration (STLC), Total Threshold Limit Concentration (TTLC), Environmental Screening Levels (ESL's) for surface soil, and Preliminary Remediation Goals (PRG). Contaminant concentrations in soil are generally considered to be nonhazardous if they are equal or less than the TTLC, and less than 10 times the STLC as defined by the State of California, Title 22. Two other screening tools used to assess the acceptability of soils are the Preliminary Remediation Goals (PRGs) for industrial soil provided by the US EPA, and the Environmental Screening Levels provided by the San Francisco Bay Regional Water Quality Control Board for shallow soils where groundwater is not a current or potential source of drinking water (commercial/industrial land use area). The attached Table 1 summarizes the results of the analytical testing. Test results in bold indicate contaminant concentrations in excess of various regulatory guidelines.

Several constituents were found to be above regulatory guidelines. Gasoline concentrations in Samples 1-1, 1-8, 1-9, 1-10 and 1-11 were high. Concentrations ranged from 6,000 ppm to 360,000 ppm. Toluene was detected over the ESL limit in Samples 1-1, 1-9, and 1-11. In particular, the concentration of Toluene in Sample 1-11 was about 420% higher than the ESL limit. The concentration of Total Xylenes in Sample 1-1 exceeded the ESL. Diesel Range Organics were detectable above the ESL limit. The ESL for DRO is 500 ppm, and concentrations reported in Samples 1-8, 1-9, 1-10, and 1-11 ranged from 710 to 1,100 ppm. Motor oil and MTBE were below action levels or were non-detectable in all the samples.

Concentrations of metals were generally below the screening levels. However, the concentration of Cobalt was above the ESL of 10 ppm in Samples 1-1, 1-2, 1-3, 1-5, 1-13, 1-14, and 1-15. High Chromium levels were detected in Samples 1-1 and 1-14. The STLC limit for Chromium is 50 ppm, and concentrations were detected at 54 and 55 ppm in the two samples. Additional WET (Waste Extraction Test) testing was performed on samples 1-1, 1-2, and 1-14 on December 12, 2005. The WET Chromium results were well below the STLC limit for Chromium.

It should be noted that the above screening tools are generally for action levels for contaminants in soil that is to remain in place, and different criteria may apply for soil that is to be transferred to or from a site. The local landfill or other location of proposed exported soil should be contacted to determine their requirements for accepting this material. The reported results are from representative samples of the soil, and do not necessarily represent the cleanliness of the entire site. These results should not be considered a clean bill of health, or prognosis of soil cleanliness. Local governing agencies may have stricter guideline standards that will govern this disposal of the soil.

Marc Hachey, P.G. 7833

Project Geologist



The test results indicate that the trenches for the jet fuel line are below action levels except the small stub out trench in the area of Sample 1-1. Further study in this area is warranted. The small stockpile of soil and pea gravel can be utilized onsite for backfill. The larger pea gravel stockpile will either have to be remediated or disposed properly.

We hope this provides the necessary information. If you should have any questions regarding this letter, please contact the undersigned at (925) 314-7100.

Sincerely,

**CONSOLIDATED ENGINEERING LABORATORIES** 

William R. Stevens, PE 43010, GE 2339

Principal Geotechnical Engineer

Attachments: Figure 1 Site plan

Table 1 – Summary of Analytical Data

STL San Francisco Analytical Lab Report, 11/15/05, 66 pp STL San Francisco Analytical Lab Report, 12/12/05, 12 pp

Distributions: 2 plus email to Addressee, (925/960-4551, Fax 925/960-4504, rctingley@ci.livermore.ca.us)

MAH/WRS:pmf

L:\Users\Geotech\RCA-Calif-81\RCO-Alameda\RCI-Livermore\81-01824-PW-Liver Airport\Analyt Sample Test 1.doc



# TABLE 1 (Samples 1-1 through 1-15) SUMMARY OF ANALYTICAL DATA

SUMMARY OF ANALYTICAL DATA									
Constituent	Reported Concentration	California Title	SFBRWQCB	California	US EPA				
	(ppm)	22	Environmental	Title 22	Residential				
		STLC (ppm)	Screening Levels -ESLs	TTLC (ppm)	PRG (ppm)				
			(ppm)		N/A				
Gasoline Range Organic		NA	400	NA	NA				
1-1 (2)	8,000			ı					
1-2	ND								
1-3	ND								
1-4	ND	,							
1-5	ND								
1-6	ND								
1-7	ND	,							
1-8 (2)	260,000								
1-9 (2)	6,000		•						
1-10 (2)	310,000								
1-11 (2)	360,000								
1-12	ND								
1-13	ND		-						
1-14	ND								
1-15	ND								
	IND	NA	0.38	NA	NA				
Benzene	ND	NA	0.36	INA	INA				
1-1	ND								
1-2	ND								
1-3	ND								
1-4	ND	j							
1-5	ND								
1-6	ND								
1-7	ND								
1-8	ND								
1-9	ND								
1-10	ND								
	ND								
1-11									
1-12	ND								
1-13	ND								
1-14	ND		ļ						
1-15	ND								
Toluene		NA	9.3	NA	NA				
1-1 (2)	59			į					
1-2	ND				.				
1-3	ND				İ				
1-4	ND								
1-5	ND								
1-6	ND ND								
1-7	ND ND								
1-8	ND								
1-9 (2)	12								
1-10	ND								
1-11 (2)	3,900								
1-12	ND								
1-13	8.3								
1-14	5.6								
1-15	ND								
1	IND	I							

Constituent	Reported Concentration (ppm)	California Title 22	SFBRWQCB Environmental	California Title 22	US EPA Residential
	(PP.11)	STLC (ppm)	Screening Levels –ESLs (ppm)	TTLC (ppm)	PRG (ppm)
Ethyl Benzene	17 .	NA	32	NA	NA
1-1	ND				
1-2	ND	!	:		
1-3 1-4	ND				
1-4	ND			:	
1-6	ND				
1-7	ND				
1-8	ND				
1-9	ND				
1-10	ND				
1-11	ND				
1-12	ND				
1-13	ND				
1-14	ND				
1-15	ND				
Total Xylenes		NA	2.3	NA	NA .
1-1 (2)	210				
1-2	. ND				
1-3	ND				
1-4	ND				
1-5	ND			ĺ	
1-6	ND				
1-7	ND				ļ
1-8	ND				
1-9	ND				
1-10 1-11	ND ND				
1-12	ND ND				
1-13	ND ND				
1-14	ND				
1-15	ND				
Diesel Range Organics		NA	500	NA	NA
1-1	200			İ	
1-2	ND				
1-3	ND		•		
1-4	6.1				
1-5	61				
1-6	ND				
1-7	ND				
1-8 (2)	1,100				
1-9 (2)	710				
1-10 (2)	750			.	
1-11 (2)	800				
1-12	16				
1-13	15				
1-14	7.5				
1-10	3	<u>L</u> .	<u></u>		

Constituent	Reported Concentration	California Title	SFBRWQCB	California	US EPA
Constituent	(ppm)	22	Environmental	Title 22	Residential
	(56)	STLC (ppm)	Screening Levels -ESLs (ppm)	TTLC (ppm)	PRG (ppm)
Motor Oil Range Organics		NA	1,000	NA	NA
1-1	ND				
1-2	ND				
1-3	ND				
1-4	ND				
1-5	ND		-		
1-6	ND				
1-7	ND		;		
1-8	ND .				
1-9	ND				
1-10	ND				
1-11	ND				
1-12	65				
1-13	68				
1-14	ND				
1-15	ND				
MTBE		NA	5.6	NA	620
1-1	ND				
1-2	ND				
1-3	ND				
1-4	ND				
1-5	ND				
1-6	ND	,			
1-7	ND				
1-8	NA 				
1-9	ND				
1-10	NA				
1-11	NA				
1-12	ND				
1-13	ND ND				
1-14	ND ND				
1-15	· ND	15	40	. 500	31
Antimony	3.8	10		. 000	- 7
1-1 1-2	ND				
1-3	ND				
1-4	ND				
1-5	ND				
1-6	ND	1			
1-7	ND ND				
1-8	ND				
1-9	ND				
1-10	ND				
1-11	ND				
1-12	ND				
1-13	ND				
1-14	ND				
1-15	ND				

Constituent	Reported Concentration (ppm)	California Title 22	SFBRWQCB Environmental	California Title 22	US EPA Residential
	(βρίτη)	STLC (ppm)	Screening Levels –ESLs (ppm) 5.5	TTLC (ppm)	PRG (ppm)
Arsenic		5	5.5	500	39
1-1	5 <i>.</i> 5				
1-2	3.9				
1-3	4.1				
1-4	2.1				
1-5	3.1				
1-6	2.7				
1-7	1.6				
1-8	ND				
1-9	1.2				
1-10	1.4			n.	
1-11	1.3				
1-12	1.7				
1-13	4.2				
1-14	4.1				
1-15	4.1	100	1,500	10,000	5,400
Barium 1-1	170	100	1,000	10,000	J,+UU .
1-1	190				
1-3	180		-		
1-4	35				,
1-5	140				
1-6	45		•		
1-7	26				
1-8	35		,		
1-9	27				
1-10	46				
1-11	46		$\overline{}$		
1-12	49				
1-13	160				
1-14	170				
1-15	150				
Beryllium		0.75	8.0	75	150
1-1	ND				
1-2	ND				
1-3	ND				
1-4	ND				
1-5	ND				
1-6	- ND				
1-7	ND		·		
1-8	ND			İ	
1-9	ND				
1-10	ND ND				ļ
1-11	ND	·			
1-12	ND ND				
1-13 1-14	ND ND				
1-14	ND ND				
1-10	עאו ואט	L			

Constituent	Reported Concentration (ppm)	California Title 22 STLC (ppm)	SFBRWQCB Environmental Screening Levels –ESLs	California Title 22 TTLC (ppm)	US EPA Residential PRG (ppm)
Cadmium 1-1 1-2 1-3 1-4 1-5 1-6 1-7 1-8 1-9 1-10 1-11 1-12 1-13	1.6 1.5 1.5 1.0 1.3 1.2 0.8 0.5 0.5 0.5 0.8 1.2 0.9 1.5 1.5	1	(ppm) 7.4	100	3.7
1-15 Chromium – Total 1-1 (1) 1-1 WET 1-2 1-2 WET 1-3 1-4 1-5 1-6 1-7 1-8 1-9 1-10 1-11 1-12 1-13 1-14 (1) 1-14 WET 1-15	1.4  54 0.12 50 0.89 48 15 41 15 14 11 11 11 19 41 18 48 55 0.17 50	5		NA	210
Cobalt 1-1 (2) 1-2 (2) 1-3 (2) 1-4 1-5 (2) 1-6 1-7 1-8 1-9 1-10 1-11 1-12 1-13 (2) 1-14 (2) 1-15 (2)	14 14 14 4.7 11 7.8 3.4 3.9 3.5 5.9 8.2 9.7 13 14	80	10	8,000	4,700

Constituent	Reported Concentration (ppm)	California Title 22 STLC (ppm)	SFBRWQCB Environmental Screening Levels –ESLs (ppm)	California Title 22 TTLC (ppm)	US EPA Residential PRG (ppm)
Copper 1-1 1-2 1-3 1-4 1-5 1-6 1-7 1-8 1-9 1-10 1-11 1-12 1-13 1-14 1-15	35 30 31 11 26 15 8.3 9.1 7.5 13 17 19 27 29 27	25	230	2,500	2,900
Lead - Total 1-1 1-2 1-3 1-4 1-5 1-6 1-7 1-8 1-9 1-10 1-11 1-12 1-13 1-14	7.5 6.6 6.9 4.0 6.1 4.4 3.0 10 8.7 10 5.2 2.6 7.3 7.4 7.8	5	750	1,000	400
Molybdenum 1-1 1-2 1-3 1-4 1-5 1-6 1-7 1-8 1-9 1-10 1-11 1-12 1-13 1-14	ND ND ND ND ND ND ND ND ND ND ND ND ND N	350	40	3,500	390

Constituent	Reported Concentration (ppm)	California Title 22 STLC (ppm)	SFBRWQCB Environmental Screening Levels –ESLs	California Title 22 TTLC (ppm)	US EPA Residential PRG (ppm)
		20	(ppm) 150	2,000	1,600
Nickel	100	20	130	2,000	1,000
1-1	100				
1-2	93				
1-3	92		_		
1-4	28		-		
1-5	73	•			
1-6	28				
1-7	19		-		
1-8	16				
1-9	22				
1-10	32				
1-11	28				
1-12	40				
1-13	100				
1-14	110				
1-15	98				
Selenium		1	10	100	390
1-1	ND				
1-2	ND				
1-3	ND				
1-4	ND ND				
1-5	ND				
1-6	ND	,			
1-7	ND				
1-8	ND				
1-0	ND				
1-10	ND				
1-10	ND				
1-12	ND				
	ND				
1-13	ND ND		•		
1-14	ND				
1-15	IND	5	40	500	390
Silver	ND		.0		
1-1	ND			į	
1-2	ND		·		
1-3	ND .				
1-4					
1-5	ND ND			-	
1-6			·		
1-7	ND ND				
1-8	ND ND				
1-9	ND				
1-10	ND				
1-11	ND				
1-12	ND				
1-13	ND				
1-14	ND				
1-15	ND			L	<u> </u>

Constituent	Reported Concentration (ppm)	California Title 22 STLC (ppm)	SFBRWQCB Environmental Screening Levels –ESLs	California Title 22 TTLC (ppm)	US EPA Residential PRG (ppm)
Thallium 1-1	ND	7	(ppm) 13	700	5.2
1-2   1-3	ND ND				
1-4 1-5	ND ND				·
1-6 1-7	ND ND				
1-8	ND ND				
1-9 1-10	ND				
1-11 1-12	ND ND	:			
1-13 1-14	ND ND				
1-15	ND	24	200	2,400	550
Vanadium 1-1 1-2	25 25	24	200	2,400	
1-3 1-4	25 12 22				
1-5 1-6 1-7	22 28 11				
1-8 1-9	11 6.7				
1-10 1-11	12 28				
1-12 1-13	13 22				
1-14 1-15	22 23				
Zinc 1-1	47	250	600	5,000	23,000
1-2 1-3	42 45				
1-4	72 39				
1-6 1-7	31 20				
1-8 1-9	20 17 22				
1-10 1-11	24 26	1			
1-12	30 43				
1-14	44				
1-15	41		L	<u> </u>	L



Constituent	Reported Concentration (ppm)	California Title 22 STLC (ppm)	SFBRWQCB Environmental Screening Levels –ESLs (ppm)	California Title 22 TTLC (ppm)	US EPA Residential PRG (ppm)
Mercury 1-1 1-2 1-3 1-4 1-5 1-6 1-7 1-8 1-9 1-10 1-11 1-12 1-13 1-14 1-15	0.06 0.06 ND ND ND ND ND ND ND ND ND ND ND	0.2		20	2.3

ND Non Detectable

NA Not Applicable/Available

- (1) More than 10 times the California STLC. However, the test results are below the California TTLC, San Francisco Bay Regional Water Quality Board ESLs, and the US EPA PRG.
- (2) More than the San Francisco Bay Regional Water Quality Board ESLs. However, the test results are below the California TTLC, STLC and US EPA PRG.



June 14, 2006

City of Livermore
City Hall, Engineering Division
1052 South Livermore Avenue
Livermore, California 94550-4899

Attention:

Robert Tingley - Associate Engineering Technician

Subject:

**Environmental Sampling, Testing and Evaluation of Soil** 

Livermore Airport Jet Fuel Line Replacement

Livermore, California

CEL Proposal No. 81-01824-PW (10-00431-PW-CS)

Dear Mr. Tingley:

Pursuant to your request, Consolidated Engineering Laboratories (CEL) has provided environmental testing services for onsite soil at the subject site. CEL previously prepared a similar letter, dated December 14, 2005. The project site is located in Livermore Municipal Airport, off of Airway Boulevard, just inside the airport boundary near the airport entrance, just east of Terminal Circle in Livermore. Our representative visited the site on June 8, 2006, and collected 4 individual samples of the stockpiled pea-gravel removed from the project excavation. Samples were collected by hand throughout the stockpile.

The samples were transported to a California state-certified laboratory for testing. Proper chain-of-custody procedures were followed. The soil samples were analyzed for the presence of Volatile Organic Compounds by GC/MS (EPA 8260B), Gasoline Range Volatile Hydrocarbons as Gasoline with BTEX and MTBE (EPA 8021B/8015Cm), Diesel and Oil Range Extractable Hydrocarbons as Diesel and Motor Oil (EPA 8015C), and CAM 17 Metals (EPA 6020 B). Copies of the laboratory reports are attached.

Analytical results were compared to pertinent Soluble Threshold Limit Concentration (STLC), Total Threshold Limit Concentration (TTLC), Environmental Screening Levels (ESL's) for surface soil, and Preliminary Remediation Goals (PRG). Contaminant concentrations in soil are generally considered to be nonhazardous if they are equal or less than the TTLC, and less than 10 times the STLC as defined by the State of California, Title 22. Two other screening tools used to assess the acceptability of soils are the Preliminary Remediation Goals (PRGs) for industrial soil provided by the US EPA, and the Environmental Screening Levels provided by the San Francisco Bay Regional Water Quality Control Board for shallow soils where groundwater is not a current or potential source of drinking water (commercial/industrial land use area). The attached Table 1 summarizes the results of the analytical testing. Test results in bold indicate 2001 Crow Canyon Road, Suite 100 • San Ramon, CA 94583-5387 • Tel. 925 314-7100 • FAX 925 855-7140

Marc Hachey, P.G. 7833

**Project Geologist** 



contaminant concentrations in excess of various regulatory guidelines.

Several constituents were found to be above regulatory guidelines. The level of Arsenic in Sample 1 was 1 mg/kg higher than the allowed ESL. Total Chromium in Sample 1 was found to have a concentration 7 mg/kg higher than that allowed by the STLC. Lastly, all four pea-gravel samples had slightly more Cobalt concentration than the ESL allows.

It should be noted that the above screening tools are generally for action levels for contaminants in soil that is to remain in place, and different criteria may apply for soil that is to be transferred to or from a site. The local landfill or other location of proposed exported soil should be contacted to determine their requirements for accepting this material. The reported results are from representative samples of the soil, and do not necessarily represent the cleanliness of the entire site. These results should not be considered a clean bill of health, or prognosis of soil cleanliness. Local governing agencies may have stricter guideline standards that will govern this disposal of the soil.

We hope this provides the necessary information. If you should have any questions regarding this letter, please contact the undersigned at (925) 314-7100.

Sincerely, CONSOLIDATED ENGINEERING LABORATORIES

MH for WRS

William R. Stevens, PE 43010, GE 2339 Principal Geotechnical Engineer

Attachments: Figure 1 Site plan

Table 1 – Summary of Analytical Data McCampbell Analytical, Inc. Lab Data

Chain of Custody

Distributions: 2 plus email to Addressee, (925/960-4551, Fax 925/960-4504, rctingley@ci.livermore.ca.us)

MAH/WRS:pmf

L:\Users\Geotech\RCL-Livermore\81-01824-PW-Liver Airport\Analyt Sample Test 2.doc



TABLE 1 (Samples 1-4)
SUMMARY OF ANALYTICAL DATA

		RY OF ANALY I		· · · · · · · · · · · · · · · · · · ·	
Constituent	Reported Concentration	California Title	SFBRWQCB	California	US EPA
	(ppm)	22	Environmental	Title 22	Residential
		STLC (ppm)	Screening Levels –ESLs	TTLC (ppm)	PRG (ppm)
			(ppm)		
Gasoline Range Organic		NA	400	NA	NA
1 1	2.9		l .		
	1.7				
2 3	1.9				
4	3.5				
4	3.5				
Benzene	<del> </del>	NA	0.38	NA	NA
1	ND	IN/A	0.50	14/7	INC
1					
2	ND	i i			
2 3	ND	1			
4	ND			]	
Toluene		NA	9.3	NA	NA
1	0.06				
2	0.07			İ	
3	0.031		İ		
4	0.031			}	
7	0.001			İ	
Ethyl Benzene		NA	32	NA	NA
1	ND			1	, ,
1 2	ND				
2 3			1		
	ND				
4	ND			'	
Total Vidence		NA	2.3	NA	NA
Total Xylenes	ND	INC.	2.3	'\\	INA
1	ND				
2	ND				
3	ND				
4	ND				
Diesel Range Organics		NA	500	NA	NA
1	18		`		
2	100				
3	43				
4	16	1			
<b>"</b>	10	1			

Constituent	Motor Oil Range Organics 1	SFBRWQCB Environmental Screening Levels –ESLs (ppm)	California Title 22 TTLC (ppm)	US EPA Residential PRG (ppm)	
2 3	43 78 91		1,000	NA	NA
MTBE 1 2 3 4	ND ND	NA	5.6	NA	620
Antimony 1 2 3 4	ND ND	15	40	500	31
Arsenic 1 (2) 2 3	4.6 3.9	.5	5.5	500	39
1	140	100	1,500	10,000	5,400
Beryllium 1 2 3 4	ND ND ND ND	0.75	8.0	75	150

Constituent	Reported Concentration	California Title	SFBRWQCB	California	US EPA
	(ppm)	22	Environmental	Title 22	Residential
		STLC (ppm)	Screening Levels –ESLs (ppm) 7.4	TTLC (ppm)	PRG (ppm)
Cadmium		1	7.4	100	3.7
1	ND				
2	ND				
3	ND				
4	ND				
Chromium – Total		5	58	NA	210
1 (1)	57				
2 3 4	47				
3	40				
4	45				
Cobalt		80	10	8,000	4,700
1 (2)	12				
2 (2)	13				
3 (2) 4 (2)	12				
4 (2)	11				
Copper		25	230	2,500	2,900
1	34				
2 3 4	32				
3	26				
	25				ľ
Lead - Total		5	750	1,000	400
1 1	19				
2	17				
3	10				
4	12				
Molybdenum		350	40	3,500	390
1	ND				
2	1.2				
3 4	ND				
4	ND				
	1	L	L	1	l

Constituent	Reported Concentration (ppm)	California Title 22 STLC (ppm)	SFBRWQCB Environmental Screening Levels –ESLs (ppm)	California Title 22 TTLC (ppm)	US EPA Residential PRG (ppm)
Nickel 1 2 3	80 73 59 76	20	150	2,000	1,600
Selenium 1 2 3 4	ND ND ND ND	. 1	10	100	390
Silver 1 2 3 4	ND ND ND ND	5	40	500	390
Thallium 1 2 3 4	ND ND ND ND	7	13	700	5.2
Vanadium 1 2 3 4	51 44 64 41	24	200	2,400	550
Zinc 1 2 3 4	80 84 63 240	250	600	5,000	23,000
Mercury 1 2 3 4	0.095 0.10 0.052 0.056	0.2	10	20	2.3

ND Non Detectable

NA Not Applicable/Available

(1) More than 10 times the California STLC. However, the test results are below the California TTLC, San Francisco Bay Regional Water Quality Board ESLs, and the US EPA PRG.

(2) More than the San Francisco Bay Regional Water Quality Board ESLs. However, the test results are below the California TTLC, STLC and US EPA PRG.

(4)	7	12	Alexandra Alexandra	7. 7. 4		
NON-HAZARDOUS 1. Get WASTE MANIFEST	inerator's US EPA ID No.	Manifest Doc. No. 2. 2. 0. 2. 7	1			
Generator's Name and Melling Address CITY OF LIVERHORR 636 TERMINAL CIRCLE, LIVERHOR 4. Generator's Phone (925 ) 570-9150	E, CA. 94551					
5. Transporter 1 Company Name	6. US EPA ID		A. Transporter's		~~~	
UNIVERSAL ENVIRONMENTAL, INC. 7. Transporter 2 Company Name	C A D 9. 8. 3.		B. Transporter's	747—(	9999	
9. Designated Facility Name and Site Address ALTAMORT LARDFILL 10840 ALTAMORT PASS RD. LIVERMORE, CA. 94550-9745	10. US EPA ID		C. Facility's Pho		101	,
11. Waste Shipping Name and Description			12. Co	nteiners	13, Total	14. Unit
		······································	No.	Туре	Quantity	WW
a HOM-HAZARDOUS WASTE SOLID (SOIL)			0.0.1	DI	.18x.	T
b.						
a.						
d.						
D. Additional Descriptions for Materials Listed Above			E. Handling Cod	es for Wa	stes Listed Above	· <del>· · · · · ·</del>
(SOIL)				•	· · · · · · · · · · · · · · · · · · ·	
15. Special Handling Instructions and Additional Information PROFILE #55346800 CUSTOMER: GRITLER-RYAN	1.		······································	JOB	<b>#</b> 2027	-
WEAR APPROPRIATE PPE WHEN HAND 24HR EMERGENCY CONTACT: UE @	800-747-6609				<b>3</b> .	<u>\</u>
16. GENERATOR'S CERTIFICATION: 1 certify the materials		Support to federal regul	lations for reporting p	oper dispo		
Printed Typed Name  JAKK Rocupt for City	of Livernor From	Sara			Month Da	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Tohn 5 au len	Signature	011			Month De	y You
18. Transporter 2 Acknowledgement of Receipt of Materials	s			<del></del>	10110	
Printed/Typed Name	Signature:				Month De	y Ya
19. Discrepancy Indication Space				•		
20. Facility Owner or Operator: Certification of receipt of wa	uste materials covered by this manifer	it except as noted in i	tem 19.	٠.		
Printed/Typed Name	Signature /	1/1/		<del></del>	Month Oa	y Ye
					1/19	'   4

JS 03:28pm From-altemon. candfill

8254557383

T-799 P.001/002 F-984



Altamont Landfill & Resource Recovery Facility 10840 Altamont Fass Road Livermore, CA 94550-9745 (925) 455-7300 (925) 455-7383 Fax

December 19, 2005

Geoffery Risee Gettler Ryan Inc.

Re: City of Livermore

FAX: 916/631-1317

Approval of Profile # 55346800

Altamont Landfill & Resource Recovery Facility (Altamont) is pleased to submit this approval for non hazardous soil at the following rate:

Waste Description Class II Cover Soil Rate

No free liquids, moisture content must be less than 50%, and minimal debris.

The following conditions prevail regarding the above quoted rate:

Late fees will be assessed on balances exceeding 45 days.

All jobs must commence within 60 days of receiving this letter.

 We reserve the right to increase pricing 60 days after the date of this letter, or if waste stream conditions change.

The above rate applies to this profile, which expires on February 19, 2006. Please contact the Altamont Landfill for re-certification of this profile 30 days in advance to avoid delays.

Attached is a copy of the completed Waste Acceptance Form. Each truckload is required to have a copy of the Waste Acceptance Form when it arrives at our scale house. If you require a non-hazardous menifest to be signed, send it with the Waste Acceptance Form as we do not sign manifests at any other time.

All loads must be scheduled at least 24 hours in advance, NO EXCEPTIONS. Contact Perry at (925)455-7301, 1-800-449-6349, or email pfriddle@wm.com to schedule.

Thank you for the opportunity to provide service for your waste disposal needs. All billing questions should be addressed to Shari Laine at 925-455-7317 and other discrepancies should be addressed to Peggy Friddle at 925-455-7301

Sincerply,

Peggy Typh dene Friddle Ku Technical Spring Representative 1/5/06 mayer

Waste Acceptance Form attached.

Getler\_55346800\_letter.doc



CUSTOMER

1-ETTLER-REPN, INC.

1-TM ACCOUNTS PAYABLE

1/47 ACREPA (CURT, BUITE)

1/48 ACREPA (CURT, BUITE)

#### INVOICE

INVOICE NUMBER	lis a
INVOICE DATE	17 SC-36
PO#	5,5720.3
TERMS	NET 20
JOB NO.	2027
SALES REP.	SANCH ISLANFORD

#### **WORK PERFORMED**

PROVIDE ENDIDINGS TO TRANSPORT SOIL TO ALTAMONT LABORITY OF TRANSPORT

HIS TERMINAL LIFCLE, LIVERMORE

CIPOFREO BY, DENNIS GAN

REMIT TO: P.O. Box 996 Benicia, CA 94510

DESCRIPTION / ITEMIZATION

中はあるののでは

1/9/06

COMPANY AND SELECTION OF THE SELECTION OF THE CONTRACTOR

LOG #34169

ALFAMONT LANDFILL TICKET NO. 586778-1 NEW LATAR-COHEWARTE MANIFEST NO. 37027: DUTASION LANDFILL FICKET NO. 188676-1 DUTASIONE LANDFILL FICKET NO. 17427

15.6 段333

ALL AMONT CAME FILL TELETING COLORS (\*)
NON-HAZARDOUS WASTE MANIFEST NO. 42007
A TAMONT CANDELL TELETINO CONTROL
PERCHAZARIX SOLVASTA MANIFEST NO. 1,0027
ACTUAL MERSON ASTROPHY COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL MERSON COLORS (\*)
ACTUAL M

DISPOSAL THE IS DIRECT

10-053120-3

NOTE: In the event of an action or proceeding upon this agreement, the court shall award to the prevailing party court costs and reasonable attorney fees. Interest will be charged at the rate of 11%% per month (18% per annum) on all overdue accounts.

AMOUNT DUE

29323

### UE Universal Environmental, Inc.

4101 Industrial Way	۲.
P.O. Box 10120	
HAZARDOUS WASTE HAULIN	G

P.O. Box 996

3ox 996 Benicia, CA 94510 707 Reno, NV 89510-0120 775-351-2500

707-747-6699

REMEDIATION.

INDUSTRIAL CLEANING

DISC 3240	ICC # MC	271664	
MANIFEST#	DATE	1-9-06	
With Man 1991	P.O. #		
CONTACT	JOB#	2027	
CUSTOMER Geffler Ryan	•		
JOB LOCATION LIVERMOND AIRPORT 136 TE	۸۰۰		· · · · · · · · · · · · · · · · · · ·
Est a pursual f	CITY Livermore	·	STATE CA
SERVICES PERFORMED LOAD three Load	at Airport & 1211 LA	2 of Altonot	
			<u>:</u>
DELIVER BIN #			
PICK UP BIN #			
PRODUCT 561/ ORIGIN	Livermone	DESTINATION A	tomois_
ARRIVE JOB	ARRIVE DISPOSAL _		
DEPART JOB	DEPART DISPOSAL		
TRUCK# /143 TRAILER# 8851	START 0530 STOP	1600 TIME _	1012 HOUR
CAPACITY TIME OUT	TO	LESS _	HOUR
#LOADS 3 DM/YD/LBS/GALS	LINER 3	N/O NET _	11/12 HOUR
DISPOSAL SITE Altament	PER DIEM	TOLL	
DRIVERS NAME John Semler	LABORER		
	•		
Let Sember	•	<u> </u>	er
DRIVERS SIGNATURE	CUSTOMER	RAUTHORIZATION	

NOTE: in the event of action or proceeding upon this agreement, the court shall award to the prevailing party court costs and resonable attorney fees. Interest will be charged at the rate of 1 1/2% per month (18% per annum) on all overdue accounts.

19255517888

## LE Universal Environmental, Inc.

**GETTLER RYAN INC** 

4101 Industrial Way P.O. Box 10120

P.O. Box 996 Benicia, CA 94510 Reno, NV 89510-0120 775-

1510 707-747-6699 775-351-2500

HAZARDOUS WASTE HAULING

LOCATION: 19255517888

REMEDIATION

INDUSTRIAL CLEANING

2100 40 40		·	
DISC 3240	ICC # M	C271664	
MANIFEST# 0401 0602	DATE	9.5AN OF	
· · · · //-	P.O. #	•	
CONTACT	JOB#	2027	*
CUSTOMER COTT OF LIVERMON SINCE	ONT		
JOB LOCATION 986 TERMINAL CI	<del></del>	· · · · · · · · · · · · · · · · · · ·	1 1
CIT			STATE can
SERVICES PERFORMED Had Dirt I'm	Disposal	···········	
Traffic wreck on		Comyo	
DELIVER BIN #	<u> </u>	-61 91 ()	
PICK UP BIN#			
	envious Singent	DESTINATION	1/20 = 1 = C.
ARRIVE JOB 67/5 11/5	ARRIVE DISPOSAL		HTAMONT LANDLIN
DEPART JOB 0915 1200	DEPART DISPOSAL		
	ART AS30 STOP	1630 TIME	295 HOUR
CAPACITY Equal TIME OUT	TO:	LESS	HOUR
#LOADS / DM/YD/LBS/GALS 24		W/O NET	HOUR HOUR
DISPOSAL SITE ALTAMONT LANGEIL (Liversione	PER DIEM	TOLL	HOUR
DRIVERS NAME GLOW BLOW			
CLEND OLSEN	LABORER WAL	ren source holy	
40 M		00	· .
DRIVERS SIGNATURE	CUSTOME	P AUTUODIZATION	_
PHACHO SIGNATORE	COSTOME	R AUTHORIZATION	i '

NOTE: In the event of action or proceeding upon this agreement, the court shall award to the prevailing party court costs and resonable attorney fees. Interest will be charged at the rate of 1 1/2% per month (18% per annum) on all overdue accounts

Mark!

MASTER Altamont Landfill & RRF 40 Altamont Puss Road Jermore CA 94551

DATE: 01/09/2006 TIME IN: 11:55 TIME OUT: 11:56

TICKET: 586837-1

ARRIER: UM / Universal ennytronmental TRUCK: 1143 TRAILER#:

CUSTOMER: GETT / Gettler Ryan Inc GENERATOR: LIUCI / Livermore City of ORIGIN: LIV / Livermore City of DESTINATION: NAPUR APP APP ARMIFEST WASTE / BUCKIFFER Q PER

32027 C2C / Cies Litter Public Trail Trail Court of Court of City of Per Court of City of Per Court of City of Per Court of City of Per Court of City

My signature, as customer, confirms the information reported to the weighmaster is correct, and understand and agree to all WM rules and policies while on site.

WEIGHMASTER CERTIFICATE

THIS IS TO CERTIFY that the following described commodity was weighed, measured, or counted by a weighmaster, whose signature is on this certificate. Who is a recognized authority of accuracy, as prescribed by Chapter 7 (commencing with Section 12700) of Division 5 of the California Business and Professions Code, administered by the Division of Measurement Standards of the California

6.

MASTER Altamont Landfill & RRF .Ø Altamont Pass Road ærmore CA 94551 DATE: 01/09/2006 TIME IN: 12:36 TIME OUT: 12:36 TICKET: 586875-1 I/0: I

ARRIER: UN / Universal ennvironmental TRUCK: 1141 TRATLER#: CUSTOMER: GETT / Gettler Ryan Inc GENERATUR: LIVCI / Livermore, Lity of ORIGIN: LIV / Livermore
DESTINATION: NA ANDREADP MANIFEST WASTE / DESCRIPTION

QUE PE

DEPUTY IN: Brown Consor

ROSS: 7452 LES TARE: 36200 LES Majual Transporto LOSS - 19.10

CUSTOMER:

My signature, as oustomer, confirms the information reported to the weighnaster is correct, and understand and agree to all WM rules and policies while on site.

WEIGHMASTER CERTIFICATE

THIS IS TO CERTIFY that the following described commodity was weighed, measured, or counted by a weighmaster, whose signature is on this certificate, who is a recognized authority of accuracy, as prescribed by Chapter 7 (commencing with Section 12700) of Division 5 of the California Business and Professions Code, administered by the Division of Measurement Standards of the California Department of food and Agriculture.

PI):

WHASTER Altemont Landtill & RAF 3840 Altamont Yass Road AVarmore UA 94551

194 E: 01/09/2005 TIME IN: 09:28 Based tino onli

TICKET: 586/39-1 1/02-1

CARRIER: UN / Universal ennytronmentat TRUCK: 1143 TRALLERE! CUSTOMER: GETT / Wettlar Ryan Line

GENERATOR: LIVET / Livermore, City of ORIGIN: LIV Onore DESTINATION: NOT TON AUGUST AND AUGUST OF THE PROPERTY MANTFEST

MSTE PEES RIPTION

UEPUIT (N: Phi DEPUTY NOT: Bri

CUSTOMER:

42027

my signalians, as the same and the same is correct, and understand and agree to all im rules, and policies while on site. MERGRANDIES CERTIFICATE

INIS 15 10 CARILLY char the following described commodity was weighed, measured, or counted by a weighmenter, whose signature is on this certificate, who is a recognized authority of accuracy, is prescribed by chapter / (commencing with Section 12/60) of Division 5 of the California Business and Professions Code, administered by the Divicion of deaversment Standards of the california Department of rood and Agricusture.

Cul

.LGHMASTER Altemont Landfill & RRI .0840 Altemone Pass Road .lvermore CA 94551

OATE: 01/09/2006 TIME IN: 13:38 (IME OUT: 13:38

800

FICKET: 586914-1

bns: 12.26

CARRILE: UN / Universal ennvironmental fruck: 1143 TRALLER: CUSTOMER: BETT / Battler Ryan Inc BENERATUR: LIVE Livernose City of ORIGIN: LIV LIVERNOSE CITY of DESTINATION: MAY STUD AS MARKETEST WAS A DESTINATION OF THE CONTROL OF TH

UEPUTY IN: Broin PE OEPUTY UUT: Broin 100

OBMUTY OUT: Broom GRUSS
TARE
CUSTOMEK: Q

my signature, as customer, confirms the information reported to the velgomester is correct, and understand and agree to all WM rules and policies while on site.

WEIGHMASTER CERFIFICALE

THIS IS TO CENTERY that the rollowing described commodity was weighed, measured, or counted byea weighmaster, whose signature is on this certificate. Who is a recognized authority of accuracy, as prescribed by Chapter 7 (commencing with section 12700) of Division 5 of the California Business and Professions Code. administered by the Ulvision of Measurement Standards of the California Department of food and Agriculture.

Barrier and the same of the sa							
GU .			W				, <u>1</u>
NON-HAZARDOUS WASTE MANIFEST  1. Generator	's US EPA ID No	. / Manifest	1	Page 1 of			
Generator's Name and Mailing Address CITY OF LIVERHORE				: :			<del></del>
636 TERRITAL CIRCLE, LIVERMORE, C Generator's Phone (925 ) 570-9150	A. 94551				•	•	
Transporter i Company Name UNIVERSAL ENVIRONMENTAL, INC.	6. [C. A. D.	US EPA ID Number 9.8,3,6,5.2.2		Transporter's	Phone -747-6	699	
. Transporter 2 Company Name	8.	US EPA ID Number		Transporter	Phone		
Designated Facility Name and Site Address ALTAMORT LANDFILL	10.	US EPA ID Number	C.	Facility's Pho	one .		
10840 ALTAMONT PASS RD. LIVERMORE, CA. 94550-9745	[C. A. D.	9.8.1.3.8.2.	7.3.2		55~73		7-27
Waste Shipping Name and Description			1.0	No.	Type	13. Total Quantity~	Unit WVV
NON-HAZARDOUS WASTE SOLID (SOIL)		LIVEVIN	invie	0.01	DI	187	T
				?			
	•			1		·	
<u> </u>	·			<del>\</del>		• • • •	+
				<u>.  </u>			
Additional Descriptions for Materials Listed Above     (SOIL)			E.	Hending Co	195 TOT YV8	stes Listed Above	
			1				
is. Special Handling Instructions and Additional Information PROFILE #55346800 CUSTOMER: GETTLER-RYAN					JOB	<b>≢</b> 2027	
PROFILE #55346800 CUSTOMER: GETTLER-RYAN WEAR APPROPRIATE PPE WHEN HANDLING 24HR EMERGENCY CONTACT: UE @ 800-	-7476609						
PROFILE #55346800 CUSTOMER: GETTLER-RYAN WEAR APPROPRIATE PPE WHEN HANDLING 24HR EMERGENCY CONTACT: UE @ 800-	-747-6609 sed above on this n	landest are not aubject to to	oderál regulation	us for reporting			y Yeu
PROFILE #55346800 CUSTOMER: GETTLER-RYAN WEAR APPROPRIATE PPE WHEN HANDLING 24HR EMERGENCY CONTACT: UE @ 800- 16. GENERATOR'S CERTIFICATION: I certify the materials describ Printed Typed Name    ALK ROLLA     17. Transporter 1 Acknowledgement of Receipt of Materials Printed Typed Name	-747-6609		deral regulation	us for reporting		sal of Hezardous W	7 0.1
PROFILE #55346800 CUSTOMER: GETTLER-RYAN WEAR APPROPRIATE PPE WHEN HANDLING 24HR EMERGENCY CONTACT: UE @ 800- 16. GENERATOR'S CERTIFICATION: I certify the meterials describ Printed/Typed Name  JACK ROCLAN 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name  JOHN Sanden	-747-6609	gnaturely	ederal regulation	a for reporting		sal of Hazardous W Month Da Of O	7 0.5
PROFILE #55346800 CUSTOMER: GETTLER-RYAN  WEAR APPROPRIATE PPE WHEN HANDLING 24HR EMERCENCY CONTACT: UE & 800-  16. GENERATOR'S CERTIFICATION: I certify the materials describ Printed/Typed Name    ALK ROCAN  17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name  18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name  19. Discrepancy Indication Space	-747-6609	gnature of the second	derial regulation	us for reporting		sal of Hezardous W  Month Da  O() O  Monds Da  (0) O	7 0
PROFILE #55346800 CUSTOMER: GETTLER-RYAN  WEAR APPROPRIATE PPE WHEN HANDLING 24HR EMERGENCY CONTACT: UE @ 800-  16. GENERATOR'S CERTIFICATION: I certify the materials describ Printed/Typed Name    ACK ROCCA       Printed/Typed Name   Tokk Sander   18. Transporter 2 Acknowledgement of Receipt of Materials   Printed/Typed Name   19. Discrepancy Indication Space	-747-6609  red above on this n	gnature ( )	lambe			sal of Hezardous W  Month Da  O() O  Monds Da  (0) O	7 0
PROFILE #55346800 CUSTOMER: GETTLER-RYAN  WEAR APPROPRIATE PPE WHEN HANDLING 24HR EMERGENCY CONTACT: UE & 800-  16. GENERATOR'S CERTIFICATION: I certify the materials describ  Printed/Typed Name  JOHN Semice  18. Transporter 2 Acknowledgement of Receipt of Materials  Printed/Typed Name  19. Discrepancy Indication Space  19. Discrepancy Indication Space	od above on this n	gnature () y this manifest except as	lambe		proper dispo	sal of Hezardous W  Month Da  O() O  Monds Da  (0) O	7 0.5 7 0.5 9 0
WEAR APPROPRIATE PPE WHEN HANDLING 24 HR EMERGENCY CONTACT: UE 8 800-  16. GENERATOR'S CERTIFICATION: I certify the materials describ Printed/Typed Name  17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name  18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name  19. Discrepancy Indication Space	od above on this n	gnature ( )	lambe		proper dispo	sal of Hazardous W  Month Da  Of O  Month Da  Month Da	9 9

	C.	,		ાત		S. M. C.		
	NON-HAZARDOUS WASTE MANIFEST	1. Generalor's US EPA I		Manifest Doc. No. 7 · 2 · 0 · 2 · 7	2. Page 1 of	:		
.(	Generator's Name and Mailing Address CITY OF LIVERHORE 636 TERMINAL CIRCLE, LIVER 4. Generator's Phone (925 ) 576-9150		551	,				
	5. Transporter 1 Company Name UNIVERSAL KHVIRONMKHTAL,	INC. C. A	US EPA ID N	umber 5, 2, 2, 7, 2	A. Transports	rs Phone 7-747-6	699	
	7. Transporter 2 Company Name	8.   .	US EPA ID N		B. Transporte	r's Phone		
	9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT PASS ED.	10.	US EPA ID N	umber	C. Facility's P	hone		
	LIVERMORE, CA. 94550-974	5   C. A	D 9 8 1 3	8, 2, 7, 3, 2	925	<b>-455</b> -73	01	:
	11. Waste Shipping Name and Description		•		12. N	Containers  Type	13. Total Quantity	14. Unit W/Vol
	- NON-HAZARDOUS WASTE SOLID (SOIL)	·						
	(3011)			, 	0.0	TOI	GL.4.15	T
GMZ	b		٠					
E A A	G	<u></u>	<u>-</u>					:
ÖR						. 3		
	d.	:	·	•				
	Additional Descriptions for Materials Listed Above (SOIL)				E. Handling C	odes for Wa	ites Listed Above	
	15. Special Handling Instructions and Additional Information PROFILE #55346800 CUSTOMER: GETTLER-RYAN	mation .			<u>L.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	JOB	<b>≸</b> 2027	
	WEAR APPROPRIATE PPE WHEN 1 24HR EMERGENCY CUNTACT: U	RANDLING E @ 800-747-60	60 <del>9</del>		٠	*;		
	16. GENERATOR'S CERTIFICATION: 1 certify the m	aterials described above on t		bject to tederal regula	tions for reporting	proper dispo	ral of Hazardous Wa	rie.
¥	Printed Typed Name  JACK KOWAN FOR CITY		Signiture	Din			Month Day	10p Non
Ā	<ol> <li>Transporter 1 Acknowledgement of Receipt of Me Printed/Typed Name</li> </ol>	aterials _	Signature				Month Day	Your
2402	6/600 OLSON  18. Transporter 2 Acknowledgement of Receipt of Ma	Jarinie	Des	n Ols	<u> </u>		19/149	106
HE CEMPORTHE	Printed/Typed Name	ridi)dis	Signature	;			Month Day	Year
	19. Discrepancy Indication Space	i				<del></del>		
#40-L		٠.		. •				
	20. Facility Owner or Operator: Certification of receip	t of waste materials cover	ed by this manifest e	xcept as noted in ite	am 19.			
177	Printed/Typed Name		Signature	nBr	<i></i>		Month Day	Year
1		TRAK	ISPORTER #1					

	, i			۰ •						Ţ,
NON-HAZARDOUS WASTE MANIFEST	1. Generator's US			Manifest Doc.		Page 1	BiGE?∜			
Generator's Name and Malling Address CITY OF LIVERSORE 636 TERMINAL CIRCLE, LIVE 4. Generator's Phone (925) 570-9150				[8.2.0.2.	1		<u>.                                    </u>	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	
5. Transporter 1 Company Name UNIVERSAL ENVIRONMENTAL,	······································	6.	US EPAID N	lumber 5, 2, 2, 7	2 A.	Transporte	r's Phone 7—747—	6600		
7. Transporter 2 Company Name		8. I	US EPA ID N			Transporté		A Para de Mariantes		
Designated Facility Name and Site Address     ALTAMONT LANDFILL		10.	US EPA ID N	lumber	C.	Facility's P	hone			
10840 ALTAMONT PASS RD. LIVERMORE, CA. 94550-974	5	C A D	9, 8, 1, 3	, 8, 2, 7, 3,	2	925-	-455-7:	301		
11. Waste Shipping Name and Description			•			12.	Containers . Type	13. Total Quanti	l W	14. Unit
a. NON-HAZARDOUS WASTE SOLID (SOIL)				<b></b>	w			666		T
b.		······································					<del>-   -</del>	727		Ľ
. محمد 6.		• •					<u>.  </u>	<u> </u>		
u.	٠.				·					
d.									1	
D. Additional Descriptions for Materials Listed Above	· ·	<u> </u>			E	Handling Co	des for We	stes Listed A	bove	
(SOIL)	:					٠	٠.	•		
15. Special Handling instructions and Additional Infor PROFILE #55346800 CUSTOMER: GETTLER—RYAN	mation						JOB	<b>#2027</b>		
WEAR APPROPRIATE PPR WHEN E 24HR EMERGENCY CONTACT: UE		<b>/-</b> 6609			,			in the second se		
16. GENERATOR'S CERTIFICATION: I certify the ma	terials described abov			bject to rederal reg	ulations	for reporting	proper dispo	Bal of Hazardo	us Wasie.	<u> </u>
Printed/Typed Name JACK ROWA		Sign	Pel	Character 1	_<	<b>&gt;</b>		Month	Day 1	/84I
17. Transporter 1 Acknowledgement of Receipt of Mat Printed/Typed Name GLUN OLSON	terials	Sign	aturey	in Ol	Para	<u> </u>	······································	Month (D)		oar
18. Transporter 2 Acknowledgement of Receipt of Mal	terials			<del></del>		<u> </u>		14/1	4 719	
Printed/Typed Name		Sign	alure		<del>,,,,</del>			Month ·	Day Y	oar •
19. Discrepancy Indication Space				,						
20. Facility Owner or Operator: Certification of receipt	of waste materials o	covered by th	ls manifest ex	copt as noted in	item 1:	9.	· · · · · · · · · · · · · · · · · · ·		•	
Printed/Typed Name	· • • • • • • • • • • • • • • • • • • •	Sign	atere	14				Hong	Day Y	7
	TI	RANSPO	RTER #1	· · · · · · · · · · · · · · · · · · ·			Versy.			

#### **APPENDIX B**

Drilling Permit Exploratory Boring Logs

# ONE OF THE PARTY O

#### **ZONE 7 WATER AGENCY**

100 NORTH CANYONS PARKWAY, LIVERMORE, CALIFORNIA 94551 VOICE (925) 454-5000 FAX (925) 454-5728

#### DRILLING PERMIT APPLICATION

FOR APPLICANT TO COMPLETE	FOR OFFICE USE
LOCATION OF PROJECT Livermore Airport Terminal Circle at Airport Blud Livermore Lat 37.695 Long 121.815 California Coordinates Source ft. Accuracy the APN ft. CCE ft.	PERMIT NUMBER 27059 WELL NUMBER APN PERMIT CONDITIONS
CLIENT	(Circled Permit Requirements Apply)
CLIENT CITY of LIVERIAL Address 1052 SCIVERIAL ADDRESS 1052 SCIPPING 1	A. GENERAL  1. A permit application should be submitted so as to arrive at the Zone 7 office five days prior to proposed starting date.  2. Submit to Zone 7 within 60 days after completion of permitted work the original Department of Water Resources Water Well Drillers Report or equivalent for well projects or drilling logs and location sketch for geotechnical projects.  3. Permit is void if project not begun within 90 days of approval date.  B. WATER SUPPLY WELLS  1. Minimum surface seal thickness is two inches of cement grout placed by tremie.  2. Minimum seal depth is 50 feet for municipal and industrial wells.
PROPOSED WELL USE New Domestic	is specially approved.  3. An access port at least 0.5 inches in diameter is required on the wellhead for water level measurements.  4. A sample port is required on the discharge pipe near the wellhead.  C. GROUNDWATER MONITORING WELLS INCLUDING PIEZOMETERS  1. Minimum surface seal thickness is two inches of cement grout placed by tremie.  2. Minimum seal depth for monitoring wells is the maximum depth practicable or 20 feet.  D. GEOTECHNICAL. Backfill bore hole with compacted cuttings or heavy bentonite and upper two feet with compacted material. In areas of known or suspected contamination, tremied cement grout shall be used in place of compacted cuttings.
SOIL BORINGS Number of Borings 10 Hole Diameter in. Depth in. Number US  SOIL BORINGS Number of Borings 10 Hole Diameter in. Depth 30 Hole Diameter in. Depth 30 ESTIMATED STARTING DATE April 2 2007 ESTIMATED COMPLETION DATE April 4, 2007	E. CATHODIC. Fill hole above anode zone with concrete placed by tremie.  WELL DESTRUCTION. See attached.  SPECIAL CONDITIONS. Submit to Zone 7 within 60 days after the completion of permitted work the well installation report including all soil and water laboratory analysis results.
I hereby agree to comply with all requirements of this permit and Alameda County Ordinance No. 73-68.  APPLICANT'S SIGNATURE CHIPALLY FOR CEL, Date March 26, 20  Chris Palmer	Approved Mill Mill Date 3/30/07  Wyman Hong Date 3/30/07

ATTACH SITE PLAN OR SKETCH

Revised: April 27, 2005

Project No.81-01824-A Logged by: CMP BORING NO. B-1 Date: April 2, 2007

Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc. 26' Static: 22?

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe

BOREHOLE COMPLETION:

Well Installed: No Total Depth: 32'

Sample No.	PID /OV	Contin. Rush/	oa E Deptl	Lithology Log	Well Detail/ Backfill
			<b>—</b>	Asphalt	1,22
B-1 to 4'	0		#	CL - Sandy CLAY, dark brown 10YR3/3, fmed. sand 30-40%, low plasticity, stiff, damp.	
B-1 to 8'	0		- 5	Same as above, increasing sand.	
B-1 to 12'	0		10	SW - SAND with Clay, brownish yellow 10YR6/6, clay up to 20%, low plasticity, fcrs. sand 80%, rare fine gravel, med. dense, damp.	
B-1 to 16'	0		15	Same as above, fcrs. sand, clay decreases occurs as matrix, color change to light yellowish brown 10YR6/4, dense, damp.	
B-1 to 20'	0			CL - Sandy CLAY, dark yellowish brown 10YR4/4, fmed. sand 30-40%, clay lean, low plasticity, 60-70%, med. stiff, damp.	
B-1 to 24'	0		20	CL - Sandy CLAY, grayish brown 2.5YR5/2, f. sand 5-15%, clay low plasticity, 75%+, med. stiff, damp.	
B-1 to 28'	0		25	Increase in fmed. sand to 45%, med. stiff, moist.  Becomes very moist to saturated at about 26 feet.	
B-1 to 32'	0		30	SW - SAND, grayish brown 2,5YR4/2, fcrs. sand 90%, fines 10% and slightly plastic, dense, saturated.	
			E	CL - Sandy CLAY, dark grayish brown 2.5YR4/2, fmed. sand 15-25%, clay low plasticity, stiff ,damp.	
			35	Bottom of Boring =32 feet Water enters borehole slowly	
				Reviewed by PG	

Project No.81-01824-A BORING NO. B-2 Logged by: CMP Date: April 2, 2007

Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc: 26.5' Static: NM

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well Installed: No Total Depth: 32'

Sample No.	PID /OV	Contin. E Push/ E Core	Depth	Lithology Log	Well Detail/ Backfill
				Asphalt	ۯ؞ۯ
B-2 to			$\Box$		1 22
4'	0			CL - CLAY, dark yellowish brown 10YR3/4, f. sand 20%, low plasticity, lean, stiff, damp.	
}			4—1	om, damp.	
			1-5		
B-2 to 8'	0		<del> </del>	CL - Sandy CLAY, dark yellowish brown 10YR3/4, fcrs. sand 40%, rare gravel	
Ĭ			1	clay 60% lean low plsticity, stiff, damp.	
				Sand content varies from about 45-65% at 8 feet, stiff, damp.	
B-2 to 12'	0		10	SC-SW - Clayey SAND to SAND interbedded, brown 10YR5/2, fcrs. sand 70-90%, clay varies 10-30%, lean low plasticity, rare gravel, dense, damp.	
			泪	olay valies 10-50%, learn low plasticity, rate graves, defise, damp.	
			$\overline{\mathbf{I}}$	Same as above, less med. crs. sand, lenss of sand 2-4 inches thick, dense,	2.2
B-2 to	0			damp.	
16'			15		
			III.	Pushes hard 16-20 feet.	
B 244			$\mathcal{H}$	T dolloo hard To 20 feet.	
B-2 to 20'	0		<del>/  </del>		
			<del>}                                    </del>	SP - SAND, grayish brown 10YR5/2, f. sand 80-90%, fines 10-20%, nonplastic to slighlty plastic, dense, damp.	
			20	to slightly plastic, defise, damp.	
B-2 to	0		$\square$		
24'					_   ^^^
1			$\vdash$	SP-SC - SAND and Clayey SAND, grayish brown 10YR5/2, f. sand 70-90%,	
Date			25	clay/fines low plasticity lean, dense, damp to very moist.	
B-2 to 28'	0		<b>/▼</b>	CL - CLAY, yellowish brown 10YR5/6, v. f. sand<5%, stiff, damp.	
			H	Sand interbed about 26 to 28 feet, saturated, low core recovery.	
			1		
B-2 to			3.	Sand interbed fines 10-15%, sand 85%, dense saturated at	
32'	0		30	31.5-31.8, then clay as above, not saturated 31.8-32, stiff, damp.	
			$\bot$		
				. ·	
			35	Bottom of Boring = 32 feet	
				Water enters borehole slowly, some collapse or swell 28-32 feet,	
				sampled with Hydropunch	
1					
				Paviound by DC	
	<u> </u>			Reviewed by PG	

Project No.81-01824-A BORING NO. B-3 Logged by: CMP BORING NO. B-3

Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc: 25' Static: 25'?

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well Installed: No Total Depth: 28'

Sample No.	PID /OV	Contin. De De Core	oth Lithology Log	Well Detail/ Backfill
			Concrete	2.2
B-3 to 4'	0	<i> </i>  2 -		
"	U	[2]-	CL - Sandy CLAY, dark yellowish brown 10YR3/4, f. sand 15-20%, low plasticity lean clay, med. stiff, damp.	
		l <del>K4</del> -	lean day, med. sun, damp.	
B-3 to	_		Same as above, thin sand beds 2-4 inches thick with crs. sand, o/w med.	
8'	0		stiff, damp.	
1			Increse in sand at 8 feet, pushes hard 8-12 feet, stiff, damp.	
			- In south at 8 1884, pastion hard 8 12 1881, suit, damp.	
B-3 to 12'	0	10		
'~			SW - SAND, light yellowish gray 10YR6/2, fcrs. sand 90%, fines slightly	
		124	plastic, may contain very thin clay beds 1-2 inches thick, very dense, damp.	
B-3 to	0			1 22
16'	Ū	15		
			SC - Clayey SAND. brown 10YR5/2, f. sand 75%, lean low plasticity clay 25%,	
D 24a		<i> </i>  /_	faint bedding, very dense, damp.	1 22
B-3 to 20'	0			
		20	Same as above, less and, clay inc. to 40%, possible caliche, very dense, damp.	1 22
B-3 to	0			٦٩٩
24'			Same as above, inc. in sand to 75%, then transition to underlying straum, dense, damp.	1 2
				<b>-  </b>   ∴
B-3 to		25	CL - Silty CLAY, brown 10YR5/2, lean, no sand, stiff, damp.	
28'	0		SW-SC - SAND and Clayey SAND, brown 10YR4/3, fmed. sand 70-80%, clay lean low plasticity 20-30%, dense, saturated.	22
			CL - CLAY, brown 10YR4/3, f. sand<5%, clay lean low plasticity, stiff, damp.	<b>1</b>   ##
				7 -
		30		
		-	-	
			1	
		35		
			Bottom of Boring = 28 feet  Water enters borehole slowly	
		-	<del>-</del>	
	-		<del>-</del>	
			Reviewed by PG	1

Project No.81-01824-A BORING NO. B-4 Logged by: CMP Date: April 3, 2007

Logged by: CMP Date: Ap Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc. 25' Static: NM

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well Installed: No Total Depth: 32'

Sample No.	PID /OV	Contin. Push/ Core	Samp	Depth	Lithology Log	Well Detai Backfill
<b>-</b>					Asphalt	
B-4 to 4'	0				CL - Silty CLAY, brown 10YR5/6, v.f. sand <5%, clay lean low platicity, med.	
					stiff, damp.	
			1	<del></del> 5		
B-4 to 8'	0					
O					OW CAND I I WOOD I I WOULD I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN IN I WOULD IN IN I WOULD IN IN IN I WOULD IN IN I WOULD IN IN I WOULD IN IN IN IN I WOULD IN IN IN IN IN IN IN IN IN IN IN IN IN	
					SW - SAND, pale brown 10YR6/4, fcrs. sand 90%, fines 10% and nonplastic, rare gravel, massive, dense damp.	2.2
B-4 to	0			10	Same as above, crude crs. sand grain-sized defined bedding, nonplastic fines,	
12'					very dense, damp.	
			К			٦٩٩
B-4 to	0					
16'				15	Same crude grain-sized defined bedding, very dense, damp.	
			$\mathbb{N}$		CL - Silty CLAY, brown 10YR4/3, clay low plasticity lean 90%, v.f. sand 10%,	
B-4 to	0				caliche(?), hard, damp.	
20'	U					1,2,2
			4	20	Same as above, massive clay, v.f. sand inc. to 10-15%, pushes hard 20-24 feet.	
					ourne as above, massive day, v.r. saint inc. to 10-10-70, pusites hard 20-24 leet.	
B-4 to 24'	0				Conduction Clause Condition and Circles High at CO 5 CO 5 at a few and	200
					Sandy Clay to Clayey Sand interbed 6 inches thick at 22.5-23 feet, o/w same clay below 23 feet, stiff to hard, damp.	2.2
				25		
B-4 to 28'	0				SC - Clayey SAND, gray 10YR5/1, fmed sand 70%, clay 30%, low plasticity,	
20					very dense, very moist to saturated.	
B-4 to					Borehole collapses to 17 feet after recovery of 25 foot sample. Use Hydropunch	^^^
32'	0			30	for water sample, push tool to 32 feet, then pull back to 27 for water entry.	2.2
Hydropunci	١ .					
				35		
					Bottom of Boring = 32 feet Water enters borehole slowly	
İ					vvaler efficis poreficie slowly	
		ļ				
					Reviewed by PG	

Project No.81-01824-A Logged by: CMP

BORING NO. B-5 Date: April 3, 2007

Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc: 24.5' Static: NM

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well Installed: No Total Depth: 32'

Sample No.	PID /OV	Contin. ED Core	epth	Lithology Log	Well Detail/ Backfill
				Asphalt	
B-5 to 4'	0			CL - Sandy CLAY, dark yellowish brown 10YR3/4, lean low plasticity, v.f. sand <5%, med. stiff, damp.	
B-5 to 8'	0		- 5	CL - Sandy CLAY, brown, 10YR4/3, f. crs. sand 20%, gravel 1%, clay lean low plasticity 80%, massive to crudely bedded, stiff, damp.	
B-5 to 12'	0		10	SW - SAND, grayish brown 10YR5/2, f. crs. sand 85%, f. gravel 5%, fines 10% nonplastic to slighlty plastic, very dense, damp.	
B-5 to 16'	0		15	CL - Silty CLAY, yellowish brown 10YR5/4, low-mod. plasticity, v.f. sand <5%, dissem. in clay, minor caliche, hard, damp.	
B-5 to 20'	0		20	Same as above, pushes hard, no caliche, hard, damp.	
B-5 to 24'	0		25	CL-SC - Sandy CLAY to Clayey SAND, dark grayish brown 10YR4/2, fmed. sand 40-70%, fines 40-70% varies, low plasticity, locally contains 2-4 inch thick sand beds at 23-24 feet, hard to dense, damp, moist at 24 feet	
B-5 to 28'				SP - SAND, dark grayish brown 10Yr4/3, sand 95%, nonplastic fines 5%, massive to faint bedding, very dense saturated.	
B-5 to 32' Hydropunc	n I		30	Borehole collapses at 8 feet, use Hydropunch to collect water sample, push to 32 feet, pull back to 27 feet to collect sample.	
			35	Bottom of Boring =32 feet Water enters borehole slowly	
				Reviewed by PG	

BORING NO. B-6

Logged by: CMP Date: April 3, 2007 Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Project No.81-01824-A

Water Levels: 1st Enc: 27'? Static: 24'

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well Installed: No Total Depth: 36'

Sample No.	PID /OV	Contin. E	Depth	Lithology Log	Well Detail/ Backfill
				Asphalt	2.2
B-6 to 4'	0	[/	4—1	CL - Silty CLAY, brown 10YR4/3, f. crs. sand 5%, clay lean low plasticity,	
· ·			$\mathcal{H}$	stiff, damp.	2,2
			5		^^^
B-6 to	0		1,1		
8'			+	SW-SC - SAND and Clayey SAND, dark grayish brown 10YR4/2, .f-crs. sand 60-75%	
			$\vdash$	fines 25-40% slight to low plasticity, dense, damp.	
B-6 to	0		10		22
12'	ľ		<b>4</b> "		
		K	<del>1  </del>		
B-6 to			$\vdash$	CL - Silty CLAY, dark yellowish brown 10YR4/6, low-mod. plasticity, v.f. sand 5%,	
16'	0		15	some caliche. hard, damp.	2.2
		Q	7 '°	Same as above, light tan mottles and caliche(?), f. sand to 10%, hard, damp.	
			<b>3—</b> 1		
B-6 to 20'	0		H		
			<b>1</b>	Operation where the stand FOV commence with the stand of the standard stand	
			20	Same as above, v.f. sand 5%,, some very thin sandy zones 18-24 feet, very slow push at 20 feet	2,2
B-6 to 24'	0		1—1	3 inch thick f. med. sand bed at 23-23.3 feet, hard, damp, becomes damp	22
24			} <u> </u> {	to moist at 24 feet.	20
	ļ.				
B-6 to	0		25	CL - Sandy CLAY, yellowish brown 10YR5/4, f. sand 30%, clay 70% low plasticity	
28'			<b>/</b>	lean, massive, hard, damp to moist; pushes very hard to 27 feet.	
		l K	+		22
B-6 to			1	CO OL Claver CAND to Cond. Clave in the condition of the	
32'	0		30	SC-CL - Clayey SAND to Sandy CLAY, yellowish brown10YR5/4, vf. f. sand 50-75%, fines/clay 25-50% low plasticity lean, local thin sand beds, hard to	
			1	dense, damp to slightly moist.	
B-6 to			1		
36'	0			CL - Sandy CLAY, brown 10YR4/3, f. sand 10-30%, dissem. in clay, clay 70%	
			35	low plasticity, hard, damp.	
					] —
				Bottom of Boring = 36 feet Water enters borehole slowly	
				Tratel effects potential slowly	
			40		
				Positive d has DO	
	1			Reviewed by PG	

Project No.81-01824-A BORING NO. B-7 Logged by: CMP Date: April 3, 2007

Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc: 25.5' Static: 23.5'

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well installed: No Total Depth: 32'

Sample No.	PID /OV	Contin. Push/ Core	Dept	h Lithology Log	Well Detail Backfill
			71_	Asphalt	2.2
B-7 to 4'	0			CL - Silty CLAY, brown 10YR4/3, f. crs. sand 5%, clay lean low plasticity, stiff, damp.	
B-7 to 8'	0		5	SW-SC - SAND and Clayey SAND, dark grayish brown 10YR4/2, f. crs. sand varies 60-80%, clay 20-40% low plasticity, dense, damp.	
B-7 to 12'	0		10	Same as above, locally crs. gravel 10%, f. crs. sand 80-85%, fines <5-10%, very dense, damp.	
B-7 to 16'	0		15	CL - Silty CLAY, yellowish brown 10YR5/6, low-mod. plasticity, f. sand 10-20% dissem. in clay, hard, damp.  Same as above, minor tan mottles, caliche infilled fractures, hard, damp.	
B-7 to 20'	0				
B-7 to 24'	0		20	Sand interbed 4-6 inch thick at 23.5 feet, inc. sand from 25-30%, hard, damp.	
B-7 to 28'	0		25€	CL - Sandy CLAY, brown 10YR4/3, f. sand 30-40%, dissem. in clay, clay low plasticity, hard, damp. Sandy interbed damp to moist.  CL - CLAY, brown 10YR4/3, sandy beds from 25-26 feet, clay low plasticity lean, hard, damp.	
B-7 to 32'	0		30	Same as above, sandy interbed sturated at 28.5-29 feet, then clay damp.	
			35	Bottom of Boring = 32 feet Water enters borehole slowly	
				Reviewed by PG	

Project No.81-01824-A BORING NO. B-8 Logged by: CMP Date: April 4, 2007

Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc: 24' Static: 24?

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well Installed: No Total Depth: 32'

Sample No.	PID /OV	Contin. 2	Depth	Lithology Log	Well Detail/ Backfill
				Asphalt	٦٠٦
B-8 to 4'	0		#	CI - Sandy CLAY, brown 10YR4/3, f. sand 20%, clay 80%, low plasticity, massive, hard, damp.	
B-8 to 8'	0		-5	Same as above, med. sand 15-20%, color change to dark yellowish brown 10YR3/4, lean, sandy interbed at 6 feet, hard, damp.	
B-8 to 12'	0		10	SC-SW - Clayey SAND to SAND, brown 10YR5/3, f. crs. sand 90%, fines 10% slightly plastic, crs. sand beds 0.2-1.0 inches thick from 11-14 feet, dense, damp.	
B-8 to 16'	0		15	Same as above, faint bedding, rare fine gravel, sand 80-90%, fines 10-20% are slighlty plastic, dense damp.	
B-8 to 20'	0		20	CL - Silty CLAY, yellowish brown 10YR5/4, lean low plasticity, v.f. sand 10%, caliche, stiff to hard, damp.	
B-8 to 24'	0			Same as above, v.f. sand 5%, massive, stiff, damp to moist at about 24 feet.	
B-8 to 28'	0		25	SP - SAND, yellow brown 10YR5/4, f. sand 90%, fines 10% slightly plastic, thin clay beds at 24-26 feet intebedded with sand, med. dense, saturated.	
B-8 to 32' Hydropunci	0		30	Insufficient yield of water, push Hydropunch to 32 feet collect water sample.	
			35	Bottom of Boring = 32 feet Water enters borehole slowly	ائدا
				Reviewed by PG	

Project No.81-01824-A BORING NO. B-9 Logged by: CMP Date: April 4, 2007

Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc: 25' Static: 22'

#### **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well Installed: No Total Depth: 32'

Sample No.	PID /OV	Contin. Push/ Core	B Depth		Well Detail/ Backfill
B-9 to 4'	0			Asphalt  CL - Sandy CLAY, dark yellowish brown 10YR3/4, f. med. sand 30-40%, massive, stiff, damp.  Sand inc. to near 50% at 5 feet.	
B-9 to 8'	0		5	SC-SW - Clayey SAND to SAND, varigated to gray 10YR5/1, fcrs. sand 70-90%, fines 10-30% and slighlty plastic, dense, damp.	
B-9 to 12'	0		10	Same as above, local fine gravel beds, crudely bedded crs. sand strata, very dense, damp.	
B-9 to 16'	0		15	Same as above, massive fcrs sand beds, very little fines, then sharp contact.	
B-9 to 20'	0		20	CL - Sandy CLAY, dark yellowish brown 10YR4/4, low plasticity lean, v.f. sand 10-20%, very faint bedding at 16 feet, stiff, damp; pushes hard 16 19 feet.  Same as above, stiff, damp.	
B-9 to 24'	0			SC-SP - Clayey SAND to SAND, dark yellowish brown 10YR4/4, f. sand 75-90%,	
B-9 to 28'	0		25	fines 10-25% clay low plasticity, massive, dense, damp.  Same as above, interbeds of SP sand very moist to saturated, SC clayey SAND damp to moist.	
B-9 to 32'	0		30	CL - Sandy CLAY, yellow brown 10YR4/6, low to mod. plasticity, v.f. sand 10-20%, stiff, damp.	
			35	Bottom of Boring = 32 feet Water enters borehole slowly	
				Reviewed by PG	

# Consolidated Engineering Laboratories, Inc.

Project No.81-01824-A BORING NO. B-10 Logged by: CMP Date: April 4, 2007

Client: City of Livermore Airport Location: Fuel Pipeline and USTs

Permit: Zone 7 #27059

Water Levels: 1st Enc: 25' Static: NM

# **Exploratory Boring Log**

Page 1 of 1

Drilling Method: GeoProbe BOREHOLE COMPLETION:

Well Installed: No Total Depth: 32'

Grout Seal: 32' to Surface

Sample No.	PID /OV	Contin. Push/ Core	Sample	Depth	Lithology Log	Well Detail/ Backfill
					Asphalt	2,2
B-10 to 4'	0				CL - Sandy CLAY, brown 10YR4/3, f. sand 20-30%, clay 70-80% lean low	
	_				plasticity, massive, stiff, damp.	
				<del>-</del> 5	color change to very dark brown 10YR2/2, v.f. sand 15%, massive, stiff, damp.	
B-10 to 8'	0					
<b>1</b> 2404					Same as above, crs. sand interbed 3 inches thick at 1 feet, inc. in sand overall,	1,24
B-10 to 12'	0			10	stiff, damp.	
			$\mathbb{Z}$		SC - Clayey SAND, yellowish brown 10YR5/8, f. med. sand 70-80%, clay/fines	
B-10 to					20-305, low plasticity, dense damp.	
16'	0			15	CL - Silty CLAY, dark yellowish brown 10YR4/6, low-mod. plasticity, some caliche,	
1			$\searrow$	13	f. sand 10%, stiff to hard, damp.	
B-10 to				$\vdash$	Same as above, v.f. sand 20-25% dissem. in clay, stiff to hard, damp.	
20'	0					
			$\mathbb{K}$	20		
B-10 to	0				In according and to provide 500% of 50	2,2
24'					Increasing sand to nearly 50%, stiff, damp.	
B-10 to	0			<del>25</del> ▼	SC-SP - Clayey SAND to SAND, yellowish brown 10YR5/6, f. sand 60-90%, clay 10-40% low plasticity, dense, damp to moist.	2,2
28'					10-40% fow plasticity, defise, damp to moist.	2,2
			$\vdash$		hin clay interbeds and saturated sand beds , clay decreases to 10%, vf. f. sand	
B-10 to 32'	n			30	90%, water entry into borehole very slow.	
Hydropunc		į			Hydropunch to 32 feet to collect sufficient yield for samples.	
1						ا تنا ا
				35	Bottom of Boring = 32 feet Water enters borehole slowly	
					vvaler enters buteriole slowly	
				<u> </u>		
				-	Reviewed by PG	

# **APPENDIX C**

Chemical Analytical Data Chain-of-Custody

Consolidated Engineering Laborat	Client Project ID: #81-01824-A; Livermore	Date Sampled:	04/02/07
2001 Crow Canyon Road, Suite	Airport-Pipeline	Date Received:	04/02/07
100 San Ramon, CA 94583	Client Contact: Chris Palmer	Date Reported:	04/06/07
builtuiioi, oli 71000	Client P.O.:	Date Completed:	04/06/07

WorkOrder: 0704022

April 06, 2007

Dear Chris:

#### Enclosed are:

- 1). the results of 11 analyzed samples from your #81-01824-A; Livermore Airport-Pipeline project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Best regards,

Angela Rydelius, Lab Manager

Consolidated Eng 2001 Crow Canyon San Ramon, CA 94	Road, S	<i>-</i>		orie	es,	inc.													of Custody
Ph. 925/314-7100 Fx. 925/855-7140	000														ı				<u>il2,2007</u> 51-01824-A
Project name: <u>Livlu</u>	ore Aiv	port-	ز D	pel	<u>lin</u>	e					.4				F	ag	e_		of
Relinquished by: (IM) Received by: Suk at Date received: 4/2/07  Print name: Ombalan Print name:  Company name: Canolidatul Enga Labola Lab name: McCanylell Time received: 15/5  Leuk at 4/2 (8:3:																			
Special Instructions  N-5 day  Please check on TPND row  Jet fuel			per of samples	Tum Around Time	Analysis Requested	TPWG/BJEX/MT8E+	8015; 8260B	TPHDiesel 8015											Recieved in good condition  Yes No  Total # of Samples
Sample I.D. Dat	Time	Matrix	En Z	TuT	Anaf	HOT		Ha.F.											. Comments
B-1-2=2.5 4/2/ B-1-2=8.5-8 (1 B-1-3c/12-12)	0900	50il	1	N N								<b>-</b>							HOU)
B-1-4e16.5-16	0920		1	N						_					1				MOLD
B-1-5019520	0930		1	1/		_		/				$\Box$							
B-1-6c28.5-24 B-1-7c28.5-28	0945	<del>                                     </del>	-	N		-			$\vdash$	$\dashv$	_	$\dashv$		_	$\dashv$				HOLD
R-1-8c345-32 V	1040	V	İ	N			Z			士									
B-1 water 26-28 4121	77 1010	water	4	N									- 1	E'C.	49	ου Έπ ΔΕ	0 IV SEM 0	✓ CAR	APPROPRIATE  CHARLES IN LAB  PRINCE OF LAB

. f3()

vier: 40 valle mei valles 4/2/07 MAI

Consolidated I 2001 Crow Can San Ramon, CA	yon	Road, S			orie	<b>&gt;</b> S,	inc	;.								D	ate	: <u>A</u>	pn	of Custody
Ph. 925/314-71 Fx. 925/855-71				digwa Alex		·	سيدعد	acus.			······································	ne de la constante de la const			·					1-01824-A _of
Project name: Li	ver	nore A	rport	- p	;pe	ln	٤.							_		-				
Relinquished by: Print name; Company name;	COAS	MPalm MPalm Vidatal Es	ago, Los	<u>bs</u>	Re P L	ab ı	ived nati nan	ne:		M/8	lri cCi	k any	(C)							: <u>4/2/67</u> :: <u>1515</u>
Special Instructions N-5-doug Please sheds on The Jetfuel		ruge fo		ber of samples	Around Time	Analysis Requested	CA/BTEX/ATOR	5015;8260	TAMBLESEL BOIS					:						Recieved in good condition Yes No Total # of Samples
Sample I.D.	Date	Time	Matrix	Num	Tum	Anal	Mar	678	MOL										-[	. Comments
B-2-103.5-4.0	4/2/0	7 1115	Soil	1																
B-2-207.5-80		1120		1					/	1_										
B-2-3011.5-12	<u> </u>	1130					_	ļ.,	_	<u> </u>				 			$\perp$	_		
B-2-4015.5-160		1135	<del>                                     </del>	11		<u> </u>			$\angle$	1_							$\dashv$	_	_	
B-2-5019-5-200		1150		11		<u> </u>	<u> </u>	ļ_		ļ				 			$\dashv$	_	$\dashv$	
B-2-60235-24		1205		11		<u> </u>	_	<u> </u>		<u> </u>				 		.	_		_	
B·2-7027.5-28		1220		<u>  '</u>	_	ļ	1		$\bigvee$	1_							$\dashv$	_	_	
B-2 water c 28-32	4/2/0	7 1245	wester	4													-			

ver: 4/2/07

£36



1534 Willow Pass Rd Pittsburg, CA 94565-1701 (925) 252-9262

# **CHAIN-OF-CUSTODY RECORD**

Page 1 of 1

5 days

WorkOrder: 0704022

ClientID: CEL

☐ EDF

Fax

✓ Email

HardCopy

☐ ThirdParty

Requested TAT:

Report to:

Chris Palmer

Consolidated Engineering Laboratori 2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Email: cp@ce-labs.com TEL:

925,485,5000

FAX: 925.485.5019

ProjectNo: #81-01824-A; Livermore Airport-Pipelin

PO:

Bill t

Accounts Payable

Consolidated Engineering Laboratori

2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

ap@ce-labs.com

Date Received 04/02/2007

Date Printed: 04/02/2007

				[				Req	uested	Tests	(See le	gend b	elow)			
Sample ID	ClientSampID	Matrix	Collection Date	Hold	1	2	3	4	5	6	7	8	9	10	11	12
0704022-001	B-1 @ 2-2.5	Soil	04/02/07 9:00:00		Α	T	Α	<u> </u>		Γ		1	_	T	<u> </u>	T —
0704022-003	B-1-3 @ 11.5-12	Soil	04/02/07 9:10:00		Α		Α						1			†
0704022-005	B-1-5 @ 19.5-20	Soil	04/02/07 9:30:00		Α		Α									
0704022-007	B-1-7 @ 27.5-28	Soil	04/02/07 10:00:00		Α		Α				1	<u> </u>				<del> </del>
0704022-008	B-1-8 @ 31.5-32	Soil	04/02/07 10:40:00		Α		Α									<u> </u>
0704022-009	B-1 Water 26-28'	Water	04/02/07 10:10:00			Α	·	В				1		1"		<b></b>
0704022-010	B-2-1 @ 3.5-4.0	Soil	04/02/07 11:15:00		Α		Α									1
0704022-011	B-2-2 @ 7.5-8.0	Soil	04/02/07 11:20:00		Α		Α							1		
0704022-013	B-2-4 @ 15.5-16.0	Soil	04/02/07 11:35:00		A		Α					-	1			
0704022-016	B-2-7 @ 27.5-28'	Soil	04/02/07 12:20:00		Α		Α									
0704022-017	B-2 Water @ 28-32'	Water	04/02/07 12:45:00			Α		В		···-						<b>†</b>

#### Test Legend:

1 G-MBTEX_S	2 G-MBTEX_W	3 MBTEXOXY-8260B_S	4 MBTEXOXY-8260B_W	5
6	7	8	9	10
11	12			

The following SampIDs: 0704022-001A, 0704022-003A, 0704022-005A, 0704022-007A, 0704022-008A, 0704022-009A, 0704022-010A, 0704022-011A, 0704022-013A, 0704022-016A, 0704022-017A contain testgroup.

Prepared by: Melissa Valles

#### **Comments:**

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.

Comments:

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

# Sample Receipt Checklist

Client Name:	Consolidated Engineering Labor	atories	Date and	Time Received: 04/02/07	7:26:21 PM
Project Name:	#81-01824-A; Livermore Airport	Pipeline	Checklist	completed and reviewed by:	Melissa Valles
WorkOrder N°:	0704022 Matrix Soil/Water		Carrier:	Courier	•
	Cha	in of Custody (CO	C) Information	<u>n</u>	
Chain of custod	y present?	Ye 🔽	No 🗆		
Chain of custody	y signed when relinquished and received?	Ye 🔽	No □		
Chain of custody	y agrees with sample labels?	Ye 🗹	No 🗌		
Sample IDs note	d by Client on COC?	Ye 🔽	No 🗆		
Date and Time o	f collection noted by Client on COC?	Ye 🗹	No 🗆		
Sampler's name	noted on COC?	Ye 🗹	No 🗆		
		Sample Receipt In	<u>iformation</u>		
Custody seals in	stact on shippping container/cooler?	Ye 🗆	No 🗆	NA 🔽	
Shipping contain	er/cooler in good condition?	Ye 🔽	No 🗆		
Samples in prop	er containers/bottles?	Ye 🗹	No 🗆		
Sample containe	ers intact?	Ye 🗹	No 🗆		
Sufficient sample	e volume for indicated test?	Ye 🗹	No 🗆		
	Sample Pres	ervation and Hold	Time (HT) Inf	ormation	
All samples rece	ived within holding time?	Ye 🗹	No 🗆		
Container/Temp	Blank temperature	Cooler Temp: 4	I.9°C	na 🗆	
Water - VOA via	ls have zero headspace / no bubbles?	Ye 🗹	No 🗆 No	VOA vials submitted $\Box$	
Sample labels cl	necked for correct preservation?	Ye 🗹	No 🗌		
		,			
		·			
Client contacted:	Date conta	cted:		Contacted by:	



"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

Client Project ID: #81-01824-A; Livermore
Airport-Pipeline

Date Sampled: 04/02/07

Date Received: 04/02/07

Client Contact: Chris Palmer

Date Extracted: 04/02/07-04/04/07

Client P.O.:

Date Analyzed 04/03/07-04/04/07

# Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline with BTEX and MTBE\*

Extracti	on method SW5030B		Anal	ytical methods SV	V8021B/8015Cm			Work Orde	r: 070	4022
Lab ID	Client ID	Matrix	TPH(g)	MTBE	Benzene	Toluene	Ethylbenzene	Xylenes	DF	% SS
001A	B-1 @ 2-2.5	S	ND	ND	ND	ND	ND	ND	1	86
003A	B-1-3 @ 11.5-12	S	ND	ND	ND	ND	ND	ND	1	92
005A	B-1-5 @ 19.5-20	S	ND	ND	ND	ND	ND	ND	1	96
007A	B-1-7 @ 27.5-28	S	ND	ND	ND	ND	ND	ND	I	97
008A	B-1-8 @ 31.5-32	S	ND	ND	ND	ND	ND	ND	1	101
009A	B-1 Water 26-28'	w	ND	ND	ND	ND	ND	ND	1	90
010A	B-2-1 @ 3.5-4.0	S	ND	ND	ND	ND	ND	ND	1	96
011A	B-2-2 @ 7.5-8.0	S	ND	ND	ND	ND	ND	ND	1	93
013A	B-2-4 @ 15.5-16.0	S	ND	ND	ND	ND	ND	ND	1	82
016A	B-2-7 @ 27.5-28	S	ND	ND	ND	ND	ND.	ND	1	79
017A	B-2 Water @ 28-32'	w	ND	. ND	ND	ND	ND	ND	1	91
								!		
		ļ							<u> </u>	
									<u> </u>	
	···									
-	orting Limit for DF =1;	W	50	5.0	0.5	0.5	0.5	0.5	1	μg/L
	means not detected at or ove the reporting limit	S	1.0	0.05	0.005	0.005	0.005	0.005	1	mg/Kg

<sup>\*</sup> water and vapor samples and all TCLP & SPLP extracts are reported in µg/L, soil/sludge/solid samples in mg/kg, wipe samples in µg/wipe, product/oil/non-aqueous liquid samples in mg/L.

<sup>#</sup> cluttered chromatogram; sample peak coelutes with surrogate peak.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (stoddard solvent / mineral spirit?); f) one to a few isolated non-target peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) reporting limit raised due to high MTBE content; k) TPH pattern that does not appear to be derived from gasoline (aviation gas). m) no recognizable pattern; n) TPH(g) value derived using a client specified carbon range; o) results are reported on a dry weight basis; p) see attached narrative.



"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824-A;
Livermore Airport-Pipeline

Date Sampled: 04/02/07

Date Received: 04/02/07

Date Extracted: 04/02/07-04/04/07

Client P.O.:

Date Analyzed: 04/03/07-04/04/07

	Client P.	O.:		Date Analyzed:	04/03/07-0	4/04/07	
	• •	ates and BTEX b	•				
Extraction Method: SW5030B		lytical Method: SW826		I	Work Order:	0704022	
Lab ID	0704022-001A	0704022-003A	0704022-005A	0704022-007A			
Client ID	B-1 @ 2-2.5	B-1-3 @ 11.5-12	B-1-5 @ 19.5-20	B-1-7 @ 27.5-28	Reporting		
Matrix	S	S	S	S	DF =1		
DF	1	. 1	1	1	S	W	
Compound		Conc	entration		mg/kg	μg/L	
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	0.5	
Benzene	ND	ND	ND	ND	0.005	0.5	
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0	
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5	
Ethylbenzene	ND	ND	ND	ND	0.005	0.5	
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5	
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5	
Toluene	ND	ND	ND	ND	0.005	0.5	
Xylenes	ND	ND	ND	ND	0.005	0.5	
	Surr	ogate Recoveries	s (%)				
%SS1:	103	100	101	100			
%SS2:	108	107	107	106			
%SS3:	113	114	113	114			
Comments							

<sup>\*</sup> water and vapor samples are reported in μg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in μg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824-A; Livermore Airport-Pipeline

Client Contact: Chris Palmer

Client P.O.:

Date Sampled: 04/02/07

Date Received: 04/02/07-04/04/07

Date Extracted: 04/02/07-04/04/07

2	Client P.	O.:		Date Analyzed:	04/03/07-0	4/04/07
	Oxygen	ates and BTEX b	y GC/MS*			
Extraction Method: SW5030B	Ana	lytical Method: SW826	0B		Work Order:	0704022
Lab ID	0704022-008A	0704022-009B	0704022-010A	0704022-011A		
Client ID	B-1-8 @ 31.5-32	B-1 Water 26-28'	B-2-1 @ 3.5-4.0	B-2-2 @ 7.5-8.0	Reporting	
Matrix	S	W	S	S	DF	=1
DF	1	1	1	1	S	W
Compound		Conce	entration		mg/kg	μg/L
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	0.5
Benzene	ND	ND	ND	ND	0.005	0.5
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5
Ethylbenzene	ND	ND	ND	ND	0.005	0.5
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5
Toluene	ND	ND	ND	ND	0.005	0.5
Xylenes	ND	ND	ND	ND	0.005	0.5
	Surr	ogate Recoveries	s (%)			
%SS1:	99	111	100	96		
%SS2:	105	97	105	105		-
%SS3:	110	105	108	110		
Comments						

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824-A;
Livermore Airport-Pipeline

Date Sampled: 04/02/07

Date Received: 04/02/07

Client Contact: Chris Palmer

Date Extracted: 04/02/07-04/04/07

Client P.O.:

Date Analyzed: 04/03/07-04/04/07

# Oxygenates and BTEX by GC/MS\*

Extraction Method: SW5030B	Ana	ytical Method: SW820	0B	Work Order:	0704022
Lab ID	0704022-013A	0704022-016A	0704022-017B		
Client ID	B-2-4 @ 15.5-	B-2-7 @ 27.5-	B-2 Water @ 28-	Reporting	
Matrix	S	S	w	DF :	=1
DF	1	1	. 1	S	W
Compound		Conc	entration	mg/kg	μg/L
tert-Amyl methyl ether (TAME)	ND	ND	ND	0.005	0.5
Benzene	ND	ND	ND	0.005	0.5
t-Butyl alcohol (TBA)	ND	ND	ND	0.05	5.0
Diisopropyl ether (DIPE)	ND	ND	ND	0.005	0.5
Ethylbenzene	ND	ND	ND	0.005	0.5
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	0.005	0.5
Methyl-t-butyl ether (MTBE)	ND	ND	ND	0.005	0.5
Toluene	ND	ND	ND	0.005	0.5
Xylenes	ND	ND	ND	0.005	0.5
	Surre	ogate Recoveries	s (%)		· · · · · · ·
%SS1:	95	94	113		
%SS2:	105	105	97		
%SS3:	109	107	107		
Comments					

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



"When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories 2001 Crow Canyon Road, Suite 100

Client Project ID: #81-01824-A; Livermore Airport-Pipeline

Date Sampled: 04/02/07

Client P.O.:

Date Received: 04/02/07

San Ramon, CA 94583

Client Contact: Chris Palmer

Date Extracted: 04/02/07

Date Analyzed 04/03/07-04/04/07

## Diesel (C10-23) and Jet Fuel (C9-C18) Range Extractable Hydrocarbons as Diesel and Jet Fuel\*

Extraction method: S	W3510C/SW3550C	Analytical m	ethods: SW8015C	Wor	k Order: 0	704022
Lab ID	Client ID	Matrix	TPH(d)	TPH(jf)	DF	% SS
0704022-001A	B-1 @ 2-2.5	S	1.0,g,b	ND	1	92
0704022-003A	B-1-3 @ 11.5-12	S	ND	ND	1	108
0704022-005A	B-1-5 @ 19.5-20	S	ND	ND	1	108
0704022-007A	B-1-7 @ 27.5-28	S	ND	ND	1	107
0704022-008A	B-1-8 @ 31.5-32	S	ND	ND	1	106
0704022-009A	B-1 Water 26-28'	w	84,g,b	53	1	90
0704022-010A	B-2-1 @ 3.5-4.0	S	ND	ND	1	107
0704022-011A	B-2-2 @ 7.5-8.0	s	ND	ND	1	108
0704022-013A	B-2-4 @ 15.5-16.0	S	ND	ND	1	108
0704022-016A	B-2-7 @ 27.5-28'	S	ND	ND	1	103
0704022-017A	B-2 Water @ 28-32'	w	100,b	81	1	100
				·		
·						
	orting Limit for DF =1;	w	50	50	με	g/L
i e	eans not detected at or ve the reporting limit	S	1.0	1.0	mg	/Kg

<sup>\*</sup> water samples are reported in µg/L, wipe samples in µg/wipe, soil/solid/sludge samples in mg/kg, product/oil/non-aqueous liquid samples in mg/L, and all DISTLC / STLC / SPLP / TCLP extracts are reported in  $\mu$ g/L.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified diesel is significant; b) diesel range compounds are significant; no recognizable pattern; c) aged diesel? is significant); d) gasoline range compounds are significant; e) unknown medium boiling point pattern that does not appear to be derived from diesel; f) one to a few isolated peaks present; g) oil range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; k) kerosene/kerosene range; l) bunker oil; m) fuel oil; n) stoddard solvent/mineral spirit.



<sup>#</sup> cluttered chromatogram resulting in coeluted surrogate and sample peaks, or; surrogate peak is on elevated baseline, or; surrogate has been diminished by dilution of original extract.

# QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704022

EPA Method SW8021B/8015Cm	Extraction SW5030B				Ва	tchID: 27	165	Sp	Spiked Sample ID: 0703731-015A			
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	
, many to	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(btex <sup>f</sup>	ND	0.60	93	91.6	1.55	96.8	97.4	0.545	70 - 130	30	70 - 130	30
MTBE	ND	0.10	85.4	79.4	7.28	85.4	84.9	0.542	70 - 130	30	70 - 130	30
Benzene	ND	0.10	91.2	87.8	3.79	90.5	91	0.581	70 - 130	30	70 - 130	30
Toluene	ND	0.10	91.8	88.8	3.33	91.3	92	0.721	70 - 130	30	70 - 130	30
Ethylbenzene	ND	0.10	98	94.9	3.27	98.1	97.6	0.532	70 - 130	30	70 - 130	30
Xylenes	ND	0.30	110	107	3.08	110	110	0	70 - 130	30	70 - 130	30
%SS:	84	0.10	86	83	3.48	80	83	3.72	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27165 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-001A	04/02/07 9:00 AM	04/02/07	04/03/07 4:17 PM	0704022-003A	04/02/07 9:10 AM	04/02/07	04/03/07 4:48 PM
0704022-005A	04/02/07 9:30 AM	04/02/07	04/03/07 5:49 PM	0704022-007A	04/02/07 10:00 AM	04/02/07	04/03/07 11:24 PM
0704022-008A	. 04/02/07 10:40 AM	04/02/07	04/03/07 11:55 PM				i

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.



# QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704022

EPA Method SW8021B/8015Cm	Extra	ction SW	5030B		BatchID: 27231			Sp	Spiked Sample ID: 0704022-016A			
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)
· · · · · · · · · · · · · · · · · · ·	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(btex <sup>£</sup>	ND	0.60	112	97	13.9	102	108	5.89	70 - 130	30	70 - 130	30
MTBE	ND	0.10	111	120	7.88	107	105	1.86	70 - 130	30	70 - 130	30
Benzene	ND	0.10	95.2	102	6.79	93.9	92.5	1.47	70 - 130	30	70 - 130	30
Toluene	ND	0.10	90	90.2	0.181	86.2	84.8	1.62	70 - 130	30	70 - 130	30
Ethylbenzene	ND	0.10	97.2	97.3	0.115	94.4	94.7	0.326	70 - 130	30	70 - 130	30
Xylenes	ND	0.30	94.4	87.7	7.25	91.3	92	0.727	70 - 130	30	70 - 130	30
%SS:	79	0.10	87	107	20.3	97	102	4.46	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27231 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-010A	04/02/07 11:15 AM	04/02/07	04/04/07 2:27 AM	0704022-011A	04/02/07 11:20 AM	04/02/07	04/04/07 2:53 AM
0704022-013A	04/02/07 11:35 AM	04/02/07	04/04/07 3:27 AM	0704022-016A	04/02/07 12:20 PM	04/02/07	04/04/07 4:00 AM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.



1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com

Telephone: 877-252-9262 Fax: 925-252-9269

## QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704022

EPA Method SW8021B/8015Cm	Extraction SW5030B				BatchID: 27221			Sp	Spiked Sample ID: 0704024-002A			
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	
	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(btex <sup>f</sup>	ND	60	97.8	98.2	0.470	110	110	0	70 - 130	30	70 - 130	30
МТВЕ	ND	10	81	89.2	9.70	119	124	4.05	70 - 130	30	70 - 130	30
Benzene	ND	10	88.1	94.3	6.75	95.7	102	5.94	70 - 130	30	70 - 130	30
Toluene	ND	10	88.3	95	7.27	106	111	4.87	70 - 130	30	70 - 130	30
Ethylbenzene	ND	10	92.9	97.3	4.66	103	106	3.42	70 - 130	30	70 - 130	30
Xylenes	ND	30	103	110	6.25	113	117	2.90	70 - 130	30	70 - 130	30
%SS:	90	10	91	92	0.486	95	99	3.44	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27221 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-009A	04/02/07 10:10 AM	04/04/07	04/04/07 9:31 PM	0704022-017A	04/02/07 12:45 PM	04/04/07	04/04/07 10:04 PM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = <math>100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.



## QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704022

EPA Method SW8260B	Extra	ction SW	/5030B		Bat	chID: 27	207	Spiked Sample ID: 0703763				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acce	eptance	Criteria (%)	)
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	0.050	101	98.4	2.83	96.6	97.6	1.00	70 - 130	30	70 - 130	30
Benzene	ND	0.050	107	107	0	106	106	0	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	0.25	96	100	4.18	95.4	94.4	1.03	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	0.050	115	114	1.70	112	112	0	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND.	0.050	108	105	2.64	102	103	0.957	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	0.050	108	105	2.64	102	104	1.62	70 - 130	30	70 - 130	30
Toluene	ND	0.050	96.9	94.6	2.39	94.3	93.8	0.485	70 - 130	30	70 - 130	30
%SS1:	97	0.050	97	97	0	97	98	0.162	70 - 130	30	70 - 130	30
%SS2:	102	0.050	100	99	0.926	99	99	0	70 - 130	30	70 - 130	30
%SS3:	93	0.050	107	108	0.739	107	107	0	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27207 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-001A	04/02/07 9:00 AM	04/02/07	04/03/07 7:34 PM	0704022-003A	04/02/07 9:10 AM	04/02/07	04/03/07 8:18 PM
0704022-005A	04/02/07 9:30 AM	04/02/07	04/03/07 9:04 PM	0704022-007A	04/02/07 10:00 AM	04/02/07	04/03/07 9:51 PM
0704022-008A	04/02/07 10:40 AM	04/02/07	04/03/07 10:39 PM	0704022-010A	04/02/07 11:15 AM	04/02/07	04/04/07 1:00 AM
0704022-011A	04/02/07 11:20 AM	04/02/07	04/04/07 1:47 AM	0704022-013A	04/02/07 11:35 AM	04/02/07	04/04/07 2:35 AM
0704022-016A	04/02/07 12:20 PM	04/02/07	04/04/07 3:21 AM				<b>'</b>


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com

Telephone: 877-252-9262 Fax: 925-252-9269

## QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704022

EPA Method SW8260B	Extra	ction SW	5030B		Ва	tchID: 27	217	Spiked Sample ID: 0704012-006B				16B
Anaiyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)
	µg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	10	106	108	1.50	95.8	99.2	3.50	70 - 130	30	70 - 130	30
Benzene	ND	10	115	113	1.99	107	109	2.48	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	50	98.6	94.2	4.49	96.3	93.6	2.91	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	10	122	122	0	112	115	2.10	70 - 130	30	70 - 130	30
Ethanol	ND	500	101	96.6	3.98	94.8	96.9	2.09	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	10	114	114	0	103	107	3.85	70 - 130	30	70 - 130	30
Methanol	ND	2500	102	100	1.78	101	101	0	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	10	113	114	0.737	101	106	4.46	70 - 130	30	70 - 130	30
Toluene	ND	10	95.7	98	2.38	92.6	93.6	1.09	70 - 130	30	70 - 130	30
%SS1:	101	10	104	98	5.29	98	98	0	70 - 130	30	70 - 130	30
%SS2:	100	10	98	98	0	98	98	0	70 - 130	30	70 - 130	30
%SS3:	110	10	106	107	1.14	108	108	0	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### **BATCH 27217 SUMMARY**

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-009B	04/02/07 10:10 AM	04/04/07 .	04/04/07 1:40 AM	0704022-017B	04/02/07 12:45 PM	04/04/07	04/04/07 2:26 AM

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



## QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704022

EPA Method SW8015C	Extra	Extraction SW3550C				BatchID: 27193			Spiked Sample ID: 0703752-005A				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)		
7 thatyto	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD	
TPH(d)	6800	20	NR	NR	NR	98.7	98.5	0.162	70 - 130	30	70 - 130	30	
%SS:	104	50	105	93	12.4	100	100	0	70 - 130	30	70 - 130	30	

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### **BATCH 27193 SUMMARY**

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-001A	04/02/07 9:00 AM	1 04/02/07	04/04/07 12:33 AM	0704022-003A	04/02/07 9:10 AM	04/02/07	04/03/07 7:56 PM

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

QA/QC Officer

# QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704022

EPA Method SW8015C	Extra	ction SW	/3550C		Bat	chID: 27	232	Sp	iked Sam	ple ID:	0704022-01	6A
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	e Criteria (%)	)
Analyto	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(d)	ND	20	101	101	0	113	114	0.772	70 - 130	30	70 - 130	30
%SS:	103	50	103	103	0	114	122	7.15	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### **BATCH 27232 SUMMARY**

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-005A	04/02/07 9:30 AM	04/02/07	04/03/07 9:04 PM	0704022-007A	04/02/07 10:00 AM	04/02/07	04/03/07 10:12 PM
0704022-008A	04/02/07 10:40 AM	04/02/07	04/03/07 11:21 PM	0704022-010A	04/02/07 11:15 AM	04/02/07	04/04/07 12:29 AM
0704022-011A	04/02/07 11:20 AM	04/02/07	04/04/07 1:37 AM	0704022-013A	04/02/07 11:35 AM	04/02/07	04/04/07 2:46 AM
0704022-016A	04/02/07 12:20 PM	04/02/07	04/04/07 12:29 AM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com

Telephone: 877-252-9262 Fax: 925-252-9269

# QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder 0704022

EPA Method SW8015C	Extra	ction SW	/3510C		Bat	chID: 27	211	Sp	iked Samı	ole ID:	N/A	
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	
7 thatyto	μg/L	µg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(d)	N/A	1000	N/A	N/A	N/A	114	111	2.50	N/A	N/A	70 - 130	30
%SS:	N/A	2500	N/A	N/A	N/A	110	111	0.719	N/A	N/A	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### **BATCH 27211 SUMMARY**

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-009A	04/02/07 10:10 AM	04/02/07	04/04/07 2:54 AM	0704022-017A	04/02/07 12:45 PM	04/02/07	04/03/07 11:21 PM

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

QA/QC Officer

Consolidated Engineering Laborat	Client Project ID: #81-01824-A; Livermore	Date Sampled:	04/02/07
2001 Crow Canyon Road, Suite	Airport-Pipeline	Date Received:	04/02/07
100 San Ramon, CA 94583	Client Contact: Chris Palmer	Date Reported:	04/06/07
San Kamon, CA 94303	Client P.O.:	Date Completed:	04/16/07

WorkOrder: 0704022

April 16, 2007

Dear Chris:

#### Enclosed are:

- 1), the results of 2 analyzed samples from your #81-01824-A; Livermore Airport-Pipeline project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Best regards,

Angela Rydelius, Lab Manager

Consolidated E 2001 Crow Can San Ramon, CA	yon R	oad, S	<b>Labor</b> uite 10	ato 0	orie	s,	lnc	•												_	of Custody
Ph. 925/314-710 Fx. 925/855-714					····			-	***************************************					***************************************	-		F	roj	. Ne	o. <u>8</u>	TI-01824-A
Project name: <u>Liv</u>	linor	e Air,	oort-	<i>(ز (</i> ل)	rel	1/h	e				····		4		- 		-	ag	e _		_ of
Relinquished by: Print name: Company name:	CY / I A	レンスリ メス・レ	f		-	rınt	กฉก	ne.		M		le le									d: <u>4/2/07</u> d: <u>1515</u>
Special Instructions N-5 day Please check on TPN! Jet fuel	تستك	7		ber of samples	Around Time	Analysis Requested		+		Diesel 8015	meoth, equth, 1.210CA anded										Recieved in good condition Yes No Total # of Samples
Sample I.D.	Date	Time	Matrix	Num	Tum	Anah		TPM		TON	Hoard								·		Comments
B-102=25	4/2/07	0900	Soil	١	N						X		$\bot$	$\Box$							
B-1-2@8.5-8		0905		<del></del>	N								_	$\dashv$	_	_				_	HOU)
B-1-3c125-12 B-1-4c155-16		0910		1	N			_	_		X	+	$\dashv$	$\dashv$					-	_	WOLD
B-1-50 195-20		0930		li	11					/	X		十								
B-1-6028.5-24		0945		ī	N																HOLD
B-1-7cz#5-28		1000		I	N						X										
R-1-80315-32	V	1040	V	L	N						X		$\dashv$	$\dashv$	_						<u> </u>
B-1 water 26-29'	412/07	1010	water	4	N			_			X	+	1		]	TEVL COOK SF AL	4C SSN	F Ai	SEN OIN	√ <u>√</u> AB.	APPROPRIATE CONTINUES PRESERVED IN LAB

vier: 40 Valle mei, Valles 4/2/07 MAI

130

RESURVATION VOAS (186)

Consolidated E 2001 Crow Can San Ramon, CA	yon F	load, S	<b>Labo</b> uite 10	rato	orie	25,	Inc	<b>.</b>			•					- 1				of Custody
Ph. 925/314-716 Fx. 925/855-714			and the second s			-		<b>A</b> irice -			<del>dan 's Cl</del> i						Proj	. No	3. <u>8</u>	0f
Project name: Li	ivern	rore Ai	rport	- P	je	lu	٤.				<u> </u>									
Relinquished by: Print name: Company name;	COASO	Palme NPalm idated to	gr. Loss	75	Re P L	ab i	ived nam	ne::			•	k (s	hel							: <u>4/2/67</u> :: <u>1515</u>
Special Instructions N-5-doug Please check on The Jetfuel		uge fo		ber of samples	Around Time	rsis Requested	G/BTEX/MTGE	5015; 8260	TAMBIESEL BOIS	. CHOIT, 1.2DCA MODER										Recieved in good condition  Yes No  Total # of Samples
Sample I.D.	Date	Time	Matrix	N Engl	Tum	Anah	MRI	848	MOL	meat.										. Comments
B-2-103.5-4.0	4/2/07	1115	Soil	1				1		X										
B-2-207.5-80		1120		1				K	/	<u>1×</u>				$\bot$						
B-2-30 11.5-12		1130			<u> </u>	_	_	ļ.,		_			_ -	_	_		<u> </u>			
B-2-4015.5-160		1135		1	_	<del> </del>		1	$\angle$	<u>1×</u>			4	$\dashv$	_					
B-2-5019.5-20.0		1150		11	<u> </u>	<u> </u>	<u> </u>	_	<u> </u>	<u> </u>	<b> </b>		4	4	4					
B-2-6023.5'-24'		1205		1-	_	_		<u> </u>	<u> </u>	_			$\bot$	4	_					
B.2-7 c 27.5-28		1220		1	_	_	1	1	$\bigvee$	<u>]×</u>			4	_	_	_	<u> </u>			
B-2 water c 28-32	4/2/07	1245	wester	4					Z	X				+						
	<del>                                     </del>	1	<del>                                     </del>	+-	T	1	+-	<b>†</b>	1	T			$\neg$	十	十		$T^-$			

vec: Me Vall 4/2/07

+30



1534 Willow Pass Rd

# **CHAIN-OF-CUSTODY RECORD**

Page 1 of 1

	g, CA 94565-1701 52-9262			e e	7	VorkO	rder:	070402	2 <b>A</b>		Client	ID: CE	L				
(923) 2.	32 7202			☐ EDF		Excel		Fax		<b>✓</b> Emai	l	☐ Hard	Сору	∏Thi	rdParty		
	d Engineering Laboratori Canyon Road, Suite 100	TEL: 92	@ce-labs.c 5.485.5000 31-01824-A;			19	Co 20 Sa	onsolida 01 Crov in Ram	Payabl ated En w Cany on, CA ıbs.com	gineeri on Roa 94583	-		1	Date A	ted TA eceive dd-On: rinted:	04/02 04/12	1/2001
				•					Req	uested	Tests	(See le	gend b	elow)			
Sample ID	ClientSampID	ı	Matrix	<b>Collection Date</b>	Hold	1	2	3	4	5	6	. 7	8	9	10	11	12
0704022-009	B-1 Water 26-28	3'	Water	4/2/07 10:10:00		С								T			
0704022-017	B-2 Water @ 28-3	32'	Water	4/2/07 12:45:00		С		<u></u>	l	<u> </u>	<u> </u>	<u> </u>			Ţ <u>.</u>		
Test Legend:  1 9-0X 6 11	7 12			8				9						5 10	Malice		

Comments:

Etoh, Meoh, and 1,2 DCA added 4/10/07 per C.P.

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.



1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories	Client Project ID: #81-01824-A;	Date Sampled: 04/02/07
2001 Crow Canyon Road, Suite 100	Livermore Airport-Pipeline	Date Received: 04/02/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/12/07
Surraunon, Crivisco	Client P.O.:	Date Analyzed 04/12/07

#### Oxygenated Volatile Organics + EDB and 1,2-DCA by P&T and GC/MS\*

On J Bonne	ca vomene Organ	ines . LDD and 1,	Dering i are	ind GC/MG		
Extraction Method: SW5030B	Ana	lytical Method: SW826	0B		Work Order:	0704022
Lab ID	0704022-009C	0704022-017C				
Client ID	B-1 Water 26-28'	B-2 Water @ 28- 32'				Limit for
Matrix	W	W				
DF	1	1			S	w
Compound		Conce	entration		ug/kg	μg/L
1,2-Dichloroethane (1,2-DCA)	ND	ND			NA	0.5
Ethanol	ND	ND			NA	50
Methanol	ND	ND			NA	500
	Surr	ogate Recoveries	s (%)			
%SS1:	96	95				
Comments						

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; J) analyte detected below quantitation limits; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824-A;
Livermore Airport-Pipeline

Date Sampled: 04/02/07

Date Received: 04/02/07

Client Contact: Chris Palmer

Date Extracted: 04/02/07

Client P.O.:

Date Analyzed: 04/03/07-04/04/07

Oxygenates and BTEX by GC/MS\* Extraction Method: SW5030B Analytical Method: SW8260B Work Order: 0704022 Lab ID 0704022-001A 0704022-003A 0704022-005A 0704022-007A B-1 @ 2-2.5 B-1-3 @ 11.5-12 | B-1-5 @ 19.5-20 B-1-7 @ 27.5-28 Client ID Reporting Limit for DF =1 Matrix S S S S DF 1 1 1 1 S W Compound Concentration mg/kg ug/L tert-Amyl methyl ether (TAME) ND ND ND ND 0.005 NA Benzene ND ND ND ND 0.005 NA ND t-Butyl alcohol (TBA) ND ND ND 0.05 NĄ 1,2-Dichloroethane (1,2-DCA) ND ND ND ND 0.005 NA Diisopropyl ether (DIPE) ND ND ND ND 0.005 NA ND Ethanol ND ND ND 0.25 NA Ethylbenzene ND ND ND ND 0.005 NA Ethyl tert-butyl ether (ETBE) ND ND ND ND 0.005 NA ND ND ND ND 2.5 NA Methyl-t-butyl ether (MTBE) ND ND ND 0.005 ND NA Toluene ND ND ND ND 0.005 NA **Xylenes** ND ND ND ND 0.005 NA Surrogate Recoveries (%) %SS1: 103 100 101 100 %SS2: 108 107 106 107 %SS3: 113 114 113 114 Comments

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.



Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824-A;
Livermore Airport-Pipeline

Date Sampled: 04/02/07

Date Received: 04/02/07

Client Contact: Chris Palmer
Date Extracted: 04/02/07

Client P.O.:
Date Analyzed: 04/03/07-04/04/07

Oxygenates and BTEX by GC/MS\* Extraction Method: SW5030B Analytical Method: SW8260B Work Order: 0704022 0704022-008A 0704022-010A 0704022-011A Lab ID 0704022-013A B-1-8 @ 31.5-32 B-2-1 @ 3.5-4.0 B-2-2 @ 7.5-8.0 B-2-4 @ 15.5-Client ID Reporting Limit for 16.0 DF =1 Matrix S S S S DF 1 1 1 1 S W Compound Concentration mg/kg ug/L tert-Amyl methyl ether (TAME) ND ND ND ND 0.005 NA Benzene ND ND ND ND 0.005 NA t-Butyl alcohol (TBA) ND ND ND ND 0.05 NA 1,2-Dichloroethane (1,2-DCA) ND ND ND ND 0.005 NA Diisopropyl ether (DIPE) ND ND ND ND 0.005 NA ND ND Ethanol ND ND 0.25 NA Ethylbenzene ND ND ND ND 0.005 NA Ethyl tert-butyl ether (ETBE) ND ND ND ND 0.005 NA Methanol ND ND ND ND 2.5 NA Methyl-t-butyl ether (MTBE) ND ND ND 0.005 ND NA ND Toluene ND ND ND 0.005 NA **Xylenes** ND ND ND ND 0.005 NA Surrogate Recoveries (%) %SS1: 99 100 96 95

# %SS1: 99 100 96 95 %SS2: 105 105 105 105 %SS3: 110 108 110 109 Comments

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.




Client Project ID: #81-01824-A; Consolidated Engineering Laboratories Date Sampled: 04/02/07 Livermore Airport-Pipeline Date Received: 04/02/07 2001 Crow Canyon Road, Suite 100 Client Contact: Chris Palmer Date Extracted: 04/02/07 San Ramon, CA 94583 Client P.O.: Date Analyzed: 04/03/07-04/04/07 Oxygenates and BTEX by GC/MS\* Extraction Method: SW5030B Analytical Method: SW8260B Work Order: 0704022 Lab ID 0704022-016A B-2-7 @ 27.5-Client ID Reporting Limit for 28' DF =1 Matrix S DF 1 S W Compound Concentration mg/kg ug/L tert-Amyl methyl ether (TAME) ND 0.005 NA Benzene ND 0.005 NA t-Butyl alcohol (TBA) ND 0.05 NA 1,2-Dichloroethane (1,2-DCA) ND 0.005 NA Diisopropyl ether (DIPE) ND 0.005 NA ND Ethanol 0.25 NA Ethylbenzene ND 0.005 NA Ethyl tert-butyl ether (ETBE) ND 0.005 NA Methanol ND 2.5 NA Methyl-t-butyl ether (MTBE) ND 0.005 NA Toluene ND 0.005 NA Xylenes ND 0.005 NA Surrogate Recoveries (%) %SS1: 94 %SS2: 105 %SS3: 107 Comments

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

# QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704022

EPA Method SW8260B	260B Extraction SW5030B BatchID: 27401								7401 Spiked Sample ID: 0704242-006B					
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	criteria (%)			
	μg/L	μg/L_	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD		
tert-Amyl methyl ether (TAME)	ND	10	97.8	96.8	1.06	94.2	94.9	0.786	70 - 130	30	70 - 130	30		
t-Butyl alcohol (TBA)	ND	50	89	85.8	3.61	88.8	90.2	1.64	70 - 130	30	70 - 130	30		
1,2-Dibromoethane (EDB)	ND	10	87.6	87.4	0.254	88.2	88	0.189	70 - 130	30	70 - 130	30		
1,2-Dichloroethane (1,2-DCA)	ND	10	105	105	0	102	102	0	70 - 130	30	70 - 130	30		
Diisopropyl ether (DIPE)	ND	10	114	112	1.51	110	110	0	70 - 130	30	70 - 130	30		
Ethanol	ND	500	95.6	92.5	2.99	92.4	99.1	6.49	70 - 130	30	70 - 130	30		
Ethyl tert-butyl ether (ETBE)	ND	10	105	104	0.490	101	101	0	70 - 130	30	70 - 130	30		
Methanol	ND	2500	101	100	0.792	101	100	0.435	70 - 130	30	70 - 130	30		
Methyl-t-butyl ether (MTBE)	ND	10	103	103	0	99.7	101	1.08	70 - 130	30	70 - 130	30		
%SS1:	104	10	95	94	1.14	94	94	0	70 - 130	30	70 - 130	30		

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27401 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704022-009C	04/02/07 10:10 AM	04/12/07	04/12/07 8:14 PM	0704022-017C	04/02/07 12:45 PM	04/12/07	04/12/07 8:57 PM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



Consolidated Engineering Laborat	Client Project ID: #81-01824-A	Date Sampled:	04/02/07
2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583		Date Received:	04/03/07
	Client Contact: Chris Palmer	Date Reported:	04/09/07
	Client P.O.:	Date Completed:	04/09/07

WorkOrder: 0704059

April 09, 2007

Dear Chris:

Enclosed are:

- 1). the results of 7 analyzed samples from your #81-01824-A project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.


All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Best regards,

Angela Rydelius, Lab Manager

#### Consolidated Engineering Laboratories, Inc. **Chain of Custody** 2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583 Date: Apri [2,2007 Ph. 925/314-7100 Proj. No. 81-01824-A Fx. 925/855-7140 Page \_/ of \_/ Project name: <u>Livermore Airport UST/Pipeline</u> Relinquished by: OWelle Received by: Denk Date received: 994/3/07 carpalmer DEPLIK CHRITAN Print name: Print name: Jime received: $\frac{300}{412/67}$ Company name: Carso idatuch Eugulal. Lab name: MCCAMPBELL Special Instructions Recleved in good condition N-5 day Please run TPHD for dress and Matrix Marix Yes / No Tet Fuel Total # of Samples Sample I.D. Date Time Comments 4/2/07 1405 Soil B-3+c25-30 N B-3-207,5-80° 1410 B-3-30 11.5-12.0 1415 W B-3-4015.5-16.0' 1425 B-3-5@19.5-20.0' W B-3-60 23.5-24,0 1500 B-3-7 C 27.5-280 N 1520 HOLO GOOD CONDITION APPROPRIATE PLESERVED IN LAB DECHLORINATED N LA B-3 water c 25-27 4/2107 1550 water 4/N PRESERVATION

4101



# **CHAIN-OF-CUSTODY RECORD**

Page 1 of 1

5 days

WorkOrder: 0704059

Bill t

ClientID: CEL

EDF

Fax

✓ Email

HardCopy

☐ ThirdParty

Requested TAT:

Report to:

Chris Palmer

Consolidated Engineering Laboratori

2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Email: cp@ce-labs.com

ProjectNo: #81-01824-A

TEL:

PO:

925.485.5000

FAX: 925.485.5019

Accounts Payable

Consolidated Engineering Laboratori

2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

ap@ce-labs.com

Date Received 04/03/2007

Date Printed: 04/04/2007

				L	Requested Tests (See legend below)												
Sample ID	ClientSampID	Matrix	Collection Date Ho	old	1	2	3	4	5		6	7	8	9	10	11	12
0704059-001	B-3-1@ 2.5-3.0'	Soil	4/2/07 2:05:00 PM   [	71	Α		1	I A	T			-	Γ			r -	T
0704059-002	B-3-2 @7.5-8.0'	Soil	4/2/07 2:10:00 PM	<b>=</b>  -	A	•		A				· · ·			<del> </del> -	_	$\vdash$
0704059-003	B-3-3 @ 11.5-12.0'	Soil	4/2/07 2:15:00 PM	<del>-</del>	A			A								<del> </del>	<del></del>
0704059-004	B-3-4 @ 15.5-16.0'	Soil	4/2/07 2:25:00 PM	51	Α			A									+
0704059-005	B-3-5 @ 19.5-20.0'	Soil	4/2/07 2:40:00 PM [	5	Α			A						<del></del> -		<b>-</b>	<del> </del>
0704059-006	B-3-6 @ 23.5-24.0'	Soil	4/2/07 3:00:00 PM [	5	A		_	A	†	·							$\vdash$
0704059-008	B-3 Water 25-27	Water	4/2/07 3:50:00 PM	7		Α	В		<b>T</b>	$\dashv$					<del> </del>	<del> </del>	<del> </del>

#### Test Legend:

1 G-MBTEX_S	2 G-MBTEX_W	3 MBTEX-8260B_W	4 MBTEXOXY-8260B_S	5
6	7	8	9	10
11	12			

The following SampIDs: 0704059-001A, 0704059-002A, 0704059-003A, 0704059-004A, 0704059-005A, 0704059-006A, 0704059-008A contain testgroup.

Prepared by: Melissa Valles

#### **Comments:**

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.



"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories	Client Project ID: #81-01824-A	Date Sampled:	04/02/07
2001 Crow Canyon Road, Suite 100		Date Received:	04/03/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted:	04/03/07-04/06/07
	Client P.O.:	Date Analyzed	04/05/07-04/06/07


### Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline\*

action method: S		Analytical meth	ods: SW8015Cm	Work Order: 07	04059
Lab ID	Client ID	Matrix	TPH(g)	DF	%
001A	B-3-1@ 2.5-3.0'	S	ND .	1	7
002A	B-3-2 @7.5-8.0'	S	ND	ı	-
003A	B-3-3 @ 11.5-12.0'	S	ND	- 1	
004A	B-3-4 @ 15.5-16.0'	S	ND	1	8
005A	B-3-5 @ 19.5-20.0'	s	ND	1	
006A	B-3-6 @ 23.5-24.0'	S	ND	1	8
008A	B-3 Water 25-27	w	ND,i	1	9
					-
Repo	rting Limit for DF =1;	w	50		
ND m	eans not detected at or ve the reporting limit	S	1.0	μg mg	

* water and vapor samples and all TCLP & SPLP extracts are reported in µg/L, soil/sludge/solid	samples in mg/kg,	wipe samples in µg/wipe,
product/oil/non-aqueous liquid samples in mg/L.		

<sup>#</sup> cluttered chromatogram; sample peak coelutes with surrogate peak.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (stoddard solvent / mineral spirit?); f) one to a few isolated non-target peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) reporting limit raised due to high MTBE content; k) TPH pattern that does not appear to be derived from gasoline (aviation gas). m) no recognizable pattern; n) TPH(g) value derived using a client specified carbon range; o) results are reported on a dry weight basis; p) see attached narrative.



1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

when Ottanty	Counts				Letephone	877-252-9262 Fax: 92	5-252-9269		
		ent Proj	ject ID: #	81-018	324-A	Date Sampled:	04/02/07		
2001 Crow Canyon Road, Suite 100	,	Date Recei					04/03/07		
San Ramon, CA 94583	Cli	Client Contact: Chris Palmer Date Ex				Date Extracted:	04/04/07		
San Kamon, CA 94363		Client P.O.: Date Analyzed:					04/04/07		
	0				y GC/MS*				
Extraction Method: SW5030B			tical Method:	SW826	0B		Work Order:	0704059	
Lab ID	0704059-0	008B							
Client ID	B-3 Water 2	25-27					Reporting	I imit for	
							DF		
Matrix	W						1		
DF	1						S	w	
Compound				Conce	entration		ug/kg	μg/L	
tert-Amyl methyl ether (TAME)	ND						NA	0.5	
Benzene	ND						NA	0.5	
t-Butyl alcohol (TBA)	ND	_					NA	5.0	
Diisopropyl ether (DIPE)	ND						NA	0.5	
Ethylbenzene	ND					·	NA	0.5	
Ethyl tert-butyl ether (ETBE)	ND						NA	0.5	
Methyl-t-butyl ether (MTBE)	ND						NA	0.5	
Toluene	ND						NA	0.5	
Xylenes	ND						NA	0.5	
		Surrog	gate Reco	veries	(%)				
%SS1:	122								
%SS2:	102								

110

%SS3:

Comments

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.

Consolidated Engineering Laboratories Client Project ID: #81-01824-A Date Sampled: 04/02/07 Date Received: 04/03/07 2001 Crow Canyon Road, Suite 100 Client Contact: Chris Palmer Date Extracted: 04/03/07 San Ramon, CA 94583 Client P.O.: Date Analyzed: 04/04/07 Oxygenates and BTEX by GC/MS\* Extraction Method: SW5030B Analytical Method: SW8260B Work Order: 0704059 Lab ID 0704059-001A 0704059-002A 0704059-003A 0704059-004A B-3-1@ 2.5-3.0' B-3-2 @7.5-8.0' B-3-3 @ 11.5-B-3-4 @ 15.5-Client ID Reporting Limit for 12.0' 16.0' DF =1 Matrix S S S S DF 1 1 1 1 S W Compound Concentration mg/kg ug/L tert-Amyl methyl ether (TAME) ND ND ND 0.005 NA Benzene ND ND ND ND 0.005 NA t-Butyl alcohol (TBA) ND ND ND ND 0.05 NA Diisopropyl ether (DIPE) ND ND ND 0.005 NA Ethylbenzene ND ND ND ND 0.005 NA Ethyl tert-butyl ether (ETBE) ND ND ND ND 0.005 NA Methyl-t-butyl ether (MTBE) ND ND ND ND 0.005 NA

%SS1:	102	100	100	101	
%SS2:	105	105	105	105	
%SS3:	103	105	104	107	
Comments					

ND

ND

Surrogate Recoveries (%)

ND

ND

ND

ND

0.005

0.005

NA

NA

ND

ND

Toluene

**Xylenes** 

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.

# McCampbell Analytical, Inc. "When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.nccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

1300				rerephone.	617-232-9262 Fax: 92	J-4J4-9409		
Consolidated Engineering Laboratories		Client Pr	oject ID: #81-018		Date Sampled: 04/02/07			
2001 Crow Canyon Road, Suite 100					Date Received: 04/03/07			
San Ramon, CA 94583		Client Co	ontact: Chris Pal	mer	Date Extracted: 04/03/07			
		Client P.0	O.:		Date Analyzed:	04/04/07		
Extraction Method: SW5030B			ates and BTEX b	•		Work Order:	0704059	
Lab ID	0704059	9-005A	0704059-006A					
Client ID	B-3-5 @	_	B-3-6 @ 23.5- 24.0'			Reporting		
Matrix	S	3	S			DF	=1	
DF			1			S	w	
Compound		Concentration					ug/L	
tert-Amyl methyl ether (TAME)	NI	D	ND			0.005	NA	
Benzene	NI	D	ND			0.005	NA	
t-Butyl alcohol (TBA)	NI	D	ND			0.05	NA	
Diisopropyl ether (DIPE)	NI	0	ND			0.005	NA	
Ethylbenzene	NI	0	ND			0.005	NA	
Ethyl tert-butyl ether (ETBE)	NI	)	ND			0.005	NA	
Methyl-t-butyl ether (MTBE)	NI	)	ND			0.005	NA	
Toluene	NI	0	ND			0.005	NA	
Xylenes	NI	)	ND			0.005	NA	
		Surro	ogate Recoveries	(%)				
%SS1:	10	0	101					
%SS2:	10	5	107					
%SS3:	10	4	102					
Comments								

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



# McCampbell Analytical, Inc.

"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories	Client Project ID: #81-01824-A	Date Sampled: 04/02/07
2001 Crow Canyon Road, Suite 100		Date Received: 04/03/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/03/07
,	Client P.O.:	Date Analyzed: 04/04/07

## Diesel (C10-23) and Jet Fuel (C9-C18) Range Extractable Hydrocarbons as Diesel and Jet Fuel\*

Extraction method: SW	73510C/8W3550C	Analytical me	thods: SW8015C	Wo	rk Order: 0	704059
Lab ID	Client ID	Matrix	TPH(d)	TPH(jf)	DF	% SS
0704059-001A	B-3-1@ 2.5-3.0'	S	ND	ND	1	99
0704059-002A	B-3-2 @7.5-8.0'	S	ND	ND	1	99
0704059-003A	B-3-3 @ 11.5-12.0'	S	ND	ND	1	100
0704059-004A	B-3-4 @ 15.5-16.0'	S	ND	ND	1	112
0704059-005A	B-3-5 @ 19.5-20.0'	S	ND	ND	1	109
0704059-006A	B-3-6 @ 23.5-24.0'	S	ND	ND	1	112
0704059-008A	B-3 Water 25-27	w	ND,i	ND	1	102
-	ing Limit for DF =1;	w	50	50	lra	/L
	ans not detected at or ethe reporting limit	S	1.0	1.0	mg	

* water samples are reported in µg/L, wipe samples in µg	g/wipe, soil/solid/sludge samples in mg	g/kg, product/oil/non-aqueous liquid samples in
mg/L, and all DISTLC / STLC / SPLP / TCLP extracts a		•

<sup>#</sup> cluttered chromatogram resulting in coeluted surrogate and sample peaks, or; surrogate peak is on elevated baseline, or; surrogate has been diminished by dilution of original extract.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified diesel is significant; b) diesel range compounds are significant; no recognizable pattern; c) aged diesel? is significant); d) gasoline range compounds are significant; e) unknown medium boiling point pattern that does not appear to be derived from diesel; f) one to a few isolated peaks present; g) oil range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; k) kerosene/kerosene range; l) bunker oil; m) fuel oil; n) stoddard solvent/mineral spirit.



# QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704059

EPA Method SW8260B	Extra	ction SW	5030B		BatchID: 27207				piked Sample ID: 0703763-002A				
Analyte	Sample	Spiked	MS	MS MSD		MS-MSD LCS		LCS-LCSD	Acc	eptance	Criteria (%)	)	
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD	
tert-Amyl methyl ether (TAME)	ND	0.050	101	98.4	2.83	96.6	97.6	1.00	70 - 130	30	70 - 130	30	
Benzene	ND	0.050	107	107	0	106	106	0	70 - 130	30	70 - 130	30	
t-Butyl alcohol (TBA)	ND	0.25	96	100	4.18	95.4	94.4	1.03	70 - 130	30	70 - 130	30	
Diisopropyl ether (DIPE)	ND	0.050	115	114	1.70	112	112	0	70 - 130	30	70 - 130	30	
Ethyl tert-butyl ether (ETBE)	ND	0.050	108	105	2.64	102	103	0.957	70 - 130	30	70 - 130	30	
Methyl-t-butyl ether (MTBE)	ND	0.050	108	105	2.64	102	104	1.62	70 - 130	30	70 - 130	30	
Toluene	ND	0.050	96.9	94.6	2.39	94.3	93.8	0.485	70 - 130	30	70 - 130	30	
%SS1:	97	0.050	97	97	0	97	98	0.162	70 - 130	30	70 - 130	30	
%SS2:	102	0.050	100	99	0.926	99	99	0	70 - 130	30	70 - 130	30	
%SS3:	93	0.050	107	108	0.739	107	107	0	70 - 130	30	70 - 130	30	

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27207 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704059-001A	04/02/07 2:05 PM	1 04/03/07	04/04/07 3:11 PM	0704059-002A	04/02/07 2:10 PM	04/03/07	04/04/07 3:55 PM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



# QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704059

EPA Method SW8015C	Extraction SW3510C					BatchID: 27211			Spiked Sample ID: N/A				
Analyte	Sample	Sample Spiked MS		MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acceptance Criteria (%)				
	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD	
TPH(d)	N/A	1000	N/A	N/A	N/A	114	111	2.50	N/A	N/A	70 - 130	30	
%SS:	N/A	2500	N/A	N/A	N/A	110	111	0.719	N/A	N/A	70 - 130	30	

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27211 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704059-008A	04/02/07 3:50 PM	04/03/07	04/04/07 8:14 PM			······	···········

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com

Telephone: 877-252-9262 Fax: 925-252-9269

# QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704059

EPA Method SW8021B/8015Cm	Extra	ction SW		BatchID: 27231			Sp	Spiked Sample ID: 0704022-016A				
Analyte	Sample Spiked MS			MSD	MS-MSD	LCS	LCS LCSD	LCS-LCSD	Acceptance Criteria (%)			
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(btex <sup>£</sup>	ND	0.60	112	97	13.9	102	108	5.89	70 - 130	30	70 - 130	30
МТВЕ	ND	0.10	111	120	7.88	107	105	1.86	70 - 130	30	70 - 130	30
Benzene	ND	0.10	95.2	102	6.79	93.9	92.5	1.47	70 - 130	30	70 - 130	30
Toluene	ND	0.10	90	90.2	0.181	86.2	84.8	1.62	70 - 130	30	70 - 130	30
Ethylbenzene	ND	0.10	97.2	97.3	0.115	94.4	94.7	0.326	70 - 130	30	70 - 130	30
Xylenes	ND	0.30	94.4	87.7	7.25	91.3	92	0.727	70 - 130	30	70 - 130	30
%SS:	79	0.10	87	107	20.3	97	102	4.46	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27231 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704059-001A	04/02/07 2:05 PM	04/03/07	04/05/07 8:04 AM	0704059-002A	04/02/07 2:10 PM	04/03/07	04/05/07 8:37 AM
0704059-003A	04/02/07 2:15 PM	04/03/07	04/05/07 9:11 AM	0704059-004A	04/02/07 2:25 PM	04/03/07	04/05/07 9:44 AM
0704059-005A	04/02/07 2:40 PM	04/03/07	04/05/07 10:17 AM	0704059-006A	04/02/07 3:00 PM	04/03/07	04/05/07 1:17 PM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = <math>100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.



1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com

Telephone: 877-252-9262 Fax: 925-252-9269

# QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704059

EPA Method SW8015C	Extra	BatchID: 27232			Spiked Sample ID: 0704022-016A							
Analyte	Sample Spiked MS		MSD	MS-MSD	LCS LCSD	LCS-LCSD	Acceptance Criteria (%)					
	mg/Kg	mg/Kg mg/Kg % Rec. % Re				% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(d)	ND	20	101	101	0	113	114 .	0.772	70 - 130	30	70 - 130	30
%SS:	103	50	103	103	0	114	122	7.15	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27232 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704059-001A	04/02/07 2:05 PM	04/03/07	04/04/07 5:26 AM	0704059-002A	04/02/07 2:10 PM	04/03/07	04/04/07 6:34 AM
0704059-003A	04/02/07 2:15 PM	04/03/07	04/04/07 7:43 AM	0704059-004A	04/02/07 2:25 PM	04/03/07	04/04/07 5:26 AM
0704059-005A	04/02/07 2:40 PM	04/03/07	04/04/07 6:34 AM	0704059-006A	04/02/07 3:00 PM	04/03/07	04/04/07 7:43 AM

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

# QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704059

EPA Method SW8260B	Extra	BatchID: 27255			Sp	Spiked Sample ID: 0704052-016B						
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)
	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
Benzene	ND	10	103	103	0	99.1	99.9	0.838	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	10	101	102	0.843	95.8	97.7	2.01	70 - 130	30	70 - 130	30
Toluene	ND	10	95.1	90.2	5.37	90.2	90.3	0.110	70 - 130	30	70 - 130	30
%SS1:	121	10	95	100	4.65	95	96	1.09	70 - 130	30	70 - 130	30
%SS2:	102	10	102	101	0.879	100	100	0	70 - 130	30	70 - 130	30
%SS3:	110	10	108	108	0	109	108	0.583	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27255 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704059-008B	04/02/07 3:50 PM	04/04/07	04/04/07 8:23 PM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



# QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704059

EPA Method SW8260B Extraction SW5030B					Ва	tchID: 27	259	Sp	Spiked Sample ID: 0704059-006A				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)	
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD	
tert-Amyl methyl ether (TAME)	ND	0.050	96.5	95.4	1.12	96.8	96.1	0.733	70 - 130	30	70 - 130	30	
Benzene	ND	0.050	101	101	0	98.2	101	2.66	70 - 130	30	70 - 130	30	
t-Butyl alcohol (TBA)	ND	0.25	84.5	86.1	1.86	94.2	95.9	1.76	70 - 130	30	70 - 130	30	
Diisopropyl ether (DIPE)	ND	0.050	109	108	0.420	107	108	0.735	70 - 130	30	70 - 130	30	
Ethyl tert-butyl ether (ETBE)	ND	0.050	102	101	0.887	102	102	0	70 - 130	30	70 - 130	30	
Methyl-t-butyl ether (MTBE)	ND	0.050	102	101	0.846	104	102	1.92	70 - 130	30	70 - 130	30	
Toluene	ND	0.050	91.4	91.6	0.175	89.3	91.8	2.80	70 - 130	30	70 - 130	30	
%SS1:	101	0.050	92	92	0	93	93	0	70 - 130	30	70 - 130	30	
%SS2:	107	0.050	100	100	0	101	100	0.591	70 - 130	30	70 - 130	30	
%SS3:	102	0.050	109	108	0.343	109	108	0.0728	70 - 130	30	70 - 130	30	

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27259 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704059-003A	04/02/07 2:15 PM	04/03/07	04/04/07 4:42 PM	0704059-004A	04/02/07 2:25 PM	04/03/07	04/04/07 5:29 PM
0704059-005A	04/02/07 2:40 PM	04/03/07	04/04/07 6:16 PM	0704059-006A	04/02/07 3:00 PM	04/03/07	04/04/07 7:00 PM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



# QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704059

EPA Method SW8021B/8015Cm	Extra	ction SW	5030B		Ва	tchID: 27	234	Sp	piked Sample ID: 0704052-008A				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)	
	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD	
TPH(btex <sup>£</sup>	ND	60	90	93.5	3.76	106	108	1.74	70 - 130	30	70 - 130	30	
MTBE	ND	10	82	87.4	6.44	115	109	5.08	70 - 130	30	70 - 130	30	
Benzene	ND	10	87.5	90.8	3.70	95.3	99.8	4.60	70 - 130	30	70 - 130	30	
Toluene	ND	10	87.3	91.1	4.34	103	110	6.71	70 - 130	30	70 - 130	30	
Ethylbenzene	ND	10	92	95.2	3.37	96.4	107	10.1	70 - 130	30	70 - 130	30	
Xylenes	ND	30	103	107	3.17	100	120	18.2	70 - 130	30	70 - 130	30	
%SS:	95	10	90	90	0	93	98	5.29	70 - 130	30	70 - 130	30	

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27234 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704059-008A	04/02/07 3:50 PM	04/06/07	04/06/07 2:59 AM				***


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.



Consolidated Engineering Laborat	Client Project ID: #81-01824-A	Date Sampled:	04/02/07
2001 Crow Canyon Road, Suite		Date Received:	04/03/07
100 San Ramon, CA 94583	Client Contact: Chris Palmer	Date Reported:	04/09/07
builtainon, Ori 74303	Client P.O.:	Date Completed:	04/16/07

WorkOrder: 0704059

April 16, 2007

Dear Chris:

## Enclosed are:

- 1). the results of 1 analyzed sample from your #81-01824-A project,
- 2). a QC report for the above sample
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Best regards,

Angela Rydelius, Lab Manager

+10

Consolidated I 2001 Crow Can San Ramon, CA	yon R	load, S	Labo Suite 10	rate	orie	es, I	nc	•									1					of Cus दुरळा	stody
Ph. 925/314-71 Fx. 925/855-714											ζ.					<b>.</b>					٠.	01824-A	
Project name: <u>Ui</u>	verm	ore A	inport	U	15	T/ F	Dipe	eln	ne									Pag	e_		(	of _ <i>/</i>	
Relinquished by: Print name: Company name:	Cu	Mall W	er		P	rint ı ab n	nan	ne: e:	7	) L WC 16:	AM TK	<u> </u>	MC	TAN	(					ive eive	ıd:		
Special Instructions N-5 day Dease rem TAME Jet Full		dresed a	end/ Matrix	ber of samples	Tum Around Time	Analysis Requested	1 2 47 1 1 1 1 1 1 1 1 1		Diesel by Bors	meeth 1,2pc+	•											Recieved in good Yes No Total # of Samp	
Sample I.D.	Date			Į.	<del></del>	Anal		K K	T/Ó.M	etott addk												. Comme	ents
B-3-1 c2.5-3.0	412107		Soil	1	N		4	4	$\angle$	X	_		_			_	_	_	_		_		
B-3-207,5-80'		1410		1	W		_	4	4	Ϋ́				ļ				_	<u> </u>		ļ		
B-3-3011.5-12.0		1415		Ц.	W	-	{	4	4	<u> </u>						_			_	<u> </u>			
B-3-4015.5-14.0'		14215		1	N	-		$\mathcal{A}$	$\leq$	X				_			_		_	ļ	-	·	
8-3-56 19.5-20.0		1990		-	N	$\vdash \vdash$			4	Λ Χ						_	<u> </u>	_	$\vdash$	_			
B-3-4c 23.5-24.0 B-3-7c 27.5-28.0	-	1500		1	NN	┝╼┼		$\mathcal{A}$	4	<u> </u>	-			<u> </u>			_		_		-	1.107	
D-7-167112-500		1520		-	14	$\vdash$	$\dashv$	$\dashv$				ICE		73		$\overline{}$	/		<u> </u>	$\vdash$	<del> </del>	HOLO	·
B-3 water c 25-27	4/21117	1550	water	4	N	-	$\dashv$	$\forall$	$\overline{}$	$\overline{\mathbf{x}}$				DNDI ACE RINA		VI A	- <del>-</del>	A C	PRO	PRIA INER RVEI		/ AD	
J DIBVIOLE ESCI	110101	1 5 50	www		1 1	┝╌┼	$\dashv$	$\overline{}$	$\dashv$	-				VATI		OAS		٦			THER		
							+	_	$\neg$		-								=				

# McCampbell Analytical, Inc.



1534 Willow Pass Rd Pittsburg, CA 94565-1701 (925) 252-9262

# **CHAIN-OF-CUSTODY RECORD**

5 days

	WorkOrder:	070405	A	ClientID:	CEL	
EDF ·	☐ Excel	Fax	<b>✓</b> Emai		HardCopy	ThirdParty

Report to: Chris Palmer

> Consolidated Engineering Laboratori 2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Email: cp@ce-labs.com TEL:

PO:

925.485.5000

ProjectNo: #81-01824-A

FAX: 925.485.5019

Bill t Accounts Payable

Consolidated Engineering Laboratori

2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583

ap@ce-labs.com

Requested TA

Date Receive 04/03/2007 Date Add-On: 04/11/2007

Date Printed: 04/11/2007

				Requested Tests (See legend below)											
Sample ID	ClientSamplD	Matrix	Collection Date Hold	1	2	3	4	5	6	7	8	9	10	11	12
0704059-008	B-3 Water 25-27	Water	4/2/07 3:50:00 PM	С				ļ							

## Test Legend:

1	9-OXYS_W	2	3	4	5
6		7	8 1	9	10
11		12			

Prepared by: Melissa Valles

Comments:

Etoh, Meoh, and 1,2 DCA added 4/10 per C.P

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.



# McCampbell Analytical, Inc.

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laborate	ories Client P	roject ID: #81-018	324-A	Date Sampled:	04/02/07			
2001 Crow Canyon Road, Suite 100	)			Date Received:	04/03/07			
San Ramon, CA 94583	Client C	Contact: Chris Pal	mer	Date Extracted: 04/12/07				
Sun rumon, C.17 1000	Client P	.0.:		Date Analyzed:	04/12/07			
Oxygenat  Extraction Method: SW5030B	-	nics + EDB and 1	•	and GC/MS*	Work Order:	0704059		
Lab ID	0704059-008C				WOIR GIGGI.	0704037		
Client ID	B-3 Water 25-27				Reporting DF			
Matrix	W							
DF	1				S	w		
Compound		Conce	entration		ug/kg	μg/L		
1,2-Dichloroethane (1,2-DCA)	ND				NA	0.5		
Ethanol	ND				NA	50		
Methanol	ND				NA	500		
	Suri	ogate Recoveries	s (%)					
%SS1:	96							
Comments	i							

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; I) analyte detected below quantitation limits; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

	<b>†</b>	
2001 Crow Canyon Road, Suite 100		Date Received: 04/03/07
San Ramon, CA 94583	lient Contact: Chris Palmer	Date Extracted: 04/03/07
	lient P.O.:	Date Analyzed: 04/04/07

## Oxygenates and BTEX by GC/MS\*

Extraction Method: SW5030B Analytical Method: SW8260B Work Order: 0704059

Extraction Method: SW5030B	Ana	lytical Method: SW826	0B .		Work Order:	0704059	
Lab ID	0704059-001A	0704059-002A	0704059-003A	0704059-004A			
Client ID	B-3-1@ 2.5-3.0'	B-3-2 @7.5-8.0'	B-3-3 @ 11.5- 12.0'	B-3-4 @ 15.5- 16.0'	Reporting Limit for DF =1		
Matrix	S	S	S	S	] "	1	
DF	1	1	1	1	S	W	
Compound		Conce	entration		mg/kg	ug/L	
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	NA	
Benzene	ND	ND	ND	ND	0.005	NA	
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	NA	
1,2-Dichloroethane (1,2-DCA)	ND	ND	ND	ND	0.005	NA	
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	NA	
Ethanol	ЙD	ND	ND	ND	0.25	NA	
Ethylbenzene	ND	ND	ND	ND	0.005	NA	
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	NA	
Methanol	ND	ND	ND	ND	2.5	NA	
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	NA	
Toluene	ND	ND	ND	ND	0.005	NA	
Xylenes	ND	ND	ND	ND	0.005	NA	
	Surr	ogate Recoveries	s (%)				
%SS1:	102	100	100	101			
%SS2:	105	105	105	105			
%SS3:	103	105	104	107			
Comments							
± . 1	17 11 1 1	1:1 1 : 1	1	11111		T D O	

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Consolidated Engineering Laboratories Client Project ID: #81-01824-A Date Sampled: 04/02/07 Date Received: 04/03/07 2001 Crow Canyon Road, Suite 100 Client Contact: Chris Palmer Date Extracted: 04/03/07 San Ramon, CA 94583 Client P.O.: Date Analyzed: 04/04/07

## Oxygenates and BTEX by GC/MS\*

Analytical Method: SW8260B Extraction Method: SW5030B Work Order: 0704059 Lab ID 0704059-005A 0704059-006A

Client ID	B-3-5 @ 19.5- 20.0'	B-3-6 @ 23.5- 24.0'		Reporting DF		
Matrix	S	S		DF	-1	
DF	1	1		S	W	
Compound		Concentration				
tert-Amyl methyl ether (TAME)	ND	ND		0.005	NA	
Benzene	ND	ND		0.005	NA	
t-Butyl alcohol (TBA)	ND	ND		0.05	NA	
1,2-Dichloroethane (1,2-DCA)	ND	ND		0.005	NA	
Diisopropyl ether (DIPE)	ND	ND		0.005	NA	
Ethanol	ND	ND		0.25	NA	
Ethylbenzene	ND	ND		0.005	NA	
Ethyl tert-butyl ether (ETBE)	ND	ND		0.005	NA	
Methanol	ND	ND		2.5	NA	
Methyl-t-butyl ether (MTBE)	ND	ND		0.005	NA	
Toluene	ND	ND		0.005	NA	
Xylenes	ND	ND		0.005	NA	
	Surr	ogate Recoveries	s (%)			
%SS1:	100	101				
%SS2:	105	107				
%SS3:	104	102				

%SS1:	100	101		
%SS2:	105	107		
%SS3:	104	102		
Comments				

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



# QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704059

EPA Method SW8260B	Extra	Extraction SW5030B BatchID: 27401							Spiked Sample ID: 0704242-006B			
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	S-LCSD Acceptance Criteria (%)			)
	µg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	10	97.8	96.8	1.06	94.2	94.9	0.786	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	50	89	85.8	3.61	88.8	90.2	1.64	70 - 130	30	70 - 130	30
1,2-Dibromoethane (EDB)	ND	10	87.6	87.4	0.254	88.2	88	0.189	70 - 130	30	70 - 130	30
1,2-Dichloroethane (1,2-DCA)	ND	10	105	105	0	102	102	0	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	10	.114	112	1.51	110	110	0	70 - 130	30	70 - 130	30
Ethanol	ND	500	95.6	92.5	2.99	92.4	99.1	6.49	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	10	105	104	0.490	101	101	0	70 - 130	30	70 - 130	30
Methanol	ND	2500	101	100	0.792	101	100	0.435	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	10	103	103	0	99.7	101	1.08	70 - 130	30	70 - 130	30
%SS1:	104	10	95	94	1.14	94	94	0	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27401 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704059-008C	04/02/07 3:50 PM	04/12/07	04/12/07 11:12 PM				

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = <math>100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



Consolidated Engineering Laborat	Client Project ID: #81-01824-A;Livemore	Date Sampled:	04/03/07
2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583	Airport UST/pipeline	Date Received:	04/03/07
	Client Contact: Chris Palmer	Date Reported:	04/10/07
	Client P.O.:	Date Completed:	04/10/07

WorkOrder: 0704052

April 10, 2007

Dear Chris:

## Enclosed are:

- 1). the results of 12 analyzed samples from your #81-01824-A;Livemore Airport UST/pipeline project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Best regards,

Angela Rydelius, Lab Manager

ted Engineering Laboratories, Inc.
Canyon Road, Suite 100

#### Consolidated Engineering Laboratories, Inc. Chain of Custody 2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583 Date: April 3, 2007 Ph. 925/314-7100 Proj. No. 81-01824-A Fx. 925/855-7140 Page \_\_\_\_ of \_\_\_ Project name: Livemore Airport UST/pipelme Relinquished by: CMPdune Date received: 4/3/07 Received by: am Palmer Print name: Print name: JOHLIL CARTA Time received: 1500 Company name: Consolidated Engeligh. MECAMPRELL( Lab name: Special Instructions Recieved in good condition N-5 day turn Alease check for Jet Fuel in Yes \_\_\_ No TPWD unge Total # of Samples Sample I.D. Date | Time Matrix Comments 413/07 0800 50i N B-4-1020-25 N B-4-207,5-8,0-0810 B-4-30115-120 0815 W) HOLA B-4-4@15.5-160 N 0825 0845 B-4-5@19,5-20.00 N B-4-6@23.5-24.0 0900 B-4-7027.5-28.0 0920 HOLD B-4 water 4/3/07/10/5 water 14 N

Consolidated Engineering Laboratories, Inc. **Chain of Custody** 2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583 Date: <u>April 3</u> 2007 Proj. No. <u>81-01824-A</u> Ph. 925/314-7100 Fx. 925/855-7140 Page 2 of 2 Project name: Civemore Aryport UST/Pipelme Relinquished by: ChiPalmer Date received: <u>4/3/07</u> Received by: CM Palmer Print name: Print name: DALIK CHETAM Time received: \_1300 Company name: Consolidated Eugen Labs Lab name: MCCAMABEZL 16:20 Special Instructions N-5 day tum. Phase check farjet full in Diesel range Recieved in good condition Matrix Mumber of samples Yes \_\_\_ No \_\_\_ Total # of Samples Sample I.D. Date Time . Comments 4/3/07 1005 B-5-10 3,5-4,0 Soi N B.5-207,5-8.0 1110 B-5-3011.5-12.0 1115 B-5-4015.5-16,0 1125 B-5-5@19,5-20,0 1140 HOLD B.5-6@23.5-25 1155 B-5-70 27,5-78 HOLD 1215 B-5 worter H3107 1230 Water 4 N

# McCampbell Analytical, Inc.



1534 Willow Pass Rd Pittsburg, CA 94565-1701 (925) 252-9262

# **CHAIN-OF-CUSTODY RECORD**

✓ Email

Page 1 of 1

WorkOrder: 0704052

ClientID: CEL

HardCopy

ThirdParty

5 days

Report to:

Chris Palmer

Consolidated Engineering Laboratori 2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Email:

cp@ce-labs.com 925.485.5000

FAX: 925.485.5019

EDF

ProjectNo: #81-01824-A;Livemore Airport UST/pip

TEL:

Bill t

☐ Fax

Accounts Payable

Consolidated Engineering Laboratori

2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

ap@ce-labs.com

Requested TAT:

Date Received 04/03/2007 Date Printed: 04/03/2007

					Requested Tests (See legend below)											
Sample ID	ClientSampID	Matrix	<b>Collection Date</b>	Hold	1	2	3	4	5	6	7	8	9	10	11	12
0704052-001	B-4-1@2.0-2.5'	Soil	04/03/07 8:00:00		Α		Α	l	ľ	Ι	<u> </u>	Т	T			
0704052-002	B-4-2@7.5-8.0'	Soil	04/03/07 8:01:00		A		Α									
0704052-004	B-4-4@15.5-16.0'	Soil	04/03/07 8:25:00		Α		Α							<del></del>		
0704052-005	B-4-5@19.5-20.0'	Soil	04/03/07 8:45:00		Α		Α		Ĭ							
0704052-006	B-4-6@23.5-24.0'	Soil	04/03/07 9:00:00		Α		Α						1			
0704052-008	B-4 water	Water	04/03/07 10:15:00			Α		В								
0704052-009	B-5-1@3.5-4.0'	Soil	04/03/07 11:05:00		Α		Α									
0704052-010	B-5-2@7.5-8.0'	Soil	04/03/07 11:10:00		Α		Α									
0704052-011	B-5-3@11.5-12.0'	Soil	04/03/07 11:15:00		Α		Α								-	
0704052-012	B-5-4@15.5-16.0'	Soil	04/03/07 11:25:00		Α		Α				1		<u> </u>		<del></del>	
0704052-014	B-5-6@23.5-25'	Soil	04/03/07 11:55:00		Α		Α						1			
0704052-016	B-5 Water	Water	04/03/07 12:30:00			Α		В								

## Test Legend:

1 G-MBTEX_S	2 G-MBTEX_W	3 MBTEXOXY-8260B_S	4 MBTEXOXY-8260B_W	5
6	7	8	9	10
11	12			

The following SampIDs: 0704052-001A, 0704052-002A, 0704052-004A, 0704052-005A, 0704052-006A, 0704052-008A, 0704052-009A, 0704052-010A, 0704052-011A, 0704052-012A, 0704052-014A, 0704052-016A contain testgroup.

Prepared by:	Chloe Lam
--------------	-----------

#### Comments:

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.

# Sample Receipt Checklist

Client Name: Consolidated Engineer	ing Laboratories	Date	and Time Received: 04/03/07	6:24:33 PM					
Project Name: #81-01824-A;Livemore	Airport UST/pipelin	e Chec	klist completed and reviewed by	: Chloe Lam					
WorkOrder N°: 0704052 Matrix	Soil/Water	Carrie	er: <u>Client Drop-In</u>						
Chain of Custody (COC) Information									
Chain of custody present?	Ye 🗸	No 🗆							
Chain of custody signed when relinquished an	d received? Ye	No 🗆							
Chain of custody agrees with sample labels?	Ye 🗸	No 🗆							
Sample IDs noted by Client on COC?	Ye 🗸	No 🗆							
Date and Time of collection noted by Client on C	OC? Ye	No 🗆							
Sampler's name noted on COC?	Ye 🗹	No 🗆							
	Sample Rec	ceipt Information	<u>n</u>						
Custody seals intact on shippping container/co	ooler? Ye	No 🗆	NA 🗹						
Shipping container/cooler in good condition?	Ye 🔽	No □							
Samples in proper containers/bottles?	Ye 🗹	No □							
Sample containers intact?	Ye 🗹	No □							
Sufficient sample volume for indicated test?	Ye 🗸	No 🗆							
<u>S</u> e	ample Preservation an	d Hold Time (HT	<u>) Information</u>						
All samples received within holding time?	Ye 🗹	No 🗆							
Container/Temp Blank temperature	Cooler Te	mp: 9.6°C	na 🗆						
Water - VOA vials have zero headspace / no b	oubbles? Ye 🗹	No 🗆	No VOA vials submitted $\Box$						
Sample labels checked for correct preservation	n? Ye ✔	No 🗌							
Client contacted:	Date contacted:		Contacted by:						



# McCampbell Analytical, Inc.

"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories	Client Project ID: #81-01824-	Date Sampled: 04/03/07
2001 Crow Canyon Road, Suite 100	A;Livemore Airport UST/pipeline	Date Received: 04/03/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/03/07-04/06/07
Suit Turning City 1000	Client P.O.:	Date Analyzed 04/04/07-04/06/07

## Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline\*

Extraction method: SW5030B Analytical methods: SW8015Cm Work Order: 0704052 Lab ID Client ID Matrix TPH(g) % SS DF A100 B-4-1@2.0-2.51 S ND 90 002A B-4-2@7.5-8.0' S ND 1 86 004A B-4-4@15.5-16.0' S ND 86 005A B-4-5@19.5-20.01 S ND 1 88 006A B-4-6@23.5-24.0' S ND 87 008A B-4 water W ND 95 009A B-5-1@3.5-4.0' S ND 1 86 010A B-5-2@7.5-8.0' S ND 1 85 011A S B-5-3@11.5-12.0' ND 1 86 012A B-5-4@15.5-16.0' S ND 1 85 014A S B-5-6@23.5-25' ND 1 85 016A B-5 Water w ND 88 Reporting Limit for DF =1; W 50 μg/L ND means not detected at or S 1.0 mg/Kg above the reporting limit

* water and vapor samples and all TCLP & SPLP extracts are reported in µg/L, soil/sludge/solid samples in mg/kg, wipe sample	es in μg/wipe,
product/oil/non-aqueous liquid samples in mg/L.	

<sup>#</sup> cluttered chromatogram; sample peak coelutes with surrogate peak.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (stoddard solvent / mineral spirit?); f) one to a few isolated non-target peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) reporting limit raised due to high MTBE content; k) TPH pattern that does not appear to be derived from gasoline (aviation gas). m) no recognizable pattern; n) TPH(g) value derived using a client specified carbon range; o) results are reported on a dry weight basis; p) see attached narrative.





Consolidated Engineering Laboratories	Client Project ID: #81-01824-	Date Sampled: 04/03/07
2001 Crow Canyon Road, Suite 100	A;Livemore Airport UST/pipeline	Date Received: 04/03/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/03/07-04/05/07
	Client P.O.:	Date Analyzed: 04/04/07-04/05/07

	Client P.	O.:		Date Analyzed:	04/04/07-0	4/05/07/
		ates and BTEX b	•			
Extraction Method: SW5030B	<del></del>	lytical Method: SW826		T	Work Order:	0704052
Lab ID	0704052-001A	0704052-002A	0704052-004A	0704052-005A		
Client ID	B-4-1@2.0-2.5'	B-4-2@7.5-8.0'	B-4-4@15.5- 16.0'	B-4-5@19.5- 20.0'	Reporting DF	
Matrix	S	S	S	S	] "	_1
DF	DF 1 1 1 1 1					
Compound		Conce	entration		mg/kg	μg/L
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	0.5
Benzene	ND	ND	ND	ND	0.005	0.5
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5
Ethylbenzene	ND	ND	ND	ND	0.005	0.5
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5
Toluene	ND	ND	ND	ND	0.005	0.5
Xylenes	ND	ND	ND	ND	0.005	0.5
	Surr	ogate Recoveries	s (%)			
%SS1:	103	101	99	95		
%SS2:	105	105	107	105		
%SS3:	102	101	111	107		
Comments						

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Consolidated Engineering Laboratorie	1	Date Sampled: 04/03/07
2001 Crow Canyon Road, Suite 100	A;Livemore Airport UST/pipeline	Date Received: 04/03/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/03/07-04/05/07
Suit Tearion, C.17 1000	Client P.O.:	Date Analyzed: 04/04/07-04/05/07
Extraction Method: SW5030B	Oxygenates and BTEX by GC/MS*  Analytical Method: SW8260B	Work Order 0704052

Extraction Method: SW5030B	Anal	ytical Method: SW826	0B	Work Order:	0704052		
Lab ID	0704052-006A	0704052-008B	0704052-009A	0704052-010A			
Client ID	B-4-6@23.5- 24.0'	B-4 water	B-5-1@3.5-4.0'	B-5-2@7.5-8.0'	Reporting Limit fo  DF =1		
Matrix	S	W	S	S	Dr =1		
DF	1	1	. 1	1	S	W	
Compound		Conce	entration		mg/kg	μg/L	
tert-Amyl methyl ether (TAME)	ND	ND	. ND	ND	0.005	0.5	
Benzene	ND	ND	ND	ND	0.005	0.5	
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0	
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5	
Ethylbenzene	ND	ND	ND	ND	0.005	0.5	
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5	
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5	
Toluene	ND	ND	ND	ND	0.005	0.5	
Xylenes	ND	ND	ND	ND	0.005	0.5	
	Surre	ogate Recoveries	s (%)				
%SS1:	97	120	98	98			
%SS2:	104	101	106	104			
%SS3:	107	109	105	105			
Comments							

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100
San Ramon, CA 94583

Client Project ID: #81-01824A;Livemore Airport UST/pipeline
Date Sampled: 04/03/07

Client Contact: Chris Palmer
Date Extracted: 04/03/07-04/05/07

Client P.O.:
Date Analyzed: 04/04/07-04/05/07

	Oxygen	ates and BTEX b	y GC/MS*				
Extraction Method: SW5030B	Ana	lytical Method: SW826	0B		Work Order:	0704052	
Lab ID	0704052-011A	0704052-012A	0704052-014A	0704052-016B			
Client ID	B-5-3@11.5- 12.0'	B-5-4@15.5- 16.0'	B-5-6@23.5-25'	B-5 Water	Reporting		
Matrix	S	S	S	W	DF =1		
DF	S	W					
Compound	mg/kg	μg/L					
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	0.5	
Benzene	ND	ND	ND	ND	0.005	0.5	
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0	
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5	
Ethylbenzene	ND	ND	ND	ND	0.005	0.5	
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5	
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5	
Toluene	ND	ND	ND	ND	0.005	0.5	
Xylenes	ND	ND	ND	ND	0.005	0.5	
	Surr	ogate Recoveries	s (%)				
%SS1:	104	105	95	121		·	
%SS2:	108	106	104	102		•	
%SS3:	106	106	105	110			

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

Comments

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~I vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



# McCampbell Analytical, Inc.

"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories

Client Project ID: #81-01824A;Livemore Airport UST/pipeline

Date Sampled: 04/03/07

Date Received: 04/03/07

Client Contact: Chris Palmer

Date Extracted: 04/03/07

Client Project ID: #81-01824A;Livemore Airport UST/pipeline


Date Received: 04/03/07

Date Analyzed: 04/04/07-04/09/07

		Client P.O.:		Date Analyzed: 0	4/04/07-04	/09/07
Di Extraction method: SW3			Extractable Hydrocathods: SW8015C	arbons as Diesel and Jet F	uel* 'ork Order: 0	704052
Lab ID	Client ID	Matrix	TPH(d)	TPH(jf)	(jf) DF	
0704052-001A	B-4-1@2.0-2.5'	S	ND	ND	ī	101
0704052-002A	B-4-2@7.5-8.0'	S	ND	ND	1	91
0704052-004A	B-4-4@15.5-16.0'	S	ND	ND	1	102
0704052-005A	B-4-5@19.5-20.0'	S	ND	ND	1	102
0704052-006A	B-4-6@23.5-24.0'	S	ND	ND	1	93
0704052-008A	B-4 water	w	110,g,b	86	1	117
0704052-009A	B-5-1@3.5-4.0'	S	ND	ND	1	93
0704052-010A	B-5-2@7.5-8.0'	S	ND	ND	1	106
0704052-011A	B-5-3@11.5-12.0'	S	ND	ND	1	109
0704052-012A	B-5-4@15.5-16.0'	S	ND	ND	1	99
0704052-014A	B-5-6@23.5-25'	S	ND	ND	1	91
0704052-016A	B-5 Water	w	ND	ND	1	102
	·					
	ng Limit for DF =1;	w	50	50	με	r/L
	the reporting limit	S	1.0	1.0	mg	/Kg

<sup>\*</sup> water samples are reported in µg/L, wipe samples in µg/wipe, soil/solid/sludge samples in mg/kg, product/oil/non-aqueous liquid samples in mg/L, and all DISTLC / SPLP / TCLP extracts are reported in µg/L.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified diesel is significant; b) diesel range compounds are significant; no recognizable pattern; c) aged diesel? is significant); d) gasoline range compounds are significant; e) unknown medium boiling point pattern that does not appear to be derived from diesel; f) one to a few isolated peaks present; g) oil range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; k) kerosene/kerosene range; l) bunker oil; m) fuel oil; n) stoddard solvent/mineral spirit.



<sup>#</sup> cluttered chromatogram resulting in coeluted surrogate and sample peaks, or; surrogate peak is on elevated baseline, or; surrogate has been diminished by dilution of original extract.

# QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704052

EPA Method SW8021B/8015Cm	Extraction SW5030B				BatchID: 27231 Sp			piked Sample ID: 0704022-016A				
Analyte	Sample Spiked MS			MSD	SD MS-MSD LCS LCSD			LCS-LCSD	Acc	eptance	Criteria (%)	
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(btex)	ND	0.60	112	97	13.9	102	108	5.89	70 - 130	30	70 - 130	30
МТВЕ	ND	0.10	111	120	7.88	107	105	1.86	70 - 130	30	70 - 130	30
Benzene	ND	0.10	95.2	102	6.79	93.9	92.5	1.47	70 - 130	30	70 - 130	30
Toluene	ND	0.10	90	90.2	0.181	86.2	84.8	1.62	70 - 130	30	70 - 130	30
Ethylbenzene	ND	0.10	97.2	97.3	0.115	94.4	94.7	0.326	70 - 130	30	70 - 130	30
Xylenes	ND	0.30	94.4	87.7	7.25	91.3	92	0.727	70 - 130	30	70 - 130	30
%SS:	79	0.10	87	107	20.3	97	102	4.46	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27231 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-001A	04/03/07 8:00 AM	04/03/07	04/05/07 2:06 AM	0704052-002A	04/03/07 8:01 AM	04/03/07	04/05/07 2:37 AM
0704052-004A	04/03/07 8:25 AM	04/03/07	04/05/07 3:07 AM	0704052-005A	04/03/07 8:45 AM	04/03/07	04/05/07 3:38 AM
0704052-006A	04/03/07 9:00 AM	04/03/07	04/05/07 4:08 AM	0704052-009A	04/03/07 11:05 AM	04/03/07	04/05/07 2:54 PM
0704052-010A	04/03/07 11:10 AM	04/03/07	04/05/07 6:40 AM	0704052-011A	04/03/07 11:15 AM	04/03/07	04/04/07 9:31 PM
0704052-012A	04/03/07 11:25 AM	04/03/07	04/04/07 10:01 PM				

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = <math>100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com

Telephone: 877-252-9262 Fax: 925-252-9269

# QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704052

EPA Method SW8015C	Extra	Extraction SW3550C				BatchID: 27232			Spiked Sample ID: 0704022-016A				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	,	
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD	
TPH(d)	ND	20	101	101	0	113	114	0.772	70 - 130	30	70 - 130	30	
%SS:	103	50	103	103	0	114	122	7.15	70 - 130	30	70 - 130	30	

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27232 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-001A	04/03/07 8:00 AM	04/03/07	04/04/07 4:19 PM	0704052-002A	04/03/07 8:01 AM	04/03/07	04/05/07 2:51 AM
0704052-004A	04/03/07 8:25 AM	04/03/07	04/04/07 5:27 PM	0704052-005A	04/03/07 8:45 AM	04/03/07	04/04/07 6:36 PM
0704052-006A	04/03/07 9:00 AM	04/03/07	04/04/07 4:14 PM	0704052-009A	04/03/07 11:05 AM	04/03/07	04/04/07 5:26 PM

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

# QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder 0704052

EPA Method SW8021B/8015Cm	Extraction SW5030B				BatchID: 27234 Sp			piked Sample ID: 0704052-008A				
Analyte	Sample Spiked MS			MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acceptance Criteria (%)			
	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(btexf	ND	60	90	93.5	3.76	106	108	1.74	70 - 130	30	70 - 130	30
MTBE	ND	10	82	87.4	6.44	115	109	5.08	70 - 130	30	70 - 130	30
Benzene	ND	10	87.5	90.8	3.70	95.3	99.8	4.60	70 - 130	30	70 - 130	30
Toluene	ND	10	87.3	91.1	4.34	103	110	6.71	70 - 130	30	70 - 130	30
Ethylbenzene	ND	10	92	95.2	3.37	96.4	107	10.1	70 - 130	30	70 - 130	30
Xylenes	ND	30	103	107	3.17	100	120	18.2	70 - 130	30	70 - 130	30
%SS:	95	10	90	90	0	93	98	5.29	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27234 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-008A	04/03/07 10:15 AM	04/06/07	04/06/07 1:52 AM	0704052-016A	04/03/07 12:30 PM	04/06/07	04/06/07 2:25 AM

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.

# QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder 0704052

EPA Method SW8260B	Extra	ction SW	5030B		Ba	tchID: 27	255	Sp	iked Sam	ple ID:	0704052-01	6B
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)
	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	10	94.6	95.3	0.701	90.2	92.3	2.29	70 - 130	30	70 - 130	30
Benzene	ND	10	103	103	0	99.1	99.9	0.838	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	50	93.8	93.1	0.777	91.4	89.6	2.00	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	10	109	110	0.395	105	106	1.27	70 - 130	30	70 - 130	30
Ethanol	ND	500	105	100	4.98	91	93	1.99	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	10	101	102	0.542	96.1	98	1.88	70 - 130	30	70 - 130	30
Methanol	ND	2500	102	101	0.476	100	100	0	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	10	101	102	0.843	95.8	97.7	2.01	70 - 130	30	70 - 130	30
Toluene	ND ,	10	95.1	90.2	5.37	90.2	90.3	0.110	70 - 130	30	70 - 130	30
%SS1:	121	10	95	100	4.65	95	96	1.09	70 - 130	30	70 - 130	30
%SS2:	102	10	102	101	0.879	100	100	0	70 - 130	30	70 - 130	30
%SS3:	110	10	108	108	0	109	108	0.583	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27255 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-008B	04/03/07 10:15 AM	04/04/07	04/04/07 6:54 PM	0704052-016B	04/03/07 12:30 PM	04/04/07	04/04/07 7:39 PM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



# QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704052

EPA Method SW8015C	Extra	Extraction SW3550C					BatchID: 27260			Spiked Sample ID: 0704052-010A				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)		
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD		
TPH(d)	ND	20	114	114	0	101	102	0.338	70 - 130	30	70 - 130	30		
%SS:	106	50	115	115	0	87	87	0	70 - 130	30	70 - 130	30		

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27260 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-010A	04/03/07 11:10 AM	04/03/07	04/04/07 4:19 PM	0704052-011A	04/03/07 11:15 AM	04/03/07	04/04/07 1:57 PM
0704052-012A	04/03/07 11:25 AM	04/03/07	04/04/07 1:57 PM	0704052-014A	04/03/07 11:55 AM	04/03/07	04/04/07 6:37 PM

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

# QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704052

EPA Method SW8021B/8015Cm	Extra	ction SW	5030B		BatchID: 27261			Sp	Spiked Sample ID: 0704052-014A				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)		
, many to	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD	
TPH(btex <sup>£</sup>	ND	0.60	94.8	93	1.93	102	108	5.94	70 - 130	30	70 - 130	30	
MTBE	ND	0.10	97.6	97.5	0.0785	104	107	2.75	70 - 130	30	70 - 130	30	
Benzene	ND	0.10	92.9	91.8	1.24	102	104	2.15	70 - 130	30	70 - 130	30	
Toluene	ND	0.10	85.2	85.2	0	94.6	95.4	0.861	70 - 130	30	70 - 130	30	
Ethylbenzene	ND	0.10	90.4	92.1	1.85	100	99.8	0.192	70 - 130	30	70 - 130	30	
Xylenes	ND	0.30	86.3	86.7	0.385	95.7	95.3	0.349	70 - 130	30	70 - 130	30	
%SS:	85	0.10	86	85	1.21	94	95	1.57	70 - 130	30	70 - 130	30	

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27261 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-014A	04/03/07 11:55 AM	04/03/07	04/05/07 7:41 AM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = <math>100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.



# QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704052

EPA Method SW8260B	Extra	ction SW	/5030B		Bat	tchID: 27	207	Sp	iked Sam	ple ID:	0703763-00	)2A
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	e Criteria (%)	 )
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	0.050	101	98.4	2.83	96.6	97.6	1.00	70 - 130	30	70 - 130	30
Benzene	ND	0.050	107	107	0	106	106	0	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	0.25	96	100	4.18	95.4	94.4	1.03	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	0.050	115	114	1.70	112	112	0	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	0.050	108	105	2.64	102	103	0.957	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	0.050	108	105	2.64	102	104	1.62	70 - 130	30	70 - 130	30
Toluene	ND	0.050	96.9	94.6	2.39	94.3	93.8	0.485	70 - 130	30	70 - 130	30
%SS1:	. 97	0.050	97	97	0	97	- 98	0.162	70 - 130	30	70 - 130	30
%SS2:	102	0.050	100	99	0.926	99	99	0	70 - 130	30	70 - 130	30
%SS3:	93	0.050	107	108	0.739	107	107	0	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27207 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-001A	04/03/07 8:00 AM	04/03/07	04/04/07 7:46 PM	0704052-002A	04/03/07 8:01 AM	04/03/07	04/04/07 8:32 PM
0704052-004A	04/03/07 8:25 AM	04/03/07	04/04/07 10:07 PM	ĺ			•


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



# QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder 0704052

EPA Method SW8260B	Extra	ction SW	/5030B		Bat	chID: 27	259	Sp	iked Samı	ole ID:	0704059-00	6A
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	0.050	96.5	95.4	1.12	96.8	96.1	0.733	70 - 130	30	70 - 130	30
Benzene	ND	0.050	101	101	0	98.2	101	2.66	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ИD	0.25	84.5	86.1	1.86	94.2	95.9	1.76	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	0.050	109	108	0.420	107	108	0.735	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	0.050	102	101	0.887	102	102	0	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	0.050	102	101	0.846	104	102	1.92	70 - 130	30	70 - 130	30
Toluene	ND	0.050	91.4	91.6	0.175	89.3	91.8	2.80	70 - 130	30	70 - 130	30
%SS1:	101	0.050	92	92	0	93	93	0	70 - 130	30	70 - 130	3.0
%SS2:	107	0.050	100	100	0	101	100	0.591	70 - 130	30	70 - 130	30
%SS3:	102	0.050	109	108	0.343	109	108	0.0728	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27259 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-005A	04/03/07 8:45 AM	04/03/07	04/05/07 3:39 AM	0704052-006A	04/03/07 9:00 AM	04/03/07	04/05/07 12:24 AM
0704052-009A	04/03/07 11:05 AM	04/03/07	04/05/07 1:11 AM	0704052-010A	04/03/07 11:10 AM	04/03/07	04/05/07 2:00 AM
0704052-011A	04/03/07 11:15 AM	04/03/07	04/04/07 1:39 PM	0704052-012A	04/03/07 11:25 AM	04/03/07	04/04/07 2:25 PM
0704052-014A	04/03/07 11:55 AM	04/03/07	04/05/07 2:49 AM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = <math>100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



# QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder 0704052

EPA Method SW8015C	Extra	Extraction SW3510C			BatchID: 27211				iked Sam	ple ID:	N/A	
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	
, many to	μg/L	µg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(d)	N/A	1000	N/A	N/A	N/A	114	111	2.50	N/A	N/A	70 - 130	30
%SS:	N/A	2500	N/A	N/A	N/A	110	111	0.719	N/A	N/A	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

## BATCH 27211 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-008A	04/03/07 10:15 AM	04/03/07	04/09/07 5:34 PM	0704052-016A	04/03/07 12:30 PM	04/03/07	04/04/07 9:32 PM

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

Consolidated Engineering Laborat	ineering Laborat Client Project ID: #81-01824-A;Livemore Airport UST/pipeline	Date Sampled:	04/03/07
2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583		Date Received:	04/03/07
	Client Contact: Chris Palmer	Date Reported:	04/10/07
	Client P.O.:	Date Completed:	04/16/07

WorkOrder: 0704052

April 16, 2007

Dear Chris:

## Enclosed are:

- 1). the results of 3 analyzed samples from your #81-01824-A;Livemore Airport UST/pipeline project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Best regards,

Angela Rydelius, Lab Manager

0704052- CEL

#### Consolidated Engineering Laboratories, Inc. **Chain of Custody** 2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583 Date: April 3, 2007 Proj. No. 81-01824-A Ph. 925/314-7100 Fx. 925/855-7140 Page \_ l of 2 Project name: Livemore Airport UST/pipe/me Date received: 4/3/07 Relinquished by: Clubdune Received by: CM Palmer DEXIL CARTAN Print name: Print name: Time received: 1500 Lab name: Company name: Consolidatal Evan Lap. MERAMPRELL Special Instructions ment, etutt, 1.210CA gall Recieved in good condition N-5 day turn Alease check for Jet Fuel in Analysis Requested Yes \_\_\_ No \_\_\_ Around Time TPHD unge Total # of Samples Date | Time Sample I.D. Matrix Comments N 4/3/07 0800 501 B-4-102.0-2.5 IN 0810 13-4-207,5-8.0 HOLD W) B-4-3011.5-120 0815 N B-4-4@15,5-160 0825 0845 B-4-5@19.5-20.0 W B-4-6@23.5-24.0 0900 HOLD B-4-7027.5-28.0 0920 413107 1015 water 4 N B-4 water

Consolidated Engineering Laboratories, Inc. **Chain of Custody** 2001 Crow Canyon Road, Suite 100 Date: <u>April 3</u> 2007 Proj. No. <u>81-01824-</u>A San Ramon, CA 94583 Ph. 925/314-7100 Fx. 925/855-7140 Page 2 of 2 Project name: Civernal Airport UST/Pipe/me Relinquished by: Clarature Date received: 4/3/07 Received by: r on Palmer Print name: Print name: DECIK CHETAM Time received: \_\_1300 Company name: Consolidated Euge LAIS MCCAMPIELL Lab name: 16:20 Special Instructions Recieved in good condition N-5 day tum. Please check fajet full m Matrix Number of samples Yes \_\_\_ No \_\_\_ Diesel runge Total # of Samples Sample I.D. Date | Time Comments B-5-10 3,5-4,0 4/3/07 1005 Soil N B-5-207,5-80 1110 B-5-3011.5-12.0 1115 13-5-4e15.5-16,0 1125 HOLD B-5-5@19,5-20,0 1140 11155 B-5-6@23.5-25 HOLD B-5-7c27,5-28. 1215 4/3/07/1230 Water 4 N B-Swater



1534 Willow Pass Rd

# **CHAIN-OF-CUSTODY RECORD**

Pittsburg, CA 94565- (925) 252-9262	1701				7	WorkO	rder:	07040	5 A		Client	tID: CI	CIL.				
				☐ EDF		Excel	!	Fax		<b>✓</b> Emai	1	☐ Har	dCopy	∏Thi	rdParty		
Report to: Chris Palmer Consolidated Engineeri 2001 Crow Canyon Roa San Ramon, CA 94583	d, Suite 100	TEL: 9	sp@ce-labs.c 25.485.5000 f81-01824-A			19	Co 20 Sa	nsolid: 01 Cro n Ram	w Can	ngineer yon Roa 94583	ad, Sui	ooratori te 100	1	Date A	ted TA eceive dd-On: rinted:	04/03 04/11	1/2007
									Par	unetod	Tacte	(See le	aend k	olow)			
Sample ID	ClientSampID		Matrix	Collection Date	Hold	1.	2	3	4	5	6	7	8	9	10	11	12
0704052-004	B-4-4@15.5-16.0	•	Soil	4/3/07 8:25:00 AM		Α							T	1			
0704052-008	B-4 water		Water	4/3/07 10:15:00			С			1	1						
0704052-016	B-5 Water		Water	4/3/07 12:30:00			С				<u> </u>						<u></u>
Test Legend:																	
1 9-0XYS_S	2	9-OXYS	w	3					4					5			
6	7			8				[	9					10			
11	12			<del></del>											•		
													Pre	epared b	y: Chlo	e Lam	

Comments:

Meoh, Etoh, and 1,2 DCA added 4/10/07 per C.P.

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.



"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories	Client Project ID: #81-01824- A;Livemore Airport UST/pipeline	Date Sampled: 04/03/07
2001 Crow Canyon Road, Suite 100	A,Livelilore Airport OS 1/piperine	Date Received: 04/03/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/11/07-04/12/07
- San Tamon, 67-7 15 36	Client P.O.:	Date Analyzed 04/12/07

Oxygenat	ed Volatile Organ	nics + EDB and 1	2-DCA by P&T a	and GC/MS*	
Extraction Method: SW5030B	Anal	ytical Method: SW826	0B	Work Order:	0704052
Lab ID	0704052-004B	0704052-008C	0704052-016C		
Client ID	B-4-4@15.5- 16.0'	B-4 water	B-5 Water		Limit for
Matrix	S	W	W		
DF	1	1	1	S	W
Compound		Conce	entration	mg/kg	μg/L
1,2-Dichloroethane (1,2-DCA)	ND	ND	ND	0.005	0.5
Ethanol	ND	ND	ND	0.25	50
Methanol	ND	ND	ND	2.5	500
	Surr	ogate Recoveries	s (%)		
%SS1:	95	99	97		
Comments					

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824A;Livemore Airport UST/pipeline

Date Sampled: 04/03/07

Date Received: 04/03/07

Date Extracted: 04/03/07

Client P.O.:

Date Analyzed: 04/04/07-04/05/07

Oxygenates and BTEX by GC/MS\* Extraction Method: SW5030B Analytical Method: SW8260B Work Order; 0704052 0704052-001A Lab ID 0704052-002A 0704052-005A 0704052-006A B-4-2@7.5-8.0' B-4-1@2.0-2.51 B-4-5@19.5-B-4-6@23.5-Client ID Reporting Limit for 20.0' 24.0' DF = 1Matrix S S S S DF 1 1 1 1 S Concentration Compound mg/kg ug/L tert-Amyl methyl ether (TAME) ND ND ND ND 0.005 NA ND ND Renzene ND ND 0.005 NA t-Butyl alcohol (TBA) ND ND ND ND 0.05 NA 1,2-Dichloroethane (1,2-DCA) ND ND ND ND NA 0.005 Diisopropyl ether (DIPE) ND ND ND ND 0.005 NA Ethanol ND ND ND ND 0.25 NA Ethylbenzene ND ND ND ND 0.005 NA Ethyl tert-butyl ether (ETBE) ND ND ND ND 0.005 NA Methanol ND ND ND ND 2.5 NA Methyl-t-butyl ether (MTBE) ND ND ND ND 0.005 NA Toluene ND ND ND ND 0.005 NA Xylenes ND ND ND ND 0.005 NΑ Surrogate Recoveries (%) %SS1: 103 101 97 95 %SS2: 105 105 105 104 %SS3: 102 101 107 107 Comments

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

Consolidated Engineering Laboratories	Client Project ID: #81-01824-	Date Sampled: 04/03/07
2001 Crow Canyon Road, Suite 100	A;Livemore Airport UST/pipeline	Date Received: 04/03/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/03/07
Sali Ration, CA 74303	Client P.O.:	Date Analyzed: 04/04/07-04/05/07
	Overgenates and RTFY by CC/MS*	

#### Oxygenates and BTEX by GC/MS\*

	Onjgon	ates and DIEM	y GC/1110			
Extraction Method: SW5030B	Anal	ytical Method: SW826	0B		Work Order:	0704052
Lab ID	0704052-009A	0704052-010A	0704052-011A	0704052-012A		
Client ID	B-5-1@3.5-4.0'	B-5-2@7.5-8.0'	B-5-3@11.5- 12.0'	B-5-4@15.5- 16.0'	Reporting DF	
Matrix	S	S	S	S		-1
DF	1	1	1	1	S	W
Compound		Conce	entration		mg/kg	ug/L
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	NA
Benzene	ND	ND	ND	ND	0.005	NA
t-Butyl alcohol (TBA)	ND .	ND	ND	ND	0.05	NA
1,2-Dichloroethane (1,2-DCA)	ND	ND	ND	ND	0.005	NA
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	NA
Ethanol	ND	ND	ND	ND	0.25	NA
Ethylbenzene	ND	ND ·	ND	ND	0.005	NA
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	NA
Methanol	ND	ND	ND	ND	2.5	NA
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	NA
Toluene	ND	ND	ND	ND	0.005	NA
Xylenes	ND	ND	ND	ND	0.005	NA
	Surr	ogate Recoverie	s (%)			
%SS1:	98	98	104	105		
%SS2:	106	104	108	106		
%SS3:	105	105	106	106		
Comments						

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Client Project ID: #81-01824-Consolidated Engineering Laboratories Date Sampled: 04/03/07 A:Livemore Airport UST/pipeline Date Received: 04/03/07 2001 Crow Canyon Road, Suite 100 Client Contact: Chris Palmer Date Extracted: 04/03/07 San Ramon, CA 94583 Client P.O.: Date Analyzed: 04/04/07-04/05/07 Oxygenates and BTEX by GC/MS\* Analytical Method: SW8260B Extraction Method: SW5030B Work Order: 0704052 Lab ID 0704052-014A B-5-6@23.5-251 Client ID Reporting Limit for DF =1 Matrix S DF 1 S W Concentration Compound mg/kg ug/L tert-Amyl methyl ether (TAME) ND 0.005 NA ND 0.005 NA Benzene t-Butyl alcohol (TBA) ND 0.05 NA 1,2-Dichloroethane (1,2-DCA) ND 0.005 NA NA Diisopropyl ether (DIPE) ND 0.005 NΑ Ethanol ND 0.25 0.005 Ethylbenzene ND NA Ethyl tert-butyl ether (ETBE) ND 0.005 NA Methanol ND 2.5 NA ND 0.005 NA Methyl-t-butyl ether (MTBE) Toluene ND 0.005 NA ND 0.005 NA **Xylenes** Surrogate Recoveries (%) %SS1: 95 %SS2: 104 %SS3: 105 Comments

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

### QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704052

EPA Method SW8260B	Extra	ction SW	5030B		Ba	tchID: 27	'323	Sp	iked Samı	ole ID:	0704151-00	1B
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)
Zilalyto	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	0.050	96.7	95.3	1.48	94.6	101	6.29	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	0.25	93.2	93.4	0.167	88.7	95.9	7.85	70 - 130	30	70 - 130	30
1,2-Dibromoethane (EDB)	ND	0.050	89.3	90.3	1.07	88.5	93.3	5.29	70 - 130	30	70 - 130	30
1,2-Dichloroethane (1,2-DCA)	ND	0.050	102	102	0	102	107	5.28	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ИD	0.050	112	111	0.150	110	116	4.69	70 - 130	30	70 - 130	30
Ethanol	ND	2.5	102	102	0	95.7	95.4	0.301	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	0.050	102	102	0	102	108	5.72	70 - 130	30	70 - 130	30
Methanol	ND	12.5	101	102	0.457	101	102	0.991	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	0.050	102	101	0.524	101	106	5.26	70 - 130	30	70 - 130	30
%SS1:	95	0.050	92	92	0	96	94	1.50	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27323 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-004B	04/03/07 8:25 AM	04/11/07	04/12/07 2:53 AM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com

Telephone: 877-252-9262 Fax: 925-252-9269

### **OC SUMMARY REPORT FOR SW8260B**

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704052

EPA Method SW8260B	Extra	ction SW	5030B		Ba	tchID: 27	401	Sp	iked Samı	ole ID:	0704242-00	6B
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	
Analyte	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	10	97.8	96.8	1.06	94.2	94.9	0.786	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	50	89	85.8	3.61	88.8	90.2	1.64	70 - 130	30	70 - 130	30
1,2-Dibromoethane (EDB)	ND	10	87.6	87.4	0.254	88.2	88	0.189	70 - 130	30	70 - 130	30
1,2-Dichloroethane (1,2-DCA)	ND	10	105	105	0	102	102	. 0	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	10	114	112	1.51	110	110	0	70 - 130	30	70 - 130	30
Ethanol	ND	500	95.6	92.5	2.99	92.4	99.1	6.49	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	10	105	104	0.490	101	101	0	70 - 130	30	70 - 130	30
Methanol	ND	2500	101	100	0.792	101	100	0.435	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	10	103	103	0	99.7	101	1.08	70 - 130	30	70 - 130	30
%SS1:	104	10	95	94	1.14	94	94	0	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27401 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704052-008C	04/03/07 10:15 AM	1 04/12/07	04/12/07 9:42 PM	0704052-016C	04/03/07 12:30 PM	04/12/07	04/12/07 10:27 PM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



Consolidated Engineering Laborat	Client Project ID: #81-01824-A; Livermore Airport UST/Pipeline	Date Sampled:	04/03/07-04/04/07
2001 Crow Canyon Road, Suite	All port OS 1/Pipeline	Date Received:	04/04/07
100 San Ramon, CA 94583	Client Contact: Chris Palmer	Date Reported:	04/11/07
,	Client P.O.:	Date Completed:	04/11/07

WorkOrder: 0704083

April 11, 2007

Dear Chris:

#### Enclosed are:

- 1). the results of 23 analyzed samples from your #81-01824-A; Livermore Airport UST/Pipeline project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Best regards,

Angela Rydelius, Lab Manager

Consolidated I 2001 Crow Can San Ramon, CA	yon F	load, S			orie	:S,	lnc	•															of			st	OC	ly
Ph. 925/314-71 Fx. 925/855-714							······································		•									Pı	oj.	.No	) D. <u>{</u>	<u>31</u>	-0(	824	- M			ļ
Project name: <u>Ci</u>	vemo	re An	port	И	57,	1P,	pl	liv	e						···			Pa	3 <b>9</b> (	<del>-</del>			of _	<u> </u>	_			
Relinquished by: Print name: Company name:	_ C 0	u pal 11	extensi	Los	P	rint	ved nan	ne:	1	X10	IK	Oh	STA		<u> </u>								<u> </u>				7	
Special Instructions N - 5 day tumanum Please check TPHO Pa	d ugl for	jet feul	2	ber of samples	Tum Around Time	ysis Requested		1/67EX/MT8E+ 5015/60-60B	Diasel 8015														Yes	3 <u></u>	_ N	lo	nditio	
Sample I.D.	Date	Time	Matrix	Num	Tu	Amaí		TPH SXYS	TON															. C	omr	nent	\$	
B-6-1035-4.0	413/67	1335	Soil	1	N																		炮	<b>=</b> 7).				
B-6-20T.5-80		1340		1	N				_									$\perp$				L						
B-6-3011,5-12.0		1350		1	N	_								_			Ļ	1				L		·				
B-6-4@15.5-14.0		1400		1	W				$\angle$					<u> </u>		_	Ļ	1	_			_				_		
B-6-50 19.5-20.0		1415		1	W	_										_	L		_	<b></b>		_						
B-6-6023,5-24	<del>                                     </del>	1440	<u> </u>	1	N				$\angle$								<u> </u>	_	_		_	<del> </del>						
B6-70275-28		1520	<del>                                     </del>	1	M		_							- 1	E/I	2	10	٤ ا	4	/	1	ļ_						
13-6-8031,5-32		1545	<del>                                     </del>	1	N	<u> </u>		$\triangle$	4					Z:	OOD	-	عبنا	-	41				PROPR		/			
<del>/                                    </del>	1,1,5	100	. 40	Ļ	<del> </del>	ļ	_		_,					D	ECHI	ORn	TA	ED I	N I	. /	a.C	PR	ESERV BIALS	ED IN			·	
B-to water	1913/01	1625	unter	4	-				4	_			_	P	RESE	RVA	110	N_	4			F			<u> </u>	••••		

·	Consolidated I 2001 Crow Can San Ramon, CA	nyon R	Road, S			orie	<del>2</del> \$,	inc	• /#												n of Custody
	Ph. 925/314-71 Fx. 925/855-714						-,											Pro	oj. N	lo. <u>8</u>	81-01824-14
	Project name:(	Livern	nove.	Atupo	<u>+</u>	US	; <u>T</u>	Pi	pė	In	<u></u>							Pa	ge_	2	_ of _5_
	Relinquished by: Print name: Company name:	am.	Palmer	1-	<u></u>	P	ecei rint .ab r	nar	me:	7		YU.	K C	MC		- - -					d: <u>April 4, 2007</u> ed: 1755
	Special Instructions N-5 day tuman Please Leck TPHD ro	orend ange of	n jet l	fuel  Matrix	ber of samples	Around Time	Analysis Requested	TOHGIBTEXIMTBET	resel rais												Recleved in good condition Yes No Total # of Samples
	Sample I.D.	Date	Time	Matrix	Num	Tum	Anafy	TAHG	Tomb												. Comments
	B-7=3@11.5-12.0	413/07	1700	Soil		7		Z	Z								1	1_			
	13-7-48 15,5-16.0		1715			N		Z	/									$\mathbb{L}$			
	B-7-50 19.5-20.0	<del>                                     </del>	1735		11	N			$\angle$	_											
	B-7-6@23.5-24.0		1750	'	4	N	1			1_									<u> </u>		
	13-7-70 27.5-28.0	ļ'	1805		1.	N	<u></u>		L	$oldsymbol{oldsymbol{oldsymbol{oldsymbol{\bot}}}$		4				_			$oldsymbol{ol}}}}}}}}}}}}}}$		HOLD
20		1	<u></u>	<del> </del> '	<u>Ļ</u> '	<u> </u>	╄	<u> </u>	<u>_</u>	<u> </u>	$\sqcup$	_	Щ			_			_		
$\nu$	B-7 worter	H3107	1845	Water	4	M	<del> </del>		Z	<del>_</del>	$\bot$			$\dashv$		_				_	
			<del> </del>	-	<b> </b> '	<del> </del>	<del> </del>		<del> </del>	<del>                                     </del>		-		_	$\dashv$	-+		4-	<u> </u>	-	
		<b>}</b> '	<del></del>	<u> </u>	<del></del>	<del>  '</del>	<del> -</del>		├-	—	$\vdash$			$\dashv$	$\rightarrow$	-+		-	╄		
		<b></b> '		1	<b>—</b>	-	┼		├					-		-+	-		_		

	Consolidated I 2001 Crow Can San Ramon, CA Ph. 925/314-71 Fx. 925/855-714 Project name:	yon R A 9458 00 40	oad, S	uite 10	00					7. 0				;			I F	Date Proj	e: <u>/</u> .:No	<u>)pn</u>	of Custody (14, 2007) (151-01824-A) (of 5
	Relinquished by:	Cem	Elme			Re	ecei	ived	by	1:	er De Vector	VUI.	<u> </u>	AV	TA	- 7~(					1: <u>April 4, 2007</u> d: <u>1758</u>
	Special Instructions N-5 day fumar	arnd			nber of samples	Tum Around Time	Analysis Requested		TOHG/BJEXIMTBE+ dxys 801.513+8260B	brisel saiss											Recieved in good condition Yes No Total # of Samples
	Sample I.D.	Date	Time	Matrix	N P	Ę	Anal		10HG 0XXS	五											Comments
	B-8-103,5-4.0	414/07		Soil	1	N				Z											
	B-8-207.5-8.0'	<del>                                     </del>	0810		1	N	_													·	HOLD
	B-8-3@11.5-12	<del>                                     </del>	0820		1	M	_					_	_				 				HOLD
	B-8-4@15.5-160	<del> -</del> -	0830	<del>                                     </del>	<u> </u>	K	-		_	K	_	_	_		<b>-</b>		 				1.4. 1
	B-8-5019.5-20	<del>                                     </del>	0640		1	N	-										 				HOLD
	B-8-6@23.5-24		0855		1	N	-	┞╶┤	_	$\vdash$	-					_	 				Lie A
	6 6 10 775 28	1	CO TO		12	對	-	<del>  -  </del>													HEED .
t40	B-8-ainter	414107	1310	worter	4	Ŋ			Z	Z											
		<del> </del>			-	-	<del> </del>	H				$\dashv$	$\dashv$		-						

ody
dition
· · · · · · · · · · · · · · · · · · ·
_

Consolidated Engine 2001 Crow Canyon R San Ramon, CA 9458	oad, S			orie	<b>≥</b> S,	Inc												of Custody
Ph. 925/314-7100 Fx. 925/855-7140					•									- 1	Proj. No. 81-01824-A			
	ect name: Livemore Airpo				+, UST/Pipeline										Page <u>5</u> of <u>5</u>			
Print name: CM	Relinquished by: CMPalmer Print name: CMPalmer Company name: Causolidated Engr. Laborated Park C					Print name: Dalle Wirth									Date received: April 4, 2007 Time received: 1755			
Special Instructions N-5 day townsmud Please check TPHD rong	c faje		ber of samples	Around Time	rsis Requested	107EX/MTBE+	1, esel 67 8015B											Recieved in good condition  Yes No  Total # of Samples
Sample I.D. Date	Time	Matrix	N E	Tum	Anat	PPHG PXXO	That					_						Comments
B-10-1 c 3.5-4,0 414107		Soil	1	N								$\Box$						
B-10-20.7.5-8.0' 4/4/07		Sail	1	M														HOLD
B-10-3-C11.5-12 414/07		Soil		N														HOLD
B-10-4@15.5-16- 414/07		Soil	1	N			$\angle$		<u> </u>									
B-10-5019.5-20 4140	1220	Soil	1	N					$\bot$									HOLD
B-10-60 23.5-24 4/4/07	1235	Soil	1	N	ļ_	/	4				_	$\blacksquare$	1		_			
13-10 water 4/4/07	1400	water	4	N	-	7		+-	+	$\left  \cdot \right $	$\dashv$	-	+	-	-	-		
	1	1	1	1	1		1	1	1	1	ŀ	- 1	-	- 1 -	1			

1534 Willow Pass Rd Pittsburg, CA 94565-1701

# **CHAIN-OF-CUSTODY RECORD**

(925) 25	2-9262				Work	Order	: 0704	083	Clientl	D: CEL					
			☐ EDF	Ε	]Excel		Fax	V	] Email	☐ HardCo	эру	∏Thi	rdParty		
	d Engineering Laboratori Canyon Road, Suite 100	Email: cp@ce-labs. TEL: 925.485.500 ProjectNo: #81-01824-A PO:	0 FAX: 925,48			Co 20 Sa	onsolida 01 Crov	v Canyor on, CA 9	ineering La n Road, Sui 4583		Da	te Rec		04/04/ 04/10/	
								Reque	ested Tests	(See lege	nd h	elow)			=
Sample ID	ClientSamplD	Matrix	Collection Date	Hold	1	2	3	4	5 6	7	8	9	10	11	12
0704083-001	B-6-1 @ 3.5-4.0	Soil	4/3/07 1:35:00 PM		Α		A			7- 1		T	Т	T	T -
0704083-002	B-6-2 @ 7.5-8.0	Soil	4/3/07 1:40:00 PM				Α			+		<u> </u>	-	<del></del>	
0704083-004	B-6-4 @ 15.5-16.0	Soil	4/3/07 2:00:00 PM		Α		Α					<b>†</b>	1	<del> </del>	<del>                                     </del>
0704083-006	B-6-6 @ 23.5-24	Soil	4/3/07 2:40:00 PM		Α		Α				-	<del>                                     </del>		<del>                                     </del>	├──
0704083-008	B-6-8 @ 31.5-32	Soil	4/3/07 3:45:00 PM		Α		Α					1	+	<del></del>	├
0704083-009	B-6 Water	Water	4/3/07 4:25:00 PM			Α		В					<del> </del>		<del> </del>
0704083-010	B-7-3 @ 11.5-12.0	Soil	4/3/07 5:00:00 PM		A		Α					1	<del> </del>		$\vdash$
0704083-011	B-7-4 @ 15.5-16.0	Soil	4/3/07 5:15:00 PM		A		Α					†	<del>                                     </del>		├──
0704083-012	B-7-5 @ 19.5-20.0	Soil	4/3/07 5:35:00 PM		Α	-	Α						<del> </del>	<u> </u>	<del>                                     </del>
0704083-013	B-7-6 @ 23.5-24.0	Soil	4/3/07 5:50:00 PM		Α		Α						<del> </del>		<del>                                     </del>
0704083-015	B-7 Water	Water	4/3/07 6:45:00 PM			Α		В					<del> </del>	<del> </del>	<del> </del>
0704083-016	B-8-1 @ 3.5-4.0	Soil	4/4/07 8:05:00 AM		Α		Α								<del>                                     </del>
0704083-019	B-8-4 @ 15.5-16.0	Soil	4/4/07 8:30:00 AM		Α		Α						<del> </del>	<u> </u>	
0704083-021	B-8-6 @ 23.5-24	Soil	4/4/07 8:55:00 AM		Α		Α						<del> </del>		<u></u>
0704083-022	B-8-Water	Water	4/4/07 1:10:00 PM			Α		В							
Test Legend:												1			· · · · · ·
1 G-MBT	EX_S 2 7	G-MBTEX_W	3 MBTEX	DXY-	3260B_	3	4		XOXY-8260	B_W_		5			
			8		<del> </del>		9	<u> </u>	······		[1	10			
The following Samp 0704083-011A, 070	pIDs: 0704083-001A, 0704083- 04083-012A, 0704083-013A, 07	002A, 0704083-004A, 070 704083-015A, 0704083-01	4083-006A, 0704083- 6A, 0704083-019A, 0	008A 7040	., 07040 83-021 <i>/</i>	83-009. N, 07040	A, 07040 083-022/	83-010A, A,		P	repai	red by:	Meliss	sa Valle	<u>s</u>

#### **Comments:**



1534 Willow Pass Rd Pittsburg, CA 94565-1701 (925) 252-9262

## **CHAIN-OF-CUSTODY RECORD**

0704000

Page 1 of 1

workOrder:	0/04083	Chentid:	CEL

☐ EDF Excel □ Fax **▼** Email HardCopy ThirdParty Report to: Bill t Requested TAT: 5 days Chris Palmer Email: cp@ce-labs.com Accounts Payable Consolidated Engineering Laboratori TEL: 925.485.5000 FAX: 925.485.5019 Consolidated Engineering Laboratori 2001 Crow Canyon Road, Suite 100 ProjectNo: #81-01824-A; Livermore Airport UST/Pi Date Received 04/04/2007 2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583 San Ramon, CA 94583 Date Printed: 04/10/2007 ap@ce-labs.com

XX7.-.1-0-..1.

								Req	uested	Tests	(See le	gend b	elow)			
Sample ID	ClientSamplD	Matrix	Collection Date	Hold	1	2	3	4	5	6	7	8	9	10	11	12
0704083-023	B-9-1 @ 3.5-4.0	Soil	4/4/07 9:35:00 AM		Α	<u> </u>	A			1	T	Τ	Г	Γ		$\overline{}$
0704083-026	B-9-4 @ 15.5-16.0	Soil	4/4/07 10:15:00		Α		A		<u> </u>		T	1	<del> </del>			$\overline{}$
0704083-028	B-9-6 @ 23.5-24	Soil	4/4/07 10:35:00		Α		Α		<b>†</b>			1 -	<del> </del>	-		
0704083-029	B-9 Water	Water	4/4/07 2:25:00 PM			Α	i	В	<u> </u>				<del> </del>	<del> </del>		$\vdash$
0704083-030	B-10-1 @ 3.5-4.0	Soil	4/4/07 11:20:00		Α		Α		ļ				<del> </del>		<del> </del>	<u> </u>
0704083-033	B-10-4 @ 15.5-16	Soil	4/4/07 12:10:00		Α		Α					<del> </del>	<del> </del>	-	<u></u>	<u> </u>
0704083-035	B-10-6 @ 23.5-24	Soil	4/4/07 12:35:00		Α		A				1		†			<del> </del>
0704083-036	B-10 Water	Water	4/4/07 2:00:00 PM			Α		В				1	<del> </del>			<del>                                     </del>

#### Test Legend:

1 G-MBTEX_S	2 G-MBTEX_W	3 MBTEXOXY-8260B_S	4 MBTEXOXY-8260B_W	5
6	7	8	9	10
11	42	_		

The following SampIDs: 0704083-001A, 0704083-002A, 0704083-004A, 0704083-006A, 0704083-008A, 0704083-009A, 0704083-010A, 0704083-011A, 0704083-012A, 0704083-013A, 0704083-015A, 0704083-016A, 0704083-019A, 0704083-021A, 0704083-022A,

Prepared by: Melissa Valles

#### **Comments:**

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.

Client Name:

Comments:

Consolidated Engineering Laboratories

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Date and Time Received: 4/4/07 6:25:18 PM

### Sample Receipt Checklist

Project Name: #81-01824-A; Livermore Airport	UST/Pipeline	Checklist	completed and reviewed by:	Melissa Valles
WorkOrder N°: 0704083 Matrix Soil/Water		Carrier:	Courier	
<u>Cha</u>	in of Custody (C	COC) Informatio	<u>n</u>	
Chain of custody present?	Ye 🗹	No 🗆		
Chain of custody signed when relinquished and received?	Ye 🗹	No 🗆		
Chain of custody agrees with sample labels?	Ye 🗹	No 🗌		
Sample IDs noted by Client on COC?	Ye 🔽	No 🗆		
Date and Time of collection noted by Client on COC?	Ye 🗹	No 🗆		
Sampler's name noted on COC?	Ye 🗹	No 🗆		
	Sample Receipt	Information		
Custody seals intact on shippping container/cooler?	Ye 🗆	No 🗆	NA 🗹	
Shipping container/cooler in good condition?	Ye 🗹	No □		
Samples in proper containers/bottles?	Ye 🗹	No 🗆		
Sample containers intact?	Ye 🗸	No □		
Sufficient sample volume for indicated test?	Ye 🗹	No 🗆		
Sample Pres	ervation and Ho	old Time (HT) Int	formation	
All samples received within holding time?	Ye 🗸	No 🗆		
Container/Temp Blank temperature	Cooler Temp:	6.3°C	na 🗆	
Water - VOA vials have zero headspace / no bubbles?	Ye 🔽	No □ No	VOA vials submitted	
Sample labels checked for correct preservation?	Ye 🗹	No 🗌		
Client contacted: Date conta	cted:		Contacted by:	



"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269


Consolidated Engineering Laboratories	Client Project ID: #81-01824-A; Livermore Airport UST/Pipeline	Date Sampled: 04/03/07-04/0	04/07
2001 Crow Canyon Road, Suite 100	Diverniere 7 in point 0 0 1/1 i pennie	Date Received: 04/04/07	
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/04/07-04/0	07/07
	Client P.O.:	Date Analyzed 04/06/07-04/0	07/07

Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline\* Extraction method: SW5030B Analytical methods: SW8015Cm Work Order: 0704083 Lab ID Client ID Matrix TPH(g) DF 001A B-6-1 @ 3.5-4.0 S ND 85 002A B-6-2 @ 7.5-8.0 S ND 90 1 004A B-6-4 @ 15.5-16.0 S ND 88 006A B-6-6 @ 23.5-24 S ND 1 99 008A B-6-8 @ 31.5-32 S ND 92 009A B-6 Water W ND,i 1 97 010A B-7-3 @ 11.5-12.0 S ND 1 90 011A B-7-4 @ 15.5-16.0 S ND 1 94 012A B-7-5 @ 19.5-20.0 S ND 89 013A B-7-6 @ 23.5-24.0 S ND 1 91 015A B-7 Water W ND,i 1 95 016A B-8-1 @ 3.5-4.0 S ND 1 87 019A S B-8-4 @ 15.5-16.0 ND 1 90 021A B-8-6 @ 23.5-24 S ND 1 85 022A B-8-Water W ND,i 97 023A B-9-1 @ 3.5-4.0 S ND 82 Reporting Limit for DF =1; W 50 μg/L ND means not detected at or

above the reporting limit	S	1.0	mg/Kg
* water and vapor samples and all TCLP & SPLP extraproduct/oil/non-aqueous liquid samples in mg/L.	cts are repo	rted in µg/L, soil/sludge/solid samples in mg/kg, wipe samples	in μg/wipe,

<sup>#</sup> cluttered chromatogram; sample peak coelutes with surrogate peak.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (stoddard solvent / mineral spirit?); f) one to a few isolated non-target peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) reporting limit raised due to high MTBE content; k) TPH pattern that does not appear to be derived from gasoline (aviation gas). m) no recognizable pattern; n) TPH(g) value derived using a client specified carbon range; o) results are reported on a dry weight basis; p) see attached narrative.





"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories	Client Project ID: #81-01824-A; Livermore Airport UST/Pipeline	Date Sampled: 04/03/07-04/04/07
2001 Crow Canyon Road, Suite 100	Livermore Airport OS 1/Fiperme	Date Received: 04/04/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/04/07-04/07/07
,	Client P.O.:	Date Analyzed 04/06/07-04/07/07

		Chefit I .O.,	Date Analyze	a 04/06/07-04/0	1//0/
			e Hydrocarbons as Gasoline*		
Extraction method: S'		Analytical meth	ods: SW8015Cm	Work Order: 07	04083
Lab ID	Client ID	Matrix	TPH(g)	DF	% S
026A	B-9-4 @ 15.5-16.0	S	ND	1	86
028A	B-9-6 @ 23.5-24	S	ND	1	86
029A	B-9 Water	w	ND,i	1	96
030A	B-10-1 @ 3.5-4.0	S	ND	1	82
033A	B-10-4 @ 15.5-16	S	ND	1	86
035A	B-10-6 @ 23.5-24	S	ND	1	84
036A	B-10 Water	w	ND,i	1	91
	rting Limit for DF =1;	W	50	ц	<u>'</u> L
	eans not detected at or ve the reporting limit	S	1.0		/Kg

ND means not detected at or		30	L μg/L
above the reporting limit	S	1.0	mg/Kg
* water and vapor samples and all TCLP & SPLP extrac	ts are repo	rted in µg/L, soil/sludge/solid samples in mg/kg, wipe samples	in ug/wine

# cluttered chromatogram; sample peak coelutes with surrogate peak.

product/oil/non-aqueous liquid samples in mg/L.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (stoddard solvent / mineral spirit?); f) one to a few isolated non-target peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) reporting limit raised due to high MTBE content; k) TPH pattern that does not appear to be derived from gasoline (aviation gas). m) no recognizable pattern; n) TPH(g) value derived using a client specified carbon range; o) results are reported on a dry weight basis; p) see attached narrative.



"When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories Client Project ID: #81-01824-A; Date Sampled: 04/03/07-04/04/07 Livermore Airport UST/Pipeline 2001 Crow Canyon Road, Suite 100 Date Received: 04/04/07 Client Contact: Chris Palmer Date Extracted: 04/04/07-04/06/07 San Ramon, CA 94583 Client P.O.: Date Analyzed: 04/05/07-04/06/07

Oxygenates and BTEX by GC/MS*										
Extraction Method: SW5030B	Ana	Analytical Method: SW8260B								
Lab ID	0704083-001A	0704083-001A								
Client ID	B-6-1 @ 3.5-4.0	B-6-2 @ 7.5-8.0	B-6-4 @ 15.5- 16.0	B-6-6 @ 23.5-24	Reporting Limit for					
Matrix	S	S	S	S	DF =1					
DF	1	1	1	1	S	W				
Compound		Conce	entration		mg/kg	μg/L				
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	0.5				
Benzene	ND	ND	ND	ND	0.005	0.5				
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0				
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5				
Ethylbenzene	ND	ND	ND	ND	0.005	0.5				
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5				
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5				
Toluene	ND	ND	ND	ND	0.005	0.5				
Xylenes	ND	ND .	ND	ND	0.005	0.5				
	Surre	gate Recoveries	(%)							
%SS1:	105	106	104	107						
%SS2:	106	106	104	103						
%SS3:	106	103	106	102						
Comments					· · · · · · · · · · · · · · · · · · ·					

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



"When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

Client Project ID: #81-01824-A;
Livermore Airport UST/Pipeline

Date Sampled: 04/03/07-04/04/07

Date Received: 04/04/07

Client Contact: Chris Palmer

Date Extracted: 04/04/07-04/06/07

Client P.O.:

Date Analyzed: 04/05/07-04/06/07

#### Oxygenates and BTEX by GC/MS\*

	Oxygen	ates and BIEX b	y GC/MS*				
Extraction Method: SW5030B	Anal	lytical Method: SW826	60B	_	Work Order:	0704083	
Lab ID	0704083-008A	0704083-009B	0704083-010A	0704083-011A			
Client ID	B-6-8 @ 31.5-32	B-6 Water	B-7-3 @ 11.5- 12.0	B-7-4 @ 15.5- 16.0	Reporting		
Matrix	S	W	S	S	DF =1		
DF	1	1	1	. 1	S	W	
Compound	·	Conce	entration		mg/kg	μg/L	
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	0.5	
Benzene	ND	ND	ND	ND	0.005	0.5	
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0	
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5	
Ethylbenzene	ND	ND	ND	ND	0.005	0.5	
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5	
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5	
Toluene	ND	ND	ND	ND	0.005	0.5	
Xylenes	ND	ND	ND	ND	0.005	0.5	
	Surre	gate Recoveries	s (%)				
%SS1:	105	115	103	102			
%SS2:	103	105	104	104			
%SS3:	102	107	103	103			
Comments		i			<u> </u>	****	

<sup>\*</sup> water and vapor samples are reported in μg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in μg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



				Totopitono, C	177-232-9202 Fax: 92	3-232-7207	
Consolidated Engineering Laborate			oject ID: #81-01		Date Sampled:	04/03/07-0	4/04/07
2001 Crow Canyon Road, Suite 100		Livermore Airport UST/Pipeline			Date Received: 04/04/07		
San Ramon, CA 94583		Client Co	ontact: Chris Pal	mer	Date Extracted:	04/04/07-0	4/06/07
,		Client P.	O.:		Date Analyzed: 04/05/07-04/06/07		
		Oxygen	ates and BTEX b	y GC/MS*			
Extraction Method: SW5030B		Anal	ytical Method: SW826	0B		Work Order:	0704083
Lab ID	070408	3-012A	0704083-013A	0704083-015B	0704083-016A		
Client ID	B-7-5 @ 20	@ 19.5- ).0	B-7-6 @ 23.5- 24.0	B-7 Water	B-8-1 @ 3.5-4.0		Limit for
Matrix	S	S	S	W	S	υr	=1
DF	1	1	1	1	1	S	w
Compound		Concentration				mg/kg	μg/L
tert-Amyl methyl ether (TAME)	N.	D	ND	ND	ND	0.005	0.5
Benzene	N	D	ND	ND	ND	0.005	0.5
t-Butyl alcohol (TBA)	N	D	ND	ND	ND	0.05	5.0
Diisopropyl ether (DIPE)	N	D	ND	ND	ND	0.005	0.5
Ethylbenzene	N	D	ND	ND	ND	0.005	0.5
Ethyl tert-butyl ether (ETBE)	NI	D	ND	ND	ND	0.005	0.5
Methyl-t-butyl ether (MTBE)	N	D	ND	ND	ND	0.005	0.5
Toluene	NI	D	ND	ND	ND	0.005	0.5
Xylenes	NI	D	ND	ND	ND	0.005	0.5
		Surro	gate Recoveries	(%)			
%SS1:	10	)2	102	115	102		
%SS2:	10	)4	104	104	104		
%SS3:	10	)2	103	109	103		

<sup>\*</sup> water and vapor samples are reported in μg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in μg/wipe.




Comments

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824-A;
Livermore Airport UST/Pipeline

Date Sampled: 04/03/07-04/04/07

Date Received: 04/04/07

Client Contact: Chris Palmer
Date Extracted: 04/04/07-04/06/07

Client P.O.:

Date Analyzed: 04/05/07-04/06/07

Oxygenates and BTEX by GC/MS\*

	Oxyger	ates and BTEX b	y GC/MS*			
Extraction Method: SW5030B	Ana	lytical Method: SW826	0B		Work Order:	0704083
Lab ID	0704083-019A	0704083-021A	0704083-022B	0704083-023A		
Client ID	B-8-4 @ 15.5- 16.0	B-8-6 @ 23.5-24	B-8-Water	B-9-1 @ 3.5-4.0	Reporting DF	
Matrix	S	S	W	S	Dr	=1
DF	1	1	1	1	S .	w
Compound		Conce	entration		mg/kg	μg/L
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	0.5
Benzene	ND	ND	ND	ND	0.005	0.5
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5
Ethylbenzene	ND	ND	ND	ND	0.005	0.5
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5
Toluene	ND	ND	ND	ND	0.005	0.5
Xylenes	ND	ND	ND	ND	0.005	0.5
	Surr	ogate Recoveries	(%)		·	
%SS1:	100	97	115	97		
%SS2:	104	107	105	105		
%SS3:	102	104	108	103		
Comments			i			

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.


h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.

Consolidated Engineering Laboratories Client Project ID: #81-01824-A; Date Sampled: 04/03/07-04/04/07 Livermore Airport UST/Pipeline Date Received: 04/04/07 2001 Crow Canyon Road, Suite 100 Client Contact: Chris Palmer Date Extracted: 04/04/07-04/06/07 San Ramon, CA 94583 Client P.O.: Date Analyzed: 04/05/07-04/06/07

#### Oxygenates and BTEX by GC/MS\*

Extraction Method: SW5030B	Δ Δ	lytical Method: SW826	OP.		Work Order:	0704083	
	Lab ID 0704083-026A 0704083-028A 0704083-029B 0704083-030A						
Lau ID			0704083-029B	<u> </u>			
Client ID	B-9-4 @ 15.5-	B-9-6 @ 23.5-24	B-9 Water	B-10-1 @ 3.5-4.0	Reporting	Limit for	
	16.0					=1	
Matrix	S	S	W	S			
DF	1	1	1	1	S	W	
Compound		Conce	entration		mg/kg	μg/L	
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	0.5	
Benzene	ND	ND	ND	ND	0.005	0.5	
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	5.0	
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	0.5	
Ethylbenzene	ND	ND	ND	ND	0.005	0.5	
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	0.5	
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	0.5	
Toluene	ND	ND	ND	ND	0.005	0.5	
Xylenes	ND	ND	ND	ND	0.005	0.5	
	Surr	ogate Recoveries	(%)				
%SS1:	95	93	109	96			
%SS2:	106	104	105	104			
%SS3:	101	102	106	102			
Comments			i				

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.



ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Consolidated Engineering Laborate	ories	ries Client Project ID: #81-01824-A; Livermore Airport UST/Pipeline			Date Sampled:	04/03/07-0	4/04/07
2001 Crow Canyon Road, Suite 100	Livermo	re Airport US1/Pi	peline	Date Received: 04/04/07			
San Ramon, CA 94583	Client C	ontact: Chris Pal	mer	Date Extracted: 04/04/07-04/06/07			
San Kamon, CA 94383		Client P.	O.:		Date Analyzed:	04/05/07-0	4/06/07
		Oxygen	ates and BTEX b	y GC/MS*			
Extraction Method: SW5030B		Anal	ytical Method: SW826	0B		Work Order:	0704083
Lab ID	07040	83-033A	0704083-035A	0704083-036B			
Client ID		1 @ 15.5- 16	B-10-6 @ 23.5- 24	B-10 Water		Reporting DF	
Matrix		S	S	W		) Dr	-1
DF		1	1	1		S	W
Compound			Conce	entration		mg/kg	μg/L
tert-Amyl methyl ether (TAME)	]	ND	ND	ND		0.005	0.5
Benzene	]	ND	ND	ND		0.005	0.5
t-Butyl alcohol (TBA)	]	ND	ND	ND		0.05	5.0
Diisopropyl ether (DIPE)	]	ND	ND	ND		0.005	0.5
Ethylbenzene	. ]	ND	ND	ND		0.005	0.5
Ethyl tert-butyl ether (ETBE)	]	ND	ND	ND		0.005	0.5
Methyl-t-butyl ether (MTBE)	1	ND	ND	ND		0.005	0.5
Toluene	]	ND	ND	ND		0.005	0.5
Xylenes	]	ND	ND	ND		0.005	0.5
		Surr	ogate Recoveries	(%)			
%SS1:		95	94	112			
%SS2:	:	104	103	106			
%SS3:		104	102	108			
Comments		i					

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



"When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

Client Project ID: #81-01824-A;
Livermore Airport UST/Pipeline

Date Sampled: 04/03/07-04/04/07

Date Received: 04/04/07

Client Contact: Chris Palmer

Date Extracted: 04/04/07

Client P.O.:

Date Analyzed: 04/05/07-04/10/07

## Diesel (C10-23) and Jet Fuel (C9-C18) Range Extractable Hydrocarbons as Diesel and Jet Fuel\*

Extraction method: SW	3510C/SW3550C	C Analytical methods: SW8015C Work				k Order: 0704083	
Lab ID	Client ID	Matrix	TPH(d)	TPH(jf)	DF	% SS	
0704083-001A	B-6-1 @ 3.5-4.0	S	ND	ND	1	112	
0704083-002A	B-6-2 @ 7.5-8.0	S	ND	ND	1	89	
0704083-004A	B-6-4 @ 15.5-16.0	·S	ND	ND	1	114	
0704083-006A	B-6-6 @ 23.5-24	S	ND	ND	1	111	
0704083-008A	B-6-8 @ 31.5-32	S	ND	ND	1	98	
0704083-009A	B-6 Water	w	ND,i	ND	1	100	
0704083-010A	B-7-3 @ 11.5-12.0	S	ND	ND	1	107	
0704083-011A	B-7-4 @ 15.5-16.0	S	ND	ND	1	111	
0704083-012A	B-7-5 @ 19.5-20.0	S	ND	ND	1	113	
0704083-013A	B-7-6 @ 23.5-24.0	S	ND	ND	1	114	
0704083-015A	B-7 Water	w	55,b,i	ND	1	103	
0704083-016A	B-8-1 @ 3.5-4.0	S	ND	ND .	1	116	
0704083-019A	B-8-4 @ 15.5-16.0	S	ND	ND	1	111	
0704083-021A	B-8-6 @ 23.5-24	S	ND	ND	1	113	
0704083-022A	B-8-Water	·w	110,b,i	94	1	98	
0704083-023A	B-9-1 @ 3.5-4.0	S	ND	ND	1	101	
	ing Limit for DF =1;	w	50	50	με	:/L	
ND mea	ans not detected at or	2	1.0	1.0		15.7	

Į	above the reporting mine	٠,	_
	* water samples are reported in µg/L, wipe samples in µg/wipe, soil/solid/sludge samples in mg/kg, product/oil/non-aqueous liquid samp	oles i	n
	mg/L, and all DISTLC / STLC / SPLP / TCLP extracts are reported in µg/L.		

1.0

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified diesel is significant; b) diesel range compounds are significant; no recognizable pattern; c) aged diesel? is significant); d) gasoline range compounds are significant; e) unknown medium boiling point pattern that does not appear to be derived from diesel; f) one to a few isolated peaks present; g) oil range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; k) kerosene/kerosene range; l) bunker oil; m) fuel oil; n) stoddard solvent/mineral spirit.



mg/Kg

1.0

above the reporting limit

<sup>#</sup> cluttered chromatogram resulting in coeluted surrogate and sample peaks, or; surrogate peak is on elevated baseline, or; surrogate has been diminished by dilution of original extract.



"When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories	Client Project ID: #81-01824-A;	Date Sampled: 04/03/07-04/04/07
2001 Crow Canyon Road, Suite 100	Livermore Airport UST/Pipeline	Date Received: 04/04/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 04/04/07
	Client P.O.:	Date Analyzed: 04/05/07-04/10/07

#### Diesel (C10-23) and Jet Fuel (C9-C18) Range Extractable Hydrocarbons as Diesel and Jet Fuel\*

Extraction method: SW3	3510C/SW3550C		nethods: SW8015C		rk Order: 0	704083
Lab ID	Client ID	Matrix	TPH(d)	TPH(jf)	DF	% SS
0704083-026A	B-9-4 @ 15.5-16.0	S	ND	ND	1	104
0704083-028A	B-9-6 @ 23.5-24	S	ND	ND	1	103
0704083-029A	B-9 Water	w	ND,i	ND	1	100
0704083-030A	B-10-1 @ 3.5-4.0	S	ND	ND	1	100
0704083-033A	B-10-4 @ 15.5-16	S	ND	ND	1	101
0704083-035A	B-10-6 @ 23.5-24	S	ND	ND	1	100
0704083-036A	B-10 Water	w	ND,i	ND	1	98
		•				
•	ing Limit for DF =1;	w	50	50	μя	ı/L
ND means not detected at or		S	1.0	1.0	mg	

ND	VV	30	30	μg/L
ND means not detected at or		1.0	1.0	mg/Kg
above the reporting limit				

<sup>\*</sup> water samples are reported in µg/L, wipe samples in µg/wipe, soil/solid/sludge samples in mg/kg, product/oil/non-aqueous liquid samples in mg/L, and all DISTLC / STLC / SPLP / TCLP extracts are reported in  $\mu$ g/L.

<sup>#</sup> cluttered chromatogram resulting in coeluted surrogate and sample peaks, or; surrogate peak is on elevated baseline, or; surrogate has been diminished by dilution of original extract.

<sup>+</sup>The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified diesel is significant; b) diesel range compounds are significant; no recognizable pattern; c) aged diesel? is significant); d) gasoline range compounds are significant; e) unknown medium boiling point pattern that does not appear to be derived from diesel; f) one to a few isolated peaks present; g) oil range compounds are significant; h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; k) kerosene/kerosene range; l) bunker oil; m) fuel oil; n) stoddard solvent/mineral spirit.

### QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704083

EPA Method SW8260B	Extra	ction SW	5030B		Ва	tchID: 27	259	Spiked Sample ID: 0704059-006A				
Analyte	Sample	Sample Spiked MS I		MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acceptance Criteria (%)			
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	0.050	96.5	95.4	1.12	96.8	96.1	0.733	70 - 130	30	70 - 130	30
Benzene	ND	0.050	101	101	0	98.2	101	2.66	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	0.25	84.5	86.1	1.86	94.2	95.9	1.76	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	0.050	109	108	0.420	107	108	0.735	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	0.050	102	101	0.887	102	102	0	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	0.050	102	101	0.846	104	102	1.92	70 - 130	30	70 - 130	30
Toluene	ND	0.050	91.4	91.6	0.175	89.3	91.8	2.80	70 - 130	30	70 - 130	30
%SS1:	101	0.050	92	92	0	93	93	0	70 - 130	30	70 - 130	30
%SS2:	107	0.050	100	100	0	101	100	0.591	70 - 130	30	70 - 130	30
%SS3:	102	0.050	109	108	0.343	109	108	0.0728	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions:

NONE

#### BATCH 27259 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704083-001A	04/03/07 1:35 PM	04/04/07	04/05/07 2:44 PM	0704083-002A	04/03/07 1:40 PM	04/04/07	04/05/07 3:29 PM
0704083-004A	04/03/07 2:00 PM	04/04/07	04/05/07 4:14 PM	0704083-006A	04/03/07 2:40 PM	04/04/07	04/05/07 5:00 PM
0704083-008A	04/03/07 3:45 PM	04/04/07	04/05/07 5:44 PM	0704083-010A	04/03/07 5:00 PM	04/04/07	04/05/07 6:30 PM
0704083-011A	04/03/07 5:15 PM	04/04/07	04/05/07 7:14 PM	0704083-012A	04/03/07 5:35 PM	04/04/07	04/05/07 8:00 PM
0704083-013A	04/03/07 5:50 PM	04/04/07	04/05/07 8:45 PM				ľ


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



### QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704083

EPA Method SW8015C	Extra	ction SW	3550C	BatchID: 27260 Spi				piked Sample ID: 0704052-010A				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	)
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	Rec. % RPD MS/		RPD	LCS/LCSD	RPD
TPH(d)	ND	20	114	114	0	101	102	0.338	70 - 130	30	70 - 130	30
%SS:	106	50	115	115	0	87	87	0	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27260 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704083-001A	04/03/07 1:35 PM	04/04/07	04/05/07 5:34 PM	0704083-002A	04/03/07 1:40 PM	04/04/07	04/05/07 7:55 PM
0704083-004A	04/03/07 2:00 PM	04/04/07	04/05/07 7:50 PM	0704083-006A	04/03/07 2:40 PM	04/04/07	04/05/07 8:59 PM
0704083-008A	04/03/07 3:45 PM	04/04/07	04/10/07	0704083-010A	04/03/07 5:00 PM	04/04/07	04/05/07 11:16 PM
0704083-011A	04/03/07 5:15 PM	04/04/07	04/06/07 12:24 AM	0704083-012A	04/03/07 5:35 PM	04/04/07	04/06/07 3:49 AM
0704083-013A	04/03/07 5:50 PM	04/04/07	04/06/07 4:57 AM	0704083-016A	04/04/07 8:05 AM	04/04/07	04/06/07 6:06 AM
0704083-019A	04/04/07 8:30 AM	04/04/07	04/06/07 7:14 AM	0704083-021A	04/04/07 8:55 AM	04/04/07	04/06/07 8:22 AM
0704083-023A	04/04/07 9:35 AM	04/04/07	04/05/07 6:42 PM	0704083-026A	04/04/07 10:15 AM	04/04/07	04/05/07 5:34 PM
0704083-028A	04/04/07 10:35 AM	04/04/07	04/05/07 7:50 PM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



### QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704083

EPA Method SW8021B/8015Cm	Extra		BatchID: 27261 Sp			piked Sample ID: 0704052-014A						
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	: Criteria (%)	)
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(btex <sup>£</sup>	ΝD	0.60	94.8	93	1.93	102	108	5.94	70 - 130	30	70 - 130	30
мтве	ND	0.10	97.6	97.5	0.0785	104	107	2.75	70 - 130	30	70 - 130	30
Benzene	ND	0.10	92.9	91.8	1.24	102	104	2.15	70 - 130	30	70 - 130	30
Toluene	ND	0.10	85.2	85.2	. 0	94.6	95.4	0.861	70 - 130	30	70 - 130	30
Ethylbenzene	ND	0.10	90.4	92.1	1.85	100	99.8	0.192	70 - 130	30	70 - 130	30
Xylenes	ND	0.30	86.3	86.7	0.385	95.7	95.3	0.349	70 - 130	30	70 - 130	30
%SS:	85	0.10	86	85	1.21	94	95	1.57	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27261 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704083-001A	04/03/07 1:35 PM	04/04/07	04/06/07 12:42 PM	0704083-002A	04/03/07 1:40 PM	04/04/07	04/06/07 4:05 AM
0704083-004A	04/03/07 2:00 PM	04/04/07	04/06/07 5:05 AM	0704083-006A	04/03/07 2:40 PM	04/04/07	04/06/07 5:35 AM
0704083-008A	04/03/07 3:45 PM	04/04/07	04/06/07 6:05 AM	0704083-010A	04/03/07 5:00 PM	04/04/07	04/06/07 6:35 AM
0704083-011A	04/03/07 5:15 PM	04/04/07	04/06/07 7:05 AM	0704083-012A	04/03/07 5:35 PM	04/04/07	04/06/07 7:35 AM
0704083-013A	04/03/07 5:50 PM	04/04/07	04/06/07 7:25 AM	0704083-016A	04/04/07 8:05 AM	04/04/07	04/06/07 8:05 AM
0704083-019A	04/04/07 8:30 AM	04/04/07	04/06/07 8:32 AM	0704083-021A	04/04/07 8:55 AM	04/04/07	04/06/07 9:06 AM
0704083-023A	04/04/07 9:35 AM	04/04/07	04/06/07 9:40 AM	0704083-026A	04/04/07 10:15 AM	04/04/07	04/06/07 10:13 AM
0704083-028A	04/04/07 10:35 AM	04/04/07	04/06/07 10:47 AM	0704083-030A	04/04/07 11:20 AM	04/04/07	04/06/07 4:53 PM
0704083-033A	04/04/07 12:10 PM	04/04/07	04/06/07 9:06 AM	0704083-035A	04/04/07 12:35 PM	04/04/07	04/06/07 9:36 AM


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

£ TPH(btex) = sum of BTEX areas from the FID.

# cluttered chromatogram; sample peak coelutes with surrogate peak.



#### **QC SUMMARY REPORT FOR SW8260B**

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704083

EPA Method SW8260B	Extra	ction SW	5030B		Ва	tchID: 27	273	3 Spiked Sample ID: 0704076-00				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	1
·	µg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	10	96.4	98.7	2.33	96.2	97.4	1.15	70 - 130	30	70 - 130	30
Benzene	ND	10	107	108	0.352	107	107	0	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	50	92.5	94.8	2.43	88.4	91.8	3.75	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	10	113	115	1.66	113	114	0.814	70 - 130	30	70 - 130	30
Ethanol	ND	500	106	105	1.43	93.4	99.6	5.94	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	10	103	106	2.28	103	105	1.28	70 - 130	30	70 - 130	30
Methanol	ND	2500	102	100	2.07	102	101	0.972	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	1.2	10	104	106	1.37	102	104	2.01	70 - 130	30	70 - 130	30
Toluene	ND	10	93.1	96.2 .	3.23	91.8	94.1	2.52	70 - 130	30	70 - 130	30
%SS1:	107	10	98	95	2.73	98	96	2.28	70 - 130	30	70 - 130	30
%SS2:	105	10	99	99	0	99	99	0	70 - 130	30	70 - 130	30
%SS3:	. 89	10	105	107	1.73	108	109	1.12	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27273 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704083-009B	04/03/07 4:25 PM	04/05/07	04/05/07 4:54 PM	0704083-015B	04/03/07 6:45 PM	04/05/07	04/05/07 5:39 PM
0704083-022B	04/04/07 1:10 PM	04/05/07	04/05/07 10:12 PM	0704083-029B	04/04/07 2:25 PM	04/05/07	04/05/07 7:09 PM
0704083-036B	04/04/07 2:00 PM	04/05/07	04/05/07 7:53 PM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



1534 Willow Pass Road, Pittsburg, CA 94565-1701

 Web; www.mccampbell.com
 E-mail: main@mccampbell.com

 Telephone: 877-252-9262
 Fax: 925-252-9269

### QC SUMMARY REPORT FOR SW8021B/8015Cm

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704083

EPA Method SW8021B/8015Cm	Extra		BatchID: 27275			Sp	Spiked Sample ID: 0704077-001A					
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acc	eptance	Criteria (%)	
,,	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(btex <del>f</del>	ND	60	109	108	1.08	99.1	97.7	1.41	70 - 130	30	70 - 130	30
МТВЕ	ND	10	107	102	4.97	119	119	0	70 - 130	30	70 - 130	30
Benzene	ND	10	92.2	94.5	2.53	96.9	95	1.99	70 - 130	30	70 - 130	30
Toluene	ND	10	102	104	2.49	107	104	2.23	70 - 130	30	70 - 130	30
Ethylbenzene	ND	10	99.7	102	2.25	103	101	1.35	70 - 130	30	70 - 130	30
Xylenes	ND	30	110	113	2.99	113	113	0	70 - 130	30	70 - 130	30
%SS:	97	10	97	98	1.17	98	94	3.51	70 - 130	30	70 - 130	30


All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27275 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704083-009A	04/03/07 4:25 PM	04/07/07	04/07/07 1:20 AM	0704083-015A	04/03/07 6:45 PM	04/07/07	04/07/07 1:50 AM
0704083-022A	04/04/07 1:10 PM	04/07/07	04/07/07 11:08 PM	0704083-029A	04/04/07 2:25 PM	04/07/07	04/07/07 2:51 AM
0704083-036A	04/04/07 2:00 PM	04/07/07	04/07/07 3:04 AM				ſ

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.



<sup>%</sup> Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

<sup>£</sup> TPH(btex) = sum of BTEX areas from the FID.

<sup>#</sup> cluttered chromatogram; sample peak coelutes with surrogate peak.

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com

Telephone: 877-252-9262 Fax: 925-252-9269

### QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704083

EPA Method SW8015C	Extra	ction SW	3550C		Ва	tchID: 27	278	Sp	Spiked Sample ID: 0704083-0			5A
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acce	eptance	Criteria (%)	
	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(d)	ND	20	99.5	98.5	1.05	125	119	5.08	70 - 130	30	70 - 130	30
%SS:	100	50	102	101	1.76	117	114	2.02	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27278 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704083-030A	04/04/07 11:20 AM	04/04/07	04/05/07 8:59 PM	0704083-033A	04/04/07 12:10 PM	04/04/07	04/05/07 10:07 PM
0704083-035A	04/04/07 12:35 PM	04/04/07	04/06/07 7:14 AM				

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

QA/QC Officer

1534 Willow Pass Road, Pittsburg, CA 94565-1701

Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

### QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Soil

QC Matrix: Soil

WorkOrder: 0704083

EPA Method SW8260B	EPA Method SW8260B Extraction SW5030B				BatchID: 27282			Spiked Sample ID: 0704083-035A				
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	LCSD Acceptance Crit		Criteria (%)	)
7 maryte	mg/Kg	mg/Kg	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	0.050	97.9	98.7	0.875	94.1	94.4	0.300	70 - 130	30	70 - 130	30
Benzene	ND	0.050	108	104	2.93	104	103	0.995	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	0.25	89	94.1	5.66	85	87.3	2.64	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	0.050	114	113	0.847	110	110	0	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	0.050	106	104	1.85	101	101	0	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	0.050	104	105	0.509	100	99.9	0.125	70 - 130	30	70 - 130	30
Toluene	ND	0.050	93.7	91	2.85	91.8	90.9	0.999	70 - 130	30	70 - 130	30
%SS1:	94	0.050	98	97	1.22	96	95	1.47	70 - 130	30	70 - 130	30
%SS2:	103	0.050	99	99	0	99	99	0	70 - 130	30	70 - 130	30
%SS3:	102	0.050	109	108	0.646	109	108	1.07	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27282 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704083-016A	04/04/07 8:05 AM	04/04/07	04/05/07 9:30 PM	0704083-019A	04/04/07 8:30 AM	04/04/07	04/05/07 11:49 PM
0704083-021A	04/04/07 8:55 AM	04/04/07	04/06/07 8:40 AM	0704083-023A	04/04/07 9:35 AM	04/04/07	04/06/07 9:25 AM
0704083-026A	04/04/07 10:15 AM	04/04/07	04/06/07 12:44 PM	0704083-028A	04/04/07 10:35 AM	04/04/07	04/06/07 1:30 PM
0704083-030A	04/04/07 11:20 AM	04/04/07	04/06/07 2:16 PM	0704083-033A	04/04/07 12:10 PM	04/04/07	04/06/07 3:00 PM
0704083-035A	04/04/07 12:35 PM	04/04/07	04/06/07 3:48 PM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



### QC SUMMARY REPORT FOR SW8015C

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704083

EPA Method SW8015C Extraction SW3510C			BatchID: 27274 Spiked Sample ID: N/A									
Analyte	Sample Spiked MS MSD MS-MSD LCS		LCS	LCSD	LCS-LCSD Acceptance Crit		Criteria (%)	)				
Allalyto	μg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
TPH(d)	N/A	1000	N/A	N/A	N/A	102	102	0	N/A	N/A	70 - 130	30
%SS:	N/A	2500	N/A	N/A	N/A	98	106	7.11	N/A	N/A	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27274 SUMMARY

	Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
	0704083-009A	04/03/07 4:25 PM	04/04/07	04/05/07 11:16 PM	0704083-015A	04/03/07 6:45 PM	04/04/07	04/06/07 12:24 AM
	0704083-022A	04/04/07 1:10 PM	04/04/07	04/06/07 3:49 AM	0704083-029A	04/04/07 2:25 PM	04/04/07	04/06/07 4:57 AM
l	0704083-036A	04/04/07 2:00 PM	04/04/07	04/06/07 10:11 PM				

MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.

A/QC Officer

Consolidated Engineering Laborat 2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583	Client Project ID: #81-01824-A; Livermore	Date Sampled:	04/03/07-04/04/07
	Airport UST/Pipeline	Date Received:	04/04/07
	Client Contact: Chris Palmer	Date Reported:	04/11/07
	Client P.O.:	Date Completed:	04/16/07

WorkOrder: 0704083

April 16, 2007

Dear Chris:

Enclosed are:

- 1). the results of 5 analyzed samples from your #81-01824-A; Livermore Airport UST/Pipeline project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Best regards,

Angela Rydelius, Lab Manager

Consolidated E 2001 Crow Can	i <mark>ngin</mark> yon R	e <mark>ering</mark> oad, S	<b>Labor</b> uite 10	atc 0	rie	<b>:</b> S,	Inc.	•									(	<b>}</b> t	a	ir	1	of	C	u	sto	dy
San Ramon, CA																	E	Date	e: <u>/</u>	Por	11.	<u>3, Z</u>	do	7		
Ph. 925/314-710 Fx. 925/855-714																	F	roj	, No	o. <u>E</u>	<u>31-</u>	-0(8	324- -	M		
Project name:	remo	re An	port	U	S7.	/P/	pl	lin	e						_		<u> </u>	ag	e	<u></u>	_ (	<u> </u>	5			
Relinquished by: Print name: Company name:	O 1	a Pala	ת ממת		Р	rint.	nan	ne: e:	, l	100	IK_	C/W	N K	<u> </u>								,	7:5		2007	-
Special Instructions N-5day tumanum Aleane check TAHD for	d ugl for	jet feul	2	ber of samples	Around Time	Analysis Requested		TPHG/BICK/MTBE+ OXYS SOIS/BOLOB	TPH Diesel 8015	metholot, Laden andey		Tables .	,									Yes	·	_ N	od cond	-
Sample I.D.	Date	Time	Matrix	Num	Tul	Anat		TPH( OXYS	TPH	mert.													. Co	omn	nents	
B-6-1035-4.0	4/3/67	1335	Soil	1	N					X												HE	<b>=</b> 0			
B-6-201.5-80	. ]	1340			N	<u> </u>		$\angle$	/	X									_	<u> </u>	$\downarrow$					
B-6-3011,5-12.0		1350		1	N	<u> </u>			ļ ,	\										_	↓_					
B-6-4015,5-14.0		1400		1	N	<u> </u>			/	X				<b>_</b>				_	_	_	_				<b>-</b>	
B-6-50 19.5-20.0		1415			W	<u> </u>				<u> </u>									_	<u> </u>	1-					
B-6-60235-24		1440		1	N	<u> </u>	<u> </u>		$\angle$	X							-	_	_	_	_					
B6-70275-28		1520		L	M	<del> </del>		<u> </u>	ļ.,						E/C	5.	02		/	1/	4_					
B-6-8031,5-3L		1545		1	N	_		1		X				G	OOD BAD ECHI	CON	ITIC S AB	IVI		_		PROPR		/		
	<u> </u>	<del> </del> _	1 2 2	Ļ	_	<del> </del>	-	ļ.,	ļ.,	<u></u>				├				Una		0.8EG	_PRI	ESERV	ED IN			
10 13 to with	1913/07	1625	worth	4	$oldsymbol{\perp}$	4		K	u	X				P	RESE	RVA'	ION	¥	上	<u> </u>	+					

#### Consolidated Engineering Laboratories, Inc. Chain of Custody 2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583 Date: April 3, 2007 Proj. No. 81-01824-A Ph 925/314-7100 Fx. 925/855-7140 Page Z of 5 Project name: Liver more Airport UST/Pipéline Relinquished by: Chipalmen Received by: -Date received: April 4, 2007 CM Palmer DOUR CHOTAM Print name: Print name: Time received: 1755 Mc Campbell Company name: consolidated Engritables. Lab name: Special Instructions Recieved in good condition N-5 day turnaround Please deck TPHD range for jet fuel Matrix Matrix Yes \_\_\_\_ No \_\_\_ Total # of Samples . Comments Sample I.D. Date Time B-7=3@11.5-12.0 4/3/07 Soil 1700 1715 B-7-4015,5-16.0 B-7-50 19.5-20,0 1735 1750 B-7-6@23.5-24.0 HOLD B-7-70 27.5-28.0 1805 120 4/3/07 1845 Water 4 N B-7 worter

Consolidated E 2001 Crow Can San Ramon, CA	yon Re	oad, Si			rie	s, i	nc.						;							of Custody १५,२ळ७
Ph. 925/314-71					•	•										P	roj.	No	8	1.01824-A
Fx. 925/855-714  Project name:		iove A	luport	- U	157	T/ F	D <sub>ipe</sub>	1/2	ne_					····	•	P	age	) 	3_	of <u>5</u>
Relinquished by: Print name: Company name:	CANSOL'A	Polare	1 Crib		P	rint :	nam	ne: e:		e CA	RUK	C	AVC	TR	mi					: <u>April 4, 2007</u> 1: <u>1</u> 758
Special Instructions N - 5 day tumar			Matrix	per of samples	Tum Around Time	sis Requested	1 0 0 0 1 1 1 1 1 1 1	10HG/67EX/MISE+ 0xys 8015B+8260B	usel souss	yati, 1,2 De4 acates										Recieved in good condition  Yes No  Total # of Samples
Sample I.D.	Date	Time	Matrix	Num	Tum	Anaty		S S	(PKA	meat.									*	. Comments
B-8-103,5-4.0	414/07	0805	Soil	1	N				$\angle$	X										
B-8-207.5-8.0'		0810		1	N						_					 $\Box$		_		HOLD
B-8-3@11.5-12	<u> </u>	0820		1	N			_						_						HOLD
B-8-4@15,5-16:0	<u> </u>	0830	<u> </u>	1	N	<b> </b>		4	$\angle$	X	_	_					$\dashv$	_		1.4. 1
B-8-5019,5-20	1	0640	<del>                                     </del>	1	N	<u> </u>											_	_		HOLD
B-8-6@23,5-24	<del>     </del>	0858		11	N	-			_	Χ										
6 6-70-75-88	丰	6	土	ΙĒ	其	}_														<del>                                    </del>
B-8-water	4/4107	1310	water	4	N	-				X										·
D // Woodel				Ë	Ė							_					_			

Consolidated Engineering Laboratories, Inc. 2001 Crow Canyon Road, Suite 100 San Ramon, CA 94583 Ph. 925/314-7100													Chain of Custody  Date: April 4, 2007  Proj. No. 51.01824-A							
Fx. 925/855-714																				<i>‡</i>
Project name:(	-ive	mor	re Al	upart (	'U	<u>57</u>	/Pi	pel.	Nre	-							Pa	ge _	4	of5
Print name: CMPalmer Print name: DPLIK CARTANI Company name: Consolidated Engr Labs Tye Lab name:														d: <u>April 4, 2007</u> ed:						
Special Instructions N-5 day turna Please check TPWI	iru	el vugi t			ber of samples	Turn Around Time	Analysis Requested		SIBTEX MTBE+ by SOIS walk FOOR	TPH Dieuclby BoisB	ototh 1,20cA actated of 5d-y									Recieved in good condition  Yes No  Total # of Samples
Sample I.D.	Dat			Matrix	Nun	Tum	Anal		TPH OXYS	TOHD	inest.									. Comments
B-9-1035-40	414	07 0	935	Soil	1	N.				$\angle$	X							$oldsymbol{\perp}$		
B-9-207.5-80'	Ĺ	0	950		l	N	<u> </u>								$\downarrow$	$\bot$				HOLD
B-9-3@11.5-12.0		10	100		Ĺ	N.										_	 $\bot$	_		HOLD
B-9-4015,5-16.0		10	15		1	N	<u> </u>		$\angle$	$\angle$	X			$\perp$		_	 			
B-9-50-19.5-20		10	020		1	N	<u> </u>									_	 			HOLD
B-9-60 23.5-24		((	035		1	N	<u> </u>		$\angle$	/	X					_	 	_		
		$\bot$				_	_		_					$\Box$		_	 	$\bot$	_	
B-9 worter	4141	07 15	425	water	l	7			/	/	X									·
	T	$\neg \uparrow$			Τ	П									T	- 1			T	

12.0

Consolidated E 2001 Crow Can San Ramon, CA Ph. 925/314-710 Fx. 925/855-714	yon Ro 3 9458 00	oad, Ši			rie	es,	lnc	•								D P	ate: roj.	A)	0 <u>0</u>	of Custody 14,2007 1-01824-A
Project name:	-ivem	iore A	Irpor	+,	US	7/	Pip	di	ne.						-	P	age		)	of <u>5</u>
Relinquished by: Print name: Company name:	CMI	Palmer		s ast	P	rint	ived nar nam	ne:		D	MK CAV	< (/	W							: <u>April 4, 2007</u> : <u>1758</u>
Special Instructions N-5 day towner Please check TPHD		c fajei		ber of samples	Around Time	Analysis Requested	TPHG/BTEX/MTBE+	siesel by 8015B	PTOTT, 1.21/CT astract											Recieved in good condition  Yes No  Total # of Samples
Sample I.D.	Date	Time	Matrix	Num	Tum,	Arrai	SAXO	17401	The start											. Comments
B-10-1 e 3.5-4.0	414107	1120	Suil	1	N			/	X											
	4/4/07		Sail	1	N															HOLD
		<u> </u>	5011		N	_											$\perp$			HOLD
	414/07		Soil	1	N	<u> </u>	/	/	X					 			_	_	_	
13-10-5019.5-20			Soil	1	N	_		ļ_,	<u>,                                     </u>		<u> </u>			 		_	_	_ _	$\perp$	HOLD
B-10-60 23.5-24	4/4/07	1235	Soil	1	N	ļ		/	X					 		_	_	_	$\bot$	
	<u> </u>				ļ	ļ	١.,	ļ.,						 		_	_		.	
13-10 water	414/07	1400	water	14	N	<del> </del>	1	4	X	-	<del> </del>			 			_	_	$\dashv$	
	<del> </del>	ļ	<del> </del>	├	├	ļ	<del> </del>	<u> </u>	_	-	├-			 		-	-		-	
	<del> </del>		-	-	╀	-	-	_	╀		-			 		$\dashv$	$\dashv$	-	$\dashv$	

## McCampbell Analytical, Inc.



Comments:

1534 Willow Pass Rd Pittsburg, CA 94565-1701 (925) 252-9262

# **CHAIN-OF-CUSTODY RECORD**

Page 1 of 1

(925) 252-9	9262				1	VorkOr	der:	070408	3 A		Client	D: CE	L				
,				EDF		] Excel	[	Fax		🗹 Email		Hard	Сору	∏ Thii	dParty		
Report to:						E	Bill t		D l-1	_			R	equest	ed TA	5	days
	Engineering Laboratori nyon Road, Suite 100 A 94583	Email: TEL: ProjectNo: PO:	cp@ce-labs.c 925.485.5000 #81-01824-A;				Co 20 Sa		ated En w Cany on, CA	gineeri on Roa 94583		oratori e 100	· D	ate Ad	ceive ld-On: inted:	04/11	/2007
									Req	uested	Tests	(See leg	gend b	elow)			
Sample ID	ClientSamplD		Matrix	<b>Collection Date</b>	Hold	1	2	3	4	5	6	7	8	9	10	11	12
0704083-009	B-6 Water		Water	4/3/07 4:25:00 PM		С	_										
0704083-015	B-7 Water		Water	4/3/07 6:45:00 PM		С											
0704083-022	B-8-Water		Water	4/4/07 1:10:00 PM		С											
0704083-029	B-9 Water		Water	4/4/07 2:25:00 PM		С					<u> </u>		<u> </u>				
0704083-036	B-10 Water		Water	4/4/07 2:00:00 PM		С			İ					J			
				y .													
Test Legend:																	
1 9-OXYS	_W 2			3				4						5			
6	7			8			司	9	1				Ī	10			
11	12			L					<u> </u>				L				
													Prepa	red by:	Meliss	a Valle	<u>.s</u>

NOTE: Samples are discarded 60 days after results are reported unless other arrangements are made. Hazardous samples will be returned to client or disposed of at client expense.

Meoh, Etoh, and 1,2 DCA added 4/10/07 per C.P.

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

Client Project ID: #81-01824-A;
Livermore Airport UST/Pipeline

Date Sampled: 04/03/07-04/04/07

Date Received: 04/04/07

Client Contact: Chris Palmer

Date Extracted: 04/13/07

Client P.O.:

Date Analyzed 04/13/07

#### Oxygenated Volatile Organics + EDB and 1,2-DCA by P&T and GC/MS\*

Extraction Method: SW5030B	Anal	ytical Method: SW826	0B		Work Order:	0704083
Lab ID	0704083-009C	0704083-015C	0704083-022C	0704083-029C		
Client ID	B-6 Water	B-7 Water	B-8-Water	B-9 Water	Reporting DF	
Matrix	W	W	W	W	]	
DF	1	1	1	1	S	W
Compound		Conce	entration		ug/kg	μg/L
1,2-Dichloroethane (1,2-DCA)	ND	NĐ	ND	ND	NA	0.5
Ethanol	ND	ND	ND	ND	NA	50
Methanol	ND	ND	ND	ND	NA	500
	Surr	ogate Recoveries	s (%)		.,	
%SS1:	97	98	102	98		.,,
Comments	i	i	i	i		

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; J) analyte detected below quantitation limits; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.

Consolidated Engineering Laboratories	Client Project ID: #81-01824-A;	Date Sampled:	04/03/07-04/04/07
2001 Crow Canyon Road, Suite 100	Livermore Airport UST/Pipeline	Date Received:	04/04/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted:	04/13/07
San Kamon, CA 94363	Client P.O.:	Date Analyzed	04/13/07

	- EDB and 1,2-DCA by P&T  Method: SW8260B	Work	porting	0704083			
04083-036C 3-10 Water W	Method: SW8260B		porting				
3-10 Water W		Re		Limit for			
W		Re		Limit for			
			Reporting Limit for DF =1				
1		1 1					
r .			S	W			
	Concentration	u	g/kg	μg/L			
ND			NA	0.5			
ND			NA	50			
ND			NA	500			
Surrogat	e Recoveries (%)						
97							
i							
	ND ND Surrogat	ND ND Surrogate Recoveries (%)	ND ND Surrogate Recoveries (%)	ND NA NA NA NA NA NA Surrogate Recoveries (%)			

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; J) analyte detected below quantitation limits; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.

## McCampbell Analytical, Inc.

"When Ouality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

Client Project ID: #81-01824-A;
Livermore Airport UST/Pipeline

Date Sampled: 04/03/07-04/04/07

Date Received: 04/04/07

Client Contact: Chris Palmer

Date Extracted: 04/04/07

Client P.O.:

Date Analyzed: 04/05/07-04/06/07

#### Oxygenates and BTEX by GC/MS\*


Extraction Method: SW5030B Analytical Method: SW8260B Work Order: 0704083

Lab ID         0704083-001A         0704083-002A         0704083-004A         0704083-004A           Client ID         B-6-1@3.5-4.0         B-6-2@7.5-8.0         B-6-4@15.5-16.0         B-6-6@2           Matrix         S         S         S         S           Compound         Concentration           tert-Amyl methyl ether (TAME)         ND         ND         ND         ND           Benzene         ND         ND         ND         ND           t-Butyl alcohol (TBA)         ND         ND         ND         ND           1,2-Dichloroethane (1,2-DCA)         ND         ND         ND         ND           Diisopropyl ether (DIPE)         ND         ND         ND         ND           Ethanol         ND         ND         ND         ND           Ethyl benzene         ND         ND         ND         ND           Ethyl tert-butyl ether (ETBE)         ND         ND         ND         ND           Methanol         ND         ND         ND         ND	23.5-24 Reportion S  mg/kg 0.005	NA
Matrix   S   S   S   S   S	Reporti	DF =1  W ug/L NA
DF         1         1         1         1           Compound           Compound         Concentration           tert-Amyl methyl ether (TAME)         ND         ND         ND         ND           Benzene         ND         ND         ND         ND         ND           Benzene         ND	S mg/kg 0.005	W ug/L NA
Compound         Concentration           tert-Amyl methyl ether (TAME)         ND         ND         ND         ND           Benzene         ND         ND         ND         ND           t-Butyl alcohol (TBA)         ND         ND         ND         ND           1,2-Dichloroethane (1,2-DCA)         ND         ND         ND         ND           Diisopropyl ether (DIPE)         ND         ND         ND         ND           Ethanol         ND         ND         ND         ND           Ethylbenzene         ND         ND         ND         ND           Ethyl tert-butyl ether (ETBE)         ND         ND         ND         ND           Methanol         ND         ND         ND         ND	mg/kg	ug/L NA
tert-Amyl methyl ether (TAME)         ND         ND         ND         ND           Benzene         ND         ND         ND         ND         ND           t-Butyl alcohol (TBA)         ND         ND         ND         ND         ND         ND           1,2-Dichloroethane (1,2-DCA)         ND	NA	
Benzene         ND         ND         ND         ND           t-Butyl alcohol (TBA)         ND         ND         ND         ND           1,2-Dichloroethane (1,2-DCA)         ND         ND         ND         ND           Diisopropyl ether (DIPE)         ND         ND         ND         ND           Ethanol         ND         ND         ND         ND           Ethylbenzene         ND         ND         ND         ND           Ethyl tert-butyl ether (ETBE)         ND         ND         ND         ND           Methanol         ND         ND         ND         ND		
t-Butyl alcohol (TBA) ND ND ND ND ND ND ND 1,2-Dichloroethane (1,2-DCA) ND ND ND ND ND ND ND ND ND ND ND ND ND	0.005	
1,2-Dichloroethane (1,2-DCA)         ND         ND         ND         ND           Diisopropyl ether (DIPE)         ND         ND         ND         ND         ND           Ethanol         ND         ND         ND         ND         ND         ND           Ethylbenzene         ND         ND         ND         ND         ND         ND           Ethyl tert-butyl ether (ETBE)         ND         ND         ND         ND         ND           Methanol         ND         ND         ND         ND         ND		NA
Diisopropyl ether (DIPE)  ND  ND  ND  ND  ND  ND  ND  ND  ND  N	0.05	NA
Ethanol ND ND ND ND ND Ethylbenzene ND ND ND ND ND ND ND ND ND ND ND ND ND	0.005	NA
Ethylbenzene ND ND ND ND ND  Ethyl tert-butyl ether (ETBE) ND ND ND ND ND  Methanol ND ND ND ND ND	0.005	NA
Ethyl tert-butyl ether (ETBE) ND ND ND ND ND ND ND ND ND ND ND ND ND	0.25	NA
Methanol ND ND ND ND	0.005	NA
	0.005	NA
	2.5	NA
Methyl-t-butyl ether (MTBE) ND ND ND ND	0.005	NA
Toluene ND ND ND ND	0.005	NA
Xylenes ND ND ND ND	0.005	NA
Surrogate Recoveries (%)		
%SS1: 105 106 104 107	7	
%SS2: 106 106 104 103	3	
%SS3: 106 103 106 102	2	
Comments		

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



### McCampbell Analytical, Inc. "When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Web: www.mccampbell.com E-mail: main@mccampbell.com Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories Client Project ID: #81-01824-A; Date Sampled: 04/03/07-04/04/07 Livermore Airport UST/Pipeline Date Received: 04/04/07 2001 Crow Canyon Road, Suite 100 Client Contact: Chris Palmer Date Extracted: 04/04/07 San Ramon, CA 94583 Client P.O.: Date Analyzed: 04/05/07-04/06/07

#### Oxygenates and BTEX by GC/MS\*


Analytical Method: SW8260B Extraction Method: SW5030B Work Order: 0704083

Extraction Method: SW3030B	Anai	ytical Method: 5 W 820	UB .		work Order:	0704083
Lab ID	0704083-008A	0704083-010A	0704083-011A	0704083-012A		
Client ID	B-6-8 @ 31.5-32	B-7-3 @ 11.5- 12.0	B-7-4 @ 15.5- 16.0	B-7-5 @ 19.5- 20.0	Reporting DF	
Matrix	S	S	S	S		
DF	1	1	1	1	S	w
Compound		Conce	entration		mg/kg	ug/L
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	NA
Benzene	ND	ND	ND	ND	0.005	NA
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	NA
1,2-Dichloroethane (1,2-DCA)	ND	ND	ND	ND	0.005	NA
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	NA
Ethanol	ND	ND	ND	ND	0.25	NA
Ethylbenzene	ND	ND	ND	ND	0.005	NA
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	NA
Methanol	ND	ND	ND	ND	2.5	NA
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	NA
Toluene	ND	ND	ND	ND	0.005	NA
Xylenes	ND	ND	ND	ND	0.005	NA
	Surr	ogate Recoverie	s (%)			
%SS1:	105	103	102	102		
%SS2:	103	104	104	104		
%SS3:	102	103	103	102		
Comments						

* water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP
extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



<sup>#</sup> surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

Date Analyzed: 04/05/07-04/06/07

"When Ouality Counts"

Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824-A; Livermore Airport UST/Pipeline	Date Sampled: 04/03/07-04/04/07	
Livermore Airport 081/Pipeline	Date Received: 04/04/07	
Client Contact: Chris Palmer	Date Extracted: 04/04/07	-

#### Oxygenates and BTEX by GC/MS\*

Client P.O.:

	Oxygen	ates and DIEV D	y GC/MS						
Extraction Method: SW5030B	Work Order: 0704083								
Lab ID	0704083-013A	0704083-016A	0704083-019A	0704083-021A	1				
Client ID	B-7-6 @ 23.5- 24.0	B-8-1 @ 3.5-4.0	B-8-4 @ 15.5- 16.0	B-8-6 @ 23.5-24	Reporting DF				
Matrix	S	S	S	S		Dr –I			
DF	1	1	1	1	S	W			
Compound		Conce	entration		mg/kg	ug/L			
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	NA			
Benzene	ND	ND	ND	ND	0.005	NA			
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	NA			
1,2-Dichloroethane (1,2-DCA)	ND	ND	ND	ND	0.005	NA			
Diisopropyl ether (DIPE)	ŃD	ND	ND	ND	0.005	NA			
Ethanol	ND	ND	ND	ND	0.25	NA			
Ethylbenzene	ND	ND	ND	ND	0.005	NA			
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	NA			
Methanol	ND	ND	ND	ND	2.5	NA			
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	NA			
Toluene	ND	ND	ND	ND	0.005	NA			
Xylenes	ND	. ND	ND	ND	0.005	NA			
	Surrogate Recoveries (%)								
%SS1:	102	102	100	97					
%SS2:	104	104	104	107					
%SS3:	103	103	102	104					
Comments									

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



Consolidated Engineering Laboratories
2001 Crow Canyon Road, Suite 100

San Ramon, CA 94583

Client Project ID: #81-01824-A;
Livermore Airport UST/Pipeline

Date Sampled: 04/03/07-04/04/07

Date Received: 04/04/07

Client Contact: Chris Palmer

Date Extracted: 04/04/07

Client P.O.:

Date Analyzed: 04/05/07-04/06/07

#### Oxygenates and BTEX by GC/MS\*

Extraction Method: SW5030B Analytical Method: SW8260B Work Order: 0704083

Extraction Method: SW 5030B Analytical Method: SW 8260B Work Order: 0704083								
Lab ID	0704083-023A	0704083-026A	0704083-028A	0704083-030A				
Client ID	B-9-1 @ 3.5-4.0	B-9-4 @ 15.5- 16.0	B-9-6 @ 23.5-24	B-10-1 @ 3.5-4.0	Reporting			
Matrix	S	S	S	S	DF =1			
DF	1	1	1	1	S	W		
Compound Concentration						ug/L		
tert-Amyl methyl ether (TAME)	ND	ND	ND	ND	0.005	NA		
Benzene	ND ,	ND	ND	ND .	0.005	NA		
t-Butyl alcohol (TBA)	ND	ND	ND	ND	0.05	NA		
1,2-Dichloroethane (1,2-DCA)	ND	ND	ND	ND	0.005	NA		
Diisopropyl ether (DIPE)	ND	ND	ND	ND	0.005	NA		
Ethanol	ND	ND	ND	ND	0.25	NA		
Ethylbenzene	ND	ND	ND	ND	0.005	NA		
Ethyl tert-butyl ether (ETBE)	ND	ND	ND	ND	0.005	NA		
Methanol	ND	ND	ND	ND	2.5	NA		
Methyl-t-butyl ether (MTBE)	ND	ND	ND	ND	0.005	NA		
Toluene	ND	ND	ND	ND	0.005	NA		
Xylenes	ND	ND	ND	ND	0.005	NA		
Surrogate Recoveries (%)								
%SS1:	97	95	93	96				
%SS2:	105	106	104	104				
%SS3:	103	101	102	102				
Comments								

<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



# McCampbell Analytical, Inc. "When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701
Web: www.mccampbell.com E-mail: main@mccampbell.com
Telephone: 877-252-9262 Fax: 925-252-9269

Consolidated Engineering Laboratories	Client Project ID: #81-01824-A; Livermore Airport UST/Pipeline	Date Sampled: 0	04/03/07-04/04/07
2001 Crow Canyon Road, Suite 100	Livermore Airport OS 1/Pipeline	Date Received: 0	)4/04/07
San Ramon, CA 94583	Client Contact: Chris Palmer	Date Extracted: 0	)4/04/07
Dan Ranon, Crip 1909	Client P.O.:	Date Analyzed: 0	)4/05/07-04/06/07


#### Oxygenates and BTEX by GC/MS\*

Extraction Method: SW5030B Analytical Method: SW8260B Work Order: 0704083 0704083-033A Lab ID 0704083-035A B-10-4 @ 15.5-B-10-6 @ 23.5-Client ID Reporting Limit for 16 24 DF = 1Matrix S S DF 1 1 w S Concentration Compound ug/L mg/kg ND ND 0.005 NΑ tert-Amyl methyl ether (TAME) ND ND 0.005 NA Benzene ND 0.05 NA t-Butyl alcohol (TBA) ND 1,2-Dichloroethane (1,2-DCA) ND ND 0.005 NA ND 0.005 NA Diisopropyl ether (DIPE) ND 0.25 NA Ethanol ND ND ND ND 0.005 NA Ethylbenzene Ethyl tert-butyl ether (ETBE) ND ND 0.005 NA Methanol ND ND 2.5 NA ND ND 0.005 NA Methyl-t-butyl ether (MTBE) Toluene ND ND 0.005 NA ND ND 0.005 NΑ Xylenes Surrogate Recoveries (%) %SS1: 95 94 %SS2: 104 103 %SS3: 104 102 Comments

ND means not detected above the reporting limit; N/A means analyte not applicable to this analysis.

# surrogate diluted out of range or coelutes with another peak; &) low surrogate due to matrix interference.

h) lighter than water immiscible sheen/product is present; i) liquid sample that contains greater than ~1 vol. % sediment; j) sample diluted due to high organic content/matrix interference; k) reporting limit near, but not identical to our standard reporting limit due to variable Encore sample weight; m) reporting limit raised due to insufficient sample amount; n) results are reported on a dry weight basis; p) see attached narrative.



<sup>\*</sup> water and vapor samples are reported in µg/L, soil/sludge/solid samples in mg/kg, product/oil/non-aqueous liquid samples and all TCLP & SPLP extracts are reported in mg/L, wipe samples in µg/wipe.

#### QC SUMMARY REPORT FOR SW8260B

W.O. Sample Matrix: Water

QC Matrix: Water

WorkOrder: 0704083

EPA Method SW8260B	d SW8260B Extraction SW5030B BatchID: 2740					401	Spiked Sample ID: 0704242-006B					
Analyte	Sample	Spiked	MS	MSD	MS-MSD	LCS	LCSD	LCS-LCSD	Acce	eptance	Criteria (%)	)
Analyte	µg/L	μg/L	% Rec.	% Rec.	% RPD	% Rec.	% Rec.	% RPD	MS / MSD	RPD	LCS/LCSD	RPD
tert-Amyl methyl ether (TAME)	ND	10	97.8	96.8	1.06	94.2	94.9	0.786	70 - 130	30	70 - 130	30
t-Butyl alcohol (TBA)	ND	50	89	85.8	3.61	88.8	90.2	1.64	70 - 130	30	70 - 130	30
1,2-Dibromoethane (EDB)	ND	10	87.6	87.4	0.254	88.2	88	0.189	70 - 130	30	70 - 130	30
1,2-Dichloroethane (1,2-DCA)	ND	10	105	105	0	102	102	0	70 - 130	30	70 - 130	30
Diisopropyl ether (DIPE)	ND	10	114	112	1.51	110	110	0	70 - 130	30	70 - 130	30
Ethanol	ND	500	95.6	92.5	2.99	92.4	99.1	6.49	70 - 130	30	70 - 130	30
Ethyl tert-butyl ether (ETBE)	ND	10	105	104	0.490	101	101	0	70 - 130	30	70 - 130	30
Methanol	ND	2500	101	100	0.792	101	100	0.435	70 - 130	30	70 - 130	30
Methyl-t-butyl ether (MTBE)	ND	10	103	103	0	99.7	101	1.08	70 - 130	30	70 - 130	30
%SS1:	104	10	95	94	1.14	94	94	0	70 - 130	30	70 - 130	30

All target compounds in the Method Blank of this extraction batch were ND less than the method RL with the following exceptions: NONE

#### BATCH 27401 SUMMARY

Sample ID	Date Sampled	Date Extracted	Date Analyzed	Sample ID	Date Sampled	Date Extracted	Date Analyzed
0704083-009C	04/03/07 4:25 PM	04/13/07	04/13/07 9:25 AM	0704083-015C	04/03/07 6:45 PM	04/13/07	04/13/07 10:13 AM
0704083-022C	04/04/07 1:10 PM	04/13/07	04/13/07 12:10 PM	0704083-029C	04/04/07 2:25 PM	04/13/07	04/13/07 12:55 PM
0704083-036C	04/04/07 2:00 PM	04/13/07	04/13/07 1:40 PM				


MS = Matrix Spike; MSD = Matrix Spike Duplicate; LCS = Laboratory Control Sample; LCSD = Laboratory Control Sample Duplicate; RPD = Relative Percent Deviation.

% Recovery = 100 \* (MS-Sample) / (Amount Spiked); RPD = 100 \* (MS - MSD) / ((MS + MSD) / 2).

MS / MSD spike recoveries and / or %RPD may fall outside of laboratory acceptance criteria due to one or more of the following reasons: a) the sample is inhomogenous AND contains significant concentrations of analyte relative to the amount spiked, or b) the spiked sample's matrix interferes with the spike recovery.

N/A = not enough sample to perform matrix spike and matrix spike duplicate.

NR = analyte concentration in sample exceeds spike amount for soil matrix or exceeds 2x spike amount for water matrix or sample diluted due to high matrix or analyte content.



## **APPENDIX D**

2000-foot Radius Well Search Information

LIVERMORE AIRPORT	WELL 2000 FOOT RADIUS	WELL SEARCH	DWR Well Data

Map Number	Owner well no.	Date Installed/completed	State Well No/Location	CA DWR No.	Well Depth (ft)	Well dia. (in)
	State DWR Log Inform.					
1	L. Lupton, Livermore	July, 1951(?)	T3S R1E 1G2	01-810	208	12
2	L. Lupton, Livermore	July, 1951(?)	T3S R1E 1G2	01-810	208	12
3	Unreadable	Unreadable	T3S R1E 1Q	01-981	Unreadable	Unreadable
4	Ala. Cnty. Flood Zone 7	11/6/1980	T3S R1E 1R2	O62569	54	12?
5	Ala. Cnty. Flood Zone 7	9/10/1980	T3S R1E 1R1	107392	32	Not stated
6	Ala. Cnty. Flood Zone 7	Oct. 1977	T3S R1E 1H3	107417A	80	2.5
7	Ala. Cnty. Flood Zone 7	Nov. 1975	T3S R1E 1P2	107417B	50	2.5
8	John Moniz	7/1/1969	T3S R1E south 1/2?	13398	333	12 3/4
9	Ala. Cnty. Flood Zone 7	Nov. 1975	T3S R1E 1R1	253974	37	2.5
10	City of Livermore	7/28/1988	T3S R1E 1P3	259569	480	12
11	Lawrence Lupton	16 Sep., 1950	T3S R1E 1G2	261447	208	12
12	John Moniz	Dec, 1998	T3S R1E 1N2	510075	440	18
13	EdwinHagemann	25-Sep-54	T3S R1E 1P1	530	297	10
14	City of Livermore	March, 1998	T3S R1E 1N1	701237	519	15
15	Shea	March, 2001?	T3S R1E 1J2	742177	31	Not stated
16	TKG International	14-Apr-00	T3S R1E 1J3	773838	700	16
17	August Hagemann	July, 1950	T3S R1E 12C1	#01-3039	268	12
18	August Hagemann	Unknown	T3S R1E 12D1	# 01-3040	120	8
19	EdwinHagemann	Unknown	T3S R1E 12E1	#01-0341	276	12
20	EdwinHagemann	Aug. 1949	T3S R1E 12F1	#01-3042	240	14
21	Livermore Sewage	Oct. 1959	T3S R1E 12H1	#01-3043	212	8
22	City of Livermore	Apr. 1986	T3S R1E 12B1	150996	170	Not stated
Zor	ne 7 Water Agency Informat	ion				
23	Hagemann	1975	T3S R1E 12C2	Not Stated	136	10
24	Zone 7 Water Agency	Nov. 1975	T3S R1E 12D2	261450F	46	2.5
25	City of Livermore?	Unknown	T3S R1E 12C3	Not Stated	522	Not Stated
26	Zone 7 Water Agency	12/19/2000	T3S R1E 1L1	Not Stated	70	2
27	City of Livermore	May, 2002	T3S R1E 12E2	# 03-3112	41.5	2
28	City of Livermore	May, 2002	T3S R1E 12E3	# 01-3113	41.5	1

Sources: State Dept. of Water Resources, Sacramento, CA; Zone 7 Water Agency, Livermore, CA.

Current status of reported wells not verified in all cases.

See report Figure 5 for locations of wells corresponding to numbers 1 thorugh 28 listed.

Screened Intervals (ft)	Slot Size/Type (in)	Depth To Water (ft)	Yield gpm	Stated Use	Santiary/surfaceseal (ft)
Not stated	Not stated	Not Stated	Not Stated	Irrigation	Not Stated
Not stated	Not stated	Not Stated	Not Stated	Irrigation	Not Stated
Unreadable	Unreadable	Unreadable	Unreadable	Unreadable	Unreadable
49-54	1/8"	19 at completion	Not Stated	Monitoring	Cement grout 0-10
Not stated	Not stated	15.9	Air pumped 3 min.	Destruction	Cement grout 0-32'
70-75	Not stated	64	Not Stated	Monitoring	Cement 0-64'
40-45	Not stated	39	Not Stated	Monitoring	Cement 0-11'
154-201; 283-290; 309-333	slots 160x2.5"	Not Stated	Not Stated	Domestic	Not Stated
22-27	0.04	19 at completion	Not Stated	Monitoring	Concrete 0-20'
245-265;280-300;360-400;440-460	0.045	135 at completion	500 gpm after 12 hr	Municipal	0-110' conductor cemented
158?-166?	1/8x4	70 at completion	12 gpm	Irrigation	Yes, no interval given
380-420	3/16"x4	104	175 gpm	Recharge	Cement 0-220'
212-240	Cut into casing	104	Not Stated	Irrigation	Not Stated
374-424	0.05	104 at completion	380 gpm at 8 hr	Monitoring	0-220'
Not stated	Not stated	Not Stated	Not Stated	Destruction	0-31'
270-290	0.032	7	500 after 3 hr	Irrigation	0-57'
133-158; 213-217; 248-259	"perforated"	121	Not Stated	Irrigation?	Not Stated
84-86; 104-109	"perforated"	Not Stated	Not Stated	Water supply	Not Stated
200-219; 231-234; 239-267	"perforated"	66	Not Stated	Irrigation?	Not Stated
115-118;126-132;145-165;193-199;226-234	Not stated	122	Not Stated	Irrigation?	Not Stated
94-120; 157-172	75 perf.; 42 perf.	103	185 after 8 hr	Not Stated	Not Stated
80-90'; 2-12'	Not stated	60	Not Stated	Irrigation?	Not Stated
Not Stated	Not Stated	Not Stated	Not Stated	Water supply	Not Stated
36-41'	Not Stated	34 a completion	Not Stated	Monitoring	Not Stated
Unknown	Not Stated	Not Stated	Not Stated	Not Stated	Not Stated
60-70'?	Not Stated	Not Stated	Not Stated	Monitoring	Not Stated
15-40'	0.02	39 at completion	Not Stated	Monitoring	0-10'
25-41'	0.02	Not Stated	Not Stated	Monitoring	0-22'

#### **Current Status**

Unknown

Unknown

Unreadable

Unknown

Destroyed

Unknown

Unknown

Unknown

Unknown

Inactive

Unknown

Assumed Active

Unknown

**Assumed Active** 

Destroyed

Assumed Active

Destroyed

Destroyed

Unknown

Unknown

Assumed Active

Destroyed

Destroyed

Assumed Active

Unknown or cathodic?

Assumed Active

**Assumed Active** 

**Assumed Active**