From: <u>Jeff Adams</u>

To: Roe, Dilan, Env. Health

Subject: Jordan Ranch - maps and discussion

Date: Friday, February 15, 2013 9:34:06 AM

Attachments: 7828000001-ParcelH-1-GroundwaterAssessment-021113-REVIEW3.pdf

Jordan vicinity overview.pdf

Good morning, Dilan:

I have attached a couple of figures for your review. One is an aerial vicinity overview of the Jordan Ranch property, the other is a map outlining the results of the groundwater assessment work.

Would you be available for a phone call to discuss in the coming days?


Thank you, Jeff

Jeffrey A. Adams, PhD, PE Associate




ENGEO Incorporated 2010 Crow Canyon Place, Suite 250 San Ramon, CA 94583 (925) 866-9000 Phone (888) 279-2698 Fax www.engeo.com

*******Due to the potential that information by electronic media can deteriorate, be damaged, lost or modified unintentionally or otherwise, use of this electronic data by anyone other than ENGEO Incorporated shall be at the sole risk of such user and without liability or legal exposure to ENGEO Incorporated. The recipient is responsible for verifying the accuracy of data against governing hard copy documentation. Recipient assumes all risks in the changing or modification of data and revisions or updating of hard copy documents.**********



To see all the details that are visible on the screen, use the "Print" link next to the map.





From: Roe, Dilan, Env. Health

To: "Lockwood, George@Waterboards"

Cc: <u>Drogos, Donna, Env. Health; "Ravi Nandwana"; Jeff Adams</u>
Subject: RE: JORDAN RANCH (T06019797353), 4233 FALLON

Date: Friday, February 15, 2013 4:12:00 PM

Hi George:

Thank-you for bringing this to our attention. I have adjusted the site location on the GeoTracker map to accurately locate its position. The monitoring wells are located incorrectly (i.e., they should be located west of the pond rather than to the east as currently site). I have rejected the GEO_XY and GEO_Z data on GeoTracker and requested the RP's consultants to verify the survey data, and re-upload to GeoTracker in order to properly locate the wells.

Dilan Roe, P.E.

Hazardous Materials Specialist Alameda County Environmental Health 1131 Harbor Bay Parkway Alameda, CA 94502 510.567.6767; Ext. 36767

QIC: 30440

dilan.roe@acgov.org

PDF copies of case files can be reviewed/downloaded at:

http://www.acgov.org/aceh/lop/ust.htm

From: Lockwood, George@Waterboards [mailto:George.Lockwood@waterboards.ca.gov]

Sent: Friday, February 15, 2013 1:07 PM

To: Drogos, Donna, Env. Health; Roe, Dilan, Env. Health Subject: JORDAN RANCH (T06019797353), 4233 FALLON

Donna

Please check the location of this site in relation with the four ESI points associated with the site. It appears that either the site or the wells are not located correctly. If it is the site, one can relocate it in GeoT. If it is the ESI, the ESI will have to be denied and the re-uploaded.

Thank you