

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK)/ CONTAMINATION SITE REPORT

EMERGENCY <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFETY CODE.	
REPORT DATE 8-1-6		CASE #		SIGNED: <i>[Signature]</i> DATE: 12/06/06	
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT Joseph A. Cotton		PHONE (510) 703-5420		SIGNATURE <i>[Signature]</i>
	REPRESENTING <input type="checkbox"/> LOCAL AGENCY <input type="checkbox"/> REGIONAL BOARD <input type="checkbox"/> OWNER/OPERATOR <input checked="" type="checkbox"/> OTHER... PROPERTY OWNER		COMPANY OR AGENCY NAME IMPACT ENVIRONMENTAL SERVICES		
	ADDRESS 39120 ARGONAUT WAY, STE. 223 FREMONT CA 94538				
RESPONSIBLE PARTY	NAME MRS. SHIRLEY THOMPSON <input type="checkbox"/> Unknown			PHONE (510) 527-5702	
	ADDRESS 1155 HOPKINS ST. BERKELEY CA 94702				
SITE LOCATION	FACILITY NAME (IF APPLICABLE) 1409-1417 12TH St. Oakland		OPERATOR —		PHONE (510) 703-5420
	ADDRESS 1409 - 1417 12th St. Oakland ALAMEDA 94607				
	CROSS STREET MANDELA PARKWAY				
IMPLEMENTING AGENCIES	LOCAL AGENCY AGENCY NAME CITY OF OAKLAND FIRE DEPT. HAZARDOUS MATERIAL DIV.			PHONE 510 238-7759	
	REGIONAL BOARD SAN FRANCISCO BAY REGION			PHONE 510 622-2423	
SUBSTANCES INVOLVED	(1) NAME PETROLEUM AS GASOLINE - WATER UP TO 110,000 ug/L			QUANTITY LOST (GALLONS) Unknown	
	(2) NAME BENZENE - SOIL TO 5.9 mg/kg			QUANTITY LOST (GALLONS) Unknown	
DISCOVERY/ABATEMENT	DATE DISCOVERED SEPTEMBER 1999		HOW DISCOVERED <input type="checkbox"/> Tank Test <input type="checkbox"/> Tank Removal <input type="checkbox"/> Nuisance Conditions <input type="checkbox"/> Inventory Control <input type="checkbox"/> Subsurface Monitoring <input checked="" type="checkbox"/> Other... SOIL BORINGS IN 1999		
	DATE DISCHARGE BEGAN Unknown		METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) <input type="checkbox"/> Remove Contents <input type="checkbox"/> Close Tank <input type="checkbox"/> Repair Tank <input type="checkbox"/> Change Procedure <input type="checkbox"/> Replace Tank <input checked="" type="checkbox"/> Other... APPEARS USTs WERE REMOVED <input type="checkbox"/> Repair Piping		
	HAS DISCHARGE BEEN STOPPED? UNKNOWN. APPEARS USTs removed. Residual TPHg & BTEX in SOIL & GROUNDWATER <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
SOURCE/CAUSE	SOURCE OF DISCHARGE <input type="checkbox"/> Tank Leak <input type="checkbox"/> Piping Leak <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> Other...		CAUSE(S) <input type="checkbox"/> Overfill <input type="checkbox"/> Corrosion <input type="checkbox"/> Rupture/Failure <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> Spill <input type="checkbox"/> Other...		
	CHECK ONE ONLY <input type="checkbox"/> Undetermined <input type="checkbox"/> Soil Only <input checked="" type="checkbox"/> Groundwater <input type="checkbox"/> Drinking Water - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)				
CURRENT STATUS	CHECK ONE ONLY <input type="checkbox"/> No Action Taken <input type="checkbox"/> Case Closed (Cleanup Completed or Unnecessary) <input type="checkbox"/> Leak Being Confirmed <input checked="" type="checkbox"/> Pollution Characterization INCOMPLETE CHARACTERIZATION <input type="checkbox"/> Remediation Plan <input type="checkbox"/> Post Cleanup Monitoring in Progress <input type="checkbox"/> Preliminary Site Assessment Workplan Submitted <input type="checkbox"/> Cleanup Underway <input type="checkbox"/> Preliminary Site Assessment Underway				
	CHECK APPROPRIATE ACTION(S) <input type="checkbox"/> Cap Site (CD) <input type="checkbox"/> Excavate & Treat (ET) <input type="checkbox"/> Treatment at Hookup (HU) <input checked="" type="checkbox"/> Other... NO ACTION TAKEN TO DATE <input type="checkbox"/> Contamination Barrier (CB) <input type="checkbox"/> No Action Required (NA) <input type="checkbox"/> Enhanced Bio Degradation (IT) <input type="checkbox"/> Vacuum Extract (VE) <input type="checkbox"/> Remove Free Product (FP) <input type="checkbox"/> Replace Supply (RS) <input type="checkbox"/> Excavate & Dispose (ED) <input type="checkbox"/> Pump & Treat Groundwater (GT) <input type="checkbox"/> Vent Soil (VS) OTHER THAN UST REMOVED				
COMMENTS	TPHg & BTEX detected in soil in SEPTEMBER 1999 during SUBSURFACE CHARACTERIZATION. ADDITIONAL CHARACTERIZATION & SITE REMEDIATION STILL NEEDED.				