

RO2958. 2008-04-11. Jerry Wickham visited site at 55 98th Avenue in Oakland. Primary purpose of site visit was to verify that planned borings were within the former tank pit. Field work consisting of three vapor probes and one soil boring was underway. Met with Ted Sison of SCS Engineers and discussed locations of borings. Based on location provided from aerial photo review by Steve Clements, he was able to scale off and then locate the borings using GPS. I was not able to find a remnant of the former concrete pad or well STMW-1. There was a low mound in the approximate former location of concrete pad. Not able to verify that concrete pad definitely removed although I inspected several depressions in mounded area and did not observe a concrete pad. I did observe isolated pieces of concrete in widely scattered locations. In a later phone call with Steve Clements, he expressed confidence in locations based on location of concrete pad on circa 1965 aerial photo.