



Atlantic Richfield Company
(a BP affiliated company)

P.O. Box 1257
San Ramon, California 94583
Phone: (925) 275-3801
Fax: (925) 275-3815

30 April 2009

Re: First Quarter 2009 Status Report
Former Richfield Oil Company Service Station #472
6415 International Blvd.
Oakland, California
ACEH Case # RO0002982

RECEIVED

10:16 am, May 01, 2009

Alameda County
Environmental Health



"I declare, that to the best of my knowledge at the present time, that the information and/or recommendations contained in the attached document are true and correct."

Submitted by:

Paul Supple
Environmental Business Manager

30 April 2009

Project No. 09-88-601

Atlantic Richfield Company
P.O. Box 1257
San Ramon, California 94583
Submitted via ENFOS

Attn.: Mr. Paul Supple

Re: First Quarter 2009 Status Report, Former Richfield Oil Company Service Station #472
6415 International Blvd., Oakland, California; ACEH Case #RO0002982

Dear Mr. Supple:

Provided herein is the *First Quarter 2009 Status Report* for Former Richfield Oil Company Service Station #472 (herein referred to as Station #472) located at 6415 International Boulevard, Oakland, California. This report presents a summary of current developments at the Site through First Quarter 2009.

Should you have questions regarding this submission, please do not hesitate to contact us at (530) 566-1400.

Sincerely,


BROADBENT & ASSOCIATES, INC.



Thomas A. Venus, P.E.
Senior Engineer



Robert H. Miller, P.G., C.HG.
Principal Hydrogeologist



Enclosures

cc: Mr. Paresh Khatri, Alameda County Environmental Health (Submitted via ACEH ftp Site)
Electronic copy uploaded to GeoTracker

STATION #472 QUARTERLY GROUND-WATER STATUS REPORT

Facility: #472	Address:	6415 International Boulevard, Oakland, California
Environmental Business Manager:		Mr. Paul Supple
Consulting Company/Contact Person:		Broadbent & Associates, Inc.(BAI)/Rob Miller & Tom Venus (530)566-1400
Consultant Project No.:		09-88-601
Primary Agency/Regulatory ID No.:		Alameda County Environmental Health (ACEH) ACEH Case #RO0002982

WORK PERFORMED THIS QUARTER (First Quarter 2009):

1. Prepared and submitted *Underground Storage Tank Unauthorized Release (Leak)/ Contamination Site Report* (BAI 2/20/2009).
2. Prepared and submitted *Work Plan for Soil & Ground-Water Investigation* (BAI 3/30/2009).
3. No environmental work was conducted at the site during the First Quarter of 2009.

WORK PROPOSED FOR NEXT QUARTER (Second Quarter 2009):

1. Prepared and submitted this First Quarter 2009 Status Report (contained herein).
2. Upon ACEH approval, implement soil and ground-water investigation.

DISCUSSION:

In a letter dated 29 January 2009, ACEH requested the preparation and submittal of an Underground Storage Tank (UST) Unauthorized Release Form and Soil and Ground-Water Investigation Work Plan. On 20 February 2009, BAI submitted the requested UST unauthorized release report form. On 30 March 2009, BAI submitted the requested soil and ground-water investigation work plan. BP is awaiting ACEH approval of the recently submitted Work Plan prior to initiation of field activities. For reference, a site map from the submitted work plan with proposed monitoring well locations is provided as Drawing 1.


ATTACHMENTS:

Drawing 1 Site Map with Proposed Monitoring Well Locations, Former Service Station #472, 6415 International Boulevard, Oakland, California

INTERNATIONAL BOULEVARD

64TH AVENUE

Grocery Store



LEGEND

- ▼ Proposed Monitoring Well
- Phase II Soil Boring

NOTES: SITE MAP ADAPTED FROM GEOCON FIGURES.
SITE DIMENSIONS AND FACILITY LOCATIONS NOT VERIFIED.

